

Available from

NRC/GPO Sales Program
Superintendent of Documents
Government Printing Office
Washington, D.C. 20402

A year's subscription consists of
12 issues of this publication

Single copies of this publication
are available from National Technical
Information Service, Springfield, VA 22161

Microfiche of single copies are
available from NRC/GPO Sales Program
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Title List of Documents Made Publicly Available

January 1-31, 1981

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Items by Facility Name	xvii
Docketed Items	1
Low Level Radwaste Disposal Sites – Docket 27	1
Domestic Licensing of Source Material – Docket 40	1
Domestic Licensing of Production and Utilization Facilities – Docket 50	5
Domestic Licensing of Special Nuclear Material – Docket 70	268
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions – Docket 71	276
Nondocketed Items	281
10CFR – Commission Meeting Records	281
ACRS – Advisory Committee on Reactor Safeguards	282
COMMISSION – NRC Commissioners	284
CONTRACT – NRC Contracts and Modifications	287
DISCLOSURE – Financial Disclosure Information	291
FOIA – Freedom of Information Act Requests and Releases	292
GEN TECH IS – Generic Technical Issues	299
I&E – Inspection and Enforcement	299
MISC – Public Document Room Miscellaneous	300
NUREG – NUREG Reports and Related Correspondence	300
ORG – Correspondence with Other Organizations	304
PR – Proposed Rule	304
PRM – Petition for Rulemaking	335
PROJ – Projects - Predocket Licensing	335
PT21 – Noncompliance Reports and Related Correspondence	335
QA999 – Quality Assurance Inspections	335
REGGD – Regulatory Guides	337
RES – Research and Technical Assistance Reports	339
REVIEW GRP – NRC Research Review Groups	342
SECY – Position Papers Before the Commission	343
STATE PROG – State Programs	344
TOPREP – Vendor Reports and Related Correspondence	346
WASTE MGT – Nuclear Waste Management	348
XPORTLIC – Export and Import Licenses	348
Personal Author Index	357
Corporate Source Index	389
Report Number Index	413
Cross Reference of Enclosures to Principal Documents	417
Appendix A – Definitions of Docket 50 Categories	431
Appendix B – Definitions of Nondocketed Categories	439

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.


DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters

Appendix A sets forth those categories and described the materials available in each. Omission from a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:



1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number
3. Description of information contained in the document
4. Personal author. An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source
6. Date of document described
7. Pages in document
8. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to video terminals.
9. This three-digit portion of this entry is the number of the frame on which this document starts.
10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS


The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records
 ACRS — Advisory Committee on Reactor Safeguards
 COMMISSION — NRC Commissioners
 CONTRACT — NRC Contracts and Modifications
 DISCLOSURE — Financial Disclosure Information
 FOIA — Freedom of Information Act Requests and Releases

I&E — Inspection and Enforcement
 MISC — Public Document Room Miscellaneous
 NUREG — NUREG Reports and Related Correspondence
 ORG — Correspondence with other organizations
 PR — Proposed Rule
 PRM — Petition for Rulemaking
 PROJ — Projects-Predocket Licensing
 PT9 — Public Records
 PT21 — Noncompliance Reports and Related Correspondence
 QA999 — Quality Assurance Inspections
 REGGD — Regulatory Guides
 RES — Research and Technical Assistance Reports
 REVIEW GRP — NRC Research Review Groups
 RM — Rulemakings
 SECY — Position Papers Before the Commission
 STATE PROG — State Programs
 TOPREP — Vendor Reports and Related Correspondence
 WASTE MGT — Nuclear Waste Management
 XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocketed category
2. NRC Accession Number
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author
6. Corporate, agency or other nonindividual source
7. Contract or financial (FIN) number (if any). If the document has a secondary report number It will appear following this entry.
8. Date of document described
9. Pages in document
10. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to video terminals.
11. This three-digit portion of this entry is the number of the frame on which this document starts.

the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTIS on this page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 497-9530.

2. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-039	Sheffield, IL, Nuclear Engineering Co.	1	40-8649	Flinchbaugh Products, Inc.	4
27-047	Barnwell, SC, Chem-Nuclear Systems	1	40-8674	Plateau Resources, Ltd.	4
27-048	Richland, WA, Nuclear Engineering Co.	1	40-8681	Energy Fuels Nuclear, Inc.	4
40-0299	Union Carbide Corp.	1	40-8693	Ogle Petroleum, Inc.	4
40-0800	Transnuclear, Inc.	1	40-8697	Rocky Mountain Energy Co.	4
40-1162	Western Nuclear, Inc.	1	40-8698	Plateau Resources, Ltd.	5
40-1341	Edgemont Uranium Mine, TVA and Mines Development, Inc.	2	40-8707	Envirologie Systems, Inc.	5
40-2061	West Chicago Facility, Kerr-McGee Corp.	2	40-8712	Gulf Oil Corp.	5
40-2259	Pathfinder Mines Corp.	2	40-8724	Chemtron Corp.	5
40-3392	Allied Chemical Corp.	2	40-8728	Teton Exploration Drilling Co., Inc.	5
40-3453	Atlas Minerals	2	40-8743	Conoco	5
40-3698	Bell	3	40-8768	Kerr-McGee Corp.	5
40-4492	Federal American Partners (Mining)	3	40-8771	Nuclear Assurance Corp.	5
40-5939	Bell	3	40-8778	Teton Exploration Drilling Co., Inc.	5
40-6439	Univ. of New Mexico	3	50-3	Indian Point Station, Unit 1	5
40-6622	Pathfinder Mines Corp.	3	50-5	Pennsylvania State Univ. Research Reactor	6
40-7869	Plateau Resources, Ltd.	3	50-6	Battelle Memorial Institute Research Reactor	6
40-8003	General Electric Co.	3	50-10	Dresden Nuclear Power Station, Unit 1	6
40-8027	Kerr-McGee Corp.	3	50-16	Enrico Fermi Atomic Power Plant, Unit 1	8
40-8084	Lisbon Mine, Rio Algom Corp.	3	50-27	Washington State Univ. Research Reactor	9
40-8200	Cleveland-Cliffs Iron Co.	3	50-29	Yankee-Rowe Nuclear Power Station	9
40-8304	Wyoming Mineral Corp.	3	50-54	Union Carbide Research Reactor	10
40-8380	Rocky Mountain Energy Co.	3	50-57	State Univ. of New York Research Reactor	10
40-8452	Bear Creek Uranium Co.	3	50-62	Univ. of Virginia Research Reactor	10
40-8502	Irigaray Mine, Wyoming Mining Corp.	4	50-70	General Electric Test Reactor	10
40-8511	Cotter Corp.	4	50-87	Westinghouse Critical Experiment	11
40-8584	Union 76 Minerals Exploration Co.	4	50-89	General Atomic Co.	11
40-8585	Wyoming Mineral Corp.	4			

Docket	Name	Page	Docket	Name	Page
50-111	North Carolina State Univ. Research Reactor	11	50-250	Turkey Point Plant, Unit 3	39
50-131	Omaha Veterans Administration Hospital Research Reactor	11	50-251	Turkey Point Plant, Unit 4	41
50-133	Humboldt Bay Power Plant, Unit 3	11	50-254	Quad-Cities Station, Unit 1	44
50-134	Worcester Polytechnic Institute Research Reactor	12	50-255	Palisades Nuclear Plant	46
50-142	UCLA Training Reactor	13	50-259	Browns Ferry Nuclear Power Station, Unit 1	48
50-148	Univ. of Kansas Research Reactor	13	50-260	Browns Ferry Nuclear Power Station, Unit 2	50
50-151	Univ. of Illinois Research Reactor	13	50-261	H.B. Robinson Plant, Unit 2	52
50-155	Big Rock Point Nuclear Plant	13	50-262	Brigham Young Univ. Research Reactor	54
50-156	Univ. of Wisconsin Research Reactor	17	50-263	Monticello Nuclear Generating Plant	54
50-163	General Atomic Co.	17	50-265	Quad-Cities Station, Unit 2	55
50-170	National Naval Medical Center	17	50-266	Point Beach Nuclear Plant, Unit 1	57
50-184	National Bureau of Standards Reactor	17	50-267	Fort St. Vrain Nuclear Generating Station	59
50-186	Univ. of Missouri Research Reactor	18	50-269	Oconee Nuclear Station, Unit 1	61
50-187	Space Radiation Research Reactor	18	50-270	Oconee Nuclear Station, Unit 2	63
50-188	Kansas State Univ. Research Reactor	18	50-271	Vermont Yankee Nuclear Power Station	64
50-193	Rhode Island & Providence Plantations AEC	18	50-272	Salem Nuclear Generating Station, Unit 1	67
50-201	West Valley Reprocessing Plant	18	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	70
50-206	San Onofre Nuclear Station, Unit 1	18	50-277	Peach Bottom Atomic Power Station, Unit 2	72
50-208	Columbia Univ. Research Reactor	20	50-278	Peach Bottom Atomic Power Station, Unit 3	74
50-213	Haddam Neck Plant	20	50-280	Surry Power Station, Unit 1	76
50-219	Oyster Creek Nuclear Power Plant	22	50-281	Surry Power Station, Unit 2	78
50-220	Nine Mile Point Nuclear Station, Unit 1	24	50-282	Prairie Island Nuclear Station, Unit 1	81
50-224	Univ. of California Research Reactor	26	50-285	Fort Calhoun Station, Unit 1	82
50-225	RPI Critical Experiment	27	50-286	Indian Point Station, Unit 3	84
50-228	Aerotest Radiography & Research Reactor	27	50-287	Oconee Nuclear Station, Unit 3	86
50-237	Dresden Nuclear Power Station, Unit 2	27	50-289	Three Mile Island Nuclear Station, Unit 1	88
50-238	Nuclear Ship Savannah	29	50-293	Pilgrim Nuclear Power Station, Unit 1	95
50-241	Mississippi State Univ. Research Reactor	29	50-295	Zion Nuclear Power Station, Unit 1	97
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	30	50-296	Browns Ferry Nuclear Power Station, Unit 3	99
50-245	Millstone Nuclear Power Station, Unit 1	31	50-298	Cooper Nuclear Station	101
50-247	Indian Point Station, Unit 2	33	50-301	Point Beach Nuclear Plant, Unit 2	103
50-249	Dresden Nuclear Power Station, Unit 3	36	50-302	Crystal River Nuclear Plant, Unit 3	104
			50-304	Zion Nuclear Power Station, Unit 2	106

Docket	Name	Page	Docket	Name	Page
50-305	Kewaunee Nuclear Power Plant	108	50-353	Limerick Generating Station, Unit 2	172
50-306	Prairie Island Nuclear Station, Unit 2	110	50-354	Hope Creek Nuclear Station, Unit 1	173
50-309	Maine Yankee Atomic Power Plant	111	50-355	Hope Creek Nuclear Station, Unit 2	174
50-311	Salem Nuclear Generating Station, Unit 2	113	50-356	Univ. of Illinois LOPRA Research Reactor	174
50-312	Rancho Seco Nuclear Generating Station	115	50-358	William H. Zimmer Nuclear Station, Unit 1	175
50-313	Arkansas Nuclear One, Unit 1	117	50-361	San Onofre Nuclear Station, Unit 2	176
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	119	50-362	San Onofre Nuclear Station, Unit 3	178
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	120	50-363	Forked River Nuclear Station, Unit 1	180
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	122	50-364	Joseph M. Farley Nuclear Plant, Unit 2	180
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	124	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	182
50-320	Three Mile Island Nuclear Station, Unit 2	126	50-367	Bailly Generating Station	183
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	131	50-368	Arkansas Nuclear One, Unit 2	185
50-322	Shoreham Nuclear Power Station	132	50-369	William B. McGuire Nuclear Station, Unit 1	188
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	134	50-370	William B. McGuire Nuclear Station, Unit 2	190
50-324	Brunswick Steam Electric Plant, Unit 2	135	50-373	LaSalle County Station, Unit 1	191
50-325	Brunswick Steam Electric Plant, Unit 1	138	50-374	LaSalle County Station, Unit 2	193
50-327	Sequoyah Nuclear Plant, Unit 1	140	50-376	North Coast Nuclear Plant, Puerto Rico	194
50-328	Sequoyah Nuclear Plant, Unit 2	143	50-382	Waterford Generating Station, Unit 3	194
50-329	Midland Plant, Unit 1	145	50-387	Susquehanna Steam Electric Station, Unit 1	195
50-330	Midland Plant, Unit 2	148	50-388	Susquehanna Steam Electric Station, Unit 2	198
50-331	Duane Arnold Energy Center	151	50-389	St. Lucie Plant, Unit 2	200
50-332	Barnwell Reprocessing Plant	152	50-390	Watts Bar Nuclear Plant, Unit 1	201
50-333	James A. Fitzpatrick Nuclear Power Plant	152	50-391	Watts Bar Nuclear Plant, Unit 2	202
50-334	Beaver Valley Power Station, Unit 1	154	50-392	Chi-shan Power Reactor, Unit 1, Taiwan	204
50-335	St. Lucie Plant, Unit 1	156	50-395	Virgil C. Summer Nuclear Station, Unit 1	204
50-336	Millstone Nuclear Power Station, Unit 2	158	50-396	Univ. of Virginia Cavalier Reactor	207
50-338	North Anna Power Station, Unit 1	160	50-397	WPPSS Nuclear Project, Unit 2	207
50-339	North Anna Power Station, Unit 2	162	50-400	Shearon Harris Nuclear Power Plant, Unit 1	208
50-341	Enrico Fermi Atomic Power Plant, Unit 2	164	50-401	Shearon Harris Nuclear Power Plant, Unit 2	208
50-344	Trojan Nuclear Plant	165	50-402	Shearon Harris Nuclear Power Plant, Unit 3	209
50-346	Davis-Besse Nuclear Power Station, Unit 1	167	50-403	Shearon Harris Nuclear Power Plant, Unit 4	209
50-348	Joseph M. Farley Nuclear Plant, Unit 1	169	50-404	North Anna Power Station, Unit 3	209
50-352	Limerick Generating Station, Unit 1	171	50-405	North Anna Power Station, Unit 4	209

Docket	Name	Page	Docket	Name	Page
50-409	La Crosse Boiling Water Reactor	210	50-462	Clinton Power Station, Unit 2	23
50-410	Nine Mile Point Nuclear Station, Unit 2	212	50-463	Fulton Generating Station, Unit 1	23
50-412	Beaver Valley Power Station, Unit 2	212	50-464	Fulton Generating Station, Unit 2	23
50-413	Catawba Nuclear Station, Unit 1	212	50-466	Allens Creek Nuclear Station, Unit 1	27
50-414	Catawba Nuclear Station, Unit 2	213	50-467	Allens Creek Nuclear Station, Unit 2	27
50-416	Grand Gulf Nuclear Station, Unit 1	214	STN-50-470	CESSAR System 80	27
50-417	Grand Gulf Nuclear Station, Unit 2	216	50-471	Pilgrim Nuclear Power Station, Unit 2	27
50-423	Millstone Nuclear Power Station, Unit 3	218	STN-50-480	RESAR-41	27
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	218	STN-50-482	Wolf Creek Generating Station	27
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	219	STN-50-483	Callaway Plant, Unit 1	24
STN-50-437	Floating Nuclear Plant	219	STN-50-485	Sterling Power Nuclear Project, Unit 1	24
50-438	Bellefonte Nuclear Plant, Unit 1	220	STN-50-486	Callaway Plant, Unit 2	24
50-439	Bellefonte Nuclear Plant, Unit 2	221	STN-50-488	Perkins Nuclear Station, Unit 1	24
50-440	Perry Nuclear Power Plant, Unit 1	223	STN-50-489	Perkins Nuclear Station, Unit 2	24
50-441	Perry Nuclear Power Plant, Unit 2	224	STN-50-490	Perkins Nuclear Station, Unit 3	24
50-443	Seabrook Nuclear Station, Unit 1	224	STN-50-491	Cherokee Nuclear Station, Unit 1	24
50-444	Seabrook Nuclear Station, Unit 2	225	STN-50-492	Cherokee Nuclear Station, Unit 2	24
50-445	Comanche Peak Steam Electric Station, Unit 1	226	STN-50-493	Cherokee Nuclear Station, Unit 3	24
50-446	Comanche Peak Steam Electric Station, Unit 2	228	50-496	Montague Nuclear Power Station, Unit 1	24
			50-497	Montague Nuclear Power Station, Unit 2	24
STN-50-447	CESSAR-238	229	STN-50-498	South Texas Project, Unit 1	24
50-448	Douglas Point Nuclear Station, Unit 1	229	STN-50-499	South Texas Project, Unit 2	24
50-449	Douglas Point Nuclear Station, Unit 2	229	50-500	Davis-Besse Nuclear Power Station, Unit 2	25
50-452	Greenwood Energy Center, Unit 2	229	50-501	Davis-Besse Nuclear Power Station, Unit 3	25
50-453	Greenwood Energy Center, Unit 3	230	STN-50-508	WPPSS Nuclear Project, Unit 3	25
50-454	Byron Station, Unit 1	230	STN-50-509	WPPSS Nuclear Project, Unit 5	25
50-455	Byron Station, Unit 2	231	50-510	Blue Hills Station, Unit 1	25
50-456	Braidwood Station, Unit 1	232	50-511	Blue Hills Station, Unit 2	25
50-457	Braidwood Station, Unit 2	233	50-512	Laguna Verde Station	25
50-458	River Bend Station, Unit 1	234	50-513	WPPSS Nuclear Project, Unit 4	25
50-459	River Bend Station, Unit 2	234	50-514	Pebble Springs Nuclear Plant, Unit 1	25
50-460	WPPSS Nuclear Project, Unit 1	235	50-515	Pebble Springs Nuclear Plant, Unit 2	25
50-461	Clinton Power Station, Unit 1	235	STN-50-516	Jamesport Nuclear Station, Unit 1	25

Docket	Name	Page	Docket	Name	Page
STN-50-517	Jamesport Nuclear Station, Unit 2	253	70-0033	Texas Instruments, Inc.	2
STN-50-518	Hartsville Nuclear Plant, Unit 1	253	70-0121	Dept. of Interior, Geological Survey	2
STN-50-519	Hartsville Nuclear Plant, Unit 2	254	70-0124	Teledyne Isotopes	2
STN-50-520	Hartsville Nuclear Plant, Unit 3	255	70-0135	Babcock & Wilcox Co.	2
STN-50-521	Hartsville Nuclear Plant, Unit 4	256	70-0143	Nuclear Fuel Services, Inc.	2
STN-50-522	Skagit Nuclear Power Project Unit 1	257	70-0157	Univ. of Texas	2
STN-50-523	Skagit Nuclear Power Project, Unit 2	257	70-0168	Nuclide Corp.	2
50-524	Barton, Unit 1	257	70-0261	Schlumberger Technology Corp.	2
50-525	Barton, Unit 2	257	70-0354	Univ. of Kansas	2
50-526	Barton, Unit 3	257	70-0364	Parks Township Site, Babcock & Wilcox Co.	2
50-527	Barton, Unit 4	257	70-0371	United Nuclear Corp.	2
STN-50-528	Palo Verde Nuclear Station, Unit 1	257	70-0568	Brigham Young Univ.	2
STN-50-529	Palo Verde Nuclear Station, Unit 2	258	70-0687	Union Carbide Corp.	2
STN-50-530	Palo Verde Nuclear Station, Unit 3	26B	70-0728	Univ. of Utah	2
50-537	Clinch River Breeder Reactor	261	70-0734	General Atomic Co.	2
STN-50-546	Marble Hill Nuclear Station, Unit 1	261	70-0754	Vallecitos Nuclear Center, General Electric Co.	2
STN-50-547	Marble Hill Nuclear Station, Unit 2	262	70-0818	Eastern Nazarene College	2
50-548	Fort Calhoun Station, Unit 2	263	70-0820	United Nuclear Corp.	2
STN-50-553	Phipps Bend Nuclear Station, Unit 1	263	70-0821	Washington & Lee Univ.	2
STN-50-554	Phipps Bend Nuclear Station, Unit 2	264	70-0824	Babcock & Wilcox Co.	2
STN-50-556	Black Fox Station, Unit 1	265	70-0882	Columbia Univ.	2
STN-50-557	Black Fox Station, Unit 2	265	70-0925	Cimarron Facility	2
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	265	70-1007	General Electric Co.	2
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	266	70-1035	Brigham Young Univ.	2
STN-50-580	Erie Nuclear Plant, Unit 1	267	70-1100	Combustion Engineering, Inc.	2
STN-50-581	Erie Nuclear Plant, Unit 2	267	70-1110	C-E Power Systems	2
50-582	Sundesert, Unit 1	267	70-1111	Elizabethtown College	2
50-583	Sundesert, Unit 2	267	70-1113	General Electric Co.	2
STN-50-592	Palo Verde Nuclear Station, Unit 4	267	70-1151	Westinghouse Electric Corp.	2
STN-50-593	Palo Verde Nuclear Station, Unit 5	268	70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	2
70-0008	Battelle Columbus Laboratories	268	70-1288	Univ. of Utah	2
70-0025	Rockwell International Corp.	268			
70-0027	Babcock & Wilcox Co.	268			

Docket	Name	Page	Docket	Name	Page
70-1308	Morris Operations, General Electric Co.	273	71-0401	Reliance Testing Laboratories, Inc.	273
70-1327	U-6 Conversion Facility, Allied-General Nuclear Services Corp.	274	71-0402	C&R Laboratories	273
70-1374	Idaho State Univ.	274	71-0403	Schlumberger Well Service	273
70-1436	Univ. of Oklahoma	274	71-0404	Alaska Welding Center	273
70-1462	Harper-Grace Hospital, Harper Hospital Division, Detroit, MI	274	71-0405	Energy, Inc.	273
70-1470	Veterans Administration Hospital, Los Angeles, CA	274	71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	273
70-1738	Pacific Gas & Electric Co.	274	71-5059	Model: URANY NIT-TNK, Nuclear Fuel Services, Inc.	273
70-1739	Tri-State Motor Transit Co.	274	71-5086	Model: UNC-2600, General Atomic Co.	273
70-1821	Plutonium Production Facility, Allied-General Nuclear Services Corp.	274	71-5364	Model: NPI-67-0442 Neutron Products, Inc.	273
70-1936	Texas A&M Univ.	274	71-5768	Model: BB-250-2, Combustion Engineering Co., Inc.	273
70-2249	Hutzel Hospital, Detroit, MI	274	71-5796	Model: 181361, Picker Corporation	273
70-2322	Edlow International Co.	274	71-5805	Model: ATCOR VNDB Cask, Atcor, Inc.	273
70-2375	Pacific Gas & Electric Co.	274	71-5908	Model: DOT-GM Type B, Babcock & Wilcox Co.	273
70-2434	Transnuclear, Inc.	275	71-5926	Model: 100, General Electric Co.	273
70-2479	Transnuclear, Inc.	275	71-5938	Model: HNPf, General Atomic Co.	273
70-2511	Transnuclear, Inc.	275	71-5939	Model: GE-1500, General Electric Co.	273
70-2529	Cardinal Cushing General Hospital, Breckton, MA	275	71-5957	Model: BMI-1, Dept. of Energy	273
70-2623	McGuire Spent Fuel Pool, Duke Power Co.	275	71-5971	Model: GE-200, General Electric Co.	273
70-2838	Cincinnati Gas & Electric Co.	275	71-5980	Model: GE-600, General Electric Co.	273
70-2882	Southern California Edison Co.	275	71-6144	Model: B2, Nuclear Engineering Co.	273
70-2901	Southern California Edison Co.	275	71-6273	Model: 48X, F, A, Y, Allied-General Nuclear Services Corp.	273
70-2908	Veterans Administration Hospital, San Diego, CA	275	71-6375	Model: PB-1, Chem-Nuclear Systems, Inc.	273
70-2909	Westinghouse Electric Corp. Power Systems	275	71-6400	Model: Super Tiger, Westinghouse Electric Corp.	273
70-2936	Mississippi Power & Light Co.	276	71-6458	Model: BU-5, General Electric Co.	273
70-2937	Pennsylvania Power & Light Co.	276	71-6573	Model: HIT-506, Nuclear Battery Corp.	273
71-0102	Source Products & Equipment Co., Inc.	276	71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	273
71-0179	Nuclear Containers, Inc.	276	71-6601	Model: LL-50-100, Chem-Nuclear Systems, Inc.	273
71-0358	Dept. of the Navy, USS Sierra	276	71-6642	Model: 4.5 Ton Cf, Dept. of Energy	273
71-0398	Texas A&M Univ.	276	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	273
71-0400	Dept. of the Navy	276			

Docket	Name	Page	Docket	Name	Page
71-6717	Model: 6717-B, Gamma Industries	278	71-9079	Model: HN-100 Series 2, Hittman Nuclear & Development Corp.	279
71-6744	Model: Poly Tiger, Nuclear Engineering Co.	278	71-9080	Model: HN-600, Hittman Nuclear & Development Corp.	279
71-9001	Model: 1F-300, General Electric Co.	278	71-9086	Model: HN-100 Series 1, Hittman Nuclear & Development Corp.	279
71-9007	Model: 520, Automation Industries, Inc.	278	71-9089	Model: HN-100S, Hittman Nuclear & Development Corp.	279
71-9010	Model: NLI-1/2, NL Industries, Inc.	278	71-9094	Model: CNSI-14-195-11, Chem-Nuclear Systems, Inc.	279
71-9019	Model: BU-7, General Electric Co.	278	71-9111	Model: CN6-80A, Chem-Nuclear, Inc.	279
71-9023	Model: NLI-10/24, NL Industries, Inc.	278	71-9124	Model: L2-181 & L3-181, Nuclear Engineering Co., Inc.	279
71-9032	Model: 650, Technical Operations, Inc.	278	71-9129	Model: UNI LA-50, Northeast Utilities	279
71-9033	Model: 660 & 660E, Technical Operations, Inc.	278	71-9130	Model: NP-50-XXL, Nuclear Packaging, Inc.	279
71-9035	Model: 680, Technical Operations, Inc.	278	71-9132	Model: T-3, Nuclear Packaging, Inc.	280
71-9036	Model: C-1, Source Production & Equipment Co.	278	71-9133	Model: C-10, Gamma Industries	280
71-9044	Model: GE-1600, General Electric Co.	279	71-9141	Model: 900 Type B, Technical Operations, Inc.	280
71-9065	Model: BU-4, General Electric Co.	279	71-9145	Model: NUPAC-50, Nuclear Packaging, Inc.	280
71-9070	Model: N-55, Dept. of Energy	279			
71-9072	Model: GAIIC-1, General Atomic Co.	279			
71-9074	Model: AP-100, ANEFCO, Inc.	279			

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Aerotest Radiography & Research Reactor	50-228	27	Browns Ferry Nuclear Power Station, Unit 3	50-296	9
Allens Creek Nuclear Station, Unit 1	50-466	237	Brunswick Steam Electric Plant, Unit 1	50-325	13
Allens Creek Nuclear Station, Unit 2	50-467	239	Brunswick Steam Electric Plant, Unit 2	50-324	13
Arkansas Nuclear One, Unit 1	50-313	117	Byron Station, Unit 1	50-454	23
Arkansas Nuclear One, Unit 2	50-368	185	Byron Station, Unit 2	50-455	23
Duane Arnold Energy Center	50-331	151	Callaway Plant, Unit 1	STN-50-483	24
Bailly Generating Station	50-367	183	Callaway Plant, Unit 2	STN-50-486	24
Barnwell Reprocessing Plant	50-332	152	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	12
Barton, Unit 1	50-524	257	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	12
Barton, Unit 2	50-525	257	Catawba Nuclear Station, Unit 1	50-413	21
Barton, Unit 3	50-526	257	Catawba Nuclear Station, Unit 2	50-414	21
Barton, Unit 4	50-527	257	CESSAR System 80	STN-50-470	23
Battelle Memorial Institute Research Reactor	50-6	6	Cherokee Nuclear Station, Unit 1	STN-50-491	24
Beaver Valley Power Station, Unit 1	50-334	154	Cherokee Nuclear Station, Unit 2	STN-50-492	24
Beaver Valley Power Station, Unit 2	50-412	212	Cherokee Nuclear Station, Unit 3	STN-50-493	24
Bellefonte Nuclear Plant, Unit 1	50-438	220	Chi-shan Power Reactor, Unit 1, Taiwan	50-392	20
Bellefonte Nuclear Plant, Unit 2	50-439	221	Clinch River Breeder Reactor	50-537	26
Big Rock Point Nuclear Power Plant	50-155	13	Clinton Power Station, Unit 1	50-461	2
Black Fox Station, Unit 1	STN-50-556	265	Clinton Power Station, Unit 2	50-462	2
Black Fox Station, Unit 2	STN-50-557	265	Columbia Univ. Research Reactor	50-208	7
Blue Hills Station, Unit 1	50-510	251	Comanche Peak Steam Electric Station, Unit 1	50-445	2
Blue Hills Station, Unit 2	50-511	252	Comanche Peak Steam Electric Station, Unit 2	50-446	2
Braidwood Station, Unit 1	50-456	232	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	1
Braidwood Station, Unit 2	50-457	233	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	1
Brigham Young Univ. Research Reactor	50-262	54	Cooper Nuclear Station	50-298	10
Browns Ferry Nuclear Power Station, Unit 1	50-289	48			
Browns Ferry Nuclear Power Station, Unit 2	50-290	50			

Name	Docket	Page	Name	Docket	Page
Crystal River Nuclear Plant, Unit 3	50-302	104	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	30
Davis-Besse Nuclear Power Station, Unit 1	50-346	167	Grand Gulf Nuclear Station, Unit 1	50-416	214
Davis-Besse Nuclear Power Station, Unit 1	50-500	250	Grand Gulf Nuclear Station, Unit 2	50-417	216
Davis-Besse Nuclear Power Station, Unit 3	50-501	251	Greenwood Energy Center, Unit 2	50-452	229
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	70	Greenwood Energy Center, Unit 3	50-453	230
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	134	Haddam Neck Plant	50-213	20
Douglas Point Nuclear Station, Unit 1	50-448	229	Shearon Harris Nuclear Power Plant, Unit 1	50-400	208
Douglas Point Nuclear Station, Unit 2	50-449	229	Shearon Harris Nuclear Power Plant, Unit 2	50-401	208
Dresden Nuclear Power Station, Unit 1	50-10	6	Shearon Harris Nuclear Power Plant, Unit 3	50-402	209
Dresden Nuclear Power Station, Unit 2	50-237	27	Shearon Harris Nuclear Power Plant, Unit 4	50-403	209
Dresden Nuclear Power Station, Unit 3	50-249	36	Hartsville Nuclear Plant, Unit 1	STN-50-518	253
Joseph M. Farley Nuclear Plant, Unit 1	50-348	169	Hartsville Nuclear Plant, Unit 2	STN-50-519	254
Joseph M. Farley Nuclear Plant, Unit 2	50-364	180	Hartsville Nuclear Plant, Unit 3	STN-50-520	255
Enrico Fermi Atomic Power Plant, Unit 1	50-16	8	Hartsville Nuclear Plant, Unit 4	STN-50-521	256
Enrico Fermi Atomic Power Plant, Unit 2	50-341	164	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	131
Ette Nuclear Plant, Unit 1	STN-50-580	267	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	182
Ette Nuclear Plant, Unit 2	STN-50-581	267	Hope Creek Nuclear Station, Unit 1	50-354	173
James A. Fitzpatrick Nuclear Power Plant	50-333	152	Hope Creek Nuclear Station, Unit 2	50-355	174
Floating Nuclear Plant	STN-50-437	219	Humboldt Bay Power Plant, Unit 3	50-133	11
Forked River Nuclear Station, Unit 1	50-363	180	Indian Point Station, Unit 1	50-3	5
Fort Calhoun Station, Unit 1	50-285	82	Indian Point Station, Unit 2	50-247	33
Fort Calhoun Station, Unit 2	50-548	263	Indian Point Station, Unit 3	50-286	84
Fort St. Vrain Nuclear Generating Station	50-267	59	Jamesport Nuclear Station, Unit 1	STN-50-516	253
Fulton Generating Station, Unit 1	50-463	237	Jamesport Nuclear Station, Unit 2	STN-50-517	253
Fulton Generating Station, Unit 2	50-464	237	Kansas State Univ. Research Reactor	50-188	18
General Atomic Co.	50-89	11	Kewaunee Nuclear Power Plant	50-305	108
General Atomic Co.	50-163	17	La Crosse Boiling Water Reactor	50-409	210
General Electric Test Reactor	50-70	10	Laguna Verde Station	50-512	252
GESSAR-238	STN-50-447	229	LaSalle County Station, Unit 1	50-373	191
			LaSalle County Station, Unit 2	50-374	193

Name	Docket	Page	Name	Docket	Page
Limerick Generating Station, Unit 1	50-352	171	Oconee Nuclear Station, Unit 3	50-287	80
Limerick Generating Station, Unit 2	50-353	172	Omaha Veterans Administration Hospital Research Reactor	50-131	1
Maine Yankee Atomic Power Plant	50-309	111	Oyster Creek Nuclear Power Plant	50-219	2
Marble Hill Nuclear Station, Unit 1	STN-50-546	261	Palisades Nuclear Plant	50-255	4
Marble Hill Nuclear Station, Unit 2	STN-50-547	262	Palo Verde Nuclear Station, Unit 1	STN-50-528	25
William B. McGuire Nuclear Station, Unit 1	50-369	188	Palo Verde Nuclear Station, Unit 2	STN-50-529	25
William B. McGuire Nuclear Station, Unit 2	50-370	190	Palo Verde Nuclear Station, Unit 3	STN-50-530	26
Midland Plant, Unit 1	50-329	145	Palo Verde Nuclear Station, Unit 4	STN-50-592	26
Midland Plant, Unit 2	50-330	148	Palo Verde Nuclear Station, Unit 5	STN-50-593	26
Millstone Nuclear Power Station, Unit 1	50-245	31	Peach Bottom Atomic Power Station, Unit 2	50-277	7
Millstone Nuclear Power Station, Unit 2	50-336	158	Peach Bottom Atomic Power Station, Unit 3	50-278	7
Millstone Nuclear Power Station, Unit 3	50-423	218	Pebble Springs Nuclear Plant, Unit 1	50-514	25
Mississippi State Univ. Research Reactor	50-241	29	Pebble Springs Nuclear Plant, Unit 2	50-515	25
Montague Nuclear Power Station, Unit 1	50-496	246	Pennsylvania State Univ. Research Reactor	50-5	
Montague Nuclear Power Station, Unit 2	50-497	246	Perkins Nuclear Station, Unit 1	STN-50-488	24
Monticello Nuclear Generating Plant	50-263	54	Perkins Nuclear Station, Unit 2	STN-50-489	24
National Bureau of Standards Reactor	50-184	17	Perkins Nuclear Station, Unit 3	STN-50-490	24
National Naval Medical Center	50-170	17	Perry Nuclear Power Plant, Unit 1	50-440	22
Nine Mile Point Nuclear Station, Unit 1	50-220	24	Perry Nuclear Power Plant, Unit 2	50-441	22
Nine Mile Point Nuclear Station, Unit 2	50-410	212	Phipps Bend Nuclear Plant, Unit 1	STN-50-553	26
North Anna Power Station, Unit 1	50-338	160	Phipps Bend Nuclear Plant, Unit 2	STN-50-554	26
North Anna Power Station, Unit 2	50-339	162	Pilgrim Nuclear Power Station, Unit 1	50-293	9
North Anna Power Station, Unit 3	50-404	209	Pilgrim Nuclear Power Station, Unit 2	50-471	23
North Anna Power Station, Unit 4	50-405	209	Point Beach Nuclear Plant, Unit 1	50-266	5
North Carolina State Univ. Research Reactor	50-111	11	Point Beach Nuclear Plant, Unit 2	50-301	10
North Coast Nuclear Plant, Puerto Rico	50-376	194	Prairie Island Nuclear Station, Unit 1	50-282	8
Nuclear Ship Savannah	50-238	29	Prairie Island Nuclear Station, Unit 2	50-306	11
Oconee Nuclear Station, Unit 1	50-269	61	Quad-Cities Station, Unit 1	50-254	4
Oconee Nuclear Station, Unit 2	50-270	63	Quad-Cities Station, Unit 2	50-265	5
			Rancho Seco Nuclear Generating Station	50-312	13

Name	Docket	Page	Name	Docket	Page
RESAR-41	STN-50-480	239	Susquehanna Steam Electric Station, Unit 2	50-388	19
Rhode Island & Providence Plantations AEC	50-193	18	Three Mile Island Nuclear Station, Unit 1	50-289	8
River Bend Station, Unit 1	50-458	234	Three Mile Island Nuclear Station, Unit 2	50-320	12
River Bend Station, Unit 2	50-459	234	Trojan Nuclear Plant	50-344	16
H.B. Robinson Plant, Unit 2	50-261	52	Turkey Point Plant, Unit 3	50-250	3
RPI Critical Experiment	50-225	27	Turkey Point Plant, Unit 4	50-251	4
Salem Nuclear Generating Station, Unit 1	50-272	67	UCLA Training Reactor	50-142	0
Salem Nuclear Generating Station, Unit 2	50-311	113	Union Carbide Research Reactor	50-54	0
San Onofre Nuclear Station, Unit 1	50-206	18	Univ. of California Research Reactor	50-224	2
San Onofre Nuclear Station, Unit 2	50-361	176	Univ. of Illinois LOPRA Research Reactor	50-356	1
San Onofre Nuclear Station, Unit 3	50-362	178	Univ. of Illinois Research Reactor	50-151	
Seabrook Nuclear Station, Unit 1	50-443	224	Univ. of Kansas Research Reactor	50-148	
Seabrook Nuclear Station, Unit 2	50-444	225	Univ. of Missouri Research Reactor	50-186	
Sequoyah Nuclear Plant, Unit 1	50-327	140	Univ. of Virginia Cavalier Reactor	50-396	2
Sequoyah Nuclear Plant, Unit 2	50-328	143	Univ. of Virginia Research Reactor	50-62	
Shoreham Nuclear Power Station	50-322	132	Univ. of Wisconsin Research Reactor	50-156	
Skagit Nuclear Power Project, Unit 1	STN-50-522	257	Vermont Yankee Nuclear Power Station	50-271	
Skagit Nuclear Power Project, Unit 2	STN-50-523	257	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	2
South Texas Project, Unit 1	STN-50-498	246	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	2
South Texas Project, Unit 2	STN-50-499	248	Washington State Univ. Research Reactor	50-27	
Space Radiation Research Reactor	50-187	18	Waterford Generating Station, Unit 3	50-382	1
State Univ. of New York Research Reactor	50-57	10	Watts Bar Nuclear Plant, Unit 1	50-390	2
Sterling Power Project, Nuclear, Unit 1	STN-50-485	243	Watts Bar Nuclear Plant, Unit 2	50-391	2
St. Lucie Plant, Unit 1	50-335	156	Westinghouse Critical Experiment	50-87	
St. Lucie Plant, Unit 2	50-389	200	West Valley Reprocessing Plant	50-201	
Virgil C. Summer Nuclear Station, Unit 1	50-395	204	Wolf Creek Generating Station	STN-50-482	2
Sundesert, Unit 1	50-582	267	Worcester Polytechnic Institute Research Reactor	50-134	
Sundesert, Unit 2	50-583	267	WPPSS Nuclear Project, Unit 1	50-460	2
Surry Power Station, Unit 1	50-280	76	WPPSS Nuclear Project, Unit 2	50-397	20
Surry Power Station, Unit 2	50-281	78	WPPSS Nuclear Project, Unit 3	STN-50-508	25
Susquehanna Steam Electric Station, Unit 1	50-387	195	WPPSS Nuclear Project, Unit 4	50-513	25
			WPPSS Nuclear Project, Unit 5	STN-50-509	25

Name	Docket	Page	Name	Docket	Page
Yankee-Rowe Nuclear Power Station	50-29	9	William H. Zimmer Nuclear Station, Unit 1	50-358	175
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	265	Zion Nuclear Power Station, Unit 1	50-295	97
Yellow Creek Nuclear Plant, Unit 2	STN-50-567	266	Zion Nuclear Power Station, Unit 2	50-304	106

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, NUCLEAR ENGINEERING CO

8101160120 Advises that Nuclear Engineering Co. Inc is changing name to US Ecology, Inc.
BAER, T.S. US Ecology, Inc (Formerly Nuclear Engineering) 81/12/29.
1p. 07469:337.

0101280060 Notification of contract execution, Mod 6 to "EIS on Sheffield Low Level Waste Disposal Site" Contractor NUS Corp.
HAIRSTON, C., SMITH, P. Technical Assistance Contracts Branch.
NRC-02-78-035 81/01/02 1p 07555:115

--8101280075 Mod 6, revoking change order to contract Mod 5 to "EIS on Sheffield Low Level Waste Disposal Site."
NUS Corp. MATTHEW J. Administrative Contracts Branch.
NRC-02-78-035 81/01/02 1p 07555:116

8101300116 Forwards trip rept re 801124-25 meetings w/IL govt agencies & USOR re status of low level waste disposal at Sheffield facility.
SHAFFNER, J.A. Low Level Waste Licensing Branch. 81/01/12. 3pp.
07579:341.

8101280041 Notice of ABLB reconstitution. AC Goodhope, chairman, JR Kline & FJ Remick, members. Certificate of Svc encl.
COTTER, B.P. Atomic Safety and Licensing Board Panel. 81/01/22
4pp. 07555:092.

DOCKET 27-047 DARNWELL, SC., CHEM-NUCLEAR SYSTEMS

8101270118 Forwards Waste Packaging Insp Rept 15-000039/80-20 on 801106-07. No noncompliance noted.
STOHR, J.P. Region 2, Atlanta. Fuel Facility & Materials Safety Branch. 80/12/02. 1p. 07547:213

--8101270122 Waste Packaging Insp Rept 15-000039/80-20 on 801106-07. No noncompliance noted. Major areas inspected: licensee-shipper vehicle insp for compliance w/DOT & NRC regulations re shipping peger requirements & radiation levels.
MACARTHUR, T.C., POTTER, J.P. Region 2, Atlanta. Fuel Facility & Materials Safety Branch. 80/12/02. 5pp. 07547:214.

DOCKET 27-048 RICHLAND, WA., NUCLEAR ENGINEERING CO.

0101160120 Advises that Nuclear Engineering Co. Inc is changing name to US Ecology, Inc.
BAER, T.S. US Ecology, Inc. (Formerly Nuclear Engineering). 81/12/29.
1p. 07469:337.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP

8101070272 Trip rept of 800708-09 meetings w/State of CO & Union Carbide Corp in Denver. CO re alternative tailings mgmt study for Urven mill. Investigation to determine whether tailings ponds can be reclaimed underway.
PERSON, R. Uranium Recovery Licensing Branch. 80/12/12. 5pp.
07410:345.

8101290067 Response to vendor 801113 ltr refuting NRC 800805 comments re A-9 pit equifer tests. Long-term equifer pumping test in lower river aquifer, w/observation wells in Lower Wind River & Upper Wind River, is necessary. Specific comments encl.
LINEHAN, J.J. Uranium Recovery Licensing Branch. 81/01/09. 7pp.
07575:177.

DOCKET 40-0000 TRANSNUCLEAR, INC

8101200409 Application for license to import Specs are similar to Licensee BUf-1079, w/expiration date of 850731.
MATSON, V. Transnuclear, Inc. 00/12/23 1p 07486:316

DOCKET 40-1162 WESTERN NUCLEAR, INC

8101270044 Forwards "Magnetometer & Drilling Program Results at Western Nuclear's Split Rock Impoundment."
NELSON, J.O. Colorado State Univ. 80/11/10 1p. 07547:184

--8101270049 "Magnetometer & Drilling Program Results at Western Nuclear's Split Rock Impoundment."
NELSON, J.O., ROBINETTE, M.S. Colorado State Univ. 80/11/10 11pp.
07547:185

8101100015 Forwards Split Rock Mill tailings dam insp rept for 801110-16.
BODDEN, O. Western Nuclear, Inc. 80/11/26. 4pp. 07443:053

8101100021 Forwards Split Rock Mill tailings dam insp rept for 801117-23.
BODDEN, O. Western Nuclear, Inc. 80/11/26. 4pp. 07209:001

8101280536 Forwards Source Mat'l Licensee SUA-56.
SCARANO, R.A. Uranium Recovery Licensing Branch. 80/12/04. 1p.
07550:231.

--8101280540 Source Mat'l Licensee SUA-56, authorizing Western Nuclear, Inc. to possess byproduct mat'l in form of U waste tailings generated by licensee milling operations. Scope of work for hydrology study & decontamination guidelines encl.
SCARANO, R.A. Division of Waste Management. 80/12/04. 27pp.
07550:232.

8101270346 Forwards Split Rock mill tailings dam insp rept for 801201-07.
BODDEN, O. Westinghouse Electric Corp., Nuclear Energy Systems. 80/12/10. 4pp. 07546:169

8101120151 Forwards safety evaluation supporting renewal of Licensee SUA-56.
GARCIA, P.J. Uranium Recovery Licensing Branch. 80/12/15 1p.
07439:001.

--8101120154 Safety evaluation supporting renewal of Licensee SUA-56.
GARCIA, P.J., PETTENQILL, H. Uranium Recovery Licensing Branch. 80/12/04. 32pp. 07439:002.

8101270957 Forwards Split Rock mill tailings dam insp rept for 801215-21.
BODDEN, O. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 80/12/30. 4pp. 07549:170.

8101290200 Forwards safety evaluation in support of renewal of licensee SUA-56. Rept is provided in response to 800104 memorandum of understanding. W/b encl.
PETTENQILL, H.J. Uranium Recovery Licensing Branch. 81/01/02. 1p.
07575:216.

8101290054 Trip rept of 801110-12 visit to Split Rock U Mill re resistivity survey to be conducted for identification of seepage pathways from tailings impoundment.
GARCIA, P.J. Uranium Recovery Licensing Branch. 81/01/12. 2pp.
07575:111.

DOCKET 40-1241 EDOEMONT URANIUM MINE, TVA & MINES DEVELOPMENT, INC

8101050220 Notification of contract execution, Mod 2 to "TVA Edgemont Tailings Mgt Evaluation - Contractor Geotechnical Engineers, Inc.
WILKINSON, C. A. FIELDS, J. A. Technical Assistance Contracts Branch
FIN B-6994-D 80/11/15 1p 07383 219

--8101050234 Mod 2, extending period of performance of contract through 801231 at no addl cost to "TVA Edgemont Tailings Mgt Evaluation"
CASTRO, G. Geotechnical Engineers, Inc. DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN B-6994-D 80/11/15 1p 07383 220

8101090854 Requests consultation w/ assistance of OOI to further purposes of Endangered Species Act 1978 amend. List of possible endangered or threatened species in vicinity of proposed tailings disposal site desired
MILLER, H. J. Uranium Recovery Licensing Branch 80/12/10 1p 07439 063

8101270121 Lists endangered species which may be present at site & discusses actions to be taken by licensee.
BALYER, J. W. Interior Dept. of Fish & Wildlife Service. 80/12/22 2pp 07547 045.

8101270193 Responds to FOIA request for four categories of documents
Forwards documents listed in App A. NRC could not locate documents re items 2 & 3
FELTON, J. H. Division of Rules and Records 81/01/19. 2pp. 07543 221

--8101270217 Requests that JC Gilliland, EE Evans & RF Bell be deleted as occupational medical & radiation consultants from licenses
SUA-816, SUA-652 & SUA-160 Svcs were terminated as of 751001
ML Hudson 750707 ltr ercl
BELL, R. F. Bell, R. F. MO 75/11/24 2pp

--8101270231 Summarizes preliminary results of more detailed radiation monitoring program recently completed at facility. Includes info re offsite radiation levels at Edgemont, SD until 1/4/80
results Minutes of EPA 760728 meeting w/IVA and
GILLELAND, J. E. Tennessee Valley Authority 76/05/17 13pp

--8101270234 Forwards "Semiannual Effluent Release Rpt 3. Jul-Dec 1976"
GILLELAND, J. E. Tennessee Valley Authority 77/02/25 1p

--8101270242 "Semiannual Effluent Release Rpt 3. Jul-Dec 1976."
* Tennessee Valley Authority Rtr-77-2-ED-1 76/12/31 13pp.

--8101270251 Forwards "Semiannual Effluent Release Rpt 2. Jan-June 1976"
GILLELAND, J. E. Tennessee Valley Authority 76/08/26 1p.

--8101270255 "Semiannual Effluent Release Rpt 2. Jan-June 1976" - Undated
versions of quarterly monitoring repts from 1974 to present
encl
* Tennessee Valley Authority 76/08/26 242pp

DOCKET 40-2061 WEST CHICAGO FACILITY, KERR-MCGEE CORP

8101050618 Discusses need for long-term solutions to site-related problems re project EPA anticipates responding to draft EIS upon release
MCQUIRE, J. Environmental Protection Agency 80/11/13 1p 07391:050

8101130005 Requests OOI assistance in evaluating presence of endangered species in plant area in response to vendor decommissioning plan
NIXON, W. A. Uranium Fuel Licensing Branch 80/11/13. 2pp 07308:001.

8101100252 Forwards response to 791003 "Info Required for Commission Approval of Treatment of Disposal by Incinerations"
SHELLEY, W. J. Kerr-McGee Corp. 80/12/05 8pp 07443 266

8101130537 Inform of problems associated w/site decommissioning, such as Areas Crest contamination, use of waste send as offsite
1111 natl & radioactive natl leaching to groundwater
Requests info on EIS currently being prepared
SUMMERLEE, K. L. Environmental Protection Agency 80/12/12 2pp. 07454:141

8101290535 Clarifies apparent anomalies found in stabilisation plan to license 87A-0583 High radium anomaly in Table 3.2 3g caused by coal ash spread on surface of tailings pile Table 2 was calculated to include total fugitive dust generation
SHELLEY, W. J. Kerr-McGee Corp 80/12/23 2pp 07575.293

8101290145 Confirms 810106 response to NRC 801212 request for info re EIS for decommissioning of site EIS will not address thorium residuals NRC is developing federal position re responsibilities for contamination in unrestricted areas
CRDW, W. T. Uranium Fuel Licensing Branch 81/01/14. 2pp 07575.194

DOCKET 40-2259 PATHFINDER MINES CORP

8101250289 Forwards monitoring data from Lucky Mc mill per 801114 request info includes airborne radiation monitoring, radon daughter monitoring for Jan 1979-Oct 1980 & personnel monitoring including bioassays for 1978-1980.
PDVEER, R. W. Pathfinder Mines Corp 80/11/19 500pp 07056 082

8101270581 Forwards revised mill organization chart reflecting administration change discussed per 000612 ltr
MUGENT, E. L. Pathfinder Mines Corp 81/01/23 2pp 07548 058

DOCKET 40-3392 ALLIED CHEMICAL CORP

8101100256 Informs that low level redwaste disposal permit was reinstated per encl State of NV 001202 ltr
CIPOLLA, A. J. Allied Chemical Corp 80/12/11 2pp. 07443.280

DOCKET 40-3453 ATLAS MINERALS

8101100225 Lists items for discussion at 801211 meeting in Washington DC includes future storage of tailings, seepage study, surety, license Condition 11 & 801003 FR regulations
SWANBY, G. T. Atlas Minerals 80/12/01 1p 07443 001.

8101060926 Requests that T Johnson participate in 801211 meeting w/Atlas Minerals re riprap requirements for Moab project
SCARANO, R. A. Uranium Recovery Licensing Branch 80/12/03. 1p 07401 103

8101060693 Responds to 801024 ltr re water & seepage. Visual check of river bank in Oct did not reveal seepage outflow to substantiate higher velocity statements contained in NRC 801024 ltr
SWANBY, G. T. Atlas Minerals 80/12/08 6pp 07400 183

8101210197 Advises that response to NRC 801125 ltr could not be submitted by 801208 due to late arrival of ltr. Items have been discussed previously. Audit results of environ monitoring & reporting procedures available late Jan 1981
SWANBY, G. T. Atlas Minerals 80/12/08 1p. 07488.328

8101280203 Forwards "U Feasibility Preliminary Hydrological Study for Design of Dewatering Sys for Atlas Minerals Tailings Pond, Moab, UT."
SWANBY, G. T. Atlas Minerals 80/12/12 2pp (07187:001.

--8101280210 "U Feasibility Preliminary Hydrological Study for Design of Dewatering Sys for Atlas Minerals Tailings Pond, Moab, UT."
FORDES, B. Solution Engineering, Inc 79/05/31 21pp 07187.001

8101290249 Forwards portions of radon rept sent to Archaes Natl Park to put original numbers for sampling & analysis in perspective.
DOUGLASS, T. R. Utah, State of 80/12/30 5pp 07569:357.

8101290259 RO on 810102 fire occurred in yellowcane scrubber stock P extinguished in 15 minutes. Cause unknown. Operations in area suspended. Air sampling conducted. Employees will submit urine samples for concentration evaluation
* Atlas Minerals 81/01/02 2pp 07569 362

8101290043 Documents review of licensee semiannual monitoring repts. Data required under License Condition 37 was not collected. Vendor must submit data or provide justification for omission.
GARCIA, P. J. Uranium Recovery Licensing Branch 81/01/07. 1p 07572 351

8101290031 Forwards formal responses to 001208 submittal & request for addl info & detailed outline of proposed hydrologic study to be performed at site Drill hole info & documented inflow & outflow quantities required
LIFEHAY, J. J. Uranium Recovery Licensing Branch 01/01/12 3pp
07570 399.

8101290402 Requests amend fee for 801103 application Failure to respond will indicate that application has been abandoned
WELSH, D. License Fee Management Branch 01/01/16 1p 07560 361

DOCKET 40-3690 BELL

8101270193 Responds to FOIA request for four categories of documents. Forwards documents listed in App A HRC could not locate documents re items 2 & 3
FELTON, J. M. Division of Rules and Records 01/01/15 2pp
07543 221.

8101270217 Requests that JC Gilliland, EE Evans & RF Bell be deleted as occupational medical & radiation consultants from Licensee SUA-616, SUA-652 & SUA-160 Svcs were terminated as of 751001
KL Hudson 750707 ltr encl
BELL, R F Bell, R F MO. 75/11/24 2pp

DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MINING)

8101070311 Forwards Category 2A fee for minor amend to License SUA-667
ANDRUS, N J Federal American Partners 00/12/01 1p 07415 214

DOCKET 40-5977 BELL

8101270193 Responds to FOIA request for four categories of documents. Forwards documents listed in App A HRC could not locate documents re items 2 & 3
FELTON, J. M. Division of Rules and Records 01/01/15 2pp

8101270217 Requests that JC Gilliland, EE Evans & RF Bell be deleted as occupational medical & radiation consultants from Licensee SUA-616, SUA-652 & SUA-160 Svcs were terminated as of 751001
KL Hudson 750707 ltr encl
BELL, R F Bell, R F MO. 75/11/24 2pp

DOCKET 40-6439 NEW MEXICO UNIV OF

8101070592 Forwards IE Info Notice 00-32. Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials "No written response required
ENIEZEK, J. H. Division of Fuel Facility & Materials Safety 00/08/29 1p 07415 333

DOCKET 40-6622 PATHFINDER MINES CORP

8101200019 Expresses opposition to Amend 2 to License SUA-442. Mine has not been guilty of any willful violation Jeopardy to public health, interest or safety has not been shown.
RUBBELL, J. E. Pathfinder Mines Corp 00/12/05 2pp 07497 007.

8101200635 Notifies that Amend 2 to License SUA-442, issued on 001121, should be exempt from license fee
MEYER, R. B., LINEMAN, J. Uranium Recovery Licensing Branch 00/12/29 1p. 07550 291

DOCKET 40-7869 PLATEAU RESOURCES, LTD.

8101220301 Forwards organization chart. Primary contact is UK Gupta, process manager. Secondary or alternate contact is K Jackson, licensing coordinator.
HEAD, W. J. Plateau Resources, Ltd 01/01/15 1p 07309 001.

DOCKET 40-8003 GENERAL ELECTRIC CO

8101290628 Discusses IE Insp Rept 40-8003/80-01 conducted on 801027. No non-compliance noted. Major areas inspected: activities re radiation safety, including examination of procedures, records & personnel interviews.
KINNEHAN, J. D. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/12/04 1p. 07571 327.

DOCKET 40-8027 KERR-MCCOY CORP

8101407940 Confirms discussion re applicability of Condition 13 of License SUB-1010 to existing Pond 2. Condition 13 requires that no addl process wastes to added after 801231
CRUICK, W. F. Uranium Fuel Licensing Branch 01/01/02 1p 07458 1

DOCKET 40-8084 LEBBON MINE, RIO ALGON CORP

8101290580 Summary of 801114 meeting w/vendor re 40CFR190 order amending all licenses & Amend 4 to License SUA-1119 updating environ monitoring program
KIDGLEY, J. L. Uranium Recovery Licensing Branch 00/12/21 3pp
07575 174

8101150931 Responds to 001028 ltr re notice of violation & notice of proposed imposition of civil penalties & forwards order imposing civil monetary penalties. Addl info re noncompliance requested
SIELLO, V. Director's Office, Office of Inspection and Enforcement 01/01/13 2pp. 07465 037

8101150935 Order imposing civil monetary penalties in amount of \$ based on item of noncompliance re inadequate surveys to assure against recurrence whenever intake of U ore dust by any individual exceeded 40-h control measure
SIELLO, V. Director's Office, Office of Inspection and Enforcement 01/01/13 12pp 07469 039

8101200141 EN-80-48A; notice of violation & notice of proposed imposition of civil penalties to be issued to license SUA-1119. Action based on alleged noncompliance re failure to evaluate contamination on workers prior to departure.
BROCKETT, T. M., THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 01/01/13 1p 07487 036

DOCKET 40-8200 CLEVELAND-CLIFFS IRON CO

8101290547 Forwards North Huling Pin restoration project wastewater analytical rept. All drums showed exposures of less than 0.01 ppm/hr. Drums will be stored in warehouse in Casper, WY pending approval of disposal at Gelly-Petrotonics U mill
LOUDERBACK, T. C. Cleveland-Cliffs Iron Co 00/12/22 3pp
07309 001

8101290653 Requests appropriate action re unauthorized transfer of solution mining tailings from site to Casper, WY warehouse
SCARANO, R. A. Uranium Recovery Licensing Branch 01/01/07 1p
07573 347

8101290070 Requests approval for disposal of 12 drums of waste in Gelly-Petrotonics U mill tailings pond Gelly-Petrotonics
B01113 approval of request encl.
LOUDERBACK, T. C. Cleveland-Cliffs Iron Co 00/11/10 4pp
07573 348

DOCKET 40-8304 WYOMING MINERAL CORP

8101290552 Forwards initial baseline analysis for wells located in test area. Info constitutes basis for establishment of action levels for monitor wells B17-M-1, M-2, M-3, M-4, M-5, M-6 & USHF M-21B through M-221
WICKERS, D. L. Wyoming Mineral Corp. 00/12/22 3pp 07575 268

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO

8101290539 Forwards results of Dec 1980 sampling of Patterns 3 & 4 monitor wells. Analysis of assay results shows that all parameters below U control limit on Pattern 4 wells. Pattern 3 wells show elevated levels of U & vanadium
NEUMAN, H. R. Rocky Mountain Energy Co 00/12/29 7pp 07309 001

8101290666 Forwards "Semiannual Effluent Monitoring Rept. Jul-Dec 19 Data supports conclusion that leaching operation has not caused negative impact in unrestricted areas adjoining property
SPIELER, P. R. Rocky Mountain Energy Co 01/01/21 4pp 07597 1

DOCKET 40-8452 BEAR CREEK URANIUM CO

8101100144 Forwards semiannual rept for Jan-June 1900
DUGGSON, J. H. Bear Creek Uranium Co 00/12/04 1p. 07441 338

economic of U tailings Rgt Assessment of conformance with
technical criteria & list of disposal options encl
LA-23; E.A. Rocky Mountain Energy Co 80/12/19 8pp 07575:232

DOCKET 40-8502 IRIGARAY MINE, WYOMING MINING CORP

B101270506 Submits status of excursion in shallow monitor wells Four
probable leaders discovered out of 200 coils tested Thirty
wells remain to be tested
HARROLD, D Wyoming, State of 79/06/21 1p 07576:140.

B101270601 Requests that pumping of injection Well C13 be discontinued.
pending discussion at 790814 meeting Addl pumping may
increase area groundwater sink Related info encl
HARROLD, D Wyoming, State of 79/08/08 3pp 07576:137

B101250115 Affidavit re company 790709 request that electrical logs,
geological cross-sections & Hydrology Associates regt be
kept confidential
EISENBARTH, W A Wyoming Mineral Corp 79/08/13 3pp 07309:001.

B101270109 Confirms extension until 790910 to correct shallow monitor
well excursion in Well SM-6 & grants 790810 request for
extension to prepare annual rept Requests addl info to
evaluate excursion
HARROLD, D Wyoming, State of 79/08/23 12pp 07309:001.

B012180067 Forwards "Irigaray Mine Site First Quarterly Rept. Jul-Sept
1980."
WICKERS, D L Wyoming Mineral Corp 80/11/11 2pp 07244:001

--B012180073 "Irigaray Mine Site First Quarterly Rept. Jul-Sept 1980 "
Thres oversized drawings encl
* Wyoming Mineral Corp 80/09/30. 200pp

B101270744 Forwards Casing Integrity Test Procedure, REP-80-626.
CHURDY, B W Wyoming Mineral Corp 80/12/16 1p 07549:151

--B101270749 Casing Integrity Test Procedure, REP-80-626
* Wyoming Mineral Corp 80/12/16 1p 07549:152

B101280629 Requests addl info re casing integrity test procedure
(REP-80-627) Test pressures, max acceptable leakage rates &
procedures to be followed in event of unacceptable leakage
must be specified.
MARTIN, D E Uranium Recovery Licensing Branch 81/01/12 2pp
07550:288

DOCKET 40-8511 COTTER CORP

B101200390 Source Mat'l License SUA-1273 for Urenco-USA, Inc. authorizing
research & development of U solution mining & recovery
operation
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 76/08/13
1p. 07187:001

DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO

B101100129 Forwards revised format for QA program for U in urine
samples superseding B0C827 ltr.
ACOSTA, A P Minerals Exploration Co (subs of Union Oil Co of
California) 80/11/20 1p 07441:331

--B101100134 QA program for U in urine samples, revised format.
* Minerals Exploration Co (subs of Union Oil Co of California)
80/08/31 3pp. 07441:332

B101090462 Responds to NRC telcon re leak in tailings pond liner
Measures to mitigate leak effects & monitor surrounding
wells discussed Underdrain test sys will be sampled daily.
Liner Installer will inspect soon on B10105
SNYDER, H L Union Minerals. 80/12/31 2pp 07442:263.

B101290448 Confirms B01231 telcon re leak in tailings pond liner. Pond
liquid sampled & undergoing analysis Increased monitoring
schedule established for wells surrounding pond Seem will be
inspected B10105
SNYDER, H L Union 76 Minerals Exploration Co 80/12/31 2pp
07570:340

B101210327 Forwards interim rept submitted to WY Dept of Environ
Quality on B10105
SNYDER, H L Union Minerals 81/01/06 3pp 07487:244

B01280631 Authorities payment for R Williams travel costs & prof svc
re site visits to Sweetwater & Teton projects on 010109-12
SCARANO, R A Uranium Recovery Licensing Branch 81/01/07 1p
07550:290

B101270610 Advises of Sweetwater U Mill B10223 startup
SNYDER, H L Union 76 Minerals Exploration Co 81/01/21 1p
07349:066

DOCKET 40-8589 WYOMING MINERAL CORP

B101060146 Informs that WY Mineral Corp submitted info re stack
emissions for Jan-Jul 1980 Emissions considered within
acceptable limits
MEYER, R S Uranium Recovery Licensing Branch 80/12/04 1p.
07399:086

DOCKET 40-8647 FLINCHBAUGH PRODUCTS, INC

B101290620 Discusses IE Insp Rept 40-8649/80-01 conducted on B01031
noncompliance noted Major areas inspected activities re
radiation safety, including examination of procedures &
records, personnel interviews & selective measurements
KIN, EMAN, J D Region I, Philadelphia, Fuel Facility & Materials
Safety Branch 80/12/03 1p 07571:326

DOCKET 40-8674 PLATEAU RESOURCE

B101220301 Forwards organization chart Primary contact is UK Gupta,
process manager Secondary or alternate contact is K Jackson,
licensing coordinator
HEAD, W J Plateau Resources, Ltd 01/01/15 1p 07309:001.

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC

B101100023 Forwards map per B01203 telcon confirming that historic
referenced in memorandum of agreement has not been affected
by project
BAKER, C E Energy Fuels Nuclear, Inc 80/12/03. 2pp 07443:05

B101270028 Lists steps to ensure continuity & satisfactory completion
of archeology studies Licensee & contractors shall complete
1979-80 excavations as detailed in NRC 790409 ltr
SCARANO, R A Uranium Recovery Licensing Branch 81/01/14 3pp.
07570:356

B101290095 Notifies of NRC plans to modify memorandum of agreement
mitigation of adverse effects of project Addl Condition 11
will insure involvement of dept in determination of
acceptability of contractors & labs
SCARANO, R A Uranium Recovery Licensing Branch 81/01/14 5pp.
07575:184

DOCKET 40-0693 OGLE PETROLEUM, INC

B101220596 Forwards quarterly rept. Aug-Oct 1980, for pilot R&D in sl
U solution mining operation in Bison Basin area of WY.
BAUNDERS, O A, CATCHPOLE, O J Ogle Petroleum, Inc. 80/12/04 7
07309:031

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO

B101280061 Forwards "Semiannual Effluent Monitoring Rept. Jul-Dec 19
Data supports conclusion that leaching operation has not
caused negative impact in unrestricted areas adjoining
property
SPIEGEL, P R Rocky Mountain Energy Co 81/01/21. 4pp. 07557:1

B101300438 Submits quarterly rept for Oct-Dec 1980.
ZEMMEL, M R Rocky Mountain Energy Co 81/01/23. 9pp 07586:3

DOCKET 40-0693 PLATEAU RESOURCES, LTD.

B101120184 Requests followup embankment const insp at Plateau Resources Shooting Canyon site Preliminary indication is that at least one violation has occurred
SCARANO, R A Uranium Recovery Licensing Branch. 00/12/17. 1p 07439.361

B101220301 Forwards organization chart. Primary contact is UK Oupha, process manager. Secondary or alternate contact is K Jackson, licensing coordinator
HEAD, W J Plateau Resources, Ltd 81/01/15 1p 07309.001

DOCKET 40-8707 ENVIRONMENTAL SYSTEMS, INC

B1012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records. 00/11/21 5pp

--B1012100351 Requests payment of new fee re review of 700927 license application. Payment is due whether or not license is still requested & should be made within 30 days.
MILLER, W O License Fee Management Branch 80/02/07. 1p.

DOCKET 40-8712 OULF OIL CORP

B1012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records. 80/11/21 5pp

--B1012100220 Requests partial refund of fee due Oulf Research & Development Co in connection w/withdrawal of application for license. Lists actual manhours required for review & amount of refund due
MILLER, W O License Fee Management Branch. 79/06/26. 1p.

DOCKET 40-8724 CHEMTRON CORP.

B101200122 IE Insp Rept 40-0724/80-01 on 800617-18, 0902-05 & 18-19. No noncompliance noted. Major areas inspected: Rooms C, D, E & F in Dldg 21 at McLean Facility. Facility meets criteria for release to unrestricted use
BRENIANBK1, D J Region 3, Chicago, Office of the Director
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/11/14 21pp.

DOCKET 40-8728 IETON EXPLORATION DRILLING CO., INC.

B101100026 RD on B101031, water noted in leak detection sys for north & south ponds. South pond leakage caused by liner damage during sprinkler float placement. North pond leaks only at high water level.
United Nuclear Corp 80/12/04 10pp 07443.042.

B101290343 Forwards B101210 leak insp rpt re WY R&D Testing License 2RD. After receiving estimate of water lost, better estimation of need for monitoring well in down gradient direction can be made
MATHISEN, R L Wyoming, State of. 80/12/30. 5pp. 07309.001.

DOCKET 40-8743 CONOCO

B101090866 Confirms schedule impacts resulting from efforts to evaluate Agreement Bitesse revised programs. Conoco, Inc. application review will be delayed & may necessitate contract extensions for technical assistance
HAMILL, K Uranium Recovery Licensing Branch. 80/12/10. 1p. 07428.359.

B101270328 Advises that encl Advisory Council on Historic Preservation B101030 ltr re cultural clearance for project is being forwarded to NRC. No entries exist in Natl Register for Campbell County, WY
QUIGLEY, T. W. CONOCO, Inc. (Continental Oil Co. I. 80/12/10. 2pp. 07546.176.

B101270979 Forwards Sand Rock mill project environ rpt. D Tipton 001125 & W Tomlinson 001118 requests for rpt encl. W/o rpt.
QUIGLEY, T. W. CONOCO, Inc. (Continental Oil Co. I. 80/12/16 3pp. 07549.199.

DOCKET 40-0768 KERR-MCGEE CORP

B101100162 Forwards responses to questions re SPRB O Sand Project research & development license as requested in B101024 telcon.
SHELLEY, W J Kerr-McGee Nuclear Corp 80/12/05 15pp 07441.341

DOCKET 40-8771 NUCLEAR ASSURANCE CORP

B101270321 Advises that response to NRC B101121 ltr requesting addl info re license application cannot be met by B101219 Response will be forwarded upon completion of response to State of WY
WARD, R Nuclear Assurance Corp 80/12/09 1p 07546.175

DOCKET 40-8778 IETON EXPLORATION DRILLING CO., INC

B101210369 Forwards quarterly operating rpt for Oct-Dec 1980
RICE, S. M., HILDEBRAND, P., HERLIHY, D. M. Ieton Exploration Drilling Co., Inc 81/01/09 5pp 07487.127

--B101210370 Quarterly operating rpt for Oct-Dec 1980
Ieton Exploration Drilling Co., Inc 81/01/09 40pp 07487.132

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-33 INDIAN POINT STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants. CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B101002 & by applicants as part of F&AR
EISENHUT, D. O. Division of Licensing. 80/11/13 2pp 07422.243

B101070250 Requests that oncl emergency planning info be made public available. W/o encl
SQUER, J. L. Division of Rules and Records. 80/12/17 1p 07414.297.

B101230589 Forwards security plan mods. Mods withheld (ref 10CFR2.790)
QUIGLEY, J. D. Consolidated Edison Co. of New York 81/01/16 1p 07515.249.

P. Operating license stage documents & correspondence

B101100537 Ltr to all power reactor licensees & applicants forwarding summary of B100827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl
EISENHUT, D. O. Division of Licensing. 80/10/06 6pp

B101109254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under B18 license amend application adding model leak Specs to App A should be submitted within 120 days
EISENHUT, D. O. Division of Licensing. 80/11/20 1p. 07443.274.

--B101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-1 B75 snubber inservice insp requirements
Division of Licensing. 80/11/20. 10pp. 07443.278

B101060420 Corrects B101124 FR notice. Effective date should be B10217
EISENHUT, D. O. Division of Licensing. 80/11/25 1p. 07397.361

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B10112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing. 80/11/26 8pp. 07501.234

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B10112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing. 80/11/26 8pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B10112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing. 80/11/26 8pp.

--B01220516 Summary of B01120 meeting w/EPRI licensees & consultants re inclusion of linear elastic fracture mechanics in resolution of Unresolved Safety Issue A-12 Attendee list encl
BNA10ER.R Generic Issues Branch 80/11/25 7pp 07501 23A

B01040906 Informs of NRC activities re basis for license application review scheduling & manpower & resource allocation planning
Applications & reviews which will be submitted by 1983 should be identified
T-OMP504.H.L Resource & Scheduling Branch 80/12/05 13pp
07401 071

B01210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notices of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
E15E44J1.O.O Division of Licensing 80/12/15 13pp 07489 087

B01120003 Responds to B00903 ltr re decommissioning of facility power reactor authorization for decommissioning allowed only after applicant demonstrates that dismantling & disposal of components will follow NRC guidelines Draft reply encl
DEH10.H.R Office of Nuclear Reactor Regulation, Director.
80/12/16 5pp 07447 098

--B01013004 Requests NRC response to Con Ed proposal to evade NRC atdc for decommissioning reactors & leave site as is through Yr 2006 legislation ltr to colleagues encl
BR005KY.R.L Westchester County,NY 80/09/03 5pp 07447 101

G Inspection reports, IE Bulletins & correspondence

B01200143 forwards IE Insp Repts 50-003/80-02 & 50-247/80-14 on B00903-04 No noncompliance noted
SMITH,D.H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/10 2pp 07583 105

--B010130151 IE Insp Repts 50-003/80-02 & 50-247/80-14 on B00903-04 No noncompliance noted Major areas inspected radiological monitoring sys including monitoring equipment & support facilities in emergency operations facility
JACKSON,T.J Region 1, Philadelphia, Office of the Director
B0RES,H.J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/24 7pp 07593 107

B01060890 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Yarny Turbine Steam Inlet Flange" No written response required.
GR1ER,B.H Region 1, Philadelphia, Office of the Director.
80/11/26 1p 07396 342

B01060851 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
GR1ER,B.H Region 1, Philadelphia, Office of the Director
80/12/16 1p 07377 005

R Periodic operating reports & related correspondence

B01230582 Forwards tabulation of daily record of fish collections for Dec 1980
O'TOOLE,J.D Consolidated Edison Co of New York. 81/01/15 5pp
07510 279

T Hearing transcripts on non-antitrust matters

B01120285 Commission declassification releasing transcript of B01210 discussion of Indian Point enforcement action
CHILK,B.J Office of the Secretary of the Commission. 80/12/19 2pp 07438 132

--B01120288 Married-up transcript of B01210 closed discussion of Indian Point enforcement action Pp 1-77 Supporting documentation encl
& Commissioners 80/12/10 67pp 07438 134

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

B01200419 Submits info re cost of providing add criticality monitoring sys at facility Requests 2-yr exemption from code requirements
LEVINE,B.H Pennsylvania State Univ 81/01/23 2pp. 07587 002

DOCKET 50-6 DANIELLE MEMORIAL INST RESEARCH REACTOR

O Inspection reports, IE Bulletins & correspondence

B01180777 Forwards IE Insp Repts 70-C008/80-02,30-05728/80-02 & 50-C06/80-01 & notice of violation
HEPPLER,J.O Region 3, Chicago, Office of the Director 80/12 2pp 07444 062

--B01180783 Notice of violation from Insp on B00922-26 & 1112
HEPPLER,J.O Region 3, Chicago, Office of the Director 80/12 1p. 07444 064

--B01180781 IE Insp Repts 50-006/80-01,70-0008/80-02 & 70-05720/80-02-26 & 1112 Noncompliance noted overexposure of one individual to external radiation & excess radioactivity concentrations in fuel storage pool
PECK,C.C Region 3, Chicago, Office of the Director F18HER
Region 3, Chicago, Fuel Facility & Materials Safety Branch
80/11/29 10pp 07444 069

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B01090087 Ltr to all licensees of operating reactor plants,CP No & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of FSAR
E15E44J1.O.O Division of Licensing 80/11/13 2pp.

O Adjudicatory correspondence

B012110423 Requests that NRC establish licensing board to consider request for license amendments to carry out chemical cleaning of primary coolant sys NRC should allow cleaning to proceed prior to hearings on basis of safety evaluation
GLEPICE,P Isaac, Lincoln & Beale 80/12/03 2pp 07227 130

B01180288 Order requiring NRC applicant & petitioners to file a info on license not re proposed decontamination before Commission rules on B00708 petition to hold hearing of AF Akeeme dissenting views & Certificate of Svc encl
CHILK,B.J Office of the Secretary of the Commission 81/01/14pp 07470 345

M General correspondence

B01220439 FOIA request for four categories of documents re decontamination of facility
GOLDSMITH,R Citizens for a Better Environment 80/11/05 1 07301 166

B01200672 Oppose facility flushout w/corrosive solvent Certificate of Svc encl
FERKME,R.E Affiliation Unknown 81/01/11 3pp 07486 344

B01290518 Advise that future correspondence should be addressed to IL Dept of Nuclear Safety,1035 Custer Park Drive,5th Floor Springfield,IL 62704
WRIGHT,C.H Illinois, State of 81/01/22 1p 07566 357

J Insurance & indemnity information

B01090608 Forwards guarantee of payment of deferred premiums for OSTER,J Commonwealth Edison Co 01/01/05 1p 07442 073

B01270619 Forwards Endorsements 125 & 126,65 & 66,53 & 54, & 13 to MELIA Policies NF-43,NF-187,NF-201 & NF-253, respectively
OSTER,J Commonwealth Edison Co 81/01/21 13pp 07183 001

B01270737 Forwards Endorsement 4 to Binders EB-1,EB-2,EB-3,EB-4,EB-30,EB-42 & EB-43 evidencing secondary financial protection
OSTER,J Commonwealth Edison Co 81/01/21 0pp 07309 001

D Advisory Committee on Reactor Safeguards reports & correspondence

B01200837 Certified minutes of ACRS Subcommittee on Dresden Nuclear Station,Unit 1 B01008 meeting in Washington,DC re facility,decontamination Visographs encl
* ACRS - Advisory Committee on Reactor Safeguards 80/11/21 07356 002

7911270339 Forwards revised pages re proposed amend to Tech Specs in support of primary sys chemical cleaning Fee encl
PEOPLES, D L Commonwealth Edison Co. 79/11/14 3pp. 01349 117

--7911270340 Revised pages to proposed amend to Tech Specs in support of chemical cleaning of primary sys
* Commonwealth Edison Co. 79/11/14 3pp 01399 119.

8010140126 Submits addl SEP topics to be added to NRC 791116 list for deletion from plant review. Items removed are not applicable to facility or are being reviewed as generic issue Revised listing of DBE accident & transient groups encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/11 3pp 06707 080

801220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

801220437 Responds to FOIA request for four categories of documents re decontamination of facility Forwards documents listed in App A Addl documents are available in PDR & in LPDR Morris, IL.
FELTON, J M. Division of Rules and Records. 80/11/28 3pp 07301 163

--8009190849 "Chemical Cleaning Licensing Submittal."
* Commonwealth Edison Co 01S-NR-01-012. 79/04/14 106pp 03560 106

--801220448 Forwards "Evaluation of Dresden I Chemical Cleaning Licensing Submittal." Approves cleaning operation pending review of completed test program results before cleaning begins & formulation of acceptable preservice insp program.
MACCARY, R R. Division of Reactor Licensing (NRR-1975 only) 79/06/27. 2pp.

--801190372 "Evaluation of Dresden I Chemical Cleaning Licensing Submittal."
* Materials Engineering Branch 79/06/20 9pp 03627 044

--801001003 Forwards addl questions required to complete review of Dow Chemical Co repts on technical study for chemical cleaning of facility
SHAG, L C. Engineering Branch (Pre 791030). 77/10/27. 4pp 03619 307

--8010280823 informs that chemical cleaning licensing submittal reviewed
Decontamination program as proposed releases no effluents to environ & solid wastes produced are similar in type & quantity to wastes handled routinely at plant site.
YOUNGBL, OOD, B. Assistant Director for Environmental Projects 79/06/29. 1p 03402 174

--7904040095 Responds to 790216 memo Steff did consider SRP 11.4x ETRR 11-3 in review of proposed solidification sys for chemical decontamination. Since amend addressed special decontamination program, SRP & RTP were not addressed.
WILCHISON, O W. Environmental Evaluation Branch (Pre 790625) 79/03/13. 2pp 03663 224

--7905230626 Reviews general design criteria for nuclear power plants for facilitation of operating plant decontamination or minimization of radioactive buildup on reactor plant surfaces. IM H & B 3-31
HITT, F J. Fuel Process Systems Standards Branch. 79/03/21. 13pp.

--801220449 Draft safety evaluation supporting 791114 application for amend to License DPR-2, requesting changes to Tech Specs to delete requirements for primary containment integrity during chemical cleaning of primary coolant sys
* Office of Nuclear Reactor Regulation, Director. 79/12/31 3pp.

--801220436 Proposed changes to Tech Specs 3 D.4 7.3 B & 4.8 re limiting conditions for operation & surveillance requirements, deleting requirements for primary containment integrity during cleaning of primary coolant sys
* Commonwealth Edison Co 79/12/31 3pp

02585 111
--8010170702 Forwards request for addl info re decontamination of Facility Response to questions required to complete evaluation
GRUBBS, O X Environmental Evaluation Branch (Pre 790625) 77/12/05 13pp. 03650 257.

--8010090608 Requests review of BNWL rept on chemical cleaning Com required by 780928
CHALINA, O Environmental Evaluation Branch (Pre 790625) 78/09/07 1p 03507 001

--8010090609 Forwards working draft rept on chemical cleaning. Rept currently undergoing review & revision at lab Requests comments
MOENES, O R Battelle Memorial Institute, Pacific Northwest Laboratory 78/08/24 22pp. 03507 001

--7809210151 Discusses decision against revising draft PNL rept on chemical cleaning at facility. Revision would not have significant impact
KREGER, W E Radiological Assessment Branch. 78/09/11 1p

801030555 Confirms proposal made by SEP owners group at 801202 meeting w/NRC increased involvement in SEP completion will be made Presentation met used in meeting encl
SCHIAFFSTALL, R. Kerr-McGee Chemical Corp (subs of Kerr-McGee Co) 80/12/05 12pp 07390 144

801190113 Ltr to all BWR licensees forwarding 801201 generic safety evaluation re BWR screen discharge sys Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes
EISENHUT, D O Division of Licensing. 80/12/09. 2pp. 07103 001

--801190141 Generic safety evaluation re short-term actions required to assure continuous safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl
* Division of Licensing. 80/12/01. 212pp. 07103 001

801070594 Forwards safety evaluation of SEP Topic 11-2 A. "Severe Weather Phenomena" & TX Tech Univ rept, "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Site, IL."
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 7pp 07404 289

--801070608 "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Site, IL."
MCDONALD, J R Texas Tech Univ NRC-04-76-345 80/05/31 26p 07404 296

801140047 Requests info re SEP Topic 1V-2, reactivity control sys design & protection against single failures Info should be provided within 90 days of receipt of ltr
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15. 4pp 07458 210

801210445 Forwards responses to questions on Rule 80.710. "Period Updating of FSAs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp

801160029 Notification of 801210 meeting w/SEP owners group in Bethesda, MD re SEP program schedule for licensee topic completion & assignment of lead topics to plants
RUESSELL, W T Technical Support Branch 80/12/16 2pp 07466 V.

801230339 Forwards listing of all SEP correspondence re Facility SEP owners group 801202 meeting List provides basis upon which to determine plant status Review & comments requested.
N/A encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/22 3pp 07512 092

801080141 Forwards 26 revised electrical drawings for HPCI sys addition Aperture cards in PDR
WHEECE, R F Commonwealth Edison Co 80/11/29 3pp 07512 001

B101050500 Forwards response to IUREG-0737 No response provided for Dresden 1 Unit undergoing extensive rod & decontamination outages Requirements of IUREG-0737 will be addressed prior to startup of unit scheduled for June 1986
ABEL, J S Commonwealth Edison Co 80/12/31 55pp 07385 211

B101300842 "Adequacy of Station Electric Distribution Sys Voltages, Dresden Station, Unit 1." Informal rept
UDV, A C EG&O Idaho, Inc FIN A-6256 B101300842 80/12/31 14pp 07584 319

B101090301 Forwards Revision 15 pages to CE-1-A-0A program topical rept. Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
ABEL, J S Commonwealth Edison Co 81/01/02 1p 07441 007

--B101090305 Revision 15 pages to 0A program topical rept
* Commonwealth Edison Co. CE-1-A R15. 81/01/02 52pp. 07441 008

B101300470 Responds to B01114 ltr re alleged water loss from rept. Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
SCOTT, O J Commonwealth Edison Co 81/01/11 3pp 07586 265

B101220368 Forwards offsite dose calculation & description per meteorological data requirements in NUREG-0737 Task 111 A 2
DELCORGE, L O Commonwealth Edison Co 81/01/19 1p 07497 014

--B101220374 "Offsite Dose Calculation By Meteorological Monitoring, Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants." Revision 2
COLEMAN, J C Commonwealth Edison Co BRADLEY, J P Murray & Trettel, Inc LAHTI, R P Sargent & Lundy, Inc 80/07/31 130pp 07497 015

--B101220379 "Study of Low Level Dispersion Over Northern IL"
* Murray & Trettel, Inc 74/06/30 106pp 07497 159

--B101220391 0A program for meteorological monitoring programs, Revision 2
MURRAY, J H Murray & Trettel, Inc 79/12/05 34pp 07497 264

B101260597 Forwards until B01126 revision of facility electrical drawing index & carried-up version of NRC index of drawings indices available in Central Files only
JANECEK, R F Commonwealth Edison Co 81/01/19 1p 07519 029

B101290786 Ack receipt of B01222 ltr informing NRC of wells to be sampled Requests environ contractor monthly rept
FIGHER, M L Region 3, Chicago, Fuel Facility & Materials Safety Branch 81/01/19 1p 07568 035

--B101290791 Responds to NRC B01119 ltr re well samples Now samples to begin Jan 1981 & be analyzed for gross alpha, gross beta & tritium
ONLEIN, J C Commonwealth Edison Co 80/12/22 1p 07568 036

B101270661 Responds to NRC loss of offsite power survey status rept. Partial loss of offsite power survey data should have been examined prior to processing so that only data significant to safety were included Calculated target values not valid
JANECEK, R F Commonwealth Edison Co 81/01/20 3pp 07549 006

Q Inspection reports, IE Bulletins & correspondence

B101050249 Forwards IE Info Notice B0-38, "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30 2pp 07389 130

B101050462 Forwards IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/06 2pp 07390 017

B101070113 Forwards IE Insp Repts 50-010/80-21, 50-237/80-23 & 50-249/80-27 on B01103-07 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/25 2pp 07415 011

--B101070118 Notice of violation from Insp on B01103-07.
* Region 3, Chicago, Office of the Director 80/11/24 1p 07415 013

--B101870125 IE Insp Repts 50-010/80-21, 50-237/80-23 & 50-249/80-27 on B01103-07 Noncompliance noted failure to collect weekly cooling water sample
JANECEK, R F, PHILLIPS, M P, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/11/24 10pp 07415 014

B101650533 Forwards IE Info Notice B0-43, "Failure of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05 2pp 07390 302

B101090778 Forwards IE Insp Repts 50-010/80-22, 50-237/80-24 & 50-249/80-28 on B01004-1114 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/05 2pp 07430 245

--B101690785 IE Insp Repts 50-010/80-22, 50-237/80-24 & 50-249/80-20 on B01004-1114 No noncompliance noted Major areas inspected: operational safety verification & monthly maint observation
TONGUE, T M, JORDAN, M J, WALKER, R O Region 3, Chicago, Office of the Director 00/12/05 6pp 07430 247

B101600773 Responds to IE Bulletin B0-23, "Failure of Solenoid Valve Mfg by Valtek Engineering Corp." Valves V70900-21-1 or V70900-21-3 not used in any safety-related functions. Approx 40 enshours expended in bulletin review
RAUSCH, T J Commonwealth Edison Co 80/12/12 1p 07399 122

B101080660 Forwards IE Info Notice B0-45, "Potential Failure of BWR Backup Manual Steam Capability." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 00/12/17 2pp 07420 329

B101130140 EN-B0-56 on or about B01219, notice of violation & notice of proposed imposition of civil penalty in amount of \$4,000 will be issued to licensee's Action based on alleged item of noncompliance re shipment of waste not packaged properly
FETZGER, J Enforcement Branch THOMPSON, D Director's Office 80/12/17 1p 07457 026

B101150240 Forwards Suppl 4 to IE Bulletin B0-17, "Failure of Control Rods to Insert During Scram at BWR." Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/18 1p 07465 348

B101050170 Forwards IE Bulletin B0-25, "Operating Problems w/Target Rod Safety Relief Valves at OWR." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/19 2pp 07377 301

B101650785 Addl responses to FOIA request for documents re experimental use of OOH HS-1 solvent at Dresden 1 & Peach Bottom Forwards GE rept. "Radiation Level Assessment of Dresden 1 Decontamination Pilot Loop - Final Rept."
FELTON, J M Division of Rules and Records 80/12/29 1p 07400 104

B101200155 Forwards response to IE Bulletin B0-24, "Prevention of Damage Due to Water Leakage Inside Containment (B01017 Indian Point 2 Event)." Surveillance procedures of at least monthly repetition will be instituted by 010601
RAUSCH, T J Commonwealth Edison Co 81/01/05 6pp 07486 202

R Periodic operating reports & related correspondence

B101270515 Forwards monthly operating repts for Dec 1980.
SCOTT, O J Commonwealth Edison Co 81/01/19 1p 07546 299

--B101270520 Monthly operating repts for Dec 1980.
MAXWELL, D C Commonwealth Edison Co 81/01/16 16pp 07546 300

B Reportable occurrences, LERs & related correspondence

B101290514 LER B0-003 has been cancelled
* Commonwealth Edison Co 81/01/15 2pp 07575 242

DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

J Insurance & indemnity information

B101270400 Forwards Endorsements 95 & 96 to NELA Policy NF-92
WATERS, D R Detroit Edison Co 81/01/22 4pp 07549 035

DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8101100295 Forwards proprietary comments on 801015 physical security plan Plan does not satisfy requirements applying to reactor in event that core becomes non self-protecting Response requested by 810116 Comments Withheld (ref 10CFR2 7901 TEOGEO, R L Assistant Director for Licensing 80/12/16 1p 07445 060.

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR EISENHUT, D O Division of Licensing 80/11/13 2pp

8101270720 Denies 801120 request for use of shift supervisor as fire brigade leader Util must submit official request for exemption from App R requirements Util commitment to control smoking in safety-related areas acceptable CRUTCHFIELD, O Operating Reactors Branch 5 80/12/10 3pp 07549 131

H General correspondence

8101140181 Responds to Rowe Nuclear Conversion Campaign 801006 ltr re operation of facility NRC requires util to answer citizens groups questions during formal proceedings Specific violations must be cited in order to warrant public hearing OENTON, H R Office of Nuclear Reactor Regulation, Director. 81/01/02 3pp 07461 205

P. Operating license stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants Forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports." EISENHUT, D O Division of Licensing 80/11/26 8pp

8101090088 Confirms 801202 proposal made by SEP owners group at 801202 meeting w/HRC for completion of 60% of SEP topics by 810630 Forwards mat used during 801202 presentation RCIAFFBATTALL, R KMC, Inc 80/12/05 12pp 07379 321

8101060020 Informs that SEP technical evaluations on SEP Topics 11-10, A-V-11, A-VI-4, VI-7, C 1, VI-7, F & VIII-2 are final since comments were not made by util within 60-days of receipt of NRC 800915 request. CRUTCHFIELD, O Operating Reactors Branch 5 80/12/05 1p. 07399 159

8101070115 Notifies that technical evaluations are final re SEP Topics 11-10, A-V-11, A-VI-4, VI-7, C 1, VI-7, F & VIII-2 Evaluations will be basic inputs to Facility Integrated Safety assessment. CRUTCHFIELD, O Operating Reactors Branch 5 80/12/08 2pp 07414 227

8101070474 Notifies that as result of NRC 801104 site visit, util must increase seismic capability of auxiliary feedwater sys Boils should be lightened on tanks which can supply emergency feedwater to steam generators CRUTCHFIELD, O Operating Reactors Branch 5 80/12/11 3pp. 07415 255.

8101070281 Notification of 810121 meeting w/vendor in Bethesda, MD to discuss small break LOCA methodology (Action Item 11, K 3 301 GUTHMAN, J. Reactor Systems Branch. 80/12/12 2pp. 07415 198.

8101140060 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures Info should be provided within 90 days of receipt of ltr. CRUTCHFIELD, O Operating Reactors Branch 5 80/12/13 4pp. 07458 198.

8101200639 Forwards guidelines for performing soil-structure interaction review for SEP facilities & simplified analytical approach for evaluating effects of soil-structure interaction using lumped parameter model. CRUTCHFIELD, O Operating Reactors Branch 5 80/12/15 2pp 07477 143

8101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants just comply within specified time frame EISENHUT, D O Division of Licensing 80/12/15 13pp

8101160029 Notification of 801218 meeting w/SEP owners group in Bethesda, MD re SEP program schedule for licensee topic completion & assignment of lead topics to plants RUSSELL, W T Technical Support Branch 80/12/16 2pp

8101200200 Advises that SEP review of Topic 11-2 A, "Severe Weather Phenomena," is completed Safety evaluation encl Forwards Inst of Disaster Research repl, "Tornado & Straight Wind Hazard Probability for Yankee Rowe Nuclear Power Reactor Site, MA" CRUTCHFIELD, O Operating Reactors Branch 5 80/12/17 7pp 07465 155

--8101260206 "Tornado & Straight Wind Hazard Probability for Yankee Rowe Nuclear Power Reactor Site, MA" MCCOMBS, D J R Texas Tech Univ NRC-04-76-345 80/05/01 26p 07486 162

8101230532 Forwards listing of all SEP correspondence re facility SEP owners group 801202 meeting List provides basis upon which to determine plant status Review & comments requested W/O encl. CRUTCHFIELD, O Operating Reactors Branch 5 80/12/22 2pp 07512 095

8101070383 Forwards Class 11 license amend fee for review of Proposed Change 169 re License DPR-3 KAY, J A Yankee Atomic Electric Co 80/12/26 1p 07414 319

--8101070385 Forwards util 801226 ltr & payment of license amend fee B1005, R H License Fee Management Branch 81/01/05 1p 07414 322

8101270130 Advises that SEP Topic 11-3 D has been deleted from cave of facility Site does not have underdrain sys to lower groundwater table CRUTCHFIELD, O Operating Reactors Branch 5 80/12/26 2pp 07547 293

8101280477 Forwards safety evaluation re susceptibility of safety-related sys to flooding from failure of Noncategory I sys & "Technical Evaluation of Susceptibility of Safety-Related Sys to Flooding Caused by Failure" CRUTCHFIELD, O Operating Reactors Branch 5 80/12/29 2pp 07550 296.

--8101280486 Safety evaluation re susceptibility of safety-related flooding from failure of Noncategory I sys Addl protective measures, in conjunction w/original design features are acceptable * Operating Reactors Branch 5 80/12/29 1p 07550 298

--8101280622 "Technical Evaluation of Susceptibility of Safety-Related Sys to Flooding Caused by Failure of Noncategory I sys for Yankee Rowe Power Station" * Lawrence Livermore Laboratory F117 A-0231 80/11/30 10pp 07550 299

8101140361 Forwards addl info required by NUREG-0737 re TMI Action Items addressed shift technical advisor, noble gas effluent monitor, sampling & analysis of plant effluents & control room habitability KAY, J A Yankee Atomic Electric Co 81/01/01 33pp. 07458 051

8101280460 Requests addl info re 800916 Tech Specs change request TMI Category A Lessons Learned items Schedule is required for installation of suitable flow indication for primary relief valves or justification of why indication not needed. CRUTCHFIELD, O Operating Reactors Branch 5 81/01/02 2pp 07187 001

8101090521 Clarifies responses to NRC staff requirements on Open 11 in App R to 10CFR50 re alternate shutdown capability. Inclusion of statement that util has not responded to NRC request was unnecessary & misleading HODDY, D E Yankee Atomic Electric Co 81/01/09 2pp. 07426 30

8101120293 Forwards "Reactor Containment Bldg Integrated Leak Rate Test," performed in Sept 1980 KAY, J A Yankee Atomic Electric Co 81/01/06 1p 07439 034

--8101120296 "Reactor Containment Bldg Integrated Leak Rate Test" WAGNER, D., HENDERSON, T K., AUTIO, H A. Yankee Atomic Electric Co 80/09/30 84pp 07439 035

8001130135 Submits application for withholding proprietary info from public disclosure Affidavit encl
KAY, J A Yankee Atomic Electric Co 81/01/06 1p 07452 001
SAUL, R H Westinghouse Electric Corp. 80/11/07 9pp 07452 002

8101140664 Forwards Reactor Containment Bldg Integrated Leak Rate Test, which provides evaluation of Type A test results & summary analysis of periodic Type B & Type C tests per 10CFR90 App J
KAY, J A Yankee Atomic Electric Co 81/01/06 1p 07461 167

--8101140678 "Separate Accompanying Summary Rept of Type B & C Events Since June 1977 Type A Test"
WARNER, D E HENDERSON, T A, AUTIO, H A Yankee Atomic Electric Co 80/09/30 3pp 07461 167

--8101140682 Forwards LER 77-044/03L-0
AUTIO, H A Yankee Atomic Electric Co 77/07/16 1p 07461 172

--8101140692 LER 77-044/03L-0 on 770817, observed that leakage of valves TV-211 & TV-40B greater than acceptable limits. Caused by worn seat & disc & deteriorated diaphragm, respectively. Valve seat & disc machined & diaphragm replaced
KAY, E L Yankee Atomic Electric Co 77/09/16 1p 07461 173

8101290475 Confirms 810112 authorization for Tech Specs change requested in 801022 for Surveillance requirements section may be deferred past 18-month limit, but no later than 810531
LAINAS, O C Assistant Director for Safety Assessment 81/01/12 2pp 07575 142

8101300077 Forwards Amend 62 to License DPR-3, safety evaluation & notice of issuance & availability.
CRUTCHFIELD, B Operating Reactors Branch 5 81/01/12 2pp 07583 055

--8101300092 Amend 62 to License DPR-3, revising Tech Specs to clarify term operable as applied to single failure criterion for power reactor safety sys
CRUTCHFIELD, B Operating Reactors Branch 5 81/01/12 14pp 07583 057

--8101300095 Safety evaluation supporting Amend 62 to License DPR-3
Office of Nuclear Reactor Regulation, Director 81/01/12 2pp 07583 071

--8101300099 Notice of issuance & availability of Amend 62 to License DPR-3
CRUTCHFIELD, B Operating Reactors Branch 5 81/01/12 2pp 07583 073

8101276362 Submits info to be incorporated in evaluation of SEP Topic VIII-2, diesel generators
KAY, J A Yankee Atomic Electric Co 81/01/20 2pp 07543 068

8101270652 Responds to NRC 800620 request for addl info re adequacy of station electric distribution sys voltages. Addl analysis for start of largest nonsafety load & analysis for 120-volt ac buses encl
KAY, J A Yankee Atomic Electric Co 81/01/21 8pp 07548 331

8101300481 Submits addl info on IMI Lessons Learned Item 2.1.3 re four 1-inch loop relief valves on main coolant loop bypass line in response to NRC 810102 request. Relief valves provide individual loop overpressure protection
KAY, J A Yankee Atomic Electric Co 81/01/23 2pp 07587 065

G Inspection reports, IF Bulletins & correspondence

8101070413 Forwards Suppl 1 to IE Info Notice 80-27, "Broken Studs on Turbine Turbine Steam Inlet Flange." No written response required.
ORIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 056

8101140758 Responds to IE Bulletin 80-21, Valve Yokes Suspect by Malcolm Fowler, Col. Inc. No cracks found in safety-related valve required for safe shutdown or in mitigate accident
KAY, J A Yankee Atomic Electric Co 80/12/05 2pp 07461 091

8101140763 Responds to IE Bulletin 80-20, "Leakage of Bypassed Valves." No cracks found in safety-related valve required for safe shutdown or in mitigate accident
KAY, J A Yankee Atomic Electric Co 80/12/15 1p 07461 214

response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/12/16 1p 07397 013

R Periodic operating reports & related correspondence

8101150512 Forwards monthly operating rept for Dec 1980
MCGOWAN, F Yankee Atomic Electric Co 01/01/12 1p 07463 15

--8101150514 Monthly operating rept for Dec 1980
BERNARD, D H Yankee Atomic Electric Co. 81/01/12 4pp 07463 158

S Reportable occurrences, LFRs & related correspondence

8101300703 Forwards LER 80-023/03L-0
AUTIO, H A Yankee Atomic Electric Co 81/01/26 1p 07503 32

--8101350726 LER 80-023/03L-0 on 801227, nitrogen regulator 81-11R-5 output pressure noted outside Tech Spec. Caused by setpoint drift of regulator pilot. Regulator adjusted
FRENCH, L D Yankee Atomic Electric Co 01/01/26 1p 07881 3

V Operator Examinations

8101140061 Forwards addl info required by NUREG-0737 re IMI Action Items addressed. 1st technical advisor, noble gas effluent transfer, sampling & analysis of plant effluents & control room habitability
KAY, J A Yankee Atomic Electric Co 81/01/01 33pp 07498 05

DOCKET 80-54 UNION CARBIDE RESEARCH REACTOR

P Operating license stage documents & correspondence

8101301213 Application for amend to License R-B1 & License SNM-601 change licensee name from Union Carbide Corp to Union Carbide Subsidiary B, Inc (Co B)
MCGOVERN, J J Union Carbide Corp 81/01/08 1p 07449 361

DOCKET 80-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8101280173 Forwards security plan, Revision 3, Encl withheld (ref 10CFR2.790)
HEURY, L O New York, State Univ of Buffalo 81/01/23 1p 07556 141

DOCKET 80-52 UNIV OF VIRGINIA RESEARCH REACTOR

R Periodic operating reports & related correspondence

8101300382 Submits annual operating rept for 1980, per Section 6.7 Tech Specs
FARRAR, J O Virginia, Univ of 81/01/09 14pp 07581 336

S Reportable occurrences, LFRs & related correspondence

8101300443 RO on 810119, during routine core visual examination, small air bubble discovered on top of fuel element on grid plate. Position 43 operator lifted source, which became lodged under fuel element handling bar. Caused by personnel error
SMITH, R L Virginia, Univ of 81/01/27 5pp 07581 336

DOCKET 80-70 GENERAL ELECTRIC TEST REACTOR

F Security, medical, emergency & fire protection plans

8101140760 Ack receipt of 800514 for transmitting proposed security plan Class 111 for requested
KAY, J A Yankee Atomic Electric Co 80/12/12 1p 07463 216

8101140763 Forwards revised fee for 800514 security plan in response to 80070121 for
KAY, J A Yankee Atomic Electric Co 81/01/12 1p 07463 216

--8101280171 Requests processing license 810122 ltr forwarding review fee for security plan
01098.R.H. License Fee Management Branch. 81/01/27 1p
07358 050

O Adjudicatory correspondence

0101050494 Response to ASLB 801210 notice of second prehearing conference. Prehearing process should resume immediately. Evidentiary hearing should begin 60 days after 810106 prehearing conference.
EODAR, O.L. General Electric Co 80/12/29 3pp 07390 221

--8101050506 Ninth discovery status rept Response filed opposing intervenor 780808 motion to compel & 780821 cross-motion for protective order. Lists individuals who inspected licensee on 781017 & 27.
EODAR, O.L., ALLEN, K.P. General Electric Co ALLEN, K.P. Morgan, Lewis & Bockius. 78/11/08 6pp 07390 224

--8101050515 Tenth discovery status rept Answers filed on 781130 to intervenors' 780903 interrogatories, completing all outstanding discovery obligations. Response submitted on 781117 to ASLB 781024 order. Certificate of Bvc encl.
EODAR, O.L., ALLEN, K.P. General Electric Co ALLEN, K.P. Morgan, Lewis & Bockius. 79/01/10 4pp. 07390 230

8101160197 Response to ASLB 810105 request for schedule re future conduct of proceeding. Final SER suppl will be issued 810115. discovery commenced 810121, final responses filed by 810327 & hearing commenced 810904. Certificate of Bvc encl.
EODAR, O.L. General Electric Co 81/01/13 3pp 07470 048

8101200040 Proposed discovery schedule per ASLB 810105 request Certificate of Bvc encl.
BACHMANN, R.O. Office of the Executive Legal Director. 81/01/19. 4pp 07477 318

8101270057 Joint response of intervenors Dollums, Burton & Burton, Friends of the Earth & B Shockley, proposing scheduling of prehearing conference & deadlines for discovery & testimony. Certificate of Bvc encl. Related correspondence.
WALTERMAN, H.L. Affiliation Unknown BALOWIN, W.A. Friends of the Earth, BALOWIN, W.A. Baldwin, W.A. 81/01/15. 3pp 07547 025.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8101300844 Certified minutes of ACRS Subcommittee on OETR 801104 meeting in Washington, DC to continue review of restart request. Tentative schedule & attendee list encl.
* ACRS - Advisory Committee on Reactor Safeguards. 80/12/02 8pp. 07582 293

P. Operating license stage documents & correspondence

8101290538 Notification of contract execution, Mod 2 to "OETR." Contractor: O Blemmons.
PERLMAN, J. Administrative Contracts Branch. FIN B-6829. 81/01/05. 1p. 07575 255.

8101290016 Forwards supply to 801027 safety evaluation re vendor 801203 "Analysis of Subgrade Rupture Mechanism at OETR." Potential load combinations resulting from surface offset & vibratory ground motion are limited.
MOVAK, T.M. Assistant Director for Operating Reactors. 81/01/15. 10pp 07570 346.

8101290541 Mod 2, closing out contract to "OETR." BLEMMONS, O.B. Blemmons, O.B. PERLMAN, J. Administrative Contracts Branch. FIN B-6829. 81/01/05. 1p. 07575 256

T. Hearing transcripts on non-antitrust matters

8101890048 Transcript of 810105 prehearing conference in San Francisco. CA. Pp 91-170.
* Atomic Safety and Licensing Board Panel 81/01/05. 89pp 07426 146.

DOCKET 80-87 WEBBINGHOUSE CRITICAL EXPERIMENT

F. Security, medical, emergency & fire protection plans

8101200090 Ack receipt of 800319 transmittal of Revision 2 to security plan Class III fee should be submitted, per 10CFR170 requirements for review.
01008.R.H. License Fee Management Branch. 80/12/23. 1p. 07487 111.

DOCKET 80-89 GENERAL ATOMIC CO

O Inspection reports, IE Bulletin & correspondence

8101210133 Forwards IE Insp Repts 80-089/80-02 & 80-163/80-02 on 801215-17. No noncompliance noted. Major areas inspected logs & records, review & audit & operator requalification program.
CREWB, J.L. Region 5, San Francisco. Reactor Operations Nuclear Support Branch 80/12/23 2pp 07487 335

--8101210138 IE Insp Repts 80-089/80-02 & 80-163/80-02 on 801215-17. No noncompliance noted. Major areas inspected logs & records, review & audit & operator requalification program.
FAULKNER, B. Region 5, San Francisco. Reactor Operations Nuclear Support Branch JOHNSON, A.D. Region 5, San Francisco. Office of the Director 80/12/23 4pp. 07489 357

DOCKET 80-131 NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8101120178 Forwards Amend B to License R-63 & safety evaluation. REIO, R.W. Operating Reactors Branch 4 80/12/24 2pp 07446

--8101120181 Amend B to License R-63, revising bldg & campus monitoring requirements & deleting weekly reactor & control apparatus Insp.
REIO, R.W. Operating Reactors Branch 4. 80/12/24 7pp 07446 360.

--8101120185 Safety evaluation supporting Amend B to License R-63.
* Office of Nuclear Reactor Regulation, Director 80/12/24 07447 005

DOCKET 80-131 OMAHA VET ADMIN HOSP RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8101050585 Requests assistance in reviewing and emergency plan. Part of application for renewal of License R-57 & includes add'l background info on reactor facility.
MILLER, J.R. Standardization & Special Projects Branch 80/12/1p. 07390 342

--8101050589 Forwards excerpt of application for renewal of License R-57 on emergency planning encl.
MULLON, T.P. Vet Admin. Hosp Omaha, NE 79/05/10 37pp. 07390 343

O. Inspection reports, IE Bulletin & correspondence

8101070584 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials." No written response required.
SNIETZER, J.H. Division of Fuel Facility & Materials Safety. 80/08/29. 1p 07415 331

DOCKET 80-133 HUMBOLDT BAY POWER PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FBAR.
EISENHUT, O.O. Division of Licensing. 80/11/13. 2pp.

O. Adjudicatory correspondence

8101070135 Motion to withdraw w/o prejudice 770520 application for license amend to permit resumption of operation. Certificate of Bvc encl.
LOCKE, R.F. Pacific Gas & Electric Co. 80/12/31 16pp. 07408

--8101070139 "Future Licensing Requirement Cost Impact." Bechtel Power Corp. (subs. of Bechtel Corp.) 80/12/31. 07408 152

8101230238 Response of intervenors TK Collins, E Honea, FP Cranston, Chebro, DL Mitranas, Bix Rivoire. Branch of Friends of the Earth & Sierra Club in support of 801231 motion to withdraw amend application. Certificate of Bvc encl.
BROWN, L.J. Jones, Brown & Clifford. SHERWOOD, M.R. Sierra Club. SHERWOOD, M.R. Sherwood, M.R. 81/01/15 13pp 07512 056

DOCKETED ITEMS

B101230642 Response supporting applicant 001231 motion to withdraw license amend application w/o prejudice ASLB lacks jurisdiction to grant intervenors' request to order immediate decommissioning of plant. H/Certificate of Svc GOLBERG, S C Hearing Branch 2 B1/01/21 App 07512 285

B101260917 Answer opposing until B01231 motion to withdraw license amend application Matter should be resolved permanently Certificate of Svc encl KERR, J E ; SIMPSON, J C ; EUMAS, G California, State of B1/01/22 7pp 07529 241

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for scrubbers under STB License amend application adding model Tech Specs to App A should be submitted within 120 days EISENHUT, O O Division of Licensing B0/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 2B.8 3/4 7-5 & 7-6 & 6-17 to STB scrubber inservice insp requirements
• Division of Licensing B0/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re Implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" EISENHUT, O O Division of Licensing B0/11/26 8pp

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR scram discharge sys Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes EISENHUT, O O Division of Licensing B0/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants to acceptable pending permanent design mods Criteria for implementing design mods encl
• Division of Licensing B0/12/01 212pp 07183:001

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame EISENHUT, O O Division of Licensing B0/12/15 13pp.

B101210342 Advise that Board of Supervisors will cooperate w/agencies in event of decommissioning WALSH, O Humboldt County, CA B1/01/08 1p 07490 119

B101220309 Responds to NRC B01031 ltr requesting info re participation in development of design & performance criteria for BWR scram sys. Tests, equipment, procedure verifications & any design mods will be completed before return to operation CRANE, P A Pacific Gas & Electric Co B1/01/14 1p 07500 068

B101270452 Responds to NRC B01113 ltr requesting confirmation that implementation dates in NUREG-0619 will be met Facility to shut down until decision is made re future operation. CRANE, P A Pacific Gas & Electric Co B1/01/22 1p 07549 058

O Inspection reports, IE Bulletins & correspondence

B101120252 Forwards response to Revision 1, IE Bulletin 79-26 Plans for replacement of control rod blades will not be made until resolution of seismic issue. CRANE, P A Pacific Gas & Electric Co B0/12/01 2pp 07309 001

B101050504 Forwards IE Info Notice B0-43, "Failure of Continuous Water Level Monitor for Scram Discharge Val at Dresden Unit 2." No response required. ENDELKEN, R H Region 5, San Francisco, Office of the Director B0/12/05 1p 07387 292

B101070206 Responds to IE Bulletin B0-21 Util unable to determine if valve gates supplied by Helcoln Foundry Co. Inc are used in safety-related sys since plant is in cold shutdown issue will be resolved prior to power operation. CRANE, P A Pacific Gas & Electric Co B0/12/09 2pp 07187 001.

B101120547 Responds to IE Bulletin B0-23, "Failure of Solenoid Valves Mfg by Valcor Engineering Corp." No valves used presently or planned for use in safety-related applications.

B101130108 Forwards IE Info Notice B0-45, "Potential Failure of BWR Backup Manual Scram Capability" No response required. ENDELKEN, R H Region 5, San Francisco, Office of the Director B0/12/17 1p 07449 220

B101090775 Forwards Suppl 4 to IE Bulletin B0-17, "Failure of 76 of 10 Control Rods to Fully Insert During Scram at BWR." Written responses required. ENDELKEN, R H Region 5, San Francisco, Office of the Director B0/12/18 1p 07430 335

B101050165 Forwards IE Bulletin B0-25, "Operating Problems W/Target Rod Safety Relief Valves at BWRs." No response required. ENDELKEN, R H Region 5, San Francisco, Office of the Director B0/12/19 2pp 07377 274

B101290534 Forwards IE Insp Rept B0-133/B0-05 on B01215-18. No noncompliance noted Encl withheld (ref 10CFR2 790). MORSEHAGG, L R Region 5, San Francisco, Safeguards Branch B1/01/09 2pp 07575 271.

R Periodic operating reports & related correspondence

B101130578 Forwards monthly operating rept for Dec 1980 WEENS, E D Pacific Gas & Electric Co B1/01/07 2pp 07493 230

--B101130585 Monthly operating rept for Dec 1980 BAUM, P W Pacific Gas & Electric Co B1/01/05 3pp 07483 232

S Reportable occurrences, LERs & related correspondence

B101050406 Forwards LER B0-007/03L-0 CRANE, P A Pacific Gas & Electric Co B0/12/30 1p 07390 114.

--B101050410 LER B0-007/03L-0 on B01130, events observed coming from pump 2 diesel engine fan area during testing. Caused by pulley sheave mounting flange breasting away from hub New part mfg on site. GETTY, S C Pacific Gas & Electric Co B0/12/30 1p 07390 115

DOCKET B0-134 WORCESTER POLYTECH INST RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B101290524 Releases public version of univ released emergency plan, representing pages of FSAR. FELTON, J M Division of Rules and Records B1/01/27 1p 07574:245.

--B101290631 Forwards public version of revised emergency plan for facility, consisting of FSAR Pages 36-38d. WILBUR, L C Worcester Polytechnic Inst. B1/01/19 1p 07574:246

--B101290637 Public version of revised emergency plan for facility, consisting of FSAR Pages 36-38d. Worcester Polytechnic Inst. B1/01/19 7pp 07574 247

K Utility Final Safety Analysis Report (FSAR) & amends

B101290624 Releases public version of univ released emergency plan, representing pages of FSAR. FELTON, J M Division of Rules and Records B1/01/27 1p 07574:245

--B101290631 Forwards public version of revised emergency plan for facility, consisting of FSAR Pages 36-38d. WILBUR, L C Worcester Polytechnic Inst. B1/01/19 1p 07574:246

--B101290637 Public version of revised emergency plan for facility, consisting of FSAR Pages 36-38d. Worcester Polytechnic Inst B1/01/19 7pp 07574:247.

R Periodic operating reports & related correspondence

B101160529 Submits annual operating rept for 1980. No unusual events or abnormal radiation exposures to personnel occurred. Annual major overhaul of reactor control sys was completed on schedule & all sys appear in excellent condition. WILBUR, L C Worcester Polytechnic Inst B1/01/19 1p 07493 230

DOCKET 50-142 UCLA TRAINING REACTOR

Q Adjudicatory correspondence

B101120133 Responds to NRC 801124 ltr raising questions re Ar-41 concentrations from facility. Operation of reactor meets identified regulatory requirements.
OIRCKB, W. J. Office of the Executive Director for Operations
80/12/12 1p. 07309-001

--B101120137 Ack receipt of 800103 ltr transmitting comments on 10CFR2.206 petition submitted by Committee to Bridge the Gap. Info will be considered in preparation of response to petition.
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/01/24 1p. 07309-001

B101070446 Request, submitted on behalf of intervenor Bridge the Gap, for date Univ will provide further response to intervenor first set of interrogatories. Questions 4-6 & 9 re Contention 2.
POLLOCK, M. B. Pollock, M. B. 80/12/30 2pp 07415-308

B101160284 Order scheduling B10204-05 prehearing conference re disputed contentions. Conference will be open to public but no limited appearance statements accepted. Certificate of Svc encl.
BOWERB, E. S. Atomic Safety and Licensing Board Panel. 81/01/12. 4pp. 07470-341.

P. Operating license stage documents & correspondence

B101120133 Responds to NRC 801124 ltr raising questions re Ar-41 concentrations from facility. Operation of reactor meets identified regulatory requirements.
OIRCKB, W. J. Office of the Executive Director for Operations.
80/12/12 1p. 07309-001

--B101120135 Requests justification for allowing licensee to average Argon concentrations in unrestricted areas over 12-month period. Response requested by 801210.
BRAOFORO, P. A. Commissioners. 80/11/24. 1p. 07309-001.

--B101120137 Ack receipt of 800103 ltr transmitting comments on 10CFR2.206 petition submitted by Committee to Bridge the Gap. Info will be considered in preparation of response to petition.
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/01/24. 1p. 07309-001.

Q. Inspection reports, IE Bulletins & correspondence

B101290369 Forwards 1E Insp Rept 50-142/80-03 on 801112-14. No noncompliance noted.
BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 80/12/16. 2pp. 07371-308.

--B101290374 1E Insp Rept 50-142/80-03 on 801112-14. No noncompliance noted. Major areas inspected: responses to 1E Bulletin 79-19 & 1E Circular 80-14 & environ protection, environ controls & emergency response planning programs.
CURTIS, J. R. WENBLAWSKI, F. Region 5, San Francisco, Office of the Director. BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 80/12/16. 4pp. 07371-310.

DOCKET 50-148 UNIV. OF KANBAG RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B101160378 Releases public version of emergency plan as part of license renewal application.
FELTON, J. M. Division of Rules and Records. 80/12/02. 1p. 07471-036.

--B101160391 Forwards Tech Specs, public version of emergency preparedness plan, EIA & financial liability statement re application to renew license.
MEBLER, R. B. Kansas, Univ. of. 80/03/04. 1p. 07471-057.

--B101160404 Public version of Univ emergency preparedness plan.
* Kansas, Univ. of. 80/02/29. 46pp 07471-089.

--B101160411 Forwards statement of financial considerations supporting renewal of License R-7B. Ltr certifies that future budgets for School of Engineering will include support at level indicated under Section 2 W/o encl.
KRAFT, O. C. Kansas, Univ. of. 80/03/04. 1p. 07471-143.

1 Financial information

B101160378 Releases public version of emergency plan as part of license renewal application.
FELTON, J. M. Division of Rules and Records. 80/12/02. 1p. 07471-036.

--B101160391 Forwards Tech Specs, public version of emergency preparedness plan, EIA & financial liability statement re application to renew license.
MEBLER, R. B. Kansas, Univ. of. 80/03/04. 1p. 07471-057.

--B101160411 Forwards statement of financial considerations supporting renewal of License R-7B. Ltr certifies that future budgets for School of Engineering will include support at level indicated under Section 2 W/o encl.
KRAFT, O. C. Kansas, Univ. of. 80/03/04. 1p. 07471-143.

P. Operating license stage documents & correspondence

B101160378 Releases public version of emergency plan as part of license renewal application.
FELTON, J. M. Division of Rules and Records. 80/12/02. 1p. 07471-036.

--B101160391 Forwards Tech Specs, public version of emergency preparedness plan, EIA & financial liability statement re application to renew license.
MEBLER, R. B. Kansas, Univ. of. 80/03/04. 1p. 07471-057.

--B101160390 Tech Specs 1 0-7. Q for nuclear reactor facility License R-7B
* Kansas, Univ. of. 80/03/31. 31pp. 07471-050.

--B101160404 Public version of Univ emergency preparedness plan
* Kansas, Univ. of. 80/02/29. 46pp 07471-089.

--B101160408 EIA supporting renewal of facility License R-7B Financial liability statement encl.
* Kansas, Univ. of. 80/03/31. 13pp 07471-134.

--B101160411 Forwards statement of financial considerations supporting renewal of License R-7B. Ltr certifies that future budgets for School of Engineering will include support at level indicated under Section 2 W/o encl.
KRAFT, O. C. Kansas, Univ. of. 80/03/04. 1p. 07471-143.

DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR

Q. Inspection reports, IE Bulletins & correspondence

B101160360 Forwards 1E Insp Repts 50-151/80-03 & 50-356/00-03 on 801117-19 & notice of violation.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/10. 2pp 07470-352.

--B101160374 Notice of violation from Insp on 801117-19.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 00/12/09. 1p 07470-354.

--B101160382 1E Insp Repts 50-151/80-03 & 50-356/80-03 on 801117-19. Noncompliance noted: nuclear reactor committee meetings exceeded specified frequency.
RIDGWAY, K. R., BOONE, J. M. Region 3, Chicago, Office of the Director. RIDGWAY, O. C. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09. 3pp. 07470-355.

DOCKET 50-155 B10 ROCK POINT NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

B101070387 Ltr to all licensees of operating reactor plants, CP hold & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FBAR.
EISENHUT, O. O. Division of Licensing. 80/11/13. 2pp.

B101300558 Forwards comments re required revisions to util physics security plan. Encl withheld inef 10CFR2.7901.
CRUTCHFIELD, O. O. Operating Reactors Branch 5. 80/12/15. 3pp 07584-352.

B101050570 Releases public version of util revised site emergency plan.
FELTON, J. M. Division of Rules and Records. 80/12/29. 1p. 07388-141.

DOCKETED ITEMS

--B101090576 Forwards public version of Revision 60 to site emergency plan. In response to NRC B01113 ltr Addl revisions or justification for current position is required.
HCFPIAN, O P Consumers Power Co. 80/12/19 1p 0738B 143

--B101050580 Public version of Revision 60 to site emergency plan
• Consumers Power Co 02/12/31. 225pp 0738B 144.

B101100749 Requests that encl facility emergency planning info be made publicly available W/O encl.
SOUDEK, J L Division of Rules and Records 80/12/31 1p 07443 358

B101270995 Requests that encl facility emergency planning info be made publicly available W/O encl.
SOUDEK, J L Division of Rules and Records 81/01/13. 1p 07548 362

B101290174 Forwards facility emergency planning info to be made publicly available W/O encl
SOUDEK, J L Division of Rules and Records 81/01/23. 1p 07575 203

O Adjudicatory correspondence

B012240475 Responds to B00318 ltr expressing concern re insufficient shielding & emergency planning at facility Shielding concern is being treated as 10CFR2 206 request & upgraded emergency plan will be implemented within several months
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/12/10 2pp 07324 323

--B011100496 Responds to util B00325 & 0902 addl info re deferment of plant mode pending completed risk assessment re feasibility of continued operation ATWS recirculation pump trip & alternate shutdown panel mode cannot be deferred
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/10/14 8pp 06931 202.

--B003270417 Discusses util proposed cost-benefit analysis study re equipment which NRC proposes util implement at facility discussed in encl Petoskey News-Review B00228 article.
CHRISTA-MARIA Christa-Maria 80/03/18. 2pp 02519 314

B101090932 Forwards Director's decision & notice of issuance in response to B00401 petition on behalf of Concerned Citizens for Charlevoix Area requesting facility shutdown.
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/12/18. 2pp 07430 203

--B101090937 Notice of issuance of Director's decision under 10CFR2 206, denying B00401 petition on behalf of Concerned Citizens for Charlevoix Area for facility shutdown
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/12/18 2pp 07430 204.

--B101090940 Director's decision under 10CFR2 206, denying B00401 petition on behalf of Concerned Citizens for Charlevoix Area for facility shutdown
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/12/18 6pp 07430 207

--B101090942 Urges facility shutdown on behalf of Concerned Citizens for Charlevoix Area Unshielded steel containment insufficient to contain radiation
CHRISTA-MARIA Christa-Maria 80/04/01 1p 07430 212

B101150379 Forwards Director's decision & notice of issuance in response to J Bier & SJ John 791104 & B00106 petitions to delay restart of facility. Petition treated as request for order to show cause, due to receipt after restart.
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/12/18 4pp 07463 055

--B101150390 Director's decision under 10CFR2 206, denying 791104 & B00106 petitions for order to show cause why OL should not be suspended.
DENTON, H R Office of Nuclear Reactor Regulation, Director. 80/12/18 14pp. 07463:060

--B101150397 Notice of issuance of Director's decision under 10CFR2 206, denying J Bier & BJ Johns 791104 & B00106 petitions for order to show cause why OL should not be suspended.
DENTON, H R Office of Nuclear Reactor Regulation, Director. 80/12/18 7pp 07463 024

--B101030022 Corrections to B01204 brief, in support of ASLB finding that NEPA requires preparation of EIS in spent fuel pool expansion proceeding
LEITHAUSER, J Affiliation Unknown 80/12/19 1p 07309 001

B101090627 Response to ASLAB B01212 order advising intervenor will appear at B10109 oral argument & response to ASLAB B00912 order stating that NEPA requires EIS preparation Table of citations to B01204 brief encl
O'NEILL, J Affiliation Unknown 80/12/22 17pp. 07309 001

B101060921 Response opposing Leithauser B01219 motion to postpone oral arguments from B10109 to B10121 Intervenor failed to show good cause Certificate of Bvc encl
GOLLO, J Consumers Power Co 80/12/29 3pp 07401-093.

B101050612 Order denying Intervenor Leithauser motion to postpone oral arguments until B10121. Also denies intervenor O'Neill Motion for separate &/or addl time for oral argument O'Neill reply brief stricken & errata sheet filed
TEMPKINS, B A Atomic Safety and Licensing Appeal Panel 80/12/31. 3pp 07390 256

B101070520 Order granting extension until B10116 for Commission to decide to review Director's decision re facility.
CHILK, B J Office of the Secretary of the Commission. 81/01/02. 1p 07415 114

B101080080 Informs that JE Moore will represent NRC at B10109 oral argument
MOORE, J E Hearing Branch 2 81/01/06 1p. 03775:001.

B101130148 Motion to afford J O'Neill, H Bammel for Christa-Maria & CES opportunity to present oral arguments Denied by ASLAB
B10106
LEITHAUSER, J A Affiliation Unknown 81/01/06 1p. 07452:147

--B101130154 Motion supporting J O'Neill request to grant J Leithauser opportunity to present oral arguments. Denied by ASLAB
B10106.
LEITHAUSER, J A Affiliation Unknown 81/01/06 1p 07452:148

--B101130158 Withdrawal of Intervenor J Leithauser motion to postpone oral arguments on applicability of NEPA until B10121. Denied by ASLB B10106.
LEITHAUSER, J A Affiliation Unknown. 81/01/06 1p. 07452:149.

B101150003 Order granting extension until B10130 for Commission to review Director's decision on Bier & Jones petition.
Certificate of Bvc encl
CHILK, B J Office of the Secretary of the Commission 81/01/12. 2pp 07462 132

B101160209 Reviews transcript of 791205 prehearing conference re scope of EIA
GALL, G J Isham, Lincoln & Beals 81/01/12 6pp. 07470 057.

B101230091 Memorandum & order determining that J Bier, P Barnett & BJ Johns Nov 1980 pleading is not petition to intervene. If any party considers pleading as such petition, responses due within 15 days of order Certificate of Bvc encl
GROSSMAN, H Atomic Safety and Licensing Board Panel 81/01/16 6pp 07511 335.

B101230437 Order granting extension until B10123 for Commission to decide whether to review Director's decision re Christa-Maria petition Certificate of Bvc encl
CHILK, B J Office of the Secretary of the Commission 81/01/16. 2pp 07512 133

B101220001 Confirms that B01113 petition was not intended as petition for leave to intervene in pending spent fuel pool expansion proceeding. per B01126 telcon
MOORE, J E Hearing Branch 2 81/01/19 1p 07501:314

B101220017 Confirms that B01113 petition was not intended as petition for leave to intervene in pending spent fuel pool expansion proceeding. per B01126 telcon
MOORE, J E Hearing Branch 2 81/01/19 1p. 07501:341

B101220020 Confirms that B01113 petition was not intended as petition for leave to intervene in pending spent fuel pool expansion proceeding
MOORE, J E Hearing Branch 2 81/01/19 1p. 07501:342.

8101230653 Order granting extension until 810213 for Commission to decide whether to review Director's decision re Bier & Johns petition NRC may prepare suppl explaining basis for original decision Certificate of Evc encl
CHILK.B J Office of the Secretary of the Commission 81/01/19 2pp 07512 294

8101280226 Forwards A6L8 810116 order per 810123 telcon W/o encl
MOORE, J E Hearing Branch 2 81/01/23 1p 07556 299

II General correspondence

8101070376 Demands that facility stay down until NUREO-0654 & FEHA Rept 1 requirements satisfied
CURISTA-MARIA Christo-Maria 81/01/02 1p 07414 123

J Insurance & indemnity information

8101220250 Forwards Endorsements B3 & B4 to ANI Policy NF-117 W/o Endorsement B4
IRELAND, J H Consumers Power Co 81/01/16 2pp 07496 062

P Operating license stage documents & correspondence

801180019 Advices that SEP Topics 11-2 B, 11-2 D, 111-B D & VI-B should be added to 791116 list of topics removed from review due to related generic NRC activities & nonapplicability. BWR DBE topic list encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/26 5pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lemeller Tearing on Component Supports."
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101050555 Confirms proposal made by SEP owners group at 801202 meeting w/NRC increased involvement in SEP completion will be made. Presentation not used in meeting encl.
BECHAFBETALL, R Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 80/12/05 12pp 07390 144

8101190113 Ltr to all BWR licensees forwarding 801201 generic safety evaluation re BWR steam discharge sys Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes
EISENHUT, D O Division of Licensing 80/12/09 2pp

--8101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl.
Division of Licensing 80/12/01 212pp 07183 001

8101070618 Forwards request for addl info necessary for review of SEP Topic-1V-2 re reactivity control sys design & protection against single failures. Data requested within 90 days
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 3pp 07414 154

8101210445 Forwards response to questions on Rule 50.71c, "Periodic Updating of FBARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing 80/12/15 13pp

8101160029 Notification of 801218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants.
RUSSELL, W T Technical Support Branch 80/12/16 2pp

8101210229 Advises that SEP review of Topic 11-2 A "Severe Weather Phenomena," has been completed. Safety evaluation encl.
Forwards TX Tech Univ rept: "Tornado & Straight Wind Hazard Probability for Big Rock Point..."
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/17 7pp 07492 001

--8101210233 "Tornado & Straight Wind Hazard Probability for Big Rock Point Nuclear Power Reactor Site, MI."
MCBBHALO, J R Texas Tech Univ. NRC-04-76-345 80/05/31 26pp 07492 008

8101230337 Forwards listing of all SEP correspondence re facility per SEP owners group 801202 meeting. List provides basis upon which to determine plant status Review & comments requested. W/o encl.
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/22 2pp 07512 097

8101190644 Informs that SEP Topic 11-3 B, structural & other consequences of underdrain sys failure, has been deleted from facility SEP review due to inapplicability
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/26 2pp 07476 069

8101120224 Forwards preliminary "Seismic Safety Margin Evaluation," response to SEP program
HOFFMAN, D P Consumers Power Co 81/01/09 1p 07445 264

--8101120227 Preliminary "Seismic Safety Margin Evaluation"
O'Appelonia Consulting Engineers, Inc 81/01/09 27pp 07445 265

8101130085 Forwards addl info re adequacy of offsite power sys per N 790925 request. Problems encountered in generating, relocating & assembling info in required form caused extension in requested submittal date
HOFFMAN, D P Consumers Power Co 81/01/09 5pp 07456 011

8101220234 Forwards response to NUREO-0619, "BWR Feedwater Noise & Control Rod Drive Return Line Noise Checking." NUREO not applicable due to plant design differences
HOFFMAN, D P Consumers Power Co 81/01/16 3pp 07500 071

8101230347 Notification of 810119 meeting w/utl in Bethesda, MD for overview of probabilistic risk assessment program being conducted for facility.
PAULSON, W A Operating Reactors Branch 5 81/01/16 2pp 07512 106

8101270373 Forwards emergency procedures & training program re recognition & mitigation of ATWS event. Procedures provide emergency & off normal responses to ATWS & inability to insert control rods.
HOFFMAN, D P Consumers Power Co 81/01/22 31pp 07543 052

8101280093 Submits info re anchorage & support of safety-related electrical equipment. Evaluations have been completed. List of mods to be performed encl. Mods will be completed by 810401
HOFFMAN, D P Consumers Power Co 81/01/22 3pp 07550 036

8101270691 Responds to NRC evaluation of SEP Topic 11-2 A re severe weather phenomena NOT described in Reg Guide 1.7c differs greatly from actual occurrences near site Reg guide unnecessarily severe
VINCENT, R A Consumers Power Co 81/01/23 2p 07543 232

8101290358 Forwards balance of payment for Class III fee determination re utl 801029 request for Tech Specs change re control rod drive sys isolation
HOFFMAN, D P Consumers Power Co 81/01/26 1p 07575 128

O Inspection reports, IE Bulletins & correspondence

8101050214 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Cooling Cladding." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/20 2pp 07389 041

8101060118 Forwards IE Circular 80-23, "Potential Defects in Bait Power Sys Emergency Generators." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/31 1p 07397 329

8101060644 Forwards IE Info Notice 80-39, "Malfunction of Bolinold Valves Mfg by Velcor Engineering Corp." No written response is required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/31 2pp 07401 206

8101050457 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malco Foundry Co, Inc." Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/1 2pp 07390 001

8101060628 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supp Pressure Actuators Safety-Relief Valve Operation to Cease Reactor Depressurization." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/0 2pp 07392 165

8101060344 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/1 2pp 07392 070

DOCKETED ITEMS

8101060501 Forwards 1E Bulletin 80-23, "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp. Written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/11/14
2pp 07391 229

8101150397 Forwards 1E Insp Rept 50-155/80-17 on 801103 & 07 No
noncompliance noted
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/25 2pp 07463 195

--8101150599 1E Insp Rept 50-155/80-17 on 801103 & 07 No noncompliance
noted Major areas inspected w/o activities & 1E Bulletins
79-03A & 00-08 activities.
WARO, K D Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction &
Engineering Support Branch 80/11/25 5pp 07463 197.

8101080124 Responds to 1E Bulletin 80-23 re failure of Valcor solenoid
valves No such valves used in safety-related functions
Approx 8-4 of manpower expended
HOFFMAN, D P Consumers Power Co 80/12/01 1p 07420 356

8101080134 Responds to 1E Bulletin 80-21 re Malcolm Foundry Co. Inc
supplied valve yokes. No valve parts cast by vendor used
Approx 34 man-hours expected in review
HOFFMAN, D P Consumers Power Co. 80/12/01 1p 07420 357

8101120013 Forwards 1E Insp Rept 50-155/80-16 on 801103-06 & notice of
violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety
Branch. 80/12/03. 2pp 07446 226

--8101120016 Notice of violation from Insp on 801103-06.
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety
Branch 80/12/02 1p 07446 228

--8101120018 1E Insp Rept 50-155/80-16 on 801103-05 Noncompliance noted
Failure to post radiation areas
LOVEMOALE, P C, HUETER, L J Region 3, Chicago, Office of the
Director. FISHER, W L Region 3, Chicago, Fuel Facility &
Materials Safety Branch 80/12/01. 10pp. 07446 229

8101050562 Forwards 1E Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Scram Discharge Vol at Dresden Unit 2" No
response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/05
2pp 07390 332

8101080070 Forwards 1E Info Notice 80-45, "Potential Failure of BWR
Backup Manual Scram Capability" No written response
required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/17
2pp. 07420 337.

8101100788 Forwards 1E Insp Rept 50-155/80-14 on 801020-24 & notice of
violation.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/12/17 2pp 07585 230

--8101100791 Notice of violation from Insp on 801020-24
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear
Support Branch 80/12/17. 2pp 07585 232

--8101100796 1E Insp Rept 50-155/80-14 on 801020-24 Noncompliance noted
spec/field change package 80-015 closed out w/o required
testing
SHEPLEY, B E., SPEESARO, R L Region 3, Chicago, Office of the
Director 80/12/17. 6pp. 07585 234

8101150204 Forwards Suppl 4 to 1E Bulletin 80-17, "Failure of Control
Rods to Insert During Scram at BWR." No written response
required.
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/18
2pp 07462 193

8101050179 Forwards 1E Bulletin 80-25, "Operating Problems W/Target
Rack Safety Relief Valves at BWRs." No response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/19
2pp 07377 307

8101120574 Responds to 1E Bulletin 80-24, "Prevention of Damage Due to
Water Leakage Inside Containment (October 17, 1980 Indian
Point 2 Event)." Describes open evc water sys & aspariances
w/ closed cooling water sys
HOFFMAN, D P Consumers Power Co 80/12/23. 7pp 07447 197

8101290076 Ack receipt of 801218 ltr informing NRC of steps taken to
correct violation noted in 1E Insp Rept 50-155/80-12
WISD, J A Region 3, Chicago, Safeguards Branch 81/01/06 1p
07556 358

--8101290083 Responds to NRC 801204 ltr requesting addl info for
completion of response to 1E Insp Rept 50-155/80-12 Addl
info withheld (ref 10CFR2 790)
HOFFMAN, D P Consumers Power Co. 80/12/18 1p 07566 359

8101270860 Ack receipt of 801219 ltr informing NRC of steps taken to
correct violations noted in 1E Insp Rept 50-155/80-16 &
801219 response to 1E Bulletin 80-10
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety
Branch 81/01/08 1p 07550 134.

--8101270864 Responds to NRC 801203 ltr re violations noted in 1E Insp
Rept 50-155/80-16 Corrective actions bulletin issued
requesting radiation signs be visible, storage drums moved &
operations procedure revised
HOFFMAN, D P Consumers Power Co 80/12/19. 3pp 07550 135

8101290231 Forwards long-term evaluation criteria for scram discharge
vol sys. per util 801027 commitment & 1E Bulletin 80-17
Clarifications of applicability & results of evaluation
encl Corrective actions to be implemented by 810501.
HOFFMAN, D P Consumers Power Co. 81/01/26 11pp. 07567 175

R Periodic operating reports & related correspondence

8101130229 Forwards monthly operating rept for Dec 1980.
HARTMAN, C J Consumers Power Co. 81/01/06 1p 07452 068

--8101130233 Monthly operating rept for Dec 1980
AMSTUTZ, S Consumers Power Co. 81/01/06. 7pp. 07452 069

S Reportable occurrences, LERs & related correspondence

8101060630 Forwards LER 80-040/03L-0
FROST, B R Consumers Power Co 80/12/30. 1p 07392 168.

--8101060635 LER 80-040/03L-0 on 801202, diesel fire pump unit did not
produce full discharge pressure output until after starting
time acceptance criteria Cause undetermined Engine jacket
heater thermostat control setting increased
• Consumers Power Co. 80/12/30. 1p 07392 169.

8101060668 Forwards LER 80-048/01T-0
FROST, S R Consumers Power Co 80/12/30 1p 07400 174

--8101060674 LER 80-048/01T-0 on 801219, 150 splices & five terminal
defects were found Caused by installation of faulty
equipment in original const Splices & blocks repaired or
replaced
• Consumers Power Co 80/12/30. 2pp. 07400 175

8101120339 Forwards LER 80-045/03L-0
HOFFMAN, D P Consumers Power Co 81/01/06 1p. 07447 150

--8101120379 LER 80-045/03L-0 on 801210, check valve VRD 310 in common
control rod drive 2-inch suction line leaked in excess of
acceptable criteria Caused by slight imperfections in valve
disc due to fabrication flaws
• Consumers Power Co. 81/01/06 1p 07447 159

8101130518 Forwards LER 80-046/03L-0
HOFFMAN, D P Consumers Power Co. 81/01/07. 1p. 07454 128

--8101130525 LER 80-046/03L-0 on 801211, during specific gravity checks
of 60 cell batteries for reactor depressurizing channel A
found below required specific gravity. Caused by inadequate
cleaning & reconnecting of cell terminals
• Consumers Power Co. 81/01/07. 1p. 07454 129

DOCKETED ITEMS

--B101210422 IER 00-047/03L-0 on B01217 generator output voltage failed to build up during test start of emergency diesel generator
Caused by broken pins in plug-in socket of relay socket in regulation board Stronger socket installed.
* Consumers Power Co B1/01/14 1p 07493-131

B101230533 Forwards LER 80-030/03L-0.
HOFFMAN, O. P. Consumers Power Co B1/01/20 1p. 07512-226.

--B101230535 LER 80-030/03L-0 on B01223 monthly tests for dc batteries found overdue Caused by inadequate administrative controls & personnel error Maint dept daily working schedule form revised to include surveillance of test status board
* Consumers Power Co B1/01/20 1p. 07512-227.

B101290523 Forwards LER B1-002/01Y-0.
HOFFMAN, O. P. Consumers Power Co. B1/01/26 1p. 07575-249.

--B101290528 LER B1-002/01Y-0 on B10112 discovered potential for overpressurization of control rod drive water supply sys suction line piping Caused by addition of check valve VRO-310. Design changes will be made.
* Consumers Power Co B1/01/26. 2pp. 07575-250.

T. Hearing transcripts on non-antitrust matters

B101130282 Transcript of B10109 hearing in Bethesda, MD re spent fuel pool mod Pp 1-97
* Atomic Safety and Licensing Appeal Panel B1/01/09. 99pp.
07436-205

V. Operator Examinations

B101270373 Forwards emergency procedures & training program re recognition & mitigation of ATWS event Procedures provide emergency & off normal responses to ATWS & inability to insert control rods
HOFFMAN, O. P. Consumers Power Co. B1/01/22. 31pp 07543-052

DOCKET 50-156 UNIV. OF WISCONSIN RESEARCH REACTOR

P. Operating license stage documents & correspondence

B101260467 Submits rept of changes in facility organization RJ Cashwell is appointed reactor director, BM Matusewicz will be reactor supervisor & BI Abdel-Khalik is appointed to reactor safety committee.
CASHWELL, R. J. Wisconsin, Univ. of, Madison. B1/01/15. 1p. 07532-032

DOCKET 50-163 GENERAL ATOMIC COMPANY

Q. Inspection reports, IE Bulletins & correspondence

B101210133 Forwards 1E Insp Rpts 50-089/80-02 & 50-163/80-02 on B01215-17. No noncompliance noted
CREW, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/12/23. 2pp. 07489-355

--B101210138 1E Insp Rpts 50-089/80-02 & 50-163/80-02 on B01215-17 No noncompliance noted Major areas inspected: logs & records, review & audit & operator requalification program.
FAULKNER, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. JOHNSON, A. O. Region 5, San Francisco, Office of the Director. 80/12/23. 4pp. 07489-357.

R. Periodic operating reports & related correspondence

B101050024 Forwards B00225 ltr providing annual operating rpt for 1979. Expresses regret that original rpt submitted on B00225 was not received
MOWRY, W. R. General Atomic Co. (subs. of Gulf Oil Co.). 80/12/16. 1p. 07379-334.

--B101050028 Annual operating rpt for 1979.
MOWRY, W. R. General Atomic Co. (subs. of Gulf Oil Co.). 80/02/25. 3pp 07379-335.

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

F. Security, medical, emergency & fire protection plans

B101210195 Forwards physical security plan, Tech Spec Page 56 & other requested Natl Proposed schedule outlined for meeting prior to prehearing conference re litigable contentions W/o encls
Security plan withheld (ref 10CFR2 7901)
BACHMANN, R. O. Office of the Executive Legal Director B1/01/16 2pp 07490-042

G. Adjudicatory correspondence

B101210195 Forwards physical security plan, Tech Spec Page 56 & other requested Natl Proposed schedule outlined for meeting prior to prehearing conference re litigable contentions W/o encls
Security plan withheld (ref 10CFR2 7901)
BACHMANN, R. O. Office of the Executive Legal Director B1/01/16 2pp 07490-042

B101270202 Amend to petition for leave to intervene to establish identity & interests of individual members & authority for representation Nine affidavits & Certificate of Svc encl
ENTWISLE, E. B. Citizens for Nuclear Reactor Safety, Inc
ENTWISLE, E. B. Entwisle, E. B. B1/01/16 12pp 07546-041

B101270443 Response to Citizens for Nuclear Reactor Safety, Inc B10114 amend to petition for leave to intervene Defects re interest & standing requirements in original filing cured by petition amend Certificate of Svc encl
BACHMANN, R. O. Office of the Executive Legal Director B1/01/26 4pp. 07546-295

H. General correspondence

B101060274 Responds to B01015 ltr expressing concerns re potential health & safety risks associated w/location of Armed Forces Radiobiology Research inst in heavily populated area E18 not needed for low power reactor
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/12/11. 2pp 07397-070

--B101060277 Expresses concern re Armed Forces Radiobiology Research plans to apply for reactor facility relicensing
STEEB, H. I. Affiliation Unknown 80/10/15 4pp. 07399-073

U. Congressional/Executive Correspondence

B101100133 Forwards response to Senator Barbanes 000812 ltr re facility, providing brief description of current operating experience & upcoming renewal application
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 80/09/23 1p 07444-190

--B101100135 Requests brief paper re NRC involvement w/facility, per encl JF Ahearn memo, W/o encl
ROSE, M. Commissioners 80/00/19 1p 07444-196

B101200077 Requests preparation of E18 & public hearing prior to relicensing facility. Certificate of Svc encl.
BARNES, M. D. House of Rep. 01/01/09 3pp 07486-347

DOCKET 50-184 NATIONAL BUREAU OF OCEANOGRAPHIC REACTOR

F. Security, medical, emergency & fire protection plans

B101280575 Notification of B10122 meeting w/NBB to review physical security plans Distribution list encl.
BERNARD, H. Standardization & Special Projects Branch. B1/01/12 2pp. 07550-229

P. Operating license stage documents & correspondence

B101100253 Forwards FR notice of consideration of application for license renewal at increased power level
MILLER, J. R. Standardization & Special Projects Branch. 80/12/18. 2pp. 07443-053.

--B101100259 Notice of consideration of application for license renewal

R Periodic operating reports & related correspondence

B101060629 Forwards "Semiannual Operating Rept 28-Jul-Dec 1979."
CARTER, R S Conference, Dept of. National Bureau of Standards
80/04/08 1p 07393 063

--B101060633 "Semiannual Operating Rept 28-Jul-Dec 1979"
CARTER, R S Conference, Dept of. National Bureau of Standards.
80/04/08 3pp 07395 064

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

P. Operating license stage documents & correspondence

B101090507 Requests info re facility classification re commercial
development Annual production costs for commercial purposes
at research facility are restricted by federal regulations
SULLIVAN, C J Treasury, Dept of. 81/01/05 1p 07427 327

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

Q. Inspection reports, IE Bulletins & correspondence

B101070301 Act receipt of B01106 ltr informing NRC of steps taken to
correct violations noted in IE Insp on 800924
BOCK, M E Region 5, San Francisco, Fuel Facility & Materials Safety
Branch 00/12/04 1p 07419 212

--B101070306 Responds to NRC B01016 ltr re violations noted during IE
Insp on 800924 Corrective actions annual exposure repts for
1978 & 1979 submitted as required & more systematic
screening of FR implemented
CRAM, DALL, W E Northrop Research & Technical Center. 80/11/06
1p 07415 213

DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B101270527 Forwards physical security plan Plan withheld (ref
10CFR2 790)
FAM, R E Kansas State Univ. 81/01/12 2pp 07544 035

Q. Inspection reports, IE Bulletins & correspondence

B101070585 Forwards IE Info Notice 80-32, "Clarification of Certain
Requirements for Exclusive Use Shipments of Radioactive
Materials" No written response required
SMIEZEK, J H Division of Fuel Facility & Materials Safety
80/08/29 1p 07419 329

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

P. Operating license stage documents & correspondence

B101090098 Requests rule change for shipment of spent fuel from
Harragansett, RI to Asten, SC Police escort arranged for area
near Harrisburg, PA
DIMEGLIO, A F Rhode Island, State of 80/12/04 1p 07426 293

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

Q. Adjudicatory correspondence

B101090779 Forwards memo re preliminary estimates of resource needs
should "QESMO-type" proceeding be reinstituted Info derived
from discussion during B01201 meeting
DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director
80/12/05 1p 07309 001

--B010160686 Advises that QESMO 1976 study & rpt should be revised
pending congressional mandate to reopen hearings
DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director
80/08/08 3pp 03636 212

P. Operating license stage documents & correspondence

B101090238 Forwards West Valley facility info per B01203 Request.
Draft of Congressional Act authorizing facility and
DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director.
80/12/05 3pp 07429 316

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP hold
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FEAR
EISENHUT, D O Division of Licensing. 80/11/13 2pp

B101060408 Forwards changes to physical security plan. Changes
withheld (ref 10CFR2 790).
DITCHER, Southern California Edison Co 80/12/12 2pp
07398 079

B101100075 Requests evaluation of potential effects of earthquakes
emergency responses, including earthquakes which either
initiate or follow initiation of accidents First instance
should be included in revised emergency plan
TEDESCO, R L Assistant Director for Licensing. 80/12/17 4pp
07309 001

B101100838 Informs that licensees must conduct emergency exercise w
one yr from B10401 or prior to issuance of OL Requests
schedule of drills & exercises
ENGELKEN, R M Region 5, San Francisco, Office of the Director
80/12/19 1p 07443 257

H. General correspondence

B101300256 Responds to EK Johnson ltr re location of facilities
Earthquake hazards are being re-reviewed in connection w/OL
applications for Units 2 & 3 Facilities meet NRC siting
criteria
DICKS, W J Office of the Executive Director for Operations
81/01/15 3pp 07586 129

P. Operating license stage documents & correspondence

B101200286 Forwards "Qualification Testing of One 75-HP Submersible
Electric Motor Model 7117636003, Type CUL60 for Southern CA
Edison Co" & revised info re environ qualification of RHR
s/s
MOODY, W C Southern California Edison Co. 80/09/19 4pp.
07187 001

--B101200291 "Qualification Testing of One 75-HP Submersible Elec
Motor Model 7117636003, Type CUL88 for Southern CA Edison
Co
ANDERSON, J J, FRANZ, W. SHIPWAY, O O Wyle Laboratories 57
80/06/27 147pp 07187 001

B101220466 Ltr to all power reactor licensees & applicants forward
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issues A-12, "Potential for Low Fracture
Toughness & Lateral Tearing on Component Supports."
EISENHUT, O O Division of Licensing 80/11/26 3pp

B101160415 Forwards Ofc of Nuclear Reactor Regulation interim
assessment re "Sleeving of San Onofre, Unit 1 Steam Generator
Tubes" Util may proceed w/production insertion phase of
steam generator tube repairs
CRUTCHFIELD, O O Operating Reactors Branch 5 80/11/28 3pp
07471 025

--B101160416 Interim assessment of "Sleeving of San Onofre, Unit 1
Generator Tubes"
• Office of Nuclear Reactor Regulation, Director 80/11/30
22pp 07471 028

B101050160 Confirms proposal made by SEP owners group at B01202
meeting to assume significantly increased involvement in
completion of safety evaluation program Presentation
matl used during B01202 meeting encl
SCHAFFSTALL, R SEP Owners Group 80/12/05 12pp 07378 332

B101070362 Summarizes thoughts re NRC-Southern CA Edison Co B01201
meeting Acceptance of OELTA result, assuming 90% shear
velocity as rupture velocity, deemed premature. Extreme case
of possible parameter conditions must be considered
AKI, K Massachusetts Institute of Technology 00/12/05 2pp.
07414 330

B101120142 Informs that SEP Topic 11-2 A has been completed & for
staff safety evaluation & TX Tech rpt for facility.
Requests info within 30 days if as-built facility differs
from licensing basis Info needed to complete Topic XV-16.
CRUTCHFIELD, O O Operating Reactors Branch 5. 80/12/15 6pp.
07445 318

--B101120149 "Tornado & Straight Wind Hazard Probability for San Onofre Nuclear Power Reactor Site, CA" Sheet requesting info for SEP Topic XV-16 encl
MCBONALD, J. R. Texas Tech Univ. 80/05/31. 26pp. 07445 323

B101140059 Requests info re SEP Topic IV-2, reactivity control eye design & protection against single failures info should be provided within 90 days of receipt of ltr
CRUTCHFIELD, D. D. Operating Reactors Branch 5 80/12/15 4pp.
07458:201

B101210445 Forwards response to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame.
EISENHUT, D. O. Division of Licensing 80/12/15 13pp.

B101160029 Notification of B01218 meeting w/SEP owners group in Bethesda, MD re BEP program, schedule for licensee topic completion & assignment of lead topics to plants
RUSSELL, H. T. Technical Support Branch. 80/12/16 2pp

B101060475 Provides addl info re instrument inverters powering Vital Bus 1, 2 & 3 & operational radiation monitoring sys for review of SEP Topics VI-7, O, VI-7, C, VI-10, VII-3, VIII-2 & VIII-3
BASKIN, K. P. Southern California Edison Co. 80/12/29. 8pp.
07398 114

B101090460 Application to amend license DPR-13, submitted as ETS Proposed Change 94, requesting temp waiver for ETS 3.1.4.1, 4.2 & 4.3 re nonradiological surveillance, chlorine, fish impingement & entrainment.
BASKIN, K. P. Southern California Edison Co. 81/01/05 2pp
07442:267.

B101130289 Confirms implementation dates for approved TH1-related items contained in NUREG-0737 w/exceptions listed. Procurement or construct activities will not be initiated until NRC review & concurrence. Mode targeted for completion B0101
BASKIN, K. P. Southern California Edison Co. 81/01/05 5pp.
07451:352.

B101130247 Notifies that licensee amend Application to incorporate applicable Tech Specs for implementing TH1-2 lessons learned Category A items will be submitted by B10104
BASKIN, K. P. Southern California Edison Co. 81/01/07. 1p.
07449:360

B101130544 Submits comments on NRC draft rept on B00310 loss of saltwater cooling. Forwards addl info requested in B01223 meeting & interpretation of Tech Specs re saltwater cooling sys. Encls available in Central Files only
BASKIN, K. P. Southern California Edison Co. 81/01/12 3pp.
07517:042

B101210527 Advises that licensee inadvertently omitted info from B10103 ltr re plans for implementation of Action Item 11 K.3.25 in NUREG-0737 re effect of loss of ac power on pump seals. Evaluation will be submitted by B20101
OIECH, R. Southern California Edison Co. 81/01/13 2pp.
07489:281.

B101230477 Forwards corrected copy of "Review of Repts Oeeling w/ Simulation of Earthquake Ground Motions for San Onofre Nuclear Generators Station, Unit 1 for NRC."
OERNREUTER, D. L. Lawrence Livermore Laboratory 81/01/13 2pp
07510:292.

--B101230480 "Review of Repts Oeeling w/Simulation of Earthquake Ground Motions for San Onofre Nuclear Generators Station, Unit 1 for NRC." Corrected copy.
BERNREUTER, D. L. Lawrence Livermore Laboratory. 81/01/13 6pp
07510:294.

B101160465 Forwards Westinghouse WCAP-9032 & WCAP-9808 re main steam line integrity evaluation crack appearing instantaneously would be stable both globally & locally initial circumferential flaw would show negligible growth.
BASKIN, K. P. Southern California Edison Co. 01/01/14. 2pp.
07470:284.

--B101160473 "Mechanistic Fracture Evaluation of San Onofre Unit 1 Main Steam Line Pipe Containing Postulated Through-Wall Crack."
SWAMY, S. A., YANG, C. Y., CHIRILOS, J. N. Westinghouse Electric Corp., Nuclear Energy Systems. WCAP-9832 80/11/30. 24pp. 07470:286.

--B101160476 "Fatigue Crack Growth Evaluation for San Onofre Unit 1 Main Steam Line Pipe"
SWAMY, S. A., KAISER, W. T., CHIRILOS, J. N. Westinghouse Electric Corp., Nuclear Energy Systems. WCAP-9808 80/10/31. 31pp.
07470:310.

B101270751 Provides revised sentences to NRC radiological access occupational radiation exposure expected to result from steam generator tube sleeve, submitted by NRC 801128 ltr. Corrected Page 12, reflecting revisions, will soon be issued.
BASKIN, K. P. Southern California Edison Co. 81/01/14 2pp.
07545 275

B101300468 Responds to NRC B01215 ltr requesting response within 15 days if disagreement existed w/licensing basis assumed in SEP Topic II-2 A Assessment will be delayed until B10327
MOODY, W. C. Southern California Edison Co. 81/01/26. 1p
07582 351

B101300403 Forwards evaluation of SEP Topic VIII-3.8, "OC Power Voltage Monitoring & Annunciation," revised to reflect comments provided in B00922 ltr.
CRUTCHFIELD, D. Operating Reactors Branch 5 81/01/28 4pp
07580:346

--B101300410 "OC Power Bus Bus Voltage Monitoring & Annunciation"
Operating Reactors Branch 5. 81/01/12 3pp. 07580:350

O. Inspection reports, IE Outline & correspondence

B101050074 Forwards addl info in response to Item 2.b of IE Bulletin B0-11 re masonry wall design.
HAYNES, J. G. Southern California Edison Co. 80/11/10 21pp
07309 001.

B101210604 Forwards IE Insp Rept 50-206/80-31 on B00929-1031. No noncompliance noted
CRENS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/11/28 2pp 07488:040

--B101210608 IE Insp Rept 50-206/80-31 on B00929-1031. No noncompliance noted. Major areas inspected plant operations & maint. followup on response to IE bulletins & significant events.
MILLER, L. Region 5, San Francisco, Office of the Director
FAULKENDERBY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/11/26 12pp. 07488:050

B101050489 Forwards IE Info Notice B0-43, "Failures of Continuous Level Monitor for Ocean Discharge Vol 1 at Dresden Unit 2." No response required
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 80/12/09. 1p 07387:271

B101130638 Responds to IE Bulletin B0-21 re valve yokes supplied Melco Foundry Inc. Info will not be provided by B01205 due to number of valve manufacturers involved.
HAYNES, J. G. Southern California Edison Co. 80/12/10 1p
07453 283.

B101150832 Forwards IE Info Notice B0-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No response required
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 80/12/16. 1p. 07300 001

B101210232 Provides justification for util corrective actions re of violation from B00310 loss of saltwater cooling incident. Proposed hot shutdown time limit is consistent w/emergency operating instruction B01-3-5.74
HAYNES, J. G. Southern California Edison Co. 80/12/26 2pp
07491:360

B101270511 Requests extension until B10301 to respond to IE Bulletin B0-24, "Prevention of Damage Due to Water Leakage Inside Containment (B01017 Indian Point 2 Event)."
HAYNES, J. Southern California Edison Co. 80/12/31. 1p. 075

B101060024 Responds to IE Bulletin B0-23. No Vendor Engineering Co. solenoid valves used at facility.
HAYNES, J. G. Southern California Edison Co. 81/01/02 1p.
07399:158

B101290548 Forwards IE Insp Rept 50-206/80-29 on B01103-07 & 18- notice of violation Encls withheld (ref 10CFR2 790).
NORDERHAUO, L. R. Region 5, San Francisco, Safeguards Branch. 81/01/12. 2pp 07575:266

R. Periodic operating reports & related correspondence

B101210484 Forwards monthly operating rept for Dec 1980
CURRAN, J. M. Southern California Edison Co. 81/01/07. 1p
07490:161.

--B101210489 Monthly operating rept for Dec 1980
JOY, J. H. Southern California Edison Co. 81/01/02 3pp
07490 162

B. Reportable occurrences, LERs & related correspondence

B101160504 Forwards LER 80-039/03L-0
HAYNES, J. O. Southern California Edison Co. 80/12/23 2pp
07471 268

--B101160513 LER 80-039/03L-0 on B01012, re: maint insp revealed worn thrust bearings on all turbochargers on emergency diesel generator
1. Cause under investigation. Bearings returned to manufacturer for repair.
CLARRAN, J. H. Southern California Edison Co. 80/12/23 1p
07471 270

V. Operator Examinations

O101050376 Submits addl info re description of shift technical advisor training program & plans for requalification training per 791031 request.
HAYNES, J. O. Southern California Edison Co. 80/12/30 4pp
07383 285

B101060513 Forwards "Shift Technical Advisor Training & Requalification Program," & related info in response to NRC 801031 ltr re TMI action plan requirement.
HAYNES, J. O. Southern California Edison Co. 80/12/30 5pp
07396 040.

--B101060523 "Shift Technical Advisor Training & Requalification Program"
Southern California Edison Co. 80/12/31 31pp 07396-045

DOCKET 80-208 COLUMBIA UNIV. RESEARCH REACTOR

J. Insurance & indemnity information

B101140221 Forwards Endorsement 65 to HELIA Policy NF-60.
BREICHER, H. Columbia Univ. 80/11/19 2pp 07461 265

DOCKET 80-213 HADDAM NECK PLANT

F. Security, medical, emergency & fire protection plans

O101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FBAR.
EISENHUT, D. O. Division of Licensing 80/11/13 2pp.

B101070248 Releases public version of Revision 7 to utility emergency plan.
FELTON, J. H. Division of Rules and Records 80/12/02 1p.
07404 340

--B101070256 Public version of Revision 7 to utility emergency plan re corrected dose curves in App. B, Tables 1a, 2a & 3a.
Connecticut Yankee Atomic Power Co. 80/01/25 3pp 07404 341.

B101140445 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUDEB, J. L. Division of Rules and Records. 80/12/16 1p
07461 336

B101210151 Requests schedule of drills, exercises & scenarios re requirements of final rule on emergency planning.
GRIER, B. H. Region I, Philadelphia, Office of the Director 80/12/24 2pp. 07491 307

B101090004 Discusses utility commitments re emergency plans. Revised emergency plans addressing Revision 1 to NUREG-0654/FEMA-REP-1, App. E to 10CFR50, will be submitted by B10216.
COUNSILL, W. O. Connecticut Yankee Atomic Power Co. COUNSILL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/12/31 4pp. 07442 247

B101270712 Responds to NRC B01124 ltr re fire protection features. Protection equivalent to NRC seismic criteria provided by backfitting of seismic qualification of reactor coolant pump lubrication oil sys.
COUNSILL, W. O. Connecticut Yankee Atomic Power Co. COUNSILL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/13 4pp. 07545 269

B101290175 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUDEB, J. L. Division of Rules and Records 81/01/23 1p
07535 204

J. Insurance & indemnity information

B101260296 Forwards Endorsements 65 & 66 to ANI Policy NF-151
IFFLAND, R. R. Northeast Utilities. 81/01/21 4pp 07525 134

B101260303 Forwards Endorsement 6 to ANI Binder EB-11
IFFLAND, R. R. Northeast Utilities 81/01/21 2pp 07525 138

P. Operating license stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants. Forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing 80/11/26 8pp

B101050160 Confirms proposal made by SEP owners group at 001202 meeting to assume significantly increased involvement in completion of safety evaluation program. Presentation met with during B01202 meeting encl.
SCHAFSTALL, R. SEP Owners Group 80/12/05 12pp 07370 332

B101050447 Informs NRC that util has no substantive comments on NRC draft evaluation of SEP Topic VI-4, "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation." Outlines are not applicable.
COUNSILL, W. O. Connecticut Yankee Atomic Power Co. 80/12/00 1p
07387 264

B101060869 Requests invoice be sent to util for shipping route approval review.
MILLER, W. O. License Fee Management Branch 80/12/08 1p
07400 131

--B101060873 Forwards costs & manpower incurred in review of util for route approval.
MCCORMACK, G. W. Physical Security Licensing Branch. PARTLOW, J. O. Material Control Licensing Branch 80/11/05 2pp. 07400 132

B101070126 Forwards evaluation of SEP Topic VIII-2 re diesel generators. Rept has been revised to reflect comments provided in B01003 ltr.
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/08 12pp.
07414 229

B101070377 Forwards safety evaluation of SEP Topic 11-2 A, "Severe Weather Phenomena" & TX Tech Univ. rept, "Tornado & Straight Wind Hazard Probability for Haddam Neck Nuclear Power Reactor Site, CT."
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/08 7pp.
07404 177.

--B101070586 "Tornado & Straight Wind Hazard Probability for Haddam Neck Nuclear Power Reactor Site, CT."
MACDONALD, J. R. Texas Tech Univ. NRC-04-76-345 80/03/31 2pp.
07404 184

B101140080 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures. Info should be provided within 90 days of receipt of ltr.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/15 4pp
07458 207

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D. O. Division of Licensing 80/12/15 13pp.

B101160029 Notification of B01218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants.
RUSSELL, W. T. Technical Support Branch. 80/12/16 2pp. 07467 2

B101070179 Forwards safety evaluation of SEP Topic 11-2 A re severe weather phenomena for facility w/o encl.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/18 1p.
07414 268

--B101070183 Forwards final draft of SEP technical evaluation of Topic VIII-2 re diesel generators.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/08 12pp.
07414 269.

07442 251

B101060410 Responds to NRC B01010 request for status rept of BEP topics re loss of offsite power. Seven losses of offsite power resulting from lightning occurred during 4 yrs preceding 760601.
COUNCIL.W.O. Connecticut Yankee Atomic Power Co. 80/12/23. 1p
07399.026

B10190685 Informs that BEP Topic 111-3 B, structural & other consequences of underdrain sys failure, is applicable to facility. Mat sump has been identified beneath containment bldg.
CRUTCHFIELD.O. Operating Reactors Branch 5. 80/12/26 2pp
07476 096

B101270142 Advises that BEP Topic 111-3 B re structural consequences of underdrain sys failure is applicable to facility. Mat sump has been identified beneath containment bldg.
CRUTCHFIELD.O. Operating Reactors Branch 5. 00/12/26 2pp.
07547 236.

O101090012 Forwards summary of investigation of anchorage & support of safety-related electrical equipment, per B00720 request.
COUNCIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNCIL.W.O. Connecticut Yankee Atomic Power Co. 80/12/30 Bpp 07442 239.

B101130138 Informs that, as result of numerous changes in interpretations of NRC guidelines, info transmitted on 000429 is superseded by encl revised lists. Info not vital to safety evaluation scheduled for 010201.
COUNCIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/30 66pp 07449 238.

O101120325 Finds evaluation of BEP Topic VIII-2 to be factually correct & has no further comment.
COUNCIL.W.O. Connecticut Yankee Atomic Power Co. 80/12/31. 1p.
07447:119.

B101160240 Forwards rept on post-TMI requirements in response to NUREC-0737 & NRC B01031 ltr.
COUNCIL.W.O. Connecticut Yankee Atomic Power Co. COUNCIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/31 300pp. 07460 014

B101120327 Requests extension to B10131 for submittal of proposed Tech Spec changes re operable/operability certification.
COUNCIL.W.O. Connecticut Yankee Atomic Power Co. COUNCIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 81/01/02. 1p. 07447:110

B101210337 Forwards final NRC evaluation of BEP Topic V-10.A, "RRR Bys Heat Exchanger Tube Failures." Current sampling required by plant procedures not adequate. No chemistry limits contained in specs as required in BRP 3.2 J.
CRUTCHFIELD.O. Operating Reactors Branch 5. 81/01/13 7pp.
07407:233.

Q Inspection reports, IE Bulletins & correspondence

O101180242 Forwards IE Insp Rpt 50-213/00-19 on B01006-10. No noncompliance noted.
MARTIN.W.O. Region 1, Philadelphia, Safeguards Branch. 80/11/25. 2pp. 07465:351.

--B101130249 IE Insp Rpt 50-213/80-19 on B01006-10. No noncompliance noted. Major areas inspected security plan & organization, physical barriers in protected & vital areas & access control. Oyster withheld (ref 10CFR2 7901).
DEVILIN, J.W. Region 1, Philadelphia, Safeguards Branch.
LAOUN, R.H., SMITH, O. Region 1, Philadelphia, Office of the Director. 80/11/19 1p 07465:353.

B101070340 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 80/11/26 1p. 07414.068.

B101150028 Responds to IE Bulletin 80-23, "Failures of Bolonoid Valves Mfg by Velcor Engineering Corp." No valves w/specifed part numbers in use at facilities.
COUNCIL.W.O. Connecticut Yankee Atomic Power Co. COUNCIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/03. 1p. 07462:205.

B101160575 Ack receipt of B01016 & 1106 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rpt 50-213/80-15.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 00/12/12 1p 07471 323

--B101160580 Responds to NRC telcon re violations noted in IE Insp Rpt 50-213/80-15. Corrective actions, emergency operating procedures being accomplished by "self-study" technique & operator requalification program revised.
COUNCIL.W.O. Connecticut Yankee Atomic Power Co. 80/11/06 2pp
07471.324

--B101160507 Responds to NRC 000924 ltr re violations noted in IE Insp Rpt 50-213/80-15. Corrective actions, emergency operating procedures review being accomplished by scheduled "self-study" technique & requalification program revised.
COUNCIL.W.O. Connecticut Yankee Atomic Power Co. 00/10/16 3pp
07471:326

--B101160591 Forwards IE Insp Rpt 50-213/80-15 on 000825-28 & notice of violation.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/09/24 2pp. 07471:329.

--B101160595 Notice of violation from insp on 800825-28
* Region 1, Philadelphia, Office of the Director. 80/09/23 1p
07471 331

--B101160604 IE Insp Rpt 50-213/80-15 on 800825-28. Noncompliance noted. No evidence available to document that all operators had reviewed all emergency procedures during 1979.
WIGGINS, J.T. Region 1, Philadelphia, Office of the Director
CAPITON, D.L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 00/09/23 7pp. 07471:332

B101160855 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 80/12/16 1p 07397 001

R Periodic operating reports & related correspondence

B101220408 Forwards monthly operating rept for Dec 1980.
GRAVES, R.H. Connecticut Yankee Atomic Power Co. 81/01/12. 1p.
07505 176

--B101220410 Monthly operating rept for Dec 1980
* Connecticut Yankee Atomic Power Co. 81/01/12 Opp. 07505 176

S Reportable occurrences, LERs & related correspondence

B101090626 Forwards LER 80-017/03L-0.
GRAVES, R.H. Connecticut Yankee Atomic Power Co. 81/01/05 1p.
07442 173

--B101090632 LER 80-017/03L-0 on 800909, reactor thermal power limit exceeded. Caused by abnormal increase in oil pressure due to sticking control valve or governor. Governor adjusted & load brought down.
TEST, R.Z. Connecticut Yankee Atomic Power Co. 81/01/05. 2pp
07442 174.

B101210376 RO EOT-NR/80-213/01-01 on 001217, increased impingement rate of spottish shiners were observed. Caused by echooling habits & freezing of tributaries, resulting in uneven spatial distribution in CT River.
GRAVES, R.H. Connecticut Yankee Atomic Power Co. 01/01/13. 3pp
07469 061

B101290553 Forwards Interim rept, "Investigation of Fuel Rod Failure in CT Yankee Reactor."
COUNCIL.W.O. Northeast Utilities. 81/01/19. 2pp 07574:194

--B101290568 Interim rept, "Investigation of Fuel Rod Failures in CT Yankee Reactor."
PASUPATHI, V., KLINGENSMITH, R. Bettelle Memorial Institute, Columbus Laboratories. BCL-585-19. 80/10/30 51pp Available NRC. arc. 07574:195

V Operator Examinations

B101120237 Advises of implementation of comprehensive program to upgrade & increase shift staffing at unit
C0745BL.H 0 Connecticut Yankee Atomic Power Co 80/12/31 2pp
07445 262

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT.D 0 Division of Licensing 80/11/13 2pp

B101060142 Releases public version of unit emergency plan & State of NJ civil defense - disaster control plan.
FELTON.J.H Division of Rules and Records 80/12/03 1p
07418:001

--B101080172 Forwards public version of emergency plan, in response to NRC 791010 request State of NJ civil defense - disaster control plan encl
FINFROCK.I.R Jersey Central Power & Light Co 79/12/31 1p
07418:002

--B101080179 Public version of emergency plan, Amend 1
* Jersey Central Power & Light Co 79/11/01 200pp 07418:004

--B101080186 Public version of State of NJ civil defense - disaster control plan for major nuclear facilities Except from unit emergency plan, Amend 1 encl
* New Jersey, State of 77/11/01 250pp 07418:180.

B101120216 Forwards Revision 2 to facility security officer training & qualification plan, incorporating changes outlined in NRC B101021 ltr w/o encl
FINFROCK.I.R Jersey Central Power & Light Co 81/01/07 1p
07445 255

B101160479 Releases public version of unit emergency plan
FELTON.J.H, Division of Rules and Records 81/01/13 1p
07183 001

--B101160484 Forwards public version of preliminary emergency plan, Revision 6, (facility description & safety analysis) Further mod is required prior to implementation by B10401 Transmittal ltr & Certificate of Svc encl
FINFROCK.I.R Jersey Central Power & Light Co 81/01/05 3pp
07183 001

--B101160489 Public version of preliminary emergency plan Revision 6, (facility description & safety analysis)
* Jersey Central Power & Light Co 81/01/05 200pp 07183 001.

B101300108 Forwards facility emergency planning info for placement in LPDR w/o B101000172
SOUDEB.J.L Division of Rules and Records 81/01/16 1p
07593 081

I Financial Information

B1012160144 Forwards SEC Form 10-Q, Quarterly Financial Rept & supporting mgt comments, in response to NRC 79C921, 1109 & B00811 requests for info re significant financial developments affecting utility in restart proceeding
COHOBIN.V.H General Public Utilities 80/11/26 3pp

--B1012160154 Quarterly Financial Rept Sept 1980 & supporting mgt comments
* General Public Utilities 80/11/14 44pp

J Insurance & indemnity information

B101270753 Forwards Endorsement 73 to LELIA Policy NF-164 Endorsement 71 re advance premium for 1981 will be received & transmitted soon Due to error in numbering, no Endorsement 72 exists.
GERETY.H.F General Public Utilities - GPU Service Corp 81/01/21 3pp 07545 307

P Operating license stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT.D 0 Division of Licensing 80/11/26 8pp

B101050160 Confirms proposal made by SEP owners group at B01202 meeting to assume significantly increased involvement in completion of safety evaluation program Presentation will used during B01202 meeting encl
SCHAEFFSTALL.R SEP Owners Group 80/12/03 12pp 07378:332

B101070153 Forwards request for addl info re containment isolation
CRUTCHFIELD.D Operating Reactors Branch 5 00/12/08 4pp
07414 241

B101100048 Forwards request for addl info re bypass & reset of containment isolation & other engineered safety features of facility, Description of purge & vent valves, including diagrams, is required
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/08 4pp
07445 250

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR steam discharge sys Recommends short-term actions necessary to ensure safe operation of GE BWRs pending permanent design changes
EISENHUT.D 0 Division of Licensing 80/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp 07183:001

B101070630 Notifies that technical evaluations of SEP Topics III-10 V-11 A, VI-7 C 1, VII-3 B & VIII-4 are final NRC has received no comments re repts. Evaluations will be basic input into integrated safety assessment for facility
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/15 2pp
07415 319

B101140072 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures. Info should be provided within 90 days of receipt of ltr
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/15 4pp
07458 192

B101200639 Forwards guidelines for performing soil-structure interaction reviews for SEP facilities & simplified analytical approach for evaluating effects of soil-structure interaction using lumped parameter model
CRUTCHFIELD.D Operating Reactors Branch 5 00/12/15 2pp
07477:145

B101210445 Forwards responses to questions on Rule 50.7a, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rules until program is complete Non-SEP plants must comply within specified time frame
EISENHUT.D 0 Division of Licensing 80/12/15 13pp

B101160029 Notification of B01218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants
RUBBELL.W.T Technical Support Branch 80/12/16 2pp

B101210218 Advises that SEP review of Topic III-2 A, "Severe Weather Phenomena," has been completed Safety evaluation encl
Forwards TX Tech Univ re: "Tornado & Straight Wind Hazard Probability for Oyster Creek"
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/17 7pp
07491 315

--B101210223 "Tornado & Straight Wind Hazard Probability for Oyster Creek Nuclear Power Reactor Site, NJ"
MCBENALD.J.R Texas Tech Univ. NRC-04-76-345 80/05/31 2pp
07491 322

B101190704 Forwards request for addl info re SEP Topic VII-1 A, isolation of reactor protection sys from non-safety sys
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/26 3pp
07476 097

B101190710 Advises that NRC assessment of SEP Topic VIII-2, onsite emergency power sys, is now final & will be basic input to facility integrated safety assessment
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/26 2pp
07476:103

B101190715 Informs that SEP Topic 111-3 O. structural & ether consequences of underdrain sys failure, has been deleted from facility BEP review due to inapplicability
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/26 2pp
07476 106

B101210169 Forwards request for addl info for evaluation of BEP Topic VII-1 A re isolation of reactor protection sys from nonsafety sys Description of isolation buffer circuits used for isolation of signals to on-line computer required
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/26 3pp
07491 312

B101130047 ECOLOGICAL STUDIES OF WOOD-CORING BIVALVES IN THE VICINITY OF THE BYSTER CREEK NUCLEAR GENERATING STATION Progress Report, March-May 1980.
MAGLAHO, K E., CRACKET, L. Lahigh Univ FIN A-0415 NUREG/CR-1799
80/12/31 41pp Available at NTIS 07454 324

B101060035 Forwards request for addl info within 30 days re NRC evaluation of bypassing & resetting of engineered safety features including containment isolation sys w/o encl
CRUTCHFIELD, D Operating Reactors Branch 5 81/01/02 1p
07399 149

B101090034 Forwards info re implementation dates of NUREG-0737, proposed revised dates & justification for delays Will meet all criteria established in NUREG-0737 that require mpd
FINFROCK, I R Jersey Central Power & Light Co 81/01/06 11pp
07430 005

B101160466 Forwards request for amend to App O of License DPR-16 consisting of Tech Spec Change Request 84 Tech Specs encl
FINFROCK, I R Jersey Central Power & Light Co 81/01/08 2pp
07469 001

--B101160471 Application for amend of License DPR-16 authorizing changes to Tech Specs 2 1 1.2 1 2.2 1 4.3 3.4 5.3 2.3 4 & 5 & 6 & suspension of ETR Monitoring Sections 3 1 2A2 & 3 1 2 C for two yrs.
FINFROCK, I R Jersey Central Power & Light Co 81/01/08 43pp
07469 003

--B101160469 Tech Specs 2 1-513 1 113 1 2A-D4 1-513 1-6 1.3 1 & 2-3 & 5 7 re sampling locations
* Jersey Central Power & Light Co. 80/04/15 29pp 07469 054.

B101210347 Forwards revised safety evaluation of BEP Topic VII-1-3 A re battery capacity tests Evaluation will be used as basic input to integrated safety assessment for facility unless changes reflecting as-built facility are required
CRUTCHFIELD, D Operating Reactors Branch 5 81/01/16 3pp
07487 211

B101210349 Forwards request for addl info re SEP 111-4 C, "Internally Generated Missiles (Inside Containment)" - Response requested within 30 days of receipt of ltr.
CRUTCHFIELD, D Operating Reactors Branch 5 01/01/19 3pp
07487 208

0 Inspection reports, IE Bulletins & correspondence

B101300034 Forwards IE Insp Rept 50-219/80-26 on 000714-0801 No noncompliance noted
BRIER, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/11/12 2pp 07502 286

--B101300040 IE Insp Rept 50-219/80-26 on 000714-0001. No noncompliance noted Major areas inspected radiation protection program, including work procedures, practices, plant decontamination & housekeeping
KNAPP, P J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch PLUMLEE, K E Region 1, Philadelphia, Office of the Director 80/11/10 7pp 07582 200

B101050263 Forwards response to IE Bulletin 00-11, "Masonry Wall Design," prepared by GPU Nuclear Corp
FINFROCK, I R Jersey Central Power & Light Co 80/11/14 120pp
07384 263

B101060083 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Turbine Inlet Flange" - No written response required
BRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07396 351

B101150140 Forwards Performance Appraisal Branch Mgt Insp Rept 50-219/79-18, 50-312/80-15 & 50-287/80-21 IE Performance Appraisal Branch mgt evaluation tree w/owners guide for chart, list of licensee recipients of rpt & sample ltr encl
BRIER, B H Region 1, Philadelphia, Office of the Director 80/12/02 2pp 07466 028

--B101150195 Forwards Performance Appraisal Branch Mgt Insp Rept 50-219/79-18 on 791001-05, 15-19, 29-31, 1101, 02 & 06-00
BRIER, O H Region 1, Philadelphia, Office of the Director 80/01/04 2pp 07466 038

--B101150197 Performance Appraisal Branch Mgt Insp Rept 50-219/79-18 on 791001-05, 15-19, 29-31, 1101, 02 & 06-00
Noncompliance noted Failure to provide independent verification for removal of components App A withheld (ref 10CFR2 790)
FASANO, A N, GODY, A T Region 1, Philadelphia, Office of the Director MICKLEY, D G Region 2, Atlanta, Office of the Director 79/12/19 117pp 07466 071

--B101150195 Performance Appraisal Branch Mgt Insp Rept 50-219/79-18 on 791001-05, 15-19, 29-31, 1101, 02 & 06-00
Noncompliance noted Failure to provide independent verification for removal of components App A withheld (ref 10CFR2 790)
FASANO, A N, GODY, A T Region 1, Philadelphia, Office of the Director MICKLEY, D G Region 2, Atlanta, Office of the Director 79/12/19 117pp 07466 071

B101050138 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Bore Discharge Val at Dresden Unit 2" - No response required
BRIER, O H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07376 359.

B101140938 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Melcor Foundry Co. Inc." Suppliers being contacted to confirm that sub j parts are not in use at facility.
Completion of confirmation efforts expected by 810316
FINFROCK, I R Jersey Central Power & Light Co 80/12/09 07450 359

B101140689 Responds to IE Bulletin 80-23, "Failures of Solenoid Mfg by Velcor Engineering Corp." No sub j valves in use in safety-related function at facility
FINFROCK, I R Jersey Central Power & Light Co 00/12/12 07462 024

B101060134 Forwards IE Info Notice 80-45, "Potential Failure of Backup Manual Scram Capability" - No response required
BRIER, O H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07397 348

B101070042 Forwards Suppl 4 to IE Bulletin 00-17, "Failure of Control Rods to Fully Insert During Scram at BWR" - No written response required
BRIER, B H Region 1, Philadelphia, Office of the Director 00/12/10 1p 07413 356

B101130101 Forwards IE Bulletin 80-25, "Operating Problems w/ Rock Safety-Relief Valves at BWRs" - Written response required
BRIER, O H Region 1, Philadelphia, Office of the Director 80/12/19 1p 07449 169

R Periodic operating reports & related correspondence

B101230546 Forwards monthly operating rept for Dec 1980
FINFROCK, I R Jersey Central Power & Light Co 81/01/14 07512 270

--B101230548 Monthly operating rept for Dec 1980
BRIER, J B Jersey Central Power & Light Co 81/01/14 07512 271

B101200083 Forwards twenty-second quarterly progress rept on "Study Associated w/Oyster Creek Generating Station," for 800911-1110
FINFROCK, I R Jersey Central Power & Light Co 81/01/20 07598 012

--B101280087 Twenty-second quarterly progress rept on "Woodbury Associated w/Oyster Creek Generating Station," for 800911-1110
MACKLER, BLAKE, OELMORE, C J., WILLMAN, R E Battelle Memorial Institute, Columbus Laboratories 80/12/10 23pp

R Reportable occurrences, LERs & related correspondence

8101050379 RO 801121 Fire diesel 1-2 removed from svc to determine cause of failure to start automatically on decrease in sgs pressure. Caused by failure of corrosion resistor element in cooling water line resulting in diesel overheat. FINFROCK, I R Jersey Central Power & Light Co 00/12/17 2pp 07379 344

8101050197 Forwards LER 00-055/03L-0 FINFROCK, I R Jersey Central Power & Light Co 80/12/22 3pp 07383 205

--8101050204 LER 80-055/03L-0 on 801203, core spray sys high drywell pressure switches RV-46B, RV-46C & RV-46D tripped above Tech Spec levels. Caused by instrument repeatability switches adjusted & replacement recommended. FITZGERALD, M J Jersey Central Power & Light Co 80/12/22 1p 07383 208

8101050211 Forwards LER 80-057/03L-0 FINFROCK, I R Jersey Central Power & Light Co 00/12/23 3pp 07383 215

--8101050219 LER 00-057/03L-0 on 801205, containment spray high drywell pressure switches PI-5A, B, C & D tripped above Tech Spec levels during surveillance testing. Caused by instrument repeatability switches adjusted. CROSBY, P J Jersey Central Power & Light Co. 80/12/23 1p 07383 218.

8101050223 Forwards LER 80-056/03L-0 FINFROCK, I R Jersey Central Power & Light Co. 80/12/23 3pp 07383 211

--8101050229 LER 80-056/03L-0 on 801204, main steam line high flow sensors RE-22C & RE-22Q tripped above Tech Spec levels. Caused by instrument repeatability sensor RE-22C reset. Microswitch in sensor RE-22Q replaced. FITZGERALD, M J Jersey Central Power & Light Co 80/12/23 1p 07383 214.

8101050232 Forwards LER 80-053/03L-0 FINFROCK, I R Jersey Central Power & Light Co. 80/12/23 3pp 07384 246

--8101050259 LER 80-053/03L-0 on 801130, limiting operating condition occurred when control rod drive line pumps NC08A & NC08R removed from svc to repair leaks. Caused by personnel action. Pipes replaced & pumps returned to svc. CROSBY, P J Jersey Central Power & Light Co. 80/12/23 1p 07384 249.

8101050469 Forwards LER 80-054/03L-0 FINFROCK, I R Jersey Central Power & Light Co. 80/12/23 1p 07390 199

--8101050541 LER 80-054/03L-0 on 801130, core spray sys 1 removed from svc to inspect pumps sprayed w/water due to leaking pipes. Caused by water leaking into motor lead connection box due to worn cover gaskets & open ended conduit. CROSBY, P J Jersey Central Power & Light Co 80/12/23 3pp 07390 200

8101150492 Forwards LER 80-058/03L-0 FINFROCK, I R Jersey Central Power & Light Co 81/01/09 1p 07462:314

--8101150497 LER 80-058/03L-0 on 801211, snubbers 19/6 & 19/7 on containment spray & core spray sys failed lockup test. Caused by piston seal failures. Snubbers replaced. FITZGERALD, M J Jersey Central Power & Light Co. 81/01/09 3pp 07462:315

8101150690 Forwards LER 80-060/03L-0 FINFROCK, I R Jersey Central Power & Light Co 81/01/09 1p 07465:296

--8101150695 LER 80-060/03L-0 on 801211, during routine testing, pipe break sensors for isolation condensate return lines tripped higher than Tech Spec. Caused by instrument drift. Switches reset. CROSBY, P J Jersey Central Power & Light Co. 81/01/09 3pp 07465:297

8101230951 Forwards LER 80-059/03L-0 FINFROCK, I R Jersey Central Power & Light Co. 81/01/15 1p 07512 240.

--8101230956 LER 80-059/03L-0 on 801215, discovered that main station diesel generator monthly battery surveillance tests not performed as scheduled on 800801 & 1121. Caused by personnel error. Administrative controls implemented. CROSBY, P J Jersey Central Power & Light Co 81/01/15 3pp 07512 241

8101230960 Forwards LER 80-062/03L-0 FINFROCK, I R Jersey Central Power & Light Co 81/01/16 1p 07512 244.

--8101230964 LER 80-062/03L-0 on 801218, control rod drive line pump NC08 failed in svc. Caused by failure of pump shaft outboard of balancing disc. Pump internals & motor replaced. CROSBY, P J Jersey Central Power & Light Co 81/01/16 3pp 07512 245

8101230969 Forwards LER 80-063/03L-0 FINFROCK, I R Jersey Central Power & Light Co 81/01/16 1p 07512 248

--8101230974 LER 80-063/03L-0 on 801217, reactor trip low water level indicator switch RE-18A tripped high. Caused by instrument drift. Switch reset. FITZGERALD, M J Jersey Central Power & Light Co 81/01/16 3pp 07512 249.

8101260581 Forwards LER 80-061/03L-0 FINFROCK, I R Jersey Central Power & Light Co 81/01/16 1p 07531 115

--8101260564 LER 80-061/03L-0 on 801217, snubbers - 19/11, 19/12 & 19/13 on containment spray & core spray sys common suction header failed to lock up in compression mode. Caused by main piston seal failures. Snubbers replaced. FITZGERALD, M J Jersey Central Power & Light Co 81/01/16 3pp 07531 116

8101290546 LER 81-004/01P-0 on 810116, indications show that load on emergency diesel generators, during actual LOCA, plus loss of offsite power, plus single bus failure, could exceed full load rating. Caused by anticipated load expansion. CARROLL, J T Jersey Central Power & Light Co 81/01/16 2pp 07566:355

V Operator Examinations

8101130327 Informs of changes in shift technical advisor program. Weaknesses in training program made evident by qualification exam results will be supplemented by requalification program beginning Jan 1981. FINFROCK, I R Jersey Central Power & Light Co 81/01/07 1p 07495 362

DOCKET 80-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8101070387 Ltr to all licensees of operating reactor plants. CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR. EISENHUT, O O Division of Licensing 80/11/13 2pp

8101100046 Notifies of interim rule suspending completion dates for fire protection plans previously approved by NRC FR notice encl. EISENHUT, D O Division of Licensing 80/11/26 3pp 07443:249

8101070441 Requests extensions for completion of fire protection plans required by 790725 safety evaluation. Affected plans include protection sys, shutdown panel, sprinkler sys & ventilation penetrations. DISC, O P Niagara Mohawk Power Corp. 80/12/31 2pp 07404:322

D Adjudicatory correspondence

8101300358 Forwards NRC 810113 order modifying license & granting extension of exemption from General Design Criterion 50. Reassessment of containment design for suppression pool hydrodynamic loading conditions is required. IPPOLITO, T A Operating Reactors Branch 2 81/01/13 3pp 07586:270

--8101300373 Order modifying license & granting extension of exemption from General Design Criterion 50. Reassessment of containment design for suppression pool hydrodynamic loading conditions is required. Must be installed by 830131. EISENHUT, O O Division of Licensing 81/01/13 7pp 07586:273

I Financial information

0101060639 Forwards 000008 ltr & encls re guarantee of retrospective premium in response to 801219 ltr
RUSHMORE, J W Niagara Mohawk Power Corp 80/12/29 1p 07395 054

--0101060647 Forwards financial info re guarantee of retrospective premium, per 10CFR140.
RUSHMORE, J W Niagara Mohawk Power Corp 80/08/08 6pp
07395 055

J Insurance & indemnity information

8101060639 Forwards 800808 ltr & encls re guarantee of retrospective premium in response to 801219 ltr
RUSHMORE, J W Niagara Mohawk Power Corp 80/12/29 1p 07395 054

--8101060647 Forwards financial info re guarantee of retrospective premium, per 10CFR140.
RUSHMORE, J W Niagara Mohawk Power Corp 80/08/00 6pp
07395 055

P Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except BEP licensees) forwarding Revision 1 of inservice surveillance requirements for scrubbers under BTB License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-17 to BTB scrubber inservice insp requirements
a Division of Licensing. 80/11/20. 10pp

0101220466 Ltr to all power reactor licensees & applicants forwarding summary of 001112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamelet Tearing on Component Supports"
EISENHUT, D O Division of Licensing 00/11/26 8pp

8101190113 Ltr to all OWR licensees forwarding 001201 generic safety evaluation re OWR steam discharge sys Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes.
EISENHUT, D O Division of Licensing. 80/12/09 2pp.

--8101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating OWRs. Continued operation of plants is acceptable pending permanent design mode Criteria for implementing design mode encl
a Division of Licensing. 80/12/01 212pp 07103 001

8101120278 Forwards Amend 39 to License OPR-63, safety evaluation & notice of issuance & availability.
1PPOLITB, T A Operating Reactors Branch 2 80/12/12 2pp.
07446, 333

--8101120279 Amend 39 to License OPR-63, revising Tech Specs to allow plant operation at reduced power w/three primary coolant loops operable
1PPOLITB, T A Operating Reactors Branch 2. 80/12/12 13pp.
07446 335

--0101120281 Safety evaluation supporting Amend 39 to License OPR-63
a Office of Nuclear Reactor Regulation, Director 80/12/12. 3pp
07446 348

--8101120283 Notice of issuance & availability of Amend 39 to License OPR-63.
1PPOLITB, T A Operating Reactors Branch 2 80/12/12. 2pp
07446, 351

8101210445 Forwards responses to questions on Rule 50.71s, "Periodic Updating of FBARs" & FR notice of final rule EEP plants need not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing 80/12/15. 13pp

8101140166 Advise of possible deficiencies in Ofc of Nuclear Reactor Regulation followup of licensee. Responds to inquiry re implementation of short-term Lessons Learned requirements. Listed actions will assure that no deficiencies exist
OIRCKS, W J. Office of the Executive Director for Operations 80/12/17 4pp 07462 096.

--8101140173 Forwards results of inquiry into Ofc of Nuclear Reactor Regulation implementation of short-term Lessons Learned Category A requirements Results of 1E investigation of facility will be reviewed w/o encl
CUMMINGS, J J Office of Inspector & Auditor 80/11/12 1p
07462 099

0101140162 Forwards 801217 memo reflecting agreement outlining Nuclear Reactor Regulation & 1E responsibilities for verification of implementation of NRC action plan items
OIRCKS, W J Office of the Executive Director for Operations 80/12/23 1p 07460 355

--8101140327 Requests 800129 document outlining agreement between Nuclear Reactor Regulation & 1E re responsibilities for verification of implementation of NRC action plan items
AHEARNE, J F Commissioners 80/12/10 1p 07460 359

8101050087 Responds to NRC 801113 ltr & confirms that until will meet implementation dates in NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking"
OISE, D P Niagara Mohawk Power Corp. 80/12/29 2pp 07376 299

0101060400 Forwards documentation of TMI action items requiring 81010 submitter, per NRC 801031 request Sixteen oversize drawings encl
OISE, D P Niagara Mohawk Power Corp. 00/12/31 81pp 07392 093

8101070301 informs that mod of 1eb ventilation sys, including proportional testing, will be completed prior to startup from Spring 1981 refueling outage Procedures for sample analysis per TMI action plan to be issued by 810131.
OISE, D P Niagara Mohawk Power Corp 80/12/31 1p 07414 138.

8101120241 Forwards revised "Section XI Pump & Valve Inservice Testing Program Plan Book," incorporating comments agreed to at 001006-07 meeting w/NRC
OISE, D P Niagara Mohawk Power Corp 01/01/06 1p 07438 227

--8101120245 "Section XI Pump & Valve Inservice Testing Program Plan Book"
BEHMDT, K Nuclear Energy Services, Inc 00/12/31. 90pp.
07430 220

8101210357 Forwards EIA for chemical treatment of main condenser cooling water Effect on environ during feed of Malco 7348 & 7388 to main condenser cooling water negligible Hazleton reft to Malco Chemical Corp encl
OISE, D P Niagara Mohawk Power Corp 81/01/12 16pp. 07487, 189

8101300358 Forwards NRC 810113 order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required.
1PPOLITB, T A Operating Reactors Branch 2. 81/01/13 3pp.
07586, 270

--8101300373 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required Mods must be installed by 030131.
EISENHUT, D O Division of Licensing 81/01/13 7pp 07586, 273

8101210595 Notifies that further review of facility steam discharge for conformance w/OWR owner subgroup criteria necessary. Results of further review will be forwarded by 810202
1EMPGB, T E Niagara Mohawk Power Corp. 81/01/15. 1p 07489, 270

O. Inspection reports, 1E Bulletins & correspondence

8101300814 Forwards 1E Insp Rept 50-220/80-14 on 801014-17. No noncompliance noted.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/13 2pp. 07582 188.

--0101300019 1E Insp Rept 50-220/80-14 on 801014-17 No noncompliance noted Major areas inspected, administrative controls for surveillance procedures, surveillance testing & technician qualification
GREENMAN, E D, CHUNG, J W Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/10. 9pp. 07582, 190

8101070427 Forwards Suppl 1 to 1E Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required
GRIER, D H Region 1, Philadelphia, Office of the Director. 80/11/26 1p 07414 032

8101140695 Responds to IE Bulletin 80-23. "Failure of Bolanoid Valves
Mfg by Vactor Engineering Corp. - No subj valves in use
at facility
LEMPGES, T E Niagara Mohawk Power Corp 80/12/03 1p 07308 001.

8101050144 Forwards IE Info Notice 80-43. "Failures of Continuous Water
Level Monitor For Screen Discharge Vol at Orasden Unit 2 - No
response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/05 1p 07377 237

8101300059 Responds to IE Bulletin 80-21. "Valve Vokes Supplied by
Malcolm Foundry Co. Inc." Preliminary results of util survey
of manufacturers indicates that no subj parts were used at
facilities
LEMPGES, T E Niagara Mohawk Power Corp 80/12/08 1p 07579 328.

8101220433 Ack receipt of 801104 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rpt 50-220/80-08
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/12/11 1p 07500 194

--8101220438 Responds to NRC 801015 ltr re violations noted in IE Insp
Rpt 50-220/80-08 Corrective actions procedure delayed
requiring valves to be locked Outar door seals properly
installed
LEMPGES, T E Niagara Mohawk Power Corp 80/11/04 3pp
07500 193

--8101220442 Forwards IE Insp Rpt 50-220/80-08 on 800816-0915 & notice
of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/10/15 2pp 07500 198

--8101220445 Notice of violation from insp on 800816-0915
Region 1, Philadelphia, Office of the Director 80/10/09 2pp.
07500 200

--8101220450 IE Insp Rpt 50-220/80-08 on 800816-0915 Noncompliance
noted failure to maintain reactor bldg track bay door sealed
& to maintain valves locked.
BAUPACH, W. L. HUDSON, B. Region 1, Philadelphia, Office of the
Director KISTER, H. B. Region 1, Philadelphia, Reactor Operations
Nuclear Support Branch 80/10/09 4pp 07500 202

8101210215 Immediate Action Ltr 80-53, confirming 801211 telcon re
actions to be taken in response to IE Bulletin 80-17.
"Failure of 76 of 185 Control Rods to Fully Insert During
Screen at BHR" & NRC 801002 confirmatory order.
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/12 2pp 07488 332.

8101060148 Forwards IE Info Notice 80-45. "Potential Failure of BHR
Decup Manual Screen Capability." No response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/17 1p 07391 268

8101070064 Forwards Suppl A to IE Bulletin 80-17. "Failure of 76 of 185
Control Rods to Fully Insert During Screen at BHR - No
written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/18 1p 07414 148

8101100419 Forwards response to notice of violation & proposed
imposition of civil penalty. Separate answer will be filed on
810105 re order for mod of license & order to show cause.
DONLON, W J. Niagara Mohawk Power Corp 80/12/19 1p 07443 093

--8101100428 Opposition to NRC 801126 notice of violation & proposed
imposition of civil penalty NRC ree committed substantial
errors no risk to public health & safety was caused by util
action
DONLON, W J Niagara Mohawk Power Corp. 80/12/19 78pp
07443 096

8101130103 Forwards IE Bulletin 80-25. "Operating Problems w/Target
Rock Safety-Relief Valves at BHRs." Written response
required
GRIER, B H Region 1, Philadelphia, Office of the Director.
80/12/19 1p 07449 215

8101070448 Forwards util answer & protest to NRC order for mod of
license & order to show cause.
DONLON, W J Niagara Mohawk Power Corp 81/01/03 1p 07413 206

--8101070490 Answer & protest on behalf of util to NRC 801126 order for
mod of license & order to show cause. Noncompliance
allegations w/o foundation NRC should determine that App B
satisfies 801126 order requirements Affidavit encl
DONLON, W J Niagara Mohawk Power Corp. 81/01/03 38pp.
07413 207

--8101070451 Forwards util response to notice of violation & notice of
imposition of civil penalties
DONLON, W J Niagara Mohawk Power Corp 80/12/19 1p 07413 245

--8101070455 Response to 801126 notice of violation & notice of
imposition of civil penalties Util denies noncompliance.
Requests that NRC withdraw 801126 notice of violation,
dismiss proceeding, & eliminate civil penalties App B encl
DONLON, W J Niagara Mohawk Power Corp 00/12/19 47pp.
07413 246.

8101210159 Requests addl info to evaluate util 801219 response to
801126 notice of violation & notice of proposed imposition
of civil penalties & 801229 motion to dismiss proceeding
STELLO, V Director's Office, Office of Inspection and Enforcement
81/01/09 3pp 07491 309

R. Periodic operating reports & related correspondence

8101150501 Forwards monthly operating rpt for Dec 1980.
LEMPGES, T E Niagara Mohawk Power Corp 81/01/08 2pp 07462 318

--8101150502 Monthly operating rpt for Dec 1980
ROMAN, T W Niagara Mohawk Power Corp. 81/01/08 3pp 07462 320

8101230980 Forwards list of mode installed or completed during 1980.
omitted from rpt of operating statistics & shutdown
experience for Dec 1980
LEMPGES, T E Niagara Mohawk Power Corp 81/01/16 2pp 07103 000

G Reportable occurrences, LERs & related correspondence

8101060540 Forwards LER 80-027/03L-0
DISE, G P Niagara Mohawk Power Corp. 80/12/26 1p 07396 0311

--8101060546 LER 80-027/03L-0 on 801126 operability tests were not
immediately performed as required Caused by misunderstanding
of intent of procedure Testing performed
HARRISON, P Niagara Mohawk Power Corp. 80/12/26 1p 07396 0311

8101070500 Forwards LER 80-028/04T-0.
DISE, G P Niagara Mohawk Power Corp 80/12/29 1p 07415 0711

--8101070504 LER 80-028/04T-0 on 801215 results of 801103-26 & 1201
sample tests showed detectable 1-131 at three locations.
Caused by Chinese nuclear weapons test during Oct. Plant not
accountable for detected levels.
HARRISON, P Niagara Mohawk Power Corp 80/12/29 3pp.
07415 079

8101120335 Forwards LER 80-031/01T-0
LEMPGES, T E. Niagara Mohawk Power Corp. 80/12/30 1p 07447 15

--8101120369 LER 80-031/01T-0 on 801216 feedwater flow control valve
pneumatic positioner unit 11 vented excessive amount of air.
Caused by cracked & worn rubber goods. Rubber goods replaced
& retested
HARRISON, P Niagara Mohawk Power Corp 80/12/30 1p 07447 15

8101150679 Forwards LER 80-030/04T-0
LEMPGES, T E Niagara Mohawk Power Corp 81/01/05 1p 07469 291

--8101150684 LER 80-030/04T-0 on 801204 discovered that lower limit
detection for radiological fish analysis was not within ETB.
Caused by conversion factor Tech Spec changes proposed to
update parameter
HARRISON, P Niagara Mohawk Power Corp 81/01/03 4pp
07465 292

DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

P Operating license stage documents & correspondence

8101300711 Forwards Amend 4 to License R-101, revising physical security
plan
MILLER, J R Standardization & Special Projects Branch 81/01/19
3pp 07584 154

--8101300715 Amend 4 to License R-101, revising physical security plan
MILLER, J R Standardization & Special Projects Branch, 81/01/19
2pp 07584 157

G Inspection reports, IE Bulletins & correspondence

0101290561 Forwards IE Insp Rept 50-224/80-03 on 001202-05 No noncompliance noted
BOOK, H E Region 3, San Francisco, Fuel Facility & Materials Safety Branch 80/12/19 2pp 07575 286

--0101290565 IE Insp Rept 50-224/80-03 on 001202-05 No noncompliance noted Major areas inspected environ monitoring including effluent monitoring & TLO area studies, radiation protection program, radiation surveys & posting & labeling
GILLIB, M, WENSLAWSKI, F Region 3, San Francisco, Office of the Director BOOK, H E Region 3, San Francisco, Fuel Facility & Materials Safety Branch 80/12/19 12pp 07575 208

DOCKET 50-225 RPI CRITICAL EXPERIMENT

B Reportable occurrences, IERs & related correspondence

0101200384 PNO-1-81-07 on 810120, extreme cold resulted in line break & partial drainage of RWST to reactor room sump Sample analysis indicated no activity Reactor has been shut down since Aug 1980
REITENHAUSEN, L, CAPTON, D, SMITH, G Region 1, Philadelphia, Office of the Director 81/01/21 1p 07557 060

DOCKET 50-220 AEROTEST RADIOGRAPHY & RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

0101100234 Ack receipt of 790119 ltr submitting revisions to security plan, Class III fee requested
OIGOS, R M License Fee Management Branch 80/12/22 1p 07445 217

0101060429 Requests temporary hold on review of security plan to allow applicant to incorporate changes bringing plan up-to-date Changes in emergency elem sys & bldg configuration will be submitted within two months.
NEWACHECK, R L Aerotest Operations. 80/12/30 1p 07396 203

P Operating license stage documents & correspondence

0101220323 Informs that in-pool temporary storage procedure allowing complete defueling is scheduled for 810131-0201 Defective fuel element will be removed at that time Requests confirmation of NRC approval of Tech Spec procedure.
NEWACHECK, R L Aerotest Operations 01/01/15 4pp 07500 152

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

0101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FBAR.
EISENHUT, D O Division of Licensing 80/11/13 2pp.

0101120273 Forwards suppl to fire protection safety evaluation.
IPPOLITO, T A Operating Reactors Branch 2 00/12/02 2pp 07446 325

--0101120276 Suppl to fire protection safety evaluation, Capability to achieve & maintain safe solution to any fire situation not yet adequately demonstrated.
* Office of Nuclear Reactor Regulation, Director. 80/12/02 4pp 07446 327.

O Adjudicatory correspondence

0101070669 Forwards Deviation Disposition Requests 0001696-00001735 Documents prepared per informal discovery agreement, since record of spent fuel pool mods remains open W/O encl.
Related correspondence
FITZGERALD, R. Isham, Lincoln & Beale 81/01/03 1p 07412 050

0101300233 Forwards NRC 810113 orders for mod of licensees & granting extension of exemption Licensees must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 50.
IPPOLITO, T A Operating Reactors Branch 2 81/01/13 3pp

H General correspondence

8101290518 Advises that future correspondence should be addressed to IL Dept of Nuclear Safety, 1035 Outer Park Drive, 5th Floor Springfield, IL 62704
WRIGHT, C W Illinois, State of 81/01/22 1p 07566 357

J Insurance & indemnity information

8101090608 Forwards guarantee of payment of deferred premiums for CSIAER, J Commonwealth Edison Co 01/01/03 1p.

0101270737 Forwards Endorsement 4 to Binders E0-1, E0-2, E0-3, E0-4, E0-5, E0-6 & E0-7 evidencing secondary financial protection
OSTER, J Commonwealth Edison Co. 81/01/21 8pp 07309 001

P Operating license stage documents & correspondence

8003240364 Forwards proposed amends to App A Tech Specs to include extended exposure max average planar linear heat generation rate curves Extended exposures for fuel types have been analyzed by OE & incorporated into NEDC-24146A
PEOPLES, D L Commonwealth Edison Co 80/03/19 2pp 04309.

8101220466 Ltr to all power reactor licensees & applicants for summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 0pp

0101030160 Confirms proposal made by SEP owners group at 801207 meeting to assume significantly increased involvement in completion of safety evaluation program Presentation held used during 801202 meeting encl
SCHAEFFSTALL, R SEP Owners Group 80/12/05 12pp

8101190113 Ltr to all BWR licensees forwarding 001201 generic safety evaluation re BWR scram discharge sys Recommends short-term actions necessary to assure safe operation of CE BWRs pending permanent design changes.
EISENHUT, D O Division of Licensing 80/12/09 2pp.

--8101190141 Generic safety evaluation re short-term actions recommended to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design made Criteria for implementing design mods encl.
* Division of Licensing 80/12/01, 212pp. 07103 001.

0101070594 Forwards safety evaluation of SEP Topic II-2.A, "Severe Weather Phenomena" & IX Tech Univ rept. "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Bldg, IL."
CRUTCHFIELD, D Operating Reactors Branch 3 80/12/15 7pp 07404 289.

--8101070608 "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Bldg, IL."
MCDONALD, J R Texas Tech Univ NRC-04-76-345 00/09/71 07404 296

8101140047 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures Info should be provided within 90 days of receipt of ltr
CRUTCHFIELD, D Operating Reactors Branch 3 80/12/10 4pp 07438 210.

0101210445 Forwards responses to questions on Rule 50.71e, "Permitting of FSARs" & FR notice of final rule SEP plants need not comply w/rule until notice is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 00/12/15 17pp

8101160029 Notification of 001218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants
HUBBELL, H T Technical Support Branch 80/12/16 2pp 074

8101230329 Forwards listing of all SEP correspondence re facilities SEP owners group 001202 meeting List provides basis upon which to determine plant status Review & comments requested.
W/O encl
CRUTCHFIELD, D Operating Reactors Branch 3 81/12/22 3pp 07512 099.

B101060376 Submits addl response to NRC B00822 ltr Evaluation of Pratt & Whitney butterfly valve demonstrates that loads imposed & stresses developed in components during valve closure under LOCA event fall within acceptable limits
JANECEK, R F. Commonwealth Edison Co 80/12/26 2pp 07399 027

B101230446 Forwards Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively, safety evaluation & notice of issuance & availability
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/29 2pp 07512 139

--B101230431 Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively, authorizing one-time operation for ABH w/plant chimney monitoring sys out of svc to permit installation of required monitoring improvements
CRUTCHFIELD, D Operating Reactors Branch 5 IPPOLITO, Y A Operating Reactors Branch 2 80/12/29 8pp 07512 145

--B101230453 Safety evaluation supporting Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/29 2pp 07512 149

--B101230458 Notice of issuance & availability of Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/29 2pp 07512 151

B101050500 Forwards response to NUREG-0737 No response provided Per Dresden 1 Unit undergoing extensive mod & decontamination outage Requirements of NUREG-0737 will be addressed prior to startup of unit scheduled for June 1986.
ABEL, J B Commonwealth Edison Co 80/12/31 55pp 07385 211

B101230501 Forwards Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively, safety evaluation & notice of issuance & availability
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/31 3pp 07512 157

--B101230503 Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively, replacing Tech Spec inservice insp requirements w/program meeting 10CFR 50.55a(g)
CRUTCHFIELD, D Operating Reactors Branch 5 IPPOLITO, Y A Operating Reactors Branch 2 80/12/31 6pp 07512 160

--B101230504 Safety evaluation supporting Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/31 16pp 07512 172

--B101230505 Notice of issuance & availability of Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/31 2pp 07512 188

B101290329 Informs that SEP Topic VIII-2, onsite emergency power sys, diesel generator, will be basic input to integrated safety assessment Assessment may undergo revision if facility design changes
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/31 2pp 07575 008

B101300186 Adequacy of Station Electric Distribution Sys Voltages, Dresden Station, Units 2 & 3
USV, A C. EG&O Idaho, Inc FIN A-6237 B101300186 80/12/31 11pp 07582 308

B101090001 Forwards Revision 15 pages to CE-I-A, QA program topical rept Revisions reflect Summer 1980 addenda to Section III of ASME Code & recent ASME survey for renewal of ASME corporate certifications
ABEL, J B Commonwealth Edison Co 81/01/02, 1p 07441 007

--B101090005 Revision 15 pages to QA program topical rept.
* Commonwealth Edison Co CE-I-A R15 81/01/02, 57pp 07441 008

B101300337 Submits schedule for completion of tasks attached piping sys mods Schedule based upon preliminary engineering analysis completed to date
REED, C Commonwealth Edison Co 81/01/08 1p 07455 360

B101300470 Responds to B01114 ltr re alleged water loss from facilities Belief that no direct unmonitored water has been released from station has been repeatedly confirmed by effluent monitoring program
SCOTT, J O Commonwealth Edison Co 81/01/11 3pp 07586 265

B101300233 Forwards NRC B10113 orders for mod of licensee & granting extension of exemption Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 50
IPPOLITO, Y A Operating Reactors Branch 2 81/01/13 3pp

--B101300254 Order modifying license & granting extension of exemption Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 50 by 820731
EISENHUT, D O Division of Licensing 81/01/13 7pp 07582 155

B101200296 Advises that steam discharge sys re-evaluation has been completed. In response to NRC B01001 ltr Necessary mod will be implemented in first refueling outage beginning 820101
JANECEK, R F Commonwealth Edison Co 81/01/15 2pp 07486 240

B101260482 Forwards Revision 2 to inservice insp & testing programs, detailing testing requirements for ECCS min flow valves & associated relief request (D-10) Valves are verified to close & open during normal sys surveillance tests
JANECEK, R F Commonwealth Edison Co 81/01/16 10pp 07108 003

B101220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task III, A 2
DELGECORGE, L D Commonwealth Edison Co 81/01/19 1p 07497 014

--B101220374 Offsite Dose Calculation Sys Meteorological Monitoring, Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants, Revision 2
GOLDEN, J C Commonwealth Edison Co BRADLEY, J P. Murray & Trettel, Inc 1AHT1, O P Sargent & Lundy, Inc 80/07/31 110pp 07497 015

--B101220379 Study of Low Level Dispersion Over Northern IL
* Murray & Trettel, Inc 74/06/30 106pp 07497 159

B101260597 Forwards util B01126 revision of facility electrical drawings & marked-up version of NRC index of drawings indices available in Control Files only.
JANECEK, R F Commonwealth Edison Co 81/01/19 1p 07519 049

B101290786 Ack receipt of B01222 ltr informing NRC of wells to be sampled Requests environ contractor monthly rept.
FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 81/01/19 1p 07568 035

--B101290791 Responds to NRC B01119 ltr re well samples New samples begin Jan 1981 & be analyzed for gross alpha, gross beta & tritium
COLDEM, J C Commonwealth Edison Co 80/12/22 1p 07568 035

B101270661 Responds to NRC loss of offsite power survey status rept Partial loss of offsite power survey data should have been examined prior to processing so that only data significant to safety were included Calculated target values not valid
JANECEK, R F Commonwealth Edison Co 81/01/20 3pp 07549 006

B101270481 Advises of concurrence w/NUREG-0619 re feedwater nozzles control rod drive return line nozzle cracking. In response to NRC B01113 ltr Results of further evaluations will be submitted by B10220
JANECEK, R F Commonwealth Edison Co 81/01/22 2pp 07543 010

B101280072 Forwards revised NRC evaluation of SEP Topics III-10, A & VIII-3 B to reflect comments on matters in util B01006 ltr
CRUTCHFIELD, D Systematic Evaluation Program Branch 81/01/25 2pp 07557 089

G Inspection reports, IE Bulletins & correspondence

B101050249 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding - No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30 2pp 07389 130

B101030462 Forwards IE Bulletin 80-21, "Valve Yoke Supplied by Malco Foundry Co, Inc" Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/06, 2pp 07390 017

B101070113 Forwards IE Insp Repts 50-010/80-21, 50-237/80-23 & 50-249/80-27 on B01103-07 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/25 2pp 07415 011

--B101070118 Notice of violation from insp on B01103-07
* Region 3, Chicago, Office of the Director 80/11/24, 1p 07415 013

--B101070125 IE Insp Repts 90-010/80-21, 90-237/80-23 & 90-249/80-27 on B01103-07. Noncompliance noted failure to collect weekly cooling water sample
JANUBKA, A D., PHILLIPS, M P., PAPERIELLO, C J. Region 3, Chicago, Office of the Director. 80/11/24 10pp. 07415-014

0101050530 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Bcam Discharge Vol at Oresden Unit 2 - No response required
KEPLER, J O. Region 3, Chicago, Office of the Director 80/12/05. 2pp 07390 302.

B101090778 Forwards IE Insp Repts 90-010/80-22, 90-237/80-24 & 90-249/80-20 on B01004-1114 No noncompliance noted
HEIBMAN, R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/05 2pp 07433 245

--B101090785 IE Insp Repts 90-010/80-22, 90-237/80-24 & 90-249/80-28 on B01004-1114 No noncompliance noted Major areas inspected, operational safety verification & monthly maint observation.
TONQUE, T M., JORDAN, M J., WALKER, R O. Region 3, Chicago, Office of the Director. 80/12/05. 6pp 07430-247.

B101090132 Addl response to FOIA request for documents re imposition of civil penalties. NRC requests for congressional authorization for more severe penalties & responsibilities & behavior of nuclear plant operators Forwards documents listed in app.
FELTON, J M. Division of Rules and Records. 80/12/09 3pp. 07441 194

--B101090142 IE Insp Repts 90-237/80-16 & 90-249/80-20 on B00908-10 No noncompliance noted NRC Inspector observed two operators apparently asleep Lack of operator attentiveness is considered significant safety matter
PHILLIP, G A., NORELIOUS, C E., SPEBBARD, R L. Region 3, Chicago, Office of the Director 80/09/29. 31pp

--B101090150 Discusses IE policies for reporting, evaluating & documenting significant safety matters, in light of incident at facility. Consideration of safety significance always precedes noncompliance in evaluating any concern Related info encl
STELLB, V. Office of Inspection & Enforcement, Office of the Director 80/10/01 App.

--B101090157 Requests to review any IE noncompliance in Pa re B00808 investigation of alleged sleeping control room operators at facility & info re changing NRC requirements to cover operator sleeping on duty.
BRADFORD, P. A. Commissioners 80/10/10 1p

--B101090161 Forwards draft civil penalty package re inattentiveness of operators at facility
KEPLER, J O. Region 3, Chicago, Office of the Director 80/10/10. 53pp.

0101060073 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Valves V70900-21-1 or V70900-21-3 not used in any safety-related functions. Approx 40 manhours expended in bulletin review.
RAUBCH, T J. Commonwealth Edison Co 80/12/12 1p 07399-122

B101080060 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Bcam Capability." No written response required.
KEPLER, J O. Region 3, Chicago, Office of the Director 80/12/17 2pp. 07420, 329.

B101130140 EN-80-36 on or about 801219, notice of violation & notice of proposed imposition of civil penalty in amount of \$4,000 will be issued to licensees. Action based on alleged item of noncompliance re shipment of waste not packaged properly
HEIZGER, J. Enforcement Branch, THOMPSON, O. Director's Office. 80/12/17 1p. 07457-026

B101150240 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Bcam at BWR." Written response required.
KEPLER, J O. Region 3, Chicago, Office of the Director. 80/12/18. 1p. 07465 348.

B101050170 Forwards IE Bulletin 80-25, "Operating Problems w/Target Rack Safety Relief Valves at OHM." No response required
KEPLER, J O. Region 3, Chicago, Office of the Director 80/12/19. 2pp. 07377-301.

B101080093 Responds to NRC 800018 request for monthly status rept re evaluations in response to IE Bulletin 79-14. Tabulations of piping sys w/stresses above FBAR levels & below operability limit encl.
JANECEK, R F. Commonwealth Edison Co. 80/12/22 5pp. 07421 090

B101200135 Forwards addl response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Revised initial acceptance allowables for combined piping sys stresses during SSE event provided
JANECEK, R F. Commonwealth Edison Co 81/01/05. 6pp 07486 16

B101200155 Forwards response to IE Bulletin 80-24, "Prevention of Demage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event)." Surveillance procedures, of at least monthly repetition, will be instituted by B10601
HAUSCH, T J. Commonwealth Edison Co 81/01/05 App. 07486 202

B101260482 Forwards Revision 2 to inservice insp & testing program deleting testing requirements for ECCB min flow valves & associated relief request (B-10) Valves are verified to close & open during normal sys surveillance tests
JANECEK, R F. Commonwealth Edison Co. 81/01/16 10pp 07309 0

R Periodic operating reports & related correspondence

B101270515 Forwards monthly operating repts for Dec 1980
SCOTT, O J. Commonwealth Edison Co 81/01/19 1p 07346 299

--B101270520 Monthly operating repts for Dec 1980
MAXWELL, D C. Commonwealth Edison Co 81/01/16 16pp. 07546

S Reportable occurrences, LERs & related correspondence

B101060481 Forwards LER 80-047/03L-0.
SCOTT, O J. Commonwealth Edison Co 80/12/27 1p 07391-103

--B101060484 LER 80-047/03L-0 on 801204, pressure switch PS 261-301 level exceeded Tech Spec requirements Caused by setpoint drift. Pressure switch reset
SPEROFF, R. Commonwealth Edison Co. 80/12/29. 2pp 07391 10

B101060600 Forwards LER 80-046/03L-0 & deviation rept
SCOTT, D J. Commonwealth Edison Co 80/12/29 1p 07391 133

--B101060617 LER 80-046/03L-0 on 801202, control rod driveline vol alarm not received during reactor scram Caused by incorrect cable length & routing, incorrect transducer placement & mounting & redundant transducer signal interference
HOLLAND, P. Commonwealth Edison Co. 80/12/30 2pp 07391 12

B101060598 Forwards LER 80-045/03L-0 & deviation rept
SCOTT, O J. Commonwealth Edison Co 80/12/30 1p 07391 130

--B101060604 LER 80-045/03L-0 on 801201, LPC1 eye drywell high pressure interlock pressure switch, 1501-620, found set above limit Caused by instrument drift Instrument setpoint adjusted Monthly checks will continue
SPEROFF, R. Commonwealth Edison Co 80/12/30 2pp 07391-131.

B101260586 Forwards LER 80-048/03L-0
SCOTT, D J. Commonwealth Edison Co 81/01/14 1p 07531 119

--B101260671 LER 80-048/03L-0 on 801219, isolation valve to process switch PS-16288 for automatic shutdown found closed Caused by personnel error Valve opened
SPEROFF, R. Commonwealth Edison Co. 81/01/14 2pp 07531 12

DOCKET 50-238 NUCLEAR SHIP SAVANNAH

R Periodic operating reports & related correspondence

B101300586 Forwards "NS Savannah Operations Rept." for 1980
GARVEY, J J. Commerce, Dept. of, Maritime Administration 81/01/14 1p. 07582 303

--B101300587 "NS Savannah Operations Rept." for 1980
Commerce, Dept. of, Maritime Administration 81/01/26 3pp. 07582 304.

DOCKET 50-241 MISSISSIPPI STATE UNIV RESEARCH REACTOR

H General correspondence

B101130371 Informs that CY Carley has assumed responsibility for Raleigh homogenous reactor & is contact person for all matters re facility
PAULK, J I. Mississippi State Univ. 81/01/05 1p. 07457 018

B010120402 Forwards safety evaluation of SEP Topics 11-3 A, 11-3 B & 11-3 C re hydrology, flooding & ultimate heat sink. Evaluation will be basic input to integrated safety assessment at facility.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 14pp

F Security, medical, emergency & fire protection plans

B010120387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B010120387 & by applicants as part of FSAR.
FISHER, J. O. Division of Licensing 80/11/13 2pp

B010120368 Immediate Action Ltr 80-54, confirming until B01219 commitments re radiation protection & emergency planning. Instrumentation to meet NUREG-0578 Category A, Item 2.1 & 2.2 requirements will be installed.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/12/19 2pp 07474 274

B012790583 Release public version of evacuation time estimates for facility.
FELTON, J. H. Division of Rules and Records 81/01/27 1p 07573 267

--B010129059 Forwards public version of upgraded evacuation time estimates for facilities in response to NRC B01209 ltr.
MAIER, J. E. Rochester Gas & Electric Corp 81/01/14 23pp 07573 268

P Operating license stage documents & correspondence

7904270289 Responds to NRC 790405 ltr requesting addl info re sys req'd to Class 1E DC bus battery chargers. All chargers now in use have been part of plant configuration since 1969. Adequacy of equipment presently under review.
WHITE, L. D. Rochester Gas & Electric Corp 79/04/18 3pp.

B0101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports".
EISENHUT, D. O. Division of Licensing 80/11/26 8pp.

B01050160 Confirms proposal made by SEP owners group at B01202 meeting to assume significantly increased involvement in completion of safety evaluation program. Presentation mail used during B01202 meeting encl.
SCHAFFBIAL, R. SEP Owners Group 80/12/05 12pp

B010120476 Forwards draft technical evaluation of SEP Topic VIII-2, "Diesel Generators". Evaluation will be basic input to integrated safety assessment for facility.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 15pp 07419:258

B010100161 Responds to FOIA request for five categories of documents re transportation of Pu. Forwards documents listed in Apps A & B. Info partially withheld safeguards info (ref FOIA Exemption 3).
FELTON, J. H. Division of Rules and Records 80/12/12 6pp 07437 319

--B010100401 Discusses shipment of 720 mixed oxide fuel rods containing 47.7 kg Pu Tri-State Motor Transit will be carrier & will adopt physical protection, contingency & guard training plan of carrier Tri-State will select route to be used.
WHITE, L. D. Rochester Gas & Electric Corp 80/02/08 1p

B010120323 Forwards draft technical evaluations re SEP Topics III-1, VII-2 & VII-3. Assessment compares facility w/criteria used for licensing new facilities. Evaluation will be basic input to integrated safety assessment for facility.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 2pp 07439 163

--B010120332 "SEP Review of NRC Safety Topic III-1, Associated w/Electrical, Instrumentation & Control Portion of Classification of Structures, Components & Sys for Ginna Nuclear Power Plant."
LAUDENBACH, D. H., MAYN, H. G., OILMORE, L. W. EG&O, Inc 80/08/31 11pp 07439 165.

--B010120342 "SEP Review of NRC Safety Topic VII-2, Associated w/Electrical, Instrumentation & Control Portions of Engineered Safety Feature Sys Control Logic & Design for Ginna Nuclear Power Plant."
LAUDENBACH, D. H., MAYN, H. G., OILMORE, L. W. EG&O, Inc 80/08/31 23pp 07439 176

--B010120353 "SEP Review of SEP Safety Topic VII-01, Associated w/Electrical, Instrumentation & Control Portions of Sys Requested for Safe Shutdown of Ginna Nuclear Power Plant."
LAUDENBACH, D. H., RADOSEVIC, J. R., BRODERICK, N. E. EG&O, Inc 80/09/30 38pp 07439 199

B010120402 Forwards safety evaluation of SEP Topics 11-3 A, 11-3 B & 11-3 C re hydrology, flooding & ultimate heat sink. Evaluation will be basic input to integrated safety assessment at facility.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 14pp 07446 278

B0101280441 Forwards draft "SEP Review of NRC Safety Topic V-11.0 Associated w/Electrical, Instrumentation & Control Portions of RHR Sys for Ginna Power Plant". Compares facility against NRC criteria. Requests comments by B010130.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 2pp 07558 065

--B0101280450 Draft "SEP Review of NRC Safety Topic V-11.8 Associated w/Electrical, Instrumentation & Control Portions of RHR Sys for Ginna Power Plant".
LAUDENBACH, D. H., RADOSEVIC, J. R., OILMORE, L. W. EG&O, Inc 1183-4154 80/06/06 14pp 07558 087

B010100248 Forwards draft "SEP Review of NRC Safety Topic VII-1 A Associated w/Electrical, Instrumentation & Control Portions of Isolation of Reactor Protection Sys from Non-safety Sys for Ginna Nuclear Power Plant". Requests comments by B010130.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 2pp 07183 001

--B010100262 "SEP Review of NRC Safety Topic VII-1 A Associated w/Electrical, Instrumentation & Control Portions of Isolation of Reactor Protection Sys from Non-safety Sys for Ginna Nuclear Power Plant."
LAUDENBACH, D. H., RADOSEVIC, J. R., BRODERICK, N. E. EG&O, Inc 1183-4155 80/08/31 19pp 07183 001

B0101140070 Requests info re SEP Topic IV-2, Reactivity control sys design & protection against single failures. Info should be provided within 90 days of receipt of ltr.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/15 4pp 07496 199

B0101210174 Forwards final technical assessment of SEP Topics VI-10, testing of reactor trip sys & engineered safety features, including response time testing & VI-7 A.3 re ECCB actuation sys.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/15 22pp 07488 305

B010120445 Forwards responses to questions on Rule 90.71e, "Periodic Updating of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D. O. Division of Licensing 00/12/15 13pp.

B0101270180 Forwards safety evaluation of SEP Topic 11-2 A, "Severe Weather Phenomena" & IX Tech Univ rept. "Tornado & Straight Wind Hazard Probability for Ginna (Brookwood) Nuclear Power Reactor Site, NY".
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/15 7pp 07547:259.

--B0101270155 "Tornado & Straight Wind Hazard Probability for Ginna (Brookwood) Nuclear Power Reactor Site, NY".
MACDONALD, J. R. Texas Tech Univ NRC-04-76-345 00/09/31 127 07547 266.

B010160029 Notification of B01218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topics completion & assignment of load topics to plants.
RUSSELL, H. T. Technical Support Branch 80/12/16 2pp

B010160464 Forwards TMI action plan documentation per NUREG-0737, "Clarification of TMI Action Plan Requirements".
MAIER, J. E. Rochester Gas & Electric Corp 80/12/30 1p 07396 270

--B010160469 "TMI Action Plan INUREG-07371 Documentation".
Rochester Gas & Electric Corp 80/12/30 46pp 07396 271

B101120575 SEISMIC REVIEW OF THE ROBERT E. GINNA NUCLEAR POWER PLANT AS PART OF THE SYSTEMATIC EVALUATION PROGRAM
MURRAY, R. C., NELSON, T. A., NO. 8 Lawrence Livermore Laboratory
FIN A-0233 NUREG/CR-1821 80/12/31 155pp Available at NPB
07432 001

B101150495 Forwards util comments on SEP Topic V-11 B, "RHR Interlock Requirements (Electrical Review Only)," transmitted in NRC
B01212 1tr
MAIER, J. E. Rochester Gas & Electric Corp 81/01/08 3pp
07463 154

B101150495 Forwards comments on NRC draft assessments of SEP Topics
111-10, A, V-11 A, VI-7 C, I, VI-7 F & VIII-3 B, transmitted in
NRC B00820 1tr Final NRC assessments should not be prepared
until addl opportunity to resolve util comments is provided
MAIER, J. E. Rochester Gas & Electric Corp 81/01/08 7pp

B101150520 Forwards comments on NRC draft assessments of SEP Topics
111-10, A, V-11 A, VI-7 C, I, VI-7 F & VIII-3 B, transmitted in
NRC B00820 1tr Final NRC assessments should not be prepared
until addl opportunity to resolve util comments is provided
MAIER, J. E. Rochester Gas & Electric Corp 81/01/08 7pp
07463 138

B101200414 Requests written notification re steps taken to meet NRC
requirements re override capability of engineered safety
features sys actuation signals for containment purge valve
isolation. Response requested in 45 days
CRUTCHFIELD, D. Operating Reactors Branch 5 81/01/12 3pp
07558 075

--B101280421 Safety evaluation of override of engineered safety features
sys actuation signals for containment purge valve isolation.
Licensee design is not acceptable. Requests made Draft EEP
technical evaluation encl
* Operating Reactors Branch 5 01/01/12 9pp 07558 078

B101210299 Forwards comments on NRC B01114 safe shutdown evaluation re
SEP Topics V-10 D, V-11 A, V-11 B, VI-3 & IX-3 Integrated
approach of evaluation achieved comprehensive review
MAIER, J. E. Rochester Gas & Electric Corp 01/01/13 6pp
07492 065

B101230410 Forwards response to NRC B01215 questions re SEP Topic IV-2,
"Reactivity Control Sys." Design features which limit
reactivity insertion rates & rod malfunctions from single
failure described
MAIER, J. E. Rochester Gas & Electric Corp 81/01/19 12pp
07308 001

B101230422 Forwards preliminary response to NRC assessment of SEP Topic
111-2, A, "Bovary Weather Phenomena." Unnumbered refs ingede
verification of info Design basis wind load will be
provided, pending more detailed review
MAIER, J. E. Rochester Gas & Electric Corp 81/01/19 2pp
07511 120

B101270665 Forwards responses to SEP Topic Evaluations 111-1,
"Classification," VII-2, "Engineered Safety Feature Sys
Control Logic & Design" & VII-3, "Safe Shutdown Sys." Addl
comments will be transmitted when available.
MAIER, J. E. Rochester Gas & Electric Corp. 81/01/23 16pp
07547 009

0 Inspection reports, IE Bulletins & correspondence

B101080112 Suppls 000910 response to IE Bulletin 80-20, "Failures of
Heatinghouse Type W-2 Spring Return to Neutral Control
Switches." Mod to provide for continuous continuity testing
planned.
MAIER, J. E. Rochester Gas & Electric Corp. 80/11/17 1p.
07416 344.

B101050124 Requests existing data, summaries & records of inservice insp
tests of containments w/grafted prestressing tendons.
ORNL receiving contract to compile & review records of
tendons.
EISENHUT, D. O. Division of Licensing. 80/11/25 3pp 07378 353

B101070416 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on
Jerry Turbine Steam Inlet Flange." No written response
required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
00/11/26 1p. 07414 050

B101300064 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Hilcolm Foundry Co. Inc." No subv valve yokes used at
facility.
WHITE, L. B. Rochester Gas & Electric Corp 80/12/05 1p.
07579 329.

B101100794 Responds to IE Bulletin 80-23, "Failures of Solenoid
Mfg by Valcor Engineering Corp." No subv valves in use or
planned for use in safety-related functions at facility.
MAIER, J. E. Rochester Gas & Electric Corp 80/12/10 1p
07444 043

B101060843 Forwards IE Info Notice 80-41, "Actuation of ECCS in
Recirculating Mode While in Hot Shutdown." No written
response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
80/12/16 1p 07347 017

B Periodic operating reports & related correspondence

B101210474 Forwards monthly operating rept for Dec 1980
BAND, B. A. Rochester Gas & Electric Corp 81/01/14 1p 074

--B101210476 Monthly operating rept for Dec 1980
MCHAMMA, A. E. Rochester Gas & Electric Corp 81/01/12 5p
07493 246

B Reportable occurrences, LERs & related correspondence

791140278 Responds to Eisonhut 791008 1tr re multiple equipment
failures & surveillance testing errors. Reactor trip occurred
on 760103 when steam pressure channel 47H was isolated.
Details procedure mods implemented.
WHITE, L. B. Rochester Gas & Electric Corp 79/11/07 2pp

B101210634 Submits results of investigation re engaged barring d
for emergency diesel generator 1B. Vendor concurred that
engaged barring device would not negate starting emergency
diesel generator barring device has been removed.
BAND, B. A., MAIER, J. E. Rochester Gas & Electric Corp 80/11/
2pp. 07408 337

B101120314 Forwards LER 80-011/03L-0
MAIER, J. E. Rochester Gas & Electric Corp 81/01/09 1p
07447 138

--B101120317 LER 80-011/03L-0 on B01211, bus 17 breaker from 1B
generator failed to close. Cause not stated. Testing interval
shortened to verify operability B10106
EUDAR, E. C. Rochester Gas & Electric Corp 81/01/09 1p
07417 139

SECRET 80-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D. O. Division of Licensing 80/11/13 2pp

B101120405 Releases public version of emergency plan
FELTON, J. H. Division of Rules and Records 80/11/19 1p
07437 011.

--B101120413 Forwards public version of draft Revision 7 to eme
plan
COUNSIL, H. O., FEE, W. F. Northeast Nuclear Energy Co. (subs.
Northeast Utilities) 80/10/14 3pp 07437 013

--B101120415 Public version of draft Revision 7 to emergency pl
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities)
80/10/14 107pp 07437 016

B101090004 Discusses util commitments re emergency plans. Revised
emergency plans addressing Revision 1 to NUREG-0654/FEMA-
REP-1, App E to 10CFR50, will be submitted by B10216
COUNSIL, H. O. Connecticut Yankee Atomic Power Co. COUNSIL, H.
Northeast Nuclear Energy Co. (subs. of Northeast Utilities)
80/12/31 4pp 07442 247

B101100734 Requests that encl facility emergency planning info
publicly available w/o encl
BOUDER, J. L. Division of Rules and Records 80/12/31 1p
07445 128

B101270712 Responds to NRC B01124 ltr re fire protection featu
Protection equivalent to NRC seismic criteria provided by
backfitting of seismic qualification of reactor coolant
pump lubrication oil sys
COUNSIL, H. O. Connecticut Yankee Atomic Power Co. COUNSIL, H.
Northeast Nuclear Energy Co. (subs. of Northeast Utilities)

8101290163 Forwards facility emergency planning info to be made publicly available w/o encl
SCUDER, J. L. Division of Rules and Records 81/01/23 1p
07575 159

J Insurance & indemnity information

8101270736 Forwards Endorsement 4 to NELA Binders EB-15 & EB-16
IFFLAND, R R Northeast Utilities 81/01/22 3pp 07548 039

8101270744 Forwards Endorsements 65 & 66 to NELA Policy NF-173
IFFLAND, R R Northeast Utilities 81/01/22. 4pp. 07548 046

P Operating license stage documents & correspondence

8011800524 Advises that SEP Topics II-2 B.II-2 D.III-8 B & VI-8 should be added to 791116 list of topics removed from review due to related generic NRC activities & nonapplicability BWR BBE topic list encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/26 5pp

0101220466 Ltr to all power reactor licensees & applicants forwarding summary of 001112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lameilar tearing on Component Supports"
EISENHUT, O O Division of Licensing 80/11/26. 8pp.

8101050160 Confirms proposal made by SEP owners group at 801202 meeting to assume significantly increased involvement in completion of safety evaluation proper Presentation
natl used during 801202 meeting encl
SCHIFFSTALL, R SEP Owners Group 80/12/05 12pp

8101150033 Forwards request for addl info re bypass & reset of containment isolation sys iper SEP Topic VI-31 & other engineered safety features at facility
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/08 5pp
07462 174

8101190113 Ltr to all BWR licensees forwarding 801201 generic safety evaluation re BWR steam discharges sys. Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes
EISENHUT, O O Division of Licensing 80/12/09 2pp

--8101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp 07183 001

8101140055 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures Info should be provided within 90 days of receipt of ltr
CRUTCHFIELD, O Operating Reactors Branch 5 80/12/15. 4pp
03939 001.

8101210173 Forward safety evaluation of SEP Topic II-2.A re severe weather phenomena & "Tornado & Straight Wind Hazard Probability for Millstone Nuclear Power Reactor Site, CT."
CRUTCHFIELD, O Operating Reactors Branch 5 80/12/15. 7pp
07488 272

--8101210181 "Tornado & Straight Wind Hazard Probability for Millstone Nuclear Power Reactor Site, CT"
MCDONALD, J R Texas Tech Univ NRC-04-76-345. 80/03/31. 26pp
07488 279

8101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notices of final rule. SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame.
EISENHUT, O O Division of Licensing 80/12/15 13pp

8101160029 Notification of 801218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants
RUSSELL, M F Technical Support Branch. 80/12/16 2pp.

8101230341 Forwards listing of all SEP correspondence re facility per SEP owners group 801202 meeting list provides basis upon which to determine plant status Review & comments requested w/o encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/22. 2pp.
07512 102

8101060946 Submits daily notes for 801223 Status of facilities in 1E regions encl
BIRCKS, H J Office of the Executive Director for Operations 80/12/24 3pp 07401 107

8101270124 Advises that SEP Topic III-3 B re structural consequences underdrain sys failure is not applicable to facility & has been deleted from SEP review
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/26 2pp
07547 254

8101160363 Informs that second 10-yr insp interval commenced 801220 Util proceeding w/implementation of inservice insp & testing program per 800918 ltr
COUNSILL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) 80/12/29 1p 07470 084

8101090012 Forwards summary of investigation of anchorage & support safety-related electrical equipment, per 800728 request
COUNSILL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSILL, W O Connecticut Yankee Atomic Power Co. 80/12/30. 8pp 07442 239

8101130138 Informs that, as result of numerous changes in interpretations of NRC guidelines, info transmitted on 800429 is superseded by encl revised lists info not vital to safety evaluation scheduled for 010201
COUNSILL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) 80/12/30 6pp 07449 238

8101160240 Forwards rept on post-TMI requirements in response to NUREG-0737 & IAC 801031 ltr
COUNSILL, W O Connecticut Yankee Atomic Power Co COUNSILL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) 80/12/31 300pp 07468 014

8101120327 Requests extension to 810131 for submittal of proposed BWR spec changes re operable/operability clarification.
COUNSILL, W O Connecticut Yankee Atomic Power Co COUNSILL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) 81/01/02 1p 07447 118

8101200207 Application to amend License DPR-21, revising fire protection Section 3 F to permit util to proceed w/mods identified in NRC 780926 fire protection safety evaluation. Mods will be completed prior to return to power following 1900 outage
COUNSILL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities). 81/01/05. 9pp 07486 367.

8101300508 Forwards draft safety evaluation re SEP Topic III-7, D. "Containment Structural Integrity Test" Facts upon which evaluation is based should be examined for correctness.
CRUTCHFIELD, O. Operating Reactors Branch 5 81/01/07. 5pp
07584 298

8101270670 Advises that plans for feedwater trip for reactor vessel high water level will be postponed until TMI followup rept is complete
COUNSILL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities). 81/01/16 1p 07545 192

8101290265 Responds to NRC 801200 request for info re SEP Topic VI: "Containment Isolation Sys" Delays in delivery of equipment will delay mods Commitment will be fulfilled prior to util startup from current refueling outage
COUNSILL, W O Northeast Nuclear Energy Co (subs. of Northeast Utilities). 81/01/20 4pp 07567 171

8101290219 Responds to 801113 request for compliance w/requirements contained in NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking" All necessary mods to control rod drive line completed
COUNSILL, W O FEE, W F Northeast Nuclear Energy Co (subs. of Northeast Utilities) 81/01/22 4pp 07566 321

8101280088 Forwards request for addl info on SEP Topics VII-1, A. "Isolation of Reactor Protection Sys from Non-safety Sys, Including Qualification of Isolation Devices." & VII-2. "Engineered Safety Features Sys Control Logic & Design."
CRUTCHFIELD, O Operating Reactors Branch 5 81/01/24. 3pp.
07557 064

Q Inspection reports, IE Bulletins & correspondence

8101300720 Forwards IE Insp Rept 50-245/80-19 on 801006-09, No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/05 2pp 07583 324

DOCKETED ITEMS

--B101300727 IE Insp Rept 50-245/80-19 on B01006-09 No noncompliance noted. Major areas inspected containment integrated leak rate test procedure, containment local leak rate testing & pipe support & restraint sys
CAPTION: O L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch REK1TQ.W, W1C01NG.J Region 1, Philadelphia, Office of the Director 80/11/04 7pp. 07503.326.

B101070425 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required
GR1ER,B.H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414.035

B101150020 Responds to IE Bulletin 80-23, "Failures of Solenoid Valve Mfg by Valcor Engineering Corp." No valves w/specifiaed port numbers in use at facilities
COUNCIL,W.O Connecticut Yankee Atomic Power Co. COUNCIL,W.O Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/12/03 1p 07462.205.

B101090146 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor For Scram Discharge Val at Orosdon Unit 2." No response required
GR1ER,B.H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07377.241

B101100789 Responds to IE Bulletin 80-23, "Failures of Solenoid Valve Mfg by Valcor Engineering Corp." No sub j valves in use at facilities
COUNCIL,W.O Connecticut Yankee Atomic Power Co. COUNCIL,W.O Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/12/05 1p 07444.042.

B101150536 Ack receipt of 001016 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/00-11 & 50-336/80-09 Item E now considered as single item of noncompliance
BRUNNER,E.J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/16 1p. 07464.180

--B101150540 Responds to NRC B00922 ltr re violations noted in IE Insp Repts 50-245/80-11 & 50-336/80-09 Corrective actions advised personnel that partial sys lineups will be conducted following maint where appropriate
COUNCIL,W.O., FEE,W.F. Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/10/16 4pp. 07464.181

--B101150542 Forwards IE Insp Repts 50-245/80-11 & 50-336/80-09 on B00706-0002 & notice of violation.
BRUNNER,E.J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 00/09/22 2pp 07464.105

--B101150544 Notice of violation from insp on B00706-0002
a. Region 1, Philadelphia, Office of the Director. 80/09/16 2pp. 07464.107

--B101150546 IE Insp Repts 50-245/00-11 & 50-336/80-09 on B00706-0002 Noncompliance noted failure to require restoration of equipment following maint & failure to require radiation work permit in accordance w/procedures.
SHEDLOSKY,J.T., ZIMMERMAN,R.P. Region 1, Philadelphia, Office of the Director WEINIO,R.R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/09/16 10pp. 07464.189.

B101060139 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required.
GR1ER,B.H Region 1, Philadelphia, Office of the Director 80/12/17. 1p 07391.291

B101070066 Forwards Suppl 4 to IE Bulletin 00-17, "Failures of 76 of 183 Control Rods to Fully Insert During Scram at BWR." No written response required
GR1ER,B.H Region 1, Philadelphia, Office of the Director. 80/12/18 1p 07414.146

B101130099 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rock Safety-Relief Valves at BWRs." Written response required.
GR1ER,B.H Region 1, Philadelphia, Office of the Director. 80/12/19. 1p 07449.164.

B101160363 Informs that second 10-yr insp interval commenced 801228 Util proceeding w/implementation of inservice insp & testing program per B00918 ltr
COUNCIL,W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/29. 1p. 07470.084.

B Periodic operating reports & related correspondence

B101200274 Forwards monthly operating rept for Dec 1980
MROCKZKA,E.J Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/01/13 1p 07476.335

--B101200277 Monthly operating rept for Dec 1980
HARRALL,O Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/01/07 6pp 07476.356

B Reportable occurrences, LERs & related correspondence

B101090539 PNO-1-80-178 on 001222,Chen Nuclear tractor trailer ca low level radioactive from util was involved in traffic accident near Bordentown,NJ No visible damage to cask detected. Shipment proceeded to Barnwell,SC
CARPDELL,M., KINNEHAN,J Region 1, Philadelphia, Office of the Director 80/12/23 2pp 07375.338.

B101160541 Forwards LER 80-010/01x-1
MROCKZKA,E.J. Northeast Nuclear Energy Co (subs of Northeast Utilities) 01/01/09 1p 07471.231

--B101160613 LER 80-010/01x-1 on 001105,MSRH-32 & MSRH-20 main st support members found to have failed welds between support member & support structure. Caused by lack of penetration. Oys scheduled for reanalysis per IE Bulletin 79-14
a. Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/01/09 3pp 07471.282

B101280393 PNO-1-01-06 on B10115,high airborne radioactivity was identified on refueling floor of reactor bldg.Caused by two workers cleaning area around head of reactor below refueling floor. Whole body counts indicated 20 & 200 MPC-hrs
NIMITZ,R., WEINIO,R. CHILL,B Region 1, Philadelphia, Office of the Director 81/01/19 2pp 07957.098

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

A Application/construction stage documents & correspondence

B101060299 Forwards responses to NRC B01014 ltr re proposed inservice insp & testing program
O'TOOLE,J.D Consolidated Edison Co. of New York 80/12/22 07396.136.

F Security, medical, emergency & fire protection plans

B101090307 Ltr to all licensees of operating reactor plants,CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FBAR
EISENHUT,D.O Division of Licensing 80/11/13 2pp

B101140848 Advises of provisions of 10CFR50,App R,that are applicable to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl No open items for facility W/O encl
EISENHUT,D.O Division of Licensing 80/11/24 3pp. 07461.0

B101070250 Requests that encl emergency planning info be made publicly available. W/O encl
BRUGER,J.L. Division of Rules and Records 00/12/17. 1p 07414.297

B101230589 Forwards security plan mods. Mods withheld (ref 10CFR2 O'TOOLE,J.D Consolidated Edison Co. of New York 81/01/16 93196.249.

G Adjudicatory correspondence

B101100629 Forwards revised order for mod of license,correcting B00829 order. Hearing date also revised
EISENHUT,D.O. Division of Licensing 80/09/19 3pp 07444.0

--B101108636 Revised order amending Licensee DPR-23 Info requested Bulletin 79-010 must be submitted to IE by 801101.
EISENHUT,D.O. Division of Licensing 00/09/19. App 07444.0

B101160246 Order denying request for reconsideration of Commission B00538 order but directing ASLO to conduct discretionary proceeding using full adjudicatory format. Listed issues must be addressed. Certificate of Svc encl
CHILL,B.J. Office of the Secretary of the Commission 81/01/19 19pp 07470.228

B101270319 Requests that public hearings re emergency response plans be rescheduled to earlier date
DELBELLO, A. B. Westchester County, NY B1/01/08. 2pp 07546 021

B101220139 Forwards util response to B01219 notice of violation & notice of proposed imposition of civil penalty from insp of control room activities.
O'TOOLE, J. D. Consolidated Edison Co. of New York B1/01/13 2pp 07496 064

--B101250140 Response to notice of violation from insp of control room activities. Procedure change not contrary to Tech Specs & did not involve unreviewed safety question. Alleged noncompliance not in "violation" category. Request proceeding dismissal.
O'TOOLE, J. D. Consumers Power Co. B1/01/13 9pp 07496 066

--B101220147 Response to notice of proposed imposition of civil penalty from insp of control room activities. Imposition of civil penalty inappropriate & unreasonable w/no remedial or deferential value. Requests that no penalty be imposed.
O'TOOLE, J. D. Consolidated Edison Co. of New York B1/01/13 6pp 07496 075

B101270047 Requests hearing on compaction of spent fuel pool & consequences
MILT, J., AUDIN, L., CCHREN, D. Public Interest Research Group, New York B1/01/19. 2pp. 07547-023

II. General Correspondence

B101190190 Responds to B01027 mailgram expressing concern re containment flooding incident at facility. NRC is investigating incident & has imposed civil penalties on util.
EISENHUT, D. O. Division of Licensing B01/12/30. 1p. 07475 311.

--B101190197 Expresses concern re containment flooding incident at facility.
HARRISON, J. New York, State of B01/10/27 1p 07474 312

--B101190202 Expresses concern re containment flooding incident at facility.
HARRISON, J. New York, State of B01/10/27 1p 07475 313

--B101190207 Expresses concern re containment flooding incident at facility.
HARRISON, J. New York, State of B01/10/27 1p 07475 314.

--B101190214 Expresses concern re containment flooding incident at facility.
HARRISON, J. New York, State of B01/10/27. 1p 07475 315

B101370506 Forwards response to B01204 ltr requesting response to consistent questions re containment flooding at facility on B01017. Inadequate mgt control & maint of leak detection sys were primary contributors to event.
BIRCHS, M. J. Office of the Executive Director for Operations B1/01/07 3pp 07309 001

--B101270508 Requests response to encl J Barrowe B01118 questions re B01017 containment flooding at facility.
EMERY, D. F. House of Rep B01/12/04 2pp 07309:001

B101260199 Supports shutdown of facilities
AUREY, C. Affiliation Unknown B1/01/09 1p. 07523 303.

B101280335 Requests NRC ltr to util re B01017 containment flooding event & util response
LEHIS, M. Affiliation Unknown B1/01/10 1p 07187 001

B101270304 Requests info re B10110 constituent ltr requesting safety hearings be held for facilities. Ltr encl.
WILLIAMS, H. A. Senate B1/01/15. 1p 07309 001

B101280272 Supports shutdown of facility
SCLIO, J. Affiliation Unknown B1/01/20 1p 07308:001

B101280605 Supports revocation of license
ALAGO, A., MCILLICUDDY, C., WILLOUGHBY, R. M. Affiliation Unknown B1/01/22 1p 07557 285

P. Operating license stage documents & correspondence

B101100629 Forwards revised order for mod of license, correcting refs in B003829 order. Hearing date also revised.
EISENHUT, D. O. Division of Licensing B01/09/19 3pp. 07444:030

--B101100636 Revised order amending license DPR-23 info requested by Bulletin 79-03B must be submitted to IE by B01101
EISENHUT, D. O. Division of Licensing B01/09/19 6pp 07444 030

B101230376 FOIA request for documents re Task Force on Indian Operation of Indian Point submitted to NRC B00601-1114
MILT, R. R. New York Univ B01/11/17 1p 07558 062

B101100254 Ltr to all licensees except SEP licensees forwarding Revision 1 of in-service surveillance requirements for scrubbers under ATG License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D. O. Division of Licensing B01/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 20.B 3/4 7-5 & 7-6 & 6-17
ATG scrubber in-service insp requirements
* Division of Licensing B01/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports".
EISENHUT, D. O. Division of Licensing B01/11/26 8pp 07501 234

B101210445 Forwards responses to questions on Rule 50.71a, "Periodic Updating of FSARS" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D. O. Division of Licensing B01/12/15 13pp

B101150065 Forwards safety evaluation re susceptibility of safety-related sys to flooding from failure of Noncategory 1 sys.
VAROA, B. A. Operating Reactors Branch 1 B01/12/18 2pp 07463 001

--B101150070 Safety evaluation re susceptibility of safety-related sys to flooding from failure of Noncategory 1 sys.
* Operating Reactors Branch 1 B01/12/10 2pp 07463 008

--B101150456 "Technical Evaluation of the Susceptibility of Safety-Related Sys to Flooding Caused by Failure of Noncategory 1 Sys for Indian Point 2".
LATONRE, V. R., VICTOR, R. A. Lawrence Livermore Laboratory B01/11/30 16pp 07463 009

B1012290220 Forwards "Rept on 1978-1979 Studies to Evaluate Catch Efficiency of 1 Or-2 Epibenthic Sled" Certificate of Svc encl.
O'TOOLE, J. D. Consolidated Edison Co. of New York B01/12/19 3pp 07345 069.

--B1012290323 "Rept on 1978-79 Studies to Evaluate Catch Efficiency of 1 Or-2 Epibenthic Sled".
* Texas Instruments, Inc B01/09/30 36pp 07345 072

B101060464 Forwards response to NRC B01031 ltr re Item E.2 of B00211 Confirmatory Order. Changes will be made before unit returns to svc from present refueling/maint outage. Also forwards change of schedule for implementation of Item F.2.
O'TOOLE, J. D. Consolidated Edison Co. of New York B01/12/29 7pp 07398:216.

B10106045D Forwards supplemental response to NRC 790509 ltr re PHR feedwater lines. Details welding procedures employed, defects & post-weld heat treatment.
O'TOOLE, J. D. Consolidated Edison Co. of New York B01/12/31 7pp 07396:092.

B101060454 Submits addl clarifications per B00801 ltr re installation of undervoltage relays on buses 2A, 3A, 5A & 6A. Relays will be set at .84 p.u. unit on 460 volt w/time delay of 130-0.
O'TOOLE, J. D. Consolidated Edison Co. of New York B01/12/31 2pp 07396 090

B101130711 "Adequacy of Station Electrical Distribution Bye Voltage Indian Point Nuclear Station, Unit 2." preliminary technical evaluation repl.
WEBER, D. A. Idaho National Engineering Laboratory FIN A-6226. B101130711. B01/12/31 14pp 07454 019

B101290671 Forwards Westinghouse responses & rept "Radiation Dose Terminal Block," discussed in B01031 ltr re electrical equipment environ rept. Proprietary portions withheld (ref ECFR2 790).
O'TOOLE, J. D. Consolidated Edison Co. of New York. B1/01/14 45p 07308 001.

--B010290676 Forwards eddl info requested in NRC 751218 ltr re WCAP-7929.
"Fan Cooler Motor Unit Test " Requests withholding
EICHELOINER, C Westinghouse Electric Corp 76/03/31 23pp
07308 001

B010210591 Informs that response to NRC B00827 ltr re valve
qualification program for containment purge & pressure
relief isolation valves will be provided by B01019 BRP & 2 4
Revision 1 & associated position CDB A-4 to be forwarded
B'BOULE, J D Consolidated Edison Co of New York 81/01/15 1p
07489 252

B010220362 Forwards "1978 Yr Class Rpt for Multiplant Impact Study
of Hudson River Estuary " Affidavit of svc encl Rpt
available in Central Files only
O'TOOLE, J O Consolidated Edison Co of New York 81/01/16 4pp.
07517 030

B010280365 Responds to FOIA request for documents re Task Force on
Interim Operation of Indian Point submitted to NRC after
B00531 Forwards App A documents App B documents withheld
(ref FOIA Exemption 5)
FELTON, J H Division of Rules and Records 81/01/21 3pp
07550 059.

--B010280381 Forwards draft risk analysis for facilities. Probability of
severe core damage is slight, taking into account
improvements made or committed to as of early 1980 W/o encl
FONTEICILLA, H Commissioners. 80/06/13. 1p.

--B010280388 Staff requirements memo re B00626 briefing on
recommendations of facility task force. Commission took no
action during meeting. Task force rpt & other info re
facility operation will be reviewed further.
CHILK, O J Office of the Secretary of the Commission. 80/06/30
1p

--B010280396 Discusses review of task force rpt on interim operation of
facilities. Interim operation poses no undue risk to public &
environ health & safety. Facilities should be permitted to
continue operation during proceedings.
HENORIE, J M Commissioners. 80/07/02 1p.

--B010280402 Provides JM Hendrie comments on order re interim operation
of facility. Specific language of order should be modified.
Decision on interim operation depends more heavily on task
force results.
HABBEILL, D F Commissioners. 80/06/22. 1p

0 Inspection reports, IE Bulletins & correspondence

B01080117 Submits schedule planned for response to item 2b of IE
Bulletin 80-11, "Masonry Wall Design " Study will be
completed by May 1981. w/final rpt submitted by B06615
Criteria & justification will be sent by B01231.
ZARAKAS, P Commonwealth Edison Co 00/11/07 2pp. 07416 345.

B010300143 Forwards IE Insp Repts 90-003/80-02 & 90-247/80-14 on
B00903-04 No noncompliance noted
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety
Branch. 80/11/10. 2pp 07583 105

--B010300151 IE Insp Repts 90-003/80-02 & 90-247/80-14 on B00903-04 No
noncompliance noted. Major areas inspected: meteorological
monitoring sys including monitoring equipment & support
facilities in emergency operations facility.
JACKSON, T J Region 1, Philadelphia, Office of the Director.
DOBBS, R J Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch. 80/10/24. 7pp 07583 107.

B01060090 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on
Terry Turbine Steam Inlet Flange " No written response
required.
GRIER, B H Region 1, Philadelphia, Office of the Director
00/11/26. 1p 07396 342.

B01080387 Forwards Insp rpt summarizing results of NRC mgt &
technical review of Con Ed. Decision made to re-evaluate mgt
structure. In light of leak of 100,000 gallons of water into
containment at facility W/o encl.
ORCKS, W J Office of the Executive Director for Operations.
80/12/19. 2pp 07417 335

B01060891 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown." No written
response required.
GRIER, B H Region 1, Philadelphia, Office of the Director.
80/12/16 1p. 07397 005

B01030159 EN-80-57 on or about 001219, notice of violation & not
proposed imposition of civil penalties in amount of \$5,000
will be issued to licensee Activin based on alleged item of
noncompliance re changes in procedure w/o NRC approval
RIEGLAND, J Enforcement Branch THOMPSON, D Director's B'f
80/12/17 1p 07457 027

B01050975 Ack receipt of B01117 ltr informing NRC of steps taken
correct violations noted in IE Insp Rpt 90-247/80-13
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch. 80/12/17 1p 07464 242

--B01050978 Responds to NRC B01017 ltr re violations noted in IE
Rpt 90-247/80-13. Corrective actions revised procedure
IPC-A-087 "Lithium by Atomic Absorption" has been issued.
Include acceptance criteria
ZARAKAS, P Consolidated Edison Co of New York 80/11/17
07464 243

--B01050980 Forwards IE Insp Rpt 90-247/80-13 on B00818-22 & n
violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch. 80/10/17 2pp 07464 245

--B01050981 Notice of violation from Insp on B00818-22
* Region 1, Philadelphia, Office of the Director. 80/10/19
07464 247

--B01050985 IE Insp Rpt 90-247/80-13 on B00818-22. Noncompliance
failure to follow written procedures & to perform calibr
tests in accordance w/procedural steps per Tech Specs
CHUNG, J H MCCANN, J Region 1, Philadelphia, Office of the
Director ONEEN, M L O Region 1, Philadelphia, Reactor
Operations Nuclear Support Branch. 80/10/15 17pp 07464.

B01060299 Forwards responses to NRC B01014 ltr re proposed Insp
insp & testing program
O'TOOLE, J O Consolidated Edison Co of New York 80/12/22
07396 136

B010220130 Forwards util response to B01219 notice of violation
notice of proposed imposition of civil penalty from Insp
of control room activities
O'TOOLE, J O Consolidated Edison Co of New York 81/01/13
07496 061

--B010220140 Response to notice of violation from Insp of control
activities. Procedure change not contrary to Tech Specs & did
not involve unreviewed safety question. Alleged noncompliance
not in "violation" category. Requests proceeding dismissal.
O'TOOLE, J O Consumers Power Co 81/01/13 9pp 07496 06

--B010220147 Response to notice of proposed imposition of civil
penalty from Insp of control room activities. Imposition of civil
penalty inappropriate & unreasonable w/no remedial or
deferment value. Requests that no penalty be imposed.
O'TOOLE, J O Consolidated Edison Co of New York 81/01/13
07496 075

B010270190 Forwards notice of violation & proposed imposition of
penalty & util B010103 answer re leakage of river water into
containment bldg. in response to request IE Bulletin 80-24
issued to preclude similar event
BNTZEK, J H Division of Resident & Regional Reactor Inspection
81/01/13 2pp 07543 107

--B010270194 Responds to NRC B01211 notice of violation & proposed
imposition of civil penalty based on investigation re water
leakage into containment bldg. Differing views on issues have
been cited in encl reply statement & answer to notice.
O'TOOLE, J O Consolidated Edison Co of New York. 81/01/05
100pp 07543 114.

B010220315 Confirms profilometry sys in current steam generator
program. Four tubes in steam generator 22 not passing 610
probe will remain in svc as special test cases to benchmark
predictive capability of profilometry technique.
O'TOOLE, J O Consolidated Edison Co of New York 81/01/16.
07500 156

R Periodic operating reports & related correspondence

B010140316 Forwards "1977 Yr Class Rpt for Multiplant Impact Study of
Hudson River Estuary " Certificate of Svc encl.
O'TOOLE, J O Consolidated Edison Co of New York 80/12/19.
07459 001.

--B010140326 "1977 Yr Class Rpt for Multiplant Impact Study of
River Estuary "
* Texas Instruments, Inc. 80/07/31 700pp 07459 004.

DOCKETED ITEMS

8101230582 Forwards tabulation of daily record of fish collections for Dec 1980
O'TOOLE, J O Consolidated Edison Co of New York 81/01/13 5pp
07510 279

S Reportable occurrences, LERs & related correspondence

8101090467 Forwards info in response to NRC concerns re 801017 incident of water in containment bldg info, including eight oversize drawings, available in Central Files only Proprietary rept.
WCAP-9822, withheld (ref 102FR2 790).
O'TOOLE, J O Consolidated Edison Co of New York 80/12/22 2pp
07505 242

8101050348 Forwards LER 80-015/03L-0
O'TOOLE, J O Consolidated Edison Co of New York 80/12/29 1p
07385 090

--8101050353 LER 80-015/03L-0 on 801129, setpoint for two low level alarms found 4-ft below rim level caused by alarm setpoint drift of level controller & bistable Zener diode in bistable power supply replaced Setpoints reset
MAKEPEACE, J M Consolidated Edison Co of New York 80/12/29 1p 07385 091

8101290355 Response to request for assistance re Oct 1980 incident. Event did not constitute public health hazard. Particulate examination of appropriate vessel welds found no indications of cracking
EISENHUT, D G Division of Licensing 80/12/31 2pp 07575 606

8101210102 Forwards responses to 801125 questions re 001017 containment flooding event at facility, investigation rept of event & ltr sent to util forwarding notice of violation & proposed imposition of civil penalties
STELL, V Director's Office, Office of Inspection and Enforcement 81/01/05 13pp 07491 075

8101210459 RD 81-001/01 review of svc water piping associated w/ containment fan coolers showed return lines from motor coolers are not equipped w/ monitors to detect presence of radioactivity under certain LOCA conditions
MCNITT, W A Consolidated Edison Co. of New York 81/01/09 3pp
07493 165

8101260374 PND-1-81-05 on 810112, monthly sample of auxiliary boiler condensate return identified 10-5 uCi/ml activity, primarily Co-134 & Co-137 Monitor should have detected activity but solenoid valve found closed in sample line
PLUMLEE, X. WHITE, J. CROCKER, M W Region 1, Philadelphia, Office of the Director, 81/01/13 2pp 07557 061

8101210434 Forwards LER 81-002/99X-0.
O'TOOLE, J O Consolidated Edison Co of New York 81/01/15 1p.
07493 148

--8101210440 LER 81-002/99X-0 on 810106, grid strap damage in form of torn or missing corners found on Westinghouse 1515 (9 grid) fuel assemblies Cause under evaluation Revised LER to be submitted.
MAKEPEACE, J M Consolidated Edison Co of New York 81/01/15 1p. 07493 149

8101270654 RD 81-005/01 on 810120, apparent cled perforation found on fuel rod within assembly Cause & corrective actions under evaluation
MCNITT, W A Consolidated Edison Co. of New York 81/01/20 2pp
07309 001.

8101270679 Forwards LER 80-017/03L-0.
O'TOOLE, J O Consolidated Edison Co of New York 81/01/20 1p
07545 227.

--8101270689 LER 80-017/03L-0 on 801223, five of first 10 snubbers tested did not meet acceptance criteria for lock-up rate & bleed Cause not stated. Defective snubbers will be replaced Revised LER will be submitted following test completion.
MAKEPEACE, J M Consolidated Edison Co of New York 81/01/20 1p. 07183 001

8101270724 Forwards LER 81-001/01T-0
O'TOOLE, J O Consolidated Edison Co. of New York 81/01/20 1p.
07548 112

I Hearing transcripts on non-antitrust matters

8101120206 Commission determination releasing transcript of 801210 discussion of Indian Point enforcement action
CHILK, S J Office of the Secretary of the Commission 80/12/13 2pp 07438 132

--8101120288 Marked-up transcript of 801210 closed discussion of Point enforcement action Pp 1-77 Supporting documentation encl.
* Commissioners 80/12/10 67pp 07438 134

V Operator Examinations

8101130364 Response to NRC 800731 ltr re interim criteria for shift staffing. Training class for add'l licensed reactor operator will start 810202 Interim staffing criteria will be fully met no later than 820701
O'TOOLE, J O Consolidated Edison Co of New York 81/01/07 07454 352

DOCKET 80-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP h & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 010102 & by applicants as part of FEAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

8101120273 Forwards suppl to fire protection safety evaluation
IPFOLLIO, T A Operating Reactors Branch 2 80/12/02 2pp.
07446 325

--8101120276 Suppl to fire protection safety evaluation Capabilities to achieve & maintain safe solution to any fire situation not yet adequately demonstrated
* Office of Nuclear Reactor Regulation, Director 80/12/02 07446 327

G Adjudicatory correspondence

8101090669 Forwards Deviation Disposition Requests 0001696-00001 Documents prepared per informal discovery agreement, since record of spent fuel pool mode remains open w/o encl.
Related correspondence
FILLI, B BONS, R Isham, Lincoln & Beale 81/01/05 1p. 07442

H General correspondence

8101290518 Advise that future correspondence should be addressed to Dept of Nuclear Safety, 1035 Outer Park Drive, 9th Floor Springfield, IL 62704
WRIGHT, O H Illinois, State of 81/01/22 1p 07566 357.

J Insurance & indemnity information

8101090608 Forwards guarantee of payment of deferred premiums for
OSTER, J Commonwealth Edison Co 81/01/05 1p

8101270737 Forwards Endorsement 4 to Binders EB-1, EB-2, EB-3, EB-2 EB-30, EB-42 & EB-43 evidencing secondary financial protection
OSTER, J Commonwealth Edison Co 81/01/21 8pp 07309 001.

P Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except BEP licensees) forwarding Revision 3 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D G Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28, 8 3/4 7-5 & 7-6 & 878 snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

DOCKETED ITEMS

D01190113 Ltr to all BWR licensees forwarding D01201 generic safety evaluation re DWR steam discharge sys. Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes
EISENHUT, D. G. Division of Licensing 80/12/09 2pp

--B01190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl
• Division of Licensing 80/12/01 212pp 07183.001

B01070594 Forwards safety evaluation of BEP Topic II-2 A, "Severe Weather Phenomena" & TX Tech Univ rept. "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Site, IL."
CRUTCHFIELD, D. Operating Reactors Branch 5 00/12/15 7pp.
07404.269.

--B01070608 "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Site, IL."
HCB0:WALD, J. R. Texas Tech Univ NRC-04-76-343 80/05/31 26pp
07404.276.

B01210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FBARs," & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame
EISENHUT, D. O. Division of Licensing 00/12/15 13pp

B01060946 Submits daily notes for 001223 Status of facilities in five IE regions encl.
DIRCKB, W. J. Office of the Executive Director for Operations.
80/12/24 3pp.

B01060376 Submits addl response to NRC 000022 ltr Evaluation of Pratt 6-inch butterfly valve demonstrates that loads imposed & stresses developed in components during valve closure under LOCA event fall within acceptable limits
JANECEK, R. F. Commonwealth Edison Co. 80/12/26 2pp 07399.027.

B01230446 Forwards Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively, safety evaluation & notice of issuance & availability
CRUTCHFIELD, D. Operating Reactors Branch 5. 00/12/29 2pp
07512.139

--B01230451 Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively, authorizing one-time operation for 40-h w/plant chimney monitoring sys out of svc to permit installation of required monitoring improvements.
CRUTCHFIELD, D. Operating Reactors Branch 5. 1PPOLITO, T. A. Operating Reactors Branch 2. 80/12/29. 0pp 07512.141.

--B01230453 Safety evaluation supporting Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively
• Office of Nuclear Reactor Regulation, Director 80/12/29. 2pp.
07512.149

--B01230498 Notice of issuance & availability of Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively.
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/29 2pp.
07512.151

B01050500 Forwards response to NUREC-0737. No response provided for Dresden 1 Unit undergoing extensive mod & decontamination outage. Requirements of NUREC-0737 will be addressed prior to startup of unit scheduled for June 1986
ABEL, J. B. Commonwealth Edison Co 80/12/31 55pp 07385.211.

B01230501 Forwards Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively, safety evaluation & notice of issuance & availability
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/31 3pp
07512.157.

--B01230503 Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively, replacing Tech Bpac inservice insp requirements w/program meeting 10CFR 50.55a(g).
CRUTCHFIELD, D. Operating Reactors Branch 5. 1PPOLITO, T. A. Operating Reactors Branch 2. 00/12/31 6pp 07512.160.

--B01230504 Safety evaluation supporting Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively
• Office of Nuclear Reactor Regulation, Director 80/12/31. 16pp. 07512.172.

B010300185 "Adequacy of Station Electric Distribution Sys Voltages, Dresden Station, Units 2 & 3."
UDY, A. C. EOLC Idaho, Inc FIN A-6237 B01030186 80/12/31
11pp 07562.300

B01090001 Forwards Revision 15 pages to CE-1-A.0A program topical rept. Revisions reflect Burner 1980 addenda to Section III of ASME code & recent ASME survey for removal of ASME corporate certifications
ABEL, J. B. Commonwealth Edison Co B1/01/02 1p 07441.007

--B01090005 Revision 15 pages to 0A program topical rept.
• Commonwealth Edison Co CE-1-A R15 B1/01/02 57pp
07441.008

B01130337 Submits schedule for completion of torus attached piping mods. Schedules based upon preliminary engineering analysis completed to date
REEO, C. Commonwealth Edison Co B1/01/08 1p. 07455.360

B01130470 Responds to B01114 ltr re alleged water loss from facilities. Relief that no direct unmonitored water has been released from station has been repeatedly confirmed by effluent monitoring program
SCOTT, D. J. Commonwealth Edison Co 01/01/11 3pp 07596.265

B011300294 Order modifying license & granting extension of exemption. Licensees must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 50 by D0731
EISENHUT, D. O. Division of Licensing B1/01/13 7pp 07582.159

B01200296 Advises that steam discharge sys re-evaluation has been completed, in response to NRC B01001 ltr. Necessary mods will be implemented in first refueling outage beginning 020101.
JANECEK, R. F. Commonwealth Edison Co. B1/01/15 2pp 07486.240

B01260402 Forwards Revision 2 to inservice insp & testing programs, detailing testing requirements for ECCS min flow valves & associated relief request (B-10). Valves are verified to close & open during normal sys surveillance tests
JANECEK, R. F. Commonwealth Edison Co. 01/01/16 10pp 07308.001

B01220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREC-0737 Task III A.2
DELGROHE, L. O. Commonwealth Edison Co. B1/01/19 1p 07497.014

--B01220374 "Offsite Dose Calculation Sys Meteorological Monitoring, Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants," Revision 2
GOLDEN, J. C. Commonwealth Edison Co. DRACLEY, J. P. Murray & Trettel, Inc LAHTI, O. P. Dargent & Lundy, Inc. 80/07/31 130pp
07497.015

--B01220379 "Study of Low Level Dispersion Over Northern IL."
• Murray & Trettel, Inc 74/06/30. 106pp 07497.159.

B01260597 Forwards util B01126 revision of facility electrical drawing index & marked-up version of NRC index of drawings. Indices available in Central Files only
JANECEK, R. F. Commonwealth Edison Co B1/01/19 1p. 07519.029.

B01290706 Ack receipt of B01222 ltr informing NRC of wells to be sampled. Requests environ contractor monthly rept
FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch. B1/01/19 1p 07568.035

--B01290791 Responds to NRC D01119 ltr re well samples. New samples to begin Jan 1981 & be analyzed for gross alpha, gross beta & tritium
GOLDEN, J. C. Commonwealth Edison Co. 80/12/22 1p 07568.036.

B01270381 Advises of concurrence w/NUREC-0619 re feedwater nozzle & control rod drive return line nozzle cracking, in response to NRC 001113 ltr. Results of further evaluations will be submitted by B01220
JANECEK, R. F. Commonwealth Edison Co B1/01/22 2pp 07543.010.

0. Inspection reports, IE Bulletins & correspondence

B01050249 Forwards IE Info Notice 80-30, "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/30. 2pp. 07389.133

B101070113 Forwards IE Insp Repts 50-010/80-21.50-237/80-23 & 50-249/80-27 on 801103-07 & notice of violation.
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/25 2pp 07415-011

--B101070118 Notice of violation from insp on 801103-07
* Region 3, Chicago, Office of the Director 80/11/24 1p 07415-013

--B101070125 IE Insp Repts 50-010/80-21.50-237/80-23 & 50-249/80-27 on 801103-07 Noncompliance noted failure to collect weekly cooling water sample
JANAKA, A G, PHILLIPS, M P, PAPERILL, D C J Region 3, Chicago, Office of the Director 80/11/24 10pp 07415-014

B101050933 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Bisan Discharge Vol at Dresden Unit 2." No response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/05 2pp 07399-302

5101090778 Forwards IE Insp Repts 50-010/80-22.50-237/80-24 & 50-249/80-28 on 801004-1114 No noncompliance noted.
HEISHAM, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/05 2pp 07430-245

--B101090785 IE Insp Repts 50-010/80-22.50-237/80-24 & 50-249/80-28 on 801004-1114 No noncompliance noted. Major areas inspected operational safety verification & monthly maint observation
TOLSON, J M, JORDAN, M J, WALKER, R D Region 3, Chicago, Office of the Director 80/12/05 6pp 07430-247

B101070132 Addl response to FCIA request for documents re imposition of civil penalties. LRC requests for congressional authorization for more severe penalties & responsibilities & behavior of nuclear plant operators Forwards documents listed in app
FELTON, J M Division of Rules and Records 80/12/09 3pp 07441-194

--B101090142 IE Insp Repts 50-237/80-16 & 50-249/80-20 on 800908-10 No noncompliance noted. NRC inspector observed two operators apparently asleep. Lack of operator attentiveness is considered significant safety matter.
PHILLIP, G A, MORELUS, C E, SESSARD, R L Region 3, Chicago, Office of the Director 80/09/29 31pp

--B101090150 Discusses IE policies for reporting, evaluating & documenting significant safety matters. In light of incident at facility. Consideration of safety significance always precedes noncompliance in evaluating any concern. Related info oncl
STELLIO, V Office of Inspection & Enforcement, Office of the Director 80/10/01 4pp

--B101090157 Requests to review any IE noncompliance info re 800808 Investigation of alleged sleeping control room operators at facility & info re changing NRC requirements to cover operator sleeping on duty
BRAEFORD, P A Commissioners 80/10/10 1p

--B101090161 Forwards draft civil penalty package re inattentiveness of operators at facility
KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/10 3pp

B101050073 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves Hqs by Valcor Engineering Corp." Valves V7900-21-1 or V7900-21-3 not used in any safety-related functions. Approx 40 manhours expended in bulletin review
RAUSCH, T J Commonwealth Edison Co 80/12/12 1p 07359-122

B101080260 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/17 2pp 07428-329

B101100140 EN-80-56 on CR about 801219, notice of violation & notice of proposed imposition of civil penalty in amount of \$4,000 will be issued to licensee's action based on alleged item of noncompliance re shipment of waste not packaged properly.
HETZGER, J Enforcement Branch 80/12/17 1p

B101150240 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR." Written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/18 1p 07465-348

B101050170 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rock Safety Relief Valves at BWRs." No response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/19 2pp 07377-301

B101080973 Responds to NRC 800818 request for monthly status report re evaluations in response to IE Bulletin 79-14 Tabulations of piping sys w/stresses above FSAR levels & below operability limit oncl
JANECEK, R F Commonwealth Edison Co 80/12/22 5pp 07421-050

B101200135 Forwards addl response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Revised initial acceptance evaluations for combined piping sys stresses during SSE event provided.
JANECEK, R F Commonwealth Edison Co 81/01/05 6pp 07486-100

B101280155 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (D01017 Indian Point 2 Event)." Surveillance procedures of at least monthly repetition will be instituted by B10501
RAUSCH, T J Commonwealth Edison Co 81/01/05 6pp 07486-202

B101260402 Forwards Revision 2 to inservice insp & testing program deleting testing requirements for ECCS min flow valves & associated relief request (B-101 Valves are verified to close & open during normal sys surveillance tests)
JANECEK, R F Commonwealth Edison Co 81/01/16 10pp

R Periodic operating reports & related correspondence

B101270515 Forwards monthly operating reports for Dec 1980.
SCOTT, D J Commonwealth Edison Co 81/01/19 1p 07546-299

--B101270520 Monthly operating reports for Dec 1980
MAXWELL, D C Commonwealth Edison Co 81/01/16 16pp 07546-

S Reportable occurrences, LERs & related correspondence

B101200632 Immediate action ltr confirming 801223 telcon re inadvertent repressurization of reactor from cold shutdown conditions on 801220-21. Licensee will complete onsite review to determine safety significance & preventative actions.
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/22 2pp 07477-306

B101060469 Forwards LER 80-044/03L-0.
SCOTT, D J Commonwealth Edison Co 80/12/27 1p 07391-075

--B101060477 LER 80-044/03L-0 on 801215, during hydrostatic test, tube found leaking. Caused by concentration cell corrosion. Tubes plugged & leakage stopped
* Commonwealth Edison Co 80/12/29 2pp 07391-096

B101060467 Forwards LER 80-047/01T-0.
SCOTT, D J Commonwealth Edison Co 80/12/30 1p 07391-090

--B101060471 LER 80-047/01T-0 on 801221, reactor pressure exceeded & primary coolant temp exceeded 212 F w/HPCL sys & isolation condenser out of svc & primary containment integrity broken. Caused by procedural inadequacy.
* Commonwealth Edison Co 80/12/29 4pp 07391-091

B101140620 Forwards LER 80-046/03L-0
SCOTT, D J Commonwealth Edison Co 81/01/02 1p 07461-101

--B101140623 LER 80-046/03L-0 on 801220, MSIV 3-203-20 did not meet closure time limits. Caused by misadjusted timing mechanism due to leaking hydraulic dashpot. Dashpot repaired, hydraulic oil added & timing adjusted
SPEROFF, R Commonwealth Edison Co 81/01/02 1p 07461-102

B101210647 Confirms B10106 telcon re B10109 meeting at Region 3 in Elgin, IL to discuss 801222 event at facility, documented under LER 80-47/01T-0.
KEPPLER, J G Region 3, Chicago, Office of the Director 81/01/16 1p 07488-347

B101260570 Forwards LER 80-045/03L-0.
SCOTT, D J Commonwealth Edison Co 81/01/11 1p 07531-123

--B101260568 LER 80-045/03L-0 on 801219, drywell spray header outboard isolation valve did not close from control room. Probably caused by stuck plunger on closing coil of valve motor breaker plunger freed by moving closing coil by hand.
RAUSCH, T J Commonwealth Edison Co 81/01/22 7pp 07531-124

8101270608 Forwards LER 80-049/03L-0
SCOTT, O J Commonwealth Edison Co 81/01/19 1p 07546 332

--8101270613 LER 00-049/03L-0 on 801225. Unit 3 diesel generator air start
regulator valve found blowing air. Caused by bad seal in air
start regulator valve. Valve replaced.
BAOER, B Commonwealth Edison Co 01/01/19 1p 07546 333

DOCKET 80-250 TURKEY POINT PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants. CP holders
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FBAR
EISENHUT, D O Division of Licensing. 80/11/13 2pp

8101130184 Advises of provisions of 10CFR50, App R, that are applicable
to fire protection features of facility. FR notice & summary
of staff requirements to resolve open items encl.
EISENHUT, D O Division of Licensing. 80/11/24 6pp. 07452 154

8101120468 Releases public version of util revised emergency plan.
FELTON, J M Division of Rules and Records. 80/12/02 1p.
07439 334

--8101120479 Forwards public version of revised emergency plan for
facilities
UHRIO, R E Florida Power & Light Co 80/02/15 1p. 07439 335

--8101120403 Public version of revised emergency plan for facilities.
* Florida Power & Light Co 80/02/15 23pp 07439 336

8101190377 Requests response to encl comments from NRC review of util
security plan. Encl withheld (ref 10CFR2 7901.
CLARK, R A Operating Reactors Branch 3 00/12/12 2pp. 07474 280

8101140429 Forwards facility emergency planning info to be made
publicly available. W/o encl.
EQUER, J L Division of Rules and Records 80/12/17 1p.
07461 334

8101030392 Advises that responses to items re fire protection will be
submitted by 810170
UHRIO, R E Florida Power & Light Co. 80/12/30 1p. 07375 741

8101090453 Forwards security plan info re protected area boundary at
facilities info withheld (ref 10CFR2 7901.
UHRIO, R E Florida Power & Light Co 80/12/30 1p. 07387 265

O Adjudicatory correspondence

8101100504 Forwards revised order for mod of licenses correcting refs
in 800029 order. Hearing date also revised.
EISENHUT, D O Division of Licensing. 80/09/19 3pp. 07444 263

--8101100519 Revised order amending Licenses DPR-31 & DPR-41 info
requested by IE Bulletin 79-01B must be submitted to IE
by 801101.
EISENHUT, D O Division of Licensing. 80/09/19 6pp. 07444 265

8101090001 Response interposing no objection to notion received 801212
to permit intervenor & designated experts to enter site.
Certificate of Evc encl.
GOLDBERG, B C Hearing Branch 2. 80/12/29 3pp 07377 335.

8101140886 Confirms 810107 telcon re preliminary informal conference
to discuss facility repairs & schedule for proceedings on
proposed amendments to DLs. Proposed schedule & Certificate of
Evc encl.
COLL, N A Florida Power & Light Co COLL, N A Steel, Hector &
Davis 81/01/00 3pp. 07458 222.

8101230622 Directs parties to try to resolve differences re proposed
site visit, record review conference & rept conference
results to ASLB Board agrees w/rule of reason in ASLB 000623
order.
BOWERS, E R Atomic Safety and Licensing Board Panel. 81/01/13 1p
07512 274

encl. Related correspondence
COLL, N A Steel, Hector & Davis. 81/01/16 3pp 07529 230

8101260354 Requests on behalf of MP Oncavage. 20-day extension within
which to comment on draft EIS. Comments to be submitted by
810317

CHUJIN, H Chonin, N 81/01/21 2pp. 07525 145

J Insurance & indemnity information

8101090478 Forwards Endorsement 54 to ANI Policy NF-103
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/30 3pp 07427 299

8101090571 Forwards Endorsements 4 to ANI Binders EO-25 & EB-26.
Endorsement to Binder EB-25 only encl.
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/30 2pp 07427 349

8101090401 Forwards Endorsement 53 to ANI Policy NF-103
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/31 2pp 07442 297

P Operating license stage documents & correspondence

8101100504 Forwards revised order for mod of licenses correcting refs
in 800829 order. Hearing date also revised.
EISENHUT, D O Division of Licensing. 80/09/19 3pp 07444 263

--8101100519 Revised order amending Licenses DPR-31 & DPR-41 info
requested by IE Bulletin 79-01B must be submitted to IE
by 801101.
EISENHUT, D O Division of Licensing. 80/09/19 6pp. 07444 265

8101100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under BTR license amend application adding model
tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing. 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 23.0 3/4 7-5 & 7-6 & 6-17
BTR snubber inservice insp requirements.
* Division of Licensing. 80/11/20 10pp

8101200466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Laminar Tearling on Component Supports."
EISENHUT, D O Division of Licensing. 00/11/26 6pp.

8101140854 Forwards "Assessment of Impacts of Steam Generator Repair
Program at Turkey Point Plant on Threatened or Endangered
Species".
VAROA, B A Operating Reactors Branch 1 80/12/12 3pp 07457 32

--8101140863 "Assessment of Impacts of Steam Generator Repair
Program at Turkey Point Plant on Threatened or Endangered
Species".
MARNIK, M T. Environmental Engineering Branch. 80/11/30 21pp
07457 328

8101210135 Forwards responses to questions on Rule 50.71e, "Periodic
Updating of FBARS" & FR notice of final rule. SEP plants need
not comply w/rule until program is complete. Non-SEP plants
must comply within specified time frame.
EISENHUT, D O Division of Licensing. 80/12/15 13pp

8101140679 Forwards DES safety evaluation & FR notice re steam
generator repair at facility
VAROA, B A Operating Reactors Branch 1 80/12/18 2pp. 07462 02

--8101190397 Notice of availability of NUREG-0743, DES re steam genera
repair at facilities
VAROA, S A Operating Reactors Branch 1 80/12/18 3pp
07472 176.

--8101190408 SAFETY EVALUATION REPORT RELATED TO STEAM GENERATOR REPAIR
AT TURKEY POINT PLANT UNITS 3 AND 4
* Office of Nuclear Reactor Regulation, Director NUREG-0756
80/12/31 46pp Available at N118 \$3 25 07472 237

8101140916 Forwards list of OES documentation W/o encl.
VAROA, B A Operating Reactors Branch 1. 80/12/10 7pp 07398 00

generator repair requests concept w/b encs
VARQA.S.A Operating Reactors Branch 1 80/12/18 2pp 07491:099

B101230522 Forwards DES safety evaluation rept & notice of DES issuance re steam generator repair at facilities
VARQA.S.A Licensing Branch 1 80/12/18 2pp 07512 219

--B101230524 Notice of availability of DES re steam generator repair at facilities
VARQA.S.A Licensing Branch 1 80/12/18 2pp 07512 221.

B101300223 Forwards Amends 62 & 53 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & EIA & notice of issuance & availability
VARQA.S.A Operating Reactors Branch 1 80/12/19 2pp 07582 322

--B101300237 Amends 62 & 53 to Licenses DPR-31 & DPR-41, respectively, deleting fuel residence time limit from Tech Specs App A to Licenses
VARQA.S.A Operating Reactors Branch 1 80/12/19 12pp 07582 324

--B101300250 Safety evaluation & EIA supporting Amends 62 & 53 to Licenses DPR-31 & DPR-41, respectively
• Office of Nuclear Reactor Regulation, Director 80/12/19 3pp 07582:337

--B101300261 Notice of issuance & availability & negative declaration of Amends 62 & 53 to Licenses DPR-31 & DPR-41
VARQA.S.A Operating Reactors Branch 1 80/12/19 1p 07582 340

B101050019 Verifies 801219 filing of EIS re steam generator repair Notice of availability scheduled for 801224 FR publication
Public review period ends on 810223
HILSDON, K L Environmental Protection Agency 80/12/22 1p 07385:266

B101140205 Confirms actions discussed in 801223 telcon re low level radioactively contaminated earth at site Site evaluation will be performed to identify & quantify all contaminated areas
D'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/23 2pp 07461:253

B101050338 Forwards response to 801031 ltr re NUREG-0737 implementation status of post-FMI requirements
HARIG, R E Florida Power & Light Co 80/12/26 7pp 07376 218

B101060297 Forwards proposed amend to App A of Licenses DPR-31 & DPR-41, to provide for redundancy in decay heat removal sys for all modes of reactor operation, in response to NRC BOD611 request
HARIG, R E Florida Power & Light Co 80/12/30 2pp 07399 035

--B101060303 Proposed Tech Specs providing for redundancy in decay heat removal sys for all modes of reactor operation.
• Florida Power & Light Co 80/12/30 10pp 07399 038

B101190339 Forwards list of TLO station locations near facility & proposed route for exchanging TLOs for NRC direct radiation monitoring network w/o encs.
RICHAR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07476 087

B101060309 Application to amend Licenses DPR-31 & DPR-41, moving one sample location from onsite location T79 to onsite location T72, due to high potential for oil contamination at old location
HARIG, R E Florida Power & Light Co 80/12/31 1p 07399:031

--B101060311 Proposed environ Tech Spec Table 4.12-1, Sheet 1 Util safety evaluation & sampling location map encl
• Florida Power & Light Co 80/12/31 4pp 07399:032

B101060286 Forwards responses to NUREG-0737 re shift technical advisor & ECCS outages per 801031 ltr Rept re improving emergency preparedness long-term to be submitted separately.
HARIG, R E Florida Power & Light Co 81/01/02 22pp 07396:181.

B101120421 Act receipt of draft environ impact documentation for facilities.
COYNER, M L Agriculture, Dept of. 81/01/05 1p 07449:349

B101230428 Forwards "Auxiliary Feedwater Pumps Endurance Test," per NRC 800330 ltr
HARIG, R E Florida Power & Light Co. 81/01/14 1p 07308 001

--B101230430 "Auxiliary Feedwater Pumps Endurance Test"
• Florida Power & Light Co 81-80-04 81/01/14 31pp 07308 001

B101210380 Agrees w/NRC 801212 biological assessment that facility repair program will not adversely impact threatened or endangered species. No definite decision has been made for onsite burial of spent resin.
FETERSON, D W Interior, Dept of, Fish & Wildlife Service 81/01/15 2pp 07489:070.

B101230558 Forwards BNWL 801212 ltr re steam generator repair progress. Requests placement in docket files info forms basis for conclusions reached in review of facility steam generator repair program.
BRIDENHUBER, H Operating Reactors Branch 1 81/01/21 1p 07308 001

--B101230556 Submits info in response to 801126 & 1202 telcons re potential drop of steam generator & subsequent release of radioactive rad. Release of radioactivity would be less than 10% Forwards article on deposits in primary sys.
MOENEB, O R Battelle Memorial Institute, Pacific Northwest Laboratory, 80/12/12 7pp 07308 001

B101290452 Comments on DES re steam generator repair, per NRC 801218 Request. No significant impacts to electric power, natural gas or oil pipeline industries.
HEINEMANN, J M Federal Energy Regulatory Commission 81/01/21 1p 07568 360

0 Inspection reports, IE Bulletin & correspondence

B101260019 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
D'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/21 1p 07261:179

B101080206 Forwards IE Insp Repts 50-250/80-30 & 50-251/80-30 on 800925-26. No noncompliance noted.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/11/17 2pp 07421:035

--B101080210 IE Insp Repts 50-250/80-30 & 50-251/80-30 on 800925-26. No noncompliance noted. Major areas inspected: emergency planning drill observation & previously identified items.
QUINN, O T Region 2, Atlanta, Office of the Director, JENKINS, S R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/11/10 4pp 07421:037

B101080124 Requests existing data, summaries & records of inservice 1 tests of containments w/greased prestressing tendons ORNL receiving contract to compile & review records of tendons.
EISENHUT, O O Division of Licensing, 80/11/25 3pp.

B101100829 Forwards IE Insp Repts 50-250/80-29 & 50-251/80-28 on 801021-24. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/28 2pp 07443:247.

--B101100834 IE Insp Repts 50-250/80-29 & 50-251/80-28 on 801021-24. No noncompliance noted. Major areas inspected: IE Bulletin 80-11 Followup & containment bldg tendon surveillance insp program.
LENAHAN, J J Region 2, Atlanta, Office of the Director, CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/17 5pp 07443:249.

B101190108 Forwards IE Insp Rept 50-250/80-34 on 801113-14. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/02 2pp 07460:315

--B101140113 IE Insp Rept 50-250/80-34 on B01113-14 No noncompliance noted. Major areas inspected IE Bulletin 79-13 re feedwater line repairs
CRDM/EX. B R Region 2, Atlanta, Office of the Director
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/26 4pp 07460 317

B101140036 Submits B01210 daily staff notes IE infirms of concrete block wall deviations at Farley 2 & breach of radwaste package integrity at Turkey Point 3 & 4 Plant status encl
ORCKS, W J. Office of the Executive Director for Operations.
80/12/11 3pp. 07460 292

B101140608 Requests extension until B10120 to respond to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc - Add'l time needed to contact all suppliers.
UHR10, R E Florida Power & Light Co. 80/12/11 2pp 07462 010

B101150125 Responds to IE Bulletin 80-23 Facilities do not use Valcor solenoid valves w/Part Numbers V70900-21-1 & 21-3
UHR10, R E Florida Power & Light Co 00/12/17 1p 07462 190

B101190330 Forwards response to IE Bulletin 80-08 re containment liner penetration weld examination Defects found in welds have been repaired & re-examined Table of nondestructive examination results encl
UHR10, R E Florida Power & Light Co 80/12/30 15pp 07475 220

B101210200 Responds to IE Bulletin 80-24 re water damage inside containment. Current sys configuration combined w/MUREO-0578 implementation provides assurance that component cooling water leaks will be detected & minimized
UHR10, R E Florida Power & Light Co 81/01/07 3pp. 07488 014.

B101290557 Act receipt of B10109 ltr informing NRC of steps taken to correct violation noted in IE Insp Rpts 50-250/80-19 & 50-251/80-20
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 01/01/13 1p 07575 277

R Periodic operating reports & related correspondence

B101210414 Forwards monthly operating rpts for Dec 1900.
RCHM10T, A O Florida Power & Light Co 01/01/10 1p. 07493 132.

--B101210418 Monthly operating rpts for Dec 1900
CHILSON, V T Florida Power & Light Co 81/01/10. 3pp
07493 133.

B101210425 Forwards monthly operating rpts for Dec 1980
SCHM10T, A O Florida Power & Light Co 01/01/10. 1p. 07493 136.

--B101210429 Monthly operating rpts for Dec 1980
CHILSON, V T Florida Power & Light Co 81/01/10. 9pp.
07493 137

9 Reportable occurrences, LERs & related correspondence

B101050324 Forwards LER 00-021/03L-0
RCHM10T, A O Florida Power & Light Co 80/11/28 1p. 07379 303.

--B101050342 LER 80-021/03L-0 on B01101, seismograph found inoperable following initial successful calibr check. Caused by batteries discharged by electrical problem in seismograph. Assembly returned to manufacturer for expedited repair
PACE, P L Florida Power & Light Co 00/11/28. 1p 07379 304

B101050484 Forwards LER 80-022/03L-0
RCHM10T, A O Florida Power & Light Co 80/12/03. 1p. 07378 356

--B101050542 LER 80-022/03L-0 on B01103, control rod M-B (in control bank D) dropped during power operation Cause unknown Rod retrieved & unit returned to full power per approved procedures.
PACE, P L Florida Power & Light Co. 80/12/03 1p. 07378 357.

B101050360 Forwards LER 80-023/03L-0.
RCHM10T, A O Florida Power & Light Co. 80/12/08. 1p. 07389 298

--B101050363 LER 80-023/03L-0 on B01108, surveillance check of refueling water storage tank level was not completed within required time interval. Caused by personnel error resulting in missed entry on check list Personnel have been reinsructed.
PACE, P L Florida Power & Light Co. 80/12/08 1p. 07389 299.

B101130325 Forwards LER 00-025/01T-0
RCHM10T, A O Florida Power & Light Co. 80/12/15. 1p. 07451 357

--B101130333 LER 80-025/01T-0 on B01203, AE advised that insp per IE Bulletin 79-14 revealed potential deficiency in support of accumulator nozzles JA & JO during seismic event Caused by max stress exceeding acceptance criteria
PACE, P L Florida Power & Light Co 80/12/15. 2pp. 07451 311

B101130348 Forwards LER 80-026/01T-0
RCHM10T, A O Florida Power & Light Co 00/12/23 1p 07452 010

--B101130377 LER 80-026/01T-0 on B01211, 125-volt dc battery AB out for approx 25-h Caused by servicing for annual discharge test Battery returned to full charge
PACE, P L Florida Power & Light Co 80/12/23 1p 07452 010.

B101130393 Forwards LER 00-027/01T-0
RCHM10T, A O Florida Power & Light Co 80/12/23 1p 07452 010

--B101130382 LER 80-027/01T-0 on B01212, motor operated valve in steam line from steam generator JA found closed, precluding generator monitoring Caused by valve operator inadvertently closing valve during maint
PACE, P L Florida Power & Light Co. 80/12/23 1p 07452 010

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F Security, radical, emergency & fire protection plans

B101090307 Ltr to all licensees of operating reactor plants, LFP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101130184 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open items encl
EISENHUT, D O Division of Licensing 80/11/24. 6pp 07452 150

B101120460 Releases public version of util revised emergency plan
FELTON, J H Division of Rules and Records 80/12/02 1p
07435 334

--B101120479 Forwards public version of revised emergency plan for facilities
UHR10, R E Florida Power & Light Co 80/02/15 1p. 07415 130

--B101120403 Public version of revised emergency plan for facilities
Florida Power & Light Co 00/02/15 23pp 07435 336.

B101190377 Requests response to encl comments from NRC review of security plan Encl withheld (ref 10CFR2 790).
CLARK, R A Operating Reactors Branch 3 80/12/12. 2pp 07474

B101140429 Forwards facility emergency planning info to be made publicly available w/o encl
SOUDEK, J L Division of Rules and Records. 00/12/17 1p
07461 334

B101050392 Advises that response to items re fire protection will be submitted by B10130.
UHR10, R E Florida Power & Light Co. 00/12/30 1p 07375 341

B101050453 Forwards security plan info re protected area boundary facilities info withheld (ref 10CFR2 790)
UHR10, R E Florida Power & Light Co. 00/12/30. 1p. 07387 245

0 Adjudicatory correspondence

B101100504 Forwards revised order for mod of licenses correcting r in B00829 order hearing data also revised.
EISENHUT, D O Division of Licensing. 80/09/19. 3pp

--B101100519 Revised order amending Licenses DPR-31 & DPR-41 info requested by IE Bulletin 79-018 must be submitted to IE by B01101.
EISENHUT, D O Division of Licensing 80/09/19 6pp

B101050001 Response interposing no objection to motion received B101 to permit intervenor & designated experts to enter site Certificate of Svc encl.
GOLDBERG, B C Hearing Branch 2 80/12/29. 3pp. 07377 359

B101140886 Confirms B10107 telcon re preliminary informal conference to discuss facility repairs & schedule for proceedings on proposed amendments to DLS Proposed schedule & Certificate of Svc encl
COLL/M A Florida Power & Light Co COLL/M A Steel, Hector & Davis 81/01/03 3pp 07458 222

B101230622 Directs parties to try to resolve differences re proposed site visit, record review conference & rept conference results to ASLB Board agrees w/role of reason in ASLB 820623 order
BOKERS, E S Atomic Safety and Licensing Board Panel 81/01/13 1p 07512-274

B101260503 Forwards ASLB 820723 order re steam generator repair proceedings per B10113 order Certificate of Svc encl W/o encl Related correspondence
COLL/M A Steel, Hector & Davis 81/01/16 3pp 07529 230

B101260554 Requests on behalf of RP Encovage, 20-day extension within which to comment or draft EIS. Comments to be submitted by B10317
CHEN, H N Chen, H N 81/01/21 2pp 07523 145

J Insurance & indemnity information

B101090478 Forwards Endorsement 54 to ANI Policy NF-185
FIELDER, J Marsh & McLennan, Inc M & M Nuclear Consultants, Inc Div 80/12/30 3pp 07442 259

B101090571 Forwards Enforcement 4 to ANI Binders EB-25 & EB-26 Enforcement to Binder EB-25 only encl
FIELDER, J Marsh & McLennan, Inc M & M Nuclear Consultants, Inc Div 80/12/30 2pp 07427 349

B101090481 Forwards Endorsement 53 to ANI Policy NF-185
FIELDER, J Marsh & McLennan, Inc M & M Nuclear Consultants, Inc Div 80/12/30 2pp 07442 257

P. Operating license stage documents & correspondence

B101100309 Forwards revised order for mod of licenses correcting refs in 800829 order Hearing date also revised.
EISENHUT, D O Division of Licensing 80/09/19 3pp 07444 263

--B101100319 Revised order amending licenses DPR-31 & DPR-41. Info requested by IE Bulletin 79-018 must be submitted to IE by B101101
EISENHUT, D O Division of Licensing 80/09/19 6pp 07444 265

B101100234 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STB License Amend application adding model Tech Spec 4 to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28.0 3/4 7-5 & 7-6 & 6-17 to STB snubber inservice insp requirements
Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B10112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports."
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101140894 Forwards "Assessment of Impacts of Steam Generator Repair Program at Turkey Point Plant on Threatened or Endangered Species"
VARQA, S A Operating Reactors Branch 1 80/12/12 3pp 07457 325

--B101140853 "Assessment of Impacts of Steam Generator Repair Program at Turkey Point Plant on Threatened or Endangered Species"
HAGNIK, M T Environmental Engineering Branch 80/11/30 21pp 07457-328

B101210443 Forwards responses to questions on Rule 50.71c. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/13 13pp

B101140679 Forwards DES safety evaluation & FR notice re steam generator repair at facility
VARQA, S A Operating Reactors Branch 1 80/12/18 2pp 07462 022

--B101190397 Notice of availability of NUREG-0743, DES re repair at facilities
VARQA, S A Operating Reactors Branch 1 80/12/18 07472 176

--B101190408 SAFETY EVALUATION REPORT RELATED TO STEAM GENERATOR AT TURKEY POINT PLANT UNITS 3 AND 4
Office of Nuclear Reactor Regulation, Director 80/12/31 46pp Available at NTIS \$3.25 07472 2

B101140916 Forwards list of DES documentation H/w encl
VARQA, S A Operating Reactors Branch 1 80/12/18 7p

B101210069 Forwards notice of availability of NUREG-0743, steam generator repair at facilities
VARQA, S A Operating Reactors Branch 1 80/12/18 1p

B101210126 Forwards NUREG-0743 & NUREG-0756 re facility generator repair Requests comment W/o encl
VARQA, S A Operating Reactors Branch 1 80/12/18 3p

B101230522 Forwards DES safety evaluation rept & notice re steam generator repair at facilities
VARQA, S A Licensing Branch 1 80/12/18 2pp 07512-274

--B101230524 Notice of availability of DES re steam generator repair at facilities
VARQA, S A Licensing Branch 1 80/12/18 2pp 07512-274

B101200223 Forwards Amends 62 & 53 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & EIA & notice of issuance of licenses
VARQA, S A Operating Reactors Branch 1 80/12/19 2p

--B101300239 Amends 62 & 53 to Licenses DPR-31 & DPR-41, deleting fuel residence time limit from Tech Specs. A licenses
VARQA, S A Operating Reactors Branch 1 80/12/19 07582 324

--B101300250 Safety evaluation & EIA supporting Amends 62 & 53 to Licenses DPR-31 & DPR-41, respectively
Office of Nuclear Reactor Regulation, Director 07582 337

--B101300261 Notice of issuance & availability & negative Amends 62 & 53 to Licenses DPR-31 & DPR-41
VARQA, S A Operating Reactors Branch 1 80/12/19 07582 340

B101050019 Verifies B01219 filing of EIS re steam generator repair at facilities
Notice of availability scheduled for B01224 FR public review period ends on B10223.
WILSON, K L Environmental Protection Agency 80/12/20 07385 266

B101140205 Confirms actions discussed in B01223 telcon re radioactively contaminated earth at site Site evaluation will be performed to identify & quantify all contaminated areas
GREILLY, J P Region 2, Atlanta, Office of the Director 2pp 07461 253

B101050038 Forwards response to B01031 ltr re NUREG-0743 status of post-TMI requirements
WILSON, R E Florida Power & Light Co 80/12/26 7pp

B101060297 Forwards proposed amend to App A of Licenses DPR-31, to provide for redundancy in decay heat removal for all modes of reactor operation, in response to NRC request
WILSON, R E Florida Power & Light Co 80/12/30 2pp

--B101060303 Proposed Tech Spec providing for redundant removal system for all modes of reactor operation
Florida Power & Light Co 80/12/30 10pp 07512-274

B101190339 Forwards list of TLD station locations near proposed route for exchanging TLDs for NRC direct radiation monitoring network H/w encl
STONER, J P Region 2, Atlanta, Fuel Facility & Materials Branch 80/12/30 2pp 07476 087

B101060304 Application to amend Licenses DPR-31 & DPR-41 sample location from onsite location T99 to onsite location T72, due to high potential for oil contamination at oil location
WILSON, R E Florida Power & Light Co 80/12/31 1p

--B01060311 Proposed environ tech Spec table 4 12-1, Sheet 1 Util safety evaluation & sampling location map encl
* Florida Power & Light Co 80/12/31 4pp 07399 032

B01060286 Forwards responses to NUREG-0737 re shift technical advisor & ECCB outages per B01031 ltr Rept re improving emergency preparedness long-term to be submitted separately
UHR10.R E Florida Power & Light Co 81/01/02 22pp 07396 181

B01120421 Ack receipt of draft environ impact documentation for facilities
COTNER, H L Agriculture, Dept. of 81/01/09 1p 07445 349.

B01210345 Advises that no historical sites will be affected by steam generator repair in response to B01218 cultural resource assessment request
PERCY, O W Florida, State of 81/01/09 1p 07490 118

B01220150 Submits info re proposed undervoltage protection sys design mod. in response to NRC B00818 ltr. Two OE Type 14V undervoltage relays will be installed on each 4160 V bus
Proposed Tech Spec will be submitted upon completion
UHR10.R E Florida Power & Light Co 81/01/14 2pp 07493 256.

B01230428 Forwards "Auxiliary Feedwater Pumps Endurance Test." per NRC 000530 ltr.
UHR10.R E Florida Power & Light Co 81/01/14 1p 07308 001

--B01230430 "Auxiliary Feedwater Pumps Endurance Test."
* Florida Power & Light Co. 81-80-04. 81/01/14. 31pp.
07308 001

B01210380 Agree w/NRC B01212 biological assessment that facility repair program will not adversely impact threatened or endangered species. No definite decision has been made for onsite burial of spent resin
PEIERSON, D W Interior, Dept. of, Fish & Wildlife Service 81/01/13 2pp 07409 070

B01300486 Forwards Amend 54 to License DPR-41, safety evaluation & notice of issuance & availability.
VAROA, B A Operating Reactors Branch 1. 81/01/15 2pp 07383 301

--B01300491 Amend 54 to License DPR-41, permitting continued operation of Unit 4 for its equivalent months of operation from B01113, etc which time steam generator shall be inspected.
VAROA, B A Operating Reactors Branch 1 81/01/15 3pp.
07383 303

--B01300495 Safety evaluation supporting Amend 54 to License DPR-41.
* Office of Nuclear Reactor Regulation, Director 81/01/15 7pp.
07383 308.

--B01300499 Notice of issuance & availability of Amend 54 to License DPR-41.
VAROA, B A Operating Reactors Branch 1 81/01/15 2pp
07383 315

B01230558 Forwards BNWL B01212 ltr re steam generator repair program Requests placement in docket files info forms basis for conclusions reached in review of facility steam generator repair program
GROENENBURG, M Operating Reactors Branch 1 81/01/21 1p
07308 001.

--B01230566 Submits info in response to B01126 & 1202 telcons re potential drop of steam generator & subsequent release of radioactive metl. Release of radioactivity would be less than 10% Forwards article on deposits in primary sys.
HEENEY, O R Battelle Memorial Institute, Pacific Northwest Laboratory 80/12/12 7pp 07308 001.

B01290452 Comments on GEB re steam generator repair, per NRC B01218 request. No significant impacts to electric power, natural gas or oil pipeline industries
HEINEMANN, J M Federal Energy Regulatory Commission. 81/01/21. 1p.
07568 360.

0 Inspection reports, IE Bulletins & correspondence

B012160019 Forwards IE Info Notice 80-37, "Containment Cooler Lease & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
BREILLY, J P Region 2, Atlanta, Office of the Director. 80/10/24 1p. 07261 179

B01060206 Forwards IE insp Repts 80-250/80-30 & 80-251/80-30 on B00925-26 No noncompliance noted
STONER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/11/17 2pp 07421 039

--B01080210 IE Insp Repts 80-250/80-30 & 80-251/80-30 on B00925-26 No noncompliance noted Major areas inspected emergency planning drill observation & previously identified items
OIBSOLA, O T Region 2, Atlanta, Office of the Director
JERKINS, O R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/11/10 4pp 07421 037

B01050124 Requests existing data, summaries & records of inservice insp tests of containments w/grossed prestressing tendons
UHR10.R E Division of Licensing 80/11/29 3pp

B01100829 Forwards IE Insp Repts 80-250/80-29 & 80-251/80-28 on B01021-24 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/28 2pp 07443 247

--B01100834 IE Insp Repts 80-250/80-29 & 80-251/80-28 on B01021-24 No noncompliance noted Major areas inspected IE Bulletin 80-11 followup & containment bldg tendon surveillance insp program
LENNHAN, J J Region 2, Atlanta, Office of the Director.
CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/17 3pp 07443 249.

B01140035 Submits B01210 daily staff notes. IE informs of concrete block wall deviations at Farley 2 & breach of radwaste package integrity at Turkey Point 3 & 4 Plant status encl.
DIRCKE, W J Office of the Executive Director for Operations 80/12/11 3pp 07460 252

B01140608 Requests extension until 010130 to respond to IE Bulletin 80-21, "Velve Yokes Supplied by Malcolm Foundry Co. Inc."
Addl time needed to contact all suppliers
UHR10.R E Florida Power & Light Co 80/12/11 2pp 07462 010

B01150125 Responds to IE Bulletin 80-23 Facilities do not use Valcor solenoid valves w/Part Numbers V70900-21-1 & 21-3.
UHR10.R E Florida Power & Light Co 80/12/17 1p 07462 190

B01190350 Forwards response to IE Bulletin 80-08 re containment liner penetration weld examination Defects found in welds have been repaired & re-examined Table of nondestructive examination results encl
UHR10.R E Florida Power & Light Co 80/12/30 15pp 07479 243

B01210208 Responds to IE Bulletin 80-24 re water damage inside containment Current sys configuration combined w/NUREG-0578 implementation provides assurance that component cooling water leaks will be detected & minimized
UHR10.R E Florida Power & Light Co 81/01/07 3pp 07488 014.

B01290357 Ack receipt of B01019 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 80-250/80-19 & 80-251/80-20
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/01/13 1p 07575 277

R Periodic operating reports & related correspondence

B01210414 Forwards monthly operating repts for Dec 1980.
SCHMIDT, A B Florida Power & Light Co. 81/01/10 1p. 07493 132.

--B01210418 Monthly operating repts for Dec 1980
CHILSON, V T Florida Power & Light Co 81/01/10 3pp
07493 133.

B01210425 Forwards monthly operating repts for Dec 1980.
SCHMIDT, A O Florida Power & Light Co. 81/01/10 1p 07493 136.

--B01210429 Monthly operating repts for Dec 1980
CHILSON, V T Florida Power & Light Co 81/01/10 9pp.
07493 137.

B Repertible occurrences, LERs & related correspondence

B01050480 Forwards LER 80-014/01T-0.
SCHMIDT, A O Florida Power & Light Co. 80/12/10 1p 07309 001.

--B101050534 LER EO-014/011-0 on B01126, insp per IE Bulletin 79-14 revealed deficiency in portions of accumulator & RHR sys piping inside containment. Calculated max stress exceeded criteria. Mod will be made before unit returns to svc.
PACE, P. L. Florida Power & Light Co. 80/12/10 2pp. 07309 001

B101050390 Forwards LER 80-013/024-0
SCHMIDT, A. O. Florida Power & Light Co. 80/12/11 1p. 07309:001

--B101050547 LER 80-013/033-0 on B01111, six of ten detection type detectors found inoperative during test on fire detection sys caused by corrosion of both detector base terminals & outer chamber of type D18-3/5A detector head
PACE, P. L. Florida Power & Light Co. 80/12/11 1p 07309 001.

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT, D. O. Division of Licensing 80/11/13 2pp.

H. General correspondence

B101290518 Advises that future correspondence should be addressed to
IL Dept of Nuclear Safety, 1035 Outer Park Drive, 5th Floor
Springfield, IL 62704
WRIGHT, G. H. Illinois, State of. 81/01/22 1p

J. Insurance & indemnity information

B101090603 Forwards guarantee of payment of deferred premiums for 1980
OSTER, J. Commonwealth Edison Co. 81/01/05 1p

B101270614 Forwards Endorsements 125 & 126.65 & 66.53 & 54. & 13 & 14 to NELA Policies NF-43, NF-187, NF-201 & NF-253, respectively.
OSTER, J. Commonwealth Edison Co. 81/01/21. 13pp 07183:001

B101270737 Forwards Endorsement 4 to Sincere ED-1, EB-3, EB-3, EB-29, EB-30, EB-42 & EB-43 evidencing secondary functional protection.
OSTER, J. Commonwealth Edison Co. 01/01/21 8pp.

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except BEP licensees) forwarding Revision 1 of inservice surveillance requirements for submers under B15 License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D. O. Division of Licensing. 80/11/20. 1p

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-17 to B7B submer inservice insp requirements.
Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports"
EISENHUT, D. O. Division of Licensing. 80/11/26 8pp

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR steam discharge sys. Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes.
EISENHUT, D. O. Division of Licensing 80/12/09. 2pp.

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs. Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl.
Division of Licensing 80/12/01 212pp 07183:001

B101210445 Forwards responses to questions on Buld 50.71e. "Particulate Updoping of FBARs" & FR notice of final rule BEP plants need not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame.
EISENHUT, D. O. Division of Licensing 80/12/15 13pp.

B101050376 Submits addl response to NRC B00822 ltr Evaluation of Pratt & Whitney butterfly valve demonstrates that loads imposed & stresses developed in components during valve closure under LOCA event fall within acceptable limits
JANECEK, R. F. Commonwealth Edison Co. 80/12/26. 2pp. 07399:027.

B101050500 Forwards response to NUREG-0737 No response. Dresden 1 Unit undergoing extensive mod & decontamination outage. Requirements of NUREG-0737 will be addressed prior to startup of unit scheduled for June 1985
ABEL, J. S. Commonwealth Edison Co. 80/12/31 35pp

B101300154 "Adequacy of Station Electric Distribution System Over Cities, Units 1 & 2"
LOV, A. C. EQ&G Idaho, Inc. FIN A-6256 B101300154 07583 114

B101090091 Forwards Revision 15 pages to CE-1-A, OA program. Revisions reflect Summer 1980 addenda to Section ASME code & recent ASME survey for renewal of ASME corporate certifications
ABEL, J. S. Commonwealth Edison Co. 81/01/02 1p

--B101090005 Revision 15 pages to OA program topical report
Commonwealth Edison Co. CE-1-A R15 B1/01/02

B101300337 Submits schedule for completion of torus etch tests. Schedules based upon preliminary engineering are completed to date.
REED, C. Commonwealth Edison Co. 81/01/08 1p 074

B101200296 Advises that steam discharge sys re-evaluation completed in response to NRC B01001 ltr. Necessary mod to be implemented in first refueling outage beginning 05/81
JANECEK, R. F. Commonwealth Edison Co. 81/01/15 2pp

B101220368 Forwards offsite dose calculation sys description meteorological data requirements in NUREG-0737 Task 111 A 2
DELOERGE, L. O. Commonwealth Edison Co. 81/01/19 1p

--B101220374 "Offsite Dose Calculation Sys. Meteorological Offsite Dose Calculation Program for Emergency Preparedness Operating Nuclear Power Plants," Revision 2.
GOLDBEN, J. C. Commonwealth Edison Co. 80/07/31. 1p

--B101220379 "Study of Low Level Dispersion Over Northern Illinois"
Murray & Trettel, Inc. 74/06/30 106pp.

B101270481 Advises of concurrence w/NUREG-0619 re feedwater control rod drive return line hostile cracking, in response to NRC B01113 ltr. Results of further evaluations will be submitted by B10220
JANECEK, R. F. Commonwealth Edison Co. 81/01/22 2pp

O. Inspection reports, IE Bulletins & correspondence

B101050249 Forwards IE Info Notice 00-38, "Cracking in Casing Cladding." No response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 2pp

B101050462 Forwards IE Bulletin 80-21, "Valve Yokes Bu Foundry Co, Inc." Written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 2pp

B101100115 Forwards IE Insp Repts 50-254/80-23 & 50-265/80-092-03, 1B-17, 100B, 1B-16 & 1106 No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction Support Branch 80/11/24. 2pp 07441:318

--B101100153 IE Insp Repts 50-254/80-23 & 50-265/80-092-03 noted. Major areas inspected. OA/OC program, inservice data, torus mod & activities per IE Bulletin 79-03 & 80-13
WARO, K. D. Region 3, Chicago, Office of the Director DANIELSON, D. H. Region 3, Chicago, Reactor Construction Engineering Support Branch. 80/11/19. 11pp. 074

B101080079 Forwards IE Insp Repts 50-254/80-23 & 50-265/80-092-03 & notice of violation.
HEISLER, A. F. Region 3, Chicago, Reactor Operations Support Branch 80/11/28 2pp. 07421:001.

--B101080083 Notice of violation from insp on B01020-1 re Region 3, Chicago, Office of the Director 80/07421:003

--B101080092 IE Insp Repts 50-254/80-23 & 50-265/80-092-03 Noncompliance noted. Incorrect surveillance performed. Inoperable diesel generator. Inadequate testing re pump failure.
SPESBARO, R. L., CHRISOTIMOS, N., DUPONT, B. O. Region 3, Chicago, Office of the Director. 80/11/28. 14pp. 07421:0

8101090809 Ack receipt of 801112 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/80-20 & 50-265/80-22
KEPLER, J O Region 3, Chicago, Office of the Director. 80/12/01 1p 07187 001

--8101090810 Responds to NRC 801021 ltr re violations noted in IE Insp Repts 50-254/80-20 & 50-265/80-22 Corrective actions lead blankets added to piping & ladder by Unit 2 CRO accumulators removed
ABEL, J B Commonwealth Edison Co. 80/11/12 10pp 07187 001

8101050530 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scream Discharge Vol at Oresden Unit 2 " No response required.
KEPLER, J O Region 3, Chicago, Office of the Director. 80/12/05 2pp

8101090234 Ack receipt of 801201 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/80-22 & 50-265/80-24
HEISMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09 1p 07425 274

--8101090244 Responds to NRC 801106 ltr re violations noted in IE Insp Repts 50-254/80-22 & 50-265/80-24 Corrective actions: closed charging water isolation valves & resumed control rod blade unclutching
ABEL, J B Commonwealth Edison Co. 80/12/01 2pp 07425 275

8101060073 Responds to IE Bulletin 80-23, "Failures of Solenoid Valve Meq by Valcor Engineering Corp " Valves V70900-21-1 or V70900-21-3 not used in any safety-related functions Approx 40 manhours expended in bulletin review
RAUSCH, T J Commonwealth Edison Co. 80/12/12 1p.

8101080060 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scream Capability " No written response required.
KEPLER, J O Region 3, Chicago, Office of the Director. 00/12/17 2pp

8101150240 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scream at BWR." Written response required.
KEPLER, J O Region 3, Chicago, Office of the Director. 00/12/10 1p

8101290434 Forwards IE Insp Repts 50-254/80-28 & 50-265/80-29 on 801119-20 No noncompliance noted.
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/12/18 2pp 07570 325.

--8101290438 IE Insp Repts 50-254/80-28 & 50-265/80-29 on 801119-20 No noncompliance noted. Major areas inspected licensee actions re IE Bulletin 79-14.
YIN, L T Region 3, Chicago, Office of the Director.
DANIELSON, O H Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/12/18 5pp 07570 327

8101050170 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rock Safety Relief Valves at BWRs." No response required.
KEPLER, J O Region 3, Chicago, Office of the Director. 00/12/19 2pp.

8101080093 Responds to NRC 800818 request for monthly status report re evaluations in response to IE Bulletin 79-14. Tabulations of piping sys w/stresses above FSAR levels & below operability limit encl.
JANECEK, R F Commonwealth Edison Co. 80/12/22 5pp 07421 090.

8101130198 Forwards IE Insp Repts 50-254/80-29 & 50-265/80-30 on 801208-12 No noncompliance noted.
HINO, J A Region 3, Chicago, Safeguards Branch. 80/12/24 2pp. 07452 083.

--8101130206 IE Insp Repts 50-254/80-29 & 50-265/80-30 on 801208-12 No noncompliance noted. Major areas inspected: security plan & program audit. Details withheld (ref 10CFR2 7901
CHRISTOFFER, G, KNIGLEY, J R Region 3, Chicago, Office of the Director. HINO, J A Region 3, Chicago, Safeguards Branch. 80/12/23 2pp. 07452 085

8101200135 Forwards addl response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Revised initial acceptance allowables for combined piping sys stresses during BSE event provided.
JANECEK, R F Commonwealth Edison Co 81/01/05 6pp. 07486 108.

8101200155 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event) " Surveillance procedures of at least monthly repetition will be instituted by 810601
RAUSCH, T J Commonwealth Edison Co 81/01/05 6pp

8101300574 Ack receipt of 801211 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-254/79-31
HEISMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 81/01/21 1p 07585 327

--8101300577 Responds to NRC 800214 ltr re violations noted in IE Insp Rept 50-254/79-31 Corrective actions: locked switch boxes will be inspected as part of routine shift rounds
JANECEK, R F Commonwealth Edison Co. 80/12/11 1p 07586 328

R Periodic operating reports & related correspondence

8101120153 Forwards "Environ Dose Pathway Study," Spring 1979 through Summer 1980
JANECEK, R F Commonwealth Edison Co 80/12/30 1p 07446 168

--810120156 "Environ Dose Pathway Study," Spring 1979 through Summer 1980
Eberline Instrument Corp 80/12/30 44pp 07446 169

8101200302 Forwards list of changes, test & experiments completed during Dec 1980
KALIVIANAKIS, N Commonwealth Edison Co 81/01/02 5pp 07486 28

8101210463 Forwards monthly operating repts for Dec 1980
KALIVIANAKIS, N Commonwealth Edison Co 81/01/02 1p 07493 107

--8101210465 Monthly operating repts for Dec 1980
LUBBS, R C Commonwealth Edison Co 81/01/01 32pp 07493 108

B Reportable occurrences, LERs & related correspondence

8011250354 Forwards LER 80-029/01T-0
KALIVIANAKIS, N Commonwealth Edison Co 80/11/12 1p 07056 065

--8011250358 LER 80-029/01T-0: on 801103, during suppression chamber maintenance to make weld fit-up, safety relief valve line 1-3019E-0 suffered 4-inch crack at pipe penetration. Caused by excessive force. Pipe will be repaired before startup
KOPACZ, J J Commonwealth Edison Co 80/11/12 2pp 07056 069

8101090054 Forwards six updated LERs 80-021/03L-1
KALIVIANAKIS, N Commonwealth Edison Co 80/12/19 1p 07426 233

--8101090055 First of six updated LERs 80-021/03L-1 on 800903, during local leak rate test, valves A0-1-1601-23, 24, 60, 61, 62 & 63 found to have leakage rates in excess of Tech Specs. Caused by misalignment of main shaft w/butterfly disc
KEHERT, D Commonwealth Edison Co. 80/12/19 1p 07426 236.

--8101090070 Second of six updated LERs 80-021/03L-1: on 800904, during local leak rate test, leakage through containment purge valve A0-1-1601-21, 22, 55 & 56 found excessive. Caused by main shaft misalignment preventing butterfly disc seating
KALIVIANAKIS, N Commonwealth Edison Co. 80/12/19 1p. 07426 237.

--8101090088 Third of six updated LERs 80-021/03L-1 on 800901, during main steam line local leak rate test, valves A0-1-0203-2A, 1B, 2B, 1B & 2D found to have excessive leakage. Caused by cracks in satellite disc & cage. Disc turned & seats lapped.
LUBBS, R C Commonwealth Edison Co. 80/12/19 3pp 07426 239

--8101090091 Fourth of six updated LERs 80-021/03L-1: on 800901, during main steam line drain local leak rate test, valve A0-1-220-1 found to have leakage in excess of Tech Specs. Caused by worn seal ring. Seal replaced, valve repacked & stroked.
MURRAY, B Commonwealth Edison Co 80/12/19 1p 07426 241

--8101090095 Fifth of six updated LERs 80-021/03L-1: on 800904, during feedwater check valve local leak rate test, leakage through feedwater check valve 1-220-62B found excessive. Caused by worn valve seat & dirty pivot valve. Relapsed & cleaned
WYKOFF, D Commonwealth Edison Co 80/12/19 1p. 07426 242

--8101090103 Sixth of six updated LERs 80-021/03L-1: on 800917, during feedwater check valve local leak rate test, leakage through feedwater check valve 1-220-62A found excessive. Caused by dirty valve internals. Valve retested
KUNDELICH, J R Commonwealth Edison Co 80/12/19 1p 07426 243

B101050396 Forwards LER 80-032/011-0.
KALIVIAHAKIS-N Commonwealth Edison Co 80/12/22 1p 07390.108

--B101050396 LER 80-032/011-0 re B01211 during installation of hanger per
IE Bulletin 79-14 two 1/2-inch anchor bolt holes were
drilled which penetrated primary containment caused by
faulty design plugs welded in holes
MURRAY, R Commonwealth Edison Co 80/12/22 2pp. 07390.109

B101270763 Forwards LER 80-033/03-0
KALIVIAHAKIS-N Commonwealth Edison Co. 81/01/06 1p 07549.079.

--B101270770 LER 80-033/03-0 re B01217 while placing standby gas
treatment in normal standby operation suction valve
MD-1-7503 failed to open from control room caused by dirty
auxiliary contacts. Contacts were cleaned & replaced
EDENHUR Commonwealth Edison Co 81/01/06 1p 07549.080

LOCHET 50-255 PALISADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

B101070387 Ltr to all licensees of operating reactor plants-CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing. 80/11/13 2pp

B101300550 Forwards comments re required revisions to util physical
security plan Encl withheld (ref 10CFR2 790)
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 3pp
07584.352

B101140310 Requests that util facility emergency planning info be made
publicly available w/ encl
SOUER, J L Division of Rules and Records 80/12/31 1p
07461.264

B101260732 Releases public version of util revised site emergency plan
FELICH, J H Division of Rules and Records. 81/01/16 1p.
07535.176

--B101260738 Forwards public version of revised site emergency plan
HOFFMAN, B P Consumers Power Co 81/01/02. 1p 07535.177

--B101260743 Public version of revised site emergency plan
* Consumers Power Co 81/01/01 173pp 07535.179.

O. Adjudicatory correspondence

B101120494 Discovery rept per ASLB B00223 memorandum & order Anderson to
util third round interrogatories filed B01223 Further
discovery to be reintroduced in Jan 1981 Stallo, Kaplar &
Jorgenson depositions postponed.
MCJUN, R E Rulemaking & Enforcement Division 81/01/07. 1p.
07447.209

B101130053 Third round interrogatories directed to CPC to be answered
by B10130 Concerns local leak tests of Penetration A & A
HEPA filter replacement. Certificate of Svc encl
BURNS, B O Rulemaking & Enforcement Division. 81/01/09 5pp
07448.297

B101140970 Notice of FD Lectis B10202 deposition in Columbus, OH re
alleged noncompliance by util Certificate of Svc encl.
BURNS, B O Rulemaking & Enforcement Division 81/01/13 2pp.
07458.297.

B101260523 Application for subpoena requiring F Lectis to attend,
testify & produce documents at B10209 deposition in
Columbus, OH re activities on filter testing & replacement
Proposed subpoena & Certificate of Svc encl.
BURNS, B O Rulemaking & Enforcement Division 81/01/22. 4pp
07529.293

I. Financial information

B101150506 Forwards statement of internal case flow for yr ending
801130 & projected for yr ending B1130
BORIS, W R Consumers Power Co 81/01/09 3pp 07463.150.

J. Insurance & indemnity information

B101220332 Forwards Enforcements 66 & 67 to ANI Policy NF-179
Enforcement 67 not encl
IRELAND, J H Consumers Power Co 81/01/16 2pp. 07494.094.

B101260462 Forwards Endorsement A to ANI Binder EB-20
IRELAND, J H Consumers Power Co 81/01/21 2pp

P. Operating license stage documents & correspondence

B101300367 Forwards Amend 62 to license DPR-20, safety
notice of issuance & availability
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/20
07586.174

--B101300377 Amend 62 to License DPR-20, changing Tech
re limiting condition for operation for auxiliary
sys & fire water pumps
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/20
07586.178

--B101300363 Safety evaluation supporting Amend 62 to
revising Tech Specs Section 3.5 re limiting condition
for operation for auxiliary feedwater sys & fire water
* Operating Reactors Branch 5. 80/10/20 2pp

--B101300390 Notice of issuance & availability of Amend
DPR-20
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/20
07586.185.

B101220466 Ltr to all power reactor licensees & appli
cants summary of B01112 meeting re implementation of guide
Unresolved Safety Issue A-12. "Potential for Low Pressure
Toughness & Lamellar tearing on Component Supports."
EISENHUT, D O Division of Licensing 80/11/26 2pp

B101050080 Confirms B01202 proposal made by SEP owner
meeting w/NRC for completion of 60% of SEP topics by
B10630 Forwards met used during B01202 presentation
BOHAFB, TALL, R NRC, inr 80/12/05 12pp 07379.102

B101280472 Forwards request for addl info to complete
adequacy of station electric distribution sys volta
facility Rating of Class 1E motor contactors & upper
lower limits for continuous operation required
CRUTCHFIELD, D Operating Reactors Branch 5. 80/12/15
07595.102.

B101210186 Forwards table of structures, sys & compone
classification w/respect to quality group & const r
for SEP Topic 111-1 Util must complete table & verify
existing data
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/15
07468.246

B101210445 Forwards responses to questions on Rule 50
Updating of FSARs" & FR notice of final rule. SEP pl
not comply w/rule until program is complete Non-SEP
must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15. 1p

B101160027 Notification of B01218 meeting w/SEP owner
Bethesda, MD re SEP program, schedule for licensee to
completion & assignment of lead topics to plants.
RUSSELL, W T. Technical Support Branch 80/12/16

B101160017 1st rept of B01117-19 visit to site w/Be
observe facility features re SEP structural, electric
topic reviews & to discuss open items based on self
review Util responses to SEP items & list of attend
MICHAELS, T B. Systematic Evaluation Program Branch
36pp 07465.265

B101230337 Forwards listing of all SEP correspondence
SEP owners group B01202 meeting List provides basis
which to determine plant status Review & comments re
w/o encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15
07512.097.

B101190636 Advice of detention of SEP Topic 111-3 B.1
consequences of underdrain sys failures from facility
review due to inapplicability.
CRUTCHFIELD, D Operating Reactors Branch 5. 80/12/15
07476.066

B101210149 Forwards request for addl info for NRC re
111-4 C. "Internally Generated Missiles
(Classified Containment)" & 111-4. "Boron Addition Sys."
CRUTCHFIELD, D Operating Reactors Branch 5. 80/12/15
07491.203

01290299 Informs that SEP Topics III-10 A, III-10 B, VI-7 F, VII-3 B, VIII-4 & XV-16 will be basic input to integrated safety assessment. Topic assessments may be revised if facility design is changed.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/31 2pp
07575 010

01300847 Technical Evaluation Rept. Degraded Grid Protection for Class 1E Power Sys. Palisades Plant
LEVELAND, C. J. EG&O Idaho, Inc. FIN A-6256 8101300847 80/12/31
12pp 07584 332

01140338 Forwards summary status of rept re "Inadequate Core Cooling Detection Sys." per 801219 commitment in response to NUREG-0737 Rept includes conceptual design description of inadequate core cooling detection sys.
KFFMAN, D. P. Consumers Power Co. 81/01/05 1pp 07450 011

011140344 Summary status of rept re "Inadequate Core Cooling Detection Sys."
* Consumers Power Co. 80/12/31 30pp 07450-013

01130442 Forwards proprietary & nonproprietary versions of turbine disc cracking into updating 800321 submittal
KFFMAN, D. P. Consumers Power Co. 81/01/06 2pp 07451 315

010130445 "Turbine Disc Info." nonproprietary version
* Consumers Power Co. 81/01/06 25pp 07451 317

010130450 Requests that info re turbine disc integrity be withheld per 10CFR2 790 as subg info is considered proprietary
WILLIAMS, R. Westinghouse Electric Corp. 80/03/14 7pp
07135 116

01140628 Forwards facility equipment list data sheet for rotating equipment w/rating of greater than 30 horsepower. In response to NRC 801219 telcon re SEP review
KUEHN, J. L. Consumers Power Co. 81/01/06 24pp 07309 001

01120318 Advises that NRC rept re loss of offsite power survey did 801010, still provides misleading info. such as item which shows facility w/four event rates greater than target values
KFFMAN, D. P. Consumers Power Co. 81/01/08 2pp 07447 111

01210746 Forwards draft safety evaluation of SEP Topic III-4 B, "Bito Proximity Missiles." Evaluation will be used as basic input to integrated assessment for facility unless changes reflecting as-built condition are required
CRUTCHFIELD, D. Operating Reactors Branch 5 81/01/13 9pp
07487 146

01220472 Forwards request for addl info necessary to complete SEP seismic review info identified as open items from draft NUREG/CR-1833, "Seismic Review of Palisades Nuclear Power Plant, Unit 1, As Part of SEP." W/o NUREG.
CRUTCHFIELD, D. Operating Reactors Branch 5 81/01/19 4pp
07505 205

01280077 Forwards draft evaluation of SEP Topic VII-3, "Electrical Instrumentation & Control Aspect of Sys Required for Refo Shutdown." to accompany 801105 ltr Response within 30 days requested
CRUTCHFIELD, D. Operating Reactors Branch 5 81/01/24 35pp
07557 109

01290785 SEISMIC REVIEW OF THE PALISADES NUCLEAR POWER PLANT UNIT 1 AS PART OF THE SYSTEMATIC EVALUATION PROGRAM.
JELSON, T. A., MURRAY, R. C., KESLEY, D. A. Lawrence Livermore Laboratory FIN A-0233. NUREG/CR-1833 81/01/31. 187pp. Available at NF18 15.50 07569 005

01200639 Forwards guidelines for performing soil-structure interaction reviews for SEP facilities & simplified analytical approach for evaluating effects of soil-structure interaction using lumped parameter model.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/15 2pp
07477 143

Inspection reports, IE Bulletins & correspondence

01050214 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casting Cladding." No response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/30 2pp 07389 041

8101060118 Forwards IE Circular 80-23, "Potential Defects in Beloit Pacer Sys Emergency Generators." No written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/11 1p 07397 329

810106044 Forwards IE Info Notice 80-37, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/11 2pp 07401 206

0101060457 Forwards IE Bulletin 80-21, "Valve Seats Supplied by Mainline Foundry Co. Inc." Written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/14 2pp 07390 001

8101060620 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization." No written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/14 2pp 07392 165

0101060344 Forwards IE Info Notice 80-41, "Failure of Bypass Check Valve in Decay Heat Removal Sys at Davis-Besse Unit 1." No response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/11 2pp 07392 070

8101060501 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/14 2pp 07391 229

8101090074 Forwards IE Insp Rept 80-255/80-19 on 801020-24 & notice of violation.
DAVIS, A. J. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/18 2pp 07426 245

--8101090077 Notice of violation from insp on 801020-24
* Region 3, Chicago, Office of the Director. 80/11/12 1p 07426 247

--0101090114 IE Insp Rept 80-255/80-19 on 801020-24 Noncompliance with failure to submit annual nonradiological environ rept for CV79 on time & to include all required info
JANUSAS, A. O., PHILLIPS, M. P., PAPERIELLO, C. J. Region 3, Chicago, Office of the Director 80/11/12 12pp 07426 240

0101070170 Forwards IE Insp Rept 80-255/80-21 on 801006-31 & notice of violation
EISENHART, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/21 2pp 07415 127

--8101070174 Notice of violation from insp on 801006-31
* Region 3, Chicago, Office of the Director. 80/11/21. 1p 07415 129

--8101070181 IE Insp Rept 80-255/80-21 on 801006-31 Noncompliance noted equipment operability requirements not met & steam generator tube pressure differential limit exceeded
JORGENSEN, B. L., MILLER, J. K., BOYD, D. C. Region 3, Chicago, Office of the Director. 80/11/21 8pp 07415 130

0101050124 Requests existing data, summaries & records of inservice insp tests of containment w/greased prestressing tendons
DRNL receiving contract to compile & review records of tendons.
EISENHART, D. A. Division of Licensing 80/11/25 3pp

8101300351 Forwards IE Health Physics Appraisal Rept 80-255/80-14, notice of violation & significant appraisal findings
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/21 4pp 07586 134

--0101300355 Notice of violation from health physics appraisal on 800004-15
* Region 3, Chicago, Office of the Director. 80/11/25 2pp 07586 138

--8101300361 IE Health Physics Appraisal Rept 80-255/80-14 Noncompliance noted inadequate evaluation of airborne release & failure to follow radiation protection procedures
OREGER, L. R., GRANT, W. B. Region 3, Chicago, Office of the Director CARBAUGH, E. H. Battelle Memorial Institute 80/11/25 34pp 07586 140

B101030562 Forwards IE Info Notice 80-43. "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2 - No response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/05
2pp 07390 332

B101090168 Ack receipt of B01031 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/80-17
IEISMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/08 1p 07426 355

--B101090171 Responds to LRC B01038 ltr re violations noted in IE Insp Rept 50-255/80-17 Corrective actions advised dept heads of weekly insp to be conducted re fire protection procedures & of right to be written
HOFFMAN, D. P. Consumers Power Co. 80/10/31 2pp 07426 356

B101070653 Responds to IE Bulletin 80-21 No records found concerning valves supplied from Falkco. Fo-dry. List of currently installed Anchor Darling valves encl.
HOFFMAN, D. P. Consumers Power Co 80/12/10 3pp 07415 273.

B101070100 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/16 1p 07415 027

B101290428 Forwards IE Insp Rept 50-255/80-22 on B01105.03-07.10-12.14. 17-22 & 25-26 No noncompliance noted
HEISMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/18 2pp 07570 319

--B101250432 IE Insp Rept 50-255/80-22 on B01101.03-07.10-12.14. 17-22 & 25-26 No noncompliance noted Major areas inspected maint & surveillance
JEROEISEN, B. L., HELLER, J. A., BOYD, D. C. Region 3, Chicago, Office of the Director 80/12/17 4pp 07570 321

B101150076 Ack receipt of B01210 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/80-19
DAVIES, A. 3 Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/31 1p 07462 163

--B101150079 Responds to NRC B01113 ltr re violations noted in IE Insp Rept 50-255/80-19 Corrective actions summarized rept will be issued by B10115 & effluent particulate activity calculation methods reviewed.
HOFFMAN, D. P. Consumers Power Co 80/12/10 4pp 07462 188.

B101220395 Responds to IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment" Weekly containment entries performed to search for water leakage on lower level of containment & results documented in logbook
HOFFMAN, D. P. Consumers Power Co 81/01/08 8pp 07500 255

B101220182 Ack receipt of B01017 ltr reporting violations noted in IE Insp Rept 50-255/80-15 Item 1 re plant operation for more than 36-h w/inoperable safety-related snubber remains as issued Item 2 withdrawn.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 81/01/09 2pp 07503 240

--B101220186 Responds to NRC B00924 ltr re violations noted in IE Insp Rept 50-255/80-15 Refutes items of Noncompliance 1 & 2A. BGS reviewed to provide clarification of problem re cold shutdown after snubber inoperability.
FRCDST, S. R. Consumers Power Co 80/10/17 3pp 07503 242

B101220190 Ack receipt of B01216 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/80-21 Item 1 remains classified as infraction
HEISMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 81/01/09 2pp 07503 245

--B101220200 Responds to LRC B01121 ltr re violations noted in IE Insp Rept 50-255/80-21 Corrective actions ltr sent to const superintendent confirming commitment to adhere to fire protection procedures
HOFFMAN, D. P. Consumers Power Co 80/12/16 3pp 07503 247

R Periodic operating reports & related correspondence

B101130243 Forwards monthly operating rept for Dec 1980.
KENNEDY, D. M. Consumers Power Co 81/01/08 1p 07452 097.

--B101130249 Monthly operating rept for Dec 1980.
BOOTKE, P. J. Consumers Power Co 81/01/08 4pp 07452 098.

B101200304 Submits bimonthly status rept for Dec 1980
Beinzel Corp is preparing final design details for 1 cooling mode scheduled for 1981 refueling outage
HOFFMAN, D. P. Consumers Power Co 81/01/15 1p 0

S Reportable occurrences, LERs & related correspondence

B101270123 Immediate action ltr. confining until B10109 prevent recurrence of B10106 event Corporate mgt representative will conduct daily audit of facility operations
KEPPLER, J. O. Region 3, Chicago, Office of the Director 2pp 07547 219

B101230530 Forwards LER B1-001/01T-0
HOFFMAN, D. P. Consumers Power Co 81/01/16 1p 0

--B101230531 LER B1-001/01T-0 on B10106. output breaker inadvertently opened for 1-h Caused by misalignment personnel failure to follow procedure Safety-related surveillance & maint procedures reviewed prior to
* Consumers Power Co 81/01/16 9pp 07183 001

B101230479 Forwards NRCES noncompliance notification 1
HOFFMAN, D. P. Consumers Power Co 81/01/20 1p 0

--B101230483 NRCES noncompliance notification on B01222 exceeded Tech Spec limit Caused by rupture of snubber breaker filter element Filter element replaced on Oil removal sys will be cleaned & personnel retrained
FOEB, R. L. Consumers Power Co 81/01/20 1p 0

DOCKET 80-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plan

B101090387 Ltr to all licensees of operating reactor p & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days
B10102 & by applicants as part of FSAR.
EISENHUT, O. Q. Division of Licensing 80/11/13 2p

B101210607 Transcript of 001217 briefing on TVA emergency facilities in Washington, DC Pp 1-45
* Commissioners. 80/12/17 49pp 07489 137

B101200646 Forwards request for addl info & revisions to facility guard training & qualification plan Min score for qualifying w/rifle should be stated
JPDULT, I. A. Operating Reactors Branch 2 81/01/07587 079

B101260611 Releases public version of util revised emergency plan.
FELTON, J. M. Division of Rules and Records 81/01/07531 230

--B101260619 Forwards public version of revised radio plan. In response to NRC B01113 ltr Includes State emergency plan.
MILLS, L. M. Tennessee Valley Authority. 80/12/31

--B101260624 Public version of revised util radiological plan
* Tennessee Valley Authority 80/12/31 150pp.

--B101260693 Releases public version of State of AL radio plan.
FELTON, J. M. Division of Rules and Records 81/01/07534 180

--B101260706 Public version of State of AL revised radio plan.
* Tennessee Valley Authority 80/12/31 300pp.

B101300356 Forwards revisions to safeguards contingency withheld (ref 10CFR2.7901
MILLS, L. M. Tennessee Valley Authority. 81/01/23.

Q Adjudicatory correspondence

B101160226 Petition for leave to intervene & request license amendment requests
PAUL, T. W., JOBE, R. W., HALL, M. L. Affiliation Unknown App. 07470 180

B101200070 Motion for leave to intervene in proceeding re license
amends to allow onsite storage of low level radwaste for
five yrs
CURBITT, D R , CURBITT, U J Affiliation Unknown 01/01/15 3pp
07486 339

B101200091 Petition for leave to intervene in proceeding.
MARTIN, J R , BECK, N M , DECK, R W Affiliation Unknown 01/01/16
3pp 07187 001

B101200095 Petition for leave to intervene in proceeding
MUSE, N , FREEMAN, R L , COLCLOCK, A N Affiliation Unknown 01/01/16
4pp 07406 353

B101200214 Petition for leave to intervene & request for hearing on
license amend requests
MARTIN, D L , DROUGH, O R , PIERSON, M D Affiliation Unknown
01/01/16 3pp 07476 341

B101230407 Requests to make limited appearance statement & to receive
EIS on proposed low level radwaste storage project
YBUNG, F. Affiliation Unknown 01/01/21 1p 07187 001.

B101300012 Response supporting BR & US Currott, Th Paul, RM Jobe, MC Hall,
DL Martin, OR Drough, MD Piersen, D Elg, D Havas, N Muse, RL
Freeman, AN Colock, JR Martin & NM & RW Beck petitions for
leave to intervene if amended Certificate of Evc encl.
LAVERY, J. H. Office of the Executive Legal Director 01/01/20
12pp 07582 176.

J Insurance & indemnity information

B101090406 Forwards Endorsement 53 to ANI Policy NF-198 for amend to
Condition 2
FIELDER, J Marsh & McLennan, Inc. , M & M Nuclear Consultants, Inc.
Div 00/12/29 3pp 07442 254

B101090490 Forwards Endorsement 52 to ANI Policy NF-198 for 1981
advances premiums
FIELDER, J Marsh & McLennan, Inc. , M & M Nuclear Consultants, Inc.
Div. 00/12/29 2pp 07442 083

B101090647 Forwards Endorsement 4 to NELIA Dindars ED-38, EB-39 &
ED-40 w/o Dindars ED-39 & ED-40
FIELDER, J. Marsh & McLennan, Inc. , M & M Nuclear Consultants, Inc
Div 00/12/29 2pp 07442 060.

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under BTR license amend application adding modal
Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 00/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28-D 3/4 7-9 & 7-6 & 6-17 to
BTR snubber inservice insp requirements.
* Division of Licensing. 00/11/20 10pp.

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Laminar Tearing on Component Supports."
EISENHUT, D O. Division of Licensing. 00/11/26 8pp.

B101100030 Requests input deck & simulator time re NRC comparison of
RETRAN results w/simulator results for loss of feedwater &
loss of load transients in OMR.
IPPOLITO, T A Operating Reactors Branch 2 00/12/02 2pp
07444 299

B101100082 Forwards FR notice of consideration of amends to facility
DLs re util 000731 & 1117 applications for authorization of
onsite low level waste storage for 5-yr period.
IPPOLITO, T A. Operating Reactors Branch 2. 00/12/05 2pp.
07445 204.

B101190113 Ltr to all DHR licensees forwarding 801201 generic safety
evaluation re DHR scram discharge sys Recommends short-term
actions necessary to assure safe operation of OE BWRs
pending permanent design changes.
EISENHUT, D O. Division of Licensing. 00/12/09 2pp.

--B101190141 Generic safety evaluation re short-term actions required to
assure continued safe operation of operating DHRs. Continued
operation of plants is acceptable pending permanent design
mode. Criteria for implementing design mode encl.
* Division of Licensing. 00/12/01 212pp. 07183 001.

B101050610 Forwards geologic rept re suggested graben in Gravelly
Springs, AL area Distance to facilities precludes
significance of structures. Related documentation encl
LEFEVRE, H E Geosciences Branch 00/12/11 15pp. 03775 001

B101210445 Forwards response to questions on Rule 50 7ie. "Permitting
Updating of FSARs" & FR notice of final rule SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT, D O Division of Licensing 00/12/15 13pp

B101210642 Advises that ATWS issue will be subj of future rulemaking
determine requirements & schedules for plant nodes NRC will
not comment on util 000917 ltr describing program for
resolving issue until rulemaking is finalized
EISENHUT, D O Division of Licensing 00/12/29 2pp 0740H 119

B101290033 Forwards Amends 65, 61 & 36 to Licenses DPR-33, DPR-52 &
DPR-68, respectively. EIA & notice of issuance & negative
declaration
IPPOLITO, T A Operating Reactors Branch 2. 00/12/29 3pp
07309 001

--B101290040 Amends 65, 61 & 36 to Licenses DPR-33, DPR-52 & DPR-68,
respectively, changing App B Tech Specs to delete fish
impingement monitoring program
IPPOLITO, T A Operating Reactors Branch 2 00/12/29 12pp
07309 001

--B101290046 EIA supporting Amends 65, 63 & 36 to Licenses DPR-33, DPR-52
& DPR-68, respectively. Summary review of fish impingement
encl
* Office of Nuclear Reactor Regulation, Director 00/12/29
3pp 07309 001

--B101290052 Notice of issuance & availability & negative declaration
Amends 65, 61 & 36 to Licenses DPR-33, DPR-52 & DPR-68,
respectively
IPPOLITO, T A Operating Reactors Branch 2 00/12/29 2pp
07309 001

B101190371 Advises that until 000909 response to NRC 000702 generic
re Tech Specs for TMI Lessons Learned Category A items is
inadequate Outstanding items emergency power supply relief
& safety valve position indication
IPPOLITO, T A Operating Reactors Branch 2 01/01/02 2pp.
07475 344

B101300460 Order granting extension to exemption from General Design
Criterion 50 & requiring licensees to reassess containment
design for suppression pool hydrodynamic loading
EISENHUT, D O Division of Licensing 01/01/13 7pp

--B101300467 Order granting extension to exemption from General Design
Criterion 50 & requiring licensees to reassess containment
design for suppression pool hydrodynamic loading
EISENHUT, D O Division of Licensing 01/01/13 7pp 07900 1

B101220411 Requests temporary relief from 5 F thermal rise limit &
max reservoir temp rise of 8.5 F be granted until Apr 1981.
Temp rise of 8.5 F will sustain 3-unit operation at facility
w/ current 2th hydro releases for navigation.
EL-ABHRY, M I Tennessee Valley Authority 01/01/14 3pp.
07502 246

B101220297 Grants request for temporary relief from permit condition
re allowable temp rise within certain conditions Temp at
edge of mixing zone must not exhibit change greater than
8.5 F
ZELLER, H D Environmental Protection Agency. 01/01/15 2pp
07500 069

B101300493 Forwards response to NRC 801123 request for confirmation
that NUREG-0619 implementation dates will be met Info
justifies continued operation
MILLER, L M Tennessee Valley Authority 01/01/23 3pp. 071113 0

Q Inspection reports, IE Bulletins & correspondence

B101080184 Forwards update to 000104 response to IE Bulletin 79-26
boron loss from BWR control blades Manpower required for
review & preparation approx 20-h
MILLER, L M Tennessee Valley Authority 00/11/29 3pp. 03775 0

B101050588 Forwards 1E Info Notice 80-43, "Failures of Continuous
Level Monitor for BWR Discharge Vol at Dresden Unit 2 " No
response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 00/12/01
1p. 07391 010.

MILLS, L. M. Tennessee Valley Authority 80/12/15 1p 07461 055
 * Tennessee Valley Authority 80/12/31 2pp 07442 016

B101060153 Forwards 1E Infa Notice 80-45 "Potential Failure of EWR Backup Manual Scram Capability - No response required
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/17 1p 07571 275

B101076032 Forwards Suppl 4 to 1E Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at 64% " No written response required
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/18 1p 07413 323

B101050153 Forwards 1E Bulletin 80-29, "Operating Problems W/Target Rod Safety Relief Valves at BWRs " No response required
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/19 2pp 07377 249

B101160252 Forwards response to 1E Bulletin 80-07, "BWR Jet Pump Assembly Failure - Ultrasonic & Visual Insp of jet pump beams & assembly showed no problems
 MILLS, L. M. Tennessee Valley Authority 80/12/30 2pp 07470 249

B101210157 Informs that insp program re 1E Bulletin 79-14 will not be completed by 801125 due to delays in planned schedules.
 Revised insp schedule & Dec 1980 status rept encl
 MILLS, L. M. Tennessee Valley Authority 81/01/05 3pp 07498 010

B101220376 Forwards results of spray sparger insp in response to 1E Bulletin 80-13, "Cracking in Core Spray Spargers"
 MILLS, L. M. Tennessee Valley Authority 81/01/05 2pp 07560 294

B101280505 Forwards response to 1E Bulletin 80-24, "Prevention of Damage Due to Water Leakage (Oct 17, 1980 Indian Point 2 Event) " Components requiring supplemental cooling are cooled by reactor bldg closed cooling water sys
 MILLS, L. M. Tennessee Valley Authority 01/01/05 5pp 07550 319

B101280527 Forwards results of util analyses on diesel generators & 480 V load shed logic re 1E Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls "
 MILLS, L. M. Tennessee Valley Authority 81/01/14 2pp 07550 330

B101290350 Forwards monthly status rept as of B10101 for work re 1E Bulletin 79-14, "Systemic Analysis for As-Built Safety-Related Piping Eqs. " Includes description of pipe support & valve insp
 MILLS, L. M. Tennessee Valley Authority 81/01/15 27pp 07572 327

R. Periodic operating reports & related correspondence

B101130582 Forwards monthly operating repts for Dec 1980.
 ABERCROMBIE, H. Tennessee Valley Authority 81/01/09 1p 07453 235

--B101130588 Monthly operating repts for Dec 1980
 THOM, T. Tennessee Valley Authority, 31/01/04 37pp 07453 236

B101130595 Forwards monthly operating repts for Dec 1980
 ABERCROMBIE, H. Tennessee Valley Authority 81/01/09 1p 07453 288

--B101130601 Monthly operating repts for Dec 1980
 GREEN, O. J. THOM, T. Tennessee Valley Authority 81/01/04 21pp 07453 289

S. Reportable occurrences, LERs & related correspondence

B101060715 Forwards LER 80-087/03L-0.
 GREEN, H. J. Tennessee Valley Authority 80/12/30 1p 07309 001

--B101060727 LER 80-087/03L-0 on 801201, while performing SI 4 2 8 24, core spray sparger to RPV differential pressure switch PDIS-75-2B found to operate out of Tech Specs limits caused by instrument drift. Switch inspected & recaller
 * Tennessee Valley Authority. 80/12/30 2pp 07309 001

B101090677 Forwards LER 80-088/03L-0
 GREEN, H. J. Tennessee Valley Authority 80/12/31 1p 07442 015

B101190593 Forwards LER 80-090/03L-0
 GREEN, H. J. Tennessee Valley Authority 81/01/08 1p 07475 01

--B101190603 LER 80-090/03L-0 on 801210, continuous atr monitor 1-64-90-250 declared inoperable due to iodine channel indicating downscale caused by water in sample line due to condensation. Instrument repaired & returned to svc
 * Tennessee Valley Authority. 81/01/08 2pp 07475 017

B101130409 Forwards updated LER 80-073/01T-1
 GREEN, H. J. Tennessee Valley Authority 81/01/09 1p 07436 01

--B101130412 Updated LER 80-073/01T-1 on 80092R, river water temp ri peaked above Tech Spec level. Caused by incorrect computer temp rise predictions. River flow increased
 * Tennessee Valley Authority. 81/01/09 2pp 07436 020

B101220711 Forwards first interim repl re potential flammability of expanded ceiling tile in control rooms in response to B10104 ltr Addl info to be provided by B10211
 MILLS, L. M. Tennessee Valley Authority 81/01/14 3pp 07494 0

B101160520 Forwards LER 80-091/03L-0
 GREEN, H. J. Tennessee Valley Authority 81/01/15 1p 07471 2

--B101160525 LER 80-091/03L-0 on 801217, drywell hydrogen monitor, 1-H2-76-39, would not calibrate properly to calibr gas Tech Spec. Caused by GE Model 47E22642802 sensor failure. Alternate sensor 1-H2E-76-39A connected to hydrogen monitor
 * Tennessee Valley Authority 81/01/19 2pp 07471 276

B101300620 Forwards LER 80-092/03L-0
 GREEN, H. J. Tennessee Valley Authority. 81/01/26 1p 07503 7

--B101300629 LER 80-092/03L-0 on 801230, standby gas treatment train relative humidity heaters did not function properly. Caused by open TE-65-60B switch. Switch repaired.
 * Tennessee Valley Authority. 81/01/26 2pp 07503 334

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensee within 60 days of B10102 & by applicants as part of FSAR
 EISENHUT, O. G. Division of Licensing 80/11/13 2pp

B10121607 Transcript of 801217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45
 * Commissioners 80/12/17 49pp

B101300646 Forwards request for addl info & revisions to 801001 ch to facility guard training & qualification plan. Min passing score for qualifying w/rifle should be stated.
 IPPOLITIO, T. A. Operating Reactors Branch 2 81/01/14 3pp 07587 079

B101260611 Releases public version of util revised emergency plan
 FELTON, J. H. Division of Rules and Records. 81/01/15 1p 07531 230

--B101260619 Forwards public version of revised radiological emergency plan in response to NRC 801113 ltr includes State of AL emergency plan
 MILLS, L. M. Tennessee Valley Authority. 80/12/31 1p 07531

--B101260624 Public version of revised util radiological emergency plan
 * Tennessee Valley Authority. 80/12/31 190pp 07531 232

--B101260693 Releases public version of State of AL revised emergency plan
 FELTON, J. H. Division of Rules and Records. 81/01/15 1p 07534 180

--B101260706 Public version of State of AL revised radiological emergency plan
 * Tennessee Valley Authority. 80/12/31 300pp 07534 182

B101160226 Petition for leave to intervene & request for hearing on TVA license amend requests
PAUL, T W, JOBE, R W, HALL, M L Affiliation Unknown 81/01/14 4pp 07470 180

B101200670 Motion for leave to intervene in proceeding re license amends to allow onsite storage of low level radwaste for five yrs
CURROTT, O R, CURROTT, U J Affiliation Unknown 81/01/15 5pp 07486 339

B101200091 Petition for leave to intervene in proceeding
MARTIN, J R, BECK, N M, BECK, R W Affiliation Unknown 81/01/16 5pp 07187 001

B101200095 Petition for leave to intervene in proceeding
MUSE, N, FREEMAN, R L, COLCOCK, A N Affiliation Unknown 81/01/16 4pp 07486 353

B101200214 Petition for leave to intervene & request for hearing on license amend requests
MARTIN, O L, OROUGH, Q R, PIERSON, M D Affiliation Unknown 81/01/16 5pp 07476 341

B101230407 Requests to make limited appearance statement & to receive EIS on proposed low level radwaste storage project
YOUNG, F Affiliation Unknown 01/01/21 1p 07187 001

B101300012 Response supporting OR & UJ Currott, TW Paul, RW Jobe, M Hall, CL Martin, GR Brough, MD Pierson, O Ely, O Hevas, N Muse, RL Freeman, AN Colock, JR Martin & NM & RW Beck petitions for leave to intervene if amended Certificate of Evc encl.
LAVERY, J H Office of the Executive Legal Director 81/01/20 12pp 07582 176

J Insurance & indemnity information

B101090486 Forwards Endorsement 53 to ANI Policy NF-198 for amend to Condition 2
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div. 80/12/29 3pp 07412 254

B101090490 Forwards Endorsement 52 to ANI Policy NF-198 for 1981 advances premiums
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div. 80/12/29 2pp 07442 003

B101090647 Forwards Endorsement 4 to NELA Binders EO-38, EB-39 & ED-40, W/E Binders EO-39 & ED-40
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/12/29 2pp 07442 060

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under B1B License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28, 0 3/4 7-5 & 7-6 & 6-17 to B1B snubber inservice insp requirements.
* Division of Licensing: 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of 001112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing: 80/11/26 8pp

B101100030 Requests input deck & simulator time re NRC comparison of RETRAN results w/simulator results for loss of feedwater & loss of lead transients in BMR
JPPOLITO, T A Operating Reactors Branch 2 80/12/02 2pp 07443 299

B101100022 Forwards FR notice of consideration of amends to facility OLS re util 800731 & 1117 applications for authorization of onsite low level waste storage for 5-yr period
JPPOLITO, T A Operating Reactors Branch 2 80/12/05 2pp 07443 204

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl
* Division of Licensing: 80/12/01 212pp 07183 001

B101050610 Forwards geologic rept re suggested grabon in Gravelly Springs, AL area Distance to facilities precludes significance of structures Related documentation encl
LEFEBVRE, H E Geosciences Branch 80/12/11 15pp 07375 001

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule, SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing: 80/12/15 13pp

B101210642 Advises that ATWS issue will be subj of future rulemaking determine requirements & schedules for plant mods NRC will not comment on util 800917 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT, D O Division of Licensing: 80/12/29 2pp 07488 311

B101290033 Forwards Amends 65.61 & 36 to Licenses DPR-33, DPR-92 & DPR-69, respectively, EIA & notice of issuance & negative declaration
JPPOLITO, T A Operating Reactors Branch 2 80/12/29 3pp 07309 021

--B101290040 Amends 65.61 & 36 to Licenses DPR-33, DPR-92 & DPR-69, respectively, changing App B Tech Specs to delete fish impingement monitoring program
JPPOLITO, T A Operating Reactors Branch 2 80/12/29 12pp 07309 001

--B101290046 EIA supporting Amends 65.61 & 36 to Licenses DPR-33, DPR-92 & DPR-69, respectively Summary review of fish impingement encl
* Office of Nuclear Reactor Regulation, Director 80/12/29 32pp 07309 001

--B101290057 Notice of issuance & availability & negative declaration Amends 65.61 & 36 to Licenses DPR-33, DPR-92 & DPR-69, respectively
JPPOLITO, T A Operating Reactors Branch 2 80/12/29 2pp 07309 001

B101190393 Advises that util 800909 response to NRC 800702 generic re Tech Specs for IMI Lessons Learned Category A items is inadequate Outstanding items emergency power supply relief & safety valve position indication.
JPPOLITO, T A Operating Reactors Branch 2 81/01/02 2pp 07475 344

B101220411 Requests temporary relief from B 5 F thermal rise limit & max reservoir temp rise of B 5 F be granted until Apr 1981. Temp rise of B 5 F will sustain 3-unit operation at facility w/current min hydro releases for navigation
EL-ASHRY, M T Tennessee Valley Authority 81/01/14 3pp 07502 246

B101220297 Grants request for temporary relief from permit condition re allowable temp rise within certain conditions Temp at edge of mixing zone must not exhibit change greater than B 5 F
ZELLER, H D Environmental Protection Agency 81/01/18 2pp 07500 067

B101300493 Forwards response to NRC B01123 request for confirmation that NUREG-0619 implementation dates will be met Info justifies continued operation
MILLS, L M Tennessee Valley Authority 81/01/23 3pp 07107 001

Q Inspection reports, IE Bulletins & correspondence

B101030184 Forwards update to B03104 response to IE Bulletin 79-26 retrain loss from BWR control blades, Manpower required for review & preparation approx 20-h
MILLS, L M Tennessee Valley Authority 80/11/25 3pp 03778

B101050588 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for BWR Discharge Val at Oresden Unit 2." No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/12/1p 07391 010

8101140866 Responds to IE Bulletin 80-23 Defective solenoid valves
L/rate & part numbers in bulletin are not in use at
facilities
MILLS, L M Tennessee Valley Authority 80/12/15. 1p 07461 055

8101060153 Forwards IE Info Notice 80-45. "Potential Failure of BWR
Backup Manual Scram Capability" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/17
1p 07391 275

8101070037 Forwards Supp 4 to IE Bulletin 80-17. "Failure of 76 of 185
Control Rods to Fully Insert During Scram at BWR." No
written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/18
1p 07413 323

8101050153 Forwards IE Bulletin 80-25. "Operating Problems W/Target
Rock Safety Relief Valves at BWRs." No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/19.
2pp 07377 249

8101160252 Forwards response to IE Bulletin 80-07. "BWR Jet Pump
Assembly Failure." Ultrasonic & visual insp of jet pump
beams & assembly showed no problems
MILLS, L M Tennessee Valley Authority 80/12/30 2pp 07470 249

8101160734 Ack receipt of 801209 ltr informing NRC of supplemental
steps taken to correct violations noted in IE Insp Rept
50-260/80-28
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/12/31 1p 07472 064

--8101160759 Forwards supplemental response to NRC 801017 ltr re
violations noted in IE Insp Rept 50-260/80-28 Corrective
actions liquid penetrant test performed
MILLS, L M Tennessee Valley Authority 80/12/09 3pp
07472 065

8101210157 Informs that Insp program re IE Bulletin 79-14 will not be
completed by 801125 due to delays in planned schedules
Revised Insp schedule & Dec 1980 status rept encl
MILLS, L M Tennessee Valley Authority 81/01/03 3pp 07490 010

8101220376 Forwards results of spray sparger insp in response to IE
Bulletin 80-13. "Cracking in Core Spray Spargers"
MILLS, L M Tennessee Valley Authority 81/01/05 2pp 07500 299

8101280505 Forwards response to IE Bulletin 80-24. "Prevention of
Damage Due to Water Leakage (Oct 17, 1980 Indian Point 2
Event)." Components requiring supplemental cooling are
cooled by reactor bldg closed cooling water sys
MILLS, L M Tennessee Valley Authority 81/01/03 5pp 07550 319.

8101280527 Forwards results of util analyses on diesel generators &
480 V load shed logic re IE Bulletin 80-06. "Engineered
Safety Feature (ESF) Reset Controls."
MILLS, L M Tennessee Valley Authority 81/01/14 2pp 07550 330

8101290350 Forwards monthly status rept as of 801001 for work re IE
Bulletin 79-14. "Seismic Analysis for As-Built
Safety-Related Piping Sys." Includes description of pipe
support & valve insp
MILLS, L M Tennessee Valley Authority 81/01/15 29pp 07572 327

R. Periodic operating reports & related correspondence

8101130582 Forwards monthly operating repts for Dec 1980
ABERCROMBIE, M Tennessee Valley Authority 81/01/09 1p
07453 215

--8101130588 Monthly operating repts for Dec 1980
THOM, T Tennessee Valley Authority 81/01/04 37pp 07453 236

8101130593 Forwards monthly operating repts for Dec 1980
ABERCROMBIE, M Tennessee Valley Authority 81/01/09 1p
07453 289

--8101130601 Monthly operating repts for Dec 1980
GREEN, H J THOM, T Tennessee Valley Authority 81/01/04 21pp.
07453 289

S. Reportable occurrences, LERs & related correspondence

8101130429 Forwards LER 80-056/03L-0
GREEN, H J Tennessee Valley Authority 81/01/06 1p 07454 093

--8101130436 LER 80-056/03L-0 on 801215, reactor water level
LIS-3-56A switch 2 setpoint found outside of Tech Spec
limits Caused by Verway model 4418c setpoint drift &
recalibr & functionally tested for repeatability
Tennessee Valley Authority 81/01/06 2pp 074

8101160490 Forwards LER 80-055/03L-0
GREEN, H J Tennessee Valley Authority 81/01/06 1p

--8101160498 LER 80-055/03L-0 on 801208, core spray disch
switch, 2-PB-75-16, found set outside Tech Spec limits
by Herford Model DA-700A-R04 setpoint drift. Switch
inspected & recalibr
Tennessee Valley Authority 81/01/06 2pp 074

8101190490 Forwards LER 80-057/03L-0
GREEN, H J Tennessee Valley Authority 81/01/13 1p

--8101190495 LER 80-057/03L-0 on 801215, pressure switch
& PS-1-R, which monitor main steam line low pressure
found outside Tech Spec limits Caused by setpoint drift
switches recalibr.
Tennessee Valley Authority 81/01/13 2pp 074

8101220311 Forwards first interim rept re potential flaw
suspended ceiling tile in control rooms in response to
801014 ltr Addl info to be provided by 801211
MILLS, L M Tennessee Valley Authority 81/01/14 3p

8101220444 Forwards LER 81-001/01T-0
GREEN, H J Tennessee Valley Authority 81/01/15 1p

--8101220449 LER 81-001/01T-0 on 801012, scram discharge
2-LB-85-45A found inoperable & C & -0 found affected
by one Robert Shaw switch model SL-305-EI-X sticking
setpoint drift stuck switches float chamber back flt
Tennessee Valley Authority 81/01/15 2pp 075

8101300501 Forwards LER 80-059/03L-0
GREEN, H J Tennessee Valley Authority 81/01/26 1p

--8101300512 LER 80-059/03L-0 on 801230, FR-77-16 observed
during drywell equipment drain pump operation. C
shift in model 955 GE transmitter FT77-16 zero adjust
Transmitter recalibr, tested & returned to svc
Tennessee Valley Authority 81/01/26 2pp 075

DOCKET 50-261 H O ROBINSON PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8101090287 Ltr to all licensees of operating reactor pl
& CP applicants Revised radiological emergency respon
plans must be submitted by licensees within 60 days o
810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101140830 Advises of provisions of 10CFR50, App R, that
to fire protection features of facility, FR notices & s
of staff requirements to resolve open items encl W/O
EISENHUT, D O Division of Licensing 80/11/24, App

8101230058 Releases public version of util evaluation
FELTON, J M Division of Rules and Records 81/01/08
07511 026

--8101230066 Forwards public version of preliminary res
evaluation study for 10-mile emergency planning zon
response to NRC 79/1129 request Final repl will be a
approx 810201.

UTLEY, E E Carolina Power & Light Co 80/12/29
8101210131 Releases public version of util revised emer
FELTON, J M Division of Rules and Records 81/01/13
07491 103

--8101210137 Forwards public version of revised radiolo
response plan, including State of SC emergency plan.
replaces Vol 13 of facility operating manual Cross-
to NUREG-0654 criteria encl W/O State of SC plan.
UTLEY, E E Carolina Power & Light Co 80/12/30

--8101210144 Public version of revised emergency respon
of SC emergency plan.

B101230600 Requests exemption from App R Requirement III D requiring installation of lubo oil collection for fire protection.
UTLEY, E E Carolina Power & Light Co 01/01/19 2pp 07510 316

Q Adjudicatory correspondence

B101100646 Forwards revised order for mod of license, correcting refs in B00029 order Hearing date also revised
EISENHUT, D O Division of Licensing 00/09/19 2pp 07443 150

--B101100654 Revised order amending License DPR-23 info requested by IE Bulletin 79-01B must be submitted to IE by B01101
EISENHUT, D O Division of Licensing 00/09/19 6pp 07443 152

P Operating license stage documents & correspondence

B101100646 Forwards revised order for mod of license, correcting refs in B00029 order Hearing date also revised
EISENHUT, D O Division of Licensing 00/09/19 2pp 07443 150

--B101100654 Revised order amending License DPR-23 info requested by IE Bulletin 79-01B must be submitted to IE by B01101
EISENHUT, D O Division of Licensing 00/09/19 6pp 07443 152

B101100254 Ltr to all licensees except SEP licensees forwarding Revision 1 of inservice surveillance requirements for snubbers under STB License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 00/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 20, B 3/4 7-5 & 7-6 & 6-17 to STB snubber inservice insp requirements
* Division of Licensing 00/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of 001112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low fracture Toughness & Lamellar tearing on Component Supports"
EISENHUT, D O Division of Licensing 00/11/26 6pp

B101050110 Forwards interim safety evaluation for auxiliary feedwater sys Tech Specs for plant operation w/inoperable auxiliary feedwater pumps & commitment to meet B20101 date for implementing long-term auxiliary feedwater mod required
VARDA, S A Operating Reactors Branch 1 00/12/02 2pp 07379 263

--B101050113 Safety evaluation supporting until commitment to provide auxiliary feedwater sys reliability
* Division of Licensing 00/12/02 20pp 07379 267

B101210445 Forwards responses to questions on Rule 50.71c, "Periodic Updating of FBARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 00/12/15 13pp

B101290617 Forwards Amend 54 to License DPR-23 & notice of issuance & availability
VARDA, S A Operating Reactors Branch 1 00/12/10 3pp 07571 317

--B101290622 Amend 54 to License DPR-23, requiring secondary water chemistry program to inhibit steam generator tube degradation
VARDA, S A Operating Reactors Branch 1 00/12/18 2pp 07571 320

--B101290625 Notice of issuance & availability of Amend 54 to License DPR-23
VARDA, S A Operating Reactors Branch 1 00/12/18 2pp 07571 322

B101190355 Forwards list of TLO station locations near facility & proposed route for exchanging TLOs for NRC direct radiation monitoring network w/o encl
BIOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/12/30 2pp 07476 080

B101060453 Forwards "Control Room Habitability Evaluation, HB Robinson Steam Electric Generating Plant (NRC TMI Action Plan Item III D.3.4.)"
UTLEY, E E Carolina Power & Light Co 00/12/31 3pp 07398 223

--B101060457 "Control Room Habitability Evaluation, HB Robinson Steam Electric Generating Plant (NRC TMI Action Plan Item III D.3.4.)"
SLIOER, J E, ARC1ERI, W C, NAFT, B. N. NUS Corp. NUS-3696 00/12/31 79pp 07398 226

B101060465 Provides documentation of NUREG-0737 items Submittals re emergency preparedness & control room habitability
Forthcoming
UTLEY, E E Carolina Power & Light Co 00/12/31 52pp 07398 1

B101150610 Forwards response to outstanding items re NRC interim safety evaluation of auxiliary feedwater sys reliability, per NRC B01202 request
UTLEY, E E Carolina Power & Light Co 01/01/09 0pp 07462 24

B101290345 Forwards request for addl info re adequacy of station electric distribution sys voltages w/n encl
VARDA, S A Operating Reactors Branch 1 01/01/13 1p 07573 1

B101300042 Forwards Amend 55 to License DPR-23, safety evaluation & notice of issuance & availability
VARDA, S A Operating Reactors Branch 1 01/01/16 2pp 07503 1

--B101300050 Amend 55 to License DPR-23, adding operability requirements for boron injection tank heat tracing channels consistent w/other Tech Spec requirements for similar sys
VARDA, S A Operating Reactors Branch 1 01/01/16 4pp 07503 009

--B101300057 Safety evaluation supporting Amend 55 to License DPR-23
* Office of Nuclear Reactor Regulation, Director 01/01/16 07503 013

--B101300065 Notice of issuance & availability of Amend 55 to License DPR-23
VARDA, S A Operating Reactors Branch 1 01/01/16 2pp 07503 015

Q Inspection reports, IE Bulletins & correspondence

B101050184 Forwards Revision 2 to HB Robinson & Revision 1 to Brunswick 90-day repts w/o Brunswick reft
FURR, B J Carolina Power & Light Co 00/11/21 2pp 07380 001

--B101050194 Revision 2 to "Environ Qualification of Electrical Equipment HB Robinson EO Plant Unit 2," 90-day reft
* Carolina Power & Light Co 00/11/01 100pp 07380 004

B101050124 Requests existing data, summaries & records of inservice tests of containment w/gressed prestressing tendons, DRA, receiving contract to compile & review records of tendons
EISENHUT, D O Division of Licensing 00/11/25 3pp

B101000316 Forwards IE Insp Rept 50-261/80-33 on B01028-30 No noncompliance noted
KEENA, W B Region 2, Atlanta, Safeguards Branch 00/11/26 2pp 07443 233

--B101100020 IE Insp Rept 50-261/80-33 on B01028-30 No noncompliance noted Major areas inspected natl control & accounting
BODDES, J W, KALE, J D Region 2, Atlanta, Safeguards Branch 00/11/26 4pp 07443 235

B101100823 Forwards IE Insp Rept 50-261/80-35 on B01027-31 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/11/20 2pp 07443 239

--B101100826 IE Insp Rept 50-261/80-35 on B01027-31 No noncompliance noted Major areas inspected general plant operations
BROOKS, E H Region 2, Atlanta, Office of the Director, OUICA, Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/11/26 4pp 07443 241

B101120289 Suppl response to IE Bulletin 80-15 re emergency notification sys operability following loss of offsite power Test to be performed no later than B10101
FURR, B J Carolina Power & Light Co 00/12/15 2pp 07442 325

B101060233 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/12/16 07391 341

B101220412 Forwards interim response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment" Formal response will be provided by B10120, per B01229 telcon w/P Kellogg
FURR, B J Carolina Power & Light Co 01/01/05 12pp 07500 22

8010100343 Ltr to all power reactor licensees w/plants licensed to 790101 Forwards revised Section 19CFR50 AB & App R re fire protection features in nuclear power plants & lists of requirements for resolution of open issues
EISENHUT.D.O. Division of Licensing 80/11/24 8pp. 07445

8010100909 Forwards facility emergency planning info to be made publicly available w/o encl
SOUER, J.L. Division of Rules and Records 10/12/17 1p 07427 359

8010100745 Requests that encl facility emergency planning info be publicly available w/o encl
SOUER, J.L. Division of Rules and Records 10/12/31 1p. 07445 130

8010100028 Responds to 801101 & 29 ltrs requesting ltr of support facility emergency plan NRC will respond as described in encl 60NEO-0728 in event of facility emergency w/o encl
NEPPLER, J.C. Region 3, Chicago, Office of the Director 81/1/1p. 07467 322

--8010100034 Requests ltr of support re facility emergency plan attached
HUBBARD, G. Northern States Power Co 80/11/25 2pp 01

G. Adjudicatory correspondence

8010100038 Forwards NRC 801013 order modifying license & grant extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool by hydrodynamic loading conditions is required.
JPPDL170.1 A. Operating Reactors Branch 2. 01/01/13 3pp. 07506 352

--8010100095 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading condition is required. Mods must be installed by 80Q430.
EISENHUT.D.O. Division of Licensing 81/01/13 7pp. 07

H. General correspondence

8010100336 Responds to 801021 ltr requesting info re facilities requested except for security can be inspected at POR in Minneapolis, MN
JPPDL170.1 A. Operating Reactors Branch 2 80/11/17 2pp. 07309 001

80101270659 Responds to 801203 request for info re emergency preparedness near facilities for response to O Carlson 801101 concerns FEMA working w/state & local govt to assure that planning & preparedness are completed
DIRKMS, W.J. Office of the Executive Director for Operations 81/01/02 1p 07576 141

--80101290667 Forwards O Carlson 801101 ltr re emergency planning facilities Requests response
PROXMIRE, W. Senate. 80/12/03 3pp 07576 142.

P. Operating license stage documents & correspondence

8010100254 Ltr to all licensees (except SEP licensees) forward Revision 1 of inservice surveillance requirements for scrubbers under STB License amend application adding model Tech Spec to App A should be submitted within 120 days
EISENHUT.D.O. Division of Licensing 80/11/20. 1p.

--8010100271 Revised Pages 3/4 7-22 through 26.B 3/4 7-5 & 7-4 STB scrubber inservice insp requirements
A. Division of Licensing. 80/11/20 10pp

80101220466 Ltr to all power reactor licensees & applicants for summary of 801112 meeting to implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT.D.O. Division of Licensing. 80/11/26 8pp

8010190113 Ltr to all BWR licensees forwarding 801201 generic evaluation re BWR steam discharge sys Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes.
EISENHUT.D.O. Division of Licensing 80/12/09. 2pp.

--8010190141 Generic safety evaluation re short-term actions to assure continued safe operation of operating BWRs. Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl.
A. Division of Licensing 80/12/01. 212pp. 07183:001.

8010100343 Ltr to all power reactor licensees w/plants licensed to 790101 Forwards revised Section 19CFR50 AB & App R re fire protection features in nuclear power plants & lists of requirements for resolution of open issues
EISENHUT.D.O. Division of Licensing 80/11/24 8pp. 07445

8010100909 Forwards facility emergency planning info to be made publicly available w/o encl
SOUER, J.L. Division of Rules and Records 10/12/17 1p 07427 359

8010100745 Requests that encl facility emergency planning info be publicly available w/o encl
SOUER, J.L. Division of Rules and Records 10/12/31 1p. 07445 130

8010100028 Responds to 801101 & 29 ltrs requesting ltr of support facility emergency plan NRC will respond as described in encl 60NEO-0728 in event of facility emergency w/o encl
NEPPLER, J.C. Region 3, Chicago, Office of the Director 81/1/1p. 07467 322

--8010100034 Requests ltr of support re facility emergency plan attached
HUBBARD, G. Northern States Power Co 80/11/25 2pp 01

G. Adjudicatory correspondence

8010100038 Forwards NRC 801013 order modifying license & grant extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool by hydrodynamic loading conditions is required.
JPPDL170.1 A. Operating Reactors Branch 2. 01/01/13 3pp. 07506 352

--8010100095 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading condition is required. Mods must be installed by 80Q430.
EISENHUT.D.O. Division of Licensing 81/01/13 7pp. 07

H. General correspondence

8010100336 Responds to 801021 ltr requesting info re facilities requested except for security can be inspected at POR in Minneapolis, MN
JPPDL170.1 A. Operating Reactors Branch 2 80/11/17 2pp. 07309 001

80101270659 Responds to 801203 request for info re emergency preparedness near facilities for response to O Carlson 801101 concerns FEMA working w/state & local govt to assure that planning & preparedness are completed
DIRKMS, W.J. Office of the Executive Director for Operations 81/01/02 1p 07576 141

--80101290667 Forwards O Carlson 801101 ltr re emergency planning facilities Requests response
PROXMIRE, W. Senate. 80/12/03 3pp 07576 142.

P. Operating license stage documents & correspondence

8010100254 Ltr to all licensees (except SEP licensees) forward Revision 1 of inservice surveillance requirements for scrubbers under STB License amend application adding model Tech Spec to App A should be submitted within 120 days
EISENHUT.D.O. Division of Licensing 80/11/20. 1p.

--8010100271 Revised Pages 3/4 7-22 through 26.B 3/4 7-5 & 7-4 STB scrubber inservice insp requirements
A. Division of Licensing. 80/11/20 10pp

80101220466 Ltr to all power reactor licensees & applicants for summary of 801112 meeting to implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT.D.O. Division of Licensing. 80/11/26 8pp

8010190113 Ltr to all BWR licensees forwarding 801201 generic evaluation re BWR steam discharge sys Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes.
EISENHUT.D.O. Division of Licensing 80/12/09. 2pp.

--8010190141 Generic safety evaluation re short-term actions to assure continued safe operation of operating BWRs. Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl.
A. Division of Licensing 80/12/01. 212pp. 07183:001.

Just comply within specified timeframe
EISENHUT, D O Division of Licensing 80/12/15 13pp

8101050278 Forwards commitments to implementation dates specified in NUREG-0737 re hardware, procedural & organizational requirements. Remaining submittals re design descriptions & evaluations will be provided by 810201
MAYER, L O Northern States Power Co 80/12/30 19pp 07375 317

8101120218 Forwards schedule of projected completion dates for Mark I containment long-term program re installation of major plant rods
MAYER, L O Northern States Power Co 81/01/08 2pp 07445 292

8101300386 Forwards NRC 810113 order modifying license & granting extension of exemption from General Design Criterion 50. Reassessment of containment design for suppression pool by hydrodynamic loading conditions is required
IPPOLITO, T A Operating Reactors Branch 2 81/01/13 3pp 07586 352

--8101300395 Order modifying license & granting extension of exemption from General Design Criterion 50. Reassessment of containment design for suppression pool hydrodynamic loading conditions is required. Mods must be installed by 820430
EISENHUT, D O Division of Licensing 81/01/13 7pp 07586 355

G Inspection reports, IE Bulletins & correspondence

8101100348 Forwards IE Insp Rept 50-263/80-16 on 800801-31 & notices of violation. Apps A & B App B withheld (ref 10CFR2 7901).
EISENHUT, D O Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/09 2pp 07443 333

--8101100353 Notice of violation App A, from insp on 800801-31
Region 3, Chicago, Office of the Director 80/10/07 1p 07443 335

--8101100361 IE Insp Rept 50-263/80-16 on 800801-31 Noncompliance noted failure to control access to protected areas & failure to follow maint procedures Attachment A withheld (ref 10CFR2 7901)
LITTLE, W S, BROOK, C H, MAIBON, A L Region 3, Chicago, Office of the Director 80/10/07 9pp 07443 336

8101090266 Forwards IE Info Notice 80-30, "Cracking in Charging Pump Casing Cladding " No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30 2pp 07389 168

8101100796 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/31 2pp 07444 117

8101060609 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization " No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/07 2pp 07401 116

8101060367 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1 " No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/10 2pp 07391 067

8101140504 Forwards IE Insp Rept 50-263/80-19 on 801001-31. No noncompliance noted
EISENHUT, D O Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/05 2pp 07461 149

--8101140510 IE Insp Rept 50-263/80-19 on 801001-31. No noncompliance noted. Major areas inspected: routine operations, logs & records housekeeping & routine radiation protection.
BROOK, C H, MAIBON, A L, LITTLE, W S Region 3, Chicago, Office of the Director 80/12/03 4pp 07461 151

8101080038 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability " No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17 2pp 07419 350.

8101050199 Forwards IE Bulletin 80-25, "Operating Problems w/Target Rod & Safety Relief Valves at NRRs " No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/19 2pp 07377 323

8101130118 Responds in Items 1, 2, 3 & 5 of Suppl 4 to IE Bulletin 80-25 re failure of control rods to fully insert during scram at BWR Two unplanned scrams occurred on 800829 & 0904. Procedures revised to include manual check
GILBERTS, D E Northern States Power Co 80/12/23 4pp 07449 29

8101190274 Forwards addl response to IE Bulletin 80-17, Suppl 4, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Schematic & instruction manual for scram discharge w/ water level monitoring sys encl
GILBERTS, D E Northern States Power Co 80/12/30 2pp 07473 037

8101140156 Informs that commitment to IE Bulletin 79-19 re upgrading training program for joint personnel not met. Compliance expected by 810201
GILBERTS, D E Northern States Power Co 80/12/31 1p 07460 354

8101200170 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment 1801017 Indian Point 2 Event " Facility has no open cooling water sys inside containment
GILBERTS, D E Northern States Power Co 81/01/05 2pp 07486 290

8101230499 Responds to NRC 801229 request for addl info re facility inservice insp program. Forwards Revision 1 to NEDD-24197, "Info on Reactor Vessel Matl Surveillance Program "
MAYER, L O Northern States Power Co 81/01/20 6pp 07183 001.

--8101230499 "Info on Reactor Vessel Matl Surveillance Program " Revision 1
General Electric Co NEDD-24197 R1 79/10/31 12pp 07183 001

8101260494 Forwards addl info re inservice insp program re ASME Code Section XI, in response to NRC 801229 request info provided re relief requests from weld exams & estimated man-rem exposures from volumetric exams.
MAYER, L O Northern States Power Co 81/01/20 6pp 07558 107

R Periodic operating reports & related correspondence

8101130575 Forwards monthly operating rept for Dec 1980
MAYER, L O Northern States Power Co 81/01/09 1p 07339 001

--8101130581 Monthly operating rept for Dec 1980
MYHRE, A L Northern States Power Co 81/01/02 3pp 07309 001

80CKE1 50-265 QUAD-CITIES STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

H General correspondence

8101290518 Advises that future correspondence should be addressed to H. Dept of Nuclear Safety, 1035 Outer Park Drive, 3th Floor, Springfield, IL 62704
WRIGHT, G H Illinois, State of 81/01/22 1p

J Insurance & indemnity information

8101090608 Forwards guarantee of payment of deferred premiums for 1980
OSTER, J Commonwealth Edison Co 81/01/05 1p

8101270257 Forwards Endorsement 4 to Binders EO-1, EO-2, EO-3, EO-29, EO-30, EO-42 & EO-43 evidencing secondary financial protection
OSTER, J Commonwealth Edison Co 81/01/21 8pp

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for submersible under STS license amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT.D O Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 23.B 3/4 7-5 & 7-6 & 6-17 to STS submer inservice inservice requirements
* Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Support" -
EISENHUT.D O Division of Licensing 80/11/26 0pp

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR scram discharge sys Recommends short-term actions necessary to assure safe operation of CE BWR pending permanent design changes
EISENHUT.D O Division of Licensing 80/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp 07183 001

B101210445 Forwards "Responses to questions on Rule 50.71e. "Periodic Updating of FSARs & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame."
EISENHUT.D O Division of Licensing 80/12/15 13pp

B101040376 Submits addl response to NRC B00822 ltr Evaluation of Pratt 6-inch butterfly valve demonstrates that loads imposed & stresses developed in components during valve closure under LOCA event fall within acceptable limits
JANECEK.R F Commonwealth Edison Co 80/12/26 2pp

B101090066 Forwards ANI, rept. "Failure Analysis of Cracked Core Spray Piping from Quad Cities Unit 2 BWR"
JANECEK.R F Commonwealth Edison Co 80/12/29 1p 07376 236

--B101090070 Failure Analysis of Cracked Core Spray Piping from Quad Cities Unit 2 BWR
DIECKMANS.D R, FRACEL.D M Argonne National Laboratory. 80/07/31 46pp 07376 237

B101090500 Forwards response to NUREG-0737 No response provided for Dresden 1 Unit undergoing extensive mod & decontamination outage Requirements of NUREG-0737 will be addressed prior to startup of unit scheduled for June 1986
ABEL.J B Commonwealth Edison Co. 80/12/31 58pp

B101300154 "Adequacy of Station Electric Distribution Sys Voltages. Quad Cities Units 1 & 2"
UDY.A.C E0610 Idaho, Inc. FIN A-6256 B101300154 80/12/31 9pp 07583 114.

B101090001 Forwards Revision 15 pages to CE-i-A GA program topical rept. Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certification
ABEL.J B Commonwealth Edison Co. 81/01/02 1p.

--B101090005 Revision 15 pages to GA program topical rept
* Commonwealth Edison Co. CE-i-A R15 81/01/02 37pp.

B101300337 Submits schedule for completion of torus attached piping sys mod. Schedules based upon preliminary engineering analysis completed to date
REED.C Commonwealth Edison Co 81/01/08 1p

B101300233 Forwards NRC B10113 orders for mod of licenses & granting extension of exemption Licensees must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 50
IPPDLITO.T.A Operating Reactors Branch 2 81/01/13 3pp

B101200296 Advises that scram discharge sys re-evaluation has been completed. In response to NRC B01001 ltr Necessary mod will be implemented in first refueling outage beginning 223101.
JANECEK.R F Commonwealth Edison Co. 01/01/15 2pp

B101220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task

III A 2
DELGEORGE.L O Commonwealth Edison Co 81/01/19 1p

--B101220374 "Offsite Dose Calculation Sys Meteorological Monitoring Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants." Revision 2
G3LOEL.J C Commonwealth Edison Co 00/07/31 130pp

--B101220379 "Study of Low Level Dispersion Over Northern IL"
* Murray & Tretal, Inc 74/06/30 106pp

B101270481 Advises of concurrence w/NUREG-0619 re feedwater nozzles control rod drive return line nozzle cracking. In response to NRC B01113 ltr Results of further evaluations will be submitted by B10220
JANECEK.R F Commonwealth Edison Co 81/01/22 2pp.

0 Inspection reports, IE Bulletins & correspondence

B101080249 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required
KEPPLER.J O Region 3, Chicago, Office of the Director 80/10/30 2pp

B101090462 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Melroe Foundry Co, Inc." Written response required
KEPPLER.J O Region 3, Chicago, Office of the Director 80/11/08 2pp

B101100115 Forwards IE Insp Repts 50-254/80-23 & 50-265/80-25 on B00902-03, 18-19, 100B, 19-16 & 1106 No noncompliance noted.
F109ELL.J O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/24 2pp 07441 318

--B101100153 IE Insp Repts 50-254/80-23 & 50-265/00-25 No noncompliance noted Major areas inspected: OA/OC program, inservice insp data, torque mod & activities per IE Bulletins 79-03A, 80-00 & 80-13
HARO.R O Region 3, Chicago, Office of the Director.
DANIELSON.D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/19 11pp 07441 320

B101080079 Forwards IE Insp Repts 50-254/80-25 & 50-265/80-26 on B01020-1124 & notice of violation.
HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/20 2pp 07421 001

--B101080083 Notice of violation from insp on B01020-1124
* Region 3, Chicago, Office of the Director. 00/11/28 1p, 07421 003.

--B101080092 IE Insp Repts 50-254/00-25 & 50-265/00-26 on B01020-1124 Noncompliance noted: incorrect surveillance performed for inoperable diesel generator Inadequate testing resulted in pump failure
SPESBARD.R L, CURTISOTIHOE.N, DUPONT.B O Region 3, Chicago, Office of the Director 80/11/28 14pp 07421 004

B101090000 Ack receipt of B01112 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-254/80-20 & 50-265/80-22
KEPPLER.J O Region 3, Chicago, Office of the Director. 80/12/01 07187 001.

--B101090010 Response to NRC B01021 ltr re violations noted in IE 1 Repts 50-254/80-20 & 50-265/80-22 Corrective actions, lead blankets added to piping & ladder by Unit 2 CRO accumulators removed.
ABEL.J B Commonwealth Edison Co. 80/11/12 10pp. 07187 001

B101090530 Forwards IE Info Notice 80-43, "Failures of Continuous W Level Monitor for Scram Discharge Vol at Dresden Unit 2." No response required
KEPPLER.J O Region 3, Chicago, Office of the Director. 80/12/02 2pp.

B101090234 Ack receipt of B01201 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/80-22 & 50-265/80-24
HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09 1p. 07423 274.

--B101090244 Response to NRC B01106 ltr re violations noted in IE 1 Repts 50-254/80-22 & 50-265/80-24 Corrective actions: closed charoping water isolation valves & resumed control rod blade

8101060073 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves
Mfg. by Valtor Engineering Corp." Valves V70900-21-1 or
V70900-21-3 not used in any safety-related functions. Approx
40 manhours expended in bulletin review.
RAUBCH, T J Commonwealth Edison Co 00/12/12. 1p

8101080060 Forwards IE Info Notice 80-45, "Potential Failure of BWR
Backup Manual Scram Capability." No written response
required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17
2pp.

8101150240 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control
Rods to Insert During Scram at BWR." Written response
required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/18
1p.

8101290134 Forwards IE Insp Repts 80-254/80-20 & 80-265/80-29 on
801119-20. No noncompliance noted.
FIORRELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 00/12/18 2pp 07370 325.

--810129013R IE Insp Repts 80-254/80-20 & 80-265/80-29 on 801119-20 No
noncompliance noted. Major areas inspected. Licensee actions
re IE Bulletin 79-14.
VIN, I T Region 3, Chicago, Office of the Director.
DANIELSON, B H Region 3, Chicago, Reactor Construction &
Engineering Support Branch 80/12/18 5pp 07370 327

8101050170 Forwards IE Bulletin 80-25, "Operating Problems w/Target
Rock Safety Relief Valves at BWRs." No response required.
KEPPLER, J O. Region 3, Chicago, Office of the Director 00/12/19.
2pp.

8101080093 Responds to NRC 800818 request for monthly status report re
evaluations in response to IE Bulletin 79-14 tabulations of
piping sys w/stresses above FSAR levels & below operability
limit encl.
JANECEK, R F Commonwealth Edison Co 80/12/22 5pp

8101130198 Forwards IE Insp Repts 80-254/80-29 & 80-265/80-30 on
801208-12. No noncompliance noted.
HIND, J A Region 3, Chicago, Safeguards Branch 00/12/24. 2pp
07452 003.

--8101130206 IE Insp Repts 80-254/80-29 & 80-265/80-30 on 801208-12 No
noncompliance noted. Major areas inspected. Security plan &
program audit Details withheld (ref 10CFR2.790).
CHARBIOFFER, G., KNICELEY, J R. Region 3, Chicago, Office of the
Director HIND, J A Region 3, Chicago, Safeguards Branch.
80/12/23 2pp. 07452 005

8101200135 Forwards addl response to IE Bulletin 79-14, "Seismic
Analysis for As-Built Safety-Related Piping Sys." Revised
initial acceptance allowable for combined piping sys
stresses during BBE event provided.
JANECEK, R F. Commonwealth Edison Co. 81/01/05. 6pp

8101200155 Forwards response to IE Bulletin 80-24, "Prevention of
Damage Due to Water Leakage Inside Containment (801017
Indian Point 2 Event)." Surveillance procedures, of at least
monthly repetition, will be instituted by 010601.
RAUBCH, I J Commonwealth Edison Co 81/01/05. 6pp.

R Periodic operating reports & related correspondence

8101120153 Forwards "Environ Base Pathway Study," Spring 1979 through
Summer 1980.
JANECEK, R F. Commonwealth Edison Co 80/12/30. 1p. 07446 16B

--8101120156 "Environ Base Pathway Study," Spring 1979 through Summer
1980.
Eberline Instrument Corp 80/12/30. 44pp. 07446 169.

8101200302 Forwards list of changes, test & experiments completed during
Dec 1980.
KALIVIANAKIS, N Commonwealth Edison Co. 81/01/02 5pp. 07486 262

8101210463 Forwards monthly operating repts for Dec 1980.
KALIVIANAKIS, N Commonwealth Edison Co 81/01/02 1p. 07493 187

--8101210465 Monthly operating repts for Dec 1980
TUSBS, R C Commonwealth Edison Co. 81/01/01 32pp 07493 189

6 Reportable occurrences, LERs & related correspondence

0101060472 Forwards LER 80-033/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 80/12/29 1p 07

--8101060482 LER 80-033/03L-0 on 801201. RHR sys 11 supply from
generator alarmed. Caused by blown fuse F11 due to grounded
wire in Unit 2 diesel generator to bus 24-1 circuit
breaker auxiliary contacts. Wire repaired & fuse replaced.
CLARK, O Commonwealth Edison Co 80/12/29 2pp 07391

8101060486 Forwards LER 80-036/03L-0
KALIVIANAKIS, N Commonwealth Edison Co. 00/12/29 1p 07

--8101060492 LER 80-036/03L-0 on 801203. electromagnetic relief va
30 failed to open during reactor pressure rise subsequent
scram. Caused by excessive steam leakage between retainer
plug into val below main disc. Valve replaced.
KOPACZ, J J. Commonwealth Edison Co 80/12/29 2pp 073

8101130558 Forwards LER 80-037/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 80/12/29 1p 07

--0101130605 LER 80-037/03L-0 on 801207. RHR 28 pump inoperable
excessive leakage of mechanical seal. Caused by normal wear
of O-ring sealing surface. Mechanical seal replaced. Pump
returned to svc & satisfactorily tested.
MENDENHALL, E E Commonwealth Edison Co 80/12/29 2pp
07453 329

8101270740 Forwards LER 80-038/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 81/01/07 1p 07

--8101270755 LER 80-038/03L-0 on 801210. series of six trips oc
2A reactor recirculation pump motor generator set field
breaker. Caused by defective tachometer which controls pump
speed. Tachometer was replaced on 801231.
WYCKOFF, R L Commonwealth Edison Co. 01/01/07 2pp. 075

BOCKET 80-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR.
EISENHART, L O Division of Licensing 80/11/13 2pp

0101090110 Releases public version of util preliminary draft e
plan.
FELTON, J M Division of Rules and Records 80/12/01 1p
07428 001

--0101090113 Forwards public version of preliminary draft emer
FAY, C W Wisconsin Electric Power Co 80/07/25 1p 07

--8101090115 Forwards public version of preliminary draft emer
FAY, C W Wisconsin Electric Power Co 80/07/25 1p 07

--810109011D Public version of preliminary draft emergency pla
Wisconsin Electric Power Co 80/07/31. 200pp 07428

8101090916 Forwards facility emergency planning info to be mad
publicly available w/o encl.
SOUBER, J L Division of Rules and Records 80/12/16 1p
07427 363

8101190297 Forwards request for addl info re 800822 revised sa
contingency plan. Revised plan is acceptable, but approval is
subj to responsibility matrix section mods. Requests responses
within 60 days. Request Withheld (ref 10CFR2.790).
CLARK, R A Operating Reactors Branch 3 80/12/19 2pp 0

8101260340 Requests that completion data for fire protection a
extended to 81117 to provide time required for installation
of portable diesel generator panels w/modified carbon dioxide
extinguishing sys nozzles & light fixture diffusers.
FAY, C W. Wisconsin Electric Power Co 81/01/20 2pp 075

8101290140 Forwards facility emergency planning info to be mad
publicly available w/o encl.
SOUBER, J L Division of Rules and Records 81/01/23 1p.
07575 196

8101220403 Discusses PSC of WI process for review & assessment of economic & environ impact of proposed alternative actions & of generating replacement power. Forwards application for steam generator replacement.
FAY, C W Wisconsin Electric Power Co 81/01/16 4pp 07591 263

--8101240419 Application for authority to replace steam generators at facility. Requests Certificate of Authority per State of WI statute to acquire, but not install, replacement generators. Certificate of Gvt & util environ info encl.
MCNILEN, C G Wisconsin Electric Power Co 80/12/06 26pp.
07591 289

Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for injectors under RB License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D G Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28, 9 3/4 7-3 & 7-4 & 6-17 to STS shutdown inservice insp requirements.
Division of Licensing 80/11/20 10pp

8101220465 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. Potential for Low Fracture Toughness & Lateral Tearing on Component Supports.
EISENHUT, D G Division of Licensing 80/11/26 8pp

8101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of PSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D G Division of Licensing 80/12/15 13pp.

8101100510 Forwards Amdts 46 & 51 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability.
CLARK, R A Operating Reactors Branch 3 80/12/17 2pp 07445 049.

--8101100527 Amdts 46 & 51 to Licensee DPR-24 & DPR-27, respectively, changing Tech Specs to eliminate procedural steps for testing of containment spray additive valves.
CLARK, R A Operating Reactors Branch 3 80/12/17 6pp
07445 091

--8101100536 Safety evaluation supporting Amdts 46 & 51 to Licensees DPR-24 & DPR-27, respectively.
Operating Reactors Branch 3. 80/12/17 2pp 07445:097

--8101100543 Notice of issuance & availability of Amdts 46 & 51 to Licensees DPR-24 & DPR-27, respectively.
CLARK, R A Operating Reactors Branch 3 80/12/17 2pp.
07445 099

8101100195 Informs that addl duplicate amend fee for B007919 application is still applicable as second unit required addl administrative review. In response to 801114 ltr.
MILLER, W D License Fee Management Branch 80/12/19. 1p.
07309 001

8101300175 "Instrument Bus Mods, Point Beach Nuclear Plant, Units 1 & 2"
MAYS, B F. COLC Idaho, Inc. FIM A-6296 8101300175 80/12/31.
4pp 07583 185.

8101210564 Forwards addl response to NJREQ-0737 re post-TMI requirements for operating plants. Meteorology submittal completed. Control room habitability evaluation will be provided by B1C20a.
FAY, C W Wisconsin Electric Power Co 81/01/09. 10pp 07489 236

8101160451 Responds to NRC E01219 request for second Class I license amend approval fee for B00919 Tech Spec Change Request 6A. No addl administrative effort required for issuance of Tech Spec pages for second unit.
BURSTEIN, B. Wisconsin Electric Power Co 01/01/13. 2pp
07469 397

8101260410 Forwards revised Page 7 to 801223 response to NJREQ-0737, Item 11, K 3 12.
FAY, C W Wisconsin Electric Power Co 81/01/19 2pp 07522 260.

Supplied from either 480 volt or 4160 volt sys. Electrical sys diagram encl.
FAY, C W Wisconsin Electric Power Co 01/01/21 6pp 07545 249

0 Inspection reports, IE Bulletins & correspondence

8101050225 Forwards IE Info Notice 80-30. "Cracking in Charging Pump Casting Cladding" - No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30 2pp 07389 074

8101050124 Requests existing data, summaries & records of inservice ins tests of containments w/pressured peostressing tendons. DRNL receiving contract to compile & review records of tendons.
EISENHUT, D G Division of Licensing 80/11/25 3pp

8101070263 Forwards list identifying security badge number & clearance level for Region 3 personnel. Badge numbers for personnel identified by asterisks will be provided at later date.
KEPPLER, J O Region 3, Chicago, Office of the Director 00/11/23 6pp. 07410 353.

8101050578 Forwards IE Info Notice 80-43. "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2" - No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/03 2pp 07389 336

8101150646 Forwards IE Insp Repts 50-266/80-17 & 50-301/80-17 on B01001-31. No noncompliance noted.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/04. 2pp 07465 272

--8101150651 IE Insp Repts 50-266/80-17 & 50-301/80-17 on B01001-31. No noncompliance noted. Major areas inspected operational safety verification, monthly maint & surveillance & followup on LERs, IE bulletins & circulars.
OLDENDORF, W O, JACQUE, R L, HARNICK, R F. Region 3, Chicago, Office of the Director 80/12/04. 6pp 07465 274

8101100174 Forwards IE Insp Repts 50-266/80-21 & 50-301/80-21 on B01107 re NRC evaluation of licensed activity performance.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/10 2pp. 07445 020

--8101100181 IE Insp Repts 50-266/80-21 & 50-301/80-21 re B01107 ngt meeting to discuss regulatory performance of activities at Facility Encl licensee performance evaluation was presented. Performance found adequate.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/09. 10pp. 07445:022

8101070570 Forwards results of re-evaluation of masonry walls in response to IE Bulletin 80-11 includes schedule for upgrading walls to meet criteria.
FAY, C W Wisconsin Electric Power Co. 80/12/12 4pp 07415:2/0

8101070055 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 00/12/16 1p 07415 033

8101120201 Suppl B00718 responses to IE Bulletin 80-11 re masonry wall design. Wall omitted from final analysis will be reanalyzed using criteria of B01114 ltr.
FAY, C W Wisconsin Electric Power Co 80/12/26. 2pp 07447 035.

8101200150 Responds to IE Bulletin 80-24 re preventing damage from water leakage inside containment. Facilities have only one open cooling water sys inside containment & have had no significant leakage during plant operations.
FAY, C W Wisconsin Electric Power Co. 81/01/05. 12pp. 07187 001

8101280379 Submits final response to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Manufacturers did not utilize specified valve parts castings.
BURSTEIN, B. Wisconsin Electric Power Co. 81/01/13. 1p. 07550 06

8101280521 Responds to NRC B10109 request for addl info re IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)." Info provided re closed cooling water sys experience.
BURSTEIN, B Wisconsin Electric Power Co. 81/01/13 2pp. 07550:328

R Periodic operating reports & related correspondence

B101150517 Forwards monthly operating repts for Dec 1980
FAY, C W Wisconsin Electric Power Co B1/01/12 1p 07463 163

--B101150519 Monthly operating repts for Dec 1980
FAY, C W Wisconsin Electric Power Co. B1/01/07 10pp
07463 164

B Reportable occurrences, IERs & related correspondence

B101300748 PNO-111-U0-219 on B01126, reactor tripped twice caused by closure of main feedwater regulating valve, which resulted in low-low level in Steam Generator A Unit will remain down. Refueling outage had been scheduled to begin B01120. CULDEMOND, W. C., WARNICK, R. F., HEISHMAN, R. F. Region 3, Chicago, Office of the Director B011/28 1p. 07183.001

B101050429 Forwards LER B0-014/01T-0
FAY, C W Wisconsin Electric Power Co B0/12/23 1p 07390 130

--B101050448 LER B0-014/01T-0 on B01211, results of ongoing refueling outage steam generator eddy current insp indicated defective tubes Eight tubes w/crevice defects taken out of svc Caused by corrosion Defects plugged
FAY, C W Wisconsin Electric Power Co B0/12/23 4pp 07390 131

B101120333 Forwards LER B0-015/01T-0
FAY, C W Wisconsin Electric Power Co B0/12/23 1p. 07447 146

--B101120367 LER B0-065/01T-0 on B01210, during refueling outage surveillance testing of safety-related shock suppressors, snubber J-1H-14 found to be inoperable Caused by low level in reservoir, resulting from piston rod D-ring seal leakage.
FAY, C W Wisconsin Electric Power Co B0/12/23 2pp. 07447 147.

B101300743 PNO-111-U0-W19A on B01126, reactor tripped twice Caused by closure of main feedwater regulating valve During refueling outage, licensee conducted nondestructive testing of high stress areas of feedwater piping
CULDEMOND, W. C., WARNICK, R. F., HEISHMAN, R. F. Region 3, Chicago, Office of the Director B1/01/02 2pp 07183.001.

B101270699 Forwards LER B0-019/01T-1
FAY, C W Wisconsin Electric Power Co 01/01/07 1p. 07549 060.

--B101270710 LER B0-019/01T-1 on B01210, during refueling outage surveillance testing, snubber J-1H-14 on power operated relief valve hoeder was determined inoperative Caused by low level in snubber reservoir due to O-ring seal leakage
FAY, C W Wisconsin Electric Power Co B1/01/09 2pp 07549.069

B101270967 Forwards LER B1-016/03L-0
BURSTEIN, B. Wisconsin Electric Power Co. 01/01/15 1p 07541.135.

--B101270974 LER B1-016/03L-0 on B01217, during testing, emergency diesel generator 40 failed to close in on bus Caused by slippage of flexible shaft coupling on speed sensing frequency generator drive shaft Coupling secured
FAY, C W Wisconsin Electric Power Co B1/01/13 2pp. 07541.136.

B101270960 Forwards LER B1-001/01T-0
FAY, C W Wisconsin Electric Power Co. B1/01/16 1p. 07541.131

--B101270964 LER B1-001/01T-0 on B10102, while performing monthly ventilation sys test, supply breaker for safeguards motor control ctr 1B42 tripped Caused by dust in instantaneous trip valve on breaker Breaker cleaned & tested.
FAY, C W Wisconsin Electric Power Co B1/01/16 3pp 07541.132

DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants-CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing B0/11/13 2pp

B101070242 Provides update info re admittance of NRC personnel to facility, per NRC B01107 ltr Util should train NRC personnel re badge issuance, escort duties & emergency evacuation
SEYFRIT, K V Region 4, Dallas, Office of the Director B0/12/05 2pp 07415.238

B101140212 Informs that licensee should conduct emergency exercise within one yr from B03401 or prior to issuance of OL
Schedule of drills should be provided.
SEYFRIT, K V Region 4, Dallas, Office of the Director B0/12/23 1p 07461 257

B101090602 Forwards proposed mods to security plan re elevator security Mods withheld (ref 10CFR2 790)
FULLER, J K Public Service Co of Colorado B0/12/31 1p 07428 361

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing B0/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 2B, D 3/4 7-5 & 7-6 & 6-BTS snubber inservice insp requirements
* Division of Licensing B0/11/20 10pp

B10120466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing B0/11/26 8pp.

B101210445 Forwards responses to questions on Rule 50 710, 'Periodic Updating of FSARs' & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing B0/12/15 13pp

B101120204 Responds to NRC B00307 ltr re addl TH1-2 related requirements Reiterates NRC position on rept re ECCS outage, licensee reft & proposed Tech Specs changes Table re Sys 92 outages for June 1975-Jul 1980 encl
WAREHOUR, B. Public Service Co of Colorado B0/12/26 7pp 07439 332

B101120425 Application to amend License BPR-34, changing Tech Specs Sections 4 3 10 & 5 3 3 re boiler feed snubbers & reactor bldg exhaust filter surveillance requirements, respectively.
Class II amend Fee encl
LEE, O R Public Service Co of Colorado B0/12/31 2pp 07437 334

--B101120427 Proposed Tech Specs Sections 4 3 10 & 5 3 3 re boiler snubbers & reactor bldg exhaust filter surveillance requirements, respectively
* Public Service Co of Colorado B0/12/31 11pp 07437 330

B101130369 Application for amend to License BRR-34, proposing changes Tech Specs re Class I hydraulic snubbers & reactor bldg exhaust sys
LEE, O R Public Service Co of Colorado B0/12/31 4pp. 07431.318

--B101130374 Tech Specs LCB 4 3 10, Table 4.3 10-1 & SR 5.3 3 for C hydraulic snubbers & reactor exhaust sys
* Public Service Co of Colorado B0/12/31 9pp 07451 322

B101130393 Forwards application for amend to License BPR-34, Apps A Tech Specs Includes refs, background & reason for proposed revisions, summary of proposed Tech Spec revisions, revisions to App A, proposed App B & final ecological monitoring reft.
LEE, O R Public Service Co of Colorado B1/01/02 3pp 07447 312

--B101130394 Application for amend to Apps A & B Tech Specs of Lic BPR-34 re environ monitoring Includes background & reasons for proposed revisions, summary of proposed Tech Specs revisions & proposed revisions to OL.
LEE, O R Public Service Co of Colorado B1/01/02 12pp 07447 313

--B101130396 Proposed revisions to App A Tech Specs Pages 4 B-1 th 4 B-8 inclusive, 5 B-1 & 5 B-2 & 5.9-1 through 5.9-11, inclusive, re environ monitoring
* Public Service Co of Colorado B1/01/02 22pp 07447 32

--B101130398 Proposed ETS (nonradiological) for facility.
* Public Service Co of Colorado B1/01/02 44pp 07447 32

--B101130460 Final reft, 'Ecological Monitoring, Fort St Vrain Genoa Station,' Jan 1972-Dec 1979 NROER Permit CU-C001121 encl
GLOVER, F A, JOHNS, J R, SWART, F E Thorne Ecological Institute B0/09/26 236pp 07448 012

B010270629 Forwards supplementary info for proposed change to Test Specs Table 5.1 re B01003 request for extension of fuel element core residence time capability w/reactor core refueling intervals
SMART, F E Public Service Co. of Colorado 81/01/23 5pp
07548 103

C Inspection reports, IE Bulletins & correspondence

B01070215 Forwards IE Insp Rept 50-267/80-21 on B01001-31 & notice of violation
MAOSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/14 2pp 07415 155

--B01070219 Notice of violation from insp on B01001-31
Region 4, Dallas, Office of the Director. 80/10/13 1p
07415 157

--B01070223 IE Insp Rept 50-267/80-21 on B01001-31 Noncompliance noted:
Failure to seal two valves in position as required per Tech Spec
OICKEREDN, M W, COLLINS, R E, WESTERMAN, T F Region 4, Dallas, Office of the Director 80/10/13 5pp 07415 158

B01080085 Responds to IE Bulletin 80-23 re failures of Valcor Engineering Corp solenoid valves No such valves installed at facility
SMART, F E Public Service Co. of Colorado 80/11/21 1p
07421 089

B01090264 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (October 17, 1903 Indian Port 2 Event)" Written response required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/11/26 1p 07424 031

B01080326 Forwards IE Info Notice 80-42, Effect of Radiation on Hydraulic Stubber Fluid. No response required
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/11/24 1p 07392 055

B01140191 Suppl response to IE Bulletin 80-11 re masonry wall design
Eight addl walls identified in followup insp which have potential of affecting Class 1E equipment during seismic event
SMART, F E Public Service Co. of Colorado 80/11/23 1p
07461 291

B01060293 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/11/26 1p 07392 031

B01120143 Responds to IE Bulletin 80-21 re valve bolts supplied by Malcolm Foundry Co, Inc No castings purchased from vendor
SMART, F E Public Service Co. of Colorado 80/12/03 1p
07446 337

B01070190 Ack receipt of B01103 & 10 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/80-13
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/12/04 1p 07415 138

--B01070205 Responds to NRC B01008 ltr re violations noted in IE Insp Rept 50-267/80-13 Corrective actions: duties of radiation protection manager assigned to technical svcs section
LEE, O R Public Service Co. of Colorado 80/11/03 2pp
07413 139

--B01070211 Responds to NRC B01008 ltr re violations noted in IE Insp Rept 50-267/80-13 Corrective actions: duties of radiation protection manager assigned to technical svcs dept
WAREMBOURG, D W Public Service Co. of Colorado. 80/11/18 10pp
07415 141

B01120134 Responds to IE Bulletin 80-24 re water leakage inside containment Facility secondary containment not similar to described containment
LEE, D R Public Service Co. of Colorado 80/12/05 1p 07446 353

B01080612 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Valve at Dresden Unit 2." No response required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/08 1p 07391 038

B01100067 Forwards IE Insp Rept 50-267/80-17 on B00818-22 & notice of violation. Notice of violation withheld (ref 10CFR2 790)
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/18 2pp 07443 015

--B010100074 IE Insp Rept 50-267/80-17 on B00818-22 Noncompliance noted: vital area physical barrier not locked & vital area key available to all personnel using elevator Details withheld (ref 10CFR2 790)
CALCHELL, R A, KELLY, J A Region 4, Dallas, Office of the Director 80/12/18 2pp 07443 017

R Periodic operating reports & related correspondence

B010230187 Final rept, "Ecological Monitoring Fort St Vrain Generating Station for 1972-79"
SCHAEFER, T E Public Service Co. of Colorado. GLOVER, F A, JOHNS, J R Thorne Ecological Institute 00/09/26 220pp.
07509 159

B01140486 Forwards monthly operating rept for Osc 1980
WAREMBOURG, D Public Service Co. of Colorado 81/01/09 1p
07358 151

--B01140487 Monthly operating rept for Osc 1980
GAHM, J W Public Service Co. of Colorado 81/01/09 5pp.
07458 152

G Reportable occurrences, LERs & related correspondence

B01090192 PNG-1V-01-01 on B0102, main turbine was tripped at low power conditions to investigate suspected problems w/hot reheat valves Valves failed to fully close following trip Unit will be shut down for approx seven days for repairs
WESTERMAN, T F Region 4, Dallas, Office of the Director 81/01/07 1p 07442 273

B01140625 Forwards LER 80-069/03X-1
WAREMBOURG, D Public Service Co. of Colorado. 81/01/09 1p.
07461 193

--B01140630 LER 80-065/03X-1 on B01105, reactor operated in degraded mode Caused by removal of shutoffs for verification of bleed rate. Shutoffs were adjusted & replaced.
GAHM, J W Public Service Co. of Colorado 81/01/09 4pp
07461 104

B01150639 Forwards LER 80-074/03L-0
WAREMBOURG, D Public Service Co. of Colorado 81/01/09 1p
07461 108

--B01150646 LER 80-074/03L-0 on B01210, pilot valve in fixed water vss resulted in control room alarm Caused by leakage past pilot valve seat due to corrosion & settling of sediment from fire water Corrosion removed.
GAHM, J W Public Service Co. of Colorado 81/01/09 4pp
07461 109

B01210406 Forwards LER 80-075/03L-0
WAREMBOURG, D Public Service Co. of Colorado. 81/01/14 8pp.
07493 121

--B01210410 LER 80-075/03L-0 on B01215-31, plant operated w/total p radient oxidants greater than 10 ppm & average core outlet temp greater than 1200 F on seven occasions. Caused by high moisture in helium storage tanks Tanks purged.
GAHM, J W Public Service Co. of Colorado. 81/01/14 1p
07493 129

B01210480 Forwards LER 80-077/03L-0
WAREMBOURG, D Public Service Co. of Colorado. 81/01/14 1p
07490 152

--B01210488 LER 80-077/03L-0 on B01224, one bearing water makeup pump removed from svc during normal operation. Caused by need to repair valve leak Valves repaired & pump returned to svc.
GAHM, J W Public Service Co. of Colorado. 81/01/14 3pp.
07490 153

B01220413 Forwards LER 80-076/03L-0
WAREMBOURG, D Public Service Co. of Colorado 81/01/16 4pp
07505 188

--B01220421 LER 80-076/03L-0 on B01216, results of lab carbon sample analysis of 1A reactor plant exhaust filter showed less radioactive methyl iodine removal capability than required. Caused by normal depletion of activated charcoal adsorber.
GAHM, J W Public Service Co. of Colorado 81/01/16 1p.
07505 192

8101300474 Transcript of ACRS Subcommittee for Fort St Vrain Nuclear
Generating Station 810127 meeting in Platteville, CO
Pp 1-271 Viewgraphs & supporting documents encl
* ACRS - Advisory Committee on Reactor Safeguards 81/01/27
346pp 07377-226

V. Operator Examinations

8101060536 Forwards response to 801031 request re TMI action plan
requirements, NUREG-0737, covering shift staffing
requirements, training programs & licensing exams
WAREMBOURG, D W Public Service Co. of Colorado 80/12/20 69pp.
07309-001

8101060448 Forwards response to NUREG-0737 Item I A 1 i describing
program for technical advisors.
WAREMBOURG, O W Public Service Co. of Colorado 80/12/30 43pp
07398-264.

8101220548 Forwards revised licensed operator requalification program
WAREMBOURG, O W. Public Service Co. of Colorado 81/01/02 1p
07303-062

--8101220993 Revised licensed operator requalification program
* Public Service Co. of Colorado 00/12/23 11pp 07303-063.

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
010102 & by applicants as part of FOAR
EISENHUT, O O Division of Licensing 00/11/13 2pp.

8101140294 Requests that encl facility planning info be made publicly
available w/o encl
BOUQUER, J L. Division of Rules and Records 80/12/31 1p
07461-262

8101230440 Suppl 810102 & 07 ltr & crisis mgt plan State of NC
emergency response plan for facility will be provided when
available
PARKER, W O. Duke Power Co. 01/01/19 1p 07311-124

8101290594 Releasee public version of util emergency plan
FELTMAN, J M. Division of Rules and Records 81/01/26 1p.
07187-001.

--8101290999 Forwards public version of site-specific radiological
emergency plan, consisting of Part I of State of SC
operational radiological emergency response plan Suppl
810102 submittal.
PARKER, W. B. Duke Power Co. 81/01/07 1p. 07187-001

--8101290608 Public version of site-specific radiological emergency
response plan, consisting of Part I of State of SC
operational radiological emergency response plan
* Duke Power Co. 80/12/31 33pp 07187-001

I. Financial Information

8101060503 Forwards util submission of guarantee of retrospective
premiums per code requirements & in response to NRC 801219
& 30 requests.
MORROW, N P Duke Power Co. 80/12/30. 1p 07309-001.

--8101060509 Requests that util provide approved guarantee of payment of
deferred premiums for each operating reactor over 100 Mw
per code requirements
BALITMAN, J Utility Finance Branch (formerly Antitrust &
Indemnity) 80/12/19. 1p. 07309-001.

P. Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except BEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under STS. Licensees amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT, O. O. Division of Licensing. 80/11/20 1p.

* Division of Licensing 80/11/20. 10pp
8101220466 Ltr to all power reactor licensees & applicants forward
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, O O Division of Licensing 80/11/26 8pp

8101090175 Forwards Amends 89.89 & 86 to Licenses DPR-38, DPR-47 &
DPR-55, respectively, safety evaluation & notice of issuance
& availability
REID, R W Operating Reactors Branch 4 80/12/10 2pp 07426-3

--8101090194 Amends 89.89 & 86 to Licenses DPR-38, DPR-47 & DPR-55
respectively, revising Tech Specs to redefine term "operable"
& to add general limiting conditions for operation
REID, R W Operating Reactors Branch 4 80/12/10 11pp
07426-310

--8101090193 Safety evaluation supporting Amends 89.89 & 86 to Lice
DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/10
07426-321

--8101090205 Notice of issuance & availability of Amends 89.89 & 86
Licenses DPR-38, DPR-47 & DPR-55, respectively
REID, R W Operating Reactors Branch 4 00/12/10 2pp
07426-323

8101210445 Forwards responses to questions on Rule 50.71e, "Periodi
Updating of FSARs" & FR notice of final rule. BEP plants need
not comply w/rule until program is complete Non-BEP plants
must comply within specified time frame.
EISENHUT, O O Division of Licensing 80/12/15 13pp

8101200223 Requests amend to license revising Tech Specs re disposa
burned contaminated oil, per 000819 ltr
PARKER, W O. Duke Power Co. 00/12/17 2pp 07487-028

8101070558 Forwards corrected Tech Spec pages (power distribution
curves) to NRC 800222 Cycle & reload licensee amend
REID, R W Operating Reactors Branch 4 00/12/10 2pp 07404-3

--8101070565 Corrected Tech Spec pages (power distribution curves)
Amend 01 to License DPR-38
REID, R W. Operating Reactors Branch 4 (Pre 800428). 00/12/18
8pp. 07404-359.

8101100440 Forwards Amends 90.90 & 87 to Licenses DPR-38, DPR-47 &
DPR-55, respectively, safety evaluation, EIA & notice of
issuance & availability
REID, R W Operating Reactors Branch 4. 80/12/24 2pp 07444-2

--8101100448 Amends 90.90 & 07 to Licensee DPR-38, DPR-47 & DPR-55,
respectively, allowing increase in spent fuel storage
capacity.
NOVAK, T M Assistant Director for Operating Reactors 80/12/2
7pp 07444-203.

--8101100462 Safety evaluation supporting Amends 90.90 & 07 to Lice
DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director 80/12/24
07444-213

--8101100471 EIA supporting Amends 90.90 & 87 to Licenses DPR-38, DPR-
DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director. 00/11/24
07444-222

--8101100479 Notice of issuance & availability of Amends 90.90 & 87
Licenses DPR-38, DPR-47 & DPR-55, respectively & negative
declaration
ERICKSON, P J Operating Reactors Branch 4 80/12/24 2pp
07444-231

8101050094 Application for amend of Licenses DPR-38, DPR-47 & DPR-55
changing Tech Specs, Section 4 to modify certain surveillance
requirements on annual basis for each refueling outage. Amend
fees encl.
PARKER, W B Duke Power Co. 80/12/29. 3pp 07376-301.

--8101050101 Proposed changes to Tech Specs, Section 4, modifying
surveillance requirements from performance on annual basis
to performance during each refueling outage
* Duke Power Co. 80/12/29 18pp. 07376-304

B101060483 Forwards proposed Tech Specs revision re reactor bldg & containment leakage tests, supplementing B01024 submittal. Containment air lock testing to be submitted upon review completion.
PARKER, W D Duke Power Co 80/12/29 1p 07396 318.

--B101060483 Proposed Tech Specs 3 b & 4.4 revision re reactor bldg & containment leakage tests, respectively. Containment leakage test revision reflects App J requirements.
Duke Power Co 80/12/29 15pp 07396 319

--B101060491 Test Requirement Dates & Justification for Reversed Direction Testing
Duke Power Co 80/12/29 8pp 07396 334

B101210555 Forwards list of TLO station locations near facility & proposed route for exchanging TLOs for IAC direct radiation monitoring network w/o encs.
SCHIR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07489 116

B101070269 Forwards response to NUREG-0737, post-TMI requirements, including info re shift technical advisor, short-term accident & procedures review & containment isolation operability. Control Files version of emergency plan encl.
PARKER, W D Duke Power Co 81/01/02 70pp 07389 012

--B101070286 "Thermal-Mechanical Rest - Effect on HPI on Vessel Integrity for Small Break LOCA Event w/ Extended Loss of Feedwater"
Two oversized drawings & responses to NUREG-0737 encl.
Roberts & Wilson Co 84K-1648 80/11/30 158pp

B101130404 Provides alternate methods of nondestructive exams for welds to be performed in place of hydrostatic testing, following maint or mod NRC B01107 ltr granted licensee relief from ASME Code requirements re hydrostatic testing.
PARKER, W D Duke Power Co 81/01/07 2pp 07452 111.

B101160316 Advises that response to NRC B01114 ltr requesting addl info re emergency feedwater sys will be ready for submittal by 8/03/02.
PARKER, W D Duke Power Co 81/01/12 1p 07471 148

B101270799 Forwards request for addl info re Cycle & reload NRC assumptions discussed in encl B01028 ltr should be verified as correct & applicable to facility for proposed cycle of operation.
REID, R W Operating Reactors Branch 4 81/01/12 5pp 07549 083

--B101270805 Submits addl comments re planned transfer from TAFV to TACD-2 code for fuel & ECCB analysis.
RUBENSTEIN, L S Assistant Director for Core & Containment Systems 80/10/28 2pp 07549 091

B101210493 Responds to NRC B01C01 request for proposed updated Tech Specs for fire protection program. Tech Specs currently under review & will be submitted by B10316.
PARKER, W D Duke Power Co 81/01/15 1p 07489 278

B101220428 Advises of delay of response to NRC B01027 ltr re standby shutdown facility. Response will be provided no later than B10216.
PARKER, W D Duke Power Co 81/01/15 1p 07493 252

D Inspection reports, IE Bulletins & correspondence

B101050124 Requests existing data, summaries & records of inservice insp tests of containments w/ gressed pressurizing tendons, ORNL, receiving contract to compile & review records of tendons.
EISENHUT, D O Division of Cleaning 80/11/25 3pp.

B101080141 Act receipt of B01126 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/80-32, 50-270/80-28 & 50-287/80-25.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/12 1p 07421 019

--B101080148 Act receipt of IE Insp Repts 50-269/80-32, 50-270/80-28 & 50-287/80-25 on B00902-30. No proprietary info. Corrective actions Tech Specs revised, personnel training reviewed & ltr issued to station manager.
PARKER, W D Duke Power Co 80/11/26 3pp 07421 019

--B101080155 Forwards IE Insp Repts 50-269/80-32, 50-270/80-28 & 50-287/80-25 on B00902-30 & notice of violation.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/11/03 2pp 07421 022

--B101080161 Notice of violation from insp on B00902-30, Region 2, Atlanta, Office of the Director. 80/11/03 1p 07421 024

--B101080177 IE Insp Repts 50-269/80-32, 50-270/80-28 & 50-287/80-25 on B00902-30. Noncompliance noted failure to comply w/ Tech Spec requirement for processing major procedure change.
JAFEF, J, ORDEHS, W, MYERS, D Region 2, Atlanta, Office of the Director 80/11/03 7pp 07421 025

B101150136 Suppls B00918 ltr re mods to reactor bldg spray sys for facilities. Mods to be installed during next available forced outage of sufficient duration or next refueling outage.
PARKER, W D Duke Power Co 80/12/12 1p 07462 191

B101060225 Forwards IE Info Notice 80-44, "Activation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/12 1p 07391 334

B101160258 Responds to IE Bulletin 80-23 re Valcor Engineering Co solenoid valve failure. Until will replace all Valcor solenoid valves w/ ARCO solenoid valves as soon as received.
PARKER, W D Duke Power Co 80/12/29 1p 07470 298

B101200575 Forwards response to IE Bulletin 80-24 re prevention of damage due to water leakage inside containment. Tech Specs & station directives ensure reporting of abnormal degradation of primary containment.
PARKER, W D Duke Power Co 81/01/06 11pp 07477 240

B101210213 Forwards supplemental response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls." Mods completed on high pressure injection pumps, penetration room exhaust fans, reactor bldg cooling unit fan & Keowee stert.
PARKER, W D Duke Power Co 81/01/07 13pp 07488 017.

B101190285 Forwards request for relief from ASME Code Section XI inservice insp requirements re main feedwater sys check valves. Approval requested by B10114.
PARKER, W D Duke Power Co 81/01/10 5pp 07475 332.

R Periodic operating reports & related correspondence

B101210462 Forwards monthly operating repts for Dec 1980.
PARKER, W D Duke Power Co 81/01/15 1p 07493 170.

--B101210464 Monthly operating repts for Dec 1980.
REAVIS, J A Duke Power Co 81/01/15 16pp 07493 171.

S Reportable occurrences, LERs & related correspondence

B101210502 Forwards LER 80-037/03L-0.
PARKER, W D Duke Power Co 81/01/15 2pp 07490 189.

--B101210507 LER 80-037/03L-0: on B01216, CBABT pump delivered no fuel while personnel were attempting sample test & was declared inoperable. Probably caused by low oil level in hydraulic reservoir & clogged pressure gauge line.
JOHNS, J L Duke Power Co 81/01/15 1p 07490 191

B101220378 Forwards LER 80-038/03L-0.
PARKER, W D Duke Power Co 81/01/16 3pp 07500 251

--B101220380 LER 80-038/03L-0: on B01217, during fire protection testing, main transformer automatically isolated from overhead power path. Caused by personnel error. Tech Specs revised to remove overhead path from svc prior to testing.
PHILPOTT, F T Duke Power Co 81/01/16 1p 07500 254

B101230489 Forwards LER 80-039/03L-0.
PARKER, W D Duke Power Co 81/01/19 2pp 07510 288.

--B101230491 LER 80-039/03L-0: on B01220, smoke detector covering 11b & 21b alarmed. Caused by dusty ambient conditions where detector is located. Detector replaced & string returned to svc. Twice weekly preventive maint program implemented.
JOHNS, J L Duke Power Co 81/01/19 1p 07510 290.

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101140294 Requests that encl facility planning info be made publicly available w/o encl
SOUVER, J L Division of Rules and Records 80/12/31 1p
07461 262

B101230440 Suppls B10102 & 07 ltrs & crisis mgt plan State of NC emergency response plan for facility will be provided when available
PARKER, W O Duke Power Co. 01/01/19 1p. 07511 124

B101290594 Releases public version of util emergency plan.
FELTON, J M Division of Rules and Records 81/01/26 1p
07107.001.

--B101290599 Forwards public version of site-specific radiological emergency plan, consisting of Part I of State of SC operational radiological emergency response plan Duppls B10102 submittal.
PARKER, W O Duke Power Co. 01/01/07 1p. 07107.001.

--B101290608 Public version of site-specific radiological emergency response plan, consisting of Part I of State of SC operational radiological emergency response plan
* Duke Power Co. 00/12/31 53pp 07107.001

I Financial information

B101060303 Forwards util submission of guarantee of retrospective premiums per code requirements & in response to NRC 001219 & 30 requests.
MORROW, N P Duke Power Co 00/12/30 1p. 07309.001.

--B101060309 Requests that util provide approved guarantee of payment of deferred premiums for each operating reactor over 100 Mw per code requirements
BALTZMAN, J Utility Finance Branch (formerly Antitrust & Indemnity) 00/12/19 1p 07309.001.

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except DEP licensees) forwarding Revision of inservice surveillance requirements for snubbers under STS license amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p.

--B101100271 Revised Pages 3/4 7-22 through 20.B 3/4 7-5 & 7-6 & 4-17 to STB snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of 001112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 0pp.

B101090175 Forwards Amends 89, 89 & 86 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R W Operating Reactors Branch 4. 80/12/10 2pp 07426.300.

--B101090184 Amends 89, 89 & 86 to Licenses DPR-38, DPR-47 & DPR-55 respectively, revising Tech Specs to redefine term "operable" & to add general limiting conditions for operation.
REID, R W Operating Reactors Branch 4 80/12/10 11pp
07426.310.

--B101090195 Safety evaluation supporting Amends 89, 89 & 86 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/10 2pp.
07426.321.

--B101090205 Notice of issuance & availability of Amends 89, 89 & 86 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R W Operating Reactors Branch 4. 80/12/10 2pp.
07426.323.

B101210445 Forwards responses to questions on Rule 50 710. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-BEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp

B101200223 Requests amend to license revising Tech Specs re disposal burned containers noted 011 per 000519 ltr
PARKER, W O Duke Power Co 80/12/17 2pp 07487.028

B101100440 Forwards Amends 90, 90 & 07 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation, EIA & notice of issuance & availability
REID, R W Operating Reactors Branch 4 00/12/24 2pp 07444

--B101100440 Amends 90, 90 & 07 to Licenses DPR-38, DPR-47 & DPR-55, respectively, allowing increase in spent fuel storage capacity
KOVAK, T M Assistant Director for Operating Reactors 80/12/24 7pp 07444.203

--B101100462 Safety evaluation supporting Amends 90, 90 & 07 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director 80/12/24 07444 213

--B101100471 EIA supporting Amends 90, 90 & 07 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 80/11/24 07444 222

--B101100479 Notice of issuance & availability of Amends 90, 90 & 07 to Licenses DPR-38, DPR-47 & DPR-55, respectively & negative declaration
ERICKSON, P J Operating Reactors Branch 4 80/12/24 2pp 07444.231

B101090094 Application for amend of Licenses DPR-38, DPR-47 & DPR-55, changing Tech Specs, Section 4 to modify certain surveillance requirements on annual basis for each refueling outage. Amend fees encl
PARKER, W O Duke Power Co 80/12/29 3pp 07376.301.

--B101090101 Proposed changes to Tech Specs, Section 4, modifying surveillance requirements from performance on annual basis to performance during each refueling outage
* Duke Power Co 80/12/29 18pp. 07376.304.

B101090403 Forwards proposed Tech Specs revision re reactor bldg & containment leakage tests, supplementing B101024 submittal. Containment air lock testing to be submitted upon revision completion
PARKER, W O Duke Power Co. 80/12/29 1p. 07396.318

--B101090408 Proposed Tech Specs 3 & 4.4 revision re reactor bldg containment leakage tests, respectively. Containment leakage test revision reflects App J requirements
* Duke Power Co 80/12/29 13pp 07396.319

--B101090491 "Test Requirement Bases & Justification for Reverse Direction Testing"
* Duke Power Co 80/12/29 8pp 07396.334.

B101210565 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encls
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07489.116.

B101070267 Forwards response to NUREG-0737, post-TMI requirements, including info re shift technical adviser, short-term accident & procedures review & containment isolation dependability. Central Files version of emergency plan encl.
PARKER, W O Duke Power Co 01/01/02 70pp. 95189.012

--B101070286 "Thermal-Mechanical Rept - Effect on H₂O on Vessel 1 for Small Break LOCA Event w/Extended Loss of Feedwater"
Two oversized drawings & responses to NUREG-0737 encl
* Babcock & Wilcox Co BAW-1640 80/11/30 150pp

B101130404 Provides alternate methods of nondestructive exams for to be performed in place of hydrostatic testing, following maint on mod NRC B01107 ltr granted licensee relief from ASME Code requirements re hydrostatic testing
PARKER, W O Duke Power Co. 81/01/07 2pp. 07452.111

B101150366 Advises that response to NRC B01114 ltr requesting add re emergency feedwater sys will be ready for submittal by B10302
PARKER, W O Duke Power Co. 81/01/12 1p 07471.140

B101210493 Responds to NRC B01001 request for proposed update Tech Specs for fire protection program Tech Specs currently under review & will be submitted by B10316
PARKER, W O Duke Power Co B1/01/15 1p 07489 278

B101220428 Advises of delay of response to NRC B01027 ltr re standby shutdown facility Response will be provided no later than B10216
PARKER, W O Duke Power Co 01/01/15 1p 07493 252

G. Inspection reports, IE Bulletins & correspondence

B101050124 Requests existing data, summaries & records of interservice insp tests of containment w/ increased processing tendons
DRAK receiving contract to compile & review records of tendons
EISENHUT, D O Division of Licensing B0/11/25 3pp

B101080141 Act receipt of B01126 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts B0-269/B0-32, B0-270/B0-28 & B0-207/B0-25
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/12/12 1p 07421 018

--B101080148 Act receipt of IE Insp Repts B0-269/B0-32, B0-270/B0-28 & B0-287/B0-25 on B00902-30 No proprietary info corrective actions Tech Specs reviewed, personnel training reviewed & ltr issued to station manager
PARKER, W O Duke Power Co B0/11/26 3pp 07421 019

--B101080155 Forwards IE Insp Repts B0-269/B0-32, B0-270/B0-28 & B0-287/B0-25 on B00902-30 & notice of violation.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/11/03 2pp 07421 022

--B101080161 Notice of violation from insp on B00902-30.
e Region 2, Atlanta, Office of the Director B0/11/03 1p 07421 024

--B101080177 IE Insp Repts B0-269/B0-32, B0-270/B0-28 & B0-287/B0-25 on B00902-30 Noncompliance noted failure to comply w/ Tech Spec requirement for processing major procedure change
JAFEE, F J ORDERS, W J WERS, P Region 2, Atlanta, Office of the Director B0/11/03 7pp 07421 025

B101150136 Supplis B00918 ltr re mod to reactor bldg spray sys for facilities Mod to be installed during next available forced outage of sufficient duration or next refueling outage.
PARKER, W O Duke Power Co B0/12/12 1p 07462 191

B101060225 Forwards IE Info Notice B0-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown" No written response required
B'REILLY, J P Region 2, Atlanta, Office of the Director B0/12/16 1p

B101160258 Responds to IE Bulletin B0-23 re Velcor Engineering Corp solenoid valve failures Will will replace all Velcor solenoid valves w/ ASCO solenoid valves as such as received.
PARKER, W O Duke Power Co B0/12/29 1p 07470 258

B101200575 Forwards response to IE Bulletin B0-24 re prevention of damage due to water leakage inside containment Tech Specs & station directives ensure reporting of abnormal degradation of primary containment
PARKER, W O Duke Power Co B1/01/06 11pp 07477 240

B101210213 Forwards supplemental response to IE Bulletin B0-06, "Engineered Safety Feature (ESF) Reset Controls." Heds completed on high pressure injection pumps, penetration room exhaust fans, reactor bldg cooling unit fan & Keweenaw start
PARKER, W O Duke Power Co B1/01/07 13pp 07488 017

B101190385 Forwards request for relief from ASME Code Section XI interservice insp requirements re main feedwater sys check valves Approval requested by B10114
PARKER, W O Duke Power Co 01/01/13 5pp 07475 332

R. Periodic operating reports & related correspondence

B101210462 Forwards monthly operating repts for Dec 1980.
PARKER, W O Duke Power Co B1/01/15 1p 07493 170

--B101210464 Monthly operating repts for Dec 1980.
REAVIN, J A Duke Power Co B1/01/15 16pp 07493 171

S. Reportable occurrences, LERs & related correspondence

B101300576 Forwards LER B0-021/03L-0
PARKER, W O Duke Power Co B1/01/09 1p 07582 345

--B101300578 LER B0-021/03L-0 on B01210, relay in start circuitry for TDEFH auxiliary oil pump shorted tripping dc breaker Caused by AR-15 relay coil shorting Relay replaced
JONES, J L Duke Power Co B1/01/09 2pp 07502 346

B101270640 Forwards LER B0-026/03L-0
PARKER, W O Duke Power Co B1/01/20 2pp 07548 345

--B101270680 LER B0-026/03L-0 on B01219, concentrated sulfuric acid tank pump declared inoperable because of failure to pump to isolation storage tank Caused by air in hydraulic reservoir & low oil level Oil added & station mod submitted.
JONES, J L Duke Power Co 01/01/20 1p 07548 347

DJCKE1 B0-271 VERMONT YANKEE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FBAR
EISENHUT, D O Division of Licensing B0/11/13 2pp

B101100558 Ltr to all power reactor licensees w/ plants licensed prior to 750101 Forwards revised Section 10CFR20.48 & App R re fire protection features in nuclear power plants & summary list of requirements for resolution of open issues.
EISENHUT, D O Division of Licensing B0/11/24 8pp 07448 222

G. Adjudicatory correspondence

B101070402 Joins VT Yankee Decommissioning Alliance request for full investigation of safety & mgmt of facility. Results of investigation should be publicly available.
BRUCH, C M Affiliation Unknown 00/12/23 1p 07415 299

B101210652 Forwards Director's decision under 10CFR2.206, in response to ltr
STELLD, V Director's Office, Office of Inspection and Enforcement B1/01/08 3pp 07107 001

--B101210655 Forwards Director's decision under 10CFR2.206, denying request for facility shutdown pending public hearings & investigation
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B1/01/08 3pp 07187 001

--B101210658 Forwards Director's decision under 10CFR2.206, denying request for facility shutdown pending public hearings & investigation.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B0/12/30 2pp 07187 001

--B101210660 Forwards Director's decision under 10CFR2.206, in response to ltr
STELLD, V Director's Office, Office of Inspection and Enforcement B1/01/08 1p 07187 001

--B101210661 Forwards Director's decision under 10CFR2.206, in response to ltr
STELLD, V Director's Office, Office of Inspection and Enforcement B1/01/08 1p 07187 001

--B101210663 Forwards Director's decision under 10CFR2.206, in response to City of Holland, VT ltr.
STELLD, V Director's Office, Office of Inspection and Enforcement B1/01/08 1p 07187 001

--B101210665 Forwards Director's decision under 10CFR2.206, in response to Ad Hoc Citizens Group for Safety at VT Yankee ltr.
STELLD, V Director's Office, Office of Inspection and Enforcement B1/01/08 1p 07308 001

--B101210668 Urges shutdown of facility, pending public investigation of safety & mgmt
HILSON, R Affiliation Unknown B1/01/08 1p 07308 001

--B101210669 Notice of issuance of Director's decision under 10CFR2 206. denying VT Yankee Decommissioning Alliance 001127 request for facility shutdown pending public investigation into operation & safety
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 80/12/29 2pp 07308 001

--B101210671 Director's decision under 10CFR2 206. denying VT Yankee Decommissioning Alliance 001127 request for facility shutdown pending public investigation into operation & safety
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 00/12/29 30pp. 07308 001

B101300402 Forwards NRC B10113 order granting extension to exemption from General Design Criterion 50 & requiring licensee to reassess containment design for suppression pool hydrodynamic loading
IPPOLITO, T A Operating Reactors Branch 2 81/01/13 4pp 07586 244

--B101300411 Order granting extension to exemption from General Design Criterion 50 & requiring licensee to reassess containment design for suppression pool hydrodynamic loading.
EISENHUT, O O Division of Licensing 81/01/13 7pp 07586 248.

B101220014 Order granting extension until B10206 for Commission to decide whether to review Director's decision re Callan & Richardson petition Certificate of Bwr encl
CHILK, S J Office of the Secretary of the Commission 81/01/16 2pp 07501 339

H. General Correspondence

B101070366 Demands full & public investigation into safety & mgt of facility Expresses concern re cracked pipes, worker burnout, stress corrosion, hidden costs & operation w/o water discharge permit.
CAFFERTY, J. Affiliation Unknown 80/12/28 2pp 07309 001

B101140884 Requests investigation & public hearing re repairs, damage & weaknesses at facility
KIEHNOLZ, J. Affiliation Unknown. 81/01/04 1p 07308 001

B101140897 Requests investigation re facility safety & mgt.
CHEVAN, J C Affiliation Unknown 01/01/06 2pp 07308 001

B101140906 Expresses concern over safety of facility & requests public investigation into safety & mgt.
WAIT, E. Affiliation Unknown. 81/01/09. 1p 07453 261.

B101200208 Urges close look at potential problems at facility.
CARLETON, M Affiliation Unknown 81/01/13 1p 07187 001

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except BEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under 81B License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, O. O. Division of Licensing. 80/11/20. 1p.

--B101100271 Revised Pages 3/4 7-22 through 20.8 3/4 7-3 & 7-6 & 6-17 to 81B snubber inservice insp requirements
* Division of Licensing 80/11/20. 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, O. O. Division of Licensing 80/11/26 8pp.

B101030474 Notifies that until B00912 proposed Tech Specs for TMI Lessons Learned Category A items are unacceptable. Tech Specs should contain limiting conditions for operation & actions for primary backup position indicators.
IPPOLITO, T. A. Operating Reactors Branch 2 80/12/01. 3pp. 07390. 049.

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR scram discharge sys. Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes.
EISENHUT, O. O. Division of Licensing. 80/12/09 2pp.

--B101100194 IE Insp Rept 50-271/80-10 on 003/05-0808 No noncompliance noted Major areas inspected logs, records, tours, safety sys operational verification & operational event followup portions withheld (ref 10CFR2 7901)
RAYMOND, W J, COLLINS, S J, FOLEY, T Region 1, Philadelphia, Office of the Director 80/10/07 34pp 07438 054

B101070414 Forwards Suppl 1 to IE Info Notice 80-29. "Broken Stud Terry Inhibine Steam Inlet Flange " No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 053

B101300493 Forwards IE Insp Rept 50-271/80-16 on B00929-1003.14-1. 27-31 No noncompliance noted
CARLETON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/03 2pp 07444 251

--B101100503 IE Insp Rept 50-271/80-16 on B00929-1003.14-17 & 27-31 noncompliance noted Major areas inspected inservice insp program & implementation of testing & exam requirements for refueling outage
SAMOEB, W F, MCBREARY, R A Region 1, Philadelphia, Office of the Director TRIPPL, E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/02 9pp 07444 293

B101300092 Revises 000502 response to IE Bulletin 80-17, Suppl 3. "Failure of 76 of 105 Control Rods to Fully Insert During Scram at BWR " Addl plant mode changed indications available to control room operator
EISEN, L H Vermont Yankee Nuclear Power Corp 80/12/03 2pp 07379 332

B101030134 Forwards IE Info Notice 80-43. "Failures of Continuous Level Monitor for Scram Discharge Vol at Dreedon Unit 2 " No response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07376 335

B101140913 Responds to IE Bulletin 80-23. "Failures of Solenoid Valve by Valcor Engineering Corp " Valves w/specifed parts not in use at facility
CONWAY, W F Vermont Yankee Nuclear Power Corp 80/12/11. 1p 07458 352

B101160621 Ack receipt of B01113 ltr informing NRC of steps taken correct violations noted in IE Insp Rept 50-271/80-11. Item 7 remains an item of noncompliance
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/12/11 1p 07472 010.

--B101160627 Responds to NRC B01029 ltr re violations noted in IE Rept 50-271/80-11 Conclusions supporting denial of noncompliance of Item 7 withheld (ref 10CFR2 7901).
CONWAY, W. F. Vermont Yankee Nuclear Power Corp 80/11/13 2p 07472 011

--B101160633 Ack receipt of B01003 ltr informing NRC of steps taken correct violations noted in IE Insp Rept 50-271/80-11 Responses to Item 7 not acceptable Details withheld (ref 10CFR2 7901).
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 00/10/20 2pp 07472 013

--B101160640 Responds to NRC B00909 ltr re violations noted in IE Rept 50-271/80-11. Encl withheld (ref 10CFR2 7901).
CONWAY, W F Vermont Yankee Nuclear Power Corp 80/10/03 1p 07472 015

--B101160646 Forwards IE Insp Rept 50-271/80-11 on B00728-31 & OGB Notice of violation withheld (ref 10CFR2 7901)
ORIER, B H Region 1, Philadelphia, Office of the Director 80/07/09 2pp 07472 016

--B101160653 IE Insp Rept 50-271/80-11 on B00728-31 & OGB Noncompliance noted communications device not tested at required frequency & members of security force not qualified. Details withheld (ref 10CFR2 7901).
SHEPHERD, R E Region 1, Philadelphia, Office of the Director. DEVLIN, J W Region 1, Philadelphia, Safeguards Branch. 80/01/20 2pp. 07472 018.

B101060144 Forwards IE Info Notice 80-49. "Potential Failure of Backup Manual Scram Capability." No response required
ORIER, B H Region 1, Philadelphia, Office of the Director. 80/12/17. 1p 07391 262.

B101070060 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of 76 Control Rods to Fully Insert During Scram at BWR." No written response required.
ORIER, B H Region 1, Philadelphia, Office of the Director. 80/12/18. 1p 07414 150

B101210445 Forwards responses to questions on Rule 50 71a. "Periodic Updating of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D G Division of Licensing 80/12/15 13pp

B101100712 Forwards Amend 61 to License DPR-28, safety evaluation & notice of issuance & availability
IPPOLITO, T A Operating Reactors Branch 2 80/12/18 3pp
07443 195

B101100717 Amend 61 to License DPR-28, incorporating limited operating conditions associated w/Cycle 8 operation
IPPOLITO, T A Operating Reactors Branch 2 80/12/18 21pp
07443 198

B101100727 Safety evaluation supporting Amend 61 to License DPR-28
Office of Nuclear Reactor Regulation Director 80/12/18 4pp
07443 219

B101100731 Notice of issuance & availability of Amend 61 to License DPR-28
IPPOLITO, T A Operating Reactors Branch 2 80/12/18 2pp
07443 223

B101030169 Forwards addl info in response to NRC 850818 questions re adequacy of station electric distribution sys voltages
Includes analysis for unit auxiliary transformer source & analysis w/only one startup transformer available
SMITH, R L Vermont Yankee Nuclear Power Corp 80/12/29 22pp
07377 279

B101210236 Forwards NRC positions re util 77071B, 791206 & 800702 ltrs re degraded grid voltage. Licensees must submit test Specs requiring that diesel generator operate for at least 5 minutes while loaded w/emergency load
IPPOLITO, T A Operating Reactors Branch 2 80/12/29 4pp
07187 331

B101060389 Response to NUREG-0737, Item 11.K 3 (3 Reactor core isolation cooling trip/throttle valve trip) on High Water Level & requires manual resetting at turbine before restart.
Limiting motor operator will be added for automatic reset.
CONWAY, W F Vermont Yankee Nuclear Power Corp 80/12/30 2pp
07397 358

B101060366 Response to NUREG-0737, Item 1 C. 1 re guidance for evaluation & development of procedures for transients & accidents. Util has participated in BWR owners group program to develop emergency guidelines. Provides description of substate.
SMITH, R L Vermont Yankee Nuclear Power Corp 80/12/31 3pp
07393 357

B101080391 Forwards YAE-1234, "Methods for Analysis of BWRs Steady-State Core Flow Distribution Code (FIDWR)." describing Reload B safety evaluation methods
SMITH, R L Vermont Yankee Nuclear Power Corp 80/12/31 1p
07420 315

B101080403 "Methods for Analysis of BWRs Steady-State Core Flow Distribution Code (FIDWR)"
ANSARI, A F., SLIFER, B C., TURNAGE, J C Yankee Atomic Electric Co YAE-1234 80/12/31 118pp 07420 083

B101080430 Forwards YAE-1232, "Methods for Analysis of BWRs Lattice Physics" Rept describes methods to be used in safety evaluation of Reload B
SMITH, R L Vermont Yankee Nuclear Power Corp 80/12/31 1p
07420 201

B101080443 "Methods for Analysis of BWRs Lattice Physics"
PILAT, E E., CACCIAPOLI, R., TURNAGE, J C Yankee Atomic Electric Co YAE-1232 80/12/31 108pp 07420 282

B101090006 Forwards YAE-1235, "Methods for Analysis of BWRs Transient Thermal Margin Analysis Code (TMAYUD4-YAEC)." describing methods which will be used to perform safety evaluation of Reload B
SMITH, R L Vermont Yankee Nuclear Power Corp 80/12/31 1p
07441 200

B101090009 "Methods for Analysis of BWRs Transient Thermal Margin Analysis Code (TMAYUD4-YAEC)"
BURNS, K J., SLIFER, B C., TURNAGE, J C Yankee Atomic Electric Co YAE-1235 80/12/30 25pp 07441 201

B101090939 Tech Spec Table 3.2.6 for post-accident ins Tech Spec 6.10 for integrity of sys outside containment
Vermont Yankee Nuclear Power Corp 01/01/05 3p

B101160147 Submits info re proposed schedule for remaining Results of piping analysis will be available by mid-1983. Earliest commitment date for completing required mods be 1983 refueling outage, tentatively scheduled for April 1984.
HEIDER, L H Vermont Yankee Nuclear Power Corp 01/01/07472 087

B101160379 Forwards response to documentation requirements NUREG-0737, Item 11 D 3.4 re control room habitability info will be submitted per schedule in util 801215 ltr
SMITH, R L Vermont Yankee Nuclear Power Corp 81/01/07470 085

B101200249 Forwards info detailing exceptions taken to requirements transmitted in NRC 801031 ltr
BROCK, R H Vermont Yankee Nuclear Power Corp 81/01/07486 229

B101300402 Forwards NRC B10113 order granting extension from General Design Criterion 50 & requiring licensee reassess containment design for suppression pool hydrodynamic loading
IPPOLITO, T A Operating Reactors Branch 2 81/01/13 07586 244

B101300411 Order granting extension to exemption from Criterion 50 & requiring licensee to reassess containment design for suppression pool hydrodynamic loading.
EISENHUT, D G Division of Licensing 81/01/13 7p

B101210264 Forwards errata sheets to be included w/ "Methods of BWRs Transient Thermal Margin Analysis Code (TMAYUD4-YAEC)" submitted 801231
SMITH, R L Vermont Yankee Nuclear Power Corp 81/01/07487 106

B101210367 Errata sheets of matl to be added to "Methods of BWRs Transient Thermal Margin Analysis Code (TMAYUD4-YAEC)" submitted 801231
BURNS, K J., SLIFER, B C., TURNAGE, J C Yankee Atomic Electric Co YAE-1235 ERR 81/01/14 2pp 07487 187

B101200388 Clarifies 000520 response to NRC 800312 request for info re bypass & reset of engineered safety features manual override feature for safety actuation signal due to inadvertent bypass of any other actuation signal
SMITH, R L Vermont Yankee Nuclear Power Corp 81/01/07187 001

B101270692 Forwards supplemental info in support of reactor vessel temp/pressure limitation curves. Addl describes development of curves
SMITH, R L Vermont Yankee Nuclear Power Corp 81/01/07183 001

B101270746 Forwards revision to util 800919 proposed last program
SMITH, R L Vermont Yankee Nuclear Power Corp 81/01/07545 292

B101300315 Submits results of evaluation of BWR screen design in response to NRC 801001 request. Bys mode sho implemented, including installation of two independent instrument vls & addl coolant boundary valves.
HEIDER, L H Vermont Yankee Nuclear Power Corp 81/01/07586 329

B101300487 Submits proposal to install Class IE protection end of next refueling outage, as required in NRC 80092
HEIDER, L H Vermont Yankee Nuclear Power Corp 81/01/07587 028

G Inspection reports, IE Bulletins & correspondence

B101100183 Forwards IE Insp Rpt 80-271/80-10 on 800703 noncompliance noted
BRUNNER, E J, Region 1, Philadelphia, Reactor Operation Support Branch 80/10/15 2pp 07438 032

B101140707 Updates B02919 response to IE Bulletin 00-17, Suppl 1.
"Failure of 76 of 185 Control Rods to Fully Insert During
Scram at BWR." in response to NRC request for more detailed
info re installed level monitoring sys Diagrams encl
CONWAY, W F Vermont Yankee Nuclear Power Corp 80/12/18. 4pp
07461 306

B101130391 Forwards IE Bulletin 80-25. "Operating Problems W/Target
Rod Safety-Relief Valves at BWRs " Written response
required
ORIER, B H Region 1, Philadelphia, Office of the Director.
80/12/19 1p 07449 149

B101160054 Ack receipt of B01114 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-271/80-12.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/12/19 1p 07469-281

--B101160065 Responds to NRC B01023 ltr re violations noted in IE Insp
Rept 50-271/80-12 Corrective actions weld data sheet & valve
packing list rewritten from other job associated
documentation
CONWAY, W F Vermont Yankee Nuclear Power Corp 80/11/14 5pp
07469 282

--B101160072 Forwards IE Insp Rept 50-271/80-12 on 800812-15 & notice of
violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/10/23 2pp 07469 287

--B101160077 Notice of violation from Insp on 800812-15
* Region 1, Philadelphia, Office of the Director 80/10/14 3pp
07469 289

--B101160087 IE Insp Rept 50-271/80-12 on 800812-15 Noncompliance noted.
Failure to update valve lineup procedures to include newly
installed instrument air valves
BLUMBERG, N J, RAYMOND, W, COLLINS, B Region 1, Philadelphia,
Office of the Director. 80/10/14 10pp 07469-292.

R Periodic operating reports & related correspondence

B101210500 Forwards monthly operating rept for Dec 1980
CONWAY, W F Vermont Yankee Nuclear Power Corp 81/01/14 1p
07490 177

--B101210505 Monthly operating rept for Dec 1980
BERNARD, D Vermont Yankee Nuclear Power Corp. 81/01/13 11pp
07490: 178.

B Reportable occurrences, LERs & related correspondence

B101050425 Forwards LER 80-040/03L-0
MURPHY, W P. Vermont Yankee Nuclear Power Corp 80/12/24 1p.
07390 128

--B101050433 LER 80-040/03L-0 on B01130, discovered continuous environ air
samples at sample station A12 2 not being drawn. Caused by
main fuse blowing out Entire station replaced & electrical
surge suppressor installed.
MURPHY, W P Vermont Yankee Nuclear Power Corp 80/12/24 1p.
07390: 129

B101090224 PNO-1-80-181 on B01229, while conducting surveillance for
leakage, two through-wall cracks were found in 3-ft straight
section of 4-inch cleanup sys piping Cleanup sys isolated &
power held at 25% pending repair.
GREENMAN, E., BRUNNER, E J Region 1, Philadelphia, Office of the
Director 80/12/30 2pp 07442 270

B101080247 Forwards LER 81-001/01P-0
MURPHY, W P Vermont Yankee Nuclear Power Corp 81/01/02. 1p
07419 345

--B101080252 LER 81-001/01P-0 on B10101, MSIVs 808 & 85A closing time
exceeded Tech Spec limit of 5-s & relay 9A-K3F failed to
de-energize Cause under investigation
MURPHY, W P. Vermont Yankee Nuclear Power Corp 81/01/02 2pp.
07419 346

B101150661 Forwards LER 80-042/03L-0
MURPHY, W P. Vermont Yankee Nuclear Power Corp. 81/01/12 1p.
07463 289

--B101150685 LER 80-042/03L-0 on B01211, control rod block was not
received as required per Tech Spec Caused by arm on GE
limit switch Model CW-1154 working loose & being bent by
platform arm straightened & tightened
MURPHY, W P Vermont Yankee Nuclear Power Corp 81/01/12 1p
07463 290

B101220459 Forwards LER 80-043/03L-0
MURPHY, W P Vermont Yankee Nuclear Power Corp 81/01/16 1p
07505 202

--B101220462 LER 80-043/03L-0 on B01220, reactor core isolation cool
valve 13 had seat leakage of 1.531 lbr/hr, exceeding Tech
Specs No cause noted Valve seating surfaces lepped & valve
retested
MURPHY, W P Vermont Yankee Nuclear Power Corp 81/01/16 1p
07533 203

V Operator Examinations

B101060416 Responds to HR Denton 771030 ltr & NUREG-0737, Item 1 A
util established program to hire & extensively train group
of engineers Hiring & some training completed w/estimated
completion date remaining B10601
CONWAY, W F Vermont Yankee Nuclear Power Corp 80/12/30 3pp
07399 023

BUCKET 50-272 SALEM NUCLEAR DEGENERATING STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B101070387 Ltr to all licensees of operating reactor plants, CP hold
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FBAR
EISENHUT, O O Division of Licensing 80/11/13 2pp

B101070551 Releases public version of util revised emergency plan
FELTON, J M Division of Rules and Records 80/11/14 1p
07309 001

--B101070557 Forwards public version of util B00930 revisions to
emergency plan
L13R1221, F P Public Service Electric & Gas Co. of New Jersey
80/10/03 2pp 07309 001

--B101070562 Public version of revisions to emergency plan
* Public Service Electric & Gas Co of New Jersey 80/09/30
48pp 07309 001

B101130165 Advises of provisions of 10CFR50, App R, that are applica
to fire protection features of Facility FR notice & summary
of staff requirements to resolve open items encl No open
items for Facility W/O encl
EISENHUT, O O Division of Licensing 00/11/24 3pp 07456 303

B101070533 Releases public version of revision to util emergency p
FELTON, J M Division of Rules and Records 80/12/17 1p
07404 147

--B101070540 Forwards public version of revision to emergency plan
response to NRC request for addl info
L13R1221, F P Public Service Electric & Gas Co. of New Jersey
80/12/05 1p 07404 149

--B101070543 Public version of revision to emergency plan.
* Public Service Electric & Gas Co of New Jersey 80/12/05
2pp 07404 154

B101290198 Forwards questions re guard training & qualification pl
Requests response within 30 days Questions & comments
withheld (ref 10CFR2 790)
VARDA, S A Operating Reactors Branch 1 01/01/03 2pp 07573

B101200642 Releases public version of util revised emergency plan
FELTON, J M Division of Rules and Records 81/01/06 1p
07187 001

--B101200644 Forwards public version of revised sections of emerge
ncy plan, in response to NRC request for addl info
UDER172, R A Public Service Electric & Gas Co of New Jersey
80/12/17 1p 07187: 001

--B101200645 Public version of revised sections of emergency plan
* Public Service Electric & Gas Co of New Jersey 80/12/19
130pp. 07187 001

B010270616 Requests revised ltr from NRC re-evaluating B00712 evacuation study. Lack of coordination of various NRC divs w/respect to reviewing or issuing ltr of emergency preparedness appears evident.
WDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey
B1/01/21 1p 07517 067

G. Adjudicatory correspondence

B01100690 Forwards revised order for red of license, correcting refs in B00829 order. Hearing date also revised.
EISENHUT, D. G. Division of Licensing 80/07/19 2pp. 07443:173

--B01100693 Revised order amending License DPR-70 info requested by IE Bulletin 79-012 must be submitted to IE by B01101
EISENHUT, D. G. Division of Licensing 80/09/19 6pp 07443:175

B01070410 Requests to make limited appearance statement at licensing hearing.
NOTERMAN, J. P. Affiliation Unknown 80/12/27 1p 07309:001

B01020577 Findings of fact & conclusions of law in support of B01111 exceptions to ASL3 B01027 initial decision re applicant proposed expansion of fuel storage. Certificate of Svc encl
COLEMAN, A. C., COLEMAN, E. G. Affiliation Unknown. B1/01/13 26pp 07167 001

B010230647 Order accepting intervenors AC & EG Coleman's late brief. Time for filing remaining briefs shall be computed from B01013 Certificate of Svc encl
WENHOP, C. J. Atomic Safety and Licensing Appeal Panel B1/01/19 4pp 07512:290

J. Insurance & indemnity information

B010270735 Forwards Endorsement 5 to MELIA Binder ES-60
CORREA, M. A. Marsh & McLennan, Inc., M & H Nuclear Consultants, Inc. Div B1/01/22 2pp 07548 053

B010270738 Forwards Endorsement 12 to MELIA Policy NF-230 & Endorsement 34 to MAELU Policy NF-90
CORREA, M. A. Marsh & McLennan, Inc., M & H Nuclear Consultants, Inc. Div B1/01/22 3pp 07548:050

P. Operating license stage documents & correspondence

B01100690 Forwards revised order for red of license, correcting refs in B00829 order. Hearing date also revised.
EISENHUT, D. G. Division of Licensing. 80/07/19. 2pp 07443:173

--B01100693 Revised order amending License DPR-70 info requested by IE Bulletin 79-012 must be submitted to IE by B01101
EISENHUT, D. G. Division of Licensing 80/07/19 6pp 07443:175

B01040294 Releases public version of emergency plan manual implementation procedures for facilities
FELSON, J. M. Division of Rules and Records 80/11/14. 1p. 07421 095

--B01060299 Forwards public version of emergency plan manual implementation procedures for facilities
LIPRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey. 80/10/03 2pp. 07421 076.

--B01080305 Public version of emergency plan manual implementation procedures. Revision 12
STILLMAN, J. E. Public Service Electric & Gas Co. of New Jersey. 80/08/18 170pp. 07421 098.

B01100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS License amend application. Adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D. G. Division of Licensing 80/11/20. 1p

--B01100271 Revised Pages 3/4 7-22 through 39:8 3/4 7-3 & 7-6 & 6-17 to STS snubber inservice insp requirements.
* Division of Licensing 80/11/20 10pp

B01220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lowellier Yearling on Component Supports"
EISENHUT, D. G. Division of Licensing. 80/11/26. 8pp

B01100351 Forwards Amend 28 to License DPR-70, safety notice of issuance & availability
VARQA, S. A. Operating Reactors Branch 1 80/12/09

--B01100557 Amend 28 to License DPR-70, revising Tech voltage for individual battery cells, water level in reactor cavity during spent fuel movement & administrative actions
VARQA, S. A. Operating Reactors Branch 1 80/12/09 07440 348

--B01100567 Safety evaluation supporting Amend 28 to * Operating Reactors Branch 1 80/12/09 4pp

--B01100572 Notice of issuance & availability of Amend DPR-70
VARQA, S. A. Operating Reactors Branch 1. 80/12/09 07441 005

B01080104 Requests change in fee determination for ep organizational changes to indicate whether fee is Class II or Class I
B0058, R. M. License Fee Management Branch 80/12/11 07420 347

--B01080114 Forwards ltrs to four licensees requesting for organizational changes. Since facility request similar, requests consideration whether preliminary determination of Class II fee is correct.
B0058, R. M. License Fee Management Branch 80/11/11 07420 348

B01120022 Forwards Amend 29 to License DPR-70, safety notice of issuance & availability
VARQA, S. A. Operating Reactors Branch 1 80/12/11

--B01120024 Amend 29 to License DPR-70, modifying 5-yr data for sodium hydroxide flow check from spray add through sample line near flow ductors.
VARQA, S. A. Operating Reactors Branch 1 80/12/11 07446 247

--B01120026 Safety evaluation supporting Amend 29 to * Office of Nuclear Reactor Regulation, Director 07446:253

--B01120030 Notice of issuance & availability of Amend DPR-70
VARQA, S. A. Operating Reactors Branch 1 80/12/11 07446:256.

B01210415 Forwards responses to questions on Rule 50. Updating of FSARs" & FR notice of final rule BEP plan not comply w/rule until program is complete. Non-BEP must comply within specified time frame.
EISENHUT, D. G. Division of Licensing 80/12/15. 1p

B01050083 Clarifies inability to comply w/Tech Spec Amend 27, Margin of safety available from charging & injection pumps shown Operation w/tested flow of 10 below Tech Spec does not compromise safety limits
WDERITZ, R. A. Public Service Electric & Gas Co. of 80/12/19 3pp. 07376 231

B01200634 Forwards AEC 680409 ltr. in response to request hearing for Facility License initiated 790619 w/NRC.
ROSS, W. J. Operating Reactors Branch 1 80/12/22.

--B01200636 Forwards request for addl info needed to CP application. Includes info re adequacy of QC & procedures, site selection analysis, instrumentation info in FSAR & accident analysis
MORRIS, P. A. Atomic Energy Commission, Directorate 68/04/09 19pp. 07476:282.

B01300427 Forwards Amend 30 to License DPR-70, safety notice of issuance & availability
VARQA, S. A. Operating Reactors Branch 1. 80/12/22.

--B01300433 Amend 30 to License DPR-70, revising Tech flux difference target band.
VARQA, S. A. Operating Reactors Branch 1. 80/12/22 07583 244.

--B01300437 Safety evaluation supporting Amend 30 to * Office of Nuclear Reactor Regulation, Director 07583:254.

--0101300442 Notice of issuance & availability of Amend 30 to License
OPR-70
VAROA, B. A. Operating Reactors Branch 1 80/12/22 2pp
07503 256

0101190794 Forwards summary of 001210 meeting w/uttl re uttl mgt
reorganization List of attendees encl
CARLBOM, R. T. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 00/12/23 3pp 07473 078

0101160481 Submits info re installation of high density spent fuel
tacks Evaluation of specific functions in installation
process revealed 6 7 man ren occupational exposure
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey.
80/12/31 2pp 07472 137

0101270825 Forwards Amend 31 to license OPR-70, safety evaluation &
notice of issuance & availability
VAROA, B. A. Operating Reactors Branch 1 01/01/06 2pp 07549 098

--0101270831 Amend 31 to License OPR-70, revising App A Tech Specs to
reflect changes in organization that operates & supports
operation of Units 1 & 2
VAROA, B. A. Operating Reactors Branch 1 81/01/06 17pp
07549 100

--0101270036 Safety evaluation supporting Amend 31 to License OPR-70
* Office of Nuclear Reactor Regulation, Director 81/01/06 4pp
07549 116

--0101270042 Notice of issuance & availability of Amend 31 to License
OPR-70
VAROA, B. A. Operating Reactors Branch 1 81/01/06 2pp
07549 120

0101150382 Forwards logic diagrams & electrical schematics, per NRC
01208 request. Logic Diagram 239957-0-9646 will be revised
to reflect design mod scheduled for completion during
next refueling outage. Aperture cards in POR.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey
81/01/09 1p. 07462 203

0. Inspection reports, IE Bulletins & correspondence

0101090847 Ack receipt of 001017 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-272/80-19 &
50-311/80-14
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 00/11/07 1p 03093 224

--0101090052 Responds to NRC 000929 ltr re violations noted in IE Insp
Repts 50-272/80-19 & 50-311/80-14 Corrective actions, "hold"
erect established for rejected items & reject tags will be
attached to deficient items
SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey.
80/10/17 3pp. 03893 229

--0101090858 Forwards IE Insp Repts 50-272/80-19 & 50-311/80-14 on
800728-0808 & notice of violation
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 00/09/29 2pp 03893 230

--0101090863 Notice of violation from Insp on 000720-0808
* Region 1, Philadelphia, Office of the Director 80/09/29 2pp
03893 232

--0101090888 IE Insp Repts 50-272/80-19 & 50-311/80-14 on 800720-0808.
Noncompliance noted. Failure to follow procedures for
receipt, handling & storage of safety-related matl.
NAPUDA, O., SIMONETTI, O. Region 1, Philadelphia, Office of the
Director, GREENMAN, E. O. Region 1, Philadelphia, Reactor
Operations Nuclear Support Branch 80/09/29 14pp. 03893 234

0101060039 Responds to uttl 801104 ltr revising response to IE Bulletin
80-11, "Masonry Wall Design" & requesting extension until
801203 to complete detailed analysis of masonry walls at
facilities. Extension is acceptable
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/11/19 1p. 07392 214

0101140118 Forwards IE Insp Rept 50-272/80-29 on 801105-06 No
noncompliance noted.
CARLBOM, R. T. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/11/20 2pp 07460 321

--0101140128 IE Insp Rept 50-272/80-29 on 801105-06 No noncompliance
noted. Major areas inspected components associated w/
component cooling water sys & reactor coolant pump re IE
Bulletin 79-010
PAOLINO, R. J. Region 1, Philadelphia, Office of the Director.
EDNETER, S. D. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/11/20 4pp 07460 323

0101070418 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs
Terry Turbine Steam Inlet Flange - No written response
required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/11/26 1p 07414 047

0101100768 Responds to IE Bulletin 80-23, "Failures of Solenoid Val-
ves by Valcor Engineering Corp." No sub valves used in
safety-related function at facilities
SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey
80/12/12 1p 07443 359

0101060016 Forwards IE Info Notice 00-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown" No written
response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/16 1p 07397 045

R. Periodic operating reports & related correspondence

0101210475 Forwards monthly operating rept for Dec 1980
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
81/01/12 1p 07187 001

--0101210482 Monthly operating rept for Dec 1980
MILLER, L. W. Public Service Electric & Gas Co. of New Jersey.
81/01/12 40pp 07187 001

S. Reportable occurrences, LERs & related correspondence

0101200504 LER 80-066/01X-1 on 801201, review per IE Bulletin 00-11
showed eight masonry wall areas not erected per design
Analysis underway.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
80/12/01 2pp 07300 001

0101280479 LER 00-063/01P-0 on 001204, observed that auxiliary feed
pumps may be tripped from Unit 1 or 2 control console if
steam generator low-low level condition exists Cause under
investigation.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
80/12/09 2pp. 07308 001

0101230350 Summary of 801205 meeting w/uttl re seismic design
deficiencies of masonry walls in recently constructed Bldg A
(control Facility) & adjoining walkway.
RBSB, W. J. Operating Reactors Branch 1 00/12/30 3pp 07512

0101090643 Forwards LER 80-066/03L-0
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey.
81/01/02 2pp 07442 103

--0101090651 LER 80-066/03L-0 on 801126, surveillance requirements
fire detection instruments not performed Caused by personnel
error Entry placed in night order log to emphasize
importance of completing surveillance tests.
BEELE, W. J. Public Service Electric & Gas Co. of New Jersey.
81/01/02 2pp. 07442 105

0101090658 Forwards LER 00-062/03L-0
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey
81/01/02 2pp 07442 023

--0101090707 LER 80-062/03L-0 on 001204, during refueling outage, 10
rate of 15 containment isolation valves exceeded Tech Spec
limits Caused by inadequate test equipment Valves cleaned
& internals replaced.
BEELE, W. J. Public Service Electric & Gas Co. of New Jersey.
81/01/02 1p 07442 025

0101120320 Forwards LER 80-064/03L-0
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey
81/01/06 3pp 07447 140

--0101120324 LER 80-064/03L-0 on 801207, Tech Spec flow rate not ob-
served for spray additive tank or sodium hydroxide solution. Caused
by difference between startup procedure & surveillance
procedure. Tech Specs changed
BEELE, W. J. Public Service Electric & Gas Co. of New Jersey
81/01/06 1p 07447 143

--B01120376 LER 80-067/03L-0 on B01254 valve 115J139 found stuck open, constituting degradation of primary coolant pressure boundary. Caused not stated Valve tapped w/ratchet & successfully retested
STEELE, W J Public Service Electric & Gas Co of New Jersey
81/01/08 1p 07447 153

B01120357 Forwards LER 80-069/03L-0
UDER112.R A Public Service Electric & Gas Co of New Jersey
81/01/14 2pp 07477 346

--B01120359 LER 80-069/03L-0 on B01223 steam generator 13 channel 11 steam flow failed high. Caused by failure of multiplier/ divider unit. Magan Model 112 Unit replaced, calibrator & tested
STEELE, W J Public Service Electric & Gas Co of New Jersey
81/01/14 1p 07477 346

B01120386 Forwards LER 80-069/03L-0
UDER112.R A Public Service Electric & Gas Co of New Jersey
81/01/14 2pp 07477 335

--B01120391 LER 80-069/03L-3 on B01220 leak rate on 100-foot containment air lock exceeded Tech Spec limit. Caused by shearing of inner door seals to maintain pressure. Seals adjusted & tested.
STEELE, W J Public Service Electric & Gas Co of New Jersey
81/01/14 1p 07477 357

B011260552 Forwards LER 80-065/03L-0
UDER112.R A Public Service Electric & Gas Co of New Jersey
81/01/15 2pp 07531 147

--B011260642 LER 80-065/03L-0 on B01218 steam leak found in pipe tunnel, auxiliary bldg elevation 84 ft. Caused by shearing of pipe nipple connecting valve 10V378 w/vent line. Lockdown isolated & valve removed. Retaining pipe nipple capped off.
STEELE, W J Public Service Electric & Gas Co of New Jersey
81/01/15 1p 07531 149

B011260597 Forwards updated LER 80-009/03x-2
UDER112.R A Public Service Electric & Gas Co of New Jersey
81/01/15 2pp 07531 150

--B011260650 Updated LER 80-009/03x-2 on B00117 small leak found in telltale drain & in spent fuel pit. Caused by leaking welded seams. Half-round channels welded over leaking voids.
OSBORN, J C Public Service Electric & Gas Co of New Jersey
81/01/15 1p 07531 152

B011270491 LER 81-007/01T-0 on B01019 during verification of throttle valve position during lineups, it was observed that valves were not operated to verify position where locking devices installed & bench marks aligned. Corrective action taken.
MIDOURA, J Public Service Electric & Gas Co of New Jersey
81/01/20 2pp 07163 001

B011270561 Forwards updated LER 80-054/01x-1
UDER112.R A Public Service Electric & Gas Co of New Jersey
81/01/21 3pp 07546 316

--B011270569 Updated LER 80-034/01x-1 on 791016 fire pump diesel 1 destroyed by fire & on 1016 fire pump diesel 2 failed to start. Caused by loss of lubrication for pump 1 & faulty voltage regulator for pump 2.
STEELE, W J Public Service Electric & Gas Co of New Jersey
81/01/21 1p 07546 319

V Operator Examinations

B011070329 Forwards info requested in NUREG-0737 re shift technical advisor training program, performance testing of PWR relief & safety valves, containment min pressure setpoint & instrumentation for detection of inadequate core cooling.
MITTL, R L Public Service Electric & Gas Co of New Jersey
80/12/31 140pp 07369 001

B011130322 Provides addl info re training program to qualify degreed engineers as senior reactor operator license candidates. In response to NRC B01031 request. Successful licensing of candidates will minimize routine overtime. Related info encl.
SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey
81/01/06 30pp 07447 381

A Application/Construction stage documents & correspondence

B011220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports".
EISENHUT, D D Division of Licensing 80/11/26 8pp

B011130269 Recommends denial of D Fleischaker B01017 request that Commission issue supplemental EIS re environ consequences of Class 5 accident at Facility. No evidence presented to warrant reopening environ record.
OGLESBY, D A Pacific Gas & Electric Co 81/01/08 2pp 07431 275

B011210553 Forwards environ qualification of Class 1E control cable req by Continental Wire & Cable Co. Requests ack of receipt.
CRANE, P A Pacific Gas & Electric Co 81/01/16 11pp 07489 266

B011270672 Forwards addl info re QA program per NRC B01007 request info will be incorporated into FSAR.
CRANE, P A Pacific Gas & Electric Co 81/01/22 29pp 07549 193

B011260331 Forwards info addressing issues to be reviewed for full power operation, including operating procedures, control room design, preoperational & low power testing, auxiliary feedwater sys, containment design & radiation protection.
CRANE, P A Pacific Gas & Electric Co 81/01/26 106pp 07594 178

F Security, medical, emergency & fire protection plans

B011090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B01012 & by applicants as part of FSAR.
EISENHUT, D D Division of Licensing 80/11/13 2pp

B011060312 Requests evaluation of potential complicating factors caused by earthquakes which either initiate or follow initiation of accidents. Adequacy review of state & local capabilities re earthquakes requested of FEMA.
TEDESCO, R L Assistant Director for Licensing 80/12/16 5pp 07399 048

B011100849 Informs that licensees must conduct emergency exercises with one yr from B01001 or prior to issuance of OL. Requests schedule of drills & exercises.
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/12/19 1p 07442 298

B011130741 Requests that encl facility emergency planning info be made publicly available w/o encl.
SOUER, J L Division of Rules and Records 80/12/31 1p 07445 129

B011100852 Notifies of acceptance of B00711 guard training & qualification plan.
MIRAGLIA, F J Licensing Branch 3 81/01/01 3pp 07442 299

B011120301 Forwards comments re Revision 10 of physical security plan to be resolved prior to license issuance. Comments withheld.
INF 10CFR2 790
MIRAGLIA, F J Licensing Branch 3 81/01/01 5pp 07447 204

B011190696 Requests that encl facility emergency planning info be made publicly available w/o encl B012240129.
SOUER, J L Division of Rules and Records 81/01/09 1p 07472 323

B011190700 Requests that encl facility emergency planning info be made publicly available w/o encl B012290469.
SOUER, J L Division of Rules and Records 81/01/09 1p 07472 321

B011300722 Releases public version of util emergency plan response.
FRITON, J M Division of Rules and Records 81/01/26 1p 07584 159

--B011300728 Forwards public version of response to NRC B00826 request for addl info re site emergency plan, Revision 2 & B00830 request re field property.
CRANE, P A Pacific Gas & Electric Co 81/01/13 62pp 07584 160

--B011300739 Superior Court order granting land rights to util for implementation of emergency response plans.
KIRKPATRICK, R California, State of 80/10/14 3pp 07594 220

DOCKETED ITEMS

0 Adjudicatory correspondence

8101030382 Response to joint intervenors' contentions & CA Governor Brown statement on subs in which he intends to participate Opposes litigating contentions because record is closed & no grounds exist to reopen records
CRANE, P. A., OEHR, A C Pacific Gas & Electric Co OEHR, A C Snell & Wilmer 80/12/18 47pp 07385 099

--8101050380 Advises that FEMA/NRC Bleering Committee has determined that low power testing criteria are not needed Encl position is adequate.
ORIMES, B H Emergency Preparedness Program Office letter 801119 see 18E1 RYAN, R Office of State Programs, Director 80/12/18 2pp 07385.146

8101060018 Response to Joint Intervenor's request for directed certification Opposes request because record is closed on all issues & request raises no significant new evidence.
Certificate of Bvc encl
CRANE, P A., OEHR, A C Pacific Gas & Electric Co OEHR, A C Snell & Wilmer 80/12/18 37pp 07397 066

8101210136 Informs that technical divisions will provide testimony to refute CA Governor Brown 801203 Contentions 1, 2, 3 & 5 re fuel load/low power license
TEBERCO, R L Assistant Director for Licensing 80/12/31 1p 07489 361

8101090223 Request identified as proposed findings of fact that ABLB 790927 partial initial decision be affirmed. Decision concluded that 0.75 g acceleration was appropriate, reanalysis reasonable & Category I structures adequate
OLMSTEAD, W J, KETCHEN, E O Hearing Branch 4 81/01/06 88pp 07423 284

8101120459 Certifies svc of NRC proposed findings of fact & conclusions of law in reopened seismic proceedings & response to ABLB questions on 810106
KETCHEN, E O Hearing Branch 4 81/01/06 3pp 07447 169

8101140877 Requests that WE Martin, Battelle-Columbus Lab. be deleted from svc list.
SCHERB, E B Atomic Safety and Licensing Board Panel 81/01/08 1p 07458 218

8101140749 Joint intervenors' reply to applicant & NRC responses to statement of contentions. Objections undermined by recent NRC revision of 780620 statement of policy. Adopts Governor Brown contentions Certificate of Bvc encl.
REYNOLDS, J R, OLEISCHAKER, D Ben Luis Obispo Mothers for Peace REYNOLDS, J R Center for Law in the Public Interest 81/01/08 10pp 07458 227

8101140279 Response to ABLB 801217 order requesting continued deferment of Joint Intervenor's 790909 motion on Closes 9 issues
Emergency planning contentions must be admitted & ABLB decision on seismic matters issued Certificate of Bvc encl
OLMSTEAD, W J Hearing Branch 4 81/01/12 19pp 07458 124

8101140725 Forwards NRC Div of Licensing 810101 ltr to util re Revision 10 to security plan & NRC comments on revision.
Comments withheld (ref 10CFR2.790) w/o ltr.
SMARTZ, L L Office of the Executive Legal Director 81/01/12 1p 07458 262

8101160278 Supplement to reply to POBE & NRC responses to Joint Intervenor's statement of contentions On Page 3, Line 9, 17 should be deleted & on Line 14, 14, 18 & 20 deleted & 14, 15, 18, 19 & 24 inserted Certificate of Bvc encl
REYNOLDS, J R Ben Luis Obispo Mothers for Peace REYNOLDS, J R Center for Law in the Public Interest FLEISCHAKER, D Fleischaker, D 81/01/12 5pp 07470 279

8101260701 Response opposing Joint Intervenor's & CA Governor Brown 801213 proposed findings re 791015 Imperial Valley earthquake Certificate of Bvc encl
MORTON, B., FURBUSH, M H., OEHR, A C Pacific Gas & Electric Co 81/01/16 32pp 07523 348

8101270739 Brief discussing definition of "several" as used in 10CFR73.1(c)(1). Term "several" means up to & including three entities
SMARTZ, L L Antitrust Division OLMSTEAD, W J Hearing Branch 4 81/01/19 8pp 07183 001

8101280131 Order scheduling 810128 conference w/ABLB & parties' counsel to discuss BVA re matters discussed to 810128 conference

8101280620 Response to Joint Intervenor's 810108 reply to applicant & NRC responses to contentions Revised statement of policy.
CLI-80-42, did not change Commission position TH1-related contentions must be denied w/Certificate of Bvc
MORTON, B., FURBUSH, M H., OEHR, A C Pacific Gas & Electric Co 81/01/23 13pp 07557 292

11 General correspondence

8101280446 Urges rejection of facility license in light of TH1 incident
ABJINBDN, T Affiliation Unknown 79/04/04 1p 07447 089

8101090372 Responds to 790404 postcard re facility NRC has reacted positively to improve safety of all nuclear power plants in operation & under const Response to concern re proximity of Magr3 fault in facility encl
MIRAGLIA, F Licensing Branch 3 80/12/11 3pp 07429 268

8101060030 Responds to 790414 ltr expressing concerns re facility safety Low level radioactivity effects, storage of high level radwaste & ability to withstand severe earthquake pose insignificant level of danger to public
MIRAGLIA, F J Licensing Branch 3 80/12/16 6pp 07399 151

8101090731 Responds to Apr 1979 ltr to President Carter expressing concern re nuclear power safety NRC currently requires all applicants for new OLS to modify design & operation of nuclear plants to conform to TH1-related requirements
MIRAGLIA, F J Licensing Branch 3 80/12/16 6pp 07309 001

8101120002 Responds to 790402 ltr NRC is presently conducting generic proceeding to reassess degree of confidence in disposal methods to determine disposal availability & to provide storage.
MIRAGLIA, F J Licensing Branch 3 80/12/16 4pp 07447 109

8101120191 Responds to 801208 ltr ABLB considering application for OL authorizing fuel loading & low power testing of Unit 1 ABLB reviewing portions of ABLB "Partial Initial Decision" re seismic matters & applicant physical security plan.
INGRAM, F L Office of Public Affairs 80/12/16 1p 07309 001

--8101120196 Requests info re status of facility & names of decisionmakers
GANNIB, B Affiliation Unknown 80/12/08 1p 07309 001

8101190128 Ack receipt of 801214 ltr expressing concern re opening of facilities Ltr will be placed in appropriate public docket file
MANCHETT, J O Region 5, San Francisco, Office of the Director 81/01/02 1p 07475 323

--8101190161 Expresses concern re opening of facilities
HAYZ, M Affiliation Unknown 80/12/14 1p 07475 324

8101190286 Ack receipt of 801227 ltr expressing concern re opening of facilities Ltr will be placed in appropriate public docket file
MANCHETT, J O Region 5, San Francisco, Office of the Director 81/01/02 1p 07476 089

--8101190777 Expresses concern re opening of facilities.
BERRIGAN, S Affiliation Unknown 80/12/27 1p 07476 090

8101200209 Ack receipt of 801227 ltr expressing concern re opening of facilities Ltr will be placed in appropriate public docket file
MANCHETT, J O Region 5, San Francisco, Office of the Director 81/01/02 1p 07187 001

--8101200126 Expresses concern re opening of facility.
MCFERRON, B J Affiliation Unknown 80/12/27 1p 07187 001

0 Inspection reports, IE Bulletins & correspondence

8012290008 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys w/Loss of Offsite Power" Administrative Procedure MAP C-11 will be revised to incorporate Item 5 Related correspondence
CRANE, P A Pacific Gas & Electric Co 80/11/25 2pp 07344 201

8101060014 Responds to IE Bulletin 80-19 No CP Core Model 1102X-1011 mercury-wetted relays used in logic matrix at facility
CRANE, P A Pacific Gas & Electric Co 81/01/25 1p 07467 001

--6012160154 Quarterly Financial Rept Sept 1980 & support
1980s
+ General Public Utilities 80/11/14 44pp

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) re
Revision 1 of inservice surveillance requirements for
snubbers under STS License amend application adding mod.
Tech Specs to App A should be submitted within 120 days
ESENHUT.00 Division of Licensing 08/11/20 lp

--B101100271 Revised Pages 3/4 7-22 through 20, B 3/4 7-9
STB snubber inservice insp requirements
a Division of Licensing 80/11/20 1000

8101220466 Ltr to all power reactor licensees & applicant summary of 801112 meeting re implementation of guidance Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." EISENHUT.D 0 Division of Licensing. 80/11/26 Bpp

BIO190113 Ltr to all BWR licensees forwarding BIO1201 gen
evaluation re BWR steam discharge sys Recommends short-
actions necessary to assure safe operation of GE BWRs
pending permanent design changes
EISENHUT, D O Division of Licensing 00/12/09 2pp

--B101190141 Generic safety evaluation re short-term action
assure continued safe operation of operating OWRs. Continued
operation of plants is acceptable pending permanent design
basis Criteria for implementing design mode encl
* Division of Licensing 80/12/01 213pp 07183.00

0101210449 Forwards responses to questions on Rule 90 71a.
Updating of FBARs & FR notice of final rule. BEP plants
not comply w/rule until program is complete Non-BEP plants
must comply within specified time frame
E16ENHUT.O.O Division of Licensing 80/12/15. 13pp.

8101070466 Responds to util 801126 revised schedule for up
position indication sys (acoustic monitor) for Facility
Shutdown solely to upgrade sys is unnecessary Unit 2 mod
should be completed by 810630
RE10.R W Operating Reactors Branch 4 80/12/10 200

8101090003 Forwards response to 800507 request re outage d
length of outages for all ECCS for 750101-800901
DALTROFF,B.L. Philadelphia Electric Co. 01/01/03 26p
07309-001

8101130314 Forwards info re plant sys & equipment & engine
evaluating new design stds. in response to NUREG-0737
requests
OALTRGFE, S L Philadelphia Electric Co 01/01/08 53p
07452-011

B101120299 Forwards application to amend Licenses OPR-44 &
NEDC-24229-1, "Peach Bottom Atomic Power Station Units 2
Single Loop Operation"
BRADLEY, E J Philadelphia Electric Co B1/01/09 ip.

--B10120304 Application to amend License OPR-44 & DPR-56
single loop operation beyond 24-h, provided specified
adjustments are implemented Certificate of Bvc & affid
ent.
BAUER, E. J. BRADLEY, E. J. Philadelphia Electric Co. O
6pp 07446 061

--B101120308 Proposed changes to Tech Specs to permit single
operation beyond 24-h
* Philadelphia Electric Co B1/01/09, 20pp, 07446

-B101120309 "Peach Bottom Atomic Power Station Units 2 &
Operation -
MERIKSON, P H General Electric Co. NED8-24229-1 00
33pp 07446-087

B101230474 Application for amend of License DPR-44 changin
Table 3 2 A to temporarily suspend trip level setting
prescribed for main steam line tunnel exhaust duct high
for five minutes
COOPER, K J. Philadelphia Electric Co. 01/01/19 In

810127072B Submits implemented changes called for by NUREG
Feedwater Nozzle & Control Rod Drive Return Line Nozzle
Cracking." Implementation program includes aug mod, feedw
nozzles operating procedures, insp & leak testing.
GALLAGHER, J W Philadelphia Electric Co 81/01/21 5p
0754B 066

tion reports. IE Bulletins & correspondence

Ack receipt of B01105 ltr informing NRC of steps taken to violations noted in IE Insp Repts 50-277/80-28 & 50-20
E J Region 1, Philadelphia, Reactor Operations Nuclear
Branch 80/11/13 1p 07431 329

211 Responds to NRC B01016 ltr re violations noted in IE Insp
50-277/80-28 & 50-278/80-20 Corrective actions: drywell
& reinspected & reactor startup checklist revised
withheld (ref 10CFR2 7901)
OFF, B L. Philadelphia Electric Co 80/11/05 3pp
326

218 Forwards IE Insp Repts 50-277/80-28 & 50-278/80-20 on
-31 & notice of violation
R, E J Region 1, Philadelphia, Reactor Operations Nuclear
Branch 80/10/16 3pp 07431 329

224 Notice of violation from insp on B00801-31
Region 1, Philadelphia, Office of the Director 80/10/08 3pp
332

232 Notice of violation from insp on B00801-31 Details withheld
10CFR2 7901
Region 1, Philadelphia, Office of the Director 80/10/08 1p
334

244 IE Insp Repts 50-277/80-28 & 50-278/80-20 on B00801-31
noncompliance noted Failure to follow housekeeping
procedures, failure to positively control designated vehicle
& submittal of LERs Portions withheld (ref 10CFR2 7901)
H. A. R. COWILL, C. J. RHOADS, O. O. Region 1, Philadelphia,
Office of the Director 80/10/09 15pp 07431 335

246 Forwards IE Insp Repts 50-277/80-31 & 50-278/80-23 on
1002-03 & 04 No noncompliance noted
E J Region 1, Philadelphia, Reactor Operations Nuclear
Branch 80/11/21 2pp 07500 178

546 IE Insp Repts 50-277/80-31 & 50-278/80-21 on B00930, 1002-03
No noncompliance noted Major areas inspected OA
Implementation including auditing, design & changes/

A. Q. Region 1, Philadelphia, Office of the Director
MAN, E. O. Region 1, Philadelphia, Reactor Operations Nuclear
Branch 80/11/20 11pp 07500 180

3 Forwards Suppl 1 to IE Info Notice 00-29, "Broken Studs on
turbine Steam Inlet Flange " No written response
d

4. M. Region 1, Philadelphia, Office of the Director.
6 1p 07414 030

9 Forwards IE Info Notice 80-43, "Failures of Continuous Water
monitor for BWR Discharge Vol at Dresden Unit 2 " No
e required
M. Region 1, Philadelphia, Office of the Director
5 1p 07377 245

5 Responds to IE Bulletin 80-23, "Failures of Bolts and Valves
Velcor Engineering Corp." Valves w/Parts V70900-21-1
00-21-3 are not in use in safety-related functions et
1pp
F. B. L. Philadelphia Electric Co. 80/12/10 2pp 07443 360

6 Forwards IE Info Notice 80-40, "Potential Failure of BWR
Manual BWR Capability." No response required.
M. Region 1, Philadelphia, Office of the Director
7. 1p. 07397:351.

6 Ack receipt of B01204 ltr informing NRC of steps taken to
violations noted in IE Insp Repts 50-277/80-08 &
80-07.
E J Region 1, Philadelphia, Reactor Operations Nuclear
Branch 00/12/17 1p 07502 120.

1135 Supplements response to Items A & B contained in IE Insp
50-277/80-08 & 50-278/80-07. All site personnel will
"Special Nuclear Plant Rules" for ready ref to improve
pliance.
OFF, B L. Philadelphia Electric Co 80/12/04 1p
121.

141 Ack receipt of B01119 ltr informing NRC of steps taken to
violations noted in IE Insp Repts 50-277/80-08 &
80-07
R, E J Region 1, Philadelphia, Reactor Operations Nuclear
Branch 80/12/16 1p. 07502 122.

--B01220149 Responds to NRC B01028 ltr re violations noted in IE Insp
Repts 50-277/80-08 & 50-278/80-07 Corrective actions fixed
damaged seal & reactor work permit area identification
mechanisms re located for greater access
DALTROFF, B L. Philadelphia Electric Co 80/12/04. 4pp
07502 123

--B01220153 Forwards IE Insp Repts 50-277/80-08 & 50-278/80-07 on
B00401-30 & notice of violation. Items of Noncompliance A & B
are recurring violations
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/10/28 3pp 07502 127

--B01220161 Notice of violation from insp on B00401-30
e Region 1, Philadelphia, Office of the Director 80/10/27. 2pp
07502 139

--B01220167 IE Insp Repts 50-277/80-08 & 50-278/80-07 on B00401-30
Noncompliance noted Failure to maintain fire retardant seal
on electrical cable penetration & failure to follow reactor
work permit requirements
CONOLIK, C J. BLOUGH, A R Region 1, Philadelphia, Office of the
Director GREENHAM, E D Region 1, Philadelphia, Reactor
Operations Nuclear Support Branch 80/10/27 11pp 07502 132

B01070069 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 185
Control Rods to Fully Insert During BWR " No
written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/10 1p 07414 144

B01130095 Forwards IE Bulletin 00-29, "Operating Problems w/Target
Roch Safety-Relief Valves at BWRs " Written response
required
GRIER, O H Region 1, Philadelphia, Office of the Director
80/12/19 1p 07449 134

B01150867 Ack receipt of B01119 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-277/80-29 &
50-278/80-21
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 00/12/23 1p. 07464 317

--B01150873 Responds to NRC B01030 ltr re violations noted in IE Insp
Repts 50-277/80-29 & 50-278/80-21 Corrective actions
employees instructed in correct procedure for maintaining
secondary containment App B withheld (ref 10CFR2 7901)
DALTROFF, O L. Philadelphia Electric Co 80/11/19. 3pp
07464 338.

--B01150880 Forwards IE Insp Repts 50-277/80-29 & 50-278/80-21 on
B00901-30 & notices of violation. App A & B App B withheld
(ref 10CFR2 7901)
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/10/30. 4pp 07464 341

--B01150887 Notices of violation from insp on B00901-30, App A, App B
withheld (ref 10CFR2 7901)
e Region 1, Philadelphia, Office of the Director 80/10/29 2pp
07464 343

--B01150891 IE Insp Repts 50-277/80-29 & 50-278/80-21 on B00901-30
Noncompliance noted Failure to maintain secondary
containment & failure to follow escort procedures Details
withheld (ref 10CFR2 7901)
HECADE, E C. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch. BLOUGH, A R, COWILL, C J Region 1, Philadelphia
Office of the Director 80/10/29 15pp 07464 345

B01060785 Addl response to FOIA request for documents re experimental
use of ODW NS-1 solvent at Dresden 1 & Peach Bottom Forwards
CE rept. "Radiation Level Assessment of Dresden 1
Decontamination Pilot Loop - Final Rept."
FELTOM, J M Division of Rules and Records. 00/12/29. 1p
07480 104

R Periodic operating reports & related correspondence

B010210522 Forwards monthly operating repts for Dec 1980
COONEY, M J. Philadelphia Electric Co 81/01/09. 1p 07490 210.

--B010210528 Monthly operating repts for Dec 1980
ALDEN, W M. Philadelphia Electric Co 81/01/10 10pp 07490 211

... and related correspondence

... reactor water cleanup
... temp setpoint exceeded Tech Spec
... Manual Model 25100-2 temp
... Control & related to sv
... 8/12/22 1p 07399 014

... pressure switch PS 2-2-1345
... This device caused by
... pressure switch
... 8/12/22 1p 07399 015

... cooling subcritical reactor
... exceeded Tech Spec
... reactor temp
... thermal regulation
... 8/12/30 3pp 07309 001

... A 6-49 pump room coolers failed
... adjustment of set
... 8/12/31 1p

... at 100% power during surveillance
... flow indication
... flow square root
... 8/13/05 2pp 07309 001

... 8/21/12 2pp 07501 126

... 8/1/12 1p 07501 128

... 8/1/13 2pp 07501 123

... 8/1/13 1p 07501 125

... 8/1/14 3pp 07309 001

... 8/1/16 1p 07183 001

... 8/1/16 1p 07309 001

... 8/1/19 2pp 07309 001

... 8/1/19 1p 07399 001

... 8/12/17 2pp 07445 311

... 8/12/18 2pp 07445 311

... 8/12/18 2pp 07445 311

DCCKET 50-27B PEACH BOTTOM ATOMIC POWER STATION, UNIT 3
F Security, medical, emergency & fire protection plans

8/10/90387 Ltr to all licensees of operating reactor plant & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 8/10/2 & by applicants as part of FSAR
EISENHUT.D.O. Division of Licensing 80/11/13 2pp.

8/10/90449 Notices of Commission approval of oncl inter suspending previously approved completion dates for FI protection mode Specific schedules for mode will be effective pending publication of final rule
EISENHUT.D.O. Division of Licensing 80/11/10 3pp.

8/10/230326 Releases public version of util emergency plan FELTON, J.M. Division of Rules and Records 8/10/15 07513 307

--8/10/230330 Forwards public version of emergency plan 1 PA dicotter operations plan Annex E & York, Lancaster Chester Counties, PA emergency plans
DALTRUFF, S.L. Philadelphia Electric Co 8/10/02 07513 309

--8/10/230338 Public version of emergency plan includes 8 disaster operations plan Annex E & York, Lancaster & Counties, PA emergency plans
Philadelphia Electric Co 80/12/31 600pp 07513 309

I Financial Information

8/10/2160144 Forwards SEC Form 10-Q, Quarterly Financial Report comments in response to NRC 790721.1109 & 800811 requests for info re significant financial developments affecting utility in retest proceeding
CHADON, V.H. General Public Utilities 80/11/26 3pp.

--8/10/2160154 Quarterly Financial Rept Sept 1980 & support comments
General Public Utilities 80/11/14 44pp

P Operating license stage documents & correspondence

8/10/100254 Ltr to all licensees (except BEP licensees) for Revision 1 of inservice surveillance requirements for scrubbers under 81B License amend application adding mod Tech Specs to App A should be submitted within 120 days
EISENHUT.D.O. Division of Licensing 80/11/20 1p.

--8/10/100271 Revised Pages 3/4 7-22 through 20, B 3/4 7-5 81B scrubber inservice insp requirements
Division of Licensing 80/11/20 10pp

8/10/120466 Ltr to all power reactor licensees & applicant summary of 8/11/2 meeting re implementation of guidance Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT.D.O. Division of Licensing 80/11/26 8pp

8/10/190113 Ltr to all BWR licensees forwarding 8/1201 gen evaluation re BWR screen discharge sys. Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes
EISENHUT.D.O. Division of Licensing 80/12/09 2pp.

--8/10/190141 Generic safety evaluation re short-term actions assure continued safe operation of operating BWRs Con operation of plants is acceptable pending permanent design Criteria for implementing design mod oncl.
Division of Licensing 80/12/01 212pp. 07183 001

8/10/210445 Forwards responses to questions on Rule 50.71a. Updating of FSARs & FR notice of final rule. BEP plants not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame
EISENHUT.D.O. Division of Licensing 80/12/15 13pp.

8/10/1070466 Responds to util 801126 revised schedule for up position indication sys (acoustic monitors) for facility Shutdown solely to upgrade sys is unnecessary. Unit 2 mod should be completed by 8/10/30
REID, R.W. Operating Reactors Branch 4 80/12/18 2pp

8101090303 Forwards response to 800507 request re outage dates & length of outages for all ECCS for 790101-800901
DALTROFF, S L Philadelphia Electric Co 81/01/05 26pp
07309 001

8101130314 Forwards info re plant sys & equipment & engineering studies evaluating new design stds. in response to NUREG-0737 requests
DALTROFF, S L Philadelphia Electric Co 81/01/08 53pp.
07452 011.

8101120297 Forwards application to amend Licenses DPR-44 & DPR-56 & NECB-24229-1, "Peach Bottom Atomic Power Station Units 2 & 3 Single Loop Operation"
BRAOLEY, E J Philadelphia Electric Co 81/01/09 1p 07446 060

--8101120304 Application to amend Licenses DPR-44 & DPR-56, permitting single loop operation beyond 24-h, provided specified adjustments are implemented Certificate of Svc & affidavit encl.
BAUER, E O., BRADLEY, E J Philadelphia Electric Co 81/01/09 6pp 07446 061

--8101120308 Proposed changes to Tech Specs to permit single loop operation beyond 24-h
* Philadelphia Electric Co 81/01/09 20pp 07446 067

--8101120309 "Peach Bottom Atomic Power Station Units 2 & 3 Single Loop Operation"
HERIKSON, P H General Electric Co. NECB-24229-1. 80/05/31 13pp 07446 087

8101270720 Submits implemented changes called for by NUREG-0619, "BWR Feedwater Nozzle and Control Rod Drive Return Line Nozzle Cracking." Implementation program includes sys mod, feedwater nozzle, operating procedures, insp & leak testing
GALLAGHER, J W Philadelphia Electric Co 81/01/21 5pp
07540 066

Q Inspection reports, IE Bulletins & correspondence

8101100204 Ack receipt of 801109 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-28 & 50-278/80-20
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/13 1p 07431 323

--8101100211 Responds to NRC 801016 ltr re violations noted in IE Insp Repts 50-277/80-28 & 50-278/80-20 Corrective actions drilled, cleaned & reinspected & reactor startup checklist revised. App B withheld (ref 10CFR2 7901)
DALTROFF, S L Philadelphia Electric Co 80/11/03 3pp.
07431 326.

--8101100218 Forwards IE Insp Repts 50-277/80-28 & 50-278/80-20 on 800801-31 & notice of violation.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/16 3pp 07431 324

--8101100224 Notice of violation from Insp on 800801-31
* Region 1, Philadelphia, Office of the Director. 80/10/00 2pp
07431 333

--8101100232 Notice of violation from Insp on 800801-31 Details withheld (ref 10CFR2 7901)
* Region 1, Philadelphia, Office of the Director 80/10/08 1p
07431 334

--8101100244 IE Insp Repts 50-277/80-28 & 50-278/80-20 on 800801-31 Noncompliance noted failure to follow housekeeping procedures, failure to positively control designated vehicle & late submittal of LERs. Portions withheld (ref 10CFR2 7901)
BLOUGH, A R, COWILL, C J, RICHARDS, O O Region 1, Philadelphia, Office of the Director 80/10/08 19pp 07431 335

8101220540 Forwards IE Insp Repts 50-277/80-31 & 50-278/80-23 on 800930, 1002-03 & 06 No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/21. 2pp 07500 178.

--8101220546 IE Insp Repts 50-277/80-31 & 50-278/80-23 on 800930, 1002-03 & 06 No noncompliance noted. Major areas inspected: QA program implementation including auditing, design & changes/mods.
NAPUOA, O Region 1, Philadelphia, Office of the Director
GREENMAN, E Q Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/20. 11pp. 07500 180

8101100512 Forwards IE Insp Rept 50-278/80-25 on 801029 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/25 2pp 07444 273

--8101100524 IE Insp Rept 50-278/80-25 on 801029 No noncompliance noted. Major areas inspected: motor operated & air operated valves of HPCI sys re IE Bulletin 79-018
PAOLINO, R J Region 1, Philadelphia, Office of the Director.
EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/17 3pp 07444 275

8101070423 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs of Terry Turbine Steam Inlet Flange" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p. 07414 038

8101090149 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Val at Oresdon Unit 2" No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07377 245

8101100775 Responds to IE Bulletin 80-23, "Failures of Solenoid Valve Hfg by Valcor Engineering Corp" Valves w/Parts V70903-21-1 or V70900-21-3 are not in use in safety-related functions at facilities
DALTROFF, S L Philadelphia Electric Co 80/12/10 2pp 07443 3

8101060135 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability" No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p. 07397 331

8101220125 Ack receipt of 801204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-08 & 50-278/80-07
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/17 1p 07502 120

--8101220135 Supplemental response to items A & B contained in IE Insp Repts 50-277/80-08 & 50-278/80-07 All site personnel will keep "Special Nuclear Plant Rules" for ready ref to improve compliance
DALTROFF, S L Philadelphia Electric Co 80/12/04 1p
07502 121

--8101220141 Ack receipt of 801119 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-08 & 50-278/80-07
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/16 1p 07502 122

--8101220149 Responds to NRC 801028 ltr re violations noted in IE Insp Repts 50-277/80-08 & 50-278/80-07 Corrective actions filed, damaged seal & reactor work permit area identification mechanisms re located for greater access.
DALTROFF, S L Philadelphia Electric Co 80/12/04 4pp
07502 123

--8101220153 Forwards IE Insp Repts 50-277/80-08 & 50-278/80-07 on 800401-30 & notice of violation items of Noncompliance A & D are recurring violations
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/28 3pp 07502 127

--8101220161 Notice of violation from Insp on 800401-30.
* Region 1, Philadelphia, Office of the Director 80/10/27 1p
07502 130

--8101220169 IE Insp Repts 50-277/80-08 & 50-278/80-07 on 800401-30 Noncompliance noted failure to maintain fire retardant seal on electrical cable penetration & failure to follow reactor work permit requirements.
COWILL, C J, BLOUGH, A R Region 1, Philadelphia, Office of the Director. GREENMAN, E Q. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/27 11pp. 07502 132

8101070069 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of Control Rods to Fully Insert During Scram at BWR" No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/18 1p. 07414 144.

8101130095 Forwards IE Bulletin 80-25, "Operating Problems w/Target Rock Safety-Relief Valves at BWRs" Written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07419 154

8101190867 A/c receipt of 801119 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-277/80-29 & 80-278/80-21
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/23 1p 07464 337

--8101190873 Responds to NRC 801030 ltr re violations noted in IE Insp Repts 80-277/80-29 & 80-278/80-21 Corrective actions employee instructed in correct procedure for maintaining secondary containment App B withheld (ref 10CFR2 7901)
DALTROFF, S. L. Philadelphia Electric Co 80/11/19. 7pp 07464 338.

--8101190880 Forwards IE Insp Repts 80-277/80-29 & 80-278/80-21 on 800901-30 & notices of violation App A & B App B withheld (ref 10CFR2 7901)
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/30 App 07464 341

--8101190887 Notices of violation from Insp on 800901-30 App A App B withheld (ref 10CFR2 7901)
* Region 1, Philadelphia, Office of the Director 80/10/29 2pp 07464 343

--8101190891 IE Insp Repts 80-277/80-29 & 80-278/80-21 on 800901-30 Noncompliance noted failure to maintain secondary containment & failure to follow escort procedures Details withheld (ref 10CFR2 7901)
MCABE, E. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch BLOUGH, A. R. CONNELL, C. J. Region 1, Philadelphia, Office of the Director 80/10/29 15pp. 07464 345

8101140744 Suppls 791217 response to IE Bulletin 79-26, "Baron Loss From UMR Control Blades." Certain blades depleting faster than expected Projections indicate that eight of 185 blades will exceed 34% B-10 depletion prior to Mar 1981 outage
DALTROFF, S. L. Philadelphia Electric Co 80/12/24 2pp. 07461 300

8101060785 Addl response to FOIA request for documents re experimental use of DCW NB-1 solvent at Brecken 1 & Peach Bottom Forwards CE rept, "Radiation Level Assessment of Dresden 1 Recirculation Pilot Loop - Final Rept."
FELTON, J. M. Division of Rules and Records 80/12/29 1p.

R Periodic operating reports & related correspondence

8101210522 Forwards monthly operating repts for Dec 1980
COONEY, M. J. Philadelphia Electric Co. 81/01/09 1p 07490 210.

--8101210528 Monthly operating repts for Dec 1980
ALCEN, W. H. Philadelphia Electric Co 81/01/10 10pp 07490 211

S Reportable occurrences, LERs & related correspondence

8101280505 LER 80-028/OIP-0 on 801203, WPCI declared inoperable because of recurring problems w/M3-14 valve 2 valve operator Cause unknown Diagnostics underway to determine cause
ULRICHS, H. T. Philadelphia Electric Co 80/12/04 3pp. 07308 001.

8101140519 LER 80-029/O3L-0 on 801209, main steam line radiation monitor C indicated reduced background reading w/trip setpoint greater than Tech Spec Caused by instrument zero drift Monitor recalibr
COONEY, M. J. Philadelphia Electric Co 81/01/08. 1p. 07308 001

8101200266 LER 80-030/O3L-0 on 801214, backup nitrogen battle supply to Inboard containment isolation valve A3-3506 found valved out of svc. Pressure regulation adjustment screw missing Cause unknown Backup nitrogen supply restored
COONEY, M. J. Philadelphia Electric Co 81/01/13 1p 07487 014

8101220352 RO 81-031/1P on 801113 oil leak of 3-5 gpm discovered on oil supply line to turbine manual/overspeed trip mechanism on WPCI auxiliary oil pump Probably caused by leaking valve or fitting in oil supply line
ULRICHS, H. T. Philadelphia Electric Co 81/01/13 2pp 07309 001

8101220466 LER 81-031/O3L-0 on 801218, reactor core isolation cooling inboard steam supply isolation valve did not automatically close Caused by valve closing torque switch on type SM3 Limit torque operator for valve M33-13-13 being open
COONEY, M. J. Philadelphia Electric Co. 81/01/13. 1p. 07505 204

V Operator Examinations

8101330314 Forwards info re plant sys & equipment & engineering evaluating new design stds. in response to NUREG-0737 requests
DALTROFF, S. L. Philadelphia Electric Co 81/01/08 53pp

DOCKET 80-280 BERRY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8101330717 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open item encl.
EISENHUT, D. O. Division of Licensing 80/11/24 7pp 07454

8101070595 Releases public version of util emergency plan & Commonwealth of VA, Isle of Wight County radiological emergency response plan & York County draft radiological emergency response plan - peacetime
FELTON, J. M. Division of Rules and Records 80/12/01 1p 07405 005

--8101070602 Forwards public version of util emergency plan, inc Commonwealth of VA, Isle of Wight County radiological emergency response plan & York County draft radiological emergency response plan - peacetime
BAUM, E. A. Virginia Electric & Power Co 80/06/30 2pp. 07405 006

--8101070607 Public version of emergency plan
* Virginia Electric & Power Co 80/06/16 200pp 07405:

--8101070613 Public version of Commonwealth of VA, Isle of Wight County emergency operations plan, Annex V, "Radiological Emergency Response Plan." (Part of util plan)
* Isle of Wight County, VA 79/05/31. 50pp 07405 010

--8101070622 Public version of Commonwealth of VA, York County emergency operations plan, draft Annex V, Radiological Emergency Response Plan - Peacetime " (Part of util plan)
* York, PA 80/06/30 59pp. 07405 011

8101160599 Forwards Suppl 1 to 790919 fire protection safety evaluation, based on util 801029 & 31 ltrs. Mode re cable tray covers & fire barriers are not acceptable Review status encl
VARGA, S. A. Operating Reactors Branch 1 80/12/18 6pp 07

8101100729 Requests that encl facility emergency planning info publicly available w/o encl
BOUDER, J. L. Division of Rules and Records. 80/12/31. 1p. 07449: 127.

8101140467 Advises that response plan not acceptable in present Suppl as personnel & technical assistance to be provided by State Health Dept in most cases nonexistent.
HOLMES, M. B. Berry County, VA 80/12/31. 2pp. 07461: 277.

8101160493 Releases public version of util emergency plan.
FELTON, J. M. Division of Rules and Records. 81/01/08. 1p. 07466 032

--8101160503 Forwards public version of amended emergency plan facility list of changes & emergency personnel response times encl
BAUM, E. A. Virginia Electric & Power Co. 80/12/31. 4pp. 07466 034

--8101160511 Public version of amended emergency plan for facil
* Virginia Electric & Power Co. 81/01/02 500pp. 07466:

8101270249 Notification of 801119 meeting w/util in Bethesda, MD facility fire protection safe shutdown capability.
NEIGHBOR, D. Operating Reactors Branch 1 81/01/12. 2pp. 07546 019.

8101210618 Approves util 801222 request to be excluded from sub State of NC emergency plan as part of facility emergency plan.
VARGA, S. A. Operating Reactors Branch 1 81/01/13. 2pp 07

8101290169 Forwards facility emergency planning info to be made publicly available w/o encl.
BOUDER, J. L. Division of Rules and Records 81/01/23 1p 07578: 200.

G. Adjudicatory correspondence

B101100363 Forwards revised order for mod of license, correcting refs in 800829 order Hearing date also revised
EISENHUT, D O Division of Licensing 80/09/19 3pp 07442 002

--B101100574 Revised order amending Licenses DPR-37 & DPR-32 info requested by IE Bulletin 79-018 must be submitted to IE by 801101
EISENHUT, D O Division of Licensing 80/09/19 6pp 07442 000

B101100384 Requests extension of license mod hearing request from B10108 to B10216 Hearing may still be requested but until must review environ qualification matter before making final decision re necessity of hearing
CHRISTMAN, J N Hunton & Williams 01/01/07 3pp 07457 020

H. General correspondence

B101050488 Informs that appointment of J1 Gatte as senior vice president of power operations, effective 010101, approved on 801219 by VEPD Board of Directors Discusses until corporate organization Tech Specs being revised for facilities.
FERGUSON, J H Virginia Electric & Power Co 80/12/31 2pp 07385 268

J. Insurance & indemnity information

B101100357 Forwards Endorsements 2, 5, 4, 4, 24, 5B & 31 to NELA Policies EO-70, EB-63, EB-28, EO-27, NB-316, NF-186 & NF-248, respectively
HARRFIELD, K J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 81/01/09 16pp 07451 333

P. Operating license stage documents & correspondence

B101100563 Forwards revised order for mod of license, correcting refs in 800829 order Hearing date also revised.
EISENHUT, D O Division of Licensing 80/09/19 3pp 07442 002

--B101100574 Revised order amending Licenses DPR-37 & DPR-32 info requested by IE Bulletin 79-018 must be submitted to IE by 801101.
EISENHUT, D O Division of Licensing 80/09/19 6pp 07442 004

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under BfB License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing 80/11/28 1p

--B101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-9 & 7-6 & 6-17 to BTO snubber inservice insp requirements
• Division of Licensing 80/11/20 10pp

B101100246 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101078553 Notices of preliminary fee review of util B101028 proposed Tech Specs changes. Class IV fee is applicable for Unit 1 NRC is re-evaluating Class III fee re util 8008316 application.
OIGNS, R M License Fee Management Branch 00/12/08 1p 07484 356

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FBARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing 80/12/15 13pp

B101190384 Forwards Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability.
VARQA, S A Operating Reactors Branch 1 80/12/18 3pp 07463 240

--B101150394 Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively, requiring secondary water chemistry monitoring program to inhibit steam generator tube degradation.
VARQA, S A Operating Reactors Branch 1 80/12/18 4pp 07463 242

--B101150403 Notice of issuance & availability of Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively.
VARQA, S A Operating Reactors Branch 1 80/12/18 2pp 07463 244

B101100562 Forwards safety evaluation on susceptibility of safety-related sys to flooding from failure of non-Category 1 Sys
VARQA, S A Operating Reactors Branch 1 80/12/18 2pp 07471 3

--B101100567 Safety evaluation concluding that added protective measures satisfy guidelines for protection of safety-related sys from flooding due to failure of non-Category 1 Sys
• Office of Nuclear Reactor Regulation, Director 80/12/18 2 07471 302

--B101100690 "Technical Evaluation of Susceptibility of Safety-Related Sys to Flooding Caused by Failure of Non-Category 1 Sys for Burry Units 1 & 2"
LATORRE, V R, VICIOR, R A Lawrence Livermore Laboratory 80/12/31 19pp 07471 304

B101300454 Forwards Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability.
VARQA, S A Operating Reactors Branch 1 80/12/18 3pp 07583 2

--B101300463 Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively adding requirement to follow guard training & qualification plan per 10CFR73.95b within 60 days of Commission approval.
VARQA, S A Operating Reactors Branch 1 80/12/18 4pp 07583 296

--B101300473 Notice of issuance & availability of Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively.
VARQA, S A Operating Reactors Branch 1 80/12/18 2pp 07583 298

B101190399 Approves util 801118 request to postpone B10101 install of redundant safety grade reactor coolant sys pressure input to core subcooling monitors Sys will be installed in Unit 1 prior to startup & Unit 2 in May 1981
VARQA, S A Operating Reactors Branch 1 80/12/22 2pp 07476 0

B101190242 Forwards list of YLD station locations near Facility & proposed route for exchanging TLOs for NRC direct radiation monitoring network W/O encl.
BTDHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07475 297

B101060308 Forwards response to specified items of NUREG-0737 re shi technical advisor training program & ECCS outage rept of North Anna 1 & 2
SYLVIA, D R Virginia Electric & Power Co 80/12/31 37pp 07396 099

B101190483 Ack receipt of 801208 ltr re license amend application for Check for balance due on Class IV amend to Licenses DPR-32 & DPR-37 submitted
SYLVIA, D R Virginia Electric & Power Co 01/01/04 1p 07475 328

--B101190488 Ack receipt of ltr w/checks to be processed by License Mtg Branch
OIGNS, R M License Fee Management Branch 81/01/15 1p 07475 329

B101200229 Forwards revised VEP-FRD-36, designated VEP-FRD-36A, "Control Rod Reactivity Worth Determination by Rod Swap Technique," per NRC B01107 ltr
THOMAS, W N Virginia Electric & Power Co 81/01/16 2pp 07470 001

--B101200235 "Control Rod Reactivity Worth Determination by Rod Swap Technique"
ROBB, T K, DECK, W C, OHLING, M L Virginia Electric & Power Co VEP-FRD-36A 00/12/31 61pp 07478 003

B101220354 Forwards response to item 111 D 3 4 of NUREG-0737. Also forwards "Burry Units Toxic Chemical Release Analysis"
SYLVIA, D R Virginia Electric & Power Co 81/01/19 9pp 07500 296

--B101220357 "Burry Units Toxic Chemical Release Analysis."
TOTH, K J, JUZACH, R J, SCHMIDT, E R NUS Corp NUS-3735 V1 81/01/13 18pp 07500 303

B101300193 Expresses appreciation for B101203 meeting to discuss in-house licensing activities Physics analysis methodology for reload safety evaluations will be discussed at B10128 meeting
THOMAS, W N Virginia Electric & Power Co 81/01/26 1p 07583 207

D Inspection reports, IE Bulletins & correspondence

B010290301 Forwards IE Insp Repts 50-280/80-36 & 50-281/80-40 on B01020-23 No noncompliance noted
KENNA, W R Region 2, Atlanta, Safeguards Branch 80/12/12 2pp.
07575 104

--B010290386 IE Insp Repts 50-280/80-35 & 50-281/80-40 on B01020-23 No noncompliance noted Major areas inspected mail control & accounting
LIFE, T D, MCALPINE, E J Region 2, Atlanta, Safeguards Branch 80/12/08 3pp 07575 106

B010120120 Revises B01201 completion date for corrective actions for IE Bulletin 00-18 re maint of adequate min flow through centrifugal charging pumps Surry mode to be completed by B01205 & North Anna by B01203
SYLVIA, B R Virginia Electric & Power Co 80/12/22 1p
07446 121

B010120519 Provides estimated schedule for completing masonry wall re-evaluation program required by IE Bulletin 00-11
Completion dates for Class I & II walls are B01015 & 0415, respectively
SYLVIA, B R Virginia Electric & Power Co. 80/12/26 2pp.
07447 172

B010160694 Airt receipt of B01217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-39 & 50-281/80-43
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 81/01/05 1p 07472 030

--B010160696 Responds to ARC B01125 ltr re violations noted in IE Insp Repts 50-280/80-39 & 50-281/80-43 Corrective actions: maint completed on installed pumps & refueling procedure revised
SYLVIA, B R Virginia Electric & Power Co 80/12/17 3pp
07472 031

--B010160699 Forwards IE Insp Repts 50-280/80-39 & 50-281/80-43 on 000902-1003 & notice of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/11/25 2pp. 07472 034

--B010160700 Notice of violation from Insp on 800902-1003
* Region 2, Atlanta, Office of the Director. 80/11/25 1p
07472 036

--B010160706 IE Insp Repts 50-280/80-39 & 50-281/80-43 on 800902-1003
Noncompliance noted: failure to properly evaluate & document installation of jumper hose & failure to properly seal containment door
JURAE, D J Region 2, Atlanta, Office of the Director
KELLS, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/11/25 10pp 07472 037

B010290396 Forwards response to IE Bulletin 80-23, Prevention of Damage Due to Water Leakage Inside Containment Oct 17, 1980
Indian Point 2 Event "No leakage in closed sys at North Anna 1 & 2 Summary of leakage at Surry 1 & 2 encl
SYLVIA, B R Virginia Electric & Power Co. 81/01/05 9pp
07575 133

R Periodic operating reports & related correspondence

B010200293 Forwards monthly operating repts for Dec 1980.
SYLVIA, B R Virginia Electric & Power Co 81/01/14 1p
07477 180

--B010200297 Monthly operating repts for Dec 1980
OWEN, S O, CASTELLO, D J Virginia Electric & Power Co 81/01/08 46pp. 07477 181

B Reportable occurrences, LERs & related correspondence

B01050414 Forwards LER 00-072/03L-0
WILSON, J L Virginia Electric & Power Co 80/12/23 1p.
07390 118

--B01050423 LER 80-072/03L-0 on B01124, twenty-one improperly sealed fire barrier penetrations in safety-related areas discovered & fire watches not established within 1-h Caused by erroneous interpretation of requirements
* Virginia Electric & Power Co 80/12/23 3pp 07390 119

B01090641 Forwards LERs 80-047/03L-0 & 80-073/03L-0
WILSON, J L Virginia Electric & Power Co 81/01/03 1p.

--B01090682 LER 80-047/03L-0 on B01205, discrepancies discovered in documenting performance of periodic tests PT-24 5B, 18 4, 17 2 & 17 3 Caused by operations personnel oversight
Personnel retrained & improved mgt of periodic testing
WILSON, J L Virginia Electric & Power Co 81/01/05 3pp
07442 177

--B01090661 LER 80-073/03L-0 on B01205, discrepancies discovered in documenting performance of periodic tests PT-18 B & 19 1
Caused by operations personnel oversight Personnel retrained & improved PT mgt sys developed
* Virginia Electric & Power Co 81/01/05 3pp 07442 180

B010200379 Forwards LERs 80-050/03L-0 & 80-074/03L-0
WILSON, J L Virginia Electric & Power Co 81/01/15 1p
07477 234

--B010200343 LER 80-050/03L-0 on B01228, amp reading for circuit 13A injection recirculation to boric acid tank panel B was below acceptance criteria Caused by failure of heat tracing tape due to excessive heat Heat tracing design change initiated.
WILSON, J L Virginia Electric & Power Co 81/01/15 2pp.
07477 235

--B010200348 LER 80-074/03L-0 on B01218, power leads to MOV-106A & discovered to have been reversed Cause undetermined. Power leads returned to normal & valves tested
* Virginia Electric & Power Co 81/01/15 3pp 07477 237

B010200695 Forwards LER 80-075/03L-0
WILSON, J L Virginia Electric & Power Co 81/01/15 1p
07512 262

--B010200611 LER 80-075/03L-0 on B01223, RM-CC-105 & RM-CC-106 alarm setpoints found to be greater than twice background Caused by decrease in background radiation levels resulting from defueling Alarm setpoints reduced
* Virginia Electric & Power Co 81/01/16 2pp 07512 263

V Operator Examinations

B010200308 Forwards response to specified items of NURE0-0737 re technical advisor training program & ECCB outage rept of North Anna 1 & 2
SYLVIA, B R Virginia Electric & Power Co 80/12/31 37pp

FOCAET 50-281 SURRY POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of FBAR
EISENHART, D O, Division of Licensing 80/11/13 2pp

B01010717 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open item encl.
EISENHART, D O Division of Licensing 80/11/24 7pp 07454-041

B01070595 Releases public version of util emergency plan & Commonwealth of VA, Isle of Wight County radiological emergency response plan & York County draft radiological emergency response plan - peacetime.
FELTEN, J H Division of Rules and Records 80/12/01 1p
07405 005

--B01070602 Forwards public version of util emergency plan, including Commonwealth of VA, Isle of Wight County radiological emergency response plan & York County draft radiological emergency response plan - peacetime
BALME, E A Virginia Electric & Power Co 80/06/30 2pp
07405 006

--B01070607 Public version of emergency plan.
* Virginia Electric & Power Co 80/06/16 200pp. 07405 008

--B01070613 Public version of Commonwealth of VA, Isle of Wight County emergency operations plan, Annex V, "Radiological Emergency Response Plan." (Part of util plan)
* Isle of Wight County, VA 79/03/31 50pp. 07405-010.

--B01070624 Public version of Commonwealth of VA, York County emergency operations plan, draft Annex U, Radiological Emergency Response Plan - Peacetime (Part of util plan)
* York, PA 80/06/30 39pp. 07405-011

8101160599 Forwards Suppl 1 to 790919 Fire protection safety evaluation based on util 801029 & 71 ltr's. Mods re cable tray covers & fire barriers are not acceptable. Review status encl
VAROA, S A Operating Reactors Branch 1 80/12/18 6pp 07471 210

8101100729 Requests that encl facility emergency planning info be made publicly available w/o encl
SQUIDER, J L Division of Rules and Records 80/12/31 1p
07445 127

8101140467 Advises that response plan not acceptable in present form. Supplies, personnel & technical assistance to be provided by State Health Dept in most cases nonexistent
HOLMES, M S Surry County, VA 80/12/31 2pp 07461 277

8101160493 Releases public version of util emergency plan
FELTON, J H Division of Rules and Records 81/01/08 1p
07466 032

--8101160503 Forwards public version of amended emergency plan for facility. List of changes & emergency personnel response times encl
BAUM, E A Virginia Electric & Power Co 80/12/31 4pp
07466 034

--8101160511 Public version of amended emergency plan for facility
* Virginia Electric & Power Co. 81/01/02 500pp 07466 038

8101210618 Approves util 801222 request to be excluded from submitting State of NC emergency plan as part of facility emergency plan.
VAROA, S A Operating Reactors Branch 1 81/01/13 2pp 07489 238

8101270165 Forwards facility emergency planning info to be made publicly available w/o encl
SQUIDER, J L Division of Rules and Records 81/01/23 1p
07575 200

Q Adjudicatory correspondence

8101100563 Forwards revised order for mod of license, correcting refs in 800829 order. Hearing date also revised
EISENHUT, D G Division of Licensing 80/09/19 3pp

--8101100574 Revised order amending Licenses DPR-37 & DPR-32 info requested by IE Bulletin 79-01B must be submitted to IE by 801101
EISENHUT, D G Division of Licensing 80/09/19 6pp

8101130384 Requests extension of license mod hearing request from 810108 to 810216. Hearing may still be requested but util must review environ qualification matter before making final decision re necessity of hearing
CHRISTIAN, J N Hunton & Williams 81/01/07 3pp 07457 020

II General correspondence

8101030488 Informs that appointment of JI Datta as senior vice president of power operations, effective 810101, approved on 801219 by VEPD Board of Directors. Discusses util corporate organization Tech Specs being revised for facilities.
FERGUSON, J H Virginia Electric & Power Co 80/12/31 2pp
07383 268

J Insurance & indemnity information

8101130397 Forwards Endorsements 2, 5, 4, 4, 24, 5B & 31 to NELA Policies EB-70, EB-63, EB-28, EB-27, NS-316, NF-186 & NF-240, respectively
HAIRFIELD, K J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div. 81/01/09 16pp 07451 333

P Operating license stage documents & correspondence

8101100563 Forwards revised order for mod of license, correcting refs in 800829 order. Hearing date also revised
EISENHUT, D G Division of Licensing 80/09/19 3pp 07442 002

--8101100574 Revised order amending Licenses DPR-37 & DPR-32 info requested by IE Bulletin 79-01B must be submitted to IE by 801101
EISENHUT, D G Division of Licensing 80/09/19 6pp 07442 004

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under RB License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D G Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28, 8 3/4 7-5 & 7-6 & 6-BTS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 6pp

8101070553 Notifies of preliminary fee review of util 801028 proposed Tech Specs changes. Class IV fee is applicable for Unit 1 NRC so re-evaluating Class III fee re util 800316 application
DICKER, R H License Fee Management Branch 80/12/08 1p
07404 356

8101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame
EISENHUT, D G Division of Licensing 80/12/15 13pp

8101150784 Forwards Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability
VAROA, S A Operating Reactors Branch 1 80/12/18 3pp 07463

--8101150394 Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively requiring secondary water chemistry monitoring program to inhibit steam generator tube degradation
VAROA, S A Operating Reactors Branch 1 80/12/18 4pp
07463 242

--8101150403 Notice of issuance & availability of Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively
VAROA, S A Operating Reactors Branch 1 80/12/18 2pp
07463 244

8101160562 Forwards safety evaluation on susceptibility of safety-related sys to flooding from Failure of Non-Category 1 sys
VAROA, S A Operating Reactors Branch 1 80/12/18 2pp 07471

--8101160567 Safety evaluation concluding that added protective mea satisfy guidelines for protection of safety-related sys from flooding due to failure of non-Category 1 sys
* Office of Nuclear Reactor Regulation, Director 80/12/18
07471 302

--8101160590 "Technical Evaluation of Susceptibility of Safety-Related Sys to Flooding Caused by Failure of Non-Category 1 Sys for Bury Units 1 & 2"
LAWRENCE, V R, VICTOR, R A Lawrence Livermore Laboratory 80/12/31 19pp 07471 304

8101300454 Forwards Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability
VAROA, S A Operating Reactors Branch 1 80/12/18 3pp 07583

--8101300463 Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively adding requirement to follow guard training & qualification plan per 10CFR73.35b within 60 days of Commission approval
VAROA, S A Operating Reactors Branch 1 80/12/18 4pp
07583 296

--8101300473 Notice of issuance & availability of Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively
VAROA, S A Operating Reactors Branch 1 80/12/18 2pp
07583 298

8101190359 Approves util 801118 request to postpone 810101 install of redundant safety grade reactor coolant sys pressure input to core subcooling monitors. Sys will be installed in Unit 1 prior to startup & Unit 2 in May 1981
VAROA, S A Operating Reactors Branch 1 80/12/22 2pp 07476

8101190242 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encl
STONER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07475 297

North Anna 1 & 2
SYLVIA, B R Virginia Electric & Power Co 80/12/31 37pp
07396 099

LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Branch 80/11/29 2pp 07472 034

B101190483 Act receipt of B01208 ltr re license amend application fee
Check for balance due on Class IV Amend to Licenses OFR-32 &
DPR-37 submittals
SYLVIA, B R Virginia Electric & Power Co 81/01/09 1p
07475 328

--B101190488 Act receipt of ltr w/checks to be processed by License Fee
Mgt Branch
01055, R M License Fee Management Branch 81/01/15 1p
07475 329

B101200229 Forwards revised VEP-FRD-36, designated VEP-FRD-36A, Control
Rod Reactivity Worth Determination by Rod Sweep Technique, -
per NRC 801107 ltr
THOMAS, W M Virginia Electric & Power Co 81/01/16 2pp
07478 001

--B101200235 "Control Rod Reactivity Worth Determination by Rod Sweep
Technique"
ROSS, T A, BECK, W C, ROWLAND, M L Virginia Electric & Power Co
VEP-FRD-36A 80/12/31 4pp 07478 003

B101220354 Forwards response to item 111 D 3 4 of NUREG-0737 Also
forwards Surry Onsite Toxic Chemical Release Analysis, -
SYLVIA, B R Virginia Electric & Power Co 81/01/19 9pp
07500 296

--B101220357 "Surry Onsite Toxic Chemical Release Analysis"
TOTH, K J, JUDACH, R J, SCHMIDT, E R NUS Corp NUS-3739 V1
81/01/12 18pp, 07500 305

B101300173 Expresses appreciation for B01203 meeting to discuss
in-house licensing activities Physics analysis methodology
for reload safety evaluations will be discussed at B10128
meeting
THOMAS, W M Virginia Electric & Power Co 81/01/26 1p
07586 207

B Inspection reports, IE Bulletins & correspondence

B101290301 Forwards IE Insp Repts 50-280/80-36 & 50-281/80-40 on
B01020-23 No noncompliance noted
MERRA, W B Region 2, Atlanta, Safeguards Branch, 80/12/12 2pp,
07575 104

--B101290386 IE Insp Repts 50-280/80-36 & 50-281/80-40 on B01020-23 No
noncompliance noted Major areas inspected: mat'l control &
accounting
LEE, T D, MCALPINE, E J Region 2, Atlanta, Safeguards Branch
80/12/08 3pp 07575 106

B101120120 Revises B01201 completion date for corrective actions for
IE Bulletin 80-18 re maint of aqueous ammonia flow through
centrifugal charging pumps Surry rods to be completed by
B01209 & North Anna by B01203
SYLVIA, B R Virginia Electric & Power Co 80/12/22 1p,
07446 121

B101120519 Provides estimated schedule for completing masonry wall
re-evaluation program required by IE Bulletin 80-11.
Completion dates for Class 1 & 11 walls are B10315 & 0415,
respectively.
SYLVIA, B R Virginia Electric & Power Co 80/12/26 2pp
07447 172

B101190357 Responds to IE Bulletin 79-14 re seismic analysis for
safety-related piping sys Support mods installed by B01201
except on 3-inch line in containment bldg. Vendor
verification of valve weights incomplete
SYLVIA, B R Virginia Electric & Power Co 80/12/31 3pp
07474 046

B101160694 Act receipt of B01217 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-280/80-39 &
50-281/80-43
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 81/01/09 1p, 07472 030

--B101160696 Responds to NRC B01129 ltr re violations noted in IE Insp
Repts 50-280/80-39 & 50-281/80-43 Corrective actions: maint
completed on installed pumps & refueling procedure revised
SYLVIA, B R Virginia Electric & Power Co 80/12/17 3pp
07472 031

--B101160700 Notice of violation from Insp on B00902-1003
& Region 2, Atlanta, Office of the Director 80/11/2
07472 036

--B101160706 IE Insp Repts 50-280/80-39 & 50-281/80-43 on
Noncompliance noted: failure to properly evaluate & doc
installation of jumper hose & failure to properly seal
containment door
BURKE, D J Region 2, Atlanta, Office of the Director
KELLER, P J Region 2, Atlanta, Reactor Operations Nu
Branch 80/11/29 10pp 07472 037

B101290396 Forwards response to IE Bulletin 80-24, "Prevent
Damage Due to Water Leakage Inside Containment (Oct 17, 1
Indian Point 2 Event)" No leakage in closed sys at North
Anna 1 & 2 Summary of leakage at Surry 1 & 2 encl.
SYLVIA, B R Virginia Electric & Power Co 81/01/05 9
07575 123

R Periodic operating reports & related correspondence

B101200295 Forwards monthly operating repts for Dec 1980.
SYLVIA, B R Virginia Electric & Power Co 81/01/14 1
07477 180

--B101200297 Monthly operating repts for Dec 1980
DUNN, B D, COSTELLO, D J Virginia Electric & Power Co
4pp, 07477 181

B Reportable occurrences, LERs & related correspondence

B101220485 Forwards LER 80-045/03L-0
WILSON, J L Virginia Electric & Power Co 80/12/31 1
07502 261

--B101220492 LER 80-045/03L-0 on B01207: containment vacuum
found inoperable due to open relay contact. Caused by b
lug on coil lead. Lug was replaced & circuit returned to
normal
WILSON, J L Virginia Electric & Power Co 80/12/31
07502 262

B101090474 RD on B01220 at full power, condenser cooling wa
temp exceeded max rate of change per Tech Specs. Cause no
tated Temp decreased when waterbox outlet valve throttl
due to vacuum priming problems
SYLVIA, B R Virginia Electric & Power Co 81/01/09 1
07442 262

B101090481 Forwards LERs 80-047/03L-0 & B0-073/03L-0
WILSON, J L Virginia Electric & Power Co 81/01/05 1
07442 175

--B101090492 LER 80-047/03L-0 on B01205: discrepancies disc
documenting performance of periodic tests PT-24, 5B, 1B,
17 R & 17 J. Caused by operations personnel oversight.
Personnel retrained & improved mgt of periodic test
WILSON, J L Virginia Electric & Power Co 81/01/09
07442 177

B101200333 Forwards updated LER 80-003/03L-1 & LER 80-046/
WILSON, J L Virginia Electric & Power Co 81/01/15 1
07477 229

--B101200335 Updated LER 80-003/03L-1 on B00914, MOV-CW-200
Inoperable. Caused by electrical malfunction due to
mechanical repair in progress Redundant water box inte
valve MOV-CW-206B was shut
WILSON, J L Virginia Electric & Power Co 81/01/15
07477 230

--B101200337 LER 80-045/03L-0 on B01217, breaker feeding MO
open. Caused by coat hung on operating arm of circuit
breaker. Coat removed
WILSON, J L Virginia Electric & Power Co 81/01/15
07477 232

B101200339 Forwards LERs 80-050/03L-0 & B0-074/03L-0
WILSON, J L Virginia Electric & Power Co 81/01/15 1
07477 234

injection recirculation to boric acid tank panel B was below acceptance criteria. Caused by failure of heat tracing tape due to excessive heat. Heat tracing design change initiated. WILSON, J.L. Virginia Electric & Power Co. 8/10/15 2pp 07477-235.

V Operator Examinations

B101060308 Forwards response to specified items of NUREO-0737 re shift technical advisor training program & ECCB outage report of North Anna 1 & 2
BYLVIA, B.R. Virginia Electric & Power Co. 8/12/31. 37pp

DOCKET 90-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B101090287 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of OI102 & by applicants as part of FSAR
EISENHUT, D.O. Division of Licensing. 8/11/13 2pp

B101130124 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl.
EISENHUT, D.O. Division of Licensing. 8/11/24 4pp 07449-237.

B101080249 Releases public version of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant."
FELTON, J.M. Division of Rules and Records. 8/12/01 1p. 07422-036

--B101080258 Forwards public version of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant."
Revision 1.
HAYER, L.D. Northern States Power Co. 8/10/25 1p 07422-037

--OI101080266 Revision 1 of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant."
Northern States Power Co. 8/10/25 18pp 07422-039

B101060194 Notification of 801112 meeting w/util re draft emergency plan, trip rept encl.
MARTIN, R.E. Operating Reactors Branch 3 8/12/15 2pp 07391-304.

--OI101060204 Trip rept of 801115 visit to site re current reviews of draft emergency plans.
AXELSON, W.L., PAGLIARDI, J.A. Office of Inspection & Enforcement, Office of the Director. 8/12/11 2pp. 07391-306.

B101220176 Forwards Chemical Engineering Branch fire protection safety evaluation for facilities. Proposed mods to fire barrier penetration seals, structural member coating & fire dampers are acceptable. Review status encl.
CLARK, R. Operating Reactors Branch 3 8/12/29. 6pp. 07309-001.

B101300122 Forwards facility emergency planning info for placement in LPOB, w/o B101080283
SHOUBER, J.L. Division of Rules and Records. 8/10/19. 1p. 07583-094.

H General correspondence

B101400336 Responds to 801021 ltr requesting info re facilities. Info requested, except for security, can be inspected at POR in Minneapolis, MN.
IPPOLITO, T.A. Operating Reactors Branch 2 8/11/17. 2pp 07309-001

B101290659 Responds to 801203 request for info re emergency preparedness near facilities, for response to D Carlson. 801101 concerns FEMA working w/states & local govts to ensure that planning & preparedness are completed.
DIRCKS, W.J. Office of the Executive Director for Operations. 8/10/02. 1p. 07576-141.

--B101290667 Forwards O Carlson 001101 ltr re emergency planning around facilities, Request response.
PRODMIRE, W. Senete. 8/12/03 3pp 07576-142

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under SIS License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D.O. Division of Licensing. 8/11/20 1p

--B101100271 Revised Pages 7/4 7-22 through 28.0 3/4 7-5 & 7-6 & SIS snubber inservice insp requirements
Division of Licensing. 8/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D.O. Division of Licensing. 8/11/26 8pp

B101210444 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D.O. Division of Licensing. 8/12/15 13pp.

B101120051 Forwards Amends 44 & 38 to Licensee DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability.
CLARK, R. Operating Reactors Branch 3 8/12/17 2pp. 07445-1

--B101120056 Amends 44 & 38 to Licensee DPR-42 & DPR-60, respectively, revising common station Tech Specs re current logic for actuation of safety injection & limits for control rods & power distribution.
CLARK, R. Operating Reactors Branch 3 8/12/17 25pp 07445-332.

--B101120059 Safety evaluation supporting Amends 44 & 38 to Licensee DPR-42 & DPR-60, respectively.
Office of Nuclear Reactor Regulation, Director. 8/12/17 07445-017

--B101120062 Notice of issuance & availability of Amends 44 & 38 to Licensee DPR-42 & DPR-60, respectively.
CLARK, R. Operating Reactors Branch 3 8/12/17 2pp 07445-

B101050262 Forwards "Unit 1 Reactor Bldg Integrated Leak Rate Test - Oct 1980"
HAYER, L.D. Northern States Power Co. 8/12/22 1p. 07370-250

--B101050267 "Unit 1 Reactor Containment Bldg Integrated Leak Rate Test - Oct 1980"
HAYDOLAND, P.E. Northern States Power Co. 8/10/31. 32pp. 07378-251

B101090256 Forwards commitments to hardware, procedural & organizational implementation requirements of NUREO-0737 Implementation dependent on equipment availability & firm regulatory position.
HAYER, L.D. Northern States Power Co. 8/12/30 36pp 07378-2

B101160445 Forwards supplemental info re 800131 license amend request in response to Auxiliary Sys Branch Questions 1, 3, 4 & 5. Structural Engineering Branch Questions 1, 2 & 5.
HAYER, L.D. Northern States Power Co. 8/10/14 13pp 07472-0

B101200231 Forwards rept of ECCB outages, 1976-80, per NUREO-0737, ltr 11 R. 3.17 ECCB outage frequency does not constitute excessive unavailability. No Tech Spec changes are warranted.
HAYER, L.D. Northern States Power Co. 8/10/16 2pp. 07486-22

B101270693 Forwards startup physics test rept re Unit 1, Cycle 6.
HAYER, L.D. Northern States Power Co. 8/10/22 1p 07545-234

--B101270697 "Prairie Island Startup Physics Test Rept Unit 1 Cycle 6"
Northern States Power Co. 8/10/22 4pp. 07545-235

O Inspection reports, IE Bulletins & correspondence

B101050266 Forwards IE Info Notice 00-3B, "Cracking in Charging Pipe Cooling Cladding." No response required.
KEPPLER, J.O. Region 3, Chicago, Office of the Director. 8/10/02pp. 07389-168

B101100796 Forwards IE Circular 80-23, "Potential Effects in Beloit Power Sys Emergency Generators." No written response required.
KEPPLER, J.O. Region 3, Chicago, Office of the Director. 8/10/02pp. 07444-119.

B101060509 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety Relief Valve Operation to Cause Reactor Depressurization - No written response required. KEPLER, J G Region 3, Chicago, Office of the Director. 80/11/07 2pp 07401 116

B101060267 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1 - No response required. KEPLER, J G Region 3, Chicago, Office of the Director. 80/11/10 2pp 07391 067

B101050565 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vnl at Dresden Unit 2 - No response required. KEPLER, J G Region 3, Chicago, Office of the Director. 80/12/05. 2pp 07390 337

B101070212 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches - Technical problem has prevented repairing of Indicating Terminals for switches to show total circuit continuity. GILBERTS, D E Northern States Power Co. 80/12/11 1p 07415 244

B101070082 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown - No written response required. KEPLER, J G Region 3, Chicago, Office of the Director. 80/12/16 1p 07415 044

B101290567 Forwards IE Insp Repts 50-202/80-10 & 50-306/80-18 on B01119-20 No noncompliance noted. IE15HMM, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/18 2pp 07571 331

--B101250573 IE Insp Repts 50-282/80-18 & 50-306/80-18 on B01119-20 No noncompliance noted. Major areas inspected control rod drive & position indicator checks, core distribution limits & reactor shutdown margin determination. CHVLER, H C, ROBINSON, D L, BREITER, J F Region 3, Chicago, Office of the Director. 80/12/11 3pp 07571 303

B101305276 Forwards IE Insp Repts 50-282/80-19 & 50-306/80-19 on B01001-1130 & notice of deviation. IE15HMM, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/19 2pp 07565 229

--B101305290 Notice of deviation from insp on B01001-1130. Region 3, Chicago, Office of the Director. 80/12/19 1p 07565 231

--B101305208 IE Insp Repts 50-282/80-19 & 50-306/80-19 on B01001-1130 Noncompliance noted change to impose initial conditions on maint procedures per IE Bulletin 80-12 not incorporated as committed. FEIERBERG, D C, BURROWS, D L, LITTLE, H S Region 3, Chicago, Office of the Director. 80/12/17 12pp 07585 232

B101160586 Ack receipt of B01216 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/80-17 & 50-306/80-17. HIND, J A Region 3, Chicago, Safeguards Branch. 80/12/22 1p 07470 360

--B101160792 Responds to NRC B01118 ltr re violations noted in IE Insp Repts 50-282/80-17 & 50-306/80-17 Corrective actions withheld (ref 10CFR2 790). GILBERTS, D E Northern States Power Co. 80/12/10 1p 07470 361

B101200145 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (B01017 Indian Point 2 Event) - Procedures for detecting leakage are part of post-accident monitoring instrument monthly check. GILBERTS, D E Northern States Power Co. 81/01/05. 8pp 07486 194

B101220398 Advises that unit will be unable to meet schedule to implement mods re IE Bulletin 80-11, "Masonry Wall Design" by B10315 Full implementation of mods scheduled for completion by B10331. GILBERTS, D E Northern States Power Co. 81/01/08 2pp. 07500 241

B101290742 Forwards Parameter, Inc Rept IE-121, "Metallurgical Analysis. W/Attachment A Stress Analysis of Failed Steam Generator Support Bolts from Prairie Island, Unit 1 - JORDAN, E L Division of Resident & Regional Reactor Inspection. 81/01/23 1p 07574 254

--B101290746 "Metallurgical Analysis. W/Attachment A Stress Analysis of Failed Steam Generator Support Bolts from Prairie Island, Unit 1 - FOLEY, W J Parameter, Inc. PROFIT, T L Technimet Corp. NRC-05-80-251 IE-121 00/12/08. 3pp 07574 259

--B101290747 "Analysis of Failed Steam Generator Support Bolts from Prairie Island Nuclear Generating Plant, Unit 1 - Attachment A to Parameter, Inc Rept IE-121 encl. PROFIT, T L Technimet Corp. NRC-05-80-251 70463 47pp 07574 258

H Periodic operating reports & related correspondence

B101120294 Forwards monthly operating repts for Dec 1980. HAYER, L O Northern States Power Co. 81/01/09 1p

--B101120297 Monthly operating repts for Dec 1980. HUNSTAD, A A Northern States Power Co. 81/01/02. 8 07442 347

S Reportable occurrences, IERs & related correspondence

B101270635 Forwards LER 80-038/03L-0. HAYER, L O Northern States Power Co. 81/01/21 1p

--B101270638 LER 80-038/03L-0 on B01222, during surveillance steam occlusion actuation bistable tripped above Tech Limit caused by drift of Foxboro Model 63U-CC-04DR-F bistable Bistable reinspected & calibr. HUNSTAD, A A Northern States Power Co. 01/01/21.

B101290742 Forwards Parameter, Inc Rept IE-121, "Metallurgical Analysis. W/Attachment A Stress Analysis of Failed Steam Generator Support Bolts from Prairie Island, Unit 1 - JORDAN, E L Division of Resident & Regional Reactor Inspection. 81/01/23 1p 07574 254

--B101290746 "Metallurgical Analysis. W/Attachment A Stress Analysis of Failed Steam Generator Support Bolts from Prairie Island, Unit 1 - FOLEY, W J Parameter, Inc. PROFIT, T L Technimet Corp. NRC-05-80-251 IE-121 80/12/08 3pp 07574 259

--B101290747 "Analysis of Failed Steam Generator Support Bolts from Prairie Island Nuclear Generating Plant, Unit 1 - Attachment A to Parameter, Inc Rept IE-121 encl. PROFIT, T L Technimet Corp. NRC-05-80-251 78463 47pp. 07574 258

DOCKET 80-283 FORT CALHOUN STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B101090397 Ltr to all licensees of operating reactor plants & CP applicants. Revised radiological emergency response plans must be submitted by licensee within 60 days of B10102 & by applicants as part of FOAR. EISENHUT, O G Division of Licensing. 80/11/13. 2pp.

B101140476 Notifies of withdrawal of unit 790115 & 0629 amend license changing fire protection mod implementation schedules. CLARK, R A Operating Reactors Branch 3. 80/12/22 2

B101140209 Informs that licensee should conduct emergency within one yr from B00401 or prior to issuance of OL. Schedule of drills should be provided. SEYFRIT, H V Region 4, Dallas, Office of the Director. 1p 07461 255

J Insurance & indemnity information

B101270731 Forwards Endorsement 42 to MAELU Policy MF-6148.49 & 50 to HELIA Policy NF-207. PETERSON, H E Omaha Public Power District. 81/01/22 07548 060

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except BEP licensees) Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding mo Tech Specs to App A should be submitted within 120 days. EISENHUT, O G Division of Licensing. 80/11/20. 1p

271 Revised Pages 7/4 7-22 through 28, 8 3/4 7-5 & 7-6 & 4-17 to number inservice insp requirements
Division of Licensing 80/11/20. 10pp

6 Ltr to all power reactor licensees & applicants forwarding of 801112 meeting re implementation of guidance for ved Safety Issue A-12. "Potential for Low Fracture & Lamellar Tearing on Component Supports"
T.D.O. Division of Licensing 80/11/26 8pp.

5 Forwards responses to questions on Rule 50 71a. "Periodic g of FSARs" & FR notice of final rule SEP plants need ply w/rule until program is complete Non-SEP plants ply within specified time frame.
T.D.O. Division of Licensing 80/12/15 13pp

9 Advises that analysis re asymmetric LOCA loadings described sions 1 to WCAP-955B & WCAP-9570 is applicable to y Until will participate in fracture mechanics lan sponsored by Westinghouse owners group
N.T.M. Westinghouse Electric Corp 80/12/19 1p
08

9 Forwards response to NUREG-0737 re TMI action plan
3 2 re plant shielding mods have not been finalized
1 expects to meet schedule Upgraded emergency plans
ed under separate cover Five aperture cards in PBR
C Omaha Public Power District 80/12/31 350pp
43

3 Informs of performance testing of safety & power operated valves. EPRI is conducting testing program & expects late program & issue generic rept by 810701 Plant- rpts will not be issued until later date.
C. Omaha Public Power District 81/01/06 1p 07457-019

3 Forwards info re redundant parallel flow path to auxiliary er pumps design, in response to NRC 791022 request ie provided around existing valve FII-339, which is Feedwater supply source to auxiliary Feedwater pumps
C Omaha Public Power District 81/01/09 9pp 07462 055.

1 Forwards application to amend License OPR-40, adding 4 to Tech Specs Certificate of Svc encl.
R. J. LAMB, H. R. LEIDY, A. C. LeDeup, Lamb, Leiby & MacRae
4 2pp 07462 323

36 Application to amend License DPR-40, adding Section 4 to Specs.
H. C. Omaha Public Power District. 81/01/12. 2pp
325.

30 Proposed Section 4 to Tech Specs
ha Public Power District. 81/01/12 11pp 07462 327.

9 Forwards Amend 54 to License DPR-40 & notice of issuance & lility
A Operating Reactors Branch 3. 81/01/19 3pp 07586.059

14 Amend 54 to License OPR-40, adding two licensee conditions & ing Tech Specs to incorporate add requirements because mpletion of reviews & mods to satisfy Category A ns learned recommendations.
R. A. Operating Reactors Branch 3 81/01/19. 25pp.
062.

24 Notice of issuance & availability of Amend 54 to License
R. A. Operating Reactors Branch 3 81/01/19. 2pp
087

tion reports, IE Bulletin & correspondence

2 Responds to IE Bulletin 80-19 re failures of mercury wetted relays Tabulated history of matrix relay failuree
requests exemption from requirement ordering ment of relays.
C. Omaha Public Power District. 80/10/21 3pp 07461 248

1 Forwards supplemental response to IE Bulletin 80-11 re well design. All wells function as partitions only
aring or sheer walls not found
C Omaha Public Power District. 80/11/04. 5pp 07446 157

3 Informs that 800827 ltr responding to IE Bulletin 80-04 a mod. Main feedwater sys will be modified to close
ICV-1103 & ICV-1104 on containment high pressure not containment isolation actuation signal.
C. Omaha Public Power District. 80/11/13. 1p. 07470 362.

1101070240 Forwards IE Insp Rept 50-285/80-20 on 801001-31 No noncompliance noted
RADGEN, G. L. Region 4, Dallas. Reactor Operations Nuclear Support Branch 00/11/18 2pp 07415:174

--8101070244 IE Insp Rept 50-285/80-20 on 801001-31 No noncompliance noted Major areas inspected operational safety verification & radwaste shipment
KELLEY, O. L. . KERNICUTT, D. M. Region 4, Dallas. Office of the Director 80/11/17 2pp 07415 176

8101120072 Forwards addl info on IE Bulletin 79-018 re environ qualification of Class IE equipment, in response to 801113 telcon info details splice integrity where RTV 3145 used for splice environ barrier
JOHNS, H. C. Omaha Public Power District 80/11/19 4pp 07446-033

0101090278 Forwards IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment (October 19, 1980 Indian Point 2 Event)" Written response required
SEYFRIT, K. V. Region 4, Dallas. Office of the Director 80/11/21 1p. 07425 246

0101060336 Forwards IE Info Notice 80-42. "Effect of Radiation on Hydraulic Snubber Fluid." No response required
SEYFRIT, K. V. Region 4, Dallas. Office of the Director 80/11/24 1p. 07392 066

0101120131 Forwards response to IE Bulletin 80-23 re failures of solenoid valves mfg by Valcor Engineering Corp Program initiated to replace Valcor solenoids w/ALCOA qualified ASCO NP-1 series valves Completion anticipated Fall 1981
JONES, H. C. Omaha Public Power District 80/11/24 6pp 07446 146.

8101130694 Informs that visual insp of RCP studs at Calvert Cliffs has revealed corrosion problem similar to Ft Calhoun
Insp method should be checked.
NOVAK, T. M. Assistant Director Per Operating Reactors 80/11/24 1p 07454 038

0101050124 Requests existing data, summaries & records of inservice insp tests of containments w/grooved prestressing tendons
ORNL receiving contract to compile & review records of tendons
EISENHUT, D. O. Division of Licensing 80/11/25 3pp.

0101160942 Forwards revisions updating 801031 response to IE Bulletin 79-018 re environ qualification of Class IE equipment File has been established for all documentation supporting qualification of safety-related equipment
JOHNS, H. C. Omaha Public Power District 80/11/25 8pp 07471 285

0101060307 Forwards Suppl 1 to IE Info Notice 80-29. "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required
SEYFRIT, K. V. Region 4, Dallas. Office of the Director. 80/11/26 1p 07392 046

0101120040 Responds to IE Bulletin 80-21 re valve yokes supplied by Malcolm Foundry Co, Inc. Vendors have verbally verified Malcolm Foundry not used as subcontractor for any valves
JONES, H. C. Omaha Public Power District 80/12/05 2pp 07446 260

0101050611 Forwards IE Info Notice 80-43. "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2" No response required
SEYFRIT, K. V. Region 4, Dallas. Office of the Director 80/12/00. 1p 07391:031

8101070009 Forwards IE Info Notice 80-44. "Actuation of ECCB in Recirculation Mode While in Hot Shutdown" No written response required
SEYFRIT, K. V. Region 4, Dallas. Office of the Director. 80/12/16. 1p. 07415 039

R. Periodic operating reports & related correspondence

8101160485 Forwards monthly operating rept for Dec 1980
JONES, H. C. Omaha Public Power District 81/01/08. 1p 07471 258

--8101160488 Monthly operating rept for Dec 1980
PATTERSON, T. L. Omaha Public Power District. 81/01/08 7pp.
07471 259

B Reportable occurrences, LERs & related correspondence

8101060761 Forwards LER 80-031/03L-B
JONES, H. C. Omaha Public Power District 80/12/17 1p. 07395.030.

--B101060767 LER 80-031/03L-0 on 801207, during normal operation, leak developed in weld connecting demineralized water flush line to discharge manifold of charging pump. Caused by probable piping vibration. Crack repaired & pump returned to svc. TESAREK, J. J. Omaha Public Power District 80/12/17 4pp 07393 031.

B101120300 Forwards LER 80-032/03L-0 JONES, W. C. Omaha Public Power District 80/12/19 1p 07447 123

--B101120348 LER 80-032/03L-0 on 801210, primary heat tracing circuits associated w/piping between sulfuric acid pump discharge & MCV-26B found inoperative. Caused by blown power supply fuses. Fuses replaced. MUELLER, B. Omaha Public Power District 80/12/17 4pp 07447 126

B101130358 Forwards LER 80-030/03L-0 JONES, W. C. Omaha Public Power District 80/12/22 1p 07452 078

--B101130587 LER 80-030/03L-0 801211, diesel generator 1 failed to start on secondary air sys. Caused by vanes of air motor sticking & preventing motors from turning. Vanes cleaned & motors installed. TESAREK, J. J. Omaha Public Power District 80/12/22 4pp 07452 079

B101300513 Forwards LER 81-001/017-0 JONES, W. C. Omaha Public Power District 81/01/23 1p 07584 383

--B101300519 LER 81-001/017-0 on 810114, discovered that FT-236 changing header flow lacks complete info in qualify for herb radiation svc required by IE Bulletin 79-018. Caused by incomplete matrix list. Transmitter will be replaced. McHAFFEY, R. F. Omaha Public Power District 81/01/15 4pp 07584 344

V. Operator Examinations

B101270127 Advises that until 801030 response to NRC 800731 ltr re shift menning is unacceptable. Provision for add'l senior reactor operator for each shift must be implemented by 820701. MOYAR, T. H. Assistant Director for Operating Reactors 81/01/08 3pp 07183 001

OCGNET 80-286 INDIAN POINT STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FBAR. EISENHUT, D. O. Division of Licensing 80/11/13 2pp

B101140827 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl. No open items for facility. W/o encl. EISENHUT, D. O. Division of Licensing 80/11/24 3pp 07461 017

B101070250 Requests that encl emergency planning info be made publicly available. W/o encl. BOUDER, J. L. Division of Rules and Records 80/12/17 1p 07414 297

B101070382 Notifies that meeting w/Div of Safeguards re security plan change & vital area review has been tentatively rescheduled for wk of 810122, in response to NRC 801209 ltr. HARRINGTON, W. F. Power Authority of the State of New York 80/12/29 1p 07414 109

B101190692 Requests that encl facility emergency planning info be made publicly available. W/o encl. BOUDER, J. L. Division of Rules and Records 81/01/09 1p 07472 320

B101190709 Requests that encl facility emergency planning info be made publicly available. W/o encl. BOUDER, J. L. Division of Rules and Records 81/01/09 1p 07472 286

B101300456 Requests 30-day extension to respond to NRC 801830 ltr item re vital areas. LAEL representatives will be unavailable before 810202 for vital areas conference w/units & NRC Div of Safeguards. HARRINGTON, W. F. Power Authority of the State of New York 81/01/26 1p 07581 350

O. Adjudicatory correspondence

B101100660 Forwards revised order for mod of license, 800629 order. Hearing date also revised. EISENHUT, D. O. Division of Licensing 80/09/19 3pp

--B101100666 Revised order amending License DPR-64. Infr Bulletin 79-018 must be submitted to IE by 801101. EISENHUT, D. O. Division of Licensing 80/09/19 1p

B101160246 Order denying request for reconsideration of 800530 order but directing ASLB to conduct discretionary proceeding using full adjudicatory format. Listed fees to be addressed. Certificate of Svc encl. CHILK, S. J. Office of the Secretary of the Commission 19pp 07470 228

B101270319 Requests that public hearings re emergency be rescheduled to earlier date. DELDELL, A. O. Westchester County, NY 81/01/08 2pp

B101270047 Requests hearing on completion of spent fire consequences. HOLT, J., AUDIN, L., CORREN, D. Public Interest Research York 81/01/19 2pp 07547 023

H. General correspondence

B101260199 Supports shutdown of facilities. AUBREY, C. Affiliation Unknown 81/01/09 1p 075

B101270304 Requests info re B10110 constituent ltr req hearings be held for facilities ltr encl. WILLIAMS, H. A. Senate 81/01/19 1p 07307 001

B101280272 Supports shutdown of facility. SELIG, J. Affiliation Unknown 81/01/20 1p 0730

B101280605 Supports revocation of license. ALABR, A., MCOWILLIGUDDY, C., WILLOUGHBY, R. H. Affiliat 81/01/22 1p 07597 285

P. Operating license etags documents & correspondence

B101100660 Forwards revised order for mod of license, 800629 order. Hearing date also revised. EISENHUT, D. O. Division of Licensing 80/09/19 3p

--B101100666 Revised order amending License DPR-64. Infr Bulletin 79-018 must be submitted to IE by 801101. EISENHUT, D. O. Division of Licensing 80/09/19 1p

B101220243 "Fracture Toughness of Steam Generator & Reactor Pump Supports," interim technical evaluation rept. BITLWELL, T. C., NOELL, P. N., ALLEN, A. G. Franklin Inst Research Center, NRC-03-79-118. 8101220243 80/09/07503 263

B101030297 Immediate Action Ltr 80-47 confirming 80111 measures until taking to assure operability of condenser cooler sys & to detect existence of svc water leak inside containment. GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/11/17 2pp 07389 282

B101280376 FOIA request for documents re Test Force on Operation of Indian Point submitted to NRC 800601-11. HOLT, R. R. New York Univ. 80/11/17 1p 07558 062

B101100254 Ltr to all licensees (except BEP licensees) Revision 1 of inservice surveillance requirements for snubbers under STB. License amend application adding Tech Specs to App A should be submitted within 120 d. EISENHUT, D. O. Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 26, 8 3/4 7. STB snubber inservice insp requirements. EISENHUT, D. O. Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicable summary of 801112 meeting re implementation of guidelines. Unresolved Safety Issues A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports," EISENHUT, D. O. Division of Licensing 80/11/26 8pp

Forwards responses to questions on Rule 50.71e. "Periodic of FSAs" & FR notice of final rule SEP plants need by w/rule until program is complete. Non-SEP plants by within specified time frame
O O Division of Licensing 80/12/19 13pp.

Forwards "Rept on 1970-1979 Studies to Evaluate Catch of 1 D-m2 Epibenthic Bled " Certificate of Bvc

J. O. Consolidated Edison Co of New York 80/12/19 3pp.
9

23 "Rept on 1978-79 Studies to Evaluate Catch Efficiency of Epibenthic Bled "
as Instruments, Inc 80/09/30 36pp 07345.072

Forwards schedule of implementation of outstanding items re on plan requirements in NUREO-0737 per 801231
Util will not propose Tech Specs re requirements
mission provides addl clarification.
P. Power Authority of the State of New York 80/12/30
7309 001.

Forwards application for amend of License DPR-64, changing App A to conform w/TMI-2 Lessons Learned Category erents & Westinghouse STS Class III fee encl.
P. Power Authority of the State of New York 80/12/30
420 001

16 Application for amend of License DPR-64, changing Tech Space per TMI Lessons Learned Category A Items & ghause BTB
J. P. Power Authority of the State of New York 80/12/30
07420 004

26 Proposed changes to Tech Specs App A, Bactions 3, 4 & 6 re TMI s Learned Category A Items & Westinghouse BTB Safety tion encl
ar Authority of the State of New York 80/12/30 20pp
005

Forwards "1970 Yr Class Rept for Multiplant Impact Study n River Estuary " Affidavit of svc encl Rept e in Central Files only.
J. O. Consolidated Edison Co. of New York 81/01/16 4pp.
B

Responds to FOIA request for documents re Task Force on Operation of Indian Point submitted to NRC after
Forwards App A documents App B documents withheld
A Exemption 5)
M Division of Rules and Records 81/01/21 3pp.
9

81 Forwards draft risk analysis for facilities Probability of core damage is slight, taking into account
ements made or committed to as of early 1980 W/o encl
ILLA.H Commissioners 80/06/13 1p

88 Staff requirements memo re 800626 briefing on
ondations of Facility task force Commission took no
during meeting Task force rept & other info re
y operation will be reviewed further.
B J Office of the Secretary of the Commission. 80/06/30.

96 Discusses review of task force rept on Interim operation of
ties Interim operation poses no undue risk to public &
on health & safety. Facilities should be permitted to
ne operation during proceedings
E. J. M. Commissioners 80/07/02 1p

102 Provides JM Hendrie comments on order re interim operation
ility. Specific language of order should be modified.
an on interim operation depends more heavily on task
results.
L. D. F. Commissioners 80/06/22 1p

2 Forwards proprietary & nonproprietary update to App A of
lter re IP-3 turbine disc properties info derived from
lional modal accounting for thermal & steam bending
a. Portions withheld (ref 10CFR2.790). Affidavit encl
P. Power Authority of the State of New York. 81/01/22
07593.346.

596 Nonproprietary version of "Update to App A of Authority
9 Ltr. -
ver Authority of the State of New York. 81/01/22. 37pp.
356

G Inspection reports, IE Bulletins & correspondence

8101300734 Forwards IE Insp Rept 80-206/80-14 on 800903-04 No
noncompliance noted
Encl. O H Region 1, Philadelphia, Fuel Facility & Materials Safety
Oranch 80/11/10 2pp 07903 336

--8101300740 IE Insp Rept 80-206/80-14 on 800903-04 No noncompliance
nated Major areas inspected meteorological monitoring sys
including primary & backup measurements programs
80REB.R J. Region 1, Philadelphia, Fuel Facility & Materials
Safety Oranch JACKSON, T J Region 1, Philadelphia, Office of the
Director. 80/10/24 7pp 07983 330

0101070421 Forwards Suppl 1 to IE Info Notices 80-29, "Broken Studs on
Terry Turbine Steam Inlet Flange " No written response
required
GRIER, O H Region 1, Philadelphia, Office of the Director
80/11/26 1p 07414 041

0101060011 Forwards IE Info Notices 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown " No written
response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/16 1p 07397 049

8101290275 Ack receipt of 801230 payment in full for civil penalties
imposed by NRC 801208 order
TIGHE, PSON, D Enforcement & Investigation Staff 81/01/13 1p
07575 113

R Periodic operating reports & related correspondence

0101140316 Forwards "1977 Yr Class Rept for Multiplant Impact Study of
Hudson River Estuary " Certificate of Svc encl
O'DOLE, J. O. Consolidated Edison Co of New York 80/12/19 3pp
07459.001

--8101140326 "1977 Yr Class Rept For Multiplant Impact Study of Hudson
River Estuary "
e Texas Instruments, Inc 80/07/31 700pp 07459 004

0101200287 Forwards monthly operating rept for Dec 1980.
ZULLA, B B Power Authority of the State of New York 81/01/12 1p.
07477.167

--8101200290 Monthly operating rept for Dec 1980
CONNELL, C Power Authority of the State of New York 81/01/01
4pp. 07477 160

0101230582 Forwards tabulation of daily record of fish collections for
Dec 1980
O'TOOLE, E. J. O. Consolidated Edison Co of New York 81/01/15 3pp
07510.279.

O Reportable occurrences, IERs & related correspondence

8101270834 Confirms that during routine review of surveillance test
program, determined that safety injection logic channel test
for Train A & B had exceeded; required due dates. Testing
completed immediately
ZULLA, B B Power Authority of the State of New York 80/12/23 1p.
07549.124

0101090612 Forwards LER 80-017/01T-0
ZULLA, B B. Power Authority of the State of New York. 81/01/05. 1p.
07430.357

--8101090621 LER 80-017/01T-0 on 801222, review determined that safety
injection sys logic test for Train A & B exceeded required
due dates Caused by poor communication due to clerical
error
GUMBLE, F. W. Power Authority of the State of New York 81/01/05
1p. 07430 358

8101280416 PND-1-81-04 on 810111, during sampling of vol control
tank, inadvertent gaseous release occurred resulting in 02.2
Ci noble gas being released over period of 131 minutes No
personal exposures involved. Media interest expected.
WHITE, J. RISTER, H Region 1, Philadelphia, Office of the Director
81/01/12 2pp 07557 038

8101270654 RD on 810111, during planned release of noble gas, magnitude
of release exceeded expectations. Insignificant amount of
1-131 was also released. Caused by leak in connecting
sampling sys. Leaking portion isolated & will be repaired
ZULLA, B B. Power Authority of the State of New York. 81/01/21
2pp. 07948.359

On 01/01/22, the following information was received from the State of New York:

801220466 Ltr to all power reactor licensees & app
sury of 801112 meeting re implementation of ge
Unresolved Safety Issue A-12. "Potential for Low
Toughness & Lamellar Tearing on Component Support
EISENHUT, D G Division of Licensing 80/11/26

B01090175 Forwarded Amendments 89, 84 & 04 to Licensees 1
DPR-55, respectively, safety evaluation & notice of
& availability
REID, R W Operating Reactors Branch 4 80/12/10

--B101090184 Amends 87, 89 & 86 to licenses DPR-38.1
respectively, revising Tech Specs to redefine to
to add general limiting conditions for operat
REID, R W Operating Reactors Branch 4 80/12
07426-310

-B101090195 Safety evaluation supporting Amends A9
DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Direct
07426 321

--B:01090205 Notice of issuance & availability of A
Licenses BPR-38, BPR-47 & OPR-99, respectively
REID, R W Operating Reactors Branch 4. 00/12/
07426 323

B101210445 Forwards responses to questions on Rule
Updating of FBARs" & FR notice of final rule. SEP
not comply w/rule until program is complete Non-S
just copy within specified time frame
EISENHUT.B.O Division of Licensing 80/12/15.

BIO1200223 Requests amend to license revising Tech
burned contaminated oil, per 800319 ltr
PARKER, W D, Duke Power Co 80/12/17 2pp 07

8101050107 Application to amend License BPR-55, chan
Section 3.9 re operational & axial power shaping
operational power imbalance limits & adding Tech
3.5.2.9 re operation beyond normal design cycle
PARKER, W O Duke Power Co. 80/12/22 2pp. 073

-B101050112 Proposed change to Tech Specs Section
axial power shaping rods position limits & oper
imbalance limits & adding Tech Spec 3.5.2.9 re
beyond normal design cycle length
* Date Power Co 80/12/22 lipp 07376.324

B101100440 Forwards Amends 90.90 & 87 to Licensees D
DPR-55, respectively, safety evaluation, EIA & notice
issuance & availability
REID, R W Operating Reactors Branch 4. 80/12/24

--8101100448 Amends 90.90 & B7 to Licenses OPR-38. D
respectively, allowing increase in spent fuel st
capacity
NOVAH, T M Assistant Director for Operating Re
7pp 07444. 203

--8101180462 Safety evaluation supporting Amends 90
DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Direct
07444 213

-B101103471 EIA supporting Amends 90.90 & 07 to LI
DPR-55, respectively
* Office of Nuclear Reactor Regulation, Direct
07444 222

--B101100479 Notice of issuance & availability of A
Licenses DPR-38, DPR-47 & DPR-55, respectively &
declassification
ERICKSON, P. B. Operating Reactors Branch 4. BO
07444-231

9101050094 Application for amend of Licenses DPR-30
changing Tech Specs. Section 4 to modify certain s
requirements on annual basis for each refueling o
fee encl.
PARKER, W B Duke Power Co. 80/12/29. 300 073

--B1010101: Proposed changes to Tech Specs. Section
surveillance requirements from performance on a
to performance during each refueling outage.
* Duke Power Co 80/12/29 18pp. 07376-304

Forwards proposed Tech Specs revision re reactor bldg &
leakage tests, supplementing B01024 submittal
air lock testing to be submitted upon review

Duke Power Co 80/12/29 1p 07396 310

Proposed Tech Specs 3.6 & 4.4 revision re reactor bldg &
leakage tests, respectively Containment leakage
revision reflects App J requirements
Power Co 80/12/29 15pp 07396 319

"Test Requirement Bases & Justification for Reverse
Engineering Testing"

Power Co 80/12/29 8pp 07396 334

Forwards list of TLD station locations near facility &
route for exchanging TLDs for NRC direct radiation
network w/o encls
Region 2, Atlanta, Fuel Facility & Materials Safety
01/12/30 2pp 07407 116

Forwards response to NUREG-0737, post-TMI requirements,
info re shift terminal advisor, short-term
procedures review & containment isolation
Utility Central Files version of emergency plan encl
Duke Power Co 81/01/02 70pp 95189 012

"Thermal-Mechanical Rept - Effect on HPI on Vessel Integrity
at Boral, LOCA Event W/ Extended Loss of Feedwater"
sized drawings & responses to NUREG-0737 encl
Baker & Wilcox Co BAW-1648 80/11/30 158pp

Provides alternate methods of nondestructive exams for welds
formed in place of hydrostatic testing, following
NRC B01107 ltr granted licensee relief from
requirements re hydrostatic testing.
Duke Power Co 81/01/07 2pp 07452 111

Advices that response to NRC B01114 ltr requesting addl info
on feedwater sys will be ready for submittal by

Duke Power Co 81/01/12 1p 07471 148

Forwards Reactor Physics Section evaluation of util
to reload for Cycle 5. Proposed changes in
load requirements are acceptable
V Core Performance Branch 81/01/13 2pp 07549 055

Responds to NRC B01001 request for proposed updated Tech
Specs fire protection program Tech Specs currently
under review & will be submitted by 01/03/81
Duke Power Co 81/01/15 1p 07489 270

Advices of delay of response to NRC B01027 ltr re standby
utility response will be provided no later than

Duke Power Co 81/01/15 1p 07493 252

on reports, IE Bulletins & correspondence

requests existing data, summaries & records of Inservice Insp
containments w/ greased prestressing tendons
inviting contract to compile & review records of

Division of Licensing 80/11/25 3pp

ack receipt of B01126 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-269/80-32,
50-269/80-28 & 50-287/80-25
Region 2, Atlanta, Reactor Operations Nuclear Support
01/12/82 1p 07421 018

ack receipt of IE Insp Repts 50-269/80-32, 50-270/80-28 &
50-29 on B00902-30 No proprietary info, corrective
Tech Specs revised, personnel training reviewed & ltr
to station manager
Duke Power Co 80/11/26 3pp 07421 019

Forwards IE Insp Repts 50-269/80-32, 50-270/80-28 &
50-29 on B00902-30 & notice of violation
C, Region 2, Atlanta, Reactor Operations Nuclear Support
80/11/03 2pp 07421 022

Notice of violation from Insp on B00902-30
in 2, Atlanta, Office of the Director, 80/11/03 1p
4

--B01080177 IE Insp Repts 50-269/80-32, 50-270/80-28 & 50-287/80-25 on
B00902-30 Noncompliance noted failure to comply w/ Tech Spec
requirement for processing major procedure change
JAPE, F. O'DERS, W. MYERS, D. Region 2, Atlanta, Office of the
Director 80/11/03 7pp 07421 025

B01150126 Supplis 800718 ltr re rods to reactor bldg spray sys for
facilities rods to be installed during next available forced
outage of sufficient duration or next refueling outage
PARKER, W. O. Duke Power Co 80/12/12 1p 07462 191

B01040225 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown" No written
response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/16
1p

B01140258 Responds to IE Bulletin 80-23 re Valnor Engineering Corp
solenoid valve failure Util will replace all Valnor
solenoid valves w/ ASCO solenoid valves as soon as received
PARKER, W. O. Duke Power Co 80/12/24 1p 07470 258

B01200575 Forwards response to IE Bulletin 80-24 re prevention of
damage due to water leakage inside containment Tech Specs &
station directives ensure reporting of abnormal degradation
of primary containment
PARKER, W. O. Duke Power Co 81/01/06 11pp 07477 240

B01210213 Forwards supplemental response to IE Bulletin 80-06,
"Engineered Safety Feature (ESF) Reset Controls" Mode
completed on high pressure injection pumps, penetration room
exhaust fans, reactor bldg cooling unit fan & Rescove start
PARKER, W. O. Duke Power Co 81/01/07 13pp 07488 017

B01190385 Forwards request for relief from ASME Code Section XI
Inservice Insp requirements re main feedwater system
valves Approval requested by B01014
PARKER, W. O. Duke Power Co 81/01/13 5pp 07475 312

K Periodic operating reports & related correspondence

B01210462 Forwards monthly operating reports for Dec 1980
PARKER, W. O. Duke Power Co 81/01/15 1p 07493 170

--B01210464 Monthly operating reports for Dec 1980
REAVIN, J. A. Duke Power Co 81/01/15 16pp 07493 171

B Reportable occurrences, LERs & related correspondence

B01050381 Forwards LER 80-018/03L-0
PARKER, W. O. Duke Power Co 80/12/29 2pp 07389 295

--B01050385 LER 80-018/03L-0 on B01129, oil pump on turbine-driven
emergency feedwater pump was found empty Caused by
misalignment of valves for tube oil purifier, allowing oil
from pump to flow into turbine oil storage tank
JONES, J. L. Duke Power Co 80/12/29 1p 07389 297

B01070657 Forwards LER 80-020/03L-0
PARKER, W. O. Duke Power Co 81/01/02 2pp 07430 200

--B01070666 LER 80-020/03L-0 on B01204, fire barrier in Unit 3 cable
room floor forced out of pipe sleeve & into personnel
elevator lobby Caused by operator putting foot on
penetration steel plate welded on top of sleeves
JONES, J. L. Duke Power Co 81/01/02 1p 07430 202

B01210511 Forwards LER 80-017/03L-0
PARKER, W. O. Duke Power Co 81/01/14 2pp 07490 199

--B01210516 LER 80-017/03L-0 on B01215, fire detector string B declared
inoperable due to spurious alarms Caused by excessive dust
buildup on detectors, resulting in increased sensitivity Fire
detector 3X1 replaced & string operability verified
JONES, J. L. Duke Power Co 81/01/14 1p 07490 201

B01210643 Forwards LER 81-001/01T-0
HINES, A. C. Duke Power Co 81/01/22 2pp 07548 348

--B01210650 LER 81-001/01T on B01086, polar crane found operating over
fuel transfer canal w/ reactor vessel head removed Caused
by personnel error Suspended load directed away from fuel
transfer canal
JONES, J. L. Duke Power Co 81/01/22 1p 07548 350

DOCKET 50-224 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants. CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

B101190786 Forwards NUREG-0746, "Emergency Preparedness Evaluation for
TMI-1" & notice of issuance. W/o NUREG-0746
REID, R W Operating Reactors Branch 4 80/12/10 1p 07473 051

--B101190788 Forwards NUREG-0746, "Emergency Preparedness Evaluation for
TMI-1" Certificate of Bvc encl W/o NUREG-0746
GRAY, J R Hearing Branch 1 80/12/10 6pp 07473 052

--B101190791 Notice of availability of NUREG-0746, "Emergency
Preparedness Evaluation for TMI-1"
REID, R W Operating Reactors Branch 4 80/12/10 2pp
07473 058

B101100497 Forwards errata sheet to NUREG-0746 Certificate of Bvc encl
REID, R W Operating Reactors Branch 4 80/12/24 3pp 07445 084

--B101100508 Errata to EMERGENCY PREPAREDNESS EVALUATION FOR TMI-1.
* Office of Inspection & Enforcement, Office of the Director
NUREG-0746 ERR 80/12/24 2pp 07445 087

B101060405 Forwards Revision B to security plan Revision B withheld
(ref 10CFR 2.790)
MUKILL, M O Metropolitan Edison Co 80/12/30 1p 07398 078

B101150442 Requests that encl facility emergency planning info be made
publicly available W/o encl B012190094
SCUDER, J L Division of Rules and Records 80/12/31 1p
07338 001

B101150447 Requests that encl facility emergency planning info be made
publicly available W/o encl B01220508
SCUDER, J L Division of Rules and Records 80/12/31 1p
07338 001

B101280092 Forwards emergency planning info for placement in LPOB
W/o encl
SCUDER, J L Division of Rules and Records 81/01/08 1p
07557 083

B101140245 Forwards "Review of PA REP Planning Site-Specific to TMI,"
prepared by FEMA NRC will not be issuing safety evaluation
suppl on adequacy of overall emergency preparedness for TMI
at this time
GRAY, J R Hearing Branch 1, 81/01/12 2pp 07458 004

--B101140249 Forwards "Review of PA REP Planning Site-Specific to TMI,"
JETT, O W Federal Emergency Management Agency 81/01/04 1p
07458 086

--B101140252 "Review of PA REP Planning Site-Specific to TMI,"
* Federal Emergency Management Agency 81/01/08 19pp
07458 087

B101290648 Releases public version of util response to revised
emergency plan comments
FELTON, J M Division of Rules and Records 81/01/27 1p
07187 001

--B101290652 Forwards public version of response to LRC 800909 comments
on emergency plan, Revision 2
MUKILL, M O Metropolitan Edison Co 80/12/29 41pp 07187 001

G. Adjudicatory correspondence

B101060705 Summarizes concepts discussed in 790725 meeting re proposal
to have hearings on TMI-1 restart. Statutorily required
hearing must be held if requested on all elements to suspend
or revoke license
BICKHILL, L Office of the General Counsel 79/07/26 10pp
07401 061

B101070290 Requests response to Items 3, 4, 5, 6, 7 a, 7, b, 8 & 9 of NRC
B00811 request for addl info NRC must have responses to
complete testimony on financial qualifications issue. Delay
could lead to delay in TMI-1 restart hearing completion.
REID, R W Operating Reactors Branch 4, 80/12/17 4pp 07413 293

B101120101 Notification of contract execution. Mod 1
for ASLB TMI-1 Restart Hearing " Contractor Cole &
MEMORIAL, A Administrative Contracts Branch NRC
80/12/19 1p 07446 118

--B101120104 Mod 1, extending monthly rental for Orou
B10331, to "Furnishings for ASLB TMI-1 Restart He
* Cole & Co LEGO, C D Administrative Contracts Branch
NRC-10-80-719, 80/12/19 2pp 07446 119

B101050531 Requests permission to make limited appeal
in NRC restart hearing for facility Requests sched
date & time for appearance
LYNO, T J Affiliation Unknown 80/12/22 1p 0

B101050458 Notice of withdrawal of intervenor Sholly
14, 11 & 61b) Requests ASLB give intervenors right
Contentions 8 & 9 or that Board adopt Contentions
Certificate of Bvc encl
SHOLLY, S C Affiliation Unknown 80/12/23 7pp

B101090521 Notifies Commission of withholding of tra
scheduling info from intervenor Environ Coalition
Nuclear Power & requests Commissioners direct ASLB
written schedule for remaining contentions
JOHNBRUD, J H Environmental Coalition on Nuclear
2pp 07423 262

--B101090330 Request that encl transcript of B01203
Johnsrud & C Kefford re absence of Environ Coall
Nuclear Power representative to cross-examine on
fid) be included in record Certificate of Bvc encl
JOHNBRUD, J H Environmental Coalition on Nuclear
4pp 07428 263

B101130049 Requests expedited mailing of transcripts
contents to include noted page numbers on proced
ratters & Contentions being addressed by testimony
PULLARD, R O Chesapeake Energy Alliance 80/12/3

B101080396 Advises that UCB is withdrawing Contention
status panel, Contention 7.1e instrumentation to de
inadequate core cooling & Contention 13.1e Class 9
in TMI-1 restart hearing Action due to lack of res
WEISB, E R Sheldon, Herman & Weiss 81/01/05 1

B101090073 Request by M Lewis to join intervenors' j
opposition to licensee motion for reconsideration
790702 & 0809 Commission orders Certificate of Bvc
LEWIS, M Affiliation Unknown 81/01/05 5pp 0

B101120437 Responses opposing Environ Coalition on N
B01215 motions to serve NUREG-0534, to grant exten
compere rept w/NUREG-0746, to file discovery reques
disqualify ASLB Certificate of Bvc encl
ZAHLER, R E Metropolitan Edison Co ZAHLER, R E
Potts & Troubridge 81/01/05 8pp 07442 302

B101130053 Forwards "Review of TMI-1 Control Room Fr
Viewpoint," Certificate of Bvc encl
BAXTER, T A Metropolitan Edison Co BAXTER, T A
Potts & Troubridge 81/01/05 6pp 07448 346

B101090236 Response opposing Environ Coalition on Nu
response to ASLB B01125 memorandum & order, B01204
B01211 memorandum & order Opposes extended discove
reconsideration of B00107 filing Certificate of Bv
SMARTZ, L L Office of the Executive Legal Director
07424 010

B101120506 Forwards State of PA response to M Dicks
JF Ahoarne
ADLER, R W Pennsylvania, State of 81/01/06 1p

--B101120511 Response opposing General Public Utilis
mod of NRC 790702 & 0809 orders. Expediting issu
to restart are within bounds of 790809 order. W/o
of Bvc
SMITH, D C Pennsylvania, State of 81/01/06

B101120508 Brief responding to General Public Utilis
mod of 790702 & 0809 orders to allow TMI restart p
hearing completion interposes no objection if Dire
Nuclear Reactor Regulation & Commission agree
SWANSON, D T Hearing Branch 1, COBORGUE, J E OF
Executive Legal Director 81/01/06 31pp 07445

B10120537 Response opposing util Dec 1980 request for Commission reconsideration of 790702 & 0809 orders Ltr was late & lacked factual support for assertions Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R Gschiff, Hardin & Waits 01/01/06 8pp 07445 101.

B10130027 Response opposing General Public Util request to reconsider 790702 & 0809 orders. Endorses 801210 joint response in opposition to license motion Approving restart before proceedings "shatters" NRC credibility W/Certificate of Svc * Chesapeake Energy Alliance 01/01/06 3pp 07448 293

B10130031 Notice of withdrawal of appearance in proceeding ADLER, T A Three Mile Island Alert ADLER, T A Widoeff, Reager, Selkowitz & Adler 01/01/06 2pp 07448 298

B10130042 Forwards H Dieckamp B10106 ltr to NRC BLAKE, E L Metropolitan Edison Co BLAKE, E L Shaw, Pittman, Potts & Troubridge 01/01/06 2pp. 07448 339

--B10130045 Responds to allegations that Met Ed has not been diligently pursuing legal & procedural remedies & furnishing info to NRC DIECKAMP, H General Public Utilities 01/01/06 4pp 07448 341

B10140941 Memorandum & order directing all parties, particularly TMI Alert, Antinuclear Group Representing York & Aomdot, to appear on 010109 in Harrisburg, PA if interested in hearing mgt issues schedules. SMITH, L W Atomic Safety and Licensing Board Panel 01/01/06 3pp 07438 244.

B101230083 Informa that contention re filters will be heard as early as 1 PM on 010108 SMITH, L W Atomic Safety and Licensing Board Panel 01/01/06 1p 07511 334.

B10140251 Notice of appearance in proceeding BRADFORD, L Three Mile Island Alert 01/01/08 2pp. 07470 247

B10150270 Memorandum forwarding Ahaerne 001204 memo explaining why intervenors do not receive mailed copies of transcripts SMITH, L W Atomic Safety and Licensing Board Panel 01/01/09 4pp 07462 199.

B10140242 Response opposing Aomdot 001215 motion for assistance in obtaining expert witnesses. No objection to request for extension of time to file Contention 2 testimony Certificate of Svc encl. SHANBON, O T Hearing Branch 1. 01/01/12 7pp. 07450 101.

B10140245 Forwards "Review of PA REP Planning Site-Specific to TMI," prepared by FEMA NRC will not be issuing safety evaluation suppl on adequacy of overall emergency preparedness for TMI at this time GRAY, J R Hearing Branch 1 01/01/12 2pp. 07450 004.

--B10140249 Forwards "Review of PA REP Planning Site-Specific to TMI" JETT, O W Federal Emergency Management Agency. 01/01/06 1p. 07458 086

B101230068 Requests to make limited appearance statement at restart hearing CHARLES, E R Affiliation Unknown. 01/01/12 1p. 07511 332

B101240594 Submits changes to draft response re TMI-1 restart proceeding financial info. General Public Util currently revising financial forecast, incorporating mail changes & reflecting 1901 spending levels, to be available by 010223 RUKILL, H B Metropolitan Edison Co. 01/01/13 2pp. 07409 268

B101160167 Response to Met Ed 001223 ten interrogatories on reactor vessel water level. CUTCHAM, J M Hearing Branch 3 01/01/14 7pp 07470 006

--B101160175 "Rept on Saint Lucie 1 Natural Circulation Cutdown on 000611." Certificate of Svc encl. HENDR, E V Director's Office 01/01/14 28pp. 07470 013

B101220008 Memorandum on estimated schedule & sequence of hearing for issues in proceeding Inadequate core cooling begins 010120. ASLB Question 11 possibly before 010127 & Class 9 on 010127, followed by cleanup testimony Certificate of Svc encl. SMITH, L W Atomic Safety and Licensing Board Panel. 01/01/15 7pp. 07501 330

B101230609 Informa that NRC & license plan to file testimony re planning & related contentions on 010209 instead of 010119 Svc list encl
ZAHLER, R E Shaw, Pittman, Potts & Troubridge 01/01/19 4pp 07512 265

B101230635 Statement of concurrence w/Sholly B10113 memorandum re Dieckamp B10106 ltr Requests that ASLB provide written schedule for filing & cross-examination & withdraw policy of ruling & scheduling from bench Certificate of Svc encl JOMSRUD, J H Environmental Coalition on Nuclear Power 01/01/19 2pp 07512 281

B101260261 Statement of objection to placing burden of proof on intervenor re UCB Contention 11 on reaction of zirconium cladding to produce hydrogen Hydrogen control limits waived for Sequoyah W/Certificate of Svc WEISS, E R Union of Concerned Scientists 01/01/15 11pp 07523 318

B101260275 Requests to make limited appearance statement at restart hearing HOCKER, H M Affiliation Unknown 01/01/15 1p 07308 001

B101200018 Memorandum requesting that Commission disregard Dieckamp B10106 responses to motion for reconsideration of 790702 & 0809 orders if ltr is considered, intervenors insist on reasonable time for reply Certificate of Svc encl. BODLEY, B C Affiliation Unknown * Newberry Township TMI Stead Committee * Three Mile Island Alert 01/01/16 6pp 07477

B101210204 Requests extension until 010209 to file written testimony on onsite emergency preparedness Granting extension will not delay hearing. GRAY, J R Hearing Branch 1 01/01/16 2pp. 07470 045

B101210192 Forwards license amend & supporting safety evaluation A involving energy absorbing pipes support snubbers does not appear to relate directly to issues W/o encls GRAY, J R Hearing Branch 1 01/01/19 1p 07107 001

B101230219 Response in opposition to Antinuclear Group Representing York B10108 motion to adopt Sholly contentions except Contentions B1131b1 & B11311 Emergency plan will be fully litigated Certificate of Svc encl
ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Troubridge 01/01/19 7pp 07512 040

B101230225 Response opposing Environ Coalition on Nuclear Power 01 request for Commission investigation of ECHP failure to receive transcripts & scheduling info Alternatively, request should be referred to ASLB Certificate of Svc encl JONDRIDOE, O F Metropolitan Edison Co TROUBRIDGE, O F Shaw, Pittman, Potts & Troubridge 01/01/19 9pp 07512 047

B101200311 Forwards H Dieckamp B10120 ltr to JF Ahaerne, replying to B10106 response to Dieckamp 801201 ltr Svc list also encl. BAXTER, T A Shaw, Pittman, Potts & Troubridge 01/01/21 4pp 07557 170

--B101280316 Responds to NRC B10106 reply to Dieckamp 801201 ltr re restart pending completion of restart hearings NRC has departed from Commission orders & imposed odd conditions for restart. DIECKAMP, H General Public Utilities - OPU Service Corp 01/01/20 4pp 07537 174.

B101290722 Forwards W Wegner testimony re licensee mgt capability technical resources, which apply to issues 1, 2, 4, 5, 6, 7, 10 & 11 of Commission 800306 CLF-B9-3 order. Licensee response re 800627 spill & Certificate of Svc also encl. GERNSTEIN, B L Shaw, Pittman, Potts & Troubridge. 01/01/26 4 07567 001

--B101290734 Response to ASLB 800812 questions re 800627 10,000 gal spill at TMI-1. Spill caused by operator error. Employees briefed on incident & procedures for transferring inverters revised Spill had no impact on TMI-2 * Metropolitan Edison Co 01/01/26 10pp. 07567 047

--B101290737 Drain down & maintain RCS level between 314 ft 10 inch 315 ft 3 inches Incorporates & supersedes but does not alter safety evaluation of BOP-1-00-29. Supporting documentation encl. SHIPMAN, H O, DULRID, R W, TOOLE, Y Metropolitan Edison Co. 01/01/26 59pp 07567 057.

B101290735 Application for Tech Specs Change Request 98, amending License DPR-90, Certificate of Svc & Class 111 fee encl RUKILL, H D Metropolitan Edison Co 01/01/26 3pp 07576 005

--B01290762 Order authorizing organization of General Public Utilities Nuclear Corp as wholly owned subsidiary for mgt & operation of nuclear plants.
F11251PM015 G Securities & Exchange Commission 80/09/15 3pp
07576 027.

--B01290766 Notice of proposal to organize General Public Utilities Nuclear Corp as wholly owned subsidiary for mgt & operation of nuclear plants w/related documentation
F11251PM015 G Securities & Exchange Commission 80/06/19 85pp
07576 030

--B01290771 Request that NJ Board of Public Utilities dismiss for lack of jurisdiction Util & General Public Utilities Nuclear Corp proposed operating agreement in alternative agreement should be approved
BRCKAW.R D Jersey Central Power & Light Co BRCKAW.R D
Briean.R U 80/04/11 7pp 07576.120

H General correspondence

B010150050 Urges restart of TMI-1 to reduce consumption of foreign oil
CRIPPEL.N D Affiliation Unknown 80/10/26 2pp 07465.233

B01200243 Urges facility restart due to increasing fuel costs.
DELGINARD.N H Affiliation Unknown 80/10/21 1p 07187.001

B01090162 Comments that facility should be restarted Reactor operation would reduce costs & save oil
BACHMEFER.M I Affiliation Unknown 80/10/22 1p 07309 001.

B01090086 Comments that facility should be restarted Society demands energy supply
MESS.P W Affiliation Unknown 80/10/23 1p 07442 236.

B01090145 Comments that facility should be restarted due to outstanding operation record for five yrs Energy would be less expensive w/reactor operating Coal endangers environ more than radiation.
STAY.EY.M A Affiliation Unknown 80/10/23 3pp 07309 001

B01090122 Urges facility restart Util has attempted to meet safety stds Electric rates would decrease w/reactor in operation
ZIEGLER.L J Affiliation Unknown 80/10/27 1p 07442 233

B01090134 Urges facility restart Util has attempted to meet safety stds Electric rates would decrease w/reactor in operation
ZIEGLER.L J Affiliation Unknown 80/10/27 1p 07442 232

B01090129 Urges facility restart Util has attempted to meet safety stds Electric rates would decrease w/reactor in operation
ZIEGLER.L J Affiliation Unknown 80/10/27 1p 07442 288.

B01250310 Urges facility restart Util has tried to meet all safety stds & electric rates would decrease w/reactor in operation.
ZIEGLER.L J Affiliation Unknown 80/10/27 1p 07465 226

B01090160 Urges facility restart Reactor had one of best safety records in nation Nation needs nuclear power to meet energy crisis
KUNOER.B A Affiliation Unknown 80/11/10 1p 07309 001.

B01090155 Comments that facility should be restarted Reactor has excellent safety record
JANIB.R M Affiliation Unknown 80/11/15 2pp 07309 001

B01090151 Expresses opinion that facility should be put in svc Other energy sources are too expensive
KELLER.D E Affiliation Unknown 80/11/17 1p 07309 001.

B01090181 Comments that facility should be restarted Local state & natl economy will benefit
BAMIELS.M A , OAMIELS.C M , OAMIELS.D D Affiliation Unknown.
80/11/10 1p 07309 001

B01090089 Endorses facility return to svc Reactor is safe & could contribute to area economy.
DIFFENDERFER Affiliation Unknown 80/11/19 1p. 07309 001

B01200261 Supports TMI-1 restart based on economic & energy requirements.
ISOLA.S C Affiliation Unknown 80/12/03 1p 07486 147.

B010100155 Responds to 790911 ltr inquiring why restart 18 to 24 months ASLB hearing began 801019 Forw
MUREO-0680 providing NRC evaluation of licensee com
w/concerns as of June 1980 w/o encl
EISEN4JT.D G Division of Licensing 80/12/09 1p

--B010100163 Requests reasoning behind estimate of 18
make decision on TMI-1 restart Util & patrons must
costly replacement power
ANORECH.P A Affiliation Unknown 79/09/11. 1p

B01200252 Urges immediate facility restart.
PORTER.W.E Affiliation Unknown 80/12/09 1p

B01200271 Urges immediate facility restart
TREDALE.J.R , TREDALE.A A Affiliation Unknown.
07187 001.

B01060036 Responds to B00312 ltr re TMI NRC has amer
upgrade requirements for emergency planning Public
will determine whether TMI-1 should be operated
SAYDER.B J TMI Program Office 80/12/12 3pp

B01200257 Urges facility restart because of low cost
energy
HERBICK.R.H Affiliation Unknown 80/12/12. 1p

B01200239 Urges facility restart due to energy prob
LASH.N Affiliation Unknown 80/12/16 1p 07187 001

B01200234 Opposes TMI-1 restart because of proximity
TMI-2 & shared storage pool
KLUGER.M Affiliation Unknown 80/12/17. 1p 07187 001

B01200264 Urges restart of TMI-1 only after ASLB det
GCRHLEY.J E Affiliation Unknown 80/12/17 1p.

B01200189 Supports facility shutdown
OETULLIO.N Affiliation Unknown 80/12/18 1p.

B01200192 Expresses concerns re TMI-1 restart
SCOTT.P Affiliation Unknown 80/12/18 1p 07187 001

B01200194 Opposes facility restart prior to complet
process.
Affiliation Unknown 80/12/18 1p 07187 001

B01200198 Opposes facility restart prior to complet
process
RATH.T Affiliation Unknown. 80/12/18. 1p 07187 001

B01200199 Opposes facility restart prior to complet
process
MORR.B Affiliation Unknown 80/12/18. 1p. 07187 001

B01200202 Opposes facility restart
MADDA.M S Affiliation Unknown 80/12/10 1p. 07187 001

B01200205 Opposes facility restart
EASEN.S Affiliation Unknown 80/12/18. 1p 07187 001

B01090165 Urges facility restart Dividend checks fr
not been received & value of stock has decreased.
RECHITTO.A J Affiliation Unknown. 80/12/19 1p

B01200261 Opposes facility restart
MAYOAS Affiliation Unknown. 80/12/22. 1p 07187 001

B01090630 Responds to B01118 ltr to President Cert
restart Restart hearing commenced on 801015 JA Cen
B01118 ltr to President B01006 ltr to util & util
response encl
GENTON.H R Office of Nuclear Reactor Regulation.
80/12/23. 3pp 07476 059

B010600324 Recommends restarting TMI-1 because of ex
record & relatively low cost of nuclear energy
SANDERS.M I Affiliation Unknown 80/12/24. 1p

--B010600330 Comments that TMI-1 should be restarted
overblown
EBY.U Affiliation Unknown 80/12/24. 1p

0533 Comments that TMI-1 should be restarted for good of country.
 Chamber & stockholders
 MEYER E Affiliation Unknown 80/12/21 1p

0538 Forwards ltr from citizen re facility restart TMI-1 should
 shut down permanently & Congress should emphasize to NRC
 action is not committed irrevocably to nuclear power
 LINDH B House of Rep 80/12/18 2pp

0543 Comments that NRC has delayed too long in granting util
 mission to resume operation
 BURMAN W Affiliation Unknown 80/12/26 1p

0545 Comments that facility should be restarted Nuclear power is
 necessary to provide energy needs
 EBER J J Affiliation Unknown 80/12/29 1p

0551 Comments that facility should be restarted as shutdown of
 it has driven util to brink of bankruptcy
 EYER J J Affiliation Unknown 80/12/24 1p

0554 Comments that facility should be restarted pending
 finalization of safe operation
 ERLICH E Affiliation Unknown 80/12/25 1p

0560 Comments that facility should be restarted.
 KIM J L Affiliation Unknown 80/12/16 1p

0563 Comments that facility should be restarted Shutdown is too
 long
 EBER B Affiliation Unknown 80/12/29 1p

0568 Comments that facility should be restarted Nation needs
 energy alternatives
 BLANK H J Affiliation Unknown 80/12/30 1p

0575 Responds to 801126 ltr re Lebanon Valley Chamber of Commerce
 ltr to meet w/Commission to discuss facilities
 operation issues re Unit 1 and in adjudication Chamber
 and that Commission member could meet re Unit 2 cleanup
 EYER J F Commissioners 80/12/24 1p 07462-025

0579 Urges facility restart Util needs to operate reactor to
 avoid financial condition
 EYER J F Affiliation Unknown 80/12/27 1p 07442-234

0580 Urges restart of TMI-1
 EYER J F Affiliation Unknown 80/12/29 1p 07465-229

0581 Opposes facility restart prior to completion of hearing
 on accident
 Affiliation Unknown 80/12/29 1p 07187-001

0585 Responds to FOIA request for seven categories of NRC
 documents. Forwards computer printout indicating pertinent
 documents & other documents published 1977-80 & documents in
 response to request
 EYER J F Division of Rules and Records 80/12/31 2pp.

0586 Confirms that encl listed documents responding to FOIA
 requests were received by law firm representative
 EYER J F Division of Rules and Records 80/12/18 3pp.

0587 Confirms that encl listed documents responding to FOIA
 requests were received by law firm representative
 EYER J F Division of Rules and Records 80/12/08 7pp
 6:139

0592 Confirms that encl listed documents responding to FOIA
 requests were received by law firm representative
 EYER J F Division of Rules and Records 80/12/02 3pp

0593 Confirms that listed documents responding to FOIA requests
 received by law firm representative
 EYER J F Division of Rules and Records 80/11/24 21pp
 6:149.

0595 Confirms that listed documents responding to FOIA requests
 received by law firm representative
 EYER J F Division of Rules and Records 80/11/10 5pp.
 6:170.

0597 Confirms that listed documents responding to FOIA requests
 received by law firm representative
 EYER J F Division of Rules and Records 80/11/04 2pp
 6:175

--BIO1260081 Confirms that listed documents responding to FOIA requests
 were received by law firm representative Computer printout of
 NUREG-0578 published 1977-80 & 'Std Subj Identification
 Numbering Sys 1651753 Basic Code' & Revision 1 encl
 CARR J C Division of Rules and Records 80/10/31 204p
 07506-177

BIO1060023 Expresses concern re use of nuclear power Proposes solar
 research & development as alternative energy resource
 VOGLER T R Affiliation Unknown 81/01/02 3pp 07309-001

BIO1090093 Comments that facility should be restarted Reactor is
 relatively safe & nuclear power is needed
 CECCHOLI A Affiliation Unknown 81/01/02 1p 07309-001

BIO1200172 Urges restart of TMI-1 to reduce dependence on foreign oil
 LAGERMAN A T Affiliation Unknown 81/81/03 1p 07187-001

BIO1090056 Comments that facility should be restarted to reduce
 electric bills Marked-up page of NUREG-0578 encl
 TIERNEY R E Affiliation Unknown 81/01/05 3pp 07309-001

BIO1090092 Comments that facility should be restarted Reactor is
 victim of discrimination, because other units are allowed to
 operate while mods are in progress. Restarting plant would
 lower electric bills significantly
 KAYHIE B Affiliation Unknown 81/01/05 2pp 07309-001

BIO1180310 Urges facility restart TMI shutdown impacts writer as
 taxpayer, ratepayer & stockholder
 RUGER B R C Affiliation Unknown 81/01/05 1p 07465-227

BIO1180324 Urges restart of TMI-1 & repair & use of TMI-2
 LAGERMAN A T Affiliation Unknown 81/01/05 1p 07465-228

BIO1180333 Urges restart of TMI-1
 OLEN F Affiliation Unknown 81/01/05 1p 07465-230

BIO1180338 Urges restart of TMI-1 to reduce US dependence on foreign
 energy sources
 OLEN F Affiliation Unknown 81/01/05 1p 07465-231

BIO1180345 Urges restart of TMI-1 so customers will receive
 uninterrupted energy supplies & investors will receive fair
 return on capital
 MILROY H V Affiliation Unknown 81/01/05 1p 07465-232

BIO1200179 Urges restart of TMI-1 since facility was undamaged by TMI-2
 accident
 RICK R B Affiliation Unknown 81/01/05 1p 07486-149

BIO1200255 Urges facility restart Certificate of Svc encl
 OLENSKY K Affiliation Unknown 81/01/05 4pp 07476-350

BIO1180353 Opposes immediate restart of TMI-1, Certificate of Svc encl
 BENTZ K Affiliation Unknown 81/01/07 3pp 07465-235

BIO1210293 Responds to encl 800916 ltr to President Carter re effect of
 TMI accident on electricity costs & need for federal
 assistance Resumption of TMI-1 operation is subj of hearing.
 White House 800703 ltr to PA Public Util Commission encl
 BENTON H R Office of Nuclear Reactor Regulation, Director
 81/01/07 6pp 07187-001

BIO1210298 Responds to encl 800915 ltr to President Carter re effect of
 TMI accident on electricity costs & need for federal
 assistance Resumption of TMI-1 operation is subj of hearing.
 White House 800703 ltr to PA Public Util Commission encl
 BENTON H R Office of Nuclear Reactor Regulation, Director
 81/01/07 4pp 07488-207

BIO1210309 Responds to encl 800926 ltr to President Carter re effect of
 TMI accident on electricity costs & need for federal
 assistance Resumption of TMI-1 is subj of hearing. White
 House 800703 ltr to PA Public Util Commission encl
 BENTON H R Office of Nuclear Reactor Regulation, Director
 81/01/07 3pp 07488-211

BIO1210310 Responds to encl 800929 ltr to President Carter re effect of
 TMI accident on electricity costs & need for federal
 assistance Resumption of TMI-1 is subj of hearing. White
 House 800703 ltr to PA Public Util Commission encl.
 BENTON H R Office of Nuclear Reactor Regulation, Director
 81/01/07 11pp 07488-214

BIO1260163 Comments on decision not to recognize psychological stress
 as restart issue
 HERMAN A A Affiliation Unknown 81/01/08 1p 07486-150

--B101200303 Urges restart of TMI-1 due to energy problems.
RACALE, H. Affiliation Unknown 80/12/21. 1p. 07477 228.

B101210581 Notifies of change of address for Citizens for Safe Environ
SCUTTHARD, V. Citizens for Safe Environment 81/01/08 1p.
07448 361

B101200183 Urges restart of TMI-1 because of cost to consumers Requests
reimbursement for fuel adjustment costs
WESB, J. C. Affiliation Unknown 81/01/09. 2pp. 07486 151.

B101230073 Supports facility restart
DECECCO, J. H. Affiliation Unknown 81/03/07 1p. 07811 333

B101230054 Supports facility restart
OSTERMIER, D. Affiliation Unknown 81/01/10. 2pp. 07308 001

B101280249 Supports facility restart
SHIPMAN, C. H. Affiliation Unknown 81/01/10 1p. 07553 053

B101230118 Supports facility restart Certificate of Svc encl.
DIXON, E. H. Affiliation Unknown 81/01/12 4pp. 07312 011

B101280521 Responds to 801208 ltr to Chairman Ahearne expressing
concern re delay of TMI restart Resumption of operation is
subj of ASLB hearing NRC committed to fair & thorough
decision
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
01/01/13 1p. 07550 294

--B101280625 Expresses concern re delay of TMI restart
FAULKNER, R. Affiliation Unknown 81/01/13 1p. 07550 295

B101280235 Opposes facility restart
MCKER, M. H. Affiliation Unknown 81/01/15 1p. 07398 001.

B101230079 Supports facility restart
RECHINSON, E. Affiliation Unknown 81/01/19 1p. 07308 001

B101280238 Opposes facility restart Certificate of Svc encl
BERMAN, A. A. Affiliation Unknown 81/01/19 4pp. 07308 001

B101280244 Supports facility restart
BLANDHILL, A. B. Affiliation Unknown 81/01/19 1p. 07308 001.

B101200695 Responds to 801210 ltr urging TMI-1 restart. Facility is shut
down in accordance w/NRC 790702 order requiring hearing
prior to restart Hearing commenced on 801015 & will be
completed in mid-1981.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
81/01/19 2pp. 07584 149.

I Financial information

B101210144 Forwards SEC Form 10-Q Quarterly Financial Rept & supporting
mgt comments in response to NRC 790921, 1109 & 830811
requests for info re significant financial developments
affecting utility in restart proceeding
CANDON, V. H. General Public Utilities 80/11/26 3pp.

--B101210154 Quarterly Financial Rept Repl 1980 & supporting mgt
comments.
* General Public Utilities 80/11/14 44pp.

B101070290 Requests response to items 3, 4, 5, 6, 7, 8, 9 of NRC
800811 request for addl info NRC must have responses to
complete testimony on financial qualifications issue. Delay
could lead to delay in TMI-1 restart hearing completion
REID, R. W. Operating Reactors Branch 4 80/12/17. 4pp. 07413 293.

B101210594 Submits changes to draft response re TMI-1 restart
proceeding financial info General Public Util currently
revising financial forecast, incorporating mgt changes &
reflecting 1981 spending levels to be available by 810228.
HAKILL, H. D. Metropolitan Edison Co 81/01/13 2pp. 07489 260

Proprietary info
HOFER, J. C. Office of the Secretary of the Commission
2pp. 07585 340

B101300765 Notifies of ACRS 801204-06 meeting in Washing
proposed operation of TMI-1, new safety concepts for
nuclear facilities waste storage & disposal Portions
meeting may be closed to protect proprietary info
HOFER, J. C. Office of the Secretary of the Commission
7pp. 07584 242

B101070538 Forwards ACRS 801211 status rept re review
REID, R. W. Operating Reactors Branch 4 80/12/18

--B101070546 Submits status rept on facility restart A
meeting on 801204-06, restart was discussed w/ARC, u
General Public Util Nuclear Group Restart was dis
800131-0201 & 1120-29 subcommittee meetings
PLESSE, M. G. ACRS - Advisory Committee on Reactor
80/12/11 4pp. 07403 333

P. Operating license stage documents & correspondence

B101100065 Ack receipt of util 801017 ltr providing re
onance-through steam generator auxiliary feedwater not
thermal sleeve/collar weld attachment
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operat
Support Branch 80/11/05 1p. 07444 308.

B101100234 Ltr to all licensees (except BEP licensees)
Revision 1 of inservice surveillance requirements for
submitters under STS License amend application adding
Tech Specs to App A should be submitted within 120 d
EISENHUT, D. G. Division of Licensing 80/11/20. 1p

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7
STS submeter inservice insp requirements.
* Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applic
summary of 801112 meeting re implementation of guide
Unresolved Safety Issue A-12, "Potential for Low Fra
roughness & Lamellar Tearing on Component Supports"
EISENHUT, D. G. Division of Licensing 80/11/26 8p

B101080007 Discusses license amends re fuel handling b
safety feature & addl storage capacity for low activ
solid redwastes Addl info required for resolution of
items
GAMMILL, W. P. Effluent Treatment Systems Branch 80
03891 231

B101210445 Forwards responses to questions on Rule 50
Updating of FSARs" & FR notice of final rule. BEP pla
not comply w/rule until program is complete. Non-BEP
must comply within specified time frame
EISENHUT, D. G. Division of Licensing 80/12/15 13

B101050039 Requests to register as user of Model CNS1
radioactive matl shipping cast.
HOVEY, Q. H. Metropolitan Edison Co 80/12/18 2pp

B101270580 Evaluates NUREG-0680, Suppl 1 re TMI-1 rest
no significance to waste mgt activities
JOHNSON, T. C. Low Level Waste Licensing Branch, 80/
07309 001

B101130053 Forwards Review of TMI-1 Control Room From
Viewpoint - Certificate of Svc encl
BAXTER, T. A. Metropolitan Edison Co BAXTER, T. A. S
Potts & Frowbridge. 81/01/05 6pp. 07448 346

--B101130056 "Review of TMI-1 Control Room From Human
* General Public Utilities 80/12/31. 155pp. 0

B101300203 Responds to 761230 request for Tech Spec re
Classification statement to reporting requirements w/
considered as part of 780508 request for overall rev
App. B Request re change of bases does not require am
REID, R. W. Operating Reactors Branch 4. 81/01/06.

30027 Notification of 810116 meeting w/uttl in Bethesda, MD to discuss implementation of NUREG-0737 items Certificate of enc1
/ER, H Operating Reactors Branch 4. 81/81/09 4pp 07463 205

30312 Notification of 810116 meeting between NRC & uttl to discuss requirements re NUREG-0737. Response to NUREG will be submitted during wk of 810119
LL, H, D. Metropolitan Edison Co 81/01/09 1p 07500 157

0379 Forwards uttl 801231 ltr to State of PA requesting waiver permit requirements of Dam Safety Encroachment Act
LL, H, O. Metropolitan Edison Co 81/01/13 6pp 07489 064

0507 Forwards addl safety analysis justifying Tech Spec Change Request 90, modifying reactor vessel internal vent surveillance to permit Cycle 9 operation w/o ending of surveillance
LL, H, D. Metropolitan Edison Co 81/01/14 6pp 07489 004

0507 Forwards changes & addition to Tech Spec Change Request 34A graphical errors were noted & corrected. List of tables
LL, H, O. Metropolitan Edison Co 81/01/19 2pp 07532 063

260509 Revised proposed Change 34A to Tech Specs, Sections 3.4 & 6, radioactive effluent instrumentation
Metropolitan Edison Co 01/01/19 21pp. 07532 065.

0592 Documents that actions taken per NUREG-0732, control room on reviewers in progress & slated for completion prior restart identifies exceptions. Discusses plans re-empting General Public Util design review suggestions
LL, H, D. Metropolitan Edison Co 81/01/21 3pp 07548 097

3648 Requests extension to 810915 to submit final rept re third on surveillance test of reactor containment bldg
LL, H, D. Metropolitan Edison Co 81/01/21 1p 07183 001

3674 Responds to NRC 800815 ltr re automatic opening of spheric dump valves during failure of nonnuclear instrumentation or integrated control sys. Administrative actions & rods will be completed prior to restart
LL, H, O. Metropolitan Edison Co 01/01/21 3pp. 07545 224.

1593 Forwards response to NRC 801125 request re NUREG-0737 comments. Consists of tabulation addressing items ruled for completion. Procurement factors may impede. Also addl info re emergency feedwater sys items enc1
D, R, C. Metropolitan Edison Co 81/01/23 26pp 07573 241

1657 Forwards application for amend of License DPR-50 submitted w/ Tech Spec Change Request 77
LL, H, D. Metropolitan Edison Co 01/01/26 1p 07566 333

90662 Application for amend of License DPR-50 submitted as Tech Spec Change Request 77 revising Tech Specs for Fire Protection, Certificate of svc enc1
LL, H, D. Metropolitan Edison Co. 81/01/26 3pp. 07566 334

90666 Tech Specs 3 1B & 4 1B re Fire protection & fire protection
Metropolitan Edison Co 81/01/26 18pp. 07566 337

755 Application for Tech Specs Change Request 90, amending w/ DPR-50 Certificate of Svc & Class III fee enc1.
LL, H, D. Metropolitan Edison Co 01/01/26 3pp 07576 006

90759 Proposed Tech Specs Change 90, amending OL & Apps A & B of w/ DPR-50 to establish General Public Utility Nuclear as sole entity authorized to operate facility.
Metropolitan Edison Co. 81/01/26 18pp. 07576 009

90762 Order authorizing organization of General Public Utility Nuclear Corp as wholly owned subsidiary for mgt & operation nuclear plants
SECURITIES & EXCHANGE COMMISSION 80/09/15 3pp. 76:027.

--8101290771 Request that NJ Board of Public Utilities dismiss for lack of jurisdiction uttl & General Public Utility Nuclear Corp proposed operating agreement in alternative agreement should be approved
BROKAW, R O Jersey Central Power & Light Co BROKAW, R O Bureau, R O 80/04/11 7pp 07576 130

8101300488 Forwards page inadvertently omitted from 810123 submitted in response to NUREG-0737 requirements
* Metropolitan Edison Co 81/01/29 2pp 07587 030

0 Inspection reports, IE Bulletins & correspondence

8101060632 Forwards Phase 2 submittal responding to item 26 of IE Bulletin 80-11, "Masonry Well Design"
HUXILL, H D Metropolitan Edison Co 80/11/17 1p 07399 362

--8101060637 "Re-evaluation of Safety-Related Concrete Masonry Walls"
* General Public Utilities - CPU Service Corp 80/11/17 5pp 07400 001

--8101060641 "Criteria for Re-evaluation of Concrete Masonry Walls"
* Computech Engineering Services, Inc 00/10/31 17pp 07400 007

--8101060652 "Justification for Criteria for Re-evaluation of Concrete Masonry Walls"
* Computech Engineering Services, Inc 00/10/31 32pp 07400 025

--8101060657 "Spec Masonry, 8P-9714"
* Oilbert/Com-onwealth Cos 69/08/08 15pp 07400 002

8101080103 Forwards Revision 1 to uttl 801031 response to IE Bulletin 79-010, "Environment Qualification of Class IE Equipment"
Calculation to find max temp of viton for 40-gr svc enc1.
HUXILL, H D Metropolitan Edison Co 80/11/17 3pp. 07419 245

8101070428 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required
GRJER, D H Region 1, Philadelphia, Office of the Director. 80/11/26 1p 07414 029

0101150148 Forwards Performance Appraisal Branch Mgt Insp Repts 90-219/79-18, 50-312/80-15 & 90-289/80-21 IE Performance Appraisal Branch mgt evaluation tree w/users guide for chart, list of licensee recipients of rept & sample ltr enc1
GRJER, D H Region 1, Philadelphia, Office of the Director. 00/12/82 2pp 07466 020

--0101150195 Performance Appraisal Branch Mgt Insp Rept 90-289/80-21 of 800707-11, 14-10, 27-31 & 0801. Noncompliance noted: licensee mgt controls were poor re nonlicensed training. Attachment A withheld (ref 10CFR2 740)
COBY, A T Region 1, Philadelphia, Office of the Director
HUNTER, D R Region 3, Chicago, Office of the Director
Region 2, Atlanta, Office of the Director 00/10/08 119pp 07308 001

8101150084 Ack receipt of 790626, 0713-0817 & 800602 ltrs on IE Bulletin 79-13 re feedwater pipe cracks. Feedwater pipe cracks unlikely. Augmented insps per IE Bulletin 79-13 & 79-13. Revision 2, may be discontinued. Safety evaluation enc1
RE10, R W Operating Reactors Branch 4. 80/12/05 1p. 07463 209

--8101150094 Ack receipt of 790626, 0713-0817 & 800602 ltrs re IE Bulletin 79-13 re feedwater pipe cracks. Feedwater pipe cracks unlikely. Augmented insps per IE Bulletin 79-13 & 79-13. Revision 2, may be discontinued. Safety evaluation enc1
RE10, R W Operating Reactors Branch 4 80/12/83 4pp 07463 210.

--8101150103 Forwards safety evaluation re feedwater pipe cracking & relief from augmented insp for TMI-1
GRAY, J R. Hearing Branch 1 80/12/05 1p 07463 214

--8101150116 Safety evaluation supporting uttl actions in response to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping"
* Commissioners 80/12/05 2pp 07463 215

81012023 Forwards IE 11/10/82 B0-44. "Installation of ECCS in
Regulator Pide While on Hot Shutdown - No written
response required
GRIER, B. H. Region 1 Philadelphia, Office of the Director
80/12/16 1p 07397 001

81012031 Response to IE Bulletin B0-23 "Failure of Solenoid Valves
May by Velcor Engineering Corp. No subv. valves used in
safety-related circuits
WALL, H. D. Metropolitan Edison Co. 80/12/17 1p 07398 001

81012045 Response to IE Bulletin B0-26 "Valve Yokes Supplied by
Malcolm Foundry Co. Inc. No subv. parts used at facility
WALL, H. D. Metropolitan Edison Co. 80/12/17 1p 07457 104

81012055 Forwards 810107 discussion re interpretation of order re
records related to engineer qualifications of electrical
equipment IE Bulletin 79-012 records specified to be in
place by 810201 out of in central location by 810201
WALL, H. D. Metropolitan Edison Co. 81/01/21 1p 07549 029

H. Personnel operating reports & related correspondence

81012046V Forwards monthly operating rept for Dec 1980
WALL, H. D. Metropolitan Edison Co. 81/01/15 2pp 07493 232

--81012047s Monthly operating rept for Dec 1980
MITCHELL, D. G. Metropolitan Edison Co. 81/01/15 4pp 07493 234

810120573 Forwards Ichthyological Associates "IMI Aquatic Study Monthly
Rept for Dec 1980
TEIT, T. R. General Public Utilities - CPU Services Corp. 81/01/22
1p 07183 001

--810120578 IMI Aquatic Study Monthly Rept for Dec 1980 - Study
performed for Met Ed
NASCAT, G. A. RAMEY, E. C. Ichthyological Associates, Inc.
81/01/22 24pp 07183 001

S Reportable occurrences, LERs & related correspondence

810100238 Forwards LER 80-019/G3L-0
WALL, H. D. Metropolitan Edison Co. 80/12/24 1p 07383 221

--810100246 LER 80-019/G3L-0 on 80126, A & 2 Battery room smoke detector
monthly surveillance test not performed. Caused by inadequate
implementation of administrative controls. Surveillance
modified
MITCHELL, D. G. Metropolitan Edison Co. 80/12/24 2pp 07383 222

810120353 Interim deficiency rept re electrical component cabinets
where frame is welded to embedded steel angles. Initially
reported 810107 Concrete failure & loss of positive
anchorage. Possible Review will be completed by 810306
BARKER, H. R. Gilbert/Commwealth Cos. 81/01/13 3pp 07487 205

810120524 PNO-IMI-B1-03 on 810116, licensee sentenced planned
activities to raise reactor coolant pressure & temp from
0 psig, 121 F to approx 340 psig & max 195 F. Activities
expected to last approx one wt
REKITT, W. HAVERKAMP, D. FASANO, A. H. IMI Program Office 81/01/16
2pp 07557 046

810120507 PNO-IMI-B1-0/A on 810118, operational & testing activities
temporarily terminated due to small leak in reactor top
piping discovered on 810117 RCS depressurized to 45 psig &
being held in that condition
HAVERKAMP, D. R. FASANO, A. H. BARRETT, L. H. IMI Program Office
81/01/19 2pp 07557 051

810120721 Forwards updated LER 78-004/01T-2
WALL, H. D. Metropolitan Edison Co. 81/01/22 1p 07549 071

--810120728 Updated LER 78-004/01T-2 on 780106 BSW identified transients
which may result in exceeding WWSR on WWSR safety limits
caused by positive difference between indicated reactor
power subtracted from actual reactor power
MITCHELL, D. G. Metropolitan Edison Co. 81/01/22 2pp 07549 072

810120540 LER 80-018 has been cancelled
Metropolitan Edison Co. 81/01/23 2pp 07575 247

8101050177 Transcript of 801204 Restart hearing in Harrisburg, PA
Pg. 7, 233-7, 533
Atomic Safety and Licensing Board Panel 80/12/04
07379 001

8101050538 Transcript of 801214 hearing in Harrisburg, PA
Restart Pg. B, 060-B, 937
Atomic Safety and Licensing Board Panel 80/12/19
07387 097

8101050034 Forwards NRC testimony in response to Sholly
Antinuclear Group Representing York Contention 3(c) BSW
801201 testimony re control room design
BARTZ, L. L. Antitrust Division 80/12/22 1p 0737

--8101050042 Transcript of HQ Ramirez & HE Prince testin
Contention 15 & Antinuclear Group Representing York
Contention 3(c) Prof qualifications & Certification
and
RAMIREZ, R. O. PRINCE, H. E. Human Factors Engineering
80/12/22 12pp 0737a 009

--8101050049 Forwards NUREG-0752 "Control Room Design Re
THI-1" & notice of availability Certificate of Bv
and
REID, R. W. Operating Reactors Branch 4. 80/12/22.
0737a 021

--8101050059 Notice of availability of NUREG-0752, "Cont
Review Rept for THI-1"
REID, R. W. Operating Reactors Branch 4. 80/12/22
0737a 024

--8101050063 CONTROL ROOM DESIGN REVIEW REPT FOR THI-1
Division of Human Factors Safety, NUREG-0752
0737a 025

8101050081 testimony of JM Christensen responding to 800306
CL-80-5, Issue 2, Antinuclear Group Representing York
Contention 4, Sholly Contention 14(b), Aamdt Contention
Chesapeake Energy Alliance Contention 13
CHRISTENSEN, J. Metropolitan Edison Co. 80/12/22. 1p

--8101050090 Testimony of PR Clark responding to 800306
Issue 7, Sholly Contention 14(d) & Antinuclear Group
Representing York Contention 4, questioning safety re
& operational advice re THI-1
CLARK, P. R. Metropolitan Edison Co. 80/12/22 12pp

--8101050098 Testimony of EF Gardner responding to 800306
Issue 2, Antinuclear Group Representing York Contention
Sholly Contention 14(b), Aamdt Contention 2 & Chesapeake
Energy Alliance Contention 13.
GARDNER, E. F. Metropolitan Edison Co. 80/12/22 1p

--8101050105 Testimony of R Wilson responding to 800306
Issue 11, Sholly Contention 14(b) & Antinuclear Group
Representing York Contention 4 re util ability to
THI-1 operation w/sufficient technical capability.
WILSON, R. Metropolitan Edison Co. 80/12/22. 25pp

--8101050111 Testimony of RC Arnold responding to 800306
Issue 2, Antinuclear Group Representing York Contention
Sholly Contention 14(a) re administrative structure
safe operation of THI-1.
ARNOLD, R. C. Metropolitan Edison Co. 80/12/22. 41p

--8101050123 Testimony of FL Kelly responding to 800306
Issue 2, Antinuclear Group Representing York Contention
Sholly Contention 14(b) & Aamdt Contention 2 Prof
qualifications & operator written exam and
KELLY, F. L. Metropolitan Edison Co. 80/12/22. 36pp

--8101050133 Testimony of HD Huxill, RJ Toolo, MJ Ross &
responding to 800306 Order CL-80-5, Issues 2, 4, 5 & 11, Aamdt C
Group Representing York Contention 4 & Sholly Contention
14(a), (b) & (c) re organization & technical resource
HUXILL, H. D., TOOLO, R. J., ROSS, M. J. Metropolitan Edison
80/12/22. 36pp. 07381 154

--8101050150 Testimony of RL Long, RA Knief, BL Newton &
responding to 800306 Order CL-80-5, Issues 2, 4, 5 & 11, Aamdt C
2, Chesapeake Energy Alliance 13 & Antinuclear Group
Representing York 4 & Sholly Contentions 14(b) & (c)
LONG, R. L., KNIEF, R. A., NEWTON, B. L. Metropolitan Edison
80/12/22 56pp 07381 210

0567 Transcript of 801222 hearing in Harrisburg, PA re restart
 2,938-9,108
 Atomic Safety and Licensing Board Panel 80/12/22 170pp
 16 030

0563 Transcript of 801223 hearing in Harrisburg, PA re facility
 art Pp 9,109-9,313.
 Commissioners. 80/12/23 208pp 07387 296

0558 Transcript of 801224 hearing in Harrisburg, PA re facility
 art Pp 9,314-9,390
 Atomic Safety and Licensing Board Panel 80/12/24 80pp
 17 182

0049 Transcript of 810106 hearing in Harrisburg, PA re restart
 ,391-9,329
 Atomic Safety and Licensing Board Panel 81/01/06 140pp
 7 001

0247 Transcript of 810107 restart hearing in Harrisburg, PA
 ,391-9,329
 Atomic Safety and Licensing Board Panel 81/01/07 193pp
 5:026

0249 Transcript of 810108 restart hearing in Harrisburg, PA
 ,391-9,329
 Atomic Safety and Licensing Board Panel 81/01/08 284pp
 9:001

0483 Transcript of 810114 hearing in Harrisburg, PA re restart.
 D.005-10,215
 Atomic Safety and Licensing Board Panel 81/01/14 212pp
 9:268

3415 Transcript of 810115 hearing in Harrisburg, PA re restart
 D.216-10,446
 Atomic Safety and Licensing Board Panel 81/01/15 232pp
 5:228

3221 Forwards LE Phillips supplementary testimony to testimony
 on 801201 re reactor water level instrumentation.
 HIN:J.M. Hearing Branch 3 81/01/16 1p 67490.051

810225 Supplementary testimony of LE Phillips to testimony filed on
 1201 re UCB Contention 7, Sholly Contention 5(b) &
 sinuclear Group Representing York Contention 5(b)
 ILLIPS:LE Core Performance Branch. 81/01/16 5pp
 190.052

3359 Forwards R Long, R Keaton & WS Lee testimonies re licensee
 response to TMI-2 accident per tenth issue identified by
 action 800306 order
 H:EL Shaw, Pittman, Potts & Troubridge 81/01/19 3pp
 1:042

70361 Transcript of RW Keaton & RL Long testimony re mgt response
 TMI-2 accident (CL1-80-5, issue 10).
 H:MR W. L. LONG, R. L. Metropolitan Edison Co. 81/01/19 32pp
 144 045

70367 Transcript of WS Lee testimony re mgt response to TMI-2
 10ent (CL1-80-5, issue 10).
 H:MR Metropolitan Edison Co 81/01/19. 14pp 07544 077

405 Transcript of 810120 testimony of B Levy in response to UCB
 ntion 13 Pp 1-21. Certificate of Svc encl
 8. Atomic Safety and Licensing Board Panel. 81/01/20. 35pp.
 :126

447 Transcript of 810120 hearing in Harrisburg, PA re restart.
 ,447-10,614.
 omic Safety and Licensing Board Panel. 81/01/20. 167pp
 :273.

431 Transcript of 810121 hearing in Harrisburg, PA re restart
 ,615-10,625
 omic Safety and Licensing Board Panel. 81/01/21. 212pp
 :216

435 Transcript of 810122 hearing in Harrisburg, PA re restart.
 ,826-10,936
 omic Safety and Licensing Board Panel. 81/01/22. 111pp
 :250.

--8101270729 Transcript of W Wegner testimony re licensee mgt capab
 & technical resources, which apply to Issues 1,2,4,5,6,7,10 &
 11 of Commission 800306 CL1-80-5 order & intervenor
 contentions
 WEGNER, W. Basic Energy Technology Associates WEGNER, W
 Metropolitan Edison Co 81/01/26 41pp 07567 005

--8101290734 Response to ASLB 830812 questions re 800627 10,000 ga
 spill at TMI-1 Spill caused by operator error Employees
 briefed on incident & procedures for transferring inverters
 revised Spill had no impact on TMI-2
 Metropolitan Edison Co 81/01/26 10pp. 07567 047

--8101290737 Brain down & maintain RCU level between 314 ft 10 Incl
 315 ft 3 inches Incorporates & supersedes but does not
 alter safety evaluation of SUP-1-80-29 Supporting
 documentation encl.
 SHIPMAN, H H. DULRID, R W. TGOLE, Y Metropolitan Edison Co
 80/09/30 59pp 07567 057

8101300371 Transcript of 810127 restart hearing in Harrisburg, PA
 Pp 10,937-11,095
 Atomic Safety and Licensing Board Panel 81/01/27 160pp
 07576 152

8101300395 Transcript of 810128 restart hearing in Harrisburg, PA
 Pp 11,096-11,286
 Atomic Safety and Licensing Board Panel 81/01/28 191pp
 07577 051

U Congressional/Executive Correspondence

8101090019 Responds to 801222 ltr requesting views re General Publ
 Utils 801201 ltr to NRC urging TMI-1 restart prior to end of
 hearings Commission has issued order inviting comments on
 issue by 810106 & NRC response will be forwarded
 KAPHEBER, C Office of Congressional Affairs 81/01/06 1p
 07441 101

--8101090027 Requests views re General Public Utils 801201 ltr to
 urging TMI-1 restart prior to end of hearings
 MILLER, H A Senate 80/12/22 1p. 07441 182

V Operator Examinations

8101030081 Testimony of JH Christensen responding to 800306 Order
 CL1-80-5, Issue 2, Antinuclear Group Representing York
 Contention 4, Sholly Contention 18(b), Namdt Contention 2 &
 Chesapeake Energy Alliance Contention 13
 CHRISTENSEN, J Metropolitan Edison Co 80/12/22 16pp 07281

--8101090157 "Rept of TMI-1 Operator Accelerated Retraining Progra
 Review Committee"
 CHRISTENSEN, J. OARDNER, E. F. KINEL, W R Metropolitan Edison
 80/06/01 188pp 07381 270

8101290593 Forwards response to NRC 801125 request re NUREG-0737
 requirements Consists of tabulation addressing items
 scheduled for completion Procurement factors may impede
 schedule Addl info re emergency feedwater sys items encl
 ARNOLD, R C Metropolitan Edison Co 81/01/23 26pp 07573 24

DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP hol
 & CP applicants Revised radiological emergency response
 plans must be submitted by licensees within 60 days of
 810102 & by applicants as part of FSAR.
 EISENHUT, D O. Division of Licensing 80/11/13 2pp

810130139 Advises of provisions of 10CFR50, App R, that are applica
 to fire protection Features of facility FR notice & summary
 of staff requirements to resolve open items encl.
 EISENHUT, D O Division of Licensing. 80/11/24 4pp. 07308 00

DOCKETED ITEMS

8101070166 Notifies of receipt of enclosure of Plymouth, PA 801022 ltr to utility objecting to exclusion from local emergency planning efforts. NRC has requested FEMA review of local planning efforts for facility.
IPPOLITO, T A Operating Reactors Branch 2 80/12/08 4pp 07414 249

8101095096 Forwards fire protection review Proposed mode re items 3, 1, 19, 3, 2, 4, & 3, 2, 8 acceptable.
IPPOLITO, T A Operating Reactors Branch 2 80/12/13 6pp 07393 240

G. Adjudicatory correspondence

8101000379 Forwards NRC 810113 order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required.
IPPOLITO, T A Operating Reactors Branch 2 81/01/13 3pp 07386 187

--8101000389 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required. Mode must be installed by 810331.
EISENHUT, D O Division of Licensing 81/01/13 7pp 07386 190

J. Insurance & indemnity information

8101060565 Forwards Endorsements 42 & 53 to MAELU Policy MF-58 & AN1 Policy MF-188, respectively.
FOULSHAM, P A Boston Edison Co 80/11/14 6pp 07399 160

P. Operating license stage documents & correspondence

8101100035 Immediate Action Ltr 80-49 confirming 801117 telcon re IMI Task Action Plan Category A requirements. Lists actions until will implement Request confirmation.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/18 2pp 07444 303

8101100234 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for scrubbers under STS license amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28, 8 3/4 7-3 & 7-a & 6-17 to STS scrubber inservice insp requirements.
* Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Smaller Tearing on Component Supports".
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101190113 Ltr to all BWR licensees forwarding 801201 generic safety evaluation re BWR steam discharge sys. Recommends short-term actions necessary to assure safe operation of CE BWRs pending permanent design changes.
EISENHUT, D O Division of Licensing 80/12/09 2pp 07183 001

--8101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs. Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl.
* Division of Licensing 80/12/01 212pp 07183 001

8101070162 Forwards request for addl info to complete review of uttl 600327 submittal re containment vent & purge valve operability. Info required re 20-inch butterfly valve assembly mods & seismic qualification.
IPPOLITO, T A Operating Reactors Branch 2 80/12/10 4pp 07414 245

8101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing 80/12/15 13pp

8101070387 Submits supplemental info to 801013 response to NRC 600331 ltr. Comments re overtime policy found too restrictive.
MORIS, A V Boston Edison Co 80/12/31 2pp 07414 730

8101090045 Responds to NUREG-0737 Provides info re shift technical advisor guidance for evaluation & development of procedures for transients & accidents, procedures for feedback of operating experience & training for mitigating core damage.
MORIS, A V Boston Edison Co 81/01/05 33pp 07441 082

8101190291 Submits notarized statement omitted from 810105 ltr, re ICCFRSD 341F.
MORIS, A V Boston Edison Co 81/01/09 1p 07475 337

8101000379 Forwards NRC 810113 order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required.
IPPOLITO, T A Operating Reactors Branch 2 81/01/13 3pp 07386 187

--8101000389 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required. Mode must be installed by 810331.
EISENHUT, D O Division of Licensing 81/01/13 7pp 07386 190

8101270690 Forwards addl info in response to NUREG-0737 requirements re containment isolation dependability, ECCB outage rept & auto switchover of reactor core isolation cooling.
MORIS, A V Boston Edison Co 81/01/22 34pp 07543 018

O. Inspection reports, IE Bulletins & correspondence

8101070390 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs in Terry Turbine Steam Inlet Flange." No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 095

8101050140 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for BWR Discharge Vol at Dresden Unit 2." No response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07377 229

8101090227 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No subg parts in use or planned for use at facility.
MORIS, A V Boston Edison Co 80/12/05 1p 07430 353

8101060131 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Screen Capability." No response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07397 345

8101070052 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 151 Control Rode to Fully Insert During BWR at BWR." No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/18 1p 07414 023

8101100997 Forwards IE Bulletin 80-29, "Operating Problems w/Target Rock Safety-Relief Valves at BWRs." Written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/19 1p 07449 159

R. Periodic operating reports & related correspondence

8101210470 Forwards monthly operating rept for Dec 1980.
MACHON, R D Boston Edison Co 81/01/06 1p 07493 238

--8101210470 Monthly operating rept for Dec 1980.
WHITNEY, O O Boston Edison Co 81/01/06 8pp 07493 239

B. Reportable occurrences, LERs & related correspondence

8101080356 Forwards LER 80-092/03L-0.
MACHON, R D Boston Edison Co 80/12/29 1p 07420 334

--8101080368 LER 80-092/03L-0 on 801129 reactor water cleanup pumps tripped & valve M01201-2 could not be remotely operated. Caused by burned-out OE control relay Model CR120A04002AA & blown MCC panel fuse for M01201-2 control circuit.
MCLOUGH, L H M Y Boston Edison Co 80/12/29 1p 07420 335

665 LER 80-093/03L-0 on 801213, Walworth Co reactor water cleanup
and isolation valve MD 1201-5 closed late Cause not
d Valve rechecked, stem lubricated & closure retimed
CHLIN, M T Boston Edison Co 81/01/12 1p 07474 059

6 Forwards LER 80-094/04T-0
R D. Boston Edison Co 81/01/14 1p. 07471:273

673 LER 80-094/04T-0 on 801229, lab repl indicated excessive
retention of I-131 in milk sample collected on 001120
1 by Chinese weapons test Consumption of milk poses no
t to health of public
CHLIN, M T Boston Edison Co 81/01/13 1p 07471:274

4 Forwards LER 80-095/03L-0
R O. Boston Edison Co 81/01/19 1p 07531 140

647 LER 80-095/03L-0 on 801209, fire brigade not summoned when
ical fire occurred in security bldg mechanical room
1 by personnel error Personnel instructed of necessity
flow procedures for summoning brigade
CHLIN, M T Boston Edison Co 81/01/19 1p 07531 141

ur Examinations

9 Responds to NURE0-0737 Provides info re shift technical
guidance for evaluation & development of procedures
sidents & accidents, procedures for feedback of
ing experience & training for mitigating core damage.
A V Boston Edison Co 81/01/05 33pp. 07441 002

295 ZION NUCLEAR POWER STATION, UNIT 1

ty, medical, emergency & fire protection plans

7 Ltr to all licensees of operating reactor plants, CP holders
licants Revised radiological emergency response
ust be submitted by licensees within 60 days of
e, by applicants as part of FSAR
R O Division of Licensing 00/11/13 2pp

3 Advises of provisions of 10CFR50, App R, that are applicable
protection features of facility FR notice & summary
requirements to resolve open items encl.
R O Division of Licensing 80/11/24 6pp 07447 174

142 Advises of typographical error in effective date of 801124
correct date of 810217 to be published in FR in near

UT, D O Division of Licensing 80/11/25 1p 07447:180

atory correspondence

1 Forwards revised order for mod of license, correcting refs in
order Hearing date also revised
R O. Division of Licensing 80/09/19 2pp 07444 135

80 Revised order amending Licenses DPR-39 & DPR-40 info
tting by IE Bulletin 79-018 must be submitted to IE
101.

UT, D O Division of Licensing 80/09/19 6pp. 07444: 137.

correspondence

9 Responds to Nov 1980 ltr to President Carter re containment
e cracks at facilities No cracks that will leak
ivity exist.
R O. Division of Licensing. 81/01/02. 5pp. 07471:153

ce & indemnity information

1 Forwards guarantee of payment of deferred premiums for 1980
Commonwealth Edison Co 81/01/05 1p. 07442 073.

4 Forwards Endorsements 125 & 126, 65 & 66, 93 & 94, & 13 & 14
Policies NF-43, NF-187, NF-201 & NF-253, respectively
Commonwealth Edison Co 81/01/21. 13pp. 07183 001

7 Forwards Endorsement 4 to Binders EB-1, EB-2, EB-3, EB-29,
-42 & EB-43 evidencing secondary financial
on
Commonwealth Edison Co 81/01/21. App.

P Operating license stage documents & correspondence

8101100581 "RELAP4/4007 Developmental Checkout Zion," code development
checkout rept
REYDUN, O T L Idaho National Engineering Laboratory FIN A-6052
8101100581 80/05/31 106pp 07445 220

8101100674 Forwards revised order for mod of license, correcting refs in
800829 order Hearing date also revised
EISENHUT, D O Division of Licensing 80/09/19 2pp 07444 135

--8101100680 Revised order amending Licenses DPR-39 & DPR-48 info
requesting by IE Bulletin 79-018 must be submitted to IE
by 801101
EISENHUT, D O Division of Licensing 80/09/19 6pp. 07444: 137

8101100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under STS License amend application adding model
Tech Specs to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 20, B 3/4 7-5 & 7-6 & 6-17 to
STO snubber inservice insp requirements
Division of Licensing 80/11/20 10pp.

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101140849 Requests that util propose Tech Specs changes to require 23
ft of water above reactor vessel flange to assure fuel
assemblies would be covered at all times during fuel
movement
VAROA, S A Operating Reactors Branch 1. 80/12/12 2pp 07461:332

0101210445 Forwards responses to questions on Rule 50 7ie. "Periodic
Updating of FSARs" & FR notice of final rule, SEP plants need
not comply w/rule until program is complete Non-OEP plants
must comply within specified time frame
EISENHUT, D O. Division of Licensing. 80/12/15 13pp

8101140523 Forwards review of util evaluation of steady state steam
generator operating level for purpose of maximizing dryout
time w/consideration for overfilling. Current operating level
is justified
VAROA, S A Operating Reactors Branch 1. 80/12/10 7pp. 07472:123

8101090715 Responds to 801126 memo re lack of groundwater monitoring
program et facility Map of station & elevations above sea
level encl Monitoring not required unless hydraulic gradient
or recharge properties are suitable for contamination
DIRCKS, W J. Office of the Executive Director for Operations.
80/12/23 23pp 07430 304.

8101090500 Forwards response to NURE0-0737 ltr response provided for
Oresden 1 Unit undergoing extensive mod & decontamination
outage Requirements of NURE0-0737 will be addressed prior
to startup of unit scheduled for June 1986
ABEL, J B. Commonwealth Edison Co 00/12/31. 55pp.

0101070555 "Adequacy of Station Electric Distribution Sys Voltages,
Zion Station, Unit 1," informal rept.
UDV, A C Idaho National Engineering Laboratory FIN A-6256.
8101070555. 80/12/31. 13pp 07408:059.

8101220631 "Critique of OPS Risk Study for Zion Nuclear Power Plant,"
informal rept
BUSLIN, A J, BARI, R A Brookhaven National Laboratory
BNL-NUREG-28750 80/12/31 60pp 07499:158

8101000310 Forwards Amends 59 & 56 to Licensee DPR-39 & DPR-48,
respectively & notice of issuance & availability.
VAROA, S A Operating Reactors Branch 1 00/12/31 3pp. 07587 011.

--8101000328 Amends 59 & 56 to Licensee DPR-39 & DPR-48 respectively,
allowing reinsetion of four fuel assemblies previously
irradiated in both units back into Unit 1 to irradiate high
burnup fuel for lost cycle.
VAROA, S A. Operating Reactors Branch 1. 80/12/31. 7pp
07587: 014.

--8101000338 Notice of issuance & availability of Amends 59 & 56 to
Licensee DPR-39 & DPR-48, respectively.
VAROA, S A Operating Reactors Branch 1 80/12/31. 2pp.
07587: 021.

9101050124 Requests eliciting data, summaries & records of interview in
tests of trainments w/roasted prestressing tendons
GAIL receiving contract to compile & review records of
tendons
EISENHART, B G Division of Licensing 00/11/25 3pp

6101146091 Forwarded IF Insp Repts 50-295/80-20 & 50-304/80-21 on
501001-1114 No noncompliance noted
HEIDEMAN, R F Region 3, Chicago, Reactor Operations Nuclear S:00:11
Branch 80/11/28 Zpp 07460 297

--B101140697 1E 1sp Repts: 90-299/80-20 & 90-304/80-21 on 801001-1114
No correspondence noted. Major areas inspected: operational
safety verification, jumper & lifted lead log & Unit 2
reactor trip
FOHLER, J. E., WATERS, J. R., HEIMANN, F. W. Region 3, Chicago, Office
of the Director, 8011128 14pc 07460 299

0101050530 Forwards IE Info Notice 80-43, "Failures of Continuous Wail Level Monitor For Screen Discharge Vol at Dresden Unit 2 " No response required
KEFFLER, J G Region 3, Chicago, Office of the Director. 80/12/65
23c

8101150628 Forwards IE Insp Repts 50-299/80-22 & 50-304/80-24 on
on 801117-19 L notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety
Branch, 8012/09 2pg 07463 255

--8101150634 Notice of violation from Insp on 801117-19.
DAVIS, A B Region J. Chicago. Fuel Facility & Materials Bafst,
Branch 80/12/04 Ip 07469 257

--8101130540 IE Insp Repts 50-295/80-22 & 50-304/80-24 on 801117-19
Noncompliance noted corrective actions contained in ROs
50-295/80-45 & 50-295/80-47 & confirmatory measures
PHILLIPS, M. P. JUKASKA, A. G. PAPERJELLO, G. J. Region 3. Chief
Office of the Director 80/12/03 800 07465 258

8101070214 Responds to IE Bulletin 80-11. "Masonry Wall Design" Data
on previous ltr should read 820101, not 810101
RAUSCH, T J Commonwealth Edison Co 80/12/11. 1p 07418 243

8101060073 Response to IE Bulletin 80-23. "Failures of Solenoid Valve"
Mfg by Valcor Engineering Corp. Valves V70900-21-I or
V70903-21-C not used in any safety-related functions Approx
40 manhours expended in bulletin review
RAUSCH, T J Com-on-health Edison Co 80/12/12 ip

8101070103 Forwards JE Info Notice BQ-44. "Activation of ECCB in
Recirculation Mode While in Hot Shutdown" No written
response required
KEPLER, J. G. Region 3, Chicago. Office of the Director. BQ/12/36
1: 07413 024

8101CB0093 Responds to NRC 000810 request for monthly status reports
evaluations in response to IE Bulletin 79-14. Tabulations of
piping sys w/stresses above FSAR levels & below operability
limit encl
JANECER, R F. Commonwealth Edison Co. 00/12/77 gaa

8101060285 Forwards IE Insp Repts 50-295/80-23 & 50-304/80-29 on
801117-21 & notice of violation Notice of violation withheld
(ref 10CFR2 790)
HIND, J A Region 3, Chicago, Safeguards Branch 00/12/23 2pp
07392-027

*B0106029D IE Insp Rpts 50-295/80-23 & 50-304/80-25 on B01117-21
 Noncompliance noted. Implementation of security change w/o
 Commission approval. Details withheld (ref IOCFR2 790)
 CHRISTOPHER C. PIRILE, O L Region 3, Chicago, Office of the
 Director. HIND, J A Region 3, Chicago, Refugees Branch
 80/12/22 2pp 07392 029

8101200155 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment" (801017 Indian Point 2 Event) " Surveillance procedures, of at least monthly repetition, will be instituted by 810601. BROWNE, T J. Commonwealth Edison Co. 81/01/05. App.

B101260675 Ack receipt of B01230 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 90-275/80-22 & 90-304/80-24.

FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 81/01/12, 10 07531, 169

--810126089 Responds to NRC 801209 ltr re violations noted in 1E inst
Rpts 90-299/80-22 & 90-304/80-24 Corrective actions.
recalib of all GEL detectors at 1-yr intervals
ABEL J S Commonwealth Edison Co 80/12/30 2pg 07831:160

--810126089 Responds to NRC 801209 ltr re violations noted in 1E inst
Rpts 90-299/80-22 & 90-304/80-24 Corrective actions.
recalib of all GEL detectors at 1-yr intervals
ABEL J S Commonwealth Edison Co 80/12/30 2pg 07831:160

BIOIC90462 Forward: IE Bulletin 80-21, "Velve Votes Supplied by Malcolm
Foundry Co. Inc." Written response required
KEPLER, J G Asgcon J, Chicago, Office of the Director 80/11/06
200

table occurrences. LERs & related correspondence

338 Forwards updated LER 80-091/03X-1
SER. K L Commonwealth Edison Co 80/12/31 1p 07447 176

20343 Updated LER 80-091/03X-1 on 801115, PP zone 2 pressure fell
out Tech Spec requirements & purge exhaust isolation valve
V-RV0004 found leaking at valve seat Caused by valve seat
traction during cold weather
4288.A Commonwealth Edison Co 80/12/31 1p 07447 157

346 Forwards LER 79-096/03L-0
SER. K L Commonwealth Edison Co 80/12/31 1p 07447 169

20349 LER 79-096/03L-0 on 791120, low-low Tave comparator 1TC4320N
outs found low, exceeding Tech Specs limit Caused by
instrument drift of unknown origin Comparator tested.
1117 & returned to svc
74.S Commonwealth Edison Co 80/12/31 1p 07447 166

161 Forwards LER 80-053/03L-0
SER. K L Commonwealth Edison Co 81/01/06 1p 07494 109

10916 LER 80-053/03L-0 on 800825, component cooling liquid rad
tor IRE 0017 did not respond to check source & indicator
at bottom of scale Caused by drift in monitor plateau
reau reset
1.R.E. Commonwealth Edison Co 81/01/06 1p 07494 106

41 Forwards LER 79-097/02L-0
SER. K L Commonwealth Edison Co 81/01/07 1p 07494 143

10551 LER 79-097/02L-0 on 790924, 1ed urgent alarm received while
mpting to move shutdown Unit C Caused by failure of
oscillator card in rad control logic cabinet New card
lined & installed
EMI.W.D Commonwealth Edison Co 81/01/07 1p 07494 144

59 Forwards LER 80-054/03L-0
ER. A L Commonwealth Edison Co 81/01/14 1p 07494 103

0936 LER 80-054/03L-0 on 801215, HNM miniflow control valve
-610A switch failed, making RH pump sys A unable to
ocm Caused by faulty micro switch Switch replaced &
11br
008.A Commonwealth Edison Co 81/01/14 1p 07494 104

30 Forwards LER 80-095/03L-0
ER. K L Commonwealth Edison Co 81/01/15 1p 07949 074

0733 LER 80-095/03L-0 on 801116, during normal operation, gas decay
radiation monitor CRT-PRO2B was taken out of svc for
& grab samples were not taken for two shifts Caused by
onnel oversight, Personnel re-instructed
JRE.J Commonwealth Edison Co 81/01/15 1p 07949 075

for Examinations

71 Requests that WK Houston be re-examined for senior operator
e during wk of 810112
1.R.K.L Commonwealth Edison Co 80/12/01 1p 07461 346

2-296 DROWN'S FERRY NUCLEAR POWER STATION, UNIT 2

ty, medical, emergency & fire protection plans

37 Ltr to all licensees of operating reactor plants, CP holders
licants, Revised radiological emergency response
ust be submitted by licensees within 60 days of
& by applicants as part of FBAR
IT.O.G Division of Licensing, 80/11/13, 2pp

37 Transcript of 801217 briefing on TVA emergency offsite
ies in Washington, DC, Pp 1-45
issions: 80/12/17 49pp

& Forwards request for addl info & revisions to 801001 changes
lity guard training & qualification plan, Min passing
or qualifying w/rifle should be stated
O.T.A Operating Reactors Branch 2, 81/01/14, 3pp
79.

1 Releases public version of util revised emergency plan.
J.M. Division of Rules and Records 81/01/15, 1p
30

--810126019 Forwards public version of revised radiological emergency
plan in response to HRC 801113 ltr Includes State of AL
emergency plan
HILL.S.L II Tennessee Valley Authority 80/12/31 17 07931 23

--810126034 Public version of revised util radiological emergency pl
a Tennessee Valley Authority 80/12/31 150pp 07931 732

--810126093 Releases public version of State of AL revised emergency
plan
FELTON.J.M Division of Rules and Records 81/01/16 1p
07934 180

--810126070 Public version of State of AL revised radiological emergency
plan
a Tennessee Valley Authority 80/12/31 300pp 07934 182

810130035b Forwards revisions to safeguards contingency plan Enc)
withhold ltrf HRC82 7901
HILL.S.L II Tennessee Valley Authority 81/01/23 1p 07986 228

0 Adjudicatory correspondence

8101300467 ltr for granting extension to exemption from General Design
Criteria 50 & requiring licensee to ceassess containment
design for suppression pool hydrodynamic loading
EISENHUT.D.O Division of Licensing 81/01/13 7pp 07986 122

8101160226 Petition for leave to intervene & request for hearing on T
license amend requests
PAUL.T.W., JONES.R.H., HALL.M.L. Affiliation Unknown 81/01/14
4pp 07470 160

8101200070 Motion for leave to intervene in proceeding re license
amends to allow onsite storage of low level radioactive for
five yrs.
CUMMINT.D.R., CURRIE.H.J. Affiliation Unknown 81/01/15 3pp
07486 359

8101200071 Petition for leave to intervene in proceeding
MARTIN.J.R., BECK.N.M., BECK.R.W. Affiliation Unknown 81/01/16
3pp 07187 001

8101200093 Petition for leave to intervene in proceeding
MOSE.N., FREEMAN.R.L., COLCLOCK.A.N. Affiliation Unknown 81/01/16
4pp 07486 359

8101200214 Petition for leave to intervene & request for hearing on
license amend requests
MARTIN.B.L., BRIDGES.O.R., PIERSON.N.D. Affiliation Unknown
81/01/16 3pp 07476 341

8101230407 Requests to make limited appearance statement & to receive
LIS on proposed low level radioactive storage project
VOUGRO.F. Affiliation Unknown 81/01/21 1p 07107 001

8101300012 Response supporting DR & UJ Curran, TW Paul, RW Jube, PL Hall
Bl, Martin, OR Brough, MD Pierson, O Ely, D Havos, N Muso, RC
Freeman AN Coloc, JR Martin & NM & RJ Beck petitions for
leave to intervene IF amended Certificate of Bvc oncl
LAVERTY.J II Office of the Executive Legal Director 81/01/28
12ps 07982 176

J Insurance & indemnity information

8101090485 Forwards Endorsement 53 to ANI Policy NF-198 for amend to
Condition 2
FIELDER.J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc
Div 80/12/29 3pp 07442 294

8101090490 Forwards Endorsement 52 to ANI Policy LF-198 for 1981
advances premiums
FIELDER.J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc
Div 80/12/29 2pp 07442 083

8101090647 Forwards Endorsement 4 to NEIIA Binders ED-38, ED-39 &
ED-40 w/o Binders ED-39 & ED-40
FIELDER.J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc
Div 80/12/29 2pp 07442 060

P Operating license stage documents & correspondence

8101100294 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of Inservice surveillance requirements for
subbers under B1S License amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT.D.O Division of Licensing, 80/11/20, 1p

--B101100271 Revised Pages 3/4 7-22 through 28, 3/4 7-5 & 7-6 & 6-17 to
SIS section revise line requirements
• Division of Licensing 60/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, Potential for Low Fracture
Toughness & Laminar Tearing on Component Supports
EISENHUT, D G Division of Licensing 60/11/26 8pp

B101100030 Requests input spec & simulator time re ARC comparison of
ARCRAH results w/simulator results for loss of feedwater &
loss of lead transients in BWR
JPPGLITO, T A Operating Reactors Branch 2 60/12/02 2pp
07444 299

B101100022 Forwards FR notice of consideration of amendments to facility
NLS re util B00731 & 1117 applications for authorization of
onsite low level waste storage for 5-yr period
JPPGLITO, T A Operating Reactors Branch 2 00/12/05 2pp
07445 204

B101590113 Ltr to all BWR licensees forwarding B01201 generic safety
evaluation re BWR scram discharge sys Recommends short-term
actions necessary to ensure safe operation of GE BWRs
pending permanent design changes
EISENHUT, D G Division of Licensing 60/12/09 2pp

--B101590141 Generic safety evaluation re short-term actions required to
ensure continued safe operation of operating BWRs Continued
operation of plants is acceptable pending permanent design
mods Criteria for implementing design mods encl
• Division of Licensing 60/12/01 212pp 07183 001

B101050610 Forwards geologic rept re suggested graben in Gravelly
Springs, AL above distance to facilities precludes
significance of structures Related documentation encl
LEFEVRE, H E Geosciences Branch 60/12/11 15pp 03775 001

B101210445 Forwards responses to questions on Rule 50.71a. "Periodic
Updating of FBARs" & FR notice of final rule. SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT, D G Division of Licensing 60/12/15 13pp

B101210642 Advises that ATWS issue will be subg of future rulemaking to
determine requirements & schedules for plant mods NRC will
not comment on util B00717 ltr describing program for
resolving issue until rulemaking is finalized
EISENHUT, D G Division of Licensing 60/12/29 2pp 07468 337

B101290033 Forwards Amends 65.61 & 36 to Licensee DPR-33, DPR-52 &
DPR-68, respectively, EIA & notice of issuance & negative
declaration
JPPGLITO, T A Operating Reactors Branch 2 60/12/29 3pp
07309 001

--B101290040 Amends 65.61 & 36 to Licensee DPR-33, DPR-52 & DPR-68,
respectively, changing App B Tech Spec to delete fish
impingement monitoring program
JPPGLITO, T A Operating Reactors Branch 2 60/12/29 12pp
07309 001

--B101290046 EIA supporting Amends 65.63 & 36 to Licensee DPR-33, DPR-52
& DPR-68, respectively, Summary review of fish impingement
encl
• Office of Nuclear Reactor Regulation, Director 60/12/29
32pp 07309 001

--B101290052 Notice of issuance & availability & negative declaration of
Amend 65.61 & 36 to Licensee DPR-33, DPR-52 & DPR-68,
respectively
JPPGLITO, T A Operating Reactors Branch 2 60/12/29 2pp
07309 001

B101190393 Advises that util B00909 response to NRC B00702 generic ltr
re Tech Specs for TMI Lessons Learned Category A items re
inadequate Outstanding items emergency power supply relief
& safety valve position indication
JPPGLITO, T A Operating Reactors Branch 2 61/01/02 2pp
07475 344

B101300467 Order granting extension to exemption from General Design
Criterion 3D & requiring license to reassess containment
design for suppression pool hydrodynamic loading
EISENHUT, D G Division of Licensing 61/01/13 7pp 07586 122

B101220411 Requests temporary relief from 5 F thermal rise limit & 100
max reservoir temp rise of 8.5 F be granted until Apr 1901
Temp rise of 8.5 F will sustain 3-unit operation at Facility
w/current min hydro releases for navigation
EL-ASHRY, M I Tennessee Valley Authority 01/01/14 3pp
07502 246

B101220297 Grants request for temporary relief from permit condition
re allowable temp rise within certain conditions Temp at
edge of mixing zone must not exhibit change greater than
8.5 F
ZELLER, H D Environmental Protection Agency 61/01/15 2pp
07500 069

B101300493 Forwards response to NRC B01123 request for confirmation
that NUREG-0619 implementation dates will be met info
justifies continued operation
MILLS, L M Tennessee Valley Authority 61/01/23 3pp 07181 001

G. Inspection reports, IE Bulletins & correspondence

B101080181 Forwards update to B01104 response to IE Bulletin 79-26 re
baron loss from BWR control blades Manpower required for
review & preparation approx 20-h
MILLS, L M Tennessee Valley Authority 60/11/25 3pp 03775 001

B101050580 Forwards IE Info Notice 60-43, "Failures of Continuous Mtr
Level Monitor for Scram Discharge Vol at Dresden Unit 2" No
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 60/12/13
1p 07391 010

B101140866 Responds to IE Bulletin 60-23 Defective solenoid valves
w/rate & part numbers in bulletin are not in use at
facilities
MILLS, L M Tennessee Valley Authority 60/12/15 1p 07461 031

B101060153 Forwards IE Info Notice 60-45, "Potential Failure of BWR
Backup Manual Scram Capability" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 60/12/17
1p 07391 275

B101070032 Forwards Suppl 4 to IE Bulletin 60-17, "Failure of 76 of 163
Control Rods to Fully Insert During Scram at BWR" No
written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 60/12/18
1p 07413 323

B101050153 Forwards IE Bulletin 60-25, "Operating Problems w/Target
Rock Safety Relief Valves at BWRs" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 60/12/19
2pp 07377 247

B101150252 Forwards response to IE Bulletin 60-07, "BWR Jet Pump
Assembly Failure" Ultrasonic & visual insp of jet pump
beams & assembly showed no problems
MILLS, L M Tennessee Valley Authority 60/12/30 2pp 07478 249

B101210157 Informs that insp program re IE Bulletin 79-14 will not be
completed by B01125 due to delays in planned schedules.
Revised insp schedule & Dec 1980 status rept encl
MILLS, L M Tennessee Valley Authority 61/01/05 30pp 07490 010

B101220376 Forwards results of spray sparger insp in response to IE
Bulletin 60-13, "Cracking in Core Spray Spargers"
MILLS, L M Tennessee Valley Authority 61/01/05 2pp 07503 234

B101280505 Forwards response to IE Bulletin 60-24, "Prevention of
Damage Due to Water Leakage (Oct 17, 1980 Indian Point 2
Event)." Components requiring supplemental cooling are
cooled by reactor bldg closed cooling water sys
MILLS, L M Tennessee Valley Authority 61/01/05 5pp 07550 319

B101280527 Forwards results of util analyses on diesel generator &
480 V load shed logic re IE Bulletin 60-06, "Engineered
Safety Feature (ESF) Reset Controls."
MILLS, L M Tennessee Valley Authority 61/01/14 2pp 07550 336

B101290320 Forwards monthly status rept as of B10101 for work re IE
Bulletin 79-14, "Seismic Analysis for As-Built
Safety-Related Piping Sys" Includes description of pipe
support & valve insp
MILLS, L M Tennessee Valley Authority 61/01/15 29pp 07572 321

R Periodic operating reports & related correspondence

B101120582 Forwards monthly operating reports for Dec 1980
ABERCROMBIE, H Tennessee Valley Authority 61/01/09 1p
07453 233

030599 Monthly operating repts for Dec 1980
J.M. Tennessee Valley Authority 01/01/04 37pp 07453 236

0595 Forwards monthly operating repts for Dec 1980
R.D.H.E.H. Tennessee Valley Authority 01/01/09 1p
3 288

030601 Monthly operating repts for Dec 1980
J.E.N.D., T.H.M.T. Tennessee Valley Authority 01/01/04 21pp
453 289

portable occurrences. LERs & related correspondence

0469 Forwards LER 80-058/03L-0
J.H.J. Tennessee Valley Authority 81/01/06 1p 07454 110

030505 LER 80-058/03L-0 on 801207.MSIV 1-14, 1-15, 1-26, 1-27, 1-37 &
1B & 1-51 found leaking Caused by seating surface
degradation due to normal wear Valves repaired
Tennessee Valley Authority 81/01/06 2pp 07454 111

0606 Forwards LER 80-054/01T-0
J.H.J. Tennessee Valley Authority 81/01/08 1p 07475 023

090612 LER 80-054/01T-0 on 801210, eight main steam relief valves
failed to actuate within required 1% of set pressure. Cause
unknown Set pressure reset & proper operation verified
Followup rept will be issued
Tennessee Valley Authority 81/01/08 2pp 07475 024

0476 Forwards "Analysis of Incomplete Control Rod Insertion at
the Ferry 3"
J.L.M. Tennessee Valley Authority 81/01/12 1p 07475 090

090500 "Analysis of Incomplete Control Rod Insertion at Browns
Ferry 3"
Nuclear Safety Analysis Center * Institute of Nuclear Power
Operations NSAC-20. 80/12/31. 76pp 07475 091

0311 Forwards first interim rept re potential flammability of
suspended ceiling tile in control rooms in response to
04 ltr. Addl info to be provided by 010211
J.L.M. Tennessee Valley Authority 01/01/14 3pp 07494 096

0572 Forwards updated LER 80-030/03L-1
J.H.J. Tennessee Valley Authority 01/01/17 1p 07546 320

070579 Updated LER 80-030/03L-1 on 800813, Model B2T-A1269 pressure
switches PB-1-B1A & PS-1-91A, turbine first stage pressure,
sponts drifted above Tech Spec limits Cause not stated.
Switches inspected, recalibr & tested for repeatability
Tennessee Valley Authority 01/01/19 2pp 07546 321

0668 Forwards updated LER 80-016/03L-1.
J.H.J. Tennessee Valley Authority 81/01/19 1p 07546 346

070673 Updated LER 80-016/03L-1 on 000513, cooling water flow
determined inadequate on diesel generator heat exchanger 30.
Caused by apparent restriction in cooling water piping
Flushing lines flushed
Tennessee Valley Authority 81/01/19 2pp 07546 347

0713 Forwards updated LER 80-036/03L-1
J.H.J. Tennessee Valley Authority 01/01/20 1p 07548 071

070716 Updated LER 80-036/03L-1 on 800915, diesel generator 3A would
not trip to idle speed from loaded condition. Caused by
worn pin on pinion gear to intermediate shaft gear used
in speed adjusting on Woodward governor. Governor replaced.
Tennessee Valley Authority 01/01/20 2pp 07548 072

0705 Forwards LER 80-040/03L-1
J.H.J. Tennessee Valley Authority 81/01/21 1p 07548 081

070711 LER 80-040/03L-1 on 801010, 3EB diesel generator lube oil
circulating pump discovered inoperable. Caused by locked
double row ball bearing. Lube oil circulating pump replaced
Tennessee Valley Authority 81/01/21 2pp 07548 082

0811 Forwards updated LER 80-015/03L-1.
J.H.J. Tennessee Valley Authority 81/01/26 1p 07586 310

--8101300511 Updated LER 80-015/03L-1 on 800512, RHR pump seal heat
exchanger 33 cooling water flow found inadequate per Tech
Specs Caused by apparent restriction in cooling water piping
upstream &/or downstream from heat exchanger
* Tennessee Valley Authority 81/01/26 2pp 07506 319

8101300632 Forwards LER 80-051/03L-0
GREEN.H.J. Tennessee Valley Authority 81/01/26 1p 07585 356

--8101300641 LER 80-061/03L-0 on 801230, RLC pump discharge relief valve
3B would not relieve within Tech Spec Caused by failed valve
disc or disc binding. Valve guide Valve replaced
* Tennessee Valley Authority 81/01/26 2pp 07585 357

8101300504 Forwards updated LER 80-038/03L-1
GREEN.H.J. Tennessee Valley Authority 81/01/27 1p 07586 311

--8101300520 Updated LER 80-038/03L-1 on 800907, MSIV 3-FCV-1-26 closed
too fast while running surveillance instruction Caused by
low oil level in hydraulic cylinder Oil added & flow control
valve adjusted
* Tennessee Valley Authority 81/01/27 2pp 07506 314

8101300611 Forwards LER 80-059/03L-0
GREEN.H.J. Tennessee Valley Authority 81/01/27 1p 07503 357

--8101300615 LER 80-059/03L-0 on 801231, MSIV 1-14, 1-15, 1-26, 1-27, 1-37,
1-30 & 1-51 total as-found containment leak rate exceeded
allowable rate. Caused by deterioration of valve seating
surface Maint & retest effected until rate acceptable.
* Tennessee Valley Authority 81/01/27 2pp 07583 350

BUCKET 50-290 COOPER NUCLEAR STATION

F Security, medical, emergency & fire protection plans

8101090307 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
010102 & by applicants as part of FBAR
EISENHUT.D.O. Division of Licensing 80/11/13 3pp.

8101050403 Ltr to all power reactor licensees w/plants licensed prior
to 790101. Forwards FR notice of revised 10CFR50 40 & App R
re fire protection features in nuclear power plants
EISENHUT.D.O. Division of Licensing 80/11/24 3pp 07387 266

8101140219 Informs that licensee should conduct emergency exercise
within one yr from 800401 or prior to issuance of OL
Schedule A drills should be provided.
SEYFRIT.K.V. Region 4, Dallas, Office of the Director 80/12/23
1p 07461 288

Q Adjudicatory correspondence

8101300396 Forwards NRC 810113 order granting extension to exemption
from General Design Criterion 50 & requiring licensee to
reassess containment design for suppression pool
hydrodynamic loading
IPPOLITO.T.A. Operating Reactors Branch 2 01/01/13 3pp
07586 197

P Operating license stage documents & correspondence

8101220637 "Examination of Cracked Turbine Disc From Cooper Nuclear
Power Station," informal rept
CZAJKOWSKI.C.J. Brookhaven National Laboratory FIN A-3106
BNL-NUREG-28724 80/10/31 37pp. 07499 267

8101100053 Notifies that until 801015 application to amend OL requires
Class III amend fee Application proposed Tech Spec changes
resulting from TM1-2 Lessons Learned requirements.
OIGGS.R.H. License Fee Management Branch 80/11/17 1p
07444 044

8101100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under STS license amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT.D.O. Division of Licensing 80/11/20 1p.

--8101100271 Revised Pages 3/4 7-22 through 28.0 3/4 7-5 & 7-6 & 8-17 to
STS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp.

B101070482 Notifies of installation of equipment to meet requirements of NRC B101032 (confinement, order re monitoring scan discharge vol. Fical-type level switches & ultrasonic equipment installed. Description encl)
PILANT, J. M. Nebraska Public Power District 80/11/24 4pp
07415 321

B101270486 Ltr to all power reactor licensees & applicants forwarding summary of B10112 meeting re implementation of guidance for unresolved safety issues (Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports")
EISENHUT, D. G. Division of Licensing 80/11/26 8pp

B101190113 Ltr to all BWR licensees forwarding B101201 generic safety evaluation re BWR scan discharge sys. Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes
EISENHUT, D. G. Division of Licensing 80/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs. Continuous operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp 07183 001

B101210445 Forwards responses to questions on Rule 50.71e. Periodic Updating of FRAs & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame
EISENHUT, D. G. Division of Licensing 80/12/15 13pp

B101050466 Forwards status of TMI-related requirements scheduled for implementation prior to B10101 & discussion of requirements scheduled for response between Jan & Jul 1981
PILANT, J. M. Nebraska Public Power District 80/12/30 3pp
07383 224

--B101050473 "Control Room Habitability Study"
* Stone & Webster Engineering Corp 80/12/12 35pp 07383, 262

B101120162 Forwards proposed revision to B101015 Tech Specs addressing areas of valve position indication, shift technical advisor, sys integrity & improved iodine measurements program per TMI-2 Lessons Learned Task Force requirements
PILANT, J. M. Nebraska Public Power District 81/01/06 2pp
07446 212

--B101120167 Proposed revision to B101015 Tech Specs Sections 3.5 & 6 re valve position indication, shift technical advisor, sys integrity & improved iodine measurements program per TMI-2 Lessons Learned Task Force requirements
* Nebraska Public Power District 81/01/06 8pp 07446 214

B101160448 Responds to NREG-0619 re feedwater nozzles & control rod drive return line nozzles. During spring refueling & maint outage feedwater nozzles inspected & double piston spargers installed. No other sys mods necessary
PILANT, J. M. Nebraska Public Power District 81/01/07 2pp
07470 079

B101300396 Forwards NRC B10113 order granting extension to exemption from General Design Criterion 50 & requiring licensee to reassess containment design for suppression pool hydrodynamic loading
JPMOLIT, T. A. Operating Reactors Branch 2 81/01/13 3pp
07506 197

--B101300499 Order granting extension to exemption from General Design Criterion 50 & requiring licensee to reassess containment design for suppression pool hydrodynamic loading
EISENHUT, D. G. Division of Licensing 81/01/13 7pp 07586 200

G Inspection reports, IE Bulletins & correspondence

B101100029 Forwards IE Insp Rept 50-298/80-16 on B101021-24 & 29-31. No noncompliance noted
RADSEI, D. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/14 2pp 07443 031

--B101100031 IE Insp Rept 50-290/80-16 on B101021-24 & 29-31. No noncompliance noted. Major areas inspected followed up to previously identified items. IE bulletins & short-term actions learned Category A items
BRADNER, R. O., WESTERMAN, T. F. Region 4, Dallas, Office of the Director 80/11/14 9pp 07443 033

B101090272 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (October 17, 1980 Indian Point 2 event)". Written response required
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/11/21 1p 07425 242

B101060329 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Chubbier Fluid". No response required
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/11/24 1p 07392 062

B101080074 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failures. No such valves installed at facility
PILANT, J. M. Nebraska Public Power District 80/11/24 1p
07421 068

B101060301 Forwards Suppl 1 to IE Info Notice 80-27, "Broken Studs on Terry Turbine Steam Inlet Flange". No written response required
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/11/26 1p 07392 043

B101050507 Forwards IE Info Notice 80-43, "Failures of Continuous Wet Level Monitor for Scan Discharge Vol at Dresden Unit 2". No response required
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/12/05 1p 07391 030

B10120050 Responds to IE Bulletin 80-21 re valve yokes supplied by Malcolm Foundry Co. Inc. No response received from valve vendors as yet
PILANT, J. M. Nebraska Public Power District 80/12/00 2pp
07446 262

B101070146 Ack receipt of B10103 & 1016 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/80-13
RADSEI, D. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/12/15 1p 07407 031

--B101070155 Responds to NRC B10113 ltr re violations noted in IE Insp Rept 50-298/80-13. Corrective actions time period between requalification exams & grade tests shortened to within 60 days of test date
PILANT, J. M. Nebraska Public Power District 80/12/03 2pp
07409 032

B101120138 Responds to IE Bulletin 80-24 re water leakage inside containment. No significant leakages of cooling water inside containment identified.
PILANT, J. M. Nebraska Public Power District 80/12/15 3pp
07446 254

H Periodic operating reports & related correspondence

B101130587 Forwards monthly operating rept for Dec 1980.
LESSOR, L. C. Nebraska Public Power District 81/01/05 1p
07453 277

--B101130593 Monthly operating rept for Dec 1980
BALLINGER, P. L. Nebraska Public Power District 81/01/05 4pp
07453 278

I Reportable occurrences, LERs & related correspondence

B101070514 Forwards LER 80-041/03L-D
LESSOR, L. C. Nebraska Public Power District 80/11/14 2pp
07415 111

--B101070521 LER 80-041/03L-D on B101016, svc water pump C noted with excessively. Cause undetermined. Pump disassembled & rotating assembly returned for overhaul. Other components reused.
BRAW, P. F. Nebraska Public Power District 80/11/14 1p
07415 113

B101070507 Forwards LER 80-042/03L-D
LESSOR, L. C. Nebraska Public Power District 80/11/18 2pp
07415 084

--B101070511 LER 80-042/03L-D on B101020, throttle valve BW-HD-09A on discharge of A RHR heat exchanger would not fully close. Caused by valve stem clamp slipping out of position allowing valve stem to rotate. Stem clamp keyway enlarged due to wear.
LAWRENCE, L. J. Nebraska Public Power District 80/11/18 1p
07415 086

B101070360 Forwards LER 80-039/03L-D
LESSOR, L. C. Nebraska Public Power District 80/11/19 2pp
07406 344

01070363 LER 80-039/03L-0 on 801023, snubber RH-S-27 discovered inoperable. Caused by work in area damaging snubber. Snubber repaired & protective shield installed
BUNTON, L F Nebraska Public Power District 80/11/19 1p
07406 346

070351 Forwards LER 80-043/03L-0
BBSOR, L C Nebraska Public Power District 80/11/20 2pp
0406 338

01070353 LER 80-043/03L-0 on 801021, motor operated valve RW-MH1-89B failed to open. Caused by broken wire connected to OMITE 1000-ohm variable resistor inside valve operator. Broken lead resoldered & circuit checked
BBSOR, L F Nebraska Public Power District 00/11/20 1p
07406 340

070355 Forwards LER 80-044/01T-0
BBSOR, L C Nebraska Public Power District 80/11/25 2pp
0406 341

01070357 LER 80-044/01T-0 on 801115, reactor scram occurred & normal cooldown rate exceeded. Caused by failed card (Westinghouse-Magan 398522) in computer controlled turbine control sys forcing main steam bypass valves to remain open
BBSOR, P J Nebraska Public Power District 80/11/25 1p
07406 343

070489 Forwards LER 80-045/03L-0
BBSOR, L C Nebraska Public Power District 80/11/26 2pp
0406 356

01070492 LER 80-045/03L-0 on 801102, hydraulic shock suppressor RH-S-43 found inoperable per radiological Tech Spec. Caused by suppressor installed w/reservoir connecting pipe at wrong end of reservoir. Suppressor installed properly
LAWRENCE, L J Nebraska Public Power District 80/11/26 1p
07406 358

070477 Forwards LER 80-046/03L-0
BBSOR, L C Nebraska Public Power District 80/12/19 3pp
0406 352

01070480 LER 80-046/03L-0 on 801117, isolation valve on discharge line from drywell equipment sump Q, RW-AO-74, would not open. Caused by hard & worn U-cup seal in piston air operator. New piston U-cups installed & valve retested
SCHEER, J L Nebraska Public Power District 80/12/19 1p
07406 359

270649 Forwards LER 80-048/03L-0
BBSOR, L C Nebraska Public Power District 80/12/16 2pp
0546 343

01270653 LER 80-048/03L-0 on 801121, containment oxygen concentration not reduced to less than 4% within 24-h of placing reactor in run mode. Cause unknown. Procedures will be revised to reduce potential for recurrence.
BBSOR, P J Nebraska Public Power District 80/12/16 1p
07546 345

270641 Forwards LER 80-049/03L-0
BBSOR, L C Nebraska Public Power District 80/12/19 2pp
0546 340

01270645 LER 80-049/03L-0 on 801120, MSIV B&A had slower closure time than Tech Specs allowed. Cause unknown. Closing time adjusted. Further evaluations to be performed
BUNTON, L F Nebraska Public Power District 80/12/19 1p
07546 342

270715 Forwards LER 80-051/03L-0
BBSOR, L C Nebraska Public Power District 81/01/13 2pp
0183 001

01270719 LER 80-051/03L-0 on 801216, during routine surveillance testing, HPCI turbine stop valve would not open & sys was declared inoperable. Caused by excess teflon seal matl which interfered w/relay valve on hydraulic actuator
FLANNIOAN, R Nebraska Public Power District 81/01/13 1p
07103 001

270775 Forwards LER 80-050/03L-0
BBSOR, L C Nebraska Public Power District 81/01/14 2pp
0549 081

--8101270783 LER 80-050/03L-0 on 801216, during surveillance testing, HPCI motor operated valves, RH-MO-25B, loop B injection line inboard isolation would not open. Caused by installation error. Close torque switch was readjusted
BBSOR, L F Nebraska Public Power District 81/01/14 1p
07549 083

BUCKET 90-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

0101090387 Ltr to all licensees of operating reactor plants. CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 010102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 00/11/17 2pp

8101090110 Releasea public version of util preliminary draft emergency plan
FELTON, J M Division of Rules and Records 80/12/01 1p
07421:001

--8101090113 Forwards public version of preliminary draft emergency plan
FAY, C W Wisconsin Electric Power Co 80/07/25 1p 07428:002

--8101090115 Forwards public version of preliminary draft emergency plan
FAY, C W Wisconsin Electric Power Co 80/07/25 1p 07428:003

--8101090118 Public version of preliminary draft emergency plan
* Wisconsin Electric Power Co 80/07/31 200pp 07428:005

8101090916 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUDER, J L Division of Rules and Records 80/12/16 1p
07427 360

8101190297 Forwards request for addl info re 800822 revised safeguards contingency plan. Revised plan is acceptable, but approval is sub j to responsibility matrix section mods. Requests response within 60 days. Request withheld (ref 80CFR2 790)
CLARK, R A Operating Reactors Branch 3 80/12/19 2pp 07476 051

0101260740 Requests that completion date for fire protection mods be extended to 81117 to provide time required for installation of remote diesel generator pencils w/modified carbon dioxide extinguishing sys nozzles & light fixture diffusers
FAY, C W Wisconsin Electric Power Co 81/01/20 2pp 07525 140

8101290148 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUDER, J L Division of Rules and Records 81/01/23 1p
07525 176

P Operating license stage documents & correspondence

0101100254 Ltr to all licensees (except BEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under BES license amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 4-17 STB snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

0101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of evidence for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FN notice of final rule. BEP plants need not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/19 13pp

8101100918 Forwards Amends 46 & 51 to Licenses OPR-24 & OPR-27, respectively, safety evaluation & notice of issuance & availability
CLARK, R A Operating Reactors Branch 3 80/12/17 2pp 07449 051

--8101100527 Amends 46 & 51 to Licenses OPR-24 & OPR-27, respectively, changing Tech Specs to eliminate procedural steps for testing of containment spray additive valves
CLARK, R A Operating Reactors Branch 3 80/12/17 6pp 07443 091

--010100535 Safety evaluation supporting Amends 46 & 51 to Licenses
OPR-24 & OPR-27, respectively.
* Operating Reactors Branch 3 80/12/17 2pp 07445 097

--0101100543 Notice of Issuance & availability of Amends 46 & 51 to
Licenses OPR-24 & OPR-27, respectively
CLARK, R A Operating Reactors Branch 3. 80/12/17 2pp.
07445 099

B101100175 Informs that addl duplicate amend for 800919 application
is still applicable as second unit required addl
administrative review in response to B01114 ltr
MILLER, W O License Fee Management Branch 80/12/19. 1p
07309 001

B101300175 "Instrument Bus Muds, Point Beach Nuclear Plant, Units 1 & 2."
MAYB, S E EQG Info. Inc FIN A-6255 B101300175 80/12/31
4pp 07503 189

B10120509 Forwards addl response to NUREG-0737 re post-IM1
requirements for operating plants Meteorology submitted
completed. Control room habitability evaluation will be
provided by B10206
FAY, C W Wisconsin Electric Power Co 81/01/09. 10pp 07489:256

B101160451 Responds to NRC 801219 request for second Class 1 license
amend approval fee for 800919 Tech Spec Change Request 64
No addl administrative effort required for issuance of
Tech Spec pages for second unit
BURSTEIN, S Wisconsin Electric Power Co 81/01/13 2pp
07469 357

B101260410 Forwards revised Page 7 to 801223 response to NUREG-0737.
Item 11 K 3 12
FAY, C W Wisconsin Electric Power Co 81/01/19 2pp 07522:260

B101270666 Responds to NRC 800905 ltr requesting addl info re adequacy
of electrical distribution sys All safety-related sys
supplied from either 460 volt or 4160 volt sys Electrical
sys diagram encl
FAY, C W Wisconsin Electric Power Co. 81/01/21 4pp. 07545:349

0 Inspection reports, IE Bulletins & correspondence

B101050225 Forwards IE Info Notice 80-38, "Creeping in Charging Pump
Casing Cladding." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30
2pp 07309 074

B101050124 Requests existing data, summaries & records of inservice insp
tests of containments w/greased prestressing tendons
ORNL receiving contract to compile & review records of
tendons
EISENHUT, O O Division of Licensing. 80/11/29 3pp.

B101070263 Forwards list identifying security badge number & clearance
level for Region 3 personnel. Badge numbers for personnel
identified by asterisks will be provided at later date
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/25
6pp 07410 353

B101050578 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor For Bypass Discharge Val at Dresden Unit 2." No
response required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/12/03
2pp 07309 336

B101150646 Forwards IE Insp Repts 50-266/80-17 & 50-301/80-17 on
B101001-31 No noncompliance noted.
EISENHUT, O O Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/12/09 2pp 07465 272.

--B101150651 IE Insp Repts 50-266/80-17 & 50-301/80-17 on B101001-31. No
noncompliance noted. Major areas inspected: operational
safety verification, monthly maint & surveillance & followup
on LERs, IE bulletins & circulars
GULOFORNO, W O., MAQUE, R L., WARRICK, R F Region 3, Chicago, Office
of the Director 80/12/04 6pp. 07465:274.

B101100174 Forwards IE Insp Repts 50-266/80-21 & 50-301/80-21 on
B01107 re NRC evaluation of licensed activity performance
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/12/10.
2pp. 07445 020

--B101100101 IE Insp Repts 50-266/80-21 & 50-301/80-21 re B01107 wgt
resting to discuss regulatory performance of activities at
facility Encl license performance evaluation was presented
Performance found adequate.
EISENHUT, R F Region 3, Chicago, Reactor Operations Nuclear
Support Branch 80/12/09. 10pp 07443:022.

B101070570 Forwards results of re-evaluation of mason
response to IE Bulletin 80-11 Includes schedule for
upgrading walls to meet criteria.
FAY, C W Wisconsin Electric Power Co 80/12/12 4

B101070095 Forwards IE Info Notice 80-44, "Actuation of
Recirculation Mode While in Hot Shutdown." No written
response required
KEPPLER, J O Region 3, Chicago, Office of the Director
1p 07415 033

B101120201 Suppl B00718 response to IE Bulletin 80-11
design Wall omitted from first analysis will be re-eval
using criteria of B01114 ltr
FAY, C W Wisconsin Electric Power Co 80/12/26 2

B101200150 Responds to IE Bulletin 80-24 re preventing
water leakage inside containment facilities have only
open cooling water sys inside containment & have had
significant leakage during plant operations.
FAY, C W Wisconsin Electric Power Co 81/01/05 1

B101280379 Submits final response to IE Bulletin 80-21
Supplied by Malcolm Foundry Co, Inc "Manufacturers of
utilitis specified valve parts castings"
BURSTEIN, S. Wisconsin Electric Power Co. 81/01/13

B101280521 Responds to NRC B10109 request for addl info
80-24, "Prevention of Damages Due to Water Leakage in
Containment 1 Oct 17, 1980 Indian Point 2 Event." Info
provided re closed cooling water sys experience
BURSTEIN, S. Wisconsin Electric Power Co. 81/01/13.
07530 328

R Periodic operating reports & related correspondence

B101150517 Forwards monthly operating repts for Dec 1980
FAY, C W Wisconsin Electric Power Co 81/01/12 1

--B101150519 Monthly operating repts for Dec 1980
FAY, C W Wisconsin Electric Power Co. 81/01/07.
07463 164

S Reportable occurrences, LERs & related correspondence

B012170575 Forwards LER 80-010/03L-0
FAY, C W Wisconsin Electric Power Co 80/12/11. 1

--B012170615 LER 80-010/03L-0 on B01117, safety inject
& pump theft to coupling keys found to be sheared
undetermined. Pump & motor checked for damage, keys
pump operability verified.
FAY, C W. Wisconsin Electric Power Co. 80/12/11

03CKEY 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days
B10102 & by applicants as part of FSAR.
EISENHUT, O O Division of Licensing. 80/11/13. 2p

B101090453 Notifies of Commission approval of encl rule
previously approved completion dates for fire protection
code. Specific schedules for mods will be effective in
publication of final rule.
EISENHUT, O O. Division of Licensing 80/11/18. 5p

B101190123 Requests that encl facility emergency plan
publicly available w/o encl.
SQUJER, J L Division of Rules and Records. 81/01/07.
07475:322

J Insurance & indemnity information

B101090466 Forwards Endorsement 46 to NELA Policy NF-1
FIELDER, J Mech & McLennan, Inc., M & H Nuclear Co
Div. 80/12/30. 3pp. 07442:035.

B101090475 Forwards Endorsement 49 to ANI Policy NF-1
FIELDER, J. Marsh & McLennan, Inc., M & H Nuclear Co
Div. 80/12/30. 2pp. 07442 041.

01090561 Forwards Endorsement 4 to ANI Policy EB-35
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/30 2pp 07427 345

Advisory Committee on Reactor Safeguards reports & correspondence

01300770 Notice of ACRS Subcommittee on B&W Water Reactors 801031
meeting in Washington, DC re 800226 event at facility
KOVLE, J.C. Office of the Secretary of the Commission. 80/10/14
2pp. 07504 251

Operating license stage documents & correspondence

01090739 Corrects typographical errors on Page 3 of 800722 memo re
Interim std for probability of severe core damage for
interim reliability evaluation program at facilities.
BERNERO, R.M. Probabilistic Analysis Staff (Pre 801119). 80/07/29
1p 07309:001

0101090745 Submits recommendations re interim reliability evaluation
program & interim action criteria for facilities.
Recommendations include std for corrective action re
potential severe core damage
BERNERO, R.M. Probabilistic Analysis Staff (Pre 801119). 80/07/22.
3pp. 07309 001

0101090786 Submits backfit deadlines based on hypothetical interim
acceptable risk numbers.
ROWSDME, F.H. Probabilistic Analysis Staff (Pre 801119) 80/07/11
3pp. 07309.001

0101090766 Submits addenda to 800711 memo re backfit deadlines based
upon hypothetical interim acceptable risk numbers
ROWSDME, F.H. Probabilistic Analysis Staff (Pre 801119) 80/07/23
2pp. 07309-001.

01100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of Inservice surveillance requirements for
snubbers under STB License amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT, D.O. Division of Licensing 80/11/20 1p.

0101100271 Revised Pages 3/4 7-22 through 28.0 3/4 7-5 & 7-6 & 6-17 to
STB snubber inservice insp requirements
* Division of Licensing 00/11/20 10pp

01220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Involvement Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D.O. Division of Licensing 80/11/26 8pp

01050167 Forwards "Ofc for Analysis & Evaluation of Operational Data
Actions Re Crystal River 3 Loss of Nonnuclear
Instrumentation & Integrated Control Sys Power on 800226."
Response to recommendations will be prepared by 810115.
HICKS, W.J. Office of the Executive Director for Operations.
80/12/11. 1p. 07390-074

0101050336 "Ofc for Analysis & Evaluation of Operational Data Actions
Re Crystal River 3 Loss of Nonnuclear Instrumentation &
Integrated Control Sys Power on 800226."
BENSTEIN, H.L. Director's Office. 80/11/24. 33pp. 07390:075

01050417 Forwards safety evaluation denying until 790323 application
to amend Tech Specs re dc electrical power sys surveillance
requirements
KOVAK, T.M. Assistant Director for Operating Reactors 80/12/11
1pp. 07389:320.

0101050420 Safety evaluation denying until 790323 application to amend
Tech Specs re dc electrical power sys surveillance
requirements.
* Assistant Director for Operating Reactors 80/12/11. 2pp
07389 322

01210445 Forwards responses to questions on Rule 50.71e, "Periodic
updating of FSARs" & FR notice of final rule. SEP plants need
to comply w/rule until program is complete. Non-SEP plants
not comply within specified time frame
EISENHUT, D.O. Division of Licensing 80/12/13 13pp.

01140026 Grants permission to use BUNA-N seal matl in hydraulic
nubbers until next refueling shutdown in response to until
01219 ltr Seal matl is expected to be replaced w/ethylene
propylene seals during shutdown.
EID, R.W. Operating Reactors Branch 4 80/12/19. 2pp. 07461:223

0101050260 Application for Revision 2 to Tech Spec Change Request
requesting amend to App A of License DPR-72 re emergency
power supply, diverse containment isolation, auxiliary feed
& min shift crew Certificate of Svc encl
BRIGHT, R.M. Florida Power Corp 80/12/31. App. 07389 145

--0101050264 Proposed Revision 2 to Tech Spec Change Request of
App A of License DPR-72 re emergency power supply, diverse
containment isolation, auto initiation of feedwater, auxiliary
feed flow indication & min shift crew.
* Florida Power Corp 80/12/31 20pp. 07389 149

0101050285 Forwards summary listing of proposed implementation
licensing submittal schedules in response to NRC 010131 ltr.
Drawings on aperture cards in 10B
BAYNARD, P.Y. Florida Power Corp 80/12/31. 14pp 07379 35

0101070422 Re-requests that Section 7.1 of App B to OL be deleted
Request was based on premise that area was adequately &
appropriately regulated by EPA NPDES & State of FL Dept of
Environment Regulation Permit
BRIGHT, R.M. Florida Power Corp 80/12/31 2pp 07410 136

0101150152 Ack receipt of nuclear safety review task force findings
of 800226 event Rept will be compared w/recommendations of
NREG-0667 & 0737 to identify areas needing improvement
Results of comparison will be provided Jan 1981
EISENHUT, D.O. Division of Licensing 80/12/31 2pp 07461

Inspection reports, IE Bulletins & correspondence

0101150024 Requests that until 800722 response to IE Insp Rept
50-302/80-23 be withheld from public disclosure
(ref 10CFR2.790)
BRIGHT, R.M. Florida Power Corp 80/09/22 2pp 07463 004

0101000221 Informs of nonapplicable Page 2-79A transmitted in
ltr responding to IE Bulletin 79-018 re environ
qualification of Class IE equipment Deletion of page
requested.
BAYNARD, P.Y. Florida Power Corp 80/11/19 2pp 07421 36

0101050124 Requests existing data, summaries & records of inservice
tests of containments upgraded prestressing tendons.
GMSL receiving contract to compile & review records of
tendons
EISENHUT, D.O. Division of Licensing 00/11/23 3pp

0101080052 Forwards safety evaluation re licensee actions taken in re-
sponse to IE Bulletin 79-13, "Cracking in Feedwater Bypass
Piping."
REID, R.W. Operating Reactors Branch 4 80/12/10 2pp 07461 341

--0101080058 Safety evaluation re licensee actions taken in re-
sponse to IE Bulletin 79-13, "Cracking in Feedwater Bypass Piping"
Augmented insps may be discontinued
* Operating Reactors Branch 4 80/12/10 2pp 07461 341

0101150150 Responds to IE Bulletin 80-21 No active valves in u
planned for use in safety-related sys at facility have
valve parts cast by Malcolm Foundry Co. Inc.
BAYNARD, P.Y. Florida Power Corp 80/12/13 1p 07462 192

0101060243 Forwards IE info Notice 80-44, "Actuation of ECCB i
Recirculation Mode While in Hot Shutdown" No written
response required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/12/13
1p 07391:349.

0101100013 Provides addl clarification re evaluation of svc re-
quirements by IE Bulletin 79-018 Actual svc
conditions of evaluated equipment were compared w/available
qualification data
BAYNARD, P.Y. Florida Power Corp. 80/12/22 3pp. 07443 33

0101100042 Ack receipt of 800730 & 1022 ltrs informing NRC of
taken to correct violations noted in Health Physics
Appraisal Rept 50-302/00-23
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/12/22
1p 07439:358.

--0101100046 Forwards Health Physics Appraisal Rept 50-302/00-
000616-27, notice of violation & notice of significant
appraisal findings
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
80/09/08. App 07438 001

--0101100048 Notice of violation from insp on 800516-27,
* Region 2, Atlanta, Office of the Director 80/08/03.
07438 003

010110193 IE Health Physics Appraisal Rept 20-302/80-25 on 800616-27
Nuclear Island failed to follow respiratory protection
procedures & failure to perform bioassays & medical
surveillance in timely manner
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Office of the
Director, OSHA, F. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07438 039

010110192 Forwards response to IE Bulletin 80-24, "Prevention of
Damage Due to Water Leakage Inside Containment" Oct 17, 1980
Insulation Point 2 Event 1 Closed cycle cooling water sys had
leak in reaction torient Pump 2 oil cooler header inlet
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07573 352

B. Periodic operating reports & related correspondence

010110196 Forwards monthly operating rpt for Dec 1980
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07477 174

--010110194 Monthly operating rpt for Dec 1980
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07477 175

B. Reportable occurrences, LERs & related correspondence

010110193 Forwards LER 80-053/03L-0
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07442 208

--010110191 LER 80-053/03L-0 on 801208 & 09, containment isolation valve
CAV-3 would not close after sampling pressurizer water
space failed by inadequate closing torque & faulty torque
switch valve stem lubricated Torque switch replaced
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07442 209

010110194 Forwards LER 80-052/03L-0
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07442 159

--010110192 LER 80-052/03L-0 on 801208, RCS desu equivalent 1-131
exceeded Tech Spec level Caused by leaking fuel pins &
anticipating desu equivalent scdno transient following RCS
transient RCS circulated through makeup & purification sys
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07442 160

010110190 Forwards LER 80-054/03L-0
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07442 205

--010110197 LER 80-054/03L-0 on 801210, regulating rod group insertion
Rods exceeded Caused by anticipated rod movements to
control reactor power burnout Rods added to reactor
coolant
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07442 206

010110198 Special Rept 80-03 on 801016, during Mode 1 power operation,
fuse in channel P32 blew, actuating EECs subsystem Caused by
failed relay in engineering safeguards cabinet 3B Relay was
replaced & functionally tested
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07472 139

010110195 Forwards LER 80-056/03L-0
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07471 297

--010110194 LER 80-056/03L-0 on 801219, atmospheric radiation monitor
AM-45 found inoperable, rendering control complex emergency
ventilation sys inoperable Caused by failed sample vacuum
pump due to normal LER Spent pump installed & tested
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07471 298

010110194 Forwards LER 80-055/03L-0
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07474 055

--010110195 LER 80-055/03L-0 on 801218, load sequency block 3 trip
circuit would not reset following actuation test Cause
caused to relay 42-7PAC3 but problem undetermined Relay
reinstalled & surveillance frequency doubled
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07474 056

010110192 RD on 801016 fuse in Channel R32 blew, initiating actuation
of EECs subsystem Channel 8 During Channel 1 pressure module
test Caused by failed relay in engineering safeguards
cabinet 3B Relay replaced & tested
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07469 279

010110197 Forwards LER 80-057/03L-0
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07513 034

--0101200455 LER 80-057/03L-0 on 801218, seal mat fabricated
nonapproved mat found installed in approx 13 hydraulic
snubbers Caused by failure to identify nonconforming mat
in receiving insp Personnel received training
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07438 039

DECKET 50-304 2104 NUCLEAR POWER STATION, UNIT 2
F. Security, medical, emergency & fire protection plans

0101100387 Ltr to all licensees of operating reactor plants,
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
8010102 & by applicants as part of FAR
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07438 039

0101120535 Advises of provisions of 10CFR50, App B, that are
to fire protection features of facility FR notice & summary
of staff requirements to resolve open items encl
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07438 039

--0101120542 Advises of typographical error in effective date
in FR notice & summary of staff requirements to resolve open items encl
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07438 039

B. Adjudicatory correspondence

0101100674 Forwards revised order for mod of license, correct
800829 order Hearing date also revised
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07438 039

--0101100680 Revised order amending Licenses DPR-39 & DPR-4
requesting by IE Bulletin 79-018 must be submitted to 1
by 801101
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07438 039

H. General correspondence

0101100280 Response to Nov 1980 ltr to President Carter re
structure cracks at facilities No cracks that will leak
radioactivity exist
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07438 039

J. Insurance & indemnity information

0101100608 Forwards guarantee of payment of deferred premium
OSFER, J. Commonwealth Edison Co 80/01/05 1p 07442

0101270737 Forwards Endorsement 4 to Binders EO-1, EO-2, EO-3
EO-30, EO-42 & EO-43 evidencing secondary financial
protection
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07442

P. Operating license status documents & correspondence

0101100581 "RELAP4/MQ17 Developmental Checkout Zion," code
checkout rept
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07445 220

0101100674 Forwards revised order for mod of license, correct
800829 order Hearing date also revised
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07445 220

--0101100680 Revised order amending Licenses DPR-39 & DPR-4
requesting by IE Bulletin 79-018 must be submitted to 1
by 801101
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07445 220

0101100254 Ltr to all licensees (except REP licensees) for
Revision 1 of inservice surveillance requirements for
snubbers under STS License amend application adding model
Tech Specs to App A should be submitted within 120 days
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07445 220

--0101100271 Revised Pages 3/4 7-22 through 20, B 3/4 7-5 &
STS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp.

0101220466 Ltr to all power reactor licensees & applicants
summary of 20110 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
[A] [M] [L] R. W. POOLE, Jr. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43p 07445 220

101140B49 Requests that util propose Tech Specs changes to require 23 ft of water above reactor vessel flange to assure fuel assemblies could be covered at all times during fuel movement
VARQA,B A Operating Reactors Branch 1 00/12/12 2pp 07461:332

101210445 Forwards response to questions on Rule 90 71c. "Periodic Updating of FBARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT,D G Division of Licensing 80/12/15 13pp

101160523 Forwards review of util evaluation of steady state steam generator operating level for purpose of maximizing draught time w/consideration for overfilling Current operating level is justified.
VARQA,B A Operating Reactors Branch 1 00/12/18 7pp 07472:123

101090715 Responds to 001126 memo re lack of groundwater monitoring program at Facility Map of station & elevations above sea level encl. Monitoring not required unless hydraulic gradient or recharge properties are suitable for contamination
BIRCKS,W J. Office of the Executive Director for Operations 80/12/23 23pp. 07430:304

01050900 Forwards response to NUREO-0737. No response provided for Breddon 1 Unit undergoing extensive and decontamination outage Requirements of NUREO-0737 will be addressed prior to startup of unit scheduled for June 1986
ABEL,J S. Commonwealth Edison Co 80/12/31 55pp

01140673 "Adequacy of Station Electric Distribution Sys Voltage, Zion Station, Unit 2." Informal rept
UDY,A C. Idaho National Engineering Laboratory FIN A-6256
0101140673 00/12/31 13pp 07461:116

01226631 "Critique of IPS Risk Study for Zion Nuclear Power Plant." Informal rept.
EUSLIX,A J., BARI,R A Brookhaven National Laboratory.
BNL-NUREO-28750. 00/12/31. 60pp 07499:198

01300318 Forwards Amends 59 & 56 to Licenses DPR-39 & DPR-4B, respectively & notice of issuance & availability
VARQA,B A Operating Reactors Branch 1 80/12/31 3pp 07587:011

0101300328 Amends 59 & 56 to Licenses DPR-39 & DPR-4B respectively, allowing reinjection of four fuel assemblies previously irradiated in both units back into Unit 1 to irradiate high burnup fuel for lost cycle.
VARQA,B A Operating Reactors Branch 1. 00/12/31 7pp 07587:014

0101300338 Notice of issuance & availability of Amends 59 & 56 to Licenses DPR-39 & DPR-4B, respectively.
VARQA,B A Operating Reactors Branch 1 80/12/31 2pp 07587:021

01090006 Forwards Revision 15 pages to CE-1-A.0A program topical rept. Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications.
ABEL,J S. Commonwealth Edison Co 01/01/02 1p.

0101090005 Revision to 5 pages to OA program topical rept.
Commonwealth Edison Co. CE-1-A R19. 81/01/02 57pp.

01090038 Forwards addl info in response to Section 5.1.1 of NUREO-0612. Info supersedes 801107 submittal. Detailed review of other sections of NUREO-0612 will be documented in 6-month rept.
TRAMM,T R. Commonwealth Edison Co 81/01/02 17pp. 07441:065.

01270584 Confirms intent to comply w/rept. "Interim Position for Containment Purge & Vent Valve Operation Pending Resolution of Isolation Valve Operability." Submits temporary plan for use when reactor not in refueling or cold shutdown mode.
TRAMM,T R. Commonwealth Edison Co 01/01/14 2pp. 07183:001.

01270617 Supplements util 010114 ltr re plans to use containment purge valves per NRC 791023 guidance. Discusses benefits of conducting containment purging.
TRAMM,T R. Commonwealth Edison Co. 81/01/14 2pp. 07183:001

01300750 Forwards Amends 60 & 57 to Licenses DPR-39 & DPR-4B, respectively & notice of issuance & availability.
VARQA,B A Operating Reactors Branch 1. 81/01/14. 3pp. 07583:191.

--8101300752 Amends 60 & 57 to Licenses DPR-39 & DPR-4B, respectively deleting surveillance requirements for valves physically disabled or removed from facility by plant mods from Tech Specs App A
VARQA,B A Operating Reactors Branch 1 01/01/14 12pp 07583:194

--8101300754 Notice of issuance & availability of Amends 60 & 57 Licenses DPR-39 & DPR-4B, respectively
VARQA,B A Operating Reactors Branch 1 01/01/14 2pp 07583:203

8101290270 Approves util 010114 mod to commitment to interim position re containment purge contingent on listed elements
VARQA,B A Operating Reactors Branch 1 01/01/15 2pp 07573:194

0101300816 Forwards Amends 61 & 58 to Licenses DPR-39 & DPR-4B, respectively, & notice of issuance & availability
VARQA,B A Operating Reactors Branch 1 81/01/15 3pp 07503:194

--8101300920 Amends 61 & 50 to Licenses DPR-39 & DPR-4B, respectively approving guard training & qualification plan & combining separate license conditions for security plan, safeguards contingency plan & guard training plan
VARQA,B A Operating Reactors Branch 1 81/01/15 4pp 07505:243

--8101300827 Notice of issuance & availability of Amends 61 & 50 Licenses DPR-39 & DPR-4B, respectively
VARQA,B A Operating Reactors Branch 1 81/01/15 3pp 07505:247

0101220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREO-0737 Task 111 A 2
DELEEDORCE,L O Commonwealth Edison Co 81/01/17 1p

--8101220374 "Offsite Dose Calculation Sys Meteorological Monitoring Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants." Revision 2
BOLDEN,J C Commonwealth Edison Co 00/07/31 130pp

--8101220379 "Study of Low Level Dispersion Over Northern IL." Murray & Trettel, Inc 74/06/10 106pp

0 Inspection reports, IE Bulletins & correspondence

0101090219 Forwards IE Info Notice 80-30. "Cracking in Charging Pipe Casing Cladding." No response required
KEPPLER,J O Region 3, Chicago, Office of the Director 80/10/2pp

8101090462 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by M. Foundry Co. Inc." Written response required
KEPPLER,J O Region 3, Chicago, Office of the Director 80/11/2pp

8101160152 Forwards IE Insp Rept 90-304/80-22 on 801022-23 No noncompliance noted.
REIMANN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/13 2pp 07469:351

--8101160156 IE Insp Rept 90-304/80-22 on 001022-23 No noncompliance noted. Major areas inspected. Cycle 5 core power distribution limits & control rod worth determination.
CHOULES,N C Region 3, Chicago, Office of the Director.
STREETER,J F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/13 4pp. 07469:353

8101050124 Requests existing data, summaries & records of inservice tests of containment w/greased prestressing tendons.
ORNL receiving contract to compile & review records of tendons.
EISENHUT,D G Division of Licensing 80/11/25 3pp

0101140091 Forwards IE Insp Repts 90-295/80-20 & 90-304/80-21 on 801001-1114 No noncompliance noted.
REIMANN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/28 2pp. 07460:297.

--8101140097 IE Insp Repts 90-295/80-20 & 90-304/80-21 on 001001-1114 No noncompliance noted. Major areas inspected operational safety verification, jumper & lifted lead log & Unit 2 reactor trip.
KOHLEER,J E, WATERB,J R, REIMANN,F W Region 3, Chicago, Office of the Director 80/11/28 14pp 07460:299

B101050530 Forwards IE Info Notice 80-43. "Failures of Continuous Water Level Monitor for Sicam Discharge Vol at Dresden Unit 2 - No response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/05.
2pp

B101150628 Forwards IE Insp Repts 80-295/80-22 & 80-304/80-24 on 801117-19 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/09 2pp 07465 255

--B101150634 Notice of violation from insp on 801117-19
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/09 1p 07465 257

--B101150640 IE Insp Repts 80-295/80-22 & 80-304/80-24 on 801117-19 Noncompliance noted corrective actions contained in RDE 80-295/80-45 & 80-295/80-47 & conformity measures
PHILLIPS, M P, JUNUSKA, A Q, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/12/03 8pp 07465 258

B101070214 Responds to IE Bulletin 80-11. "Masonry Wall Design - Date on previous ltr should read 820101, not 810101
RAUSCH, T J Commonwealth Edison Co 80/12/11 1p 07415 243

B101050073 Responds to IE Bulletin 80-23. "Failures of Boland Valves Mfg by Valcor Engineering Corp - Valves V70903-21-1 or V70903-21-3 not used in any safety-related functions Approx 40 manhours expended in bulletin review
RAUSCH, T J Commonwealth Edison Co 80/12/12 1p

B101070105 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required.
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/16 1p 07415 024

B101080093 Responds to NRC 800818 request for monthly status report re evaluations in response to IE Bulletin 79-14 Tabulations of piping sys w/stresses above FSAR levels & below operability limit encl
JAMECEA, R F Commonwealth Edison Co 80/12/22 5pp

B101060283 Forwards IE Insp Repts 80-295/80-23 & 80-304/80-25 on 801117-21 & notice of violation Notice of violation withheld (ref 10CFR2 790)
HINO, J A Region 3, Chicago, Safeguards Branch 80/12/23 2pp 07392 027

--B101060290 IE Insp Repts 80-295/80-23 & 80-304/80-25 on 801117-21 Noncompliance noted implementation of security change w/o Commission approval Details withheld (ref 10CFR2 790)
CHRISTOFFER, G, PIRTLE, O L Region 3, Chicago, Office of the Director HINO, J A Region 3, Chicago, Safeguards Branch 80/12/22 2pp 07392 029

B101200155 Forwards response to IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event)." Surveillance procedures of at least monthly repetition will be instituted by 010601.
RAUSCH, T J Commonwealth Edison Co 81/01/05 6pp

B101260675 Ack receipt of 801230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-295/80-22 & 80-304/80-24
FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 81/01/12 1p 07531 139

--B101260654 Responds to NRC 801209 ltr re violations noted in IE Insp Repts 80-295/80-22 & 80-304/80-24 Corrective actions.
recalibr of all OELI detectors at 1-yr intervals
ABEL, J B Commonwealth Edison Co 80/12/30 2pp 07531 160

6 Reportable occurrences, LERs & related correspondence

B101050340 Forwards LER 80-030/03L-0.
GRAESSER, K L Commonwealth Edison Co 80/12/24 1p 07385 088

--B101050345 LER 80-030/03L-0 on 801124, svc water inlet valve 2NDV-SW0002, failed to stroke to full open position. No cause stated. Valve operator & control circuit repaired
HARMOOD, R Commonwealth Edison Co 80/12/24 1p 07385 089

B101130550 Forwards LER 80-032/03L-0.
GRAESSER, K L Commonwealth Edison Co 81/01/07 1p 07454 154

--B101130559 LER 80-032/03L-0 on 801208, during PT-1 rod cluster control exercise, rod urgent alarm received Caused by faulty card in rod control logic cabinet Card replaced
KDVAR, K M Commonwealth Edison Co 81/01/07 1p 07454 157

B101130562 Forwards LER 80-031/03L-0
GRAESSER, K L Commonwealth Edison Co 81/01/08 1p 07454 169

--B101130571 LER 80-031/03L-0 on 801209, engine tripped after running unloaded for 3 minutes, placing auxiliary power sys in degraded mode Caused by loose overspeed trip level C-8 part JS-72-22A actuating master shutdown valve
KRAWCEZAK, A T Commonwealth Edison Co 81/01/08 1p 07454 170

V Operator Examinations

B101140471 Requests that JK Jousten be re-examined for senior operator license during wk of 810112
GRAESSER, K L Commonwealth Edison Co 80/12/01 1p 07461 345

DOCKET 80-305 WEAUWNEE NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FOAR.
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101140841 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open items encl. No open items for facility W/o encl
EISENHUT, D O Division of Licensing 80/11/24 3pp 07461 006

B101290256 Forwards comments re 800924 security guard training & qualification manual. Request response within 30 days. Further revisions & addl info are necessary. Comments withheld (ref 10CFR2 790)
VARQA, S A Operating Reactors Branch 1 81/01/06 2pp 07373 021

B101210315 Notification of 810115 meeting w/util in Bethesda. MO to discuss facility contingency plan Meeting closed to public.
LICCIARDO, R A Operating Reactors Branch 1 81/01/09 2pp 07488 229

B101270947 Notification of 810109 closed meeting w/util in Bethesda. MO re facility contingency plan
LICCIARDO, R A Operating Reactors Branch 1 81/01/09 2pp 07549 193

G Adjudicatory correspondence

B101100700 Forwards revised order for mod of license, correcting refs 800829 order. Hearing date also revised.
EISENHUT, D O Division of Licensing 80/09/19 2pp 07443 187

--B101100706 Revised order amending License DPR-43. Info requested by Bulletin 79-018 must be submitted to IE by 801101.
EISENHUT, D O Division of Licensing 80/09/19 6pp 07443 189

I Financial information

B101220355 Forwards cash flow for 1979 & cash flow projections for 1980 & 1981 per 10CFR140.21 requirements.
MATHENS, E R Wisconsin Public Service Corp 81/01/13 2pp 07496 356

J Insurance & indemnity information

B101210341 Forwards Endorsement 1 to NEL1A Policy EB-44 & Endorsement 50 & 51 to NEL1A Policy NF-204.
MATHENS, E R Wisconsin Public Service Corp 81/01/12 5pp 07487 225

P Operating license stage documents & correspondence

B101100780 Forwards revised order for mod of license, correcting refs 800829 order. Hearing date also revised.
EISENHUT, D O Division of Licensing 80/09/19 2pp 07443 187

--B101100706 Revised order amending License DPR-43. Info requested by Bulletin 79-018 must be submitted to IE by 801101.
EISENHUT, D O Division of Licensing 80/09/19 6pp 07443 189

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under 818 license amend application adding Model Tech Specs to App A should be submitted within 120 days. EISENHUT, D O Division of Licensing 80/11/20 1p.

--8101100271 Revised Pages 3/4 7-22 through 20.B 3/4 7-5 & 7-6 & 4-17 to 818 snubber inservice insp requirements e Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports." EISENHUT, D O Division of Licensing 80/11/26 8pp.

8101210445 Forwards responses to questions on Rule 50.71a, "Periodic Updating of FBARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame. EISENHUT, D O Division of Licensing 80/12/15 13pp.

8101050047 Confirms 001223 conversation re submittal of response to NURE0-0737 on 810103 SCIROCK, C A Wisconsin Public Service Corp. 80/12/23 1p 07385.276

8101050388 Responds to 791210 ltr & forwards request for addl info re long-term operability of containment purge & vent valves VAROA, S A Operating Reactors Branch 1. 80/12/23 3pp. 07464.277.

8101090529 Forwards responses to NURE0-0737 re post-TMI requirements. Util will meet most implementation dates specified in NURE0-0737. Other dates cannot be committed to w/o evaluating full impact of proposed mods. MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/09. 64pp. 07429.277.

8101220034 Forwards info in response to NRC 801014 ltr. Four overseas drawings encl. Aperture cards in POR MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/16. 3pp 07500.019.

8101260379 Requests Tech Specs revision to provide maint for basic acid transfer pumps. Class II amend payment encl. MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/20. 2pp. 07531.189

8101270625 Confirms 810109 telcon re high range radiation monitoring of auxiliary & shield bldg vents. Util implementing mod routing radioactive liquids back to containment. Monitoring & reroute sys scheduled for completion by 81001. MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/20 3pp. 07548.100

3 Inspection reports, IE Bulletins & correspondence

8101100202 Forwards IE Insp Rept 80-305/80-20 on 800901-30. No noncompliance noted. WEIBMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/10/29 2pp. 07437.326

--8101100209 IE Insp Rept 80-305/80-20 on 800901-30 No noncompliance noted. Major areas inspected operational safety verification, monthly maint observation & monthly surveillance observation. NELSON, R. L., FITZPATRICK, O. E., WARNICK, R. F. Region 3, Chicago, Office of the Director. 80/10/28. 6pp. 07437.328.

8101050232 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/30. 2pp. 07389.088

8101060650 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Velcor Engineering Corp." No written response is required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/31. 1p. 07392.186.

8101100795 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Operators." No written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/31. 2pp. 07444.108

8101060703 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/06. 2pp. 07400.257.

8101090441 Forwards IE Info Notice 80-40, "Excessive Nitrogen Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization." No written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/2pp. 07442.146.

8101060301 Forwards IE Info Notice 80-41, "Failure of Owing Check Valve in Orcey Heat Removal Sys at Davis Besse Unit 1." No response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/2pp. 07391.079.

8101080355 Forwards IE Insp Rept 80-305/80-23 on 800818-29.0904 & notice of violation. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/2pp. 07421.328

--8101080361 Notice of violation from insp on 800818-29.0904-05 e Region 3, Chicago, Office of the Director. 80/10/31. 4p. 07421.330.

--8101080375 IE Insp Rept 80-305 /80-23 on 800818-29.0904-05 & Noncompliance noted failure to follow procedures on calibr & surveillance & failure to establish record control accessibility. BAKER, K. R., JACKLIN, L. N., SCHULZ, R. D. Region 3, Chicago, Office of the Director. 80/10/31. 25pp. 07421.334.

--8101080375 IE Insp Rept 80-305 /80-23 on 800818-22.25-29.0904. Noncompliance noted failure to follow procedures on calibr & surveillance & failure to establish record control accessibility. BAKER, K. R. Region 3, Chicago, Reactor Construction & Engineering Support Branch. OILONER, M. L. Region 3, Chicago, Office of the Director. 80/10/31. 25pp.

8101060505 Forwards IE Bulletin 80-23, "Failures of Solenoid Valve Mfg by Velcor Engineering Corp." Written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/2pp. 07391.232.

8101070260 Forwards list identifying security badge number & class level for Region 3 personnel. Badge numbers for personnel identified by asterisks will be provided at later date. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/6pp. 07410.359.

8101140524 Forwards IE Insp Rept 80-305/80-21 on 101001-31. No noncompliance noted. WEIBMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/25 2pp. 07461.142.

--8101140531 IE Insp Rept 80-305/80-21 on 801001-31. No noncompliance noted. Major areas inspected operational safety verification monthly maint observation & headquarters requests followup. NELSON, R. L., FITZPATRICK, O. E., WARNICK, R. F. Region 3, Chicago, Office of the Director. 80/11/21. 5pp. 07461.144

8101050974 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Broom Discharge Vol at Dresden Unit 2." No response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/2pp. 07386.045.

8101070650 Responds to IE Bulletin 80-21 No Malcolm Foundry Co parts found at facility. MATHEWS, E. R. Wisconsin Public Service Corp. 80/12/11. 1p. 07415.276

8101100188 Forwards IE Insp Rept 80-305/80-27 on 801120 NRC pre results of licensee performance evaluation. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/2pp. 07445.032.

--8101100193 IE Insp Rept 80-305/80-27 re 801120 mgt meeting re regulatory performance of activities at facility. Encl licensee performance evaluation was presented. Performance found adequate. WEIBMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09. 11pp. 07445.034.

8101070098 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/1p. 07415.030.

810120316 Responds to IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp. No Valcor valves are used at facility."
MATHEWS, E. R Wisconsin Public Service Corp 81/01/02 1p
07468 232

8101220389 Responds to IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." Design change in progress to install differential pressure instrumentation on fan coil units, providing aid in leakage detection.
MATHEWS, E. R Wisconsin Public Service Corp 81/01/08 3pp
07500 263

8101220110 Ack receipt of 801111 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpt 50-305/80-19.
DAVIS, A. B Region 3, Chicago, Fuel Facility & Materials Safety Branch 81/01/09 1p 07501 360

--8101220114 Responds to NRC 801021 ltr re violations noted in IE Insp Rpt 50-305/80-19. Corrective actions add'l training for key personnel initiated & emergency preparedness upgraded.
MATHEWS, E. R Wisconsin Public Service Corp 80/11/11 2pp.
07501:361

8101300560 Ack receipt of 810107 ltr informing NRC of steps taken to correct violation noted in IE Insp Rpt 50-305/80-25.
Response inadequate Encl withheld (ref 10CFR2 7901.
KINDS, J. A Region 3, Chicago, Safeguards Branch 81/01/21. 2pp
07586 321

--8101300563 Responds to NRC 801212 ltr re violations noted in IE Insp Rpt 50-305/80-25. Corrective actions withheld (ref 10CFR2 7901)
MATHEWS, E. R Wisconsin Public Service Corp. 81/01/07 1p.
07586 323

R. Periodic operating reports & related correspondence

8101130586 Forwards monthly operating rpt for Dec 1980
MATHEWS, E. R Wisconsin Public Service Corp 81/01/00 1p
07453 272.

--8101130591 Monthly operating rpt for Dec 1980
RUTEN, G. H Wisconsin Public Service Corp 81/01/02 4pp
07493 273.

S Reportable occurrences, LERs & related correspondence

8101090708 Part 21 rpt re fire & bullet resistant doors which may not be in compliance w/applicable requirements. Util seeking labeling &/or specific assurance & proof of fire resistance from manufacturer Exhibits A-H withheld (ref 10CFR2 7901.
MATHEWS, E. R Wisconsin Public Service Corp. 80/11/20 4pp.
07579 046

8101060555 Forwards LER 80-041/01T-0
MATHEWS, E. R Wisconsin Public Service Corp 00/12/30 1p
07391:112

--8101060574 LER 80-041/01T-0 on 801216 IE Bulletin 79-018 Insp revealed three unsealed limit switches subj to failure in submerged condition. Caused by changed requirements since installation. Limit switches will be sealed.
BROKER, C. S Wisconsin Public Service Corp. 80/12/30 1p
07391 113

8101130435 Forwards LER 80-042/03L-0
MATHEWS, E. R Wisconsin Public Service Corp 81/01/09. 1p.
07494:096

--8101130440 LER 80-042/03L-0 on 801212, during 1B diesel generator testing, air start motors failed to disengage after generator startup & shutdown. Caused by valve stem & disc corrosion. Corroded parts replaced & generator returned to svc.
BROKER, C. S Wisconsin Public Service Corp 81/01/09 1p
07454:097.

8101280518 Forwards LER 80-043/03L-0 & updated LERs 00-042/03K-1 & 80-041/01K-1.
MATHEWS, E. R Wisconsin Public Service Corp 81/01/21. 1p.
07537:198

--8101280522 LER 80-043/03L-0 on 801223, boric acid transfer pump motor 1A tripped on overload. Caused by seal degradation from boric acid crystallization in seals during non-use. Pump restarted
BROKER, C. S Wisconsin Public Service Corp 81/01/22 1p
07537:199

--8101280528 Updated LER 80-042/03K-1 on 801212, diesel generator 1A start motors failed to disengage. Caused by corrosion of valve stem & disc causing valve to stick open. Corroded parts replaced.
BROKER, C. S Wisconsin Public Service Corp 01/01/22 1p
07537 200

--8101280535 Updated LER 00-041/01K-1 on 801216, during IE Bulletin 79-018 Insp, identified three limit switches not sealed, therefore susceptible to failure when submerged. Caused by judgement error during installation. Switches to be sealed.
BROKER, C. S Wisconsin Public Service Corp 01/01/22. 1p
07537 201.

09CKEY 50-306 FRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8101090392 Ltr to all licensees of operating reactor plants, CP Aides & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D. Q Division of Licensing 80/11/13 2pp.

8101130124 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility. FH notice & summary of staff requirements to resolve open items encl.
EISENHUT, D. Q Division of Licensing 00/11/24 App 07449:237

8101080249 Releases public version of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant."
FELTON, J. H Division of Rules and Records 80/12/01. 1p
07422 036

--8101080258 Forwards public version of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant."
Revision 1
HAYER, L. O Northern States Power Co 80/08/29. 1p. 07422 037

--8101080266 Revision 1 of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant."
Northern States Power Co 80/08/29 18pp 07422:039

8101060194 Notification of 001112 meeting w/util re draft emergency plan. Trip rpt encl.
MARTIN, R. E Operating Reactors Branch 3 80/12/15 2pp
07371:304

--8101060204 Trip rpt of 801115 visit to site re current reviews of draft emergency plans.
ATELSON, W. L., PAGLIARD, J. A Office of Inspection & Enforcement Office of the Director 80/12/11. 2pp 07391 306

8101220176 Forwards Chemical Engineering Branch fire protection safety evaluation for facilities. Proposed mods to fire barrier penetration seals, structural member coating & fire dampers are acceptable. Review status encl.
CLARK, R. A Operating Reactors Branch 3 00/12/29 8pp. 07509

8101300122 Forwards facility emergency planning info for placement LPDA W/c 8101080263
BOUBER, J. L Division of Rules and Records. 81/01/19. 1p.
07533:094

H General correspondence

8101100336 Responds to 001021 ltr requesting info re facilities info requested, except for security, can be inspected at PDR in Minneapolis, MN.
IPOLLITO, T. A Operating Reactors Branch 2. 80/11/17. 2pp.
07399:001

8101290639 Responds to 801203 request for info re emergency preparedness near facilities, for response to D Carlson 801101 concerns FEMA working w/state & local govt to ensure that planning & preparedness are completed.
BIRKSW, W. J. Office of the Executive Director for Operations 81/01/02 1p. 07576:141

--8101290667 Forwards D Carlson 801101 ltr re emergency planning at facilities. Requests response.
PROXNIRE, W Senate 80/12/03. 3pp 07576:142.

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under BTB license amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/28 1p

--B101100271 Revised Pages 3/4 7-22 through 21, 3/4 7-5 & 7-6 & 6-17 to BTB snubber inservice insp requirements
* Division of Licensing 80/11/28 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lemeller Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101210445 Forwards responses to questions on Rule 50.71c. "Periodic Updating of FBARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp

B101120031 Forwards Amends 44 & 38 to Licenses OPR-42 & OPR-60, respectively, safety evaluation & notice of issuance & availability.
CLARK, R Operating Reactors Branch 3 80/12/17 2pp 07445.350

--B101120056 Amends 44 & 38 to Licenses OPR-42 & OPR-60, respectively, revising common station Tech Specs re current logic for actuation of safety injection & limits for control rods & power distribution
CLARK, R Operating Reactors Branch 3 80/12/17 25pp 07445.352

--B101120057 Safety evaluation supporting Amends 44 & 38 to Licenses OPR-42 & OPR-60, respectively
* Office of Nuclear Reactor Regulation, Director. 80/12/17 5pp 07446.017

--B101120062 Notice of issuance & availability of Amends 44 & 38 to Licenses OPR-42 & OPR-60, respectively
CLARK, R Operating Reactors Branch 3 80/12/17 2pp 07446.024

B101050256 Forwards commitments to hardware, procedural & organizational implementation requirements of NUREG-0737 implementation dependent on equipment availability & firm regulatory position
MAYER, L O Northern States Power Co 80/12/30 36pp. 0737B.282

B101160445 Forwards supplemental info re 000131 license amend request, in response to Auxiliary Sys Branch Questions 1, 3, 4 & 6 & Structural Engineering Branch Questions 1, 2 & 5.
MAYER, L O Northern States Power Co. 81/01/14 13pp. 07472.009

B101200241 Forwards rept of ECCB outages, 1976-80, per NUREG-0737, Item 11, K. 3.17 ECCB outage frequency does not constitute excessive unavailability No Tech Spec changes are warranted
MAYER, L O Northern States Power Co. 81/01/16 2pp. 07486.226

O Inspection reports, IE Bulletins & correspondence

B101050266 Forwards IE Info Notice 80-30, "Cracking in Charging Pump Casing Cledding." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/30, 2pp. 07387.168

B101100776 Forwards IE Circular 80-23, "Potential Defects in Bololt Power Sys Emergency Generators." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/31, 2pp. 07444.119

B101060609 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization." No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/07 2pp. 07401.116

B101060367 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/11/10 2pp. 07391.067

B101050565 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Screen Discharge Vol at Dresden Unit 2." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/28 2pp 07390.337

B101070212 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type H-2 Spring Return to Neutral Control Switches." Technical problem has prevented rewiring of indicating lights for switches to show total circuit continuity
GILBERTS, D E Northern States Power Co 80/12/11 1p 07411

B101070082 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/28 1p 07415.044

B101290567 Forwards IE Insp Repts 50-282/80-18 & 50-306/80-18 on 801119-20 No noncompliance noted
HEIDEMAN, R F Region 3, Chicago, Reactor Operations Nuclear Branch. 80/12/18 2pp 07571.701

--B101290573 IE Insp Repts 50-262/80-10 & 50-306/80-18 on 801119-20 Noncompliance noted. Major areas inspected control rod drive & position indicator checks, core distribution limits & reactor shutdown margin determination
CHODURA, C C, ROBINSON, D L, STREETER, J F Region 3, Chicago, Office of the Director 80/12/11 5pp. 07571.303

B101300276 Forwards IE Insp Repts 50-282/80-19 & 50-306/80-19 on 801001-1130 & notice of deviation
HEIDEMAN, R F Region 3, Chicago, Reactor Operations Nuclear Branch 80/12/19 2pp 07586.229

--B101300294 Notice of deviation from Insp on 801001-1130.
* Region 3, Chicago, Office of the Director 80/12/19 1p 07586.231

--B101300308 IE Insp Repts 50-262/80-17 & 50-306/80-19 on 001001-1130 Noncompliance noted change to impose initial conditions on point procedures per IE Bulletin 80-12 not incorporated as committed
FEIERABEND, C C, BURGES, D L, LITTLE, W S Region 3, Chicago, Office of the Director 80/12/17 12pp. 07586.232

B101140336 Ack receipt of B01210 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/80-17 & 50-306/80-17.
HINO, J A Region 3, Chicago, Safeguards Branch. 80/12/22 1p 07470.369

--B101160392 Responds to NRC 801116 ltr re violations noted in IE Repts 50-282/80-17 & 50-306/80-17 Corrective actions withheld (ref 10CFR2.790)
GILBERTS, D E Northern States Power Co 80/12/10 1p 07470.361

B101200145 Responds to IE Bulletin 80-24, "Prevention of Damage Water Leakage Inside Containment (801017 Indian Point 2 Event)." Procedures for detecting leakage are part of post-accident monitoring instrument monthly check
GILBERTS, D E Northern States Power Co. 81/01/05 8pp. 07470.361

B101220398 Advises that util will be unable to meet schedule to implement mods re IE Bulletin 80-11, "Masonry Wall Design" by B10115. Full implementation of mods scheduled for completion by B10331.
GILBERTS, D E Northern States Power Co 81/01/08 2pp. 07571.303

R Periodic operating reports & related correspondence

B101120294 Forwards monthly operating repts for Dec 1980
MAYER, L O Northern States Power Co 81/01/07 1p 07442.350

--B101120297 Monthly operating repts for Dec 1980
HUNSTAD, A A Northern States Power Co 81/01/02 8pp. 07442.347

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP H & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FBAR.
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101180132 Advice of provisions of 10CFR50, App R, that are applicable to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl.
EISENHUT, D O Division of Licensing 80/11/24 4pp 07388 008

B101070980 Releases public version of utility draft emergency plan
FELTON, J M Division of Rules and Records 80/12/03 1p
07404 210

--B101070584 Forwards public version of draft utility emergency plan, Vol 2,
in response to NRC 791010 ltr
GRUCE, R H Maine Yankee Atomic Power Co 80/01/31 1p
07404 211

--B101070591 Public version of draft emergency plan, Vol 2
* Maine Yankee Atomic Power Co 80/01/30 77pp 07404 212

B101160410 Informs that review of emergency plan submittal indicates
encl addl info necessary before program can meet criteria
in NUREG-0454, Revision 1 Revised plan must be submitted
CLARK, R A Operating Reactors Branch 3 80/12/17 27pp
07471 344

B101140315 Requests that encl facility planning info be made publicly
available w/o encl
SCUDER, J L Division of Rules and Records 80/12/31 1p
07399 001

B101290167 Forwards facility emergency planning info to be made
publicly available, w/o encl
SCUDER, J L Division of Rules and Records 81/01/23 1p
07575 201

B101300542 Response to NRC B01224 ltr requesting info on implementation
of emergency preparedness exercise requirement. Exercise has
been scheduled for B10925
GARRITY, J H Maine Yankee Atomic Power Co 81/01/26 1p
07584 051

O Adjudicatory correspondence

B101090091 Order granting Bensible Maine Power motion for second FR
notice of opportunity for hearing due to B00929 license
amend application increasing spent fuel storage capacity
1A20, R M Atomic Safety and Licensing Board Panel 81/01/06 2pp
07426 358

B101290212 Responds to B01204 ltr on behalf of Bensible ME Power, re
published remarks by NRC official in support of long-term
storage plan at facility Position reflects generic issue
documented in NUREG-0575
DENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/13 1p 07309 001

B101280105 Forwards supplemental notice of proposed issuance of amend
to facility OL to be published in FR on B10128 per ASLB
B18106 order
MCURREN, H J Hearing Branch 1 81/01/26 1p 07556 084

--B101280114 Supplemental notice of proposed issuance of amend to
facility OL, revising Tech Specs to permit expansion of
spent fuel storage capacity
CLARK, R A Operating Reactors Branch 3 81/01/15 6pp
07556 085

H General correspondence

B101120213 Forwards NUREG-0575 for use in committee work w/o encl
REBBA, O Operating Reactors Branch 3 80/12/03 1p 07446 225

B101360198 Responds to B01201 ltr re E & R Miller B01110 ltr. EIA will
be prepared to consider utility proposal to replace existing
spent fuel storage racks w/ greater strength racks to provide
closer storage spacing for increased storage capacity
DITCKE, W J Office of the Executive Director for Operations
81/01/14 2pp 07183 001

--B101300206 Requests briefing matrix for response to encl E & R Miller
ltr re utility application for on-site nuclear waste storage
permit
MITCHELL, O J Senate, Environment & Public Works 80/12/01 3pp
07183 001

P Operating license stage documents & correspondence

B101140254 Ltr to all licensees (except BEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
shubbers under STB License amend application adding model
Tech Spec to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--B101140271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 4-1
STB shubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

B101280466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issues A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101180139 Forwards Page D 2-2, Figure S 2-1, omitted from B01201 Amend
30 to License DPR-36
CLARK, R A Operating Reactors Branch 3 80/12/12 4pp 07441 3

B101210445 Forwards responses to questions on Rule 50 710, "Periodic
Updating of FBARs" & FR notice of final rule. BEP plants need
not comply w/ rule until program is complete Non-BEP plants
must comply within specified time frame.
EISENHUT, D O Division of Licensing 80/12/15 13pp

B101140458 Forwards request for addl info re operational QA program
CLARK, R A Operating Reactors Branch 3 80/12/18 7pp 07461 1

B101680320 Responds to 80 Eisenhut B01031 ltr re containment pressure
setpoint Belpoint considered adequate. No changes planned.
RANDAZZA, J B Maine Yankee Atomic Power Co 80/12/22 2pp
07399 029

B101300837 "Adequacy of Station Electric Distribution Bus Voltages,
Maine Yankee Atomic Power Station." Informal rept.
UDY, A C EG&G Idaho, Inc FIN A-6296 B101300837 80/12/31
15pp 07584 093

B101220210 Forwards ECCB outage rept in response to B01031 ltr to all
licensees of operating plants.
RANDAZZA, J B Maine Yankee Atomic Power Co 81/01/07 4pp
07496 296

B101220340 Forwards info re iodine release during nuclear reactor
accidents & realistic estimates of reactor accident
consequences
GARRITY, J H Maine Yankee Atomic Power Co 81/01/16 3pp
07183 001

--B101220346 "Realistic Estimates of Consequences of Nuclear Accidents
presented at B01120 ANS conference in Washington, DC.
LEVYNSON, M. RAHAF, Electric Power Research Institute 80/11
30pp 07183 001

B101270368 Responds to NRC B01208 request for addl info re evaluation
of radiological aspects of B00929 submittal re spent fuel
pin storage. Methods described will allow ALARA objective to
be met & minimize need for scarce disposable resources.
GARRITY, J H Maine Yankee Atomic Power Co 81/01/16 5pp
07543 083

B101270657 Responds to NRC position that alternative scheme to mitigate
effects of grid degradation fails to comply w/ NRC generic
position Tech Spec changes re conditions for operation will
not provide meaningful enhancement of safety.
GRUCE, R H Maine Yankee Atomic Power Co 81/01/20 4pp
07349 025

B101270748 Submits rept on overall safety effect of power operated
relief valve isolation sys per B01031 request. Concludes that
automatic isolation of power operated relief valves are not
necessary & may not be in interest of improved safety.
RANDAZZA, J B Maine Yankee Atomic Power Co 81/01/20 2pp
07545 305

O Inspection reports, IE Outlets & correspondence

B101300026 Forwards IE Insp Rept 80-309/80-14 on B00902-1003 No
noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/11/07 2pp 07582 209

--0101300030 IE Insp Rept 50-309/80-14 on 000902-1003 No noncompliance noted Major areas inspected control room, turbine bldg, primary auxiliary bldg, spray bldg & auxiliary feed pump room & followup of IE Bulletin 79-018
MARTIN, T. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. LAZARUS, W. SWETLAND, P. Region 1, Philadelphia, Office of the Director. 80/10/22 14pp 07982 211

8101060885 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange - No written response required
GRIER, S.H. Region 1, Philadelphia, Office of the Director 80/11/26 1p 07396 340.

8101300083 Responds to IE Bulletin 80-23, "Failures of Seionold Valves Mfg by Velcor Engineering Corp." No subj valves used in safety-related functions at facility
RANOAZZA, J. B. Maine Yankee Atomic Power Co. 80/12/03 2pp 07579 330

8101050860 Forwards IE Info Notice 80-44, "Actuation of ECCB In Recirculation Mode While in Hot Shutdown - No written response required
GRIER, S.H. Region 1, Philadelphia, Office of the Director. 80/12/16 1p 07396 330

8101150101 Ack receipt of 801104 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/80-12
GRIER, S.H. Region 1, Philadelphia, Office of the Director 80/12/17 1p. 07469 305.

--8101160114 Responds to NRC 801015 ltr re violations noted in IE Insp Rept 50-309/80-12. Corrective actions surveillance program for nonsafety-related instruments established to monitor limiting conditions
RANOAZZA, J. B. Maine Yankee Atomic Power Co. 80/11/04. 2pp. 07469 306

--8101160123 Forwards IE Insp Rept 50-309/80-12 on 800825-29 & notice of violation
ORUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/19 2pp 07469 308

--8101160132 Notice of violation from Insp on 800825-29
* Region 1, Philadelphia, Office of the Director. 80/10/10 1p 07469 310.

--8101160145 IE Insp Rept 50-309/80-12 on 800825-29 Noncompliance noted failure to review & approve documents used for verification of safety-related parameters
BLUMBERG, N. Region 1, Philadelphia, Office of the Director
ORELIMAN, E. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/10. 12pp. 07469 311

R Periodic operating reports & related correspondence

8101290302 Forwards "Discharge Monitoring Rept, Dec 1980."
GARRITY, J.H. Maine Yankee Atomic Power Co. 81/01/26. 2pp. 87308 001

--8101290308 "Discharge Monitoring Rept, Dec 1980."
FLANDERS, W. Maine Yankee Atomic Power Co. 81/01/26 6pp. 07308 001.

V Operator Examinations

8101120229 Forwards "Shift Technical Advisor Program," per 80 Eleenhut 801031 ltr & NUREG-0737, "Clerification of Post-TMI-2 Requirements."
RANOAZZA, J. B. Maine Yankee Atomic Power Co. 81/01/08 4pp. 87437 347

--8101120233 "Shift Technical Advisor Program: Maine Yankee Atomic Power Co."
* Maine Yankee Atomic Power Co. 81/01/08 8pp. 07437 351.

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

E. NRC Safety Evaluation Report (SER), suppl's & correspondence

8101090882 Advises that Section 6.2.3.1 of draft Supplemental SER 5 should be examined Facility was granted exemption from requirement of General Design Criteria 57 re closed sys isolation valves
TEDESCO, R. L. Assistant Director for Licensing. 80/12/17. 1p. 07428 365

8101230298 Forwards NUREG-0517, draft Suppl 5 to SER, proposed OL, Specs & "Discussion of Environ Effects of U Fuel Cycle Activities Attributable to Operation of Salem Nuclear Generating Station, Unit 2."
MONTGOMERY, R. Office of Nuclear Reactor Regulation, Director 80/12/30 1p 07510 033

--8101230305 DRAFT SUPPLEMENT 5 TO SAFETY EVALUATION REPORT
* Office of Nuclear Reactor Regulation, Director NUREG-0517 85 80/12/29 217pp 07510 034

F Security, medical, emergency & fire protection plans

8101070551 Releases public version of util revised emergency plan
FELTON, J. M. Division of Rules and Records 80/11/14 1p 07309 001

--8101070557 Forwards public version of util 800930 revisions to emergency plan
LIBRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey 80/10/03 2pp 07309 001

--8101070562 Public version of revisions to emergency plan
* Public Service Electric & Gas Co. of New Jersey 80/09/30 40pp 07309 001.

8101000011 Forwards FR notice of revised Section 10CFR50.46 & App 10CFR50 re fire protection features of nuclear power plants Effective date for Criterion 3 of App A should be 000217 instead of 800219
TEDESCO, R. L. Assistant Director for Licensing 00/12/04 18p 07389 001

8101070533 Releases public version of revision to util emergency plan
FELTON, J. M. Division of Rules and Records 00/12/17. 1p 07404 147

--8101070540 Forwards public version of revision to emergency plan in response to NRC request for addl info.
LIBRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey 80/12/03. 1p. 07404 149

--8101070543 Public version of revision to emergency plan
* Public Service Electric & Gas Co. of New Jersey 80/12/03 26pp. 07404 154

8101200642 Releases public version of util revised emergency plan
FELTON, J. M. Division of Rules and Records 81/01/06 1p 07187 001

--8101200644 Forwards public version of revised sections of emergency plan in response to NRC request for addl info.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 80/12/19. 1p. 07107 001

--8101200645 Public version of revised sections of emergency plan
* Public Service Electric & Gas Co. of New Jersey. 80/12/19 150pp. 07187 001

8101270516 Requests revised ltr from NRC re-evaluating 800712 evacuation study. Lack of coordination of various NRC divs w/ respect to reviewing or issuing ltr re emergency preparedness appears evident.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 81/01/21. 1p 07549 067

O Adjudicatory correspondence

8101070418 Requests to make limited appearance statement at licensing hearing.
NOTERMAN, J. P. Affiliation Unknown. 00/12/27 1p. 07309 001.

J Insurance & indemnity information

8101210586 Forwards certified Endorsement 3 to NELIA Binder EB-72
CORREA, M. A. Marsh & McLennan, Inc., M & M Nuclear Consultants, Div. 81/01/14. 3pp 07409 081

8101270738 Forwards Endorsement 42 to NELIA Policy NF-230 & Endorsement 34 to MAELU Policy NF-90.
CORREA, M. A. Marsh & McLennan, Inc., M & M Nuclear Consultants, Div. 81/01/22. 3pp 07548 058

8101080274 Releases public version of emergency plan manual implementation procedures for facilities
FELTCH, J. M. Division of Rules and Records 80/11/14 1p
07321 095

--8101080299 Forwards public version of emergency plan manual implementation procedures for facilities
LIBR1221, F. P. Public Service Electric & Gas Co. of New Jersey
80/10/03 2pp 07421 095

--8101080305 Public version of emergency plan manual implementation procedures, Revision 12
SILVERIO, N. A. STILLMAN, J. L. Public Service Electric & Gas Co. of New Jersey 80/08/18 170pp. 07421 098

8101080190 Forwards confirmation that implementation dates in NUREG-0737 will be met, in response to NRC 801031 request
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey
80/12/09 10pp 07414 281

8101080797 Summary of 80120 meeting w/utl re safety-related reasoning
Calls No design criteria or QA/QC programs were established for initial const of masonry walls List of meeting attendees & agenda encl
KERRIGAN, J. Licensing Branch 3 80/12/11 6pp 07400 106

8101200634 Forwards AEC 480409 ltr. in response to request at 801200 re: hearing for facility licenses initiated 790619 meeting JWRAC
ROSS, H. J. Operating Reactors Branch 1 80/12/22 1p 07476 281

--8101200636 Forwards request for addl info needed to continue review of CP application. Includes info re adequacy of QC & insp procedures, site selection analysis, instrumentation & control info in FBAR & accident analysis
MORRIS, P. A. Atomic Energy Commission Directorate of Licensing
80/04/09 19pp 07476 282

8101190794 Forwards summary of 801210 meeting w/utl re utl mgt reorganization List of attendees encl
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 03/12/23 3pp 07473 078

8101230298 Forwards NUREG-0317, draft Suppl 5 to SER, proposed OL Tech Specs & Discussion of Environ Effects of U Fuel Cycle Activities Attributable to Operation of Salem Nuclear Generating Station, Unit 2.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
80/12/30 1p 07510 033

--8101230305 DRAFT SUPPLEMENT 5 TO SAFETY EVALUATION REPORT.
* Office of Nuclear Reactor Regulation, Director NUREG-0317 DRAFT
S5 00/12/29 217pp 07510 034

--8101230312 EIB (nonradiological) for facility.
* Office of Nuclear Reactor Regulation, Director 80/12/30
11pp 07510 256

--8101230320 Discussion of Environ Effects of U Fuel Cycle Activities Attributable to Operation of Salem Nuclear Generating Station, Unit 2. Explanatory narrative for Table B-3 encl
* Office of Nuclear Reactor Regulation, Director 00/12/30.
93pp. 07510 265

8101190586 Forwards request for addl info re masonry walls. Confirm actions utl must complete prior to issuance of BER
LEDESCO, R. L. Assistant Director for Licensing. 81/01/08 3pp.
07472 289

8101150382 Forwards logic diagrams & electrical schematics, per NRC 801208 request. Logic Diagram 239957-9-7646, dtd 11/8/76 revised to reflect design mod scheduled for completion during next refueling outage. Aperture cards in PDR.
UDERHIZ, R. A. Public Service Electric & Gas Co. of New Jersey.
81/01/09 1p 07462 203

8101180635 Forwards verification of previous correspondence as part of OL application
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey
81/01/12 5pp 07462 122

8101150629 Submits info on ECCB outages, per NUREG-0737, item 11.K.3.17. Unplanned outages are documented by incident reports. Planned outages are documented in daily log. Failure trends analyzed by review of LER's
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey
81/01/13 1p 07462 121

Washington, DC re full power OL for facility Pp 1-75 Draft
Suppl 5 to safety evaluation encl
* Com-lesconers 01/01/14 77pp. 07572 001.

--8101290675 Discusses mod of NUREG-0737 requirements for facility full power OL. Facility will be addressed as two units operating as two control rooms after 020701 for senior reactor operator training Shift training tables encl
HARRAHAN, E. J. Office of Policy Evaluations 81/01/14 3pp
07572 079

8101230441 Admits that overhead annunciator alarm vol has been modified. Results of testing determined that required vol of each annunciator speaker is unacceptably loud. Util proposes to reduce vol of each speaker
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey
81/01/16 2pp. 07510 310

0 Inspection reports, IE Bulletins & correspondence

8101090847 Ack receipt of 801017 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-272/80-19 & 80-311/80-14
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/07 1p 03893 224

--8101090852 Responds to NRC 800929 ltr re violations noted in IE Insp Repts 80-272/80-19 & 80-311/80-14. Corrective actions "hold" area established for rejected items & reject tags will be attached to deficient items
SCHNEIDER, F. H. Public Service Electric & Gas Co. of New Jersey
80/10/17 5pp 03893 225

--8101090859 Forwards IE Insp Repts 80-272/80-19 & 80-311/80-14 en 800728-0808 & notice of violation
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/27 2pp. 03893 230

--8101090863 Notice of violation from Insp en 800728-0808
* Region 1, Philadelphia, Office of the Director 00/09/25 2pp
03893 232

--8101090886 IE Insp Repts 80-272/80-19 & 80-311/80-14 on 000728-0336 Noncompliance noted. Failure to follow procedures for receipt, handling & storage of safety-related matl.
NAPUZA, O. J. SIMONETTI, G. Region 1, Philadelphia, Office of the Director GREENHAW, E. Q. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/25 14pp. 03893 234

8101060039 Responds to utcl 001104 ltr revising response to IE Bulletin 80-11, "Masonry Wall Design" & requesting extension until 001203 to complete detailed analysis of masonry walls at facilities. Extension is acceptable
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/19 1p 07392 214

8101070418 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Blade on Terry Turbine Steam Inlet Flange." No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
80/11/26 1p. 07414 047

8101100768 Responds to IE Bulletin 80-23, "Failures of Solenoid Valve Mfg by Valcor Engineering Corp." No sub valves used in safety-related function at facilities.
SCHNEIDER, F. H. Public Service Electric & Gas Co. of New Jersey
80/12/12 1p. 07443 359

8101060816 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
80/12/16 1p. 07397 045

R. Periodic operating reports & related correspondence

8101210435 Forwards monthly operating rpt for Dec 1980
MIGURA, H. J. Public Service Electric & Gas Co. of New Jersey.
81/01/12 1p 07493 156

--8101210458 Monthly operating rpt for Dec 1980
MILLER, L. W. Public Service Electric & Gas Co. of New Jersey
81/01/12 6pp 07493 157

transcripts on non-antitrust matters

Unofficial transcript of B10114 public discussion & vote in
San, DC re full power OL for facility PP 1-75 Draft
to safety evaluation encl
Commissioners B1/01/14 77pp 07572 001

Discusses mod of NUREO-0737 requirements for facility
power OL Facility will be addressed as two units
including two control rooms after B20701 for senior
operator manning shift manning tables encl.
JAN, E J Office of Policy Evaluations B1/01/14 3pp.
079

Examinations

Forwards info requested in NUREO-0737 re shift technical
training program, performance testing of PWR relief &
valves, containment min pressure setpoint &
detection for detection of inadequate core cooling
L. J. Public Service Electric & Gas Co of New Jersey.
140pp. 07309 001

Provides addl info re training program to qualify degreed
as senior reactor operator license candidates, in
to NRC B01031 request Successful Licensing of
plants will minimize routine overtime Related info encl.
R. R. H. Public Service Electric & Gas Co of New Jersey.
30pp. 07447 201

312 RANCHO SECO NUCLEAR GENERATING STATION

Emergency, medical, emergency & fire protection plans

Ltr to all licensees of operating reactor plants, CP holders
applicants Revised radiological emergency response
must be submitted by licensees within 60 days of
by applicants as part of FBAN.
O. O. Division of Licensing B0/11/13 2pp

Releases public version of revision to util draft emergency

J. M. Division of Rules and Records. B0/12/16 1p

Forwards public version of revision to draft emergency plan.
response to NRC B01010 request for addl info
DOE, W C Sacramento Municipal Utility District B0/12/02.
07309 001

Public version of revision to draft emergency plan.
Sacramento Municipal Utility District B0/11/10 150pp

Inform that licensee must conduct emergency exercise within
from B10401 or prior to issuance of OL Request
of drills & exercises.
R. H. Region 5, San Francisco, Office of the Director.
1p 07443:254

Releases ltr re util compliance w/emergency plan after
info review.

J. M. Division of Rules and Records. B1/01/08 1p

Discusses util compliance w/NRC emergency planning
elements. Emergency plan was originally submitted
Describes status of state & local govt emergency

W. K. Sacramento Municipal Utility District. B1/01/02
07495:196

Forwards facility emergency planning info for placement in
B101070564

J. L. Division of Rules and Records. B1/01/16. 1p

ing license stage documents & correspondence

Ltr to all licensees (except SEP licensees) forwarding
summary of inservice surveillance requirements for
under B18 License amend application adding model
ics to App A should be submitted within 120 days.
O. O. Division of Licensing. B0/11/20 1p.

Revised Pages 3/4 7-22 through 38.B 3/4 7-5 & 7-6 & 6-17 to
subber inservice insp requirements.
Division of Licensing B0/11/20. 10pp

0101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12. "Potential for Low Fracture
Toughness & Laminar Tearing on Component Supports."
EISENHUT, D O Division of Licensing B0/11/26 8pp

B101210445 Forwards responses to questions on Rule 50.71c. "Periodic
Updating of FSARs" & FR notice of final rule SEP plants to need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame.
EISENHUT, D O Division of Licensing B0/12/15 12pp

B101060946 Submits daily notes for B01223. Status of facilities in five
IE regions encl
DICKENS, W J Office of the Executive Director for Operations
B0/12/24 3pp 07401:107

B101130303 Advises that util takes exception to necessity of having
classification sys defining specific levels for equipment as
outlined in ANSI N45.2.2 Util program addresses requirements
for packaging based on needs of individual equipment
MATTHEW, J J Sacramento Municipal Utility District. B1/01/03 1p.
07447:275

B101270492 Forwards info per B01215 commitments for implementation of
NUREG-0737. "Clarification of TMI Action Plan Requirements."
Includes description of current shift technical advisor
training program & long-term program
MATTHEW, J J Sacramento Municipal Utility District B1/01/16
6pp 07540 196

G Inspection reports, IE Bulletins & correspondence

B101130675 Forwards IE Info Notice B0-34. "Bern Dilution of Reactor
Coolant During Steam Generator Decontamination." No written
response required
ENGELKE, R H Region 5, San Francisco, Office of the Director
B0/09/26 1p 07453 742

B101070656 Responds to IE Bulletin B0-23 No Valcor solenoid valves
mfg by Valcor Engineering Corp found
MATTHEW, J J Sacramento Municipal Utility District B0/11/24
2pp 07309 001

B101030124 Requests existing data, summaries & records of inservice insp
tests of containments w/grossed prestressing tendons
ORNL receiving contract to compile & review records of
tendons
EISENHUT, D O Division of Licensing B0/11/25 3pp

B101060095 Responds to IE Bulletin B0-21. "Valve Yokes Supplied by
Malcolm Foundry Co. Inc." No Malcolm valve parts used or
planned for use at Facility
WALBRIDGE, W C Sacramento Municipal Utility District B0/12/01
1p 07399 110

B101180140 Forwards Performance Appraisal Branch Mgt Insp Repts
50-219779-10, 50-312/B0-15 & 50-289/B0-21. IE Performance
Appraisal Branch mgt evaluation tree w/users guide for
chart, list of licensee recipients of rept & sample ltr encl.
CRICK, R H Region 1, Philadelphia, Office of the Director
B0/12/02 2pp 07466 020

B101120961 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects
in ASME BA-312 Type 304 Stainless Steel Pipe." No BA-312 or
A-312 Type 300 series fusion-welded pipe in use or planned
for use in safety-related sys
MATTHEW, J J Sacramento Municipal Utility District. B0/12/03 1p.
07447:196

B101100078 Ack receipt of B01119 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-312/B0-26.
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear
Support Branch B0/12/04 1p 07441 277

--B101100083 Responds to NRC B01107 ltr re violations noted in IE Insp
Rept 50-312/B0-26 Corrective actions air valves BFV 9350J,
BFV53604 & BFV 93210 will be isolated as required for
bldg integrity.
WALBRIDGE, W C Sacramento Municipal Utility District. B0/11/19
2pp 07441:278.

--B101100086 Ack receipt of B01017 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-312/B0-26 Addl
info required.
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear
Support Branch. B0/11/07 1p. 07441:280.

violation
CREWS, J. L. Region 5, San Francisco, Reactor Operations Nuclear
Support Branch 80/09/26 2pp 07441:285

--B101100397 Notice of violation from Insp on 800801-29
* Region 5, San Francisco, Office of the Director. 80/09/25
2pp 07441:287

--B101100103 IE Insp Rept 50-312/80-26 on 800801-29 Noncompliance noted
containment isolation valve design not in accordance
w/DCFR50 App A requirements
CANTER, H. L., O'BRIEN, J. Region 5, San Francisco, Office of the
Director FAULKENBERRY, B. Region 5, San Francisco, Reactor
Operations Nuclear Support Branch 80/09/25 8pp 07441:289

B101050496 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Steam Discharge Val at Dresden Unit 2."
No response required
ENGELKE, R. H. Region 5, San Francisco, Office of the Director
80/12/05 1p 07387:278

B101120553 Supp's response to Items 21(f) & 21(d) of IE Bulletin
80-00, "Elimination of Containment Liner Penetration Welds."
Forwards summary of radiographic test results, for
containment piping penetrations
MATTIMOE, J. J. Sacramento Municipal Utility District. 80/12/05
2pp 07447:189

B101060081 Forwards IE Insp Rept 50-312/80-34 on 801028-1106
CREWS, J. L. Region 5, San Francisco, Reactor Operations Nuclear
Support Branch 80/12/16 2pp 07309:031

--B101060009 IE Insp Rept 50-312/80-34 on 801028-1106 Noncompliance
noted closure of nonconformance repts & monthly repts not
made according to requirements
CANTER, H. L., YOUNG, T., PALMROS, M. Region 5, San Francisco, Office of
the Director 80/12/16 61pp.

B101150827 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No response
required
ENGELKE, R. H. Region 5, San Francisco, Office of the Director
80/12/16 1p 07308:001

B101210596 Forwards IE Insp Rept 50-312/80-31 on 801112-19 No
noncompliance noted
CREWS, J. L. Region 5, San Francisco, Reactor Operations Nuclear
Support Branch 80/12/17 2pp 07408:036

--B101210601 IE Insp Rept 50-312/80-31 on 801112-19 No noncompliance
noted Major areas inspected OK program, instrument calibr.
maint program & followup on IE bulletins & circulars
ZWEIHL, G. B. Region 5, San Francisco, Office of the Director
FAULKENBERRY, B. Region 5, San Francisco, Reactor Operations
Nuclear Support Branch. 80/12/16 10pp. 07458:038

B101100441 Forwards safety evaluation re util 790615, 0727 & 0813
responses to IE Bulletin 79-13, "Cracking in Feedwater Sys
Piping."
REIO, R. W. Operating Reactors Branch 4 80/12/24 3pp 07445:063

--B101100449 Safety evaluation re actions taken in response to IE
Bulletin 79-13, "Cracking in Feedwater Sys Piping."
Exemption to bulletin requirements should be granted.
* Operating Reactors Branch 4. 80/12/24. 21pp. 07445:066

B101270523 Forwards response to IE Bulletin 80-24, "Prevention of
Damage Due to Water Leakage Inside Containment (801017
Indian Point 2 Event)." Present liquid level detection sys
provides adequate detection protection
MATTIMOE, J. J. Sacramento Municipal Utility District. 81/01/06.
13pp. 07309:001

B101220303 Forwards Amend 1 to util 801031 response to IE Bulletin
79-018, "Environ Qualification of Class IE Equipment." Amend
adds info received from vendors since 801101, revises App B &
clarifies basis for interim operation.
MATTIMOE, J. J. Sacramento Municipal Utility District. 81/01/13.
300pp 07494:099

8 Reportable occurrences, LERs & related correspond

B101120260 Advises that util 790928 ltr re inadvertent
during surveillance testing adequately addresses c
IAC 790921 & 0626 ltrs Matter is resolved for fac
REIO, R. W. Operating Reactors Branch 4 80/12/19

B101060773 Forwards LER 80-048/02L-0
MATTIMOE, J. J. Sacramento Municipal Utility District
2pp 07395:027.

--B101060781 LER 80-048/02L-0 on 801201, while review
program & surveillance procedures, two remotely o
reactor bldg isolation valves discovered not tes
required by Tech Specs Caused by delation of que
* Sacramento Municipal Utility District 00/12
07395:029

B101130492 Forwards LER 80-047/01T-0.
MATTIMOE, J. J. Sacramento Municipal Utility District
2pp 07454:121

--B101130517 LER 80-047/01T-0 on 801222, IE Bulletin
lack of qualification documentation for flow tra
utilized to establish dilution flow to prevent h
precipitation following LOCA Cause not stated.
COLMBO, R. W. Sacramento Municipal Utility Distr
1p 07454:123

B101160427 RGE 80-50 & B1-1 re motor starter coils &
reading, respectively. Licensee was informed that fi
Site 3 motor starter coils will not pick up & seal
state during degraded voltage & upostulated LOCA
DUSRE, R. P. Sacramento Municipal Utility District
07309:001.

B101200221 RGE 80-50 & B1-1. Bechtel advised util tha
motor starter coils will not pick up & seal in ste
condition Second, unrelated occurrence concerns esc
west perimeter TLO monitor reading.
DUSRE, R. P. Sacramento Municipal Utility District
07476:346

B101200281 Forwards LER 80-049/03L-0.
MATTIMOE, J. J. Sacramento Municipal Utility District
2pp 07487:030

--B101200288 LER 80-049/03L-0 on 801219, during perfor
B diesel generator failed to start Cause not sta
declared operable 801222 after passing applicabl
surveillance test
COLMBO, R. W. Sacramento Municipal Utility Distr
1p 07487:032

B101230598 Forwards LER 80-050/04T-0.
MATTIMOE, J. J. Sacramento Municipal Utility Distr
2pp 07512:256.

--B101230602 LER 80-050/04T-0 on 801010, environ TLO
parameter fence indicated dose rates above Tech
by close proximity to drum storage area. Bulk res
storage bldg will be constructed.
COLMBO, R. W. Sacramento Municipal Utility Distr
1p. 07512:258.

B101280297 Forwards LER 81-001/02T-0.
MATTIMOE, J. J. Sacramento Municipal Utility Distr
2pp. 07308:001.

--B101280302 LER 81-001/02T-0 on 801018, AE notified
control room air conditioner size 3 starter coil
operate at degraded voltage Caused by design erri
mid will be performed during next refueling out
COLMBO, R. W. Sacramento Municipal Utility Distr
1p. 07308:001

DOCKETED ITEMS

operator Examinations

270492 Forwards info per 001215 commitments for implementation of REG-0737. "Clarification of TMI Action Plan Requirements" includes description of current shift technical advisor training program & long-term program
FRIMBLE, J. J. Sacramento Municipal Utility District 01/01/16
pp 07540 196

ET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

security, medical, emergency & fire protection plans

390387 Ltr to all licensees of operating reactor plants, CP holders & P applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 3102 & by applicants as part of FSAR
EISENHUT, D. O. Division of Licensing 00/11/13 2pp 07422 243

370460 Forwards proprietary comments on necessary revisions to & II info, needed re util 800909 revised security training & classification plan Comments withheld (ref 10CFR2.790)
D. R. W. Operating Reactors Branch 4 80/12/17 2pp 07415 311

40215 Informs that licensee should conduct emergency exercise within one yr from 800401 or prior to issuance of OL schedule of drills should be provided
FRIT, K. V. Region 4, Dallas, Office of the Director 00/12/23
07461 256

390595 Forwards response to NRC 801015 ltr requesting info re sponsored vital area analysis of facility info withheld (ref 10CFR2.790)
HUBLE, D. C. Arkansas Power & Light Co 80/12/31 1p 07427 353

80434 Forwards revisions & proposed changes to industrial security plan Revisions withheld (ref 10CFR2.790)
HUBLE, D. C. Arkansas Power & Light Co 81/01/02 2pp 07419 348

00394 Requests that oncl facility emergency planning info be made publicly available w/o oncl.
OER, J. L. Division of Rules and Records 81/01/09 1p
06:313

60673 Releases public version of util upgraded emergency plan.
TOM, J. M. Division of Rules and Records 01/01/16 1p
33:015

1260678 Forwards public version of upgraded emergency plan Includes state of AR radiological incident response plan & Pope, Johnson, Veil & Logan Counties, AR emergency plans.
FRIMBLE, D. C. Arkansas Power & Light Co 01/01/02 1p
7533:016

1260683 Public version of upgraded emergency plan. Includes State of AR radiological incident response plan & Pope, Johnson, Veil & Logan Counties, AR emergency plans
Arkansas Power & Light Co 81/01/01 800pp 07533 017

insurance & indemnity information

70742 Forwards Endorsement 30 to NELIA Policy MF-74 & Endorsement 30 to NELIA Policy NF-210.
HUBLE, D. C. Arkansas Power & Light Co. 01/01/21 4pp 07309:001

operating licensee stage documents & correspondence

20150 Clarifies intent of plans for position task analysis of several of personnel interviews w/personnel in positions of unclear responsibilities will not be complete until 101.
ANAUGH, W. Arkansas Power & Light Co. 80/11/19 4pp 07446 152

30254 Ltr to all licensees (except SEP licensees) forwarding list of inservice surveillance requirements for operators under BFB. Licensee amend application adding model 1 Specs to App A should be submitted within 120 days.
EISENHUT, D. O. Division of Licensing 80/11/20 1p 07443:274

1100271 Revised Pages 3/4 7-22 through 28.8 3/4 7-5 & 7-6 & 6-17 to FS snubber inservice insp requirements.
Division of Licensing 80/11/20 10pp 07443:278

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D. O. Division of Licensing 80/11/26 8pp

8101140601 Notifies that Class IV amend fee is required for util 801031 Cycle 5 reload rept
01605, R. M. License Fee Management Branch 00/12/08 1p
07462 009

8101210445 Forwards responses to questions on Rule 50.710. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D. O. Division of Licensing 80/12/19 13pp 07489 087

8101120234 Forwards safety evaluation re final design & implementation of safety-grade anticipatory reactor trip on turbine trip or loss of main feedwater
REID, R. W. Operating Reactors Branch 4 00/12/16 2pp 07446 313

--8101120239 Safety evaluation re final design & implementation of safety-grade anticipatory reactor trip on turbine trip or loss of main feedwater Design is acceptable
Operating Reactors Branch 4 80/12/16 5pp 07446 314

8101090950 Forwards Amend 49 to License DPR-51, safety evaluation & notice of issuance & availability
REID, R. W. Operating Reactors Branch 4 80/12/19 2pp 03893 316

--8101090953 Amend 49 to License DPR-51, changing power operated relief valve setpoint to 2,450 psig & high pressure reactor trip setpoint to 2,300 psig
REID, R. W. Operating Reactors Branch 4 00/12/19 10pp
03893 318

--8101090956 Safety evaluation supporting Amend 49 to License 51
Office of Nuclear Reactor Regulation, Director 80/12/19 3pp
03893 328

--8101090959 Notice of issuance & availability of Amend to License DPR-51
REID, R. W. Operating Reactors Branch 4 80/12/19 2pp
03893 331

8101050418 Advises that NRC 001113 ltr re NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking," does not pertain to Facilities Facilities are PHRs No response action will be taken
FRIMBLE, D. C. Arkansas Power & Light Co 00/12/29 1p 07389 324

8101050344 Forwards "Thermal-Mechanical Rept: Effect of HPI on Vessel Integrity for Break LOCA Event w/Extended Loss of Feedwater," in response to NUREG-0737, Item II K 2 13
FRIMBLE, D. C. Arkansas Power & Light Co 80/12/31 1p 07389 289

8101060355 Forwards info re NUREG-0737, in response to NRC 801031 ltr Includes info re shift technical advisor procedures for transients & accidents, plant shielding & thermal shock rept
FRIMBLE, D. C. Arkansas Power & Light Co 80/12/31 9pp 07393:348

8101150177 Forwards rept on power operated relief valve opening probability per requirements of NUREG-0737, Items II K 3 2 & II K 3 7
FRIMBLE, D. C. Arkansas Power & Light Co 81/01/00 17pp
07462 214

8101160406 Response to NUREG-0737, "Reporting of Safety Valve & Relief Valve Failures & Challenges" Onp challenge to electromagnetic relief valve occurred at Unit 1 from Apr-Dec 1900 No challenges to primary sys code occurred at Unit 2
FRIMBLE, D. C. Arkansas Power & Light Co 81/01/08 1p 07470 167

8101200247 Response to NRC 801208 request for payment for review of licensees 801031 Cycle 5 reload rept. Submittal was preliminary rept Fee will be submitted w/final Cycle 5 reload rept on 810201.
FRIMBLE, D. C. Arkansas Power & Light Co 81/01/13 1p 07486:220

8101230536 Forwards Oames & Moore rept entitled "Task 1 - Analytical Approach, Site-Specific Characteristics at AR Nuclear One." Requests NRC review Rept was formulated as first in series of Repts to assist in implementation of App 2 of NUREG-0654
FRIMBLE, D. C. Arkansas Power & Light Co 81/01/13 2pp 07511:16

810109201 Advises that Unit 601015 preliminary emergency feedwater upgrade design restriction is acceptable. Schedule required for addl design submittals Tech Spec & Final Incident Report
SEVFRIT, K V Assistant Director for Operating Reactors 81/01/15 2pp 07491 412

810101016 Forwards questions or recommendations of BAW-1354, "Integrated Control Sys Reliability Analysis," in response to AEP 791127 request
TRIMBLE, D C Arkansas Power & Light Co 81/01/16 2pp 07495 258

810101019 Forwards revised valve specific responses to NRC 800225 questions re: high-pressure low pressure turbine rotor New info results from more sophisticated calculations model
Regulate info on ultimately (ref 10CFR2 790)
TRIMBLE, D C Arkansas Power & Light Co 81/01/19 1p 07308 001

810101044 Nonproprietary release of Low Pressure turbine disc info - Westinghouse Electric Corp 80/09/22 21pp 07308 001

810101045 Requests classification of position re items 11 B 1 & 11 B 4 in 80-12-0737 re reactor coolant sys vents & training for investigating pipe damage
TRIMBLE, D C Arkansas Power & Light Co 81/01/19 2pp 07343 090

810101046 Inspection reports IE Bulletins & correspondence

810101047 Responds to IE Bulletin 79-17 re pipe cracks in stagnated treated water sys at PWRs. Cause discovered in heat affected areas of three welds in reactor dldg spray sys on 800121
TRIMBLE, D C Arkansas Power & Light Co 80/11/11 4pp 07446 162

810101048 Forwards IE Insp Repts 50-313/86-21 & 50-368/80-21 on 800922-1021 & notice of violation
SEVFRIT, K V Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/19 2pp 07431 350

810101049 Notice of violation from Insp on 800922-1021
SEVFRIT, K V Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/18 2pp 07431 352

810101050 IE Insp Repts 50-313/80-21 & 50-368/80-21 on 800922-1021
Noncompliance noted operability of high pressure safety injection pump & failure to sample reactor coolant sys as required
SEVFRIT, K V CALLAHAN, J J HANFICUTT, D M Region 4, Dallas, Office of the Director 80/11/18 7pp 07431 335

810101051 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (October 17, 1980 Indian Point Event)" - written response required
SEVFRIT, K V Region 4, Dallas, Office of the Director 80/11/21 1p 07425 250

810101052 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Sparger Fluid" - No response required
SEVFRIT, K V Region 4, Dallas, Office of the Director 80/11/24 1p 07425 303

810101053 Responds to IE Bulletin 80-23 re Valve solenoid valves No such valves installed at facilities Three months expended
TRIMBLE, D C Arkansas Power & Light Co 80/11/24 1p 07446 156

810101054 Requests existing data, summaries & records of inservice Insp tests of containment welded prestressing tendons
RMC receiving contract to compile & review records of tendons
EISENHART, D C Division of Licensing 80/11/25 3pp 07378 353

810101055 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Turbine Steam Inlet Flange" - No written response required
SEVFRIT, K V Region 4, Dallas, Office of the Director 80/11/26 1p 07291 109

810101056 Forwards corrected Pages 6 & 7 of IE Insp Repts 50-313/80-21 & 50-368/80-21
MADEIRA, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/26 1p 07401 050

810101057 Corrected Pages 6 & 7
Region 4, Dallas, Office of the Director 80/11/26 2pp 07401 051

810109024 Ack receipt of 800924 ltr informing NRC of correct violations noted in IE Insp Repts 50-368/80-21 & 50-313/80-13 Addl info required within 20 days
KELLY, J A Region 4, Dallas, Office of the Director 2pp 07425 271

810109025 Responds to NRC ltr re violations noted in 50-368/80-13 & 50-313/80-13 Corrective actions w/ (ref 10CFR2 790)
TRIMBLE, D C Arkansas Power & Light Co 80/09/24 07425 273

810101044 Informs of progress since 800731 ltr re IE concerning hydromotor actuator deficiencies Vendor detailed
TRIMBLE, D C Arkansas Power & Light Co 80/12/04

810101058 Ack receipt of 801010 & 1112 ltrs informing taken to correct violations noted in IE Insp Repts 50-313/80-16 & 50-368/80-16
MADEIRA, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/12/09 1p 07415 119

810101064 Responds to NRC 801023 ltr re violations noted in Repts 50-313/80-16 & 50-368/80-16 Corrective action audit repts will be reviewed by plant safety team
TRIMBLE, D C Arkansas Power & Light Co 80/11/11 07415 120

810109067 Forwards IE Info Notice 80-43, "Failures of Level Monitor for Steam Discharge Vol at Dresden Unit 2" - response required
SEVFRIT, K V Region 4, Dallas, Office of the Director 1p 07391 026

810101074 Responds to IE Bulletin 80-21 re valve gaskets
Foundry Co, Inc No valve parts in safety-related sys
Malcolm Foundry Co, Inc
TRIMBLE, D C Arkansas Power & Light Co 80/12/08

810101092 Forwards IE Info Notice 80-44, "Actuation Retraction Mode While in Hot Shutdown" - No written response required
SEVFRIT, K V Region 4, Dallas, Office of the Director 1p 07391 300

810101005 Forwards IE Insp Repts 50-313/80-19 & 50-368/80-19 & notice of violation Notice of violation withheld (ref 10CFR2 790)
KELLY, J A Region 4, Dallas, Office of the Director 2pp 07443 057

810101008 IE Insp Repts 50-313/80-19 & 50-368/80-19
Noncompliance noted guards w/o continuous monitoring
licensee authorization lists not prepared Details withheld (ref 10CFR2 790)
EVANS, C A, KELLY, J A Region 4, Dallas, Office of the Director 80/10/31 2pp 07413 059

810101034 Forwards requests for addl info re emergency reliability, based on review of licensee 791220 submittal
TMI action plan, IE Bulletins 79-05, 05A & 05B & NUREG criteria
REID, R W Operating Reactors Branch 4, 81/01/12

810101035 Periodic operating reports & related correspondence

8101010269 Forwards Intake Impingement data for Nov 1980
TRIMBLE, D C Arkansas Power & Light Co. 80/12/23

81010103075 Intake Impingement data for Nov 1980
Arkansas Power & Light Co. 80/12/19 12pp

8101010490 Forwards monthly operating rpt for Dec 1980
TRIMBLE, D C Arkansas Power & Light Co. 81/01/15

8101010494 Monthly operating rpt for Dec 1980
BRAMLETT, L B Arkansas Power & Light Co. 81/01/17 07490 168

8101010936 Forwards results of Intake Impingement monitoring for Dec 1980 per ETB 4.1.2 1(2)
TRIMBLE, D C Arkansas Power & Light Co. 81/01/29

81010109340 Results of Intake Impingement monitoring for Dec 1980
Arkansas Power & Light Co 81/01/26 16pp

sporadic occurrences, LERs & related correspondence

050320 Forwards revised LER 80-011/03X-B
HBLE.D C Arkansas Power & Light Co 80/12/26 1p 07385 083

01050438 Revised LER 80-011/03X-B on 800401, encl list of 54 hangers
declared inoperable per piping sys as-built configuration
review required by IE Bulletin 79-14 Caused by defective
design Review continuing
HIVELV, C N Arkansas Power & Light Co 80/12/26 2pp
07385 084

050331 Forwards LER 80-041/03L-0
HBLE.D C Arkansas Power & Light Co 80/12/26 1p 07385 086

01050336 LER 80-041/03L-0 on 801128, lead 41 hydrogen purge supply Pan.
BF-33A, tripped Caused by blown control fuse due to
voltage control power fuse & control transformer
increased to accommodate increased load
HIVELV, C N Arkansas Power & Light Co 80/12/26 1p
07385 087

050463 Forwards revised LER 80-011/03X-7
HBLE.D C Arkansas Power & Light Co 80/12/26 1p 07390 196

050537 Revised LER 80-011/03X-9, on 800401, encl list of 46 hangers
declared inoperable per piping sys as-built configuration
review required by IE Bulletin 79-14 Caused by defective
design Review continuing
HAMLET, L S Arkansas Power & Light Co 80/12/26 2pp
07390 197

050543 Forwards revised LER 80-039/03L-1
HBLE.D C Arkansas Power & Light Co 01/01/08 1p 07454 145

01050546 Revised LER 80-039/03L-1 on 801028, during monthly
surveillance on lead H purge sys, exhaust fan VEF-37A
ripped Caused by short in control sys which caused
effector to fail & fuse to blow
HAMLET, L S Arkansas Power & Light Co 01/01/08 2pp
07454 146

error Examinations

050555 Forwards info re NUREG-0737, in response to NRC 801031 ltr
ludes info re shift technical advisor procedures for
incidents & accidents, plant shielding & thermal shock rept
HBLE.D C Arkansas Power & Light Co 80/12/31 9pp 07393 346

050556 Requests clarification of position re items II B 1 & II D 4
NUREG-0737, re reactor coolant sys vents & training for
gating core damage
HBLE.D C Arkansas Power & Light Co 01/01/12 3pp 07543 070

050315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1
unity, medical, emergency & fire protection plans

050397 ltr to all licensees of operating reactor plants, CP holders
re applicants Revised radiological emergency response
re must be submitted by licensees within 60 days of
02 & by applicants as part of FSAR
HNUOT, D O Division of Licensing 80/11/13 2pp

010170 Advises of provisions of 10CFR50, App R, that are applicable
the protection features of facility FR notice & summary
re FR requirements to resolve open items encl. No open
re for facility, W/O encl
HNUOT, D O Division of Licensing 80/11/24 3pp 07452 150

0461 Requests relief from required 810102 submittal date for
and emergency plan. Delay needed in order to permit mgt
of state & county emergency plans, final typing &
ting Plan will be submitted by 810126
ER, R B Indiana & Michigan Electric Co 80/12/30 2pp
07465

050579 Forwards App C to modified amended security plan in response
01031 ltr Plan withheld (ref 10CFR2.790)
ER, R B Indiana & Michigan Electric Co 01/01/20 1p
07465

indicatory correspondence

050522 Forwards revised order for mod of license, correcting refs
00829 order Hearing date also revised
HNUOT, D O Division of Licensing 80/09/19 3pp 07444 280

--810100549 Revised under amending license, DPR-58 & DPR-74 info
requested by IE Bulletin 79-018 must be submitted to IE
by 801101
EISENHUT, D O Division of Licensing 80/09/19 6pp 07444 282

P Operating license stage documents & correspondence

810100932 Forwards revised order for mod of license, correcting refs
in 800829 order Hearing date also revised
EISENHUT, D O Division of Licensing 00/09/19 3pp 07444 280

--8101160547 Revised order amending Licenses DPR-58 & DPR-74 info
requested by IE Bulletin 79-018 must be submitted to IE
by 801101
EISENHUT, D O Division of Licensing 80/09/19 6pp 07444 282

8101100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
submitters under SIB license amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--8101100274 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-17
SIB submitter inservice insp requirements
4 Division of Licensing 00/11/20 10pp

8101220466 ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

0101160530 Forwards notification of 801218 meeting w/uttl to discuss
ultimate strength of containment & hydrogen control
measures. Uttil should be prepared to discuss equipment hatch
cover & structural analysis Analysis guidelines encl
NOVA, I H Assistant Director for Operating Reactors 80/12/11
4pp 07471 194

8101210445 Forwards responses to questions on Rule 50.7(e), "Periodic
Updating of FSARs" & FR notice of final rule SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp

8101150368 Summary of 801219 meeting w/uttl re ultimate strength of
containments & hydrogen control measures for containments
MINER, S Operating Reactors Branch 1 81/01/02 5pp 07463 226

8101210242 Forwards House Rept 96-1492, "Twenty-Eighth Rept by
Committee on Govt Operations," in response to uttl 801229
request W/O encl
HEIDMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support
Branch 81/01/05 1p 07492 039

8101160021 Confirms plans for 810113 meeting in Glen Ellyn, IL to
discuss recent events at facility
KEPPLER, J O Region 3, Chicago, Office of the Director 81/01/06
1p 07467 301

8101130217 Forwards response to NRC 801031 ltr re implementation of
post-TMI requirements contained in NUREG-0737
HUNTER, R B Indiana & Michigan Electric Co 81/01/08 34pp
07449 320

8101190512 Forwards "First Quarterly Rept on Hydrogen Issues," per
801007 submittal "Summary of Analyses of DC Cook
Containment Response to Hydrogen Transients" encl
HUNTER, R B Indiana & Michigan Electric Co 81/01/12 1p
07183 001

--8101190513 "First Quarterly Rept on Hydrogen Issues,"
* Indiana & Michigan Electric Co 81/01/12 34pp 07103 031

--8101190518 "Summary of Analysis of DC Cook Containment Response to
Hydrogen Burn Transients"
* Offshore Power Systems (subs of Westinghouse Electric Corp)
RP26A05 80/12/31 51pp 07183 001

8101230529 Forwards two revised pages correcting administrative errors
in 810108 submittal (AEP ARC 03398)
HUNTER, R B Indiana & Michigan Electric Co 81/01/16 5pp
07183 003

8101300494 Forwards revised pages correcting errors in 801210 submittal
re auxiliary feedwater sys automatic initiation & flow
indication
HUNTER, R B Indiana & Michigan Electric Co 81/01/23 4pp
07563 310

D Inspection Reports, IE Bulletins & correspondence

B101050239 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/30. 2pp 07389 102

B101060537 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/31. 2pp 07401 162

B101050451 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/11/06 2pp 07389 349

B101060350 Forwards IE Info Notice 80-41, "Failure of Busing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/11/10 2pp 07392 073

B101060520 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/11/14 2pp 07391 241

B101120019 Forwards IE Insp Rept 50-315/80-16 on 801021-22 & 1105-07 & notice of violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/24 2pp 07446 239

--B101120028 Notice of violation from Insp on 801021-22 & 1105-07
Region 3, Chicago, Office of the Director. 80/11/21. 1p 07446 241

--B101120034 IE Insp Rept 50-315/80-16 on 801021-22 & 1105-07
Noncompliance noted failure to follow procedure re caller of feedwater flow transmitters.
HOPKINS, B. Region 3, Chicago, Office of the Director
STREETER, J F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/21 5pp 07446 242

B101050356 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/12/05. 2pp 07390 322.

B101070077 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/12/16 1p 07415 050

B101220103 Forwards IE Investigation Rept 50-315/80-17 on 800716-30 & 1110
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/12/16 2pp 07183 001.

--B101220102 IE Investigation Rept 50-315/80-17 on 800716-30 & 1110.
Noncompliance noted improper use of plant radiation work permit sys, allowing unauthorized entry into steam generator
WEIL, C H. NDREI, LUS, C E. Region 3, Chicago, Office of the Director. 80/12/08 4pp 07183 001

B101120268 Informs of review of IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." No Valcor valves used. Total manpower effort was 70 manhours
HUNTER, R B Indiana & Michigan Electric Co. 80/12/17. 1p. 07446 265

B101120313 Responds to IE Bulletin 80-21 re valve yokes supplied by Malcolm Foundry Co. No valves employ yokes mfg by vendor
HUNTER, R B Indiana & Michigan Electric Co. 80/12/17 1p. 07446 264

B101300070 Ack receipt of 801223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/80-14 & 50-316/80-13.
HILD, J A Region 3, Chicago, Safeguards Branch. 81/01/09 1p. 07583 053

--B101300073 Updates 801022 ltr re IE Insp Repts 50-315/80-14 & 50-316/80-13 Encl withheld (ref 10CFR2 790).
HUNTER, R B Indiana & Michigan Electric Co. 80/12/23 1p 07503 094

B101280910 Supplies 800710 response to IE Bulletin 80-11, "Masonry Design." Current plant changes being reviewed to verify that all concrete masonry walls were constructed from architectural &/or structural drawings
HUNTER, R B Indiana & Michigan Electric Co. 81/01/14 2pp 07550 324

S Reportable occurrences, LERs & related correspondence

B101200367 Forwards LER 80-027/03L-0
SHALLER, D V Indiana & Michigan Power Co. 81/01/15 1p. 07477 353

--B101200371 LER 80-027/03L-0 on 801218, spent fuel pool, diesel generator floor & containment spring line peak recording
accelerographs found out of calibr. Cause unknown. Peak recording accelerographs rescaled
DELONG, S Indiana & Michigan Power Co. 01/01/15. 1p 0747

B101290516 Forwards LER 80-028/03L-0
SHALLER, D V. Indiana & Michigan Electric Co. 81/01/23 1p. 07575 244

--B101290521 LER 80-028/03L-0 on 801227, two lower ice condenser door openings exceeded torque spec. Caused by slipping insulation around doors due to adhesive bond failure. Metal screws added to all lower door insulation
DELONG, S. Indiana & Michigan Electric Co. 81/01/23 2pp. 07575 245

03CAET 80-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FBAR
EISENHUT, D O Division of Licensing. 80/11/13. 2pp.

B101130170 Advice of provisions of 10CFR50, App R, that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open items encl. No open items for Facility, W/p encl.
EISENHUT, D O. Division of Licensing. 80/11/24 3pp 07482 1

B101090461 Requests relief from required 810102 submittal date for revised emergency plan. Delay needed in order to permit mgmt review of state & county emergency plans, final typing & printing. Plan will be submitted by 810126.
HUNTER, R B Indiana & Michigan Electric Co. 80/12/30 2pp 07442 263

B101260579 Forwards App C to modified amended security plan in response to 801031 ltr. Plan withheld (ref 10CFR2 790).
HUNTER, R B. Indiana & Michigan Electric Co. 81/01/20 1p. 07531 122

G Adjudicatory correspondence

B101100332 Forwards revised order for mod of license, correcting r in 800829 order. Hearing date also revised.
EISENHUT, D O Division of Licensing. 80/09/19. 3pp

--B101100549 Revised order amending Licensee OPR-58 & OPR-74, info requested by IE Bulletin 79-010 must be submitted to IE by 801101
EISENHUT, D. O. Division of Licensing. 80/09/19. 6pp.

P Operating license stage documents & correspondence

B101100532 Forwards revised order for mod of license, correcting r in 800829 order. Hearing date also revised.
EISENHUT, D O Division of Licensing. 80/09/19. 3pp. 07444 3

--B101100549 Revised order amending Licensee OPR-58 & OPR-74, info requested by IE Bulletin 79-010 must be submitted to IE by 801101
EISENHUT, D. O. Division of Licensing. 80/09/19. 6pp. 07444 3

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Spots to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing. 80/11/20 1p.

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-3 & 7-6 & 8-17 to
STB shubber inservice insp requirements
• Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT.D O Division of Licensing 80/11/26 8pp

B10160530 Forwards notification of 801218 meeting w/uttl to discuss
ultimate strength of containment & hydrogen control
measures Util should be prepared to discuss equipment hatch
cover & structural analysis Analysis guidelines encl
NOVAK, T M Assistant Director for Operating Reactors 80/12/11
4pp 07471 154

B101050481 Ack receipt of uttl 780622 ltr forwarding rept. per Condition
2 C(3)(n) of License OPR-74 Rept is subj to Class III fee
MILLER, W O License Fee Management Branch. 80/12/12 1p
07387 024.

B101210445 Forwards responses to questions on Rule 50.71e. "Periodic
Updating of FBARs" & PR notice of final rule SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT.D O Division of Licensing 80/12/15 13pp

B101150368 Summary of 001219 meeting w/uttl re ultimate strength of
containments & hydrogen control measures for containments.
MINTER, S Operating Reactors Branch 1 81/01/02 5pp 07463 226

B101210242 Forwards House Rept 96-1452. "Twenty-Eighth Rept by
Committee on Govt Operations," in response to uttl 801229
request W/O encl
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support
Branch. 81/01/05 1p. 07492 039

B101600021 Confirms plans for 801113 meeting in Glen Ellyn, IL to
discuss recent events at facility
KEPPLER, J O Region 3, Chicago, Office of the Director. 81/01/06
1p 07467 301

B101130217 Forwards response to NRC 801031 ltr re implementation of
post-TMI requirements contained in NUREG-0737
HUNTER, R S Indiana & Michigan Electric Co. 81/01/08 34pp.
07449 320

B101190512 Forwards "First Quarterly Rept on Hydrogen Issues," per
801007 submittal. "Summary of Analyses of DC Cook
Containment Response to Hydrogen Transients" encl
HUNTER, R S Indiana & Michigan Electric Co 01/01/12 1p
07183 001

--B101190515 "First Quarterly Rept on Hydrogen Issues"
• Indiana & Michigan Electric Co 81/01/12. 34pp. 07183 001

--B101190518 "Summary of Analysis of DC Cook Containment Response to
Hydrogen Burn Transients"
• Offshore Power Systems Issbs of Westinghouse Electric Corp i
RP36A05. 80/12/31. 51pp 07183 001

B101230529 Forwards two revised pages correcting administrative errors
in B10108 submittal (AEP NRC 00398)
HUNTER, R S Indiana & Michigan Electric Co. 81/01/16 3pp
07183 001.

B101270350 Submits Class III fee in response to NRC 801212 ltr re
processing fee for licensee 780622 submittal. "Westinghouse
Reactor Protection Sys/Engineered Safety Features Actuation
Sys Setpoint Methodology."
HUNTER, R S Indiana & Michigan Electric Co 81/01/21 1p
07343 093.

B101300494 Forwards revised pages correcting errors in 801210 submittal
re auxiliary feedwater sys automatic initiation & flow
indication
HUNTER, R S Indiana & Michigan Electric Co. 81/01/23 4pp
07583 318

0 Inspection reports, IE Bulletins & correspondence

B101050239 Forwards IE Info Notice 80-30. "Cracking in Charging Pump
Casing Cladding." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/30
2pp. 07389 102

B101060537 Forwards IE Info Notice 80-39. "Malfunction of Solenoid
Valves Mfg by Valcor Engineering Corp." No written response
is required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/1
2pp 07401 162

B101050451 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by
Malcolm Foundry Co. Inc." Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/1
2pp 07389 319

B101060350 Forwards IE Info Notice 80-41. "Failure of Using Chert
Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No
response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/1
2pp 07392 073

B101060520 Forwards IE Bulletin 80-23. "Failures of Solenoid Val
Mfg by Valcor Engineering Corp." Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/1
2pp 07391 241

B101050556 Forwards IE Info Notice 80-43. "Failures of Continuous
Level Monitor for Steam Discharge Val at Grosden Unit 2." No
response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/1
2pp 07393 322

B101070077 Forwards IE Info Notice 80-44. "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown." No written
response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/1
1p 07415 050.

B101120260 Informs of review of IE Bulletin 80-23. "Failures of
Solenoid Valves Mfg by Valcor Engineering Corp." do Valcor
valves used Total manpower effort was 70 manhours
HUNTER, R S Indiana & Michigan Electric Co 80/12/17 1p
07446 265

B101120315 Responds to IE Bulletin 80-21 re valve yokes supplied
Malcolm Foundry Co. No valves employ yokes mfg by valcor
HUNTER, R S Indiana & Michigan Electric Co 80/12/17 1p
07446 264

B101306070 Ack receipt of 801223 ltr informing NRC of steps taken
correct violations noted in IE Insp Repts 50-315/80-14 &
50-316/80-13.
HINB, J A Region 3, Chicago, Safeguards Branch 81/01/09 1
07583 053

--B101300073 Updates 801022 ltr re IE Insp Repts 50-315/80-14 &
50-316/80-13 Encl withheld (ref 10CFR2 790)
HUNTER, R S Indiana & Michigan Electric Co 80/12/23 1p
07383 054.

B101280510 Supple 800710 response to IE Bulletin 80-11. "Masonry
Design." Current plant changes being reviewed to verify that
all concrete masonry walls were constructed from
architectural &/or structural drawings
HUNTER, R S Indiana & Michigan Electric Co 81/01/14. 2pp
07550 324

3 Reportable occurrences, LERs & related correspondence

B101050356 RD on 801215 spray header isolation valves CT6-124E &
CT8-128E were discovered sealed & locked closed at 9:30-h.
Valves reopened, relocked & resealed in correct position
Followup rept will be submitted by 801226
SHALLER, D V Indiana & Michigan Electric Co. 80/12/16 1p.
07376 203

B101030472 Forwards LER 80-033/01L-0
SHALLER, D V Indiana & Michigan Electric Co 80/12/22 1p
07390 203

--B101050346 LER 80-033/01L-0 on 801214 containment upper & lower
CT8 headers on east train were isolated. Caused by operator
not performing correct valve lineup. Operating shifts
retrained
KEITH, R S Indiana & Michigan Electric Co 80/12/22. 2pp
07390 204

B101060789 Forwards LER 80-033/02L-0
SHALLER, D V Indiana & Michigan Electric Co 80/12/31 1p
07393 360

8101060795 LER 80-034/03L-0 on 801204, during inservice insp testing, containment isolation valve HCR-252 was not fully seated w/shut indication in control room Cause undetermined Valve stroke adjusted & valve shut completely
WEITH, R S Indiana & Michigan Electric Co 80/12/31 2pp
07393 361

8101060384 Forwards LERs 80-035/03L-0 & 80-036/03L-0
SMALLER, D V Indiana & Michigan Electric Co 81/01/02 1p
07420 348

8101060397 LER 80-035/03L-0 on 801205, rod position identification for control rod N-9 did not respond properly Caused by connector on top of rod position detector assembly that appeared to have been stepped on Cable replaced
RISCH, INC, J Indiana & Michigan Electric Co 80/12/31 1p
07420 369

8101060406 LER 80-036/03L-0 on 801202, discovered that monthly functional test of source range nuclear instrumentation not performed Caused by personnel error Test has been added to surveillance schedule
RISCH, INC, J Indiana & Michigan Electric Co 80/12/31 2pp
07420 310

8101070485 Forwards LER 80-037/03L-0
SMALLER, D V Indiana & Michigan Electric Co 81/01/06 1p
07442 018

8101090672 LER 80-037/03L-0 on 801207, transmitter NPP-193 found to have excessive nonconservative drift causing pressurizer pressure high reactor trip setpoint to exceed Tech Spec limits Caused by setpoint drift Transmitter recalibrated
RISCH, INC, J Indiana & Michigan Electric Co 81/01/06 2pp
07442 019

8101210443 Forwards LER 80-034/03L-1
SMALLER, D V Indiana & Michigan Electric Co 81/01/13 1p
07493 153

8101210451 LER 80-034/03L-1 on 801204, containment isolation valve HCR-252 was not fully seated w/shut indication in control room Cause undetermined Valve stroke adjusted & valve shut completely
WEITH, R S Indiana & Michigan Electric Co 81/01/08 2pp
07493 154

BUCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8101090787 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810106 & by applicants as part of FEAR
EISENHUT, D O Division of Licensing 00/11/13 2pp.

8101130136 Advises of provisions of 10CFR50, App R, that are applicable to fire protection Features of facility FR notice & summary of staff requirements to resolve open items encl
EISENHUT, D O Division of Licensing 00/11/24 8pp. 07308 001

8101050437 Provides approach to resolving eight open fire protection items in response to NRC 801124 ltr re requirements for resolution Fire protection mods will be completed by 810219
LUNOVALL, A E Baltimore Gas & Electric Co 80/12/27 3pp
07399 333

8101140039 Requests that encl facility emergency planning info be made publicly available W/o encl 001220369
SEUGER, J L Division of Rules and Records 00/12/31 1p
07461 225

8101140285 Requests that encl facility planning info be made publicly available W/o encl 0012150057
SEUGER, J L Division of Rules and Records 80/12/31 1p
07461 261

8101290613 Releases public version of utility emergency plan
FELTCH, J M Division of Rules and Records 81/01/27 1p
07187 001

8101290614 Forwards public version of Attachment J-4 to 801231 emergency response plan.
GLSDON, R C Baltimore Gas & Electric Co 81/01/07 1p
07187 001

8101290621 Public version of Attachment J-4 to emergency response plan.
Baltimore Gas & Electric Co 80/12/31 1p 07187 001

H General correspondence

8101190164 Forwards updated svc list for correspondence re facility Continuing inconsistency in old svc list has caused delays in receipt of EMC ltrs
GLSDON, R C L Baltimore Gas & Electric Co 81/01/12 3pp
07476 042

I Financial information

8101190502 Forwards annual financial rept for 1979 & statement of projected cash flow for twelve months ended 010731
BARRERS, A H Baltimore Gas & Electric Co 81/01/14 5pp.
07473 251

8101190507 Annual Financial Rept 1979
Baltimore Gas & Electric Co 80/12/00 40pp 07475 256

J Insurance & indemnity information

8101060571 Forwards Endorsements 3 to RELIA Policy Ed-52 & MAELU P
XB-53
BINDERMEYER, C L Baltimore Gas & Electric Co 80/12/30 5pp.
07399 166

P Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STB License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

8101100271 Revised Pages 3/4 7-22 through 28.D 3/4 7-5 & 7-6 & 6
STB snubber inservice insp requirements
Division of Licensing 80/11/20 10pp

8101100440 Confirms 801126 mtg meeting in Baltimore, MD to discuss assessment of utility regulatory performance at facility Meeting arrangements were discussed in 001110 telcon Meeting agenda encl
GRIER, D H Region 1, Philadelphia, Office of the Director 80/11/21 2pp. 07444 303

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 001112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing 00/11/26 6pp

8101090941 Forwards Amend 48 to License DPR-53, safety evaluation & notice of issuance & availability
CLARK, R A Operating Reactors Branch 3 00/12/12 4pp 03071

8101090943 Amend 48 to License DPR-53, authorizing Cycle 3 operation level of 2,700 MWt w/increased fuel enrichment, demonstration fuel assemblies, modified guide tubes & new reactor protection sys trip
CLARK, R A Operating Reactors Branch 3 80/12/12 76pp
03871 252

8101090945 Safety evaluation supporting Amend 40 to License DPR-53
Office of Nuclear Reactor Regulation, Director. 80/12/12 50pp. 03871 328

8101090947 Notice of issuance & availability of Amend 48 to License DPR-53
CLARK, R A Operating Reactors Branch 3 00/12/12 2pp.
03872 016

8101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule. BEP plants need not comply w/rule until program is complete Non-BEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing. 00/12/15 13pp

8101150573 Confirms 801217 telcon revising Tech Spec 3.6.2.1 in response to 801217 telecopy Authorized change will become Amend 49 Tech Specs encl
NOVAH, T M Assistant Director for Operating Reactors. 80/12/10 3pp 07466 006

8101150875 Revised Tech Spec Section 3/4 & 2 re depressurisation cooling sys, containment spray sys
Assistant Director for Licensing 80/12/18 1p 07466 000

seismic evaluation program
 L1.C Operating Reactors Branch 3 80/12/18 4pp 07464.001.

8101060283 Provides addl info re scope of mod to auxiliary feedwater sys Mods will comply w/Section III of ASME code 1978 Summary Addends for equipment installation w/exception of final connections to existing sys
 ASH, R.F. Baltimore Gas & Electric Co 80/12/30. 2pp. 07399.068

8101060333 Forwards response to NRC 801031 request for status of efforts re implementation of TMI Lessons Learned requirements & request for info re NUREG-0737 items
 POINDEXTER, C.H. Baltimore Gas & Electric Co 80/12/30 27pp 07392.285

--8101060339 "Control Room Habitability Study for Calvert Cliffs Nuclear Power Station" Responses to NUREG-0737 & NUREG-0578 status info encl
 * Bechtel Power Corp (subs of Bechtel Corp) 80/11/30 47pp 07392.312

8101190416 Forwards request for addl info for review of CEN-119181-P re better steel shape selection sys info needed re 18-month fuel cycles
 CLARK, R.A. Operating Reactors Branch 3 80/12/30 3pp. 07183.001

8101190320 Application to amend licenses DPR-53 & DPR-69, changing Tech Specs Sections 3 & 4 to provide for redundancy in decay heat removal capability Class I & III fees encl
 LUNDVALL, A.E. Baltimore Gas & Electric Co 81/01/08. 2pp 07475.001

--8101190329 Proposed Tech Specs Sections 3 & 4, providing for redundancy in decay heat removal capability
 * Baltimore Gas & Electric Co 81/01/08 9pp 07475.003

8101230486 Determines that 801119 request for relief from ASME Code Section VI requirement consists of Class III & I amend per 10CFR170.22 Applicable Fee submitted
 OLSEN, R.C. Baltimore Gas & Electric Co 81/01/09 1p. 07510.291

8101220434 Submits license fee for Class III amend re seismic qualification of containment spray sys per 801217 request.
 OLSEN, R.C.L. Baltimore Gas & Electric Co 81/01/15 1p 07493.251

8101270611 Advises that footnotes will be added to Tech Spec Tables 3-3-3.3 3-4 & 4-3-2 to clarify Category A lessons learned requirements.
 BAH-OUHAT, J.H. Baltimore Gas & Electric Co 81/01/23 1p 07183.001

8101300322 Responds to NRC 810123 request for verification of actions taken in response to NRC 791107 requirements for auxiliary feedwater sys Emergency operating procedures direct operator to start up auxiliary sys if diesels fail.
 LUNDVALL, A.E. Baltimore Gas & Electric Co 81/01/26 3pp. 07183.001.

Q Inspection reports, IE Bulletins & correspondence

8101300134 Forwards IE Investigation Rept 50-317/80-18 on 801014-16 No noncompliance noted
 CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/05. 2pp 07583.096

--8101300138 IE Investigation Rept 50-317/80-18 on 801014-16 No noncompliance noted Major areas investigated allegations re p1pp support activities performed to comply w/IE Bulletin 79-02
 DURN, J.P. Region 1, Philadelphia, Office of the Director.
 MATTIA, J.C. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/03 7pp 07583.098

8101130694 Informs that visual insp of RCP studs at Calvert Cliffs has revealed corrosion problem similar to Ft Calboun.
 Insp method should be checked
 NOVAK, T.M. Assistant Director for Operating Reactors 80/11/24 1p. 07494.038

8101050124 Requests existing data, summaries & records of inservice insp tests of containments w/greased prestressing tendons.
 GYNL receiving contract to compile & review records of tendons
 EISENHUT, D.O. Division of Licensing 80/11/29 3pp 07378.333

8101140944 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No specified parts in use at facilities
 LUNDVALL, A.E. Baltimore Gas & Electric Co 80/12/10 1p 07458.360

8101150349 Ack receipt of 801107 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/80-13 & 50-318/80-12
 BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/10. 1p 07464.199

--8101150351 Responds to NRC 801015 ltr re violations noted in IE 1 Repts 50-317/80-13 & 50-318/80-12 Corrective actions entered correct setpoint for 11B RCP seal high temp/pressure intrn alarm annunc
 LUNDVALL, A.E. Baltimore Gas & Electric Co 80/11/07 2pp 07464.203

--8101150553 Forwards IE Insp Repts 50-317/80-13 & 50-318/80-12 on 800728-0801 & notice of violation
 BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/15 2pp 07464.202

--8101150555 Notice of violation from Insp on 800728-0801
 * Region 1, Philadelphia, Office of the Director 80/10/06 07464.204

--8101150558 IE Insp Repts 50-317/80-13 & 50-318/80-12 on 800728-0801 Noncompliance noted failure to maintain alarm procedures consistent w/indicated alarm status & failure to properly maintain controlled procedures.
 CHUNG, J.W., BLUMBERG, N. Region 1, Philadelphia, Office of the Director
 GREENMAN, E. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/06 16pp 07464.207

8101150562 Ack receipt of 801205 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/80-13 & 50-318/80-14
 BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/15 1p 07464.223

--8101150565 Responds to NRC 801107 ltr re violations noted in IE 1 Repts 50-317/80-13 & 50-318/80-14 Corrective actions procedural format set forth by CC1 217, plant mod procedures, approved to measure wall clearance.
 LUNDVALL, A.E. Baltimore Gas & Electric Co. 80/12/05 2pp. 07464.224

--8101150568 Forwards IE Insp Repts 50-317/80-13 & 50-318/80-14 on 800901-29 & notice of violation
 BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/07. 2pp 07464.226

--8101150570 Notice of violation from Insp on 800901-29
 * Region 1, Philadelphia, Office of the Director 80/11/05 07464.228

--8101150573 IE Insp Repts 50-317/80-13 & 50-318/80-14 on 800901-29 Noncompliance noted failure to identify inadequate spacing of storage racks in Insp program
 ARCHITZEL, R.E., CALLAHAN, C.J. Region 1, Philadelphia, Office of the Director
 MCCABE, E.C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/05 13pp. 07464.224

8101060878 Forwards IE Info Notice 80-44, "Activation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required.
 GRIER, D.H. Region 1, Philadelphia, Office of the Director 80/12/16. 1p 03896.233

8101230337 Forwards proprietary & nonproprietary versions of "End of Cycle 4 Eddy Current Insp Results: Control Element Assemblies (CEA's) Guide Tube Sleeve 1980 Calvert Cliffs 1 Refueling Outage." Proprietary rept withheld (ref 10CFR2.740)
 LUNDVALL, A.E. Baltimore Gas & Electric Co 01/01/21 3pp. 07513.001

--8101230541 Nonproprietary version of "End of Cycle 4 Eddy Current Insp Results: Control Element Assemblies (CEA's) Guide Tube Sleeves 1980 Calvert Cliffs 1 Refueling Outage"
 * Combustion Engineering, Inc. CEN-146101 11P 80/12/22 11p 07513.006

DOCKETED ITEMS

R Periodic operating reports & related correspondence

8101260570 Forwards monthly operating repts for Dec 1980
 PERSON, S B Baltimore Gas & Electric Co 01/01/81 1p 07531:126

--8101260542 Monthly operating repts for Dec 1980.
 PERSON, S B Baltimore Gas & Electric Co 01/01/81 10pp
 07531:127

S Reportable occurrences, LERs & related correspondence

8101140771 RO 80-65 10-11 on 801215, during Mode 5 operations, shutdown
 cooling flow stopped to perform leak rate test on
 penetration 41 w/o verifying that charging pumps were
 de-energized or that flow paths were closed
 * Baltimore Gas & Electric Co 80/12/16 1p 07308:001

8101050185 Forwards LER 80-065/03L-0.
 RUSSELL, L B Baltimore Gas & Electric Co 00/12/29 1p
 07282:112

--8101050192 LER 80-065/03L-0 on 801215, charging pumps found running
 contrary to Tech Spec surveillance requirement. Caused by
 failure of personnel to perform surveillance requirements
 after securing shutdown cooling flow. Procedures changed
 WENZEL, R L Baltimore Gas & Electric Co. 80/12/29 2pp
 07382:113

8101090241 PID-1-80-180 Unit 1 outage has been extended until approx
 810111. Outage caused by 001224 discovery of failed main
 turbine thrust bearing during initial Cycle 5 startup
 MCCABE, E C, BRUNNER, E J Region I, Philadelphia, Office of the
 Director 80/12/29 1p 07442:269

8101050399 Forwards LER 80-065/01T-1
 RUSSELL, L B Baltimore Gas & Electric Co 80/12/30 1p
 07390:111

--8101050403 LER 80-065/01T-1 on 801215, charging pumps discovered running
 w/shutdown cooling flow secured. Caused by operator failure
 to perform surveillance requirements of Tech Specs
 Requirements reviewed w/personnel
 WENZEL, R L Baltimore Gas & Electric Co 80/12/30 2pp
 07390:112

8101050408 Forwards updated LER 80-017/03X-2
 RUSSELL, L B Baltimore Gas & Electric Co 80/12/30 1p
 07390:116

--8101050413 Updated LER 80-017/03X-2 on 790515, during overspeed testing,
 diesel generator 12 auxiliary blower failed. Caused by
 thermal growth & subsequent contact between lobes & blower
 housing, due to extended overspeed test
 LAOIEWSKI, J, UNSTED, J M Baltimore Gas & Electric Co 80/12/30
 1p 07390:117

8101130597 Forwards LER 80-070/04X-0
 RUSSELL, L B Baltimore Gas & Electric Co 81/01/07 1p
 07453:325

--8101130607 LER 80-070/04X-0 on 800624, analysis of oyster samples showed
 excessive Ag-110m concentrations. Caused by natural tendency
 of oysters to concentrate environ silver
 BROBST, O E Baltimore Gas & Electric Co 81/01/07 1p
 07453:326

8101130617 Forwards LER 80-068/03L-0.
 RUSSELL, L B Baltimore Gas & Electric Co 81/01/09 1p
 07453:340

--8101130623 LER 80-068/03L-0 on 801210, control room air conditioning
 unit 12 heaters found defective, rendering unit inoperable
 Caused by failure of heating elements. New heating elements
 installed & unit returned to svc
 LAOIEWSKI, J B, PEACE, W B Baltimore Gas & Electric Co 81/01/09
 1p 07453:341

8101230538 Forwards LER 80-071/03L-0
 RUSSELL, L B Baltimore Gas & Electric Co. 81/01/19 1p
 07512:288

8101230523 Forwards LER 80-067/03L-0
 RUSSELL, L B Baltimore Gas & Electric Co 81/01/20 1p
 07513:017

--8101230526 LER 80-067/03L-0 on 801221, reactor protective eye chan-
 nels units for high power, thermal margin/low pressure &
 axial flux offset were bypassed to repair cold input Temp
 element 1-TE-122CD failed. Elements replaced w/calibr spacers.
 LAOIEWSKI, J B, RIZZO, P O Baltimore Gas & Electric Co 81/01/20
 1p 07513:018

8101200523 Forwards LER 80-072/03L-0
 RUSSELL, L B Baltimore Gas & Electric Co 81/01/23 1p
 07584:348

--8101300530 LER 80-072/03L-0 on 801225, during normal operation, num-
 bered component cooling heat exchanger outlet throttle valve
 1-54-9206-CV would not open, rendering heat exchanger
 inoperable. Caused by missing operator to stem key.
 LAOIEWSKI, J B, PEACE, W O Baltimore Gas & Electric Co 81/01/23
 2pp 07584:349

V Operator Examinations

8101070379 Responds to NRC 800328 request for mods to licensed oper-
 ating program. Mods include training in heat transfer,
 fluid flow & thermodynamics, installed plant sys use to
 control core accident damage & emphasis on plant transients
 LUNSVALL, A E Baltimore Gas & Electric Co 80/06/18 4pp
 07414:134

DOCKET 80-218 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP hold-
 ers & CP applicants. Revised radiological emergency response
 plans must be submitted by licensees within 60 days of
 810102 & by applicants as part of FSAR
 EISENHUT, D D Division of Licensing 80/11/13 2pp

8101130136 Advises of provisions of 10CFR50, App R, that are applica-
 ble to fire protection features of facility. FR notice & summary
 of staff requirements to resolve open items encl
 EISENHUT, D D Division of Licensing 80/11/24 8pp 07308:001

8101050437 Provides approach to resolving eight open fire protection
 items. In response to NRC 801124 ltr re requirements for
 resolution. Fire protection mods will be completed by 810219
 LUNSVALL, A E Baltimore Gas & Electric Co. 80/12/29 3pp
 07389:333

8101140039 Requests that encl facility emergency planning info be made
 publicly available. W/o encl 8012220369.
 EDWARDS, J L Division of Rules and Records 80/12/31 1p
 07461:225

8101140285 Requests that encl facility planning info be made public
 available. W/o encl 8012190057
 EDWARDS, J L Division of Rules and Records 80/12/31 1p
 07461:261

8101290613 Releases public version of util emergency plan.
 FELTON, J M Division of Rules and Records 81/01/27 1p
 07387:001

--8101290610 Forwards public version of Attachment J-4 to 801231
 emergency response plan.
 OLSON, R C Baltimore Gas & Electric Co 81/01/07 1p
 07167:001

--8101290621 Public version of Attachment J-4 to emergency response
 plan. Baltimore Gas & Electric Co 80/12/31 1p 07187:001

H General correspondence

8101190164 Forwards updated svc list for correspondence re facility
 Continuing inconsistency in old svc list has caused delays
 in receipt of PRC ltrs
 OLSON, R C Baltimore Gas & Electric Co. 81/01/12 3pp
 07476:042

I Financial information

B101190502 Forwards annual financial rept for 1979 & statement of projected cash flow for twelve months ended 810731
INWERB, A H Baltimore Gas & Electric Co 01/01/14 5pp
07475 251

--B101190507 Annual Financial Rept 1979
* Baltimore Gas & Electric Co 00/12/08 40pp. 07475 256

J Insurance & indemnity information

B101060571 Forwards Endorsements 3 to NELIA Policy ED-52 & MAELU Policy
XB-93
SHENMAKER, C L Baltimore Gas & Electric Co. 00/12/30 5pp.
07399 166

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except BEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under STB License amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT, D. O. Division of Licensing 00/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-17 to
STB snubber inservice insp requirements.
* Division of Licensing 00/11/20 10pp

B101100040 Confirms B01126 mgt meeting in Baltimore, MD to discuss NRC
assessment of util regulatory performance at facility
Meeting arrangements were discussed in 001118 telcon
Meeting agenda encl.
GRIER, B H Region I, Philadelphia, Office of the Director
00/11/21 2pp 07444:305

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B0112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing 00/11/26 6pp

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic
Updating of FSARs" & FR notice of final rule BEP plants need
not comply w/rule until program is complete. Non-BEP plants
must comply within specified time frame
EISENHUT, D O Division of Licensing 00/12/15 13pp.

B101150872 Trip rept of 001028 visit to site re auxiliary feedwater sys
seismic evaluation program
L.F.C. Operating Reactors Branch 3. 00/12/18 4pp. 07464:081.

B101060283 Provides addl info re scope of mod to auxiliary feedwater
sys. Mods will comply w/Baction 111 of ADME code 1978 Bummer
Addenda for equipment installation w/exception of final
connections to existing sys.
ASH, R F Baltimore Gas & Electric Co 00/12/30. 2pp 07399:068

B101060333 Forwards response to NRC B01031 request for status of
efforts re implementation of TMI Lessons Learned
requirements & request for info re NUREG-0737 items.
POINDEXTER, C H Baltimore Gas & Electric Co 00/12/30. 27pp.
07392:205

--B101060339 "Control Room Habitability Study for Calvert Cliffs Nuclear
Power Station." Responses to NUREG-0737 & NUREG-0578 status
info encl
* Bachtel Power Corp. (subs. of Bachtel Corp.) 00/11/30. 47pp.
07392:312

B101190573 Informs of site visit to be scheduled during refueling
outage in Jan 1981
CONNER, E L. Operating Reactors Branch 3. 01/01/05 2pp.
07474:029

B101190320 Application to amend Licenses OPR-93 & DPR-69, changing Tech
Spec Sections 3 & 4 to provide for redundancy in decay heat
removal capability Class I & III fees encl.
LUNDVALL, A E Baltimore Gas & Electric Co 01/01/08. 2pp.
07475:001.

--B101190325 Proposed Tech Specs Sections 3 & 4, providing for redundancy
in decay heat removal capability.
* Baltimore Gas & Electric Co 01/01/08. 9pp. 07475 003.

B101230486 Determines that B01119 request for relief from ASME
Section VI requirement consists of Class III & I amend per
10CFR170.22 Applicable fee submitted
CLESON, R C Baltimore Gas & Electric Co 01/01/09 1p 07

B101220434 Submits license fee for Class III amend re seismic
qualification of containment spray sys. per B01217 request
CLESON, R C L Baltimore Gas & Electric Co 01/01/15 1p
07493 251

B101270511 Advises that fontnotes will be added to Tech Spec T
3-3-3, 3-3-4 & 4-3-2 to clarify Category A lessons learned
requirements.
DANLOUIGT, J H Baltimore Gas & Electric Co 01/01/23 1p
07183 001

B101300322 Responds to NRC B01023 request for verification of
taken in response to NRC 791107 requirements for auxiliary
feedwater sys Emergency operating procedures direct operator
to start up auxiliary sys if diesels fail
LUNDVALL, A E Baltimore Gas & Electric Co. 01/01/26 3pp
07183 001

Q Inspection reports, IE Bulletins & correspondence

B101030124 Requests existing data, summarize & records of inspec
tests of containments w/gressed prestressing tendons
ORNL receiving contract to compile & review records of
tendons
EISENHUT, D. O. Division of Licensing. 00/11/29 3pp

B101070391 Forwards Suppl 1 to IE Info Notice 00-29, "Broken B
Terry Turbine Steam Inlet Flange." No written response
required
GRIER, B H Region I, Philadelphia, Office of the Director
00/11/26. 1p 07414 072

B101140944 Responds to IE Bulletin 00-21, "Valve Valve Supplies
Malcolm Foundry Co. Inc." No specified parts in use at
facilities
LUNDVALL, A E Baltimore Gas & Electric Co 00/12/10. 1p
07458 360

B101150549 Ack receipt of 001107 ltr informing NRC of steps to
correct violations noted in IE Insp Rpts 50-317/80-13 &
50-318/80-12
BRUNNER, E J Region I, Philadelphia, Reactor Operations Nuc
Support Branch. 00/12/10 1p 07464:199

--B101150551 Responds to NRC B01015 ltr re violations noted in
Rpts 50-317/80-13 & 50-318/80-12 Corrective actions enter
correct setpoint for IIB RCP seal high temp/pressure into
alarm manual
LUNDVALL, A E Baltimore Gas & Electric Co 00/11/07 2p
07464 200

--B101150553 Forwards IE Insp Rept 50-317/80-13 & 50-318/80-14
000720-0801 & notice of violation
BRUNNER, E J Region I, Philadelphia, Reactor Operations Nuc
Support Branch 00/10/15 2pp 07464:202

--B101150555 Notice of violation from insp on B00728-0801.
* Region I, Philadelphia, Office of the Director. 00/10/15
07464:204

--B101150558 IE Insp Rpts 50-317/80-13 & 50-318/80-12 on B007
Noncompliance noted: failure to maintain alarm procedures
consistent w/indicated alarm status & failure to properly
maintain controlled procedures
CHUNO, J W, OLUMBERO, N Region I, Philadelphia, Office of
Director GREENMAN, E Region I, Philadelphia, Reactor Op
Nuclear Support Branch 00/10/06 16pp 07464:207.

B101150562 Ack receipt of B01205 ltr informing NRC of steps to
correct violations noted in IE Insp Rpts 50-317/80-13 &
50-318/80-14.
BRUNNER, E J Region I, Philadelphia, Reactor Operations Nuc
Support Branch 00/12/15 1p 07464:223

--B101150565 Responds to NRC 001107 ltr re violations noted in
Rpts 50-317/80-13 & 50-318/80-14 Corrective actions.
procedure format set forth by CC 217, plant mod procedure
approved to measure wall clearance.
LUNDVALL, A E Baltimore Gas & Electric Co. 00/12/09. 2p
07464:224.

--B101150568 Forwards IE Insp Rpts 50-317/80-13 & 50-318/80-14
000901-29 & notice of violation
BRUNNER, E J Region I, Philadelphia, Reactor Operations Nuc
Support Branch 00/11/07. 2pp 07464 226

--B01150570 Notice of violation from Insp on B00901-29.
* Region I. Philadelphia. Office of the Director 80/11/05 1p
07464 228

--B01150573 IE Insp Repts 90-317/80-15 & 50-318/80-14 on B00901-29
Noncompliance noted failure to identify inadequate spacing
of storage racks in insp program
ARCHITZEL, R E., CALLAHAN, C J. Region I. Philadelphia. Office of
the Director MCCABE, E C. Region I. Philadelphia. Reactor
Operations Nuclear Support Branch 80/11/05 13pp. 07464 229.

B01060873 Forwards IE Info Notice 80-44. 'Activation of ECCS in
Recirculation Mode While in Hot Shutdown No written
response required
GRIER, R M. Region I. Philadelphia. Office of the Director.
80/12/16 1p 03896 233

B010260477 Forwards results of sleeve control element assembly guide
tube evaluation, in response to NRC 791119 request insps show
no indication of sleeve wear after two cycles Recommended
insp program encl
LUNOVALL, A E. Baltimore Gas & Electric Co 81/01/21 3pp
07532 035

R Periodic operating reports & related correspondence

B010260530 Forwards monthly operating repts for Dec 1980
PERSON, S D. Baltimore Gas & Electric Co 81/01/14 1p. 07531 126

--B010260542 Monthly operating repts for Dec 1980
PERSON, S. D. Baltimore Gas & Electric Co. 81/01/14 10pp
07531 127

S Reportable occurrences, IERs & related correspondence

B010220388 Forwards LER 80-052/03L-0
RUSSELL, L B. Baltimore Gas & Electric Co 81/01/08 1p.
07505 172

--B010220390 LER 80-052/03L-0 on B01103. CMT penetration room exhaust fan
discharge damper 22 linkage was found broken Caused by
excessive wear on clevis pin due to inadequate lubrication.
Linkage repaired & restored to svc on 001104
WENDERLICH, R L., PENCE, W D. Baltimore Gas & Electric Co
81/01/08 1p 07505 173

B010130610 Forwards LER 80-055/03L-0.
RUSSELL, L B. Baltimore Gas & Electric Co 81/01/09 1p
07453 338

--B010130615 LER 80-055/03L-0 on B01209. emergency diesel generator 12
developed fuel oil leak Caused by leak at flared type brass
compression fitting Line replaced
WENDERLICH, R L., HUSEOY, D. Baltimore Gas & Electric Co 81/01/09.
1p 07453 339.

B010150534 Forwards LER 80-057/03L-0
RUSSELL, L B. Baltimore Gas & Electric Co 81/01/13. 1p
07463 184

--B010150543 LER 80-057/03L-0 on B01214. control element assembly 3B
dropped to bottom of core. Cause undetermined. Control
element assembly 3B realigned w/group.
LAGIENSKI, J S., RIZZO, P Q. Baltimore Gas & Electric Co 81/01/13.
1p. 07463 185

B010230457 Forwards updated LER 79-009/03L-1
RUSSELL, L R. Baltimore Gas & Electric Co 81/01/20. 1p.
07513 031.

--B010230461 Updated LER 79-009/03L-1 on 790226. during test, 21 svc water
heat exchanger saltwater outlet throttle valve failed to
open upon receipt of signal Caused by packing deterioration
& accompanying seizure to shaft Shaft cleaned
CARROLL, J T., PENCE, W D. Baltimore Gas & Electric Co 81/01/20
2pp 07513 032

B010270660 RU B1-005 on B01018 power operated relief valve RC-404-ERV
inadvertently opened Caused by pressure indicating
controller PIC-103-1 failing high power relief isolation
RC-405-MOV shut, terminating discharge.
* Baltimore Gas & Electric Co. 81/01/20 2pp 07309 001

B010270677 Forwards LER 80-069/03L-0
RUSSELL, L B. Baltimore Gas & Electric Co 81/01/21. 1p
07309 001

--B010270684 LER 80-069/03L-0 on B01222. deviation found among channel
engineered safety features activation sys Caused by channel
D bistable voltmeter shifting out of tolerance due to maint
activities Distable meter recalibr
LAGIENSKI, J S., RIZZO, P Q. Baltimore Gas & Electric Co 81/01/21
2pp 07309 001

B010300533 Forwards LER 80-059/03L-0.
RUSSELL, L B. Baltimore Gas & Electric Co 81/01/26 1p.
07308 001

--B010300538 LER 80-059/03L-0 on B01226. while investigating abnormal
containment air particulate & gaseous readings, discovered
that containment atmosphere sample isolation valve was shut
Caused by personnel error Operators instructed.
OW/15, S M., RIZZO, P Q. Baltimore Gas & Electric Co 81/01/26
2pp 07308 001

V. Operator Examinations

B010707377 Responds to NRC 800328 request for mods to licensed oper
training program Mods include training in heat transfer,
fluid flow & thermodynamics, installed plant sys use to
control core accident damage & emphasis on plant transients.
LUNOVALL, A E. Baltimore Gas & Electric Co 80/06/18. 4pp
07414 134

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP hold
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B0102 & by applicants as part of FBAR.
EISENHUT, D O. Division of Licensing 80/11/13 2pp

B01070265 Releases public version of Commonwealth of PA. Dauphin Co
evacuation plan
FELTON, J M. Division of Rules and Records. 80/12/01. 1p
07309 001

--B01070270 Public version of Commonwealth of PA. Dauphin County
evacuation plan for 1, 2, 3, 5, 10 & 20-mile radius.
HALLBY, K J. Dauphin County, PA 79/04/30. 175pp 07309 001.

B01070322 Releases public version of Commonwealth of PA. emergency
plan
FELTON, J M. Division of Rules and Records 80/12/01. 1p.
07309 001.

--B01070325 Public version of Commonwealth of PA. Dept of Environ
Resources Bureau of Radiological Health plan for nuclear
generating station incidents
* Pennsylvania, State of 77/09/30 8pp. 07309 001

B01060331 Releases public version of "PA Disaster Operations Plan, Annex E
Nuclear Incidents (Fixed Facilities)," as part of
will submitted.
FELTON, J M. Division of Rules and Records. 80/12/01 1p.
07308 001.

--B01060337 Public version of "PA Disaster Operations Plan, Annex E
Nuclear Incidents (Fixed Facilities)."
* Pennsylvania, State of 79/03/28 7pp. 07308 001.

B01050633 Releases public version of "Emergency Planning Around UB
Nuclear Power Plants NRC Oversight," fourth rpt.
FELTON, J M. Division of Rules and Records. 80/12/19. 1p.
07309 001

--B01050635 Public version of "Emergency Planning Around UB Nuclear
Power Plants NRC Oversight," fourth rpt.
* House of Rep., Government Operations. 79/08/08 105pp.
07309 001.

B01060405 Forwards Revision 8 to security plan. Revision 8 withheld
ref 10CFR2, 7701
MILLER, R D. Metropolitan Edison Co 80/12/30. 1p. 07398 078.

B01050442 Requests that encl facility emergency planning info be m
publicly available. W/o encl B012190094
BOUDER, J L. Division of Rules and Records. 80/12/31. 1p.
07300 001

07308 001

B101190705 Requests that encl facility emergency planning info be made publicly available w/o encl
SDVOER, J L Division of Rules and Records B1/01/08 1p
07472 322

B101270988 Requests that encl facility emergency planning info be made publicly available w/o encl
SDVOER, J L Division of Rules and Records B1/01/13 1p
07543-398.

B101300117 Forwards facility emergency planning info for placement in LPDR w/o B101070325
SDVOER, J L Division of Rules and Records B1/01/19 1p
07583-091

G Adjudicatory correspondence

B003180520 Requests info re reasoning behind NRC decision to exempt facility from federal containment regulations covering personnel airlock. Supports revocation of UL Requests info re prospect of NRC action against B&W
CLARK, O R Affiliation Unknown B0/03/12 2pp 95023 073

B101100682 Forwards memorandum re 43 cases involving NRC includes brief description of pending litigation, pending cases & closed cases
FITZGERALD, J A Office of the General Counsel B0/12/09 35pp
07444 320.

B101260234 Responds to B01216 ltr request to extend comment period on programmatic EIS Comment period extended once & public meetings held in PA & MD re TMI-2 cleanup FES to be issued March 1981 Related correspondence
SNYDER, B J TMI Program Office B1/01/08 2pp 07523 315

--B101260245 Requests extension of period for public review of programmatic EIS Revised draft should be issued, not final revision
PETERSON, R W National Audubon Society, Central Midwest Regional Office B0/12/16 1p 07523 317

B101290762 Order authorizing organization of General Public Utilities Nuclear Corp as wholly owned subsidiary for mgmt & operation of nuclear plants
FITZBIRCH, S O Securities & Exchange Commission B0/09/15 3pp
07576 027

--B101290766 Notice of proposal to organize General Public Utilities Nuclear Corp as wholly owned subsidiary for mgmt & operation of nuclear plants w/related documentation.
FITZBIRCH, S O Securities & Exchange Commission B0/06/19 85pp.
07576 030.

--B101290771 Request that NJ Board of Public Utilities dismiles for lack of jurisdiction util & General Public Utilities Nuclear Corp proposed operating agreement in alternative, agreement should be approved.
BROKAW, R D Jersey Central Power & Light Co BROKAW, R D B0/04/11 7pp. 07576 130

H General correspondence

B101070084 Expresses opposition to nuclear power & radwaste
BROWN, C. Affiliation Unknown B0/10/27 1p. 07415 247

B101190517 Notifies that nine counties of eastern shore oppose dumping of water from facility, pending appraisal of impact on bay waters.
WINGATE, W L Maryland, State of B0/12/02 1p 07475-357.

B101050071 Requests that future correspondence for Chem-Nuclear Sys, Inc re licensed transport costs be forwarded to CP Oelteto at Met Ed, instead of RW Haward
HOVEY, O K Metropolitan Edison Co. B0/12/03 1p. 07385-278.

B101080330 Responds to B01119 ltr requesting sections of NRC regulations re responsibility for decontamination operations at facility
SNYDER, B J TMI Program Office B0/12/11 1p. 07417-351

--B101080335 Requests sections of NRC regulations re NRC responsibility if util is unable to carry out decontamination operations at facility
PETERSON, A B. Affiliation Unknown B0/11/19. 1p 07417-352

B101050064 Notifies of personnel changes in responsibilities for records of licensed transport costs for radioactive mats
Responsible party for Met Ed on registered users lists should be changed to manager of Process Support Group
HOVEY, O K Metropolitan Edison Co B0/12/13 1p 07385 277

B101140239 Responds to B01204 ltr requesting info re TMI-2 accident
Future actions can be taken at site w/o NRC review & approval Human error, plant design & equipment malfunction contributed to accident
SNYDER, B J TMI Program Office B0/12/22 2pp 07461 215

--B101140246 Requests info re TMI-2 accident
MILLER, A Affiliation Unknown B0/12/04 2pp 07461 217

B101140705 Responds to B01126 ltr re Lebanon Valley Chamber of Commerce requests to meet w/Commission to discuss facilities situation issues re Unit 1 ale in adjudication Chamber advised that Commission member could meet re Unit 2 cleanup
NEARNE, J F Commissioners B0/12/24 1p 07462 025

B101260025 Responds to FOIA request for seven categories of NRC documents Forwards computer printout indicating pertinent NUMEOs & other documents published 1977-80 & documents in response to request
FELTEN, J H Division of Rules and Records B0/12/31 2pp

--B101260031 Confirms that encl listed documents responding to FOIA requests were received by law firm representative
CARR, J C Division of Rules and Records B0/12/18 3pp

--B101260037 Confirms that encl listed documents responding to FOIA requests were received by law firm representative.
CARR, J C Division of Rules and Records B0/12/08 7pp

--B101260052 Confirms that encl listed documents responding to FOIA requests were received by law firm representative
CARR, J C Division of Rules and Records B0/12/02 3pp

--B101260060 Confirms that listed documents responding to FOIA requests were received by law firm representative
CARR, J C Division of Rules and Records B0/11/24 21pp

--B101260065 Confirms that listed documents responding to FOIA requests were received by law firm representative
CARR, J C Division of Rules and Records B0/11/10 5pp

--B101260072 Confirms that listed documents responding to FOIA requests were received by law firm representative
CARR, J C Division of Rules and Records B0/11/04 2pp

--B101260081 Confirms that listed documents responding to FOIA requests were received by law firm representative Computer printout of NUMEOs published 1977-80 & '81 Subj Identification Numbering Sys ISSINSI Basic Code & Revision 1 encl
CARR, J C Division of Rules and Records B0/10/31 204pp

--B101260091 Forwards schedule of ACRS subcommittee 790915 meeting facility accident implications Subcommittee is unfamiliar w/Michelson rept. Questions have no relevance to OIC of Inspector & Auditor investigation
STRICKLER, L J Office of Inspector & Auditor 79/09/07 1p 07507 031

--B101260099 Forwards revised tentative schedule for ACRS Ad Hoc Subcommittee 790905 meeting in Washington, DC on facility accident implications
MAJOR, R ACRS - Advisory Committee on Reactor Safeguards 79/08/30 3pp 07507 032

B101050023 Expresses concern re use of nuclear power. Proposes solid research & development as alternative energy resource
VOGLER, T R Affiliation Unknown B1/01/02 3pp 07309 001

B101210079 Responds to B00917 ltr to President Carter expressing concern re effect of TMI-2 accident on cost of electricity.
No statutory authority provides for direct federal aid for cleanup & recovery costs w/o supporting documents
DENTON, H R Office of Nuclear Reactor Regulation, Director B1/01/07 3pp 07490 222

8101210007 Responds to 800726 ltr to President Carter expressing concern re effect of TMI-2 accident on electricity costs No statutory authority provides for direct federal aid for cleanup & recovery costs W/o supporting documentation
DEWITZ, H R Office of Nuclear Reactor Regulation, Director.
81/01/07 3pp 07491 06B

8101210095 Responds to 000918 ltr to President Carter expressing concern re effect of TMI-2 accident on electricity costs No statutory authority provides for direct federal aid for cleanup & recovery costs W/o supporting documents
FENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 3pp 07491 072

8101210108 Responds to 800910 ltr to President Carter expressing concern re effect of TMI-2 accident on electricity costs No statutory authority provides for direct federal aid for cleanup & recovery costs W/o supporting documentation
FENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 3pp 07491 096

8101210253 Responds to encl 800716 ltr to President Carter re effect of TMI accident on electricity costs & need for federal assistance Resumption of TMI-1 operation is subj of hearing White House 800703 ltr to PA Public Util Commission encl
FENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 6pp 07187 001

8101210288 Responds to encl 800719 ltr to President Carter re effect of TMI accident on electricity costs & need for federal assistance Resumption of TMI-1 operation is subj of hearing White House 800703 ltr to PA Public Util Commission encl
FENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 4pp 07488 207

8101210309 Responds to encl 800726 ltr to President Carter re effect of TMI accident on electricity costs & need for federal assistance Resumption of TMI-1 is subj of hearing White House 800703 ltr to PA Public Util Commission encl
FENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 3pp 07488 211

8101210310 Responds to encl 800729 ltr to President Carter re effect of TMI accident on electricity costs & need for federal assistance Resumption of TMI-1 is subj of hearing White House 800703 ltr to PA Public Util Commission encl
FENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 11pp 07400 214

8101210594 Notifies of change of address for Citizens for Safe Environ.
SQUINARD, V Citizens for Safe Environment 81/01/08 1p.
07448 361.

8101270105 Forwards health physics evaluation per NRC 001219 ltr. W/o encl
LEWIS, S H Hearing Branch 2 81/01/14 1p 07547 040

8101290227 Ack that "i" should be under column "Oocyte" on line "hair fell out, raw sores" in Table 2 5, Page 9 of NUREG-0738. Error will be corrected on future reprints or revisions
SNYDER, B J TMI Program Office 81/01/16 1p 07575 023.

--8101290240 Inform of discrepancy within NUREG-0738 On Page 7, Table 2 3 problem found w/goats losing hair & developing raw sores On Page 9, in Table 2 3 under "Miscellaneous, Hair Fell Out, Raw Sores" no animal is listed.
BRINK, T Affiliation Unknown 80/12/17 2pp 87575 024

1 Financial Information

8101210144 Forwards BEC Form 10-0, Quarterly Financial Rept & supporting mgt comments, in response to NRC 770921, 1109 & 800811 requests for info re significant financial developments affecting utility in restate proceeding
CONNOON, V H General Public Utilities 80/11/25 3pp.

--8101210154 Quarterly Financial Rept Rept 1980 & supporting mgt comments
* General Public Utilities 80/11/14 44pp.

J Insurance & Indemnity Information

8101090496 Forwards 800007 press release announcing premium refunds based on pools' experience during 1969-1979, including TMI incident.
QUATTROCHI, J American Nuclear Insurers 81/01/06 2pp.
07442 010

D Advisory Committee on Reactor Safeguards reports & correspondence

8101200315 Outlines NRC position re requirements for shutdown & decay heat removal using safety-grade equipment, in response to NRCB 790314 memo
FENTON, H R Office of Nuclear Reactor Regulation, Director
79/09/07 3pp 07187 001

8101260025 Responds to FOIA request for seven categories of NRC documents Forwards computer printout indicating pertinent NUREG & other documents published 1979-80 & documents in response to request
FELTON, J H Division of Rules and Records 80/12/31 2pp

P Operating license stage documents & correspondence

8101290203 Forwards EEP & FR notice re decontamination & disposal of requests from 790328 TMI-2 accident Nonproprietary comments only should be submitted
SNYDER, B J TMI Program Office 00/08/14 1p. 07573 329

--8101290200 Notice of availability of NUREG-0683, OES for decontamination of TMI-2
SNYDER, B J TMI Program Office 00/08/11 2pp 07573 330.

--8101290214 DRAFT PROGRAMMATIC ENVIRONMENTAL IMPACT STATEMENT RELATIVE TO DECONTAMINATION & DISPOSAL OF RADIOACTIVE WASTES RESULTING FROM MARCH 28, 1979 ACCIDENT, THREE MILE ISLAND NUCLEAR STATION, UNIT 2 Errata
* Office of Nuclear Reactor Regulation, Director NUREG-0683
80/08/04 4pp. 07573 332

--8101290220 DRAFT PROGRAMMATIC ENVIRONMENTAL IMPACT STATEMENT RELATIVE TO DECONTAMINATION & DISPOSAL OF RADIOACTIVE WASTES RESULTING FROM MARCH 28, 1979, ACCIDENT, THREE MILE ISLAND NUCLEAR STATION, UNIT 2
* Office of Nuclear Reactor Regulation, Director. NUREG-0683.
80/07/31 250pp 07573 336

8101060270 Suggests that radwaste from TMI-2 be buried at DOE facilities, rather than at commercially-licensed burial grounds
WHEARNE, J F Commissioners. 80/10/20 2pp 07399 074.

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for encl under STS License amend application adding model Tech Spec to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing. 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 2B, D 3/4 7-5 & 7-6 & 6- STS snubber inservice insp requirements.
* Division of Licensing 00/11/20 10pp.

810120019 Forwards R Codell assessment of groundwater liquid pathway analysis for leakage of water from TMI-2 containment. Final analysis was completed following draft programmatic EIS & contains different results. Final statement will be modified.
SNYDER, B J TMI Program Office. 80/11/25 1p. 07231 344.

8101220465 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing. 80/11/26 8pp.

8101060764 Notification of contract execution, Mod 1 to "Psychological Stress Response to Venting at TMI." Contractor: Uniform Buys Univ
HARRISTON, C A, OLACOLA, A F. Technical Assistance Contracts Branch
FIN B-8892 80/11/28 1p 07400 307

--8101060770 Mod 1, extending contract period through 810115 w/no additional funding required, to "Psychological Stress Response to Venting at TMI."
* Uniformed Services Univ of the Health Sciences. DOUBOUEY, Technical Assistance Contracts Branch FIN B-8892. 80/11/28 1p 07400 308

8101090728 Confirms Advisory Panel for Decontamination of TMI-2 8011 meeting to discuss radwaste mgt issues pertinent to decontamination.
TRAVERS, W TMI Program Office 00/12/09 1p. 07430 338.

8101060955 Grants extension until 810228 to review draft programmatic EIS in response to 801118 request for delay re safe cleanup of facilities must be avoided
WHEARNE, J F Commissioners. 80/12/12 2pp 07401 113.

--B10106095s Notifies the Advisory Panel on Decontamination of TMI-2 will be unable to meet B10131 deadline for input to decontamination issue
MINYICH, J E Oauphin County, PA 80/11/18 1p 07401 115

B101120159 Forwards Ofc of Sids Development lect sheet, copies of Ofc of Nuclear Reactor Regulation delegations, 791109 FR notice, marked to indicate licensing authority changes & lect sheet re inspect of EPA B01120 ltr on TMI programmatic EIS
Office of Standards Development, Director 80/12/12 3pp.
07436 321

--B101120173 Forwards EPA review of draft EIS Final programmatic EIS should provide more info re environmental nature & disposition of redwastes from TMI-2 decontamination & health effects of various exposure levels (public & occupational)
HEDEMAN, W H Environmental Protection Agency, 80/11/20 9pp
07437 002

B101070323 Forwards agenda for NCRP Task Group SC-38 on Disposal of Accident Generated Westwater for B01218 meeting & also our TMI Program Ofc has provided Task Group w/ORNL-TM-744B re decontamination of high activity level water
SNYDER, B J TMI Program Office 80/12/15 10pp

B101210445 Forwards responses to questions on Rule 50.71a, "Periodic Updating of FBARS" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing, 80/12/13 13pp.

B101050039 Requests to register as user of Model CND1 LL-50-100 radioactive mail shipping case
HOVEY, O K Metropolitan Edison Co 80/12/18 2pp. 07395 273

B101190640 Provides TMI-2 Advisory Panel w/response to TD Cochran B01202 ltr re potential health effects of cleanup alternatives in programmatic EIS.
SNYDER, B J TMI Program Office 80/12/22 5pp 07474 034

B101140671 Restates NRC B00913 request for safety evaluation of SB9 IE Circular B0-18 stated that evaluation should include basis for determining whether unreviewed safety question exists
SNYDER, B J TMI Program Office 80/12/24 1p. 07462 021

B101270706 Notification of contract execution. "Provision of Technical Assistance to Assess Psychological Stress Re Decontamination & Disposal of Radwastes at TMI-2." Awarded to Human Design Group
LITTLE, M Administrative Contracts Branch, FIN H-793B 80/12/30 1p. 07549 125

--B101270723 Contract "Provision of Technical Assistance to Assess Psychological Stress Re Decontamination & Decontamination & Disposal of Radwastes at TMI-2." Awarded to Human Design Group
PARTNER, A B Human Design Group, PERLMAN, J Administrative Contracts Branch, FIN H-793B 80/12/30 5pp 07549 126.

B101200545 THE PUBLIC WHOLE BODY COUNTING PROGRAM FOLLOWING THE THREE MILE ISLAND ACCIDENT
OOTCHY, R L, ROEB, R J Region 1, Philadelphia, Office of the Director NUREG-0636 80/12/31 61pp Available at NTIS.
07476 142

B101260025 Responds to FBI request for seven categories of NRC documents Forwards computer printout indicating pertinent NUREGs & other documents published 1977-80 & documents in response to request
FELTON, J M Division of Rules and Records, 80/12/31 2pp.

--B101260105 Responds to 790731 request re comparison of Michelson rept w/B&W testimony before Presidential TMI Commission Repts are not incompatible
CUMMINGS, J J Office of Inspector & Auditor, 79/08/03 1p 07507 036.

--B101260113 Requests comparison between Michelson rept & B&W testimony before Presidential TMI Commission Related documentation & Columbia Journal Review Article, "At TMI" encl.
OILINSKY, V. Commissioners, 79/07/31 25pp. 07507 037.

--B101260141 Summarizes B&W 790718-20 testimony before President's Commission on TMI Accident. Includes hearing agenda & summary of reporting relationships of witnesses Primary interest was series of memos re safety issues raised by B&W.
KELLEY, C Office of Inspector & Auditor, 79/07/24 6pp 07507 081.

--B101260151 Informs that W Ward will attest to accuracy of draft of 790529 interview w/RC Jones From B&W WA Post News article encl.
BTRICKLER, L J Office of Inspector & Auditor 79/07/23 07507 087

B10120237 Forwards request for addl info re contingency plan for transfer & storage of reactor containment bldg sump water
SNYDER, B J TMI Program Office 81/01/06 6pp 07492 034.

B101210244 Disapproves B01209 request for relief from inservice requirements of Section XI of ASME Boiler & Pressure Vessel Code Requests mod & resubmission of relief request
SNYDER, B J TMI Program Office 81/01/07 2pp 07492 040.

B101210657 Responds to B01216 ltr to Chairman Ahearn requesting extension for comment on draft programmatic EIS NRC held series of meetings w/public & local officials in PA & MD to ensure adequate public input
SNYDER, B J TMI Program Office 81/01/08 3pp 07488 238

B101220623 Responds to B01224 request re submittal of submerged demineralizer s/s safety evaluation Review should consider IE Circular B0-18 in 10CFR50.59a criteria spec Anticipates submittal no later than B10206
HOVEY, O K Metropolitan Edison Co 81/01/09 1p 07510 311

B101230398 Responds to B00912 ltr re mill plans to scale down activities due to PA Public Util Commission B00910 order denying request for rate relief & NRC action schedule Encl Table 1 lists NRC requirements for safe shutdown
MEARNE, J F Commissioners 81/01/12 6pp 07358 064

--B101260106 Advises of licensee actions being taken re cleanup facility Plan has been revised due to PA Public Util Commission B00910 order denying request for rate relief & NRC action schedule considered in draft programmatic EIS
DICKAMP, M General Public Utilities 80/09/12 3pp 07489 217

B101210379 Forwards util B01231 ltr to State of PA requesting w/perm permit requirements of Dem Safety Encroachment Act
HUGILL, H O Metropolitan Edison Co. 81/01/13 6pp. 07489

B101210541 Advises of planned licensee actions in response to q raised re use of organic resins in EPICOR-11 prefilers Inorganic ion exchange media selected due to stability in radiation field
HOVEY, O K Metropolitan Edison Co. 81/01/13 2pp 07489 217

B101290244 Forwards documents in response to B10103 ltr request info to aid NCRP Task Group SC-38 on Disposal of Accident Generated Waste Water, W/N encl
SNYDER, B J TMI Program Office 81/01/13 3pp 07395 217

B101210340 Forwards EPICOR-11 liner solidification overview tech & overview logic, dtd B01218 Re-examination of alternative methods of spent resin stabilization will be conducted, per Ahearn B10112 ltr to Dickamp
HOVEY, O K Metropolitan Edison Co 81/01/15 3pp 07489 217

B101220534 Forwards info re disposal of EPICOR 11 & low activity ion exchange media in response to NRC B01027 ltr & B01218 telcon EPICOR 11 liner solidification overview schedule & overview logic encl
HOVEY, O K Metropolitan Edison Co 81/01/15 3pp 07308 010

B101230613 Forwards addl info dtd B01231 re util B01205 EPICOR solidification procurement specs.
HOVEY, O K Metropolitan Edison Co 81/01/15 20pp. 07510

B101290493 Informs that rept re liner module sump contamination originally intended for submittal on B10115 & postponed to B10123, now expected by B10127
HOVEY, O K Metropolitan Edison Co 81/01/23 1p 07568 35

B101290755 Application for Tech Specs Change Request 9B, amending License DPR-90, Certificate of SVC & Class III fees encl.
HUGILL, H B Metropolitan Edison Co 81/01/26 3pp. 07576:

0 Inspection reports, IE Bulletins & correspondence

B101070428 Forwards Suppl 1 to IE Info Notice D0-29, "Broken B1 Terry Turbine Steam Inlet Flange" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p. 07414:029.

B01140260 Responds to IE Bulletin B0-23. "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp - No subv valves in use
in safety-related applications at Facility.
HOVEY, G K Metropolitan Edison Co 80/12/12 1p 07461 268

B01140730 Updates B01120 response to IE Bulletin B0-10. "Contamination
of Nonradioactive Sys & Resulting Potential for Uncontrolled.
Uncontrolled Release of Radioactivity to Environ - Sys
identified w/potential for contamination
HOVEY, G K Metropolitan Edison Co 80/12/16 7pp 07461 297

R Periodic operating reports & related correspondence

B011060105 Forwards NRC TMI Program Ofc Weekly Status Rept* for
B01123-120A
CELLINS, J T TMI Program Office 80/12/08 7pp 07397 107

B011090771 Weekly status rept for B01207-13
CELLINS, J T TMI Program Office 80/12/12 5pp 07430 065

B011090972 Forwards NRC TMI Program Ofc Weekly status rept for wk of
B01214-20
BARRETT, L H TMI Program Office 80/12/21 4pp 07430 001

B01140217 Forwards TMI Program Ofc Weekly status rept for wk of
B01214-20
BARRETT, L H TMI Program Office 80/12/22 4pp 07461 211

B01120543 Forwards weekly status rept for wk of B01221-B01003
BARRETT, L H TMI Program Office 81/01/05 6pp 07447 181

B01210264 Forwards NRC TMI Program Ofc Weekly status rept for B01221-
010103
BARRETT, L H TMI Program Office 81/01/05 5pp 07492 052

B01220039 Forwards TMI Program Ofc Weekly status rept for B0104-10
BARRETT, L H TMI Program Office 81/01/12 5pp 07495 228

B01140574 Forwards "TMI Aquatic Study," monthly rept for Nov 1980
Requests that document be made publicly available
HICKEY, C R Environmental Engineering Branch 01/01/13 1p
07460 265

--B01140577 "TMI Aquatic Study," monthly rept for Nov 1980
HARDACCI, O A Ichthyological Associates, Inc 81/01/13 23pp
07468 266

B01300098 Forwards TMI Program Ofc weekly status rept for B0111-17
BARRETT, L H TMI Program Office 81/01/19 6pp 07579 334

B01270573 Forwards Ichthyological Associate "TMI Aquatic Study Monthly
Rept for Dec 1980
TEITZ, T R General Public Utilities - GPU Service Corp 81/01/22
1p 07183 001

--B01270578 "TMI Aquatic Study Monthly Rept for Dec 1980 " Study
performed for Met Ed
HARDACCI, O A, HANEY, E C Ichthyological Associates, Inc
81/01/22 24pp 07183 001

S Reportable occurrences, LERs & related correspondence

B01090325 Ack receipt of B01006 ltr re notification of overdue LER
Requests that in future, notification be discussed w/senior
resident inspector (SRI) prior to due date of rept
Discipline should include reasons & concurrence of SRI
GRIER, O H Region 1, Philadelphia, Office of the Director
80/10/30 1p 07417 353

B01140662 RO B0-56/1P on B01212, determined that core flood tank A
had failed Cause not stated Details will be included in
follow-up rept
HOVEY, G K Metropolitan Edison Co 80/12/15 1p 07308 001

B01050174 Forwards LER B0-055/03L-0
HOVEY, G K Metropolitan Edison Co 80/12/24 1p 07582 105

--B01050181 LER B0-055/03L-0 on B01127, emergency diesel generator
BF-X-1B failed to start Caused by inadequate maint of
shutdown ambient temp due to heater failure Shutdown temp
maintained until replacement parts installed
CHAPLIN, S D Metropolitan Edison Co 80/12/24 3pp 07382 106

B01050419 LER B0-053/01P-0 on B01223, determined that placing radia-
tion monitor HPR-220 in defeat on B01219 constituted reportable
condition Caused by instrument malfunction Repairs
completed
HOVEY, G K Metropolitan Edison Co 80/12/24 2pp 07390 122

B01140650 RB B0-56/1P on B01219, radiation monitor HPR-220 placed in
defeat, causing condition where radiation signal would not
place control room ventilation into recirculation Caused by
instrument malfunction Monitor repaired
HOVEY, G K Metropolitan Edison Co 80/12/24 1p 07462 015

B01190482 Forwards LER B0-056/01L-0
HOVEY, G K Metropolitan Edison Co 81/01/13 1p 07474 075

--B01190486 LER B0-056/01L-0 on B01212, core flood tank A level
instrumentation determined inoperable Caused by failed
component within containment bldg but exact determination
not made No action required
CHAPLIN, S D Metropolitan Edison Co 81/01/12 3pp 07474 0

B01208129 PRB-TMI-B1-01 on B01001, water samples from onsite Well 2
contained trace quantities of Cs-137 & Cs-134 Subsequent
samples on B01000, 15 & 1103 indicated concentrations at less
than lower limit of detection Item to be reviewed B0115
SHANAHAN, M, FASANO, A, BARRETT, L TMI Program Office 81/01/12
3pp 07487 033

B01280319 PRB-TMI-B1-02 on B01113, estimated 600 gallons of
concentrated sulfuric acid siphoned from storage tank,
through two valves, & out of 2-inch flange pipe Valves
inadvertently opened or left open by maint
BARRETT, L H, SHANAHAN, M, FASANO, A TMI Program Office 81/01/14
2pp 07557 048

B01230594 Advises that interim rept re slight contamination in 11R
storage modules will be submitted B0123
HOVEY, G K Metropolitan Edison Co 81/01/16 1p 07510 314

B01270637 Forwards LER B0-057/03L-0
HOVEY, G K Metropolitan Edison Co 81/01/16 1p 07548 342

--B01270671 LER B0-057/03L-0 on B01217, during surveillance proced-
ure 4203-M10, air intake tunnel chlorine monitor found
inoperable Caused by dirty probe which reduced sensitivity
Probe removed, cleaned & returned to svc
CHAPLIN, S D Metropolitan Edison Co 81/01/16 2pp 07548 3

T Hearing transcripts on non-antitrust matters

B01270250 Unofficial transcript of 790322 public meeting in
Washington, DC re protective order for all TMI records
Pg 1-B
* Commissioners 79/05/22 9pp 07546 020

B01220261 Unofficial transcript of 790802 public briefing in
Washington, DC re resins from EPICOR-11 Pg 1-32
* Commissioners 79/08/02 33pp 07504 011

B01190559 Transcript of Advisory Council for Decontamination of TMI
B01218 meeting in Harrisburg, PA Pg 1-92
* Advisory Council for Decontamination of TMI Unit 2 80/12/18
95pp 07473 180

B01190565 Transcript of Advisory Panel for Decontamination of TMI
B01220 meeting in Harrisburg, PA Pg 1-107
* Advisory Council for Decontamination of TMI Unit 2 80/12/30
111pp 07473 275

U. Congressional/Executive Correspondence

B01140743 Ack receipt of comments on draft programmatic EIS re TMI
decontamination & disposal of radwaste Comments are being
considered in final programmatic EIS scheduled for Mar 1981
Issuance w/o encl transcript of B01117 public meeting
ENYBER, B J TMI Program Office 80/12/03 1p 07308 001

B01080079 Responds to B01112 ltr re pace of regulatory review of
cleanup program General Public Utilities recent cutback in
cleanup operations primarily related to recent PA Public
Utility Commission action Lists answers to specific questions
WHEARNE, J F Commissioners 80/12/12 5pp 07422 001

--B01080094 Requests meeting to discuss handling & disposition of
level wastes from facility Only short-term solution
available for waste removal is transfer to suitable DOE
facilities
WHEARNE, J F Commissioners 80/10/20 2pp

DOCKETED ITEMS

B010200054 Poses questions re allocation of costs for facility cleanup.
Certificate of Svc encl
MOFFETT, T House of Rep 01/01/06 5pp 07486 317

V. Operator Examinations

R010190344 Confirms telcon re G Kunder B01215 operator license
application Waiver is requested to delete reactor operator
portion of senior reactor operator exam O Kunder is degree-
holding engineer for util
HOVEY, O K Metropolitan Edison Co 01/01/00 1p 07476 086

DOCKET 50-321 EDWIN 1 HATCH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

B010190387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B010102 & by applicants as part of FSAR.
EISENHUT, D G Division of Licensing 00/11/13 2pp

B010170510 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 00/12/01 1p.
07403 237

--B010170522 Forwards public version of Revision 3 to emergency plan
WIDNER, W A Georgia Power Co 00/01/31 1p 07403 239

--B010170526 Public version of Revision 3 to emergency plan
* Georgia Power Co 00/01/31 89pp 07403 240

B010260714 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 01/01/16 1p
07534 027

--B010260718 Forwards public version of emergency plan
WIDNER, W A Georgia Power Co 01/01/02 1p 07534 028

--B010260724 Public version of emergency plan
* Georgia Power Co 01/04/30 100pp 07534 030

J. Insurance & indemnity information

B010190390 Forwards Endorsement 97 to ANF Policy NF-215
FIELDER, J. Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc
Div. 00/12/31 3pp 07427 340.

B010190650 Forwards Endorsement 4 to NELA Binder EB-81
FIELDER, J. Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc
Div 00/12/31 2pp 07442 050

B010190655 Forwards Endorsement 56 to NELA Policy NF-215.
FIELDER, J. Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc
Div 00/12/31 2pp 07442 056

B010140233 Forwards Endorsement 4 to NELA Binder EB-67.
FIELDER, J. Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc.
Div 01/01/09 2pp 07461 271.

P. Operating license stage documents & correspondence

B010100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of Inservice surveillance requirements for
snubbers under STB License amend application adding model
Tech Specs to App A should be submitted within 120 days.
EISENHUT, D. G. Division of Licensing. 00/11/20 1p

--B010100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-17 to
BIS snubber inservice insp requirements
* Division of Licensing. 00/11/20. 10pp

B010220466 Ltr to all power reactor licensees & applicants forwarding
summary of 001112 meeting re implementation of guidance for
Unresolved Safety Issue A-12. "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. G. Division of Licensing 00/11/26 8pp.

B010190113 Ltr to all BWR licensees forwarding B01201 generic safety

--B010190141 Generic safety evaluation re short-term actions
ensure continued safe operation of operating BWRs. Contingency
operation of plants is acceptable pending permanent decisions.
Criteria for implementing design mods encl
* Division of Licensing 00/12/01. 212pp 07183 001

B010210445 Forwards responses to questions on Rule 50.710. "Updating of FSARs" & FR notice of final rule SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT, D G Division of Licensing 00/12/15 13pp

B010190970 Forwards request for addl info to complete review
program Shipping damage insps should be implemented &
performed for all safety-related items upon delivery
REID, R W Operating Reactors Branch 4 00/12/24. 4pp

B010190391 Forwards list of TLD station locations near Facility
proposed route for exchanging TLDs for NRC direct radiation
monitoring network W/O encl
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Branch
00/12/30 2pp 07476 083

B0101060564 Forwards info for requirements of NUREG-0737, as amended
WIDNER, W A Georgia Power Co 00/12/31. 267pp 07395 011

--B0101060573 Tech Specs 3/4 6 7 & 3/4 7 2 re chlorine detector
control room environ control sys for Unit 2
* Georgia Power Co 00/12/31 11pp 07396 023

B010220563 Forwards "Operability Review of ECCS at Plant Hatch
& 2." in response to NUREG-0737, item 11 K 3 17
WIDNER, W A Georgia Power Co 01/01/16 1p 07503 077

--B010220569 "Operability Review of ECCS at Plant Hatch Unit 1
* General Physics Corp GR-P-33009 00/12/22 75pp

B010290578 Responds to NUREG-0619, "BWR Feedwater Noise & C
Drive Return line Noise Cracking" Mode will be performed
during 1982 refueling outages Feedwater & control rod drive
repts will be submitted within time limits specified.
WIDNER, W A Georgia Power Co 01/01/22 3pp 07575 003

0. Inspection reports, IE Bulletins & correspondence

B012240275 Responds to IE Bulletin 00-17 Ultrasonic transducer
not be installed as previously reported in B00819 ltr
Devices found unreliable in environ. Cause of float failure
under investigation
WIDNER, W A Georgia Power Co 00/11/18 1p 07328 211

B010100682 Forwards IE Insp Repts 90-321/80-43 & 90-366/80-4
001104-07. No noncompliance noted
KUPPKE, C E Region 2, Atlanta, Reactor Construction & Eng
Support Branch 00/11/25 2pp 07443 167

--B010100689 IE Insp Repts 90-321/80-43 & 90-366/80-43 on B0
noncompliance noted. Major areas inspected installed
equipment review per IE Bulletin 79-010
O'DRACHS, T D., CONNELL, F E. Region 2, Atlanta, Office of
Director. 00/11/25. 4pp 07443 169.

B010100202 Responds to IE Bulletin 00-21 re valve yokes supplied
Malcolm Foundry Co, Inc. No such yokes used in facility.
Valve documentation indicates other foundries made valve
yokes in use
WIDNER, W A Georgia Power Co 00/11/26 1p 07420 359

B0101050602 Forwards IE Info Notice 00-43, "Failures of Control
Level Monitor for BWR Discharge Vol at Dresden Unit 2."
response required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
1p 07391 018

B010170033 Ack receipt of B01008 ltr requesting re-evaluation
dismissal of apparent noncompliance item contained in Hatch
Packaging Insp Repts 90-321/80-32 & 90-366/80-32 item
withdrawn
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Branch
00/12/11 1p 07408 124

--B0101070334 Responds to NRC B00917 ltr re violations noted
Packaging Repts 90-321/80-32 & 90-366/80-32 Requests
re-evaluation & dismissal of cited noncompliance All

--B101070336 Forwards Waste Packaging Insp Repts 50-321/80-32 & 50-366/80-32 on 800731 & notice of violation
STONER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/17 2pp 07408 127

--B101070338 Notice of violation from Insp on 800731
* Region 2, Atlanta, Office of the Director 80/09/15 1p 07408 129

--B101070342 Waste Packaging Insp Repts 50-321/80-32 & 50-366/80-32 on 800731 Noncompliance noted radioactive shipment not properly placarded
MACCARI, H. T. C. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/15 3pp 07408 130

B101060126 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/17 1p 07397 339

B101070333 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR." No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/18 1p 07413 329

B101050159 Forwards IE Bulletin 80-25, "Operating Problems w/Target Rock Safety Relief Valves at BWRs." No response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/19 2pp 07377 259

B101290185 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)." Drywell cooling sys composed of six cooling units each w/two fans. Normally only one fan per unit is operating
WIDNER, W. A. Georgia Power Co. 81/01/05, 7pp 07569 346

B101290376 Responds to IE Bulletin 80-07, "BWR Jet Pump Assembly Failure." No abnormal wear, stress or failed welds discovered during visual exams of Unit 2 assemblies by remote underwater television cameras Insp of Unit 1 scheduled
WIDNER, W. A. Georgia Power Co. 81/01/13, 1p 07575 131

B101290385 Responds to IE Bulletin 80-13, "Cracking in Core Spray Spargers." No cracking of core spray spargers or piping between inlet nozzle & vessel shroud was identified in Unit 2 Insp for Unit 1 scheduled during Winter 1981.
WIDNER, W. A. Georgia Power Co. 81/01/13, 1p 07575 132

B101300374 Responds to request for confirmation of response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls." Tests will be completed by Feb 1981 & June 1981 for Units 1 & 2, respectively.
WIDNER, W. A. Georgia Power Co. 01/01/26 2pp 07586 350

R Periodic operating reports & related correspondence

B101260463 Forwards monthly operating rpt for Dec 1980.
MANN, M. Georgia Power Co. 81/01/10 1p 07524 020

--B101260468 Monthly operating rpt for Dec 1980.
KAMISHILIAN, J. M. Georgia Power Co. 81/01/10, 9pp 07524 021

B101280189 Forwards monthly operating rpt for Dec 1980.
MANN, M. Georgia Power Co. 81/01/10 1p 07556 285

--B101280197 Monthly operating rpt for Dec 1980.
KAMISHILIAN, J. M. Georgia Power Co. 81/01/10, 9pp 07556 286

D Reportable occurrences, LERs & related correspondence

B101050235 RO on B01213, sprinkler sys providing protection for reactor bldg heating, ventilation & air conditioning room had been inoperative for 14 days Sys isolated to implement mods for corrective action to open item in IE Rept 50-321/80-02
MANN, M. Georgia Power Co. 80/12/19 2pp 07378 324

B101050427 RO on B01213, sprinkler sys providing protection for reactor bldg heating, ventilation & air conditioning had been inoperative for 14 days. Caused by implementation of design mods to bring sys into AFPA code compliance.
MANN, M. Georgia Power Co. 80/12/19, 2pp 07389 326

B101060582 Forwards LER 80-122/01T-0.
MANN, M. Georgia Power Co. 80/12/30 1p 07391 126

--B101060593 LER 80-122/01T-0 on B01219, OC Insp of cable spreading control bldg sprinkler hangers installed in 1978 revealed deficiencies which jeopardize seismic qualification of sprinkler sys Caused by improper installation
COOGLI, C. L. Georgia Power Co. 80/12/30 3pp 07391 127

B101060640 Forwards LER 80-119/03L-0
MANN, M. Georgia Power Co. 80/12/30 1p 07392 180

--B101060660 LER 80-119/03L-0 on B01212, routine channel check showed fission product monitors 1011-K631, particulate count & 1011-K633, noble gas count, were out of calibr Caused by discriminator setpoint drift Setpoint adjusted
NIX, R. T. Georgia Power Co. 80/12/30 2pp 07392 181

B101060514 Special Rept 1-sp-80-3 on B01206, during routine survey waste oil drums, several areas on ground were found to be contaminated Caused by storage of previous waste oil drums. Add controls re release of contaminated oil under review
MANN, M. Georgia Power Co. 80/12/31 4pp 07392 189

B101120298 Forwards LER 80-126/03L-0
MANN, M. Georgia Power Co. 81/01/06 1p 07447 122

--B101120303 LER 80-126/03L-0 on B01226, dinitrogen storage tank reduced to below Tech Spec level. Caused by pressure control valve sticking causing tank relief valve to open Pressure control loop placed in manual control
BAILEY, S. X. Georgia Power Co. 81/01/06 2pp 07447 123

B101120307 Forwards LER 80-118/03L-0
MANN, M. Georgia Power Co. 81/01/06 1p 07447 132

--B101120398 LER 80-118/03L-0 on B01212, IE11-F015B valve, RHR Inbo injection, was leaking. Caused by cracks on seating surfaces of valve disc Valve seats lapped & new disc installed
NIX, R. T. Georgia Power Co. 81/01/06 2pp 07447 133

B101230454 Forwards LER 80-127/03L-0
MANN, M. Georgia Power Co. 81/01/13 1p 07308 001

--B101230463 LER 80-127/03L-0 on B01223, w/unit in steady state op research for 3-yr inservice Insp rpt revealed lack of documentation proving visual Insp of 50% of class 1 valve internals Caused by procedural deficiency
COOGLI, C. Georgia Power Co. 81/01/13 3pp 07308 001

B101260543 Forwards LER 80-124/03L-0.
MANN, M. Georgia Power Co. 81/01/15 1p 07531 137

--B101260626 LER 81-124/03L-0 on B01228, control room air intake valve 1741-F012 failed to close in required time. Caused by faulty pilot solenoid operator. Pilot solenoid replaced
NIX, R. T. Georgia Power Co. 81/01/15, 2pp 07531 138

B101260592 Forwards LER 81-001/01T-0
MANN, M. Georgia Power Co. 81/01/15 1p 07531 153

--B101260688 LER 81-001/01T-0 on B01228, HPCI steam line pressure 1E41-H001a, c.d. actuated outside Tech Specs Caused by switch setpoint drift Switches recalibrated
NIX, R. T. Georgia Power Co. 81/01/15 2pp 07531 154

B101260601 Forwards LER 80-123/03L-0.
MANN, M. Georgia Power Co. 81/01/15, 1p 07531 156

--B101260614 LER 80-123/03L-0 on B01219 & B01226, turbine trip & valve on reactor core isolation cooling sys failed. Failures caused by gail on valve poppet & body & improper limit switch setting Gail removed & switch reset.
NIX, R. T. Georgia Power Co. 81/01/15, 2pp 07531 157

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants for summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports."
ETSENHUT, D. C. Division of Licensing, 80/11/26, 8pp

B101190379 Requests Class 11 fee for review of B01126 application extension of completion date in CPPR-95 Application Involves

DOCKETED ITEMS

B101130368 Certifies that Amend 28 to license application, consisting of Revision 20 to FSAR (OL stage) was sent by parcel post on 801211
MORIN, J P Long Island Lighting Co 80/12/17 1p 07496-018

B101050109 Forwards response to B101001 info request re environ qualification tests of safety-related equipment
NOVARRO, J P Long Island Lighting Co 00/12/21 4pp. 07376-225

B101190505 Ltr to all BWR applicants for OL co BWR scram discharge sys safety evaluation & requirements. Rept specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge vol encl
TEDESCO, R L Assistant Director for Licensing. 80/12/22 2pp 07183-001.

--B101190514 Forwards generic safety evaluation re BWR scram discharge sys Review identified two addl requirements to those proposed by owners group re scram discharge vol designs Rept should be transmitted to license applicants.
CHECK, P S Assistant Director for Plant Systems 80/12/01 2pp. 07183-001

B101200157 Summary of 801210 meeting w/Hark II owners re status of generic improved chugging load model Owners requested to justify delay in program & investigate alternatives
ANDERSON, C J Generic Issues Branch 80/12/22 4pp. 07406-143

B101140985 Summary of Dec 1900 meeting w/Hark II owners group. OE, BML, MIT, BW, Bechtel & Ebasco Svcs. Inc re suppression pool temp limits List of attendees & handouts encl
SU, T M. Generic Issues Branch 80/12/30 41pp. 07457-063

B101270165 Notification of B10113 meeting w/util in Silver Spring, MD re seismic qualification program & current program status
WILSON, J Licensing Branch 1 01/01/06 3pp. 07545-360

B101260470 Forwards Class II amend fee for application to extend CPRR-95 completion date in response to NRC 801218 request
WALSH, E J Long Island Lighting Co. 81/01/16 1p 07532-033

--B101260473 Forwards util B10116 ltr & Class II amend fee.
O1008, R M License Fee Management Branch. 81/01/22 1p 07532-034.

I. Security, medical, emergency & fire protection plans

B101090307 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, O O Division of Licensing 80/11/13 2pp

Q. Adjudicatory correspondence

B101060001 Forwards B01230 joint motion to accept stipulation & for protective order on security plan info & draft protective order & affidavit
BORDENICK, B M. Hearing Branch 4. 80/12/31. 2pp. 07397-053

--B101060002 Joint motion to accept stipulation of relationship between Suffolk County Contention 1B & specific portions of security plan & to issue protective order on security plan info. w/ draft order & affidavit of nondisclosure.
EARLEY, A F Long Island Lighting Co. BORDENICK, B M. Hearing Branch 4. DEMPSEY, P A Suffolk County, NY. 80/12/30. 11pp. 07397-055.

B101070412 Requests NRC Institute proceeding & schedule hearings per 10CFR2.204 & Section 189 of Atomic Energy Act re proposed CPRR-95 extension from B01231 to B30331. More detailed basis for request to be submitted by B10109.
LATHAM, B B. Twomey, Latham & Schmitt 80/12/31 3pp. 07414-140

B101070465 Advises of Shoreham Opponents Coalition position that CP should be suspended pending requested hearings re revocation. Issues for consideration during hearings will be detailed in B10109 submittal.
LATHAM, B B. Twomey, Latham & Schmitt 80/12/31. 3p 07414-323

--B101070468 Forwards util request for extension until B30331 to complete facility
BORDENICK, B M Hearing Branch 4. 80/11/28. 1p 07414-326

B101200059 Order granting B01231 joint motion to accept stipulation &

--B101200062 Protective order granting B01231 joint motion on plan info Permits access to protected info upon listed conditions Certificate of Gov encl
BORDER, E S Atomic Safety and Licensing Board Panel 81/01/09 07486-328

B101270675 Forwards petition of Shoreham Opponents Coalition to institute proceedings on whether good causes exist to extend completion date for CPRR-95
ROOP, J E, LATHAM, B B Twomey, Latham & Schmitt 81/01/23 07548-113

--B101270678 Petition for Shoreham Opponents Coalition to institute proceedings on whether good cause exists to extend completion date of CPRR-95
ROOP, J E, LATHAM, B B Twomey, Latham & Schmitt 81/01/23 07548-114

--B101270683 'Conservation Alternative to Power Plant at Shoreham Island.'
RASKIN, P O, DIEHARD, O, MCANULTY, O, Energy Systems Research Group, Inc ESRO 80-31 80/11/30 132pp 07548-147

B101280212 Requests that ASLB accept encl fifth stipulation
EARLEY, A F Hutton & Williams 81/01/23 1p 07556-295

--B101280222 Fifth stipulation that Suffolk County Contentions 11a(i), 11a(v) & 12(iv) will be dropped. Generic issues 11 B & 11.5A will not be pursued. Other contentions intended to be dropped listed
EARLEY, A F Long Island Lighting Co BORDENICK, B M Hearing Branch 4 DEMPSEY, P A Suffolk County, NY 81/01/21 3p 07556-296.

X Utility Final Safety Analysis Report (FSAR) & amends

B101130360 Certifies that Amend 28 to license application, consisting of Revision 20 to FSAR (OL stage) was sent by parcel post on 801211
MORIN, J P Long Island Lighting Co 80/12/19 1p 07496-018

Q Inspection reports, IE Bulletins & correspondence

B101100534 Forwards IE Insp Rept 50-322/00-16 on B00915-1022 Noncompliance noted.
KRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/20 2pp 07444-289

--B101100542 IE Insp Rept 50-322/00-16 on B00915-1022 No noncompliance noted. Major areas inspected work activities, preoperational testing & plant staff activities.
HODGINS, J C Region 1, Philadelphia, Office of the Director KISTER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/11/19. 8pp 07444-291

B101070407 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Steam Turbine Steam Inlet Flange " No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p. 07414-065

B101050125 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Scram Discharge Vol at Dresden Unit 2 " No response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p. 07376-343

B101060129 Forwards IE Info Notice 80-45, "Potential Failure of Backup Manual Scram Capability " No response required.
ORIER, B H Region 1, Philadelphia, Office of the Director 80/12/17. 1p 07397-342.

B101070414 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Fully Insert During Scram at BWR." No written response required.
ORIER, B H Region 1, Philadelphia, Office of the Director 80/12/18. 1p 07414-005.

B101150012 Forwards IE Bulletin 80-29, "Operating Problems W/ Rock Safety-Relief Valves at BWRs." No response required
ORIER, B H Region 1, Philadelphia, Office of the Director 80/12/19 1p. 07464-294

S Reportable occurrences, LERs & related correspondence

B01060485 Forwards preliminary version of "Reactor Bldg Separating Analysis Rept." providing description of analysis performed & including results for reactor bldg primary containment drywell area & 8-ft elevation of second containment
NDVARRD, J.P. Long Island Lighting Co 80/12/22 1p 07393 023

--B01060489 Preliminary version of "Reactor Bldg Separation Analysis Rept"
Stone & Webster Engineering Corp 11600 02-158A 80/12/22 75pp 07593 024

B01190319 Ack receipt of util 801120 final deficiency rept re use of inferior lubricant on 480V Nema Size 3 contactors for Square D motor control ctrs
CARLSON, R.I. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/30 1p 07476 051

--B01190327 Interim deficiency rept re use of inferior lubricant on 480V Nema Size 3 contactors for Square D motor control ctrs. Initially reported on 801022. Factory representative will repair 15 contactors by Feb 1981
NDVARRD, J.P. Long Island Lighting Co 00/11/20 2pp 07476 052.

B0CKET 50-323 DIA3LO CAN-YEN NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

B010220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports"
EISENHUT, D.G. Division of Licensing 80/11/26 0pp

B01130339 Recommends denial of O Fleischaker 801017 request that Commission issue supplemental EIS re environ consequences of Class 9 accident at facility. No evidence presented to warrant reopening environ record
CRANE, P.A. Pacific Gas & Electric Co 81/01/08 2pp 07451 275.

B010210555 Forwards environ qualification of Class 1E control cable mfg by Continental Wire & Cable Co Requests ack of receipt
CRANE, P.A. Pacific Gas & Electric Co 81/01/16 11pp 07489 286.

B010270672 Forwards addl info re QA program per NRC 801007 request info will be incorporated into FSAR
CRANE, P.A. Pacific Gas & Electric Co. 01/01/22 29pp 07345 193

B010300331 Forwards info addressing issues to be reviewed for full power operation, including operating procedures, control room design, preoperational & low power testing, auxiliary feedwater sys, containment design & radiation protection.
CRANE, P.A. Pacific Gas & Electric Co 01/01/26 106pp 07594 174

F Security, radical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01012 & by applicants as part of FSAR
EISENHUT, D.G. Division of Licensing 80/11/13 2pp

B01060012 Requests evaluation of potential complicating factors caused by earthquakes which either initiate or follow initiation of accidents Adequacy review of state & local capabilities re earthquakes requested of FEMA
TEDESCO, R.L. Assistant Director for Licensing 80/12/16 5pp 07399 048

B010100849 Informs that licensee must conduct emergency exercises within one yr from B01001 or prior to issuance of CL Requests schedule of drills & exercises
ENOELEK, R.H. Region 9, San Francisco, Office of the Director 80/12/19 1p 07442 298.

B010100741 Requests that encl facility emergency planning info be made publicly available w/o encl
SCUDER, J.L. Division of Rules and Records 80/12/31 1p 07445 129

B010100832 Notifies of acceptance of 600711 guard training & qualification plan
MIRACLIA, F.J. Licensing Branch 3 81/01/01 3pp 07442:299.

B010120591 Forwards comments re Revision 10 of physical security plan to be resolved prior to license issuance Comments withheld (ref 10CFR2 750)
MIRACLIA, F.J. Licensing Branch 3 81/01/01 5pp 07447 204

B010150696 Requests that encl facility emergency planning info be made publicly available w/o encl 0012240129
SCUDER, J.L. Division of Rules and Records 81/01/09 1p 07472 323

B010190700 Requests that encl facility emergency planning info be made publicly available w/o encl 8012290469
SCUDER, J.L. Division of Rules and Records 81/01/09 1p 07472 321

B010300722 Releases public version of util emergency plan response.
FELTON, J.H. Division of Rules and Records 81/01/26 1p 07584 159

--B010300728 Forwards public version of response to NRC 800826 request for addl info re site emergency plan, Revision 2 & 800030 request re field property
CRANE, P.A. Pacific Gas & Electric Co. 81/01/13 62pp 07504 160.

--B010300735 Superior Court order granting land rights to util for implementation of emergency response plans
MIRACLIA, F.J. California, State of 80/10/14 3pp 07584 2

G Adjudicatory correspondence

B01050382 Response to joint intervenors' contentions & CA Governor Brown statement on subjs in which he intends to participate. Opposes litigating contentions because record is closed & no grounds exist to reopen records.
CRANE, P.A., OEHR, A.C. Pacific Gas & Electric Co OEHR, A.C. Bn Wilmer 80/12/18 47pp 07385 099

--B01050380 Advises that FEMA/NRC Steering Committee has determined that power testing criteria are not needed. Encl position is adequate
CRINES, D.W. Emergency Preparedness Program Office (after B01111 see 16E), RYAN, R. Office of State Programs, Director 80/12/22 2pp 07385 146.

B010360018 Response to joint intervenors request for directed certification Opposes request because record is closed on all issues & request raises no significant new evidence. Certificate of Svc encl
CRANE, P.A., OEHR, A.C. Pacific Gas & Electric Co OEHR, A.C. Bn Wilmer 80/12/18 37pp 07397 066

B010210136 Informs that technical divisions will provide testimony to refute CA Governor Brown B01203 Contentions 1, 2, 3 & Svc fuel load/low power license.
TEDESCO, R.L. Assistant Director for Licensing 00/12/31 1p 07489 361.

B01090223 Request, identified as proposed findings of fact, that AD 790927 partial initial decision be affirmed. Decision concluded that D 75 g acceleration was appropriate, reanalysis reasonable & Category 1 structure adequate.
CLMSTEAD, W.J., KETCHEN, E.O. Hearing Branch 4 81/01/06 88pp 07423 284.

B010120439 Certifies svc of NRC proposed findings of fact & conclusions of law in reopened seismic proceedings & responses to ASLAD questions on B01016.
KETCHEN, E.O. Hearing Branch 4 81/01/06 3pp 07447 169.

B010140877 Requests that WC Martin, Batelle-Columbus Labs, be deleted from svc list
OEHR, E.S. Atomic Safety and Licensing Board Panel 81/01/08 07459 218

B010140949 Joint intervenors' reply to applicant & NRC responses to statement of contentions. Objections undermined by recent NRC revision of 780620 statement of policy. Adopts Governor Brown contentions. Certificate of Svc encl.
REYNOLDS, J.R., OLEISCHAKER, O. San Luis Obispo Mothers for Peace REYNOLDS, J.R. Center for Law in the Public Interest 81/01/08 10pp 07458 227.

B010140279 Response to ASLD 801217 order requesting continued deferral of joint intervenors 790509 motion on Class 9 issues. Emergency planning contentions must be admitted & ASLAD decision on seismic matters issued. Certificate of Svc encl.
CLMSTEAD, W.J. Hearing Branch 4 81/01/12 15pp 07458 124

8101140925 Forwards NRC Div of Licensing 810101 ltr to util re
Revision 10 to security plan & NRC comments on revision
Comments withheld (ref 10CFR2 7901 W/o ltr
SHARTZ,L L Office of the Executive Legal Director. 81/01/12. 1p
07458 262

8101160278 Supplement to reply to P&E & NRC responses to Joint
Intervenor's statement of contentions On Page 5, Line 9, 17
should be deleted & on Line 14, 14, 18 & 20 deleted & 14, 15,
18, 19 & 24 inserted Certificate of Svc encl
REYNOLDS, J R San Luis Obispo Mothers for Peace REYNOLDS, J R
Center for Law in the Public Interest FLEISCHAKER, D Fleischaker,
O B 81/01/12 3pp 07470 279

8101260301 Response opposing Joint Intervenor's & CA Governor Brown
801215 proposed findings re 791015 Imperial Valley
earthquake Certificate of Svc encl
MORTON, B., FURBUSH, M H., GEHR, A C Pacific Gas & Electric Co.
81/01/16. 32pp. 07523 340

8101270739 Brief discussing definition of "several" as used in
10CFR73.110111. Term "several" means up to & including three
attackers
SHARTZ, L L Antitrust Division OLMESTEAD, W J Hearing Branch 4.
81/01/19 8pp. 07183 001

8101280131 Order scheduling 810128 conference w/ASLB & parties' counsel
in Bethesda, MD re matters discussed in 810121 conference
cell Certificate of Svc encl
BOWERS, E B Atomic Safety and Licensing Board Panel 81/01/21
7pp. 07556 093

8101280620 Response to Joint Intervenor's 810108 reply to applicant &
NRC responses to contentions Revised statement of policy,
CL1-80-42, did not change Commission position. TMI-related
contentions must be denied w/ Certificate of Svc
MORTON, B., FURBUSH, M H., GEHR, A C Pacific Gas & Electric Co.
81/01/23 13pp 07557 292

H General correspondence

810120046 Urges rejection of Facility license in light of TMI
incident.
ROBINSON, T Affiliation Unknown. 79/04/04 1p 07447 005

8101090372 Responds to 790404 postcard re facility NRC has reacted
positively to improve safety of all nuclear power plants in
operation & under const Response to concern re proximity of
Hogri fault to facility encl
MIRAGLIA, F Licensing Branch 3 80/12/11 3pp 07425 268

8101060030 Responds to 790414 ltr expressing concerns re facility
safety. Low level radioactivity effects, storage of high
level redwaste & ability to withstand severe earthquakes
poses insignificant level of danger to public.
MIRAGLIA, F J Licensing Branch 3. 80/12/16 6pp. 07399 151

8101090791 Responds to Apr 1979 ltr to President Carter expressing
concern re nuclear power safety. NRC currently requires all
applicants for new OAs to modify design & operation of
nuclear plants to conform to TMI-related requirements.
MIRAGLIA, F J. Licensing Branch 3. 80/12/16. 6pp. 07309 001

810120002 Responds to 790402 ltr NRC is presently conducting generic
proceeding to reassess degree of confidence in disposal
methods to determine disposal availability & to provide
storage
MIRAGLIA, F. J. Licensing Branch 3. 80/12/16 4pp. 07447 105

810120191 Responds to 801208 ltr ASLB considering application for OL
authorizing fuel loading & low power testing of Unit 1.
ASLB reviewing portions of ASLB "Partial Initial Decision"
re seismic matters & applicant physical security plan
INGRAM, F. L. Office of Public Affairs. 80/12/16 1p. 07309 001

--810120196 Requests info re status of facility & names of
decisionmakers.
OAKNIB, S. Affiliation Unknown. 80/12/08. 1p. 07309 001

8101190128 Ack receipt of 801214 ltr expressing concern re opening of
facilities. Ltr will be placed in appropriate public docket
file
MANCHETT, J O Region 5, San Francisco. Office of the Director.
81/01/02 1p 07475 323

--8101190161 Expresses concern re opening of facilities.
HAYB, M Affiliation Unknown 80/12/14 1p. 07475 324

8101190286 Ack receipt of 801227 ltr expressing concern re opening of
facilities. Ltr will be placed in appropriate public docket
file
MANCHETT, J O Region 5, San Francisco. Office of the Director.
81/01/02 1p 07476 089

--8101190797 Expresses concern re opening of facilities.
BERNIGAN, S Affiliation Unknown 80/12/27 1p 07476 090

8101200209 Ack receipt of 801227 ltr expressing concern re opening of
facilities. Ltr will be placed in appropriate public docket
file
MANCHETT, J O Region 5, San Francisco. Office of the Director
81/01/02 1p 07187 001

--8101260126 Expresses concern re opening of facility
HOFBERG, S J Affiliation Unknown 80/12/27 1p 07187 001

O Inspection reports, IE Bulletins & correspondence

8101050014 Responds to IE Bulletin 00-19 No CP Core Model 162x-1011
necessary-welded rebar used in logic matrix at facility
CRANE, R A Pacific Gas & Electric Co 80/11/25. 1p 07107 001

8101130366 Forwards completed response to IE Bulletin 79-02 re pape
support base plate designs using concrete expansion bolts
CRANE, R A Pacific Gas & Electric Co 80/12/03 11pp 07309 001

8101050504 Forwards IE Info Notice 80-43, "Failures of Continuous Wa
Level Monitor for Steam Discharge Vol at Dresden Unit 2 "
No response required
ENGELKEN, R H Region 5, San Francisco. Office of the Director
80/12/09 1p 07387 292

8101190822 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown " No response
required
ENGELKEN, R H Region 5, San Francisco. Office of the Director
80/12/16 1p 07308 001

8101210145 Forwards IE Insp Repts 90-275/80-22 & 90-323/80-11 on
801202-05 & 10 No noncompliance noted
SPENCER, D S Region 5, San Francisco. Reactor Construction &
Engineering Support Branch 00/12/24 2pp 07490 001

--8101210153 IE Insp Repts 90-275/80-22 & 90-323/80-11 on 801202-05
No noncompliance noted Major areas inspected. license action
on previous insp findings, QA audits & cleanup crew work
control sys procedures
BOWERS, E B Region 5, San Francisco. Reactor Construction &
Engineering Support Branch. MIRAGLIA, F J Region 5, San Francisco
Office of the Director. 00/12/23 7pp 07490 003

I Hearing transcripts on non-antitrust matters

8101300364 Transcript of 810128 hearing in Bethesda, MD, Pp 1-206
& Atomic Safety and Licensing Board Panel 81/01/28 210pp
07578 258

DOCKET 90-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants. CP held
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FBAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101140329 Requests that each facility emergency planning info be re
publicly available. W/o encl
BOWDER, J L. Division of Rules and Records 80/12/31. 1p
07458 010

8101230059 Releases public version of util evacuation study
FELTON, J H Division of Rules and Records 81/01/08 1p
07511 026

--8101230066 Forwards public version of preliminary results of
evacuation study for 10-mile emergency planning zone, in
response to NRC 791129 request Final rept will be available
approx 810201
UTLEY, E E Carolina Power & Light Co 80/12/29 6pp. 07511 010

8101260631 Releases public version of util revised emergency plan
FELTON, J H Division of Rules and Records 81/01/16 1p
07524 300

0637 Forwards public version of revised radiological emergency plan. W/o State of SC emergency plan Cross-ref against C-0634 criteria encl
Y.E.E Carolina Power & Light Co 80/12/30 6pp 07524-310

0644 Public version of revised radiological emergency plan. W/o State of SC emergency plan.
Carolina Power & Light Co 80/12/31 180pp 07524-316

ting license stage documents & correspondence

54 Ltr to all licensees (except SEP licensees) forwarding on 1 of inservice surveillance requirements for reactors under STS License amend application adding model 1. Reactors to App A should be submitted within 120 days
UT, D O Division of Licensing 80/11/20 1p

00271 Revised Pages 3/4 7-22 through 2R, B 3/4 7-5 & 7-6 & 8-17 to scrubber inservice insp requirements
Division of Licensing 80/11/20 10pp

66 Ltr to all power reactor licensees & applicants forwarding copy of 801112 meeting re implementation of guidance for revised Safety Issue A-12. "Potential for Low Fracture Stress & Lateral Tearing on Component Supports"
UT, D O Division of Licensing 80/11/26 6pp

173 Ltr to all BWR licensees forwarding 801201 generic safety issue re BWR scram discharge sys. Recommends short-term actions necessary to ensure safe operation of OE BWRs during permanent design changes
UT, D O Division of Licensing 80/12/09 2pp

0141 Generic safety evaluation re short-term actions required to ensure continued safe operation of operating BWRs. Continued operation of plants is acceptable pending permanent design. Criteria for implementing design mods encl
Division of Licensing 80/12/01 212pp 07183-001

45 Forwards responses to questions on Rule 50.71a. "Periodic testing of FSARs" & IIR notice of final rule SEP plants need comply w/rule until program is complete. Non-SEP plants comply within specified time frame
UT, D O Division of Licensing 80/12/15 13pp

032 Forwards Amends 33 & 34 to Licenses DPR-71 & DPR-62, respectively, safety evaluation & notice of issuance & availability
TD, T A Operating Reactors Branch 2 80/12/23 2pp, 162

0539 Amends 33 & 34 to Licenses DPR-71 & DPR-62, respectively, using Tech Specs to provide one-time extension of certain surveillance intervals allowing required testing to be deferred
UL170, T A Operating Reactors Branch 2 80/12/23 3pp, 10-164

0545 Safety evaluation supporting Amends 33 & 34 to Licenses DPR-71 & DPR-62, respectively
Office of Nuclear Reactor Regulation, Director 80/12/23 3pp, 088-202

0550 Notice of issuance & availability of Amends 33 & 34 to Licenses DPR-71 & DPR-62, respectively
UL170, T A Operating Reactors Branch 2 80/12/23 2pp, 10-205

0543 Forwards Amends 32 & 33 to Licenses DPR-71 & DPR-62, respectively, safety evaluation & notice of issuance & availability
TD, T A Operating Reactors Branch 2 00/12/29 2pp, 086

0557 Amends 32 & 33 to Licenses DPR-71 & DPR-62, respectively, using Tech Specs by adding limiting conditions for operations w/bases to clarify term operable as applied to test sys
UL170, T A Operating Reactors Branch 2 80/12/29 18pp, 08-088

0566 Safety evaluation supporting Amends 32 & 33 to Licenses DPR-71 & DPR-62, respectively
Office of Nuclear Reactor Regulation, Director 80/12/29 2pp, 08-106

0571 Notice of issuance & availability of Amends 32 & 33 to Licenses DPR-71 & DPR-62, respectively
UL170, T A Operating Reactors Branch 2 80/12/29 2pp, 10-108

801060494 Forwards repl. entitled, "Control Room Habitability Evaluation, Brunswick Steam Electric Generating Plant." Rept responds to all info requested in NUREO-0737 & NRC 800507 IIR
UTLEY, E.E Carolina Power & Light Co 80/12/30 3pp 07393-099

--801060493 "Control Room Habitability Evaluation, Brunswick Steam Electric Generating Plant"
S. J. DER, J.E., ARCIERI, W.C., BROADHURST, R.H. NUS Corp. NUS-3697 80/12/31 112pp, 07393-102

801140188 Requests FR publication of encl notice of issuance of facility OL or amend. Referenced documents are available in PRR W/o encl.
e Operating Reactors Branch 2 80/12/30 1p 07461-208

801060555 Informs that 801105 application requesting extension of end dates for performing certain insp & tests requires Class III fee for one unit & Class I fee for second unit.
PL008, R.H. License Fee Management Branch 80/12/30, 1p, 07471-296

801060587 Responds to NUREO-0737 re clarification of post-TMI action plan requirements. Items addressed: shift technical supervisor, training for mitigating core damage, containment isolation dependability & inplant radiation monitoring.
UTLEY, E.E Carolina Power & Light Co 80/12/31 140pp, 07399-175.

801160442 Provides update re Mark I containment program mods. Completion scheduled for Jul 1982. Plant unique analysis experiencing 3-month slippage which will delay completion.
UTLEY, E.E Carolina Power & Light Co 81/01/00 1p, 07472-102.

801190414 Forwards corrected Pages 4-7 & 6-9 to "Control Room Habitability Evaluation, Brunswick Steam Electric Generating Plant."
UTLEY, E.E Carolina Power & Light Co 81/01/13 1p, 07476-023

--801190419 Corrected Pages 4-7 & 6-9 to "Control Room Habitability Evaluation, Brunswick Steam Electric Generating Plant"
SL10ER, J.E., ARCIERI, W.C., BROADHURST, R.H. NUS Corp. NUS-3697 ERR 81/01/13 2pp 07476-024

801190609 Responds to NRC 801209 generic BER re BWR scram discharge sys. Sys mods will be completed prior to completion of next refueling outage. Util will review any scram which occurs during cycle & verify correct sys function.
UTLEY, E.E Carolina Power & Light Co 81/01/13, 2pp, 07475-175.

0 Inspection reports, IE Bulletins & correspondence

801270073 Informs that corrective actions to 1E Insp Repts 50-324/80-24 & 50-325/80-27 will be delayed until 801212 due to manpower requirements resulting from IE Bulletins 79-018 & 80-17
TOLLISON, A.C. Carolina Power & Light Co 80/09/18 1p, 07550-105

801050184 Forwards Revision 2 to HB Robinson & Revision 1 to Brunswick 90-day repts. W/o Brunswick rept
FURR, B.J. Carolina Power & Light Co 80/11/21 2pp 07380-001

801050597 Forwards 1E Info Notice 80-43, "Failures of Continuous Meter Level Monitor for Scram Discharge Vol at Dresden Unit 2." No response required
O'REILLY, J.F. Region 2, Atlanta, Office of the Director 80/12/05, 1p 07391-014

801160264 Forwards 1E Insp Repts 50-324/80-35 & 50-325/80-38 on 801001-31. No noncompliance noted.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/12/05, 2pp, 07470-267.

--801160268 1E Insp Repts 50-324/80-35 & 50-325/80-38 on 801001-31. No noncompliance noted. Major areas inspected: plant logs, physical security barriers, radiation protection & fire protection
QUITTB, J.E. Region 2, Atlanta, Office of the Director, KULLDOG, P.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/12/04 6pp 07470-269.

801050638 Forwards supplemental response to 1E Bulletin 80-11, "Masonry Wall Design." All safety-related concrete masonry walls in diesel generator bldg will maintain structural integrity during seismic event. Three walls will be upgraded.
FURR, B.J. Carolina Power & Light Co 80/12/09 3pp, 07387-020.

801070620 Submits supplemental response to 1E Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Estimated manpower expended for response was 48-h.
FURR, O.J. Carolina Power & Light Co 80/12/15 1p, 07415-318

8101060167 Forwards 1E Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/17 1p 07391 281

8101070039 Forwards Suppl 4 to 1E Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR." No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/18 1p 07413 350

8101050161 Forwards 1E Bulletin 80-25, "Operating Problems w/Target Rod Safety Relief Valves at BWRs." No response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/19 2pp 07377 264

8101100831 Confirms corrective actions re Health Physics Appraisal Insp on 801200-19 Actions taken established program for determining effectiveness of respirator fit & improved procedures for evaluating uptake of radioactivity
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/24 1p 07443 256

8101160005 Responds to 1E Bulletin 80-24 re preventing damage from water leakage inside containment Facility does not use any open cooling water sys One leakage from closed cooling water sys caused by mechanical damage
FURR, B. J. Carolina Power & Light Co 80/12/24 2pp 07469 255

8101290220 Provides interim rept in response to 1E Bulletin 79-02, 79-07 & 79-14 Several flaws exist whose seismic requirements are unclear & which require addl review As-built walkoffs & short-term analyses completed for essential hangers.
TOLLISON, A. C. Carolina Power & Light Co 00/12/31 3pp 07569 354

R Periodic operating reports & related correspondence

8101210405 Forwards monthly operating repts for Dec 1980.
TOLLISON, A. C. Carolina Power & Light Co. 01/01/09 1p 07493 108

--8101210408 Monthly operating repts for Dec 1980
WILLIS, E. A. Carolina Power & Light Co 01/01/06 12pp 07493 109

S Reportable occurrences, LERs & related correspondence

8012230491 LER 80-051/03L-0 on 801116, during insp of reactor bldg exhaust ventilation radiation monitor 2-CAC-AT-1264, monitor particulate collector unit found missing two O-rings & misaligned particulate filter support surface
TOLLISON, A. C. Carolina Power & Light Co 80/12/16 2pp 07316 227

8101050033 Nonroutine 30-day radiological environ event rept on 801205, discovered failure to provide 30-day notification of gross beta concentration in Feb 1980 air particulate samples. Caused by computation error in original calculation.
TOLLISON, A. C. Carolina Power & Light Co 80/12/24 1p 07379 333

8101300565 RD on 000222 & 25, during weekly air particulate sampling analysis, gross beta activity exceeded Tech Spec limits Caused by computational error in original calculation
TOLLISON, A. C. Carolina Power & Light Co 80/12/24 1p 07582 362

8101050029 Fourteen-day rept on 801215, failure to install particulate filter holder rendered reactor bldg exhaust monitor inoperable Caused by personnel error. Holder replaced & operating procedures revised to ensure monitor checks
TOLLISON, A. C. Carolina Power & Light Co 80/12/29 1p 07385 272

8101050401 RO 2-00-105 on 801226, while operating at approx 56% power, reactor scrammed resulting in HPCI trip & isolation on high exhaust pressure. Caused by low level auto initiation signal Trip reset. Damaged snubbers repaired
TOLLISON, A. C. Carolina Power & Light Co 80/12/29 2pp 07378 361

8101070370 Forwards LER 80-105/03L-0
TOLLISON, A. C. Carolina Power & Light Co 80/12/30 1p 07406 349

--8101070373 LER 80-105/03L-0 on 801202, TIP machine A found w/o IIP indication which prevented closing of A TIP ball valve. Caused by bent tube guide chafing & extending probe cable until brakeage occurred.
TOLLISON, A. C. Carolina Power & Light Co. 80/12/30 2pp 07406 350

8101070498 Forwards LER 80-112/01T-0
TOLLISON, A. C. Carolina Power & Light Co 80/12/30 1p

--8101070502 LER 80-112/01T-0 on 801219, determined that sec water pump for planned maint on 2A nuclear svc water p discharge check valve 2-ED-V24 required rept Caused by Spec misinterpretation Personnel retrained
TOLLISON, A. C. Carolina Power & Light Co 80/12/31 2pp 07419 076

8101070365 Forwards LER 80-098/03L-0
TOLLISON, A. C. Carolina Power & Light Co 00/12/31 1p

--8101070358 LER 80-098/03L-0 on 801202, valve packing of re isolation cooling steam isolation valve 2-ESI-F007 Four have failed & allowed leakage of steam condensate Cause packing failure. Valve repacked
TOLLISON, A. C. Carolina Power & Light Co 80/12/31 1p 07406 348

8101070491 Forwards LER 80-108/03L-0
TOLLISON, A. C. Carolina Power & Light Co 00/12/31 1p

--8101070493 LER 80-108/03L-0 on 801202, drywell equipment d integrator indicating five gpm w/no pumps running Cause drywell equipment drain square root converter being out of calibr Converter recalibr
TOLLISON, A. C. Carolina Power & Light Co 80/12/31 1p 07406 360

8101090511 RO on 810103 during normal reactor startup & reactor pressure at 717 psig, safety relief valve B21-F013 lifted, relieving feed pump to trip Low level reactor scram resulted Pilot to F0130 replaced
TOLLISON, A. C. Carolina Power & Light Co. 01/01/05 2pp 07442 077

8101130548 Forwards LER 80-107/03L-0
TOLLISON, A. C. Carolina Power & Light Co 01/01/07 1p

--8101130554 LER 80-107/03L-0 on 801200, svc water sys primary temp reached 212F Caused by removal of shutdown cooling capability for maint w/access to primary containment op subsequent heatup of primary coolant due to decay heat
POLK, R. M. Carolina Power & Light Co. 01/01/07 4pp

8101130561 Forwards LER 80-111/03L-0
TOLLISON, A. C. Carolina Power & Light Co 01/01/07 1p

--8101130568 LER 80-111/03L-0 on 801210, 12 & 18, reactor core exceeded Tech Spec caused by increase in coolant feed product inventory originating from leaking fuel element
PASTVA, M. J. Carolina Power & Light Co 01/01/07 3pp 07454 166

8101140508 Forwards LER 80-110/03L-0
TOLLISON, A. C. Carolina Power & Light Co 01/01/08 1p

--8101140514 LER 80-110/03L-0 on 801212, surveillance require ventilation dampers isolation on fire, toxic gas or high radiation signals not performed Caused by requirements omitted from periodic test during 1979 revision.
PASTVA, M. J. Carolina Power & Light Co 01/01/08 1p

8101200624 Forwards LER 80-102/03L-0
TOLLISON, A. C. Carolina Power & Light Co 01/01/08 1p

--8101200628 LER 80-102/03L-0 on 801212, during reactor start rod 26-35 had to be bypassed in full out position to allow startup to continue. Probably caused by faulty signal from rod position feed switch to rod sequence control sys
PASTVA, M. J. Carolina Power & Light Co 01/01/08 1p

8101130535 Forwards LER 80-113/03L-0
TOLLISON, A. C. Carolina Power & Light Co. 01/01/09 1p

--8101130540 LER 80-113/05L-0 on 801211, primary containment control inerting inlet isolation valve 2-CAC-V48 had to be open/close position indication Cause unknown Suppl rept be issued following investigation
PASTVA, M. J. Carolina Power & Light Co 01/01/09 1p

8101130532 Forwards LER 80-106/01T-0
TOLLISON, A. C. Carolina Power & Light Co 01/01/09 1p

--B101150538 LER 80-106/01T-0 on B01226, HPCI sys tripped immediately after low level 2 auto-initiation on high steam line exhaust pressure signal. Caused by water hammer event in exhaust line HPCI sys trip reset
POULK.R H Carolina Power & Light Co 81/01/09 2pp. 07463 182

B101160524 Forwards LER 80-109/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/09 1p. 07471 279

--B101160581 LER 80-109/03L-0 on B01215, primary containment atmospheric monitor 2-CAC-AT-1259 tripped due to low sample flow. Caused by moisture in monitor pressure regulator & photohelic unit. Moisture removed & photohelic unit replaced
TOLLISON, A C Carolina Power & Light Co 81/01/09 2pp. 07471 279

B101220405 Forwards LER 80-115/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/15 1p. 07494 099

--B101220407 LER 80-115/03L-0 on B01222, reactor vessel conductivity, exceeded 2 umho/cm2 for 27.3-h w/highest measured value at 3.35 umho/cm2. Caused by high conductivity condensate in heater drains sys being concentrated in vessel
POULK.R H Carolina Power & Light Co 81/01/15 1p. 07494:090

B101290586 Special rept while performing periodic test of fire barrier penetration seals. 300 seals were found in nonfunctional condition. Caused by inadequate sealing during installation. Seals identified & mapped for repairs
TOLLISON, A C Carolina Power & Light Co 01/01/15 1p. 07576 151

B101270703 Forwards LER 80-114/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/20 1p. 07546 349

--B101270708 LER 80-114/03L-0 on B01224, low level switch 2E21-L16-N031D-3 actuated outside Tech Specs. Caused by instrument drift. Switch recalibr
PASTVA, M J Carolina Power & Light Co 01/01/20 1p. 07546 350

B10123027R Forwards updated LER 80-040/03L-1
TOLLISON, A C Carolina Power & Light Co 01/01/20 1p. 07553 054

--B101230202 Updated LER 80-080/03L-1 on B01019, stuck reactor instrument penetration isolation valve X76-B made containment atmospheric control monitors 1259, 1260 & 1261 inoperable. Caused by satellite nipple broken off activation switch
PASTVA, M J Carolina Power & Light Co 81/01/20 1p. 07553 055

B101270688 Forwards LER 80-119/03L-0
TOLLISON, A C Carolina Power & Light Co 01/01/21 1p. 07309 001

--B101270675 LER 80-119/03L-0 on B01225, primary containment atmospheric monitor 2-CAC-AT-1263 hydrogen analyzer transmitter had no output signal. Caused by dirty contacts on monitor local/remote switch. Contacts cleaned & monitor recalibr
PASTVA, M J Carolina Power & Light Co 01/01/21 2pp. 07309 001

B101270788 Forwards LER 80-118/03L-0
TOLLISON, A C Carolina Power & Light Co 01/01/22 1p. 07549 147

--B101270794 LER 80-118/03L-0 on B01231, position indication 38-11 showed superimposed 3 over 8 digit when at position 48. Caused by rod switch problem in rod prototypic inlet piping probe. Problem will be corrected during next available outgo
PASTVA, M J Carolina Power & Light Co 81/01/22 1p. 07549 148

B101270606 Forwards LER 80-117/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/23 1p. 07546 329

--B101270606 LER 80-117/03L-0 on B01227, RHR sys water pump 2C vibrations exceeded Tech Specs. Caused by pump diffuser entraining pin dislodging from casing & embedding between diffuser vane & pump impeller pin replaced.
PASTVA, M J Carolina Power & Light Co 81/01/23 2pp. 07546:330

B101270600 Forwards LER 80-116/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/23 1p. 07549 149

--B101270807 LER 80-116/03L-0 on B01231, pressure switch 2-E11-PB-N010A actuated outside Tech Spec limits. Caused by instrument drift. Switch recalibr
PASTVA, M J Carolina Power & Light Co 81/01/23 1p. 07549 150

LOCKE 80-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1
F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plant & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101140325 Requests that encl facility emergency planning publicly available w/o encl.
BOUDER, J L Division of Rules and Records 80/12/31 07458:010

B101230039 Releases public version of util evacuation study
FELTON, J H Division of Rules and Records 81/01/08 07911:026

--B101230046 Forwards public version of preliminary reevaluation study for 10-mile emergency planning zone, response to NRC 791129 request. Final rept will be available B10201
URLEY, E E Carolina Power & Light Co 80/12/29 6p

B101260631 Releases public version of util revised emergency plan w/o State of SC
FELTON, J H Division of Rules and Records 81/01/16 07924:208

--B101260637 Forwards public version of revised radiological plan w/o State of SC. Emergency plan cross-ref against NUREG-0634 criteria encl.
URLEY, E E Carolina Power & Light Co 80/12/30 6p

--B101260644 Public version of revised radiological emergency plan
* Carolina Power & Light Co 80/12/31 150pp. 075

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except BEP licensees) for Revision 1 of inservice surveillance requirements for snubbers under BTR License amendment application adding mod Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--B101160271 Revised Pages 3/4 7-22 through 28.8 3/4 7-5 BTR snubber inservice insp requirements
* Division of Licensing, 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicant summary of B01112 meeting re implementation of guidance Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing, 80/11/26 8pp.

B101190113 Ltr to all BWR licensees forwarding B01201 general evaluation re BWR scram discharge sys. Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes
EISENHUT, D O Division of Licensing 80/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions to assure continued safe operation of operating BWRs. Concludes operation of plants is acceptable pending permanent design changes. Criteria for implementing design mods encl.
* Division of Licensing 80/12/01 212pp. 07183:0

B101210445 Forwards responses to questions on Rule 50.71a Updating of FSARs & FR notice of final rule. BEP plants not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing 80/12/15 13pp

B101210532 Forwards Amende 33 & 34 to Licenses DPR-71 & D respectively, safety evaluation & notice of issuance & availability.
IPPOLITO, T A Operating Reactors Branch 2. 80/12/23 07488:162

--B101210539 Amende 33 & 34 to Licenses DPR-71 & DPR-62, revising Tech Specs to provide one-time extension of surveillance intervals allowing required testing to be performed.
IPPOLITO, T A Operating Reactors Branch 2. 80/12/23 07488:164

--B101210945 Safety evaluation supporting Amendments 33 & 34 to Licenses
OPR-71 & OPR-62, respectively
• Office of Nuclear Reactor Regulation, Director 00/12/23 3pp
07488 202

--B101210950 Notice of issuance & availability of Amendments 33 & 34 to
Licenses OPR-71 & OPR-62, respectively
IPPOL170.T A Operating Reactors Branch 2 00/12/23 2pp.
07488 205.

B101210943 Forwards Amendments 32 & 33 to Licenses OPR-71 & OPR-62,
respectively, safety evaluation & notice of issuance &
availability
IPPOL170.T A Operating Reactors Branch 2 00/12/29 2pp
07488 006

--B101210957 Amendments 32 & 33 to Licenses OPR-71 & OPR-62, respectively,
changing Tech Specs by adding limiting conditions for
operations & bases to clarify term operable as applied to
safety sys
IPPOL170.T A Operating Reactors Branch 2 00/12/29 18pp
07488 080

--B101210966 Safety evaluation supporting Amendments 32 & 33 to Licenses
OPR-71 & OPR-62, respectively
• Office of Nuclear Reactor Regulation, Director 00/12/29 2pp
07488 106

--B101210971 Notice of issuance & availability of Amendments 32 & 33 to
License OPR-71 & OPR-62, respectively
IPPOL170.T A Operating Reactors Branch 2 00/12/29 2pp
07488 108

B101060494 Forwards report entitled, "Control Room Habitability
Evaluation, Brunswick Steam Electric Operating Plant." Report
responds to all info requested in NUREG-0737 & NRC 800507
ltr
UTLEY, E E Carolina Power & Light Co 00/12/30 3pp 07393 099

--B101060490 "Control Room Habitability Evaluation, Brunswick Steam
Electric Operating Plant."
GL10ER, J E, ARCIERI, W C, BROADHURST, R H NUS Corp NUS-3697
00/12/31 112pp. 07393 102

B101140188 Requests for publication of final notice of issuance of
facility DL or amend Referenced documents are available in
PDR W/o encl
• Operating Reactors Branch 2 00/12/30 1p 07461 208

B101160955 Informs that B01105 application requesting extension of
end dates for performing certain insp & tests requires
Class III fee for one unit & Class I fee for second unit
0100S, R H License Fee Management Branch 00/12/30 1p.
07171-276

B101060987 Responds to NUREG-0737 re clarification of post-TMI action
plan requirements. Items addressed shift technical
supervisor training for mitigating core damage, containment
isolation dependability & inplant radiation monitoring.
UTLEY, E E Carolina Power & Light Co 00/12/31 140pp 07399 175

B101160442 Provides update re Mark I containment program costs.
Completion scheduled for Jul 1982 Plant unique analysis
experiencing 3-month slippage which will delay completion
UTLEY, E E Carolina Power & Light Co 01/01/00 1p 07472 102.

B101190414 Forwards corrected Pages 4-7 & 6-9 to "Control Room
Habitability Evaluation, Brunswick Steam Electric Operating
Plant."
UTLEY, E E Carolina Power & Light Co 01/01/13 1p 07476 023.

--B101190419 Corrected Pages 4-7 & 6-9 to "Control Room Habitability
Evaluation, Brunswick Steam Electric Operating Plant."
GL10ER, J E, ARCIERI, W C, BROADHURST, R H NUS Corp NUS-3697
ERR 01/01/13 2pp 07476 024.

B101190609 Responds to NRC 001209 generic BER re BWR scram discharge
sys. Sys mods will be completed prior to completion of next
refueling outage. Util will review any scram which occurs
during cycle & verify correct sys function.
UTLEY, E E Carolina Power & Light Co 01/01/13 2pp. 07475 175

0. Inspection reports, IE Bulletins & correspondence

B101270873 Informs that corrective actions to IE Insp Repts
50-324/80-24 & 50-325/80-27 will be delayed until 01/01/12
due to manpower requirements resulting from IE Bulletins
79-018 & 79-017.
TOLLISON, A C Carolina Power & Light Co 00/09/18 1p 07550 109.

B101050184 Forwards Revision 2 to HQ Robinson & Revision 1 to
Brunswick 90-day repts W/o Brunswick rept
FURR, B J Carolina Power & Light Co 00/11/21 2pp 07380 001

B101050397 Forwards IE Info Notice 80-43, "Failures of Continuous Wa-
Level Monitor for Scram Discharge Vol at Dresden Unit 2." No
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/12/01
1p 07391 014

B101160264 Forwards IE Insp Repts 50-324/80-35 & 50-325/80-38 on
B01001-31 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 00/12/03 2pp 07470 267

--B101160268 IE Insp Repts 50-324/80-35 & 50-325/80-38 on 001001-31 A
noncompliance noted Major areas inspected plant logs,
physical security barriers, radiation protection & fire
protection
OUTTS, J E Region 2, Atlanta, Office of the Director
KELLCOB, P J Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 00/12/04 6pp 07470 267

B101050638 Forwards supplemental response to IE Bulletin 00-11,
"Masonry Wall Design." All safety-related concrete masonry
walls in diesel generator bldg will maintain structural
integrity during seismic event. Three walls will be upgraded.
FURR, B J Carolina Power & Light Co 00/12/09 3pp. 07387 020

B101070620 Submits supplemental response to IE Bulletin 80-21, "Valve
Yokes Supplied by Malcolm Laundry Co. Inc." Estimated
manpower expended for response was 48-h.
FURR, B J Carolina Power & Light Co 00/12/15 1p 07415 310

B101060167 Forwards IE Info Notice 80-45, "Potential Failure of BWR
Backup Manual Scram Capability." No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/12/11
1p. 07371 281

B101070039 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 1
Control Rods to Fully Insert During Scram at BWR." No
written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/12/10
1p 07413 350.

B101090161 Forwards IE Bulletin 80-25, "Operating Problems W/Target
Rock Safety Relief Valves at BWRs." No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/12/11
2pp 07377 264

B101100831 Confirms corrective actions re Health Physics Appraisal
Insp on B01208-19. Actions taken established program for
determining effectiveness of respirator fit & improved
procedures for evaluating uptake of radioactivity
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/12/21
1p 07443 256

B101160005 Responds to IE Bulletin 80-24 re preventing damage from
water leakage inside containment Facility does not use any
open cooling water sys. One leakage from closed cooling
water sys caused by mechanical damage
FURR, B J Carolina Power & Light Co. 00/12/24 2pp 07469 255

B101290228 Provides interim report in response to IE Bulletins 79-02, 79-
07 & 79-14. Several lines exist whose seismic requirements
are unclear & which require add'l review. As-built walkoffs &
short-term analyses completed for essential hangers.
TOLLISON, A C Carolina Power & Light Co 00/12/31 3pp
07569 354

R. Periodic operating reports & related correspondence

B101210405 Forwards monthly operating reports for Dec 1980
TOLLISON, A C Carolina Power & Light Co 01/01/09 1p 07493 101

--B101210408 Monthly operating reports for Dec 1980
WILLIS, E A Carolina Power & Light Co 01/01/06 12pp
07493 109

S. Reportable occurrences, LERs & related correspondence

B101300502 Forwards LER 80-087/03L-0
TOLLISON, A C Carolina Power & Light Co 00/12/01 1p 07586 310

--B101300507 LER 80-097/03L-0 on 801105 control rods 50-27 & 38-23 exhibited position indication problems. Caused by defective rod position indication reed switches. Corrective maint will be completed during outage
TOLLISON, A C Carolina Power & Light Co 80/12/01 1p 07596 312

B101300568 Forwards LER 80-090/03L-0
TOLLISON, A C Carolina Power & Light Co 80/12/01 1p 07592 348

--B101300572 LER 80-090/03L-0 on 801101 during routine surveillance, containment atmospheric control monitor 1-CAC-AI-1259 was observed indicating downscale. Caused by instrument drift. Monitor recalibrated satisfactorily.
TOLLISON, A C Carolina Power & Light Co 80/12/01 2pp 07592 349

B101050033 Nonroutine 30-day radiological environ event rept on 801205 discovered failure to provide 30-day notification of gross beta concentration in Feb 1980 air particulate samples. Caused by computation error in original calculation
TOLLISON, A C Carolina Power & Light Co 00/12/24 1p 07379 333

B101000565 RO on 800222 & 25 during weekly air particulate sampling analysis, gross beta activity exceeded Tech Spec limits. Caused by computational error in original calculation
TOLLISON, A C Carolina Power & Light Co 00/12/24 1p 07592 362

B101050027 Fourteen-day rept on 801215 failure to install particulate filter holder rendered reactor bldg exhaust monitor inoperable. Caused by personnel error. Holder replaced & operating procedures revised to ensure monitor checks
TOLLISON, A C Carolina Power & Light Co 80/12/29 1p 07385 272

B101090511 RO on 810103 during normal reactor startup & heater w/ reactor pressure at 717 psig, safety relief valve 821-F0130 lifted causing feed pump to trip. Low level reactor ecran resulted. Pilot to F0130 replaced
TOLLISON, A C Carolina Power & Light Co 81/01/05 2pp 07442 077

B101090667 Forwards LER 80-086/03L-0
TOLLISON, A C Carolina Power & Light Co 01/01/05 1p 07430 283

--B101090676 LER 80-086/03L-0 on 801207 during testing, linear heat generation rate found at 13,359 kW/ft. DD-1 performed & rate exceeded limit. Apparently caused by low power range monitor D drifting w/inlet subcooling
TOLLISON, A C Carolina Power & Light Co 81/01/03 2pp 07430 284

B101200626 Forwards LER 80-091/03L-0
TOLLISON, A C Carolina Power & Light Co 01/01/08 1p 07477 259

--B101200629 LER 80-091/03L-0 on 801211 rod block monitor B observed indicating downscale. Caused by failed power supply due to defective power supply regulator & zener diode in power supply regulator circuit. Regulator & diode replaced
PASTVA, M J Carolina Power & Light Co 81/01/08 1p 07477 260

B101220399 Forwards LER 81-001/01T-0
TOLLISON, A C Carolina Power & Light Co 81/01/14 1p 07505 176

--B101220402 LER 81-001/01T-0 on 810103 feed pump tripped on high vessel level due to safety-relief valve 821-F0130, Model 67F, lift. Caused by high second stage & pilot leakage in valve. Pilot valve temporarily replaced until next scheduled outage
POUCH, R M Carolina Power & Light Co 81/01/14 1p 07505 177

B101220393 Forwards LER 80-092/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/15 1p 07505 174

--B101220396 LER 80-092/03L-0 on 801220 reactor vessel conductivity measured over Tech Spec level. Caused by removal of reactor water cleanup sys from svc for valve maint. Valves repaired & sys returned to svc.
PASTVA, M J Carolina Power & Light Co 01/01/15 1p 07505 175

B101270627 Forwards LER 81-003/03L-0
TOLLISON, A C Carolina Power & Light Co 01/01/20 1p 07546 334

--B101270631 LER 81-003/03L-0 control rod 26-35 on 810103, 18-51 on 810112, 30-31 & 22-19 on 810114 showed inaccurate position indications. Caused by buffer card failure on 26-35 defective reed switches in others. Card replaced, switches repaired.
PASTVA, M J Carolina Power & Light Co 01/01/20 1p 07546 335

B101270587 Forwards LER 80-093/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/21 1p 07546 327

--B101270595 LER 80-093/03L-0 on 801228 rod worth minimizer insert/withdrawal rod block at rod group 56 when rods withdrawn in correct position. Caused by computer rod worth minimizer software problems. Problems corrected.
PASTVA, M J Carolina Power & Light Co 01/01/21 1p

600REF 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

E NRC Safety Evaluation Report (SER), supply & correspondence

B101120176 Forwards mailed-up copy of draft SER, Suppl 4 Comments needed by 801229 to mail draft SER to ACRS members on 801230
TEDESCO, R L Assistant Director for Licensing 80/12/24 07430 319

B101270078 Forwards final version of Suppl 4 to SER on hydro control. Comments requested by 810115 w/o encl
TEDESCO, R L Assistant Director for Licensing 81/01/13 07347 208

F Security, medical, emergency & fire protection plans

B101070238 Requests that encl emergency planning info be made available w/o encl
SOUDER, J L Division of Rules and Records 80/12/17 1p 07414 296

B101090922 Forwards facility emergency planning info to be made publicly available w/o encl
SOUDER, J L Division of Rules and Records 80/12/17 1p 07427 361

B101210607 Transcript of 001217 briefing on TVA emergency off facilities in Washington, DC. Pp 1-45
Commissioners 80/12/17 49pp

B101100724 Requests that encl facility emergency planning info be made publicly available w/o encl
SOUDER, J L Division of Rules and Records 00/12/31 1p 07445 126

B101200227 Releasee public version of util revised emergency plan
FELTON, J M Division of Rules and Records 01/01/13 1p 07478 066

--B101200233 Forwards public version of revised radiological emergency plan
MILLS, L M Tennessee Valley Authority 80/12/31 1p

--B101200237 Public version of revised radiological emergency multi-jurisdictional plan encl
Tennessee Valley Authority 80/12/31 475pp 07478 066

B101300115 Forwards facility emergency planning info for plant LPOR w/o 8101000123
SOUDER, J L Division of Rules and Records 81/01/16 1p 07583 090

J Insurance & Indemnity Information

B101140353 Forwards Endorsements 32 & 33 to MAELU Policy NF-247
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants Div. 80/11/20 3pp 07457 111

B101090526 Forwards Endorsement 19 to ANI Policy NF-247
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants Div. 80/12/28 3pp 07442 280

B101090662 Forwards Endorsement 18 to NELIA Policy NF-247
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants Div. 80/12/20 2pp 07442 051

B101090566 Forwards Endorsement 2 to ANI Binder EB-66
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants Div. 80/12/30 2pp 07427 347

D Advisory Committee on Reactor Safeguards reports & correspondence

B101280531 Minutes of 242nd ACRS meeting on 800605-07 in Washington re subcommittee rept on Sequoyah Units 1 & 2 Agenda & appx encl
ACRS - Advisory Committee on Reactor Safeguards 80/12/30 700pp 07550 332

DOCKETED ITEMS

B101280487 Appro to minutes of 243rd ACRB meeting on 800710-12 in Washington, DC re Sequoyah Units 1 & 2 & FY82 Budget Agenda encl.
* ACRB - Advisory Committee on Reactor Safeguards 80/11/25
300pp. 0730B 001

B101160446 Summarizes B1010B-10 ACRB meeting w/NRC & TVA re proposed interim hydrogen control sys. Results of analyses & tests support conclusion that distributed ignition sys could improve protection against breach of containment
MARK, J. C. ACRB - Advisory Committee on Reactor Safeguards
81/01/13 1p 0747D 081.

B101300814 Concurs w/NRC recommendation to allow operation of interim distributed ignition sys at facilities NRC & util must continue to describe performance characteristics of sys over broader range of conditions
MARK, J. C. ACRB - Advisory Committee on Reactor Safeguards.
81/01/13 1p 0758A 316

B101290209 Forwards ACRB B10113 ltr re interim hydrogen control sys review.
SCHWENCER, A Licensing Branch 2 81/01/14 2pp 0757S 027

P. Operating license stage documents & correspondence

B101060040 Forwards request for proposed amend to DL to conform w/IE Bulletin 80-18 re adequate min flow through centrifugal charging pumps. Requests NRC finding on proposed mods by B10117 w/o encl.
SCHWENCER, A Licensing Branch 2 80/12/05 1p. 07399 132.

B101060256 Requests info re temp profile for equipment survivability, local detonations & pressure profiles on shell-interior walls, CLABIX modeling of ice bed heat transfer & combustion phenomena, particularly number of ignitors
TEDESCO, R. L. Assistant Director for Licensing 80/12/10 1p 07399:087.

B101100606 Forwards Amend 1 to License BPR-77, safety evaluation & notice of issuance & availability
SCHWENCER, A Licensing Branch 2. 80/12/22 2pp 07443 124.

--B101100614 Amend 1 to License BPR-77, revising Tech Specs re testing of certain valves in different mode of plant operation
SCHWENCER, A Licensing Branch 2 80/12/22 4pp 07443 126.

--B101100620 Notice of issuance & availability of Amend 1 to License BPR-77
SCHWENCER, A Licensing Branch 2. 80/12/22 2pp 07443 130

--B101100626 Safety evaluation supporting Amend 1 to License BPR-77.
* Licensing Branch 2. 80/12/22. 4pp 07443 132.

B101210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mods NRC will not comment on until 800917 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT, B. O. Division of Licensing. 80/12/29 2pp.

B101090215 Application for revisions to License BPR-77, deleting inappropriate items from license & moving completion date of items originally scheduled for completion from 820101 to Aug 1982
MILLS, L. M. Tennessee Valley Authority 80/12/30. 3pp 0737B 326

--B101090227 Proposed changes to Tech Specs, deleting inappropriate items from license & moving completion date of items originally scheduled 820101 to end of first refueling outage scheduled for Aug 1982.
* Tennessee Valley Authority. 80/12/30 3pp. 0737B:329.

B101190420 Advises that util B01009 ltr provided correct interpretation of Tech Spec Section 4.4.3.2.4 surveillance requirement.
TEDESCO, R. L. Assistant Director for Licensing 80/12/30 3pp. 0747S:171.

B101050255 Corrects error in util B01219 ltr re submission date for design details of post-incident sampling sys at facility per NUREG-0737. Details will be provided by B01010 & will apply to both units.
MILLS, L. M. Tennessee Valley Authority 80/12/31 1p 07389:144

B101050334 Forwards analyses re probability of barge collision & of resulting explosion hazard at ERCW intake structure. Analyses submitted per Item 2 C(4) of OL requirements
MILLS, L. M. Tennessee Valley Authority 80/12/31 5pp 07369 328

B101120411 Forwards proprietary & nonproprietary versions of summary rept. "Westinghouse Reactor Vessel Level Instrumentation Sys Fee Monitoring Inadequate Core Cooling (Upper Head Injection)" & application & affidavit for withholding
MILLS, L. M. Tennessee Valley Authority. 81/01/02 9pp 07439 238

B101120331 Forwards revised Page VIII-B to Vol 2 of facility core degradation program, addressing NRC concern re polyurethane foam insulation in ice condenser
CROSS, J. L. Tennessee Valley Authority. 81/01/06 2pp 07447 116

B101160429 Forwards containment purge study for facility, in support of revision to Tech Spec 3.6.1.9 re containment purge limits
MILLS, L. M. Tennessee Valley Authority 81/01/08 6pp 07472 150

B101160494 Forwards info re control room habitability, per NUREG-0737. Operators are adequately protected against effects of accidental release of chemicals. Facility can operate safely or shut down under OGA conditions
MILLS, L. M. Tennessee Valley Authority. 81/01/13 3pp 07472 134

B101220291 Advises that mod to containment boundary components will be completed by B10130. Personnel air lock has less yield pressure capacity than structural capability.
MILLS, L. M. Tennessee Valley Authority. 81/01/15 1p 07494 009

B101270702 Application to amend License BPR-77, removing independent essential raw cooling water sys trains required by Tech Spec 3.7.4. Reasons & justifications for amend encl.
CROSS, J. L. Tennessee Valley Authority 81/01/19 4pp 07545 239

B101260416 Forwards upgraded Table II to "Electrical Equipment Environmental Qualification Rept.," summarizing current interim status of electrical equipment qualification, per NRC request during B01217-19 audit. Original rept submitted B01031
CROSS, J. L. Tennessee Valley Authority 81/01/20 1p 07520:161

--B101260420 Updated Table II to "Electrical Equipment Environmental Qualification Rept."
* Tennessee Valley Authority 81/01/20 51pp 07520:162.

B101270647 Responds to NRC request during B10121 visit. Discussions re short-term thermal effects of hydrogen burn on equipment & assessment of temp curves D & E for equipment survivability evaluations encl.
CROSS, J. L. Tennessee Valley Authority 81/01/22. 5pp 07545 282

G. Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC B00707-1 Insp of Util Div of Engineering Design. OGA organization restructured to provide sufficient organizational freedom, authority & access to mgt
KIMMONS, D. H. Tennessee Valley Authority. 80/10/08 3pp 07462:012

B101100351 Forwards IE Insp Rept 50-327/80-38 on B00901-30 & notice of violation
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/11/28 2pp. 07443:341

--B101100356 Notice of violation from Insp on B00901-30
* Region 2, Atlanta, Office of the Director. 80/11/26. 1p 07443:343

--B101100364 IE Insp Rept 50-327/80-38 on B00901-30. Noncompliance no improper maint of procedure required by Tech Spec
BUTLER, B. D. Region 2, Atlanta, Office of the Director. DANCE, H. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/11/26 8pp 07443 344.

B101090825 Ack receipt of B01121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-327/80-39.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/11 1p. 07430:262.

--B101090834 Response to NRC B01030 ltr re violations noted in IE Insp

--8101690341 Forwards 1E Insp Rept 80-327/80-23 on 800916-19 & notice of violation
LEWIS R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch
00/10/30 2pp 07430 265

--8101690345 Notice of violation from insp on 800916-19
* Region 2, Atlanta, Office of the Director 80/10/29 1p
07430 267

--8101690349 1E Insp Rept 80-327/80-39 on 800916-19 Noncompliance noted
LERs not submitted in accordance w/tech Spec time requirements & diesel generator failure repts incomplete
JULIAN C Region 2, Atlanta, Office of the Director DANCE H C
Region 2, Atlanta, Reactor Operations Nuclear Support Branch
80/10/29 5pp 07430:268

8101120240 Forwards response to 1E Bulletin 80-20 re Westinghouse Type
W-2 control switches w/spring return to neutral position
Switches used in all facilities except Yellow Creek Lists
sys in which switches are employed
MILLS L M Tennessee Valley Authority 80/12/12 2pp 07447 060

8101150013 Responds to 1E Bulletin 80-23 re failures of solenoid valves
mfg by Valcor Engineering Corp Facility does not have valves
w/notes & part numbers described
MILLS L M Tennessee Valley Authority 80/12/15 1p 07462:152

810160203 Forwards 1E Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown" No written
response required
O'REILLY J P Region 2, Atlanta, Office of the Director 80/12/16
1p 07391.312

8101220303 Forwards response to 1E Bulletin 80-24, "Prevention of
Damage Due to Water Leakage Inside Containment"
CRDSS J L Tennessee Valley Authority 81/01/05 19pp 07580 274

R Periodic operating reports & related correspondence

8101050241 Forwards essential raw cooling water conduit settlement
monitoring data
MILLS L M Tennessee Valley Authority 80/12/31 1p 07378 318

--8101050250 Essential raw cooling water conduit settlement monitoring
data Oversize Tables 02 B6-1 & 02 B4-1 encl.
* Tennessee Valley Authority 80/12/31 5pp 07378 319

8101160472 Forwards monthly operating rept for Dec 1980
BALLETINE J M Tennessee Valley Authority 81/01/07 1p
07471:234

--8101160474 Monthly operating rept for Dec 1980
OUPREE D Tennessee Valley Authority 81/01/02 10pp
07471:235

8101220155 Forwards "Environ Radioactivity Levels, Sequoyah Nuclear
Plant, Annual Rept 1979" Monitoring program responsive to US
Fish & Wildlife Svc recommendations & requests.
MILLS L M Tennessee Valley Authority 81/01/15 1p 07496:081

--8101220164 "Environ Radioactivity Levels, Sequoyah Nuclear Plant, Annual
Rept 1979."
* Tennessee Valley Authority RH-00-7-802 80/08/31 33pp
07496:082

S Reportable occurrences, LERs & related correspondence

8101250336 Forwards LER 80-176/03L-0.
GREEN H J Tennessee Valley Authority 80/11/21 1p 07056 318

--8101250339 LER 80-176/03L-0 on 801020, lower steam failed 81-159, i.
overall leakage test Caused by airlock inner door ball
valve leak Valve repaired.
COTTELE W T, KIRK Q B Tennessee Valley Authority 80/11/21
2pp 07056 319

8101060166 Forwards LER 80-192/03L-0
GREEN H J Tennessee Valley Authority 80/12/30 1p 07391:BBB

--8101060477 LER 80-192/03L-0 on 801201, F14 control bank B rod position
indicator deviated by greater than 12 steps from control
bank B demand counter Caused by shift in caliber of control
bank indicator Indicator recaliber & returned to spec.
COTTELE W T, WILKEY A M Tennessee Valley Authority 80/12/30
1p 07391:089

8101070374 Forwards LER 80-194/03L-0
GREEN H J Tennessee Valley Authority 80/12/30

--8101070377 LER 80-194/03L-0 on 801201, found circuit
120-volt vital instrument power board 1-11 tripped
radiation monitors 1-RE-90-112/134/141 inoperable
failure of O-RE-90-134 motor Motor replaced.
COTTELE W T, WILKEY A M Tennessee Valley Authority
1p 07414 179

8101130690 Forwards LER 80-198/03L-0
GREEN H J Tennessee Valley Authority 81/01/05

--8101130612 LER 80-198/03L-0 on 801204, containment h
1-u7AH-43-210 failed weekly functional test 181-b
checked w/4K sample Caused by unauthorized closure
reagent air flow rotameter Analyzer returned to spec
COTTELE W T, WILKEY A M Tennessee Valley Authority
1p 07309 001

8101130457 Forwards LER 80-193/03L-0
GREEN H J Tennessee Valley Authority 81/01/06

--8101130461 LER 80-193/03L-0 on 801208, review ident
functional test instruction for monitors provided
termination of release did not adequately demonstrate
automatic isolation Caused by inadequate instruction
COTTELE W T, WILKEY A M Tennessee Valley Authority
3pp 07457 015

8101160477 Forwards LER 80-199/03L-0
GREEN H J Tennessee Valley Authority 81/01/07

--8101160483 LER 80-199/03L-0 on 801209, high steam flow
& steam/feedwater flow mismatch bistable found se
Tech Spec values Caused by low actual differential
produced at flow transmitter Setpoints recaliber
MCGRIFF J M, WILKEY A M Tennessee Valley Authority
2pp 07471 256

8101210466 RD 80-6 on 801201 & 02 Na-24 was inadvert
turbine bldg sump Caused by inadequate test instruct
poor communications between test directors & radioc
lab personnel
GREEN H J, FRASER D A Tennessee Valley Authority
10pp 07493 321

8101210449 Forwards LER 80-201/03L-0
GREEN H J Tennessee Valley Authority 81/01/14

--8101210454 LER 80-201/03L-0 on 801216, diesel gener
start during test on diesel generator 2A-A Caused
relay flashed in diesel generator control circuit
in blown fuse Relay & fuse replaced
MADDOX B D, MCGRIFF J M Tennessee Valley Authority
3pp 07187 001

8101220311 Forwards first interim rept re potential f
suspended ceiling tile in control rooms in response
801104 ltr Addl info to be provided by 810211
MILLS L M Tennessee Valley Authority 81/01/14

8101220499 Forwards LER 80-204/03L-0
GREEN H J Tennessee Valley Authority 81/01/14

--8101220509 LER 80-204/03L-0 on 801216, axial flux di
target band longer than 1-h Caused by rod stopping
maintain power & blocked borate paths due to low
settling Notice to maintain temp at 200 F put on c
MCGRIFF J M, KIRK Q B Tennessee Valley Authority
1p 07501:196

8101220511 Forwards LER 80-203/03L-0
GREEN H J Tennessee Valley Authority 81/01/14

--8101220518 LER 80-203/03L-0 on 801216, during ice co
intermediate deck door under AHU-3A found frozen
Caused by AHU-3A drain line flange leaking Ice on
door flange gasket replaced & leakage stopped.
MCGRIFF J M, KIRK Q B Tennessee Valley Authority
1p 07501:233

8101220523 Forwards LER 80-200/03L-0.
GREEN H J Tennessee Valley Authority 81/01/15

801220532 LER 80-200/03L-0 on 801217, valves 1-FCV-1-15, 16 & 17 found not to have been stoic tested after repacking on 801207. Caused by engineer & craft failure to notify proper personnel. Valves tested & personnel instructed.
MCGRIFF, J H, WIRK, G R Tennessee Valley Authority 81/01/15 1p 07497 315

801220202 Notification of noncompliance w/effluent limitations. Three samples collected on 801222 exceeded max permit limitation of 9.0 units when valve was inadvertently left open. Plant employees instructed to check all valves.
EL-ABRY, M T Tennessee Valley Authority 81/01/16 2pp 07500 087

801220318 Informa of mechanical malfunction of water treatment plant flocculator on 801001. Equalization tank sludge built up on hydraulic line & caused clogging which shut down operations. Sludge recouped to makeup demineralized sludge.
EL-ABRY, M T Tennessee Valley Authority 81/01/19 2pp 07309 001

8012300436 Submits NPDES noncompliance notification. Sewage treatment plant operator inexperienced w/varying strengths of commercial sodium hypochlorite solutions, allowed chlorine levels to remain in excess of permit limitations.
EL-ABRY, M T Tennessee Valley Authority 81/01/19 2pp 07510 312

801300509 Forwards LER 80-206/03L-0
GREEN, H J Tennessee Valley Authority 81/01/22 1p 07586 316

801300525 LER 80-206/03L-0 on 801225, cofueling water storage tank level indicator 1-LI-63-30 found failing high caused by frozen instrument lines for level transmitter inside cabinet housing lines thawed using heat gun & loop returned to svc.
MCGRIFF, J H, WIRK, G R Tennessee Valley Authority 81/01/22 1p 07586 317

Hearing transcripts on non-entirety matters

801090040 Transcript of ACRS Subcommittee on Sequoyah Nuclear Power Plant 801016 meeting in Washington, DC. Pp 1-172. Supporting documents encl.
* ACRS - Advisory Committee on Reactor Safeguards 81/01/06 242pp 07425 001

801090040 SEQUOYAH NUCLEAR PLANT, UNIT 2

Application/construction stage documents & correspondence

801220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports".
EISENHUT, D O Division of Licensing 80/11/26 0pp

801090968 Summary of 801208-12 meetings w/caseload forecast panel. Earliest projected fuel load date for facilities is 810601.
For Sequoyah Unit 2 & Aug 1992 for Watts Bar Unit 1.
KENYON, T J Licensing Branch 2 80/12/16 5pp 07429 356

801210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mode NRC will not comment on until 800917 ltr describing program for resolving issue until rulemaking is finalized.
EISENHUT, D O Division of Licensing 80/12/29 2pp

801090293 Corrects error in util 801219 ltr re submission date for design details of post-accident sampling sys at facility per NUREG-0737. Details will be provided by 80101 & will apply to both units.
MILLS, L M Tennessee Valley Authority 80/12/31 1p 07389 144

801090434 Forwards analyses re probability of barge collision & of resulting explosion hazard at ERCW intake structure. Analyses submitted per item 2 C(4) of O. requirements.
MILLS, L M Tennessee Valley Authority 80/12/31 3pp 07389 328

801120411 Forwards proprietary & nonproprietary versions of summary rept, "Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (Upper Head Injection)" & application & affidavit for withholding.
MILLS, L M Tennessee Valley Authority 81/01/02 9pp 07439 238

801120287 Forwards clarification of TMI action plan for facility per NUREG-0737 requirements. Discusses operating activity correct performance verification, containment isolation dependability & auto PORV isolation & failure rept.
MILLS, L M Tennessee Valley Authority 81/01/07 6pp 07439 326

801160494 Forwards info re control room habitability per NUREG-0737. Operators are adequately protected against effects of accidental release of chemicals. Facility can operate safely or shut down under BHA conditions.
MILLS, L M Tennessee Valley Authority 81/01/13 3pp 07472 134

801220291 Advises that mod to containment boundary components will be completed by 801030. Personnel air lock has less yield pressure capacity than structural capability.
MILLS, L M Tennessee Valley Authority 81/01/15 1p 07494 009

801270662 Advises that fuel load date will be 810415.
MILLS, L M Tennessee Valley Authority 81/01/16 1p 07545 284

E NRC Safety Evaluation Report (SER), supp & correspondence

801120176 Forwards marked-up copy of draft SER, Suppl 4. Comments needed by 801229 to mail draft SER to ACRS members on 801230.
EISENHUT, D O Assistant Director for Licensing 80/12/24 45pp 07438 319

801270670 Forwards final version of Suppl 4 to SER on hydrogen control. Comments requested by 810115 w/o encl.
EISENHUT, D O Assistant Director for Licensing 81/01/13 1p 07547 208

F Security, medical, emergency & fire protection plans

801090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of SAR.
EISENHUT, D O Division of Licensing 80/11/13 2pp

801070238 Requests that encl emergency planning info be made publicly available w/o encl.
SCUDER, J L Division of Rules and Records 80/12/17 1p 07414 296

801090922 Forwards facility emergency planning info to be made publicly available w/o encl.
SCUDER, J L Division of Rules and Records 80/12/17 1p 07427 761

801210607 Transcript of 801217 briefing on IVA emergency offsite facilities in Washington, DC. Pp 1-33.
* Commissioners 80/12/17 49pp

801100724 Requests that encl facility emergency planning info be made publicly available w/o encl.
SCUDER, J L Division of Rules and Records 80/12/31 1p 07445 126

801200227 Releases public version of util revised emergency plan.
FELT, D J Division of Rules and Records 81/01/13 1p 07479 066

801200233 Forwards public version of revised radiological emergency plan.
MILLS, L M Tennessee Valley Authority 80/12/31 1p 07478 060

801200237 Public version of revised radiological emergency plan in multi-jurisdictional plan encl.
* Tennessee Valley Authority 80/12/31 475pp 07478 069

801300115 Forwards facility emergency planning info for placement in LPR w/o 8101080123.
SCUDER, J L Division of Rules and Records 81/01/16 1p 07583 090

J Insurance & indemnity information

801140353 Forwards Endorsements 32 & 33 to MAELU Policy MF-91.
FELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/11/20 3pp 07457 111

801090526 Forwards Endorsement 19 to ANI Policy MF-247.
FELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/12/28 3pp 07442 280

801090463 Forwards Endorsement 18 to NELIA Policy MF-247.
FELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/12/28 2pp 07442 051

B101093566 Forwards Endorsement 2 to AMI Binder EB-66
FIELDER, J. Marsh & Millenian, Inc. & M & M Nuclear Consultants, Inc
Div 80/12/30 2pp 07427 347

Q Advisory Committee on Reactor Safeguards reports & correspondence

B101280531 Minutes of 242nd ACRS meeting on B00605-07 in Washington, DC
re subcommittee rept on Sequoyah Units 1 & 2 Agenda &
apps encl
* ACRS - Advisory Committee on Reactor Safeguards 80/11/06
700pp 07553 332

B101280497 Apps to minutes of 243rd ACRS meeting on B00710-12 in
Washington, DC re Sequoyah Units 1 & 2 FY82 budget Agenda
encl.
* ACRS - Advisory Committee on Reactor Safeguards 80/11/29.
399pp 07308 601

B101160446 Surmaries B10108-10 ACRS meeting w/NRC & TVA re proposed
interim hydrogen control sys. Results of analyses & tests
support conclusion that distributed ignition sys could
improve protection against breach of containment.
MARK, J C ACRS - Advisory Committee on Reactor Safeguards
81/01/13 1p 07470 081

B101300814 Concurs w/NRC recommendation to allow operation of interim
distributed ignition sys at facilities NRC & Util must
continue to describe performance characteristics of sys over
broader range of conditions.
MARK, J C ACRS - Advisory Committee on Reactor Safeguards
81/01/13 1p 07504 316

B101290207 Forwards ACRS B10113 ltr re interim hydrogen control sys
review
SCHWENGER, A Licensing Branch 2 81/01/14 2pp 07575 027.

Q Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC B08707-11
insp of Util Div of Engineering Design OA organization
restructured to provide sufficient organizational freedom,
authority & access to mgt
KIRKUS, G H Tennessee Valley Authority 80/10/00 3pp
07462 012

B10120240 Forwards response to IE Bulletin 80-20 re Westinghouse Type
W-2 control switches w/spring return to neutral position
Switches used in all facilities except Yellow Creek Units
sys in which switches are employed.
MILLS, L M Tennessee Valley Authority 80/12/12 2pp 07447 060

B101060203 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown No written
response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/16
1p

B101270030 Responds to IE Bulletin 80-23 re Valcor Engineering Corp
solenoid valve failure Valcor solenoid valves V70900-21-1 &
V70900-21-3 not used Util waiting for vendor response on
valves in package components
MILLS, L M Tennessee Valley Authority. 80/12/30 1p 07547 021

B101210239 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co, Inc ' Util is in process of obtaining
assurance from valve suppliers that no Malcolm Foundry
yokes are contained in furnished valves
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07490 057

R Periodic operating reports & related correspondence

B101050241 Forwards essential raw cooling water conduit settlement
monitoring data.
MILLS, L M Tennessee Valley Authority 80/12/31 8p 07378 318

--B101050250 Essential raw cooling water conduit settlement monitoring
data Oversight Tables 02 85-1 & 02 84-1 encl
* Tennessee Valley Authority 80/12/31 5pp. 07378 319

B101220155 Forwards "Environ Radioactivity Levels, Bequoyah Nuclear
Plant, Annual Rept 1979" Monitoring program responsive to US
Fish & Wildlife Svc recommendations & requests
MILLS, L M Tennessee Valley Authority 81/01/15 1p. 07496 081.

--B101220164 "Environ Radioactivity Levels, Bequoyah Nuclear Plant, Annual
Rept 1979 "
* Tennessee Valley Authority RH-80-7-502 80/08/31 33pp
07496 082

S Reportable occurrences, LERs & related correspondence

B101290645 Revised B00403 final deficiency rept, originally submitted
B00305, re control room heating, ventilation/air conditioning
sys Corrective actions described in final rept ineffective
in reducing air leakage Addl corrective actions provided
MILLS, L M Tennessee Valley Authority 80/12/19 2pp 07566 1

B101050405 First interim deficiency rept, originally reported on B01005
re seismic analysis for as-built safety-related piping sys
Caused by discrepancies between sys & design drawings Half
of piping & 25% of hangers already inspected
MILLS, L M Tennessee Valley Authority 80/12/29 2pp 07380 1

B101070429 First interim deficiency rept re stress corrosion cracking
in tubing on reactor coolant pump oil coolers, initially
reported on B10207 Util is considering replacement of 90-10
copper-nickel tubing Next rept will be forwarded by B10203
MILLS, L M Tennessee Valley Authority. 81/01/02 2pp 07415 1

B101140635 First interim deficiency rept, originally reported on B01005
re discrepancy in as-built vs as-analyzed piping anchor
location TVA analyzing discrepancy to determine hardware
changes necessary Next rept to be filed by B10220
MILLS, L M Tennessee Valley Authority 81/01/05 2pp 07461 1

B101140405 Second interim deficiency rept initially reported B01005
seismic analysis of check valves in chemical & vol control
sys Loads from 3-inch check valve are not significant. Next
rept will be submitted by B10210
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07461 20

B101260427 Second interim deficiency rept, originally reported on
B01002, re seismic analysis of check valve in chemical &
vol control sys Loads from 3-inch check valve at Bequoyah
insignificant Hardware changes not required
MILLS, L M Tennessee Valley Authority 81/01/06 1p. 07531 12

B101140474 First interim deficiency rept re environ qualification of
safety-related electrical equipment Vendor indicated
solenoid valves not qualified for post-accident environ in
annulus Next rept will be submitted by B10212
MILLS, L M Tennessee Valley Authority 81/01/08 2pp. 07461 1

B101140616 Final deficiency rept re diesel generator interlock dos
interlocks will be added to emergency feeder breaker
automatic close circuit before fuel load Originally reported
on B10209
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07461 1

B101190400 Interim deficiency rept, originally reported on B11210, re
fillet weld misspecification Util in process of evaluating
American Iron & Steel Inst Stds & affected welds Next rept
will be submitted by B10303
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07475 1

B101190480 Fifth interim deficiency rept re upper head injection
isolation valve accumulator weighing sys, initially reported
B00325 Westinghouse will submit revised drawings so design
changes can be incorporated
MILLS, L M Tennessee Valley Authority 81/01/09 1p. 07476 00

B101190485 Third interim deficiency rept re incorrect insulation w
used in piping analysis, initially reported B00424
As-constructed insulation drawings completed Review in
progress
MILLS, L M Tennessee Valley Authority 81/01/09 1p. 07475 36

B101190494 First interim deficiency rept re inability to retrieve
manufacturer valve drawings through any documentation sys by
unique identifier Utilizes as-built valve info comparable to
drawing input data to determine impact on seismic analysis
MILLS, L M Tennessee Valley Authority 81/01/12 2pp 07476 0

B101190388 Revised final deficiency rept, initially reported on B00403
re environ qualification of Class IE instruments in valve
room Deletes erroneous statement in safety implications
section for B0N EEB 8004, Item 6.
MILLS, L M Tennessee Valley Authority 81/01/13 5pp. 07475 2

B101220311 Forwards first interim rept re potential flammability of
suspended ceiling tile in control rooms in response to
B01104 ltr Addl info to be provided by B10211.
MILLS, L M Tennessee Valley Authority 81/01/14 3pp.

B101220562 Final deficiency rept, initially reported B01216, re environ
qualification of electrical equipment Automatic Switch Co
1183318915 solenoids will be replaced w/Valcor Model
70900-301 valves qualified for calculated accident environ.

DOCKETED ITEMS

B101220202 Notification of noncompliance w/effluent limitations Three samples collected on B01222 exceeded max permit limitation of 90 units when valve was inadvertently left open Plant employees instructed to check all valves
EL-ASHRY,M T Tennessee Valley Authority 01/01/16 2pp. 07500:087

B101220318 Informs of mechanical malfunction of water treatment plant flocculator on B01001 Equalization tank sludge built up on hydraulic line & caused crimping which shut down operations Sludge rerouted to makeup demineralizer pump
EL-ASHRY,M T Tennessee Valley Authority 01/01/19 2pp 07309:001

B101230436 Submits NPOEB noncompliance notification Sewage treatment plant operator inexperienced w/varying strengths of commercial sodium hypochlorite solutions,allowed chlorine levels to remain in excess of permit limitations
EL-ASHRY,M T Tennessee Valley Authority 01/01/19 2pp 07510:312

B101260436 First interim deficiency rept.originally reported on B01219, re inadequate steel containment penetration assembly Affected piping will be reanalyzed to determine adequacy of assembly & pipe rupture restraint design
MILLB,L M Tennessee Valley Authority 01/01/19 2pp. 07531:219

B101270732 Final deficiency rept.originally reported on B00918, re shifting of intermediate pipe break locations w/o notifying NRC Safety injection & resistance temp device lines have been re-evaluated & no unacceptable interactions found
MILLB,L M Tennessee Valley Authority 01/01/21 2pp. 07545:290

B101270609 Second interim deficiency rept.originally reported on B101024, re environ qualification of electrical equipment. Submits list of components w/inadequate documentation to verify qualification Next rept will be sent B101217.
MILLB,L M Tennessee Valley Authority 01/01/23 10pp. 07183:001

F. Hearing transcripts on non-antitrust matters

B101090040 Transcript of ACRB Subcommittee on Sequoyah Nuclear Power Plant B10106 meeting in Washington,DC Pp 1-172.Supporting documents encl
9 ACRB - Advisory Committee on Reactor Safeguards 01/01/06 242pp 07425:001

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lenticular Tearing on Component Supports"
EISENHUT,D O Division of Licensing 00/11/26 8pp

B101080345 Confirms plans for B01217 meeting in Glen Ellyn, IL to discuss recently reorganized OA unit Notice of 001217 significant licensee meeting encl.
KEPPLER,J O Region 3, Chicago, Office of the Director 00/12/12 2pp. 07417:349

B101120243 Requests concurrence re util B01126 request that open items related to structural integrity be included for resolution as part of pending structural design audit
HODD,D Licensing Branch 3 00/12/19 2pp 07309:001

--B101120250 Requests that open items re NRC audit of safety-related structures be incorporated into FSAR review & SER preparation.Proposed items external pressure analysis, penetration structural integrity & floor response spectra.
COOK,J W Consumers Power Co. 00/11/26 2pp 07309:001

B101100740 Summary of B01205 meeting w/CRC,Bechtels,Weston Geophysical Corp & Structural Mechanics Associates in Bethesda,MD re seismic input parameters
HODD,D Licensing Branch 3 00/12/22 7pp. 07187:001

B101150916 Forwards util B01231 rept re reactor vessel support mod at facilities,completing mail necessary for NRC review of revised support concept for Unit 1 Util has requested confirmation of acceptability of Unit 2 studs
MIRALIA,F Licensing Branch 3 00/12/23 2ppp 07309:001

--B101050132 Forwards public version of Amend B6 to application CLS,containing Revision 31 to FSAR
COOK,J W Consumers Power Co 00/12/16 4pp 07375:001

B101100592 Notification of B10120 meeting w/Energy Technology Engineering Ctr,util & Bechtel in Bethesda,MD to resolve differences in bending stresses calculated for underground pipes at facilities
HODD,D Licensing Branch 3 00/12/31 5pp 07443:298

B101140815 Summary of B00731 meeting w/Util,Bechtels Corp & B consultants in Bethesda,MD re request for addl soil boring & tests List of meeting attendees,agenda,summary & viewal aids used during meeting encl
HODD,D Licensing Branch 3 01/01/06 35pp 07461:060

B101220109 Updates NRC 001110 ltr granting util request for addl borings & six std penetration test requirements Detail of relaxation & changed boring locations listed
TEDESCO,N L Assistant Director for Licensing 01/01/08 07309:001

--B101220122 Concurs w/NRC B01110 ltr re util request for re making addl borings & testings of soil samples from site Forwards map showing borings in plant fill area & map showing relocated borings on cooling pond dikes
MCALLISTER,P Army,Dept of Corps of Engineers 00/12/07309:001

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT,D O Division of Licensing 00/11/13 2pp

B101070259 Requests that encl emergency planning info be made available w/o encl
SQUEDER,J L Division of Rules and Records 00/12/17 1p 07414:299

B101050116 Releases public version of util emergency plan,Revised to FSAR
FELTOLL,J M Division of Rules and Records 00/12/10 1p 07375:001

--B101050132 Forwards public version of Amend O6 to application CLS,containing Revision 31 to FSAR
COOK,J W Consumers Power Co 01/12/16 4pp 07375:001

--B101050145 Public version of Revision 31 to FSAR
Consumers Power Co 00/11/30 200pp 07375:006

B101270998 Requests that encl facility emergency planning info be publicly available w/o encl.
SQUEDER,J L Division of Rules and Records 01/01/13 1p 07548:361

G Adjudicatory correspondence

B101120444 Response to NRC interrogatories 1-3 re plant fill & discrepancies in magnitude of loading stresses Affidavits encl
EWANDEROW,H AF1F1,S Consumers Power Co 00/12/16 7pp 07442:310

B101050358 Advises of acceptance as intervenor in NRC hearing continuation of facility const.Asked requests time to make presentation at B10120-29 prehearing conference.
MARSHALL,W M Mapleton Intervenors 00/12/22 2pp 07309:001

B101050384 Forwards summary of B00730 conversation w/JO Keppler general NRC enforcement issues Because conversation could be considered ex parte contact in plant proceeding,encl summary should be served on all parties
GIBBONS,T R Commissioners 00/12/29 2pp. 07375:342

B101070684 Notice of F Rinaldi,JO Keppler,Huang,J Kane,W Ott R Erickson,J Brammer,Gilray,Shoemaker,H Singh,A Cappucci & P Chen depositions on B10106,07,09 & 19-22 re issues set forth in order modifying CPs w/Certificate of Bvcs.
FARNELL,A S Consumers Power Co FARNELL,A S 1shar, L

Certificate of Svc encl
PATON, W.D. Hearing Branch 4 80/12/30 4pp 07390 124

B101050424 Memorandum summarizing B01227 telcon between ASLB, CPC, NRC, Mr. Cherry for intervenor KP Sinclair intervenors B Stariris & SA Warren & LM Marshall for Appleton intervenors
BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/12/31
8pp 07387 075

B101070374 Confirms B01219 conversation re B01204 document request. Util documents not suit in atty-client privilege &/or work-product privilege will be available by B10119 at Midland Svc Ctr
FARNELL, A.S. Isham, Lincoln & Seale 80/12/31 1p 07415 297

B101090378 Notice of J. Maitra B10108 deposition in Bethesda, MD re 791206 order modifying CPs & B01024 contentions in app to prehearing conference order ruling on contentions
Certificate of Svc encl
FARNELL, A.S. Consumers Power Co. FARNELL, A.S. Isham, Lincoln & Seale 80/12/31 4pp 07428 260

B101050073 Interrogatories directed to licensee requesting info re piping & backfill matl Certificate of Svc encl
PATON, W.D. Hearing Branch 4 81/01/02 12pp 07376 070

B101120515 Forwards JO Hale B01202-04 depositions per B01204 motion for protective order & NRC B01205 ltr w/o encl
JONES, J.H. Hearing Branch 2 81/01/08 1p 07309 001

B101140948 Request for correction of B01231 memorandum re B01229 telephone conference call Certificate of Svc encl
ZAMARIN, R.G. Consumers Power Co. ZAMARIN, R.G. Isham, Lincoln & Seale 81/01/09 5pp 07458 251

B101140872 Response opposing intervenor B Stariris request to receive deposition copies ASLB is w/o authority per Comptroller
General B01203 ltr Certificate of Svc encl
PATON, W.D. Hearing Branch 4 81/01/12 4pp 07498 214

B101140772 Reply opposing NRC B01204 motion for protective order prohibiting further deposition of J. Kane NRC should be ordered to pay fees & costs incurred in responding to NRC motion & concluding Kane deposition Certificate of Svc encl
ZAMARIN, R.G. Consumers Power Co. ZAMARIN, R.G. Isham, Lincoln & Seale 81/01/12 34pp 07498 262

B101200154 Notice of Keppler & Haider B10116 depositions in Glen Ellyn, IL re 791206 order modifying CPs & contentions in B01024 prehearing conference order app Certificate of Svc encl
FARNELL, A.S. Consumers Power Co. FARNELL, A.S. Isham, Lincoln & Seale 81/01/14 4pp 07486 139

B101200210 Request for leave to file response to CPC B10109 reply to NRC B01204 motion for protective order transcripts not available when order was sought & time considerations noted.
Certificate of Svc encl
OLMSTEAD, W.J. Hearing Branch 4 81/01/16 4pp 07476 337

B101260480 Motion to compel K. Naidu deposition & for order directing NRC to pay util reasonable atty fees & costs Certificate of Svc encl
ZAMARIN, R.G. Consumers Power Co. ZAMARIN, R.G. Isham, Lincoln & Seale 81/01/16 5pp 07524 333

B101230164 Notice of Hendon B01027 deposition in Savoy, IL re issues in ASLB 791206 order & contentions of intervenors Stariris & Warren Certificate of Svc encl
JONES, J.H. Hearing Branch 2 81/01/19 4pp 07312 030

B101260273 Response to intervenor B Stariris B01204 interrogatories & request for production of documents Ltr to Stariris, affidavits & Certificate of Svc encl Related correspondence
* Consumers Power Co. 81/01/21. 12pp 07523 336

B101280149 Order granting NRC B10116 motion to file reply to applicant B10109 response to NRC motion for protective order. Reply must be filed & delivered to ASLB & applicant by close of business on B10126 Certificate of Svc encl
BECHHOEFER, C Atomic Safety and Licensing Board Panel 81/01/22
5pp 07556 102

B101270129 Ack receipt of telegram re free transcripts for intervenor Stariris under FOIA Request denied per encl ALAB-625
PATON, W.D. Hearing Branch 4 81/01/23. 1p. 07546 075.

summaries. BMR study & NRC policy to be given to LPDR.
PATON, W.D. Hearing Branch 4 81/01/23 2pp 07544 097

B101280259 Motion for order compelling G. Fiorelli deposition directing NRC to pay atty fees & costs incurred by util Certificate of Svc encl
FARNELL, A.S. Consumers Power Co. FARNELL, A.S. Isham, Lincoln & Seale 81/01/23 6pp 07557 148

B101290012 Proposed agenda for B10129 prehearing conference conclusion of discovery, further prehearing conferences, motions for summary disposition, filing of testimony, evidentiary hearing & filing of proposed findings of fact
MILLER, M.I. Consumers Power Co. MILLER, M.I. Isham, Lincoln & Seale 81/01/23 2pp 07567 190

--B101290020 Requests order compelling H. Thornburg deposition directing NRC to pay atty fees & costs incurred by util
MILLER, M.I. Consumers Power Co. MILLER, M.I. Isham, Lincoln & Seale 81/01/23 5pp 07567 192

--B101350025 Forwards Input for Midland order Certificate of Svc encl
SHEWMAKER, R.E. Division of Reactor Construction Inspection 79/11/30 5pp 07567 197

B101280573 Response to CPC B10109 reply to NRC motion for protective order Opposes util claim for expenses. Length & method of questioning & Zamarin conduct justify protective order Certificate of Svc encl
JONES, J.H. Office of the Executive Legal Director. 81/01/25 222

B101280611 Response opposing CPC B10115 motion to compel K. Naidu deposition. Scheduled witnesses are equally knowledgeable in exceptional circumstances order Certificate of Svc encl
OLMSTEAD, W.J. Hearing Branch 4 81/01/27 6pp 07597 14

H General correspondence

B101050314 Requests exception to NRC B01215 ltr re transcript facility proceedings. LPDR is 15 miles from home & personal responsibilities do not allow library use during regular hours.
STARIRIS, B. Affiliation Unknown 80/12/22 1p 07379 1

A Utility Final Safety Analysis Report (FSAR) & amendments

B101050116 Releases public version of util emergency plan, R to FSAR
FELTON, J.M. Division of Rules and Records 80/12/30 1

--B101050132 Forwards public version of Amend 06 to application, containing Revision 31 to FSAR
COCK, J.H. Consumers Power Co. 80/12/16 4pp

--B101050145 Public version of Revision 31 to FSAR.
* Consumers Power Co. 80/11/30 200pp. 07375 006

B101270385 Forwards Amend 07 to NL & CP applications, consisting Revision 32 to FSAR, Vols 1-3.
AULTQUIST, L. Bachtel Associates Professional Corp. 81/01/25 120

--B101270390 Revision 32 to FSAR, Vols 1-3
* Consumers Power Co. 81/01/21 900pp. 07558 121.

F Operating license stage documents & correspondence

B101190577 Explains distribution list for two generic ltr re feedwater nozzle cracking
MIRACLA, F.J. Licensing Branch 3. 81/01/06 2pp 0747

G Inspection reports, IE Bulletins & correspondence

B101050283 Forwards 1E Info Notice 80-38, "Cracking in Char Cooling Cladding." No response required
KEPPLER, J.O. Region 3, Chicago, Office of the Director 2pp 07387 240.

B101060717 Forwards 1E Bulletin 80-21, "Valve Yokes Supplied Malcolm Foundry Co., Inc." Written response required.
KEPPLER, J.O. Region 3, Chicago, Office of the Director. 2pp 07400 283

8101060374 Forwards IE Info Notice 80-41. "Failure of Sling Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/10 2pp 07391 070

8101070229 Forwards IE Insp Repts 50-329/80-31 & 50-330/80-32 on 801001-31 & notice of violation
FIORRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/19 2pp 07415 163

--8101070273 Notice of violation from Insp on 801001-31
* Region 3, Chicago, Office of the Director 00/11/18 1p 07415:165

--8101070256 IE Insp Repts 50-329/80-31 & 50-330/80-32 on 801001-31 Noncompliance noted failure to expedite 10CFR50.59 reportability determinations based on 10CFR21 info re possible defects in engine link rods
COOK, J. W. Region 3, Chicago, Office of the Director 80/11/18 8pp 07415 166

8101100011 Forwards IE Insp Repts 50-329/80-30 & 50-330/80-31 on 801007-10 & 15-23 No noncompliance noted
FIORRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/11/21 2pp 07441 297

--8101100013 IE Insp Repts 50-329/80-30 & 50-330/80-31 on 801007-10 & 15-23 No noncompliance noted Major areas inspected training records, audit activity & personnel air locks
NABU, K. R., SUTMILIN, R. N., KNOP, R. C. Region 3, Chicago, Office of the Director 80/11/21 19pp 07441 299

8101050524 Forwards IE Info Notice 80-43. "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director, 80/12/05 2pp 07390 292

8101290099 Forwards IE Insp Repts 50-329/80-27 & 50-330/80-28 on 800923-24, 1103-04, 12-13 & 19 No noncompliance noted
FIORRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/11 2pp 07367 267

--8101290122 IE Insp Repts 50-329/80-27 & 50-330/80-28 on 800923-24, 1103-04, 12-13 & 19 No noncompliance noted Major areas inspected: preservice Insp procedures, personnel certifications & data & IE Bulletin 80-08 activities
WARD, K. O. Region 3, Chicago, Office of the Director, DANIELSON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/10 11pp 07367 269

8101210526 Forwards IE Insp Repts 50-329/80-34 & 50-330/80-35 on 801101-30. No noncompliance noted.
FIORRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/12 2pp 07408 155

--8101210533 IE Insp Repts 50-329/80-34 & 50-330/80-35 on 801101-30 No noncompliance noted Major areas inspected: diesel generator link rods, metal thickness requirements & licensee performance assessment
COOK, J. W. Region 3, Chicago, Office of the Director, 80/12/11 3pp 07408 157

8101050407 Responds to NRC 800D18 ltr & Investigation Repts 50-329/80-13 & 50-330/80-14 Util disagrees w/certain aspects of rept. Bechtel memo & ltr to util from B&W encl.
COOK, J. W. Consumers Power Co. 80/12/16 11pp 07379 209

8101070079 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/16 1p 07415 047

8101290270 Forwards Mgt Meeting Repts 50-329/80-35 & 50-330/80-36 on 801124
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/18 2pp 07575 012

--8101290283 Mgt Meeting Repts 50-329/80-35 & 50-329/80-36 on 801124. Major areas discussed regulatory performance of activities as concluded in systematic assessment of licensee performance program
FIORRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/18 7pp 07575 014

8101050595 Ack receipt of 800825 & 1107 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/80-20 & 50-330/80-21
FIORRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/23 1p 07390 249

--8101050600 Responds to NRC 801108 ltr re violations noted in IE Repts 50-329/80-20 & 50-330/80-21 Corrective actions all met through const phase is receipt inspected by OC
COOK, J. W. Consumers Power Co 80/11/07 3pp 07390 250

8101060267 Ack receipt of 801217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/80-31 & 50-330/80-32
FIORRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/30 1p 07392 010

--8101060272 Responds to NRC 801119 ltr re violations noted in IE Repts 50-329/80-31 & 50-330/80-32 Corrective actions training sessions for key personnel to be conducted re proper handling of Part 21 repts
COOK, J. W. Consumers Power Co 80/12/17 1p 07392 011

8101160296 Forwards IE Insp Repts 50-329/80-33 & 50-330/80-34 on 801201-04 No noncompliance noted
FIORRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/30 2pp 07470 231

--8101160299 IE Insp Repts 50-329/80-33 & 50-330/80-34 on 801201-04 Noncompliance noted Major areas inspected hardness results of embedded bolts for lateral embolism attached to primary coolant pumps
FRB, C. M. Region 3, Chicago, Office of the Director DANIELSON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/30 5pp 07470 253

8101200591 Responds to IE Bulletin 80-23 Valcor solenoid valves used or planned for use in safety-related functions
COOK, J. W. Consumers Power Co 01/01/86 1p 07557 310

8101200586 Forwards notice of violation & notice of proposed imposition of civil penalties re NRC 800306-0731 investigation
STIEL, L. V. Director's Office, Office of Inspection and Enforcement 01/01/87 2pp 07477 290

--8101200590 Notice of violation from investigation on 800306-0731
* Director's Office, Office of Inspection and Enforcement 01/01/87 13pp 07477 292

--8101200395 Notice of proposed imposition of civil penalties in of \$39,000.00 CO for item of violation discovered during investigation on 800306-0731
* Director's Office, Office of Inspection and Enforcement 01/01/87 1p 07477 305

R Periodic operating reports & related correspondence

81012110225 Forwards monthly rept per ALAB-106 Bechtel nonconformance repts, Bechtel nonconformance rept log, Bechtel quality action requests, B&W repts of nonconformity, B&W inservice Insp nonconformance repts & util nonconformance repts encl
COOK, J. W. Consumers Power Co 80/12/23 350pp 07300 001

8101050365 Forwards Rept 32 for Jan-Mar 1901 per Conditions 2FB of Licenses CPPR-01 & CPPR-02 & 730326 Memorandum & Order ALAB-106
COOK, J. W. Consumers Power Co 80/12/30 24pp 07375 346

8101290580 Forwards ALAB-106 monthly rept for Dec 1980 Bechtel nonconformance repts, quality action requests, rept corrective action repts, repts of nonconformity, inservice Insp nonconformance repts & util nonconformance repts, encl
COOK, J. W. Consumers Power Co 81/01/23 400pp 07309 001

S Reportable occurrences, LERs & related correspondence

8101090513 Interim deficiency rept re overstressed condition in cooler supports Mod being evaluated, interim or final rept will be submitted on or before 810130.
COOK, J. W. Consumers Power Co 80/12/30 2pp 07442 285

8101090574 Interim deficiency rept, originally reported on 800327 overstressed condition in inboard cooler supports Mod, intent will be determined after analysis of actual nozzle loads & existing supports is completed by AE
COOK, J. W. Consumers Power Co. 80/12/30 2pp 07442 012

B101090185 EN-60-050 on re about B10102 notice of violation & notice of proposed imposition of civil penalties will be issued to util Action based on 16 infractions re major deficiencies in QA program for hearing contractor
BRECKETT, T. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director B1/01/02 1p 07442 274

B101140653 Interim Deficiency Rept 1 re status of low alloy quenched & tempered bolting 1.5 inches & greater in support of safety-related sys Interim or final rept to be provided by B10231 Description of investigation encl
COOK, J.W. Consumers Power Co B1/01/04 16pp. 07308 001

B101230581 Interim deficiency rept re defective away strut rod ends, initially reported on B01031 Solutions are being investigated & will be coordinated w/all vendors to obtain generic solution Next rept will be forwarded by B10227
COOK, J.W. Consumers Power Co RUTGERS, J.A. Bechtel Power Corp Isubs of Bechtel Corp J. B1/01/15 9pp 07511 220

T Hearing transcripts on non-encl trust matters

B101050033 Proposed transcript corrections to DS Hood B01229 deposition Certificate of Svc encl
PATON, W.O. Hearing Branch 4 B0/12/29 6pp 03889 289

B101300745 Transcript of ASLD B10108 hearing in Flemington, NJ Pg 1-120.
* Atomic Safety and Licensing Board Panel B1/01/08 121pp 07582 001

03067 50-330 MIOLANO PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re Implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D.G. Division of Licensing, B0/11/26 8pp

B101080345 Confirms plans for B01217 meeting in Glen Ellyn, IL to discuss recently reorganized OA unit Notice of B01217 significant licensee meeting encl
KEPPLER, J.G. Region 3, Chicago, Office of the Director B0/12/12 2pp 07417 349

B101120243 Requests concurrence re util B01126 request that open items related to structural integrity be included for resolution as part of pending structural design audit
HODD, D. Licensing Branch 3 B0/12/19 2pp. 07399 001.

--B101120250 Requests that open items re NRC audit of safety-related structures be incorporated into FSAR review & BER preparation Proposed items external pressure analysis, penetration structural integrity & floor response spectra
COOK, J.W. Consumers Power Co. B0/11/26 2pp 07309 001

B101100740 Summary of B01205 meeting w/CPC, Bechtel, Weston Geophysical Corp & Structural Mechanics Associates in Bethesda, MD re seismic input parameters
HODD, D. Licensing Branch 3. B0/12/22 7pp. 07187 001

B101150916 Forwards util B01231 rept re reactor vessel support rod at facilities, completing matl necessary for NRC review of revised support concept for Unit 1 Util has requested confirmation of acceptability of Unit 2 studs
MIRAGLIA, F. Licensing Branch 3 B0/12/23 2ppp 07309 001

B101050116 Releases public version of util emergency plan, Revision 31 to FSAR.
FELTON, J.M. Division of Rules and Records B0/12/30 1p

--B101050132 Forwards public version of Amend B6 to application for CPs & CLs, containing Revision 31 to FSAR
COOK, J.W. Consumers Power Co B0/12/16 4pp

B101100292 Notification of B10120 meeting w/Energy Technology Engineering Ctr, util & Bechtel in Bethesda, MD to resolve differences in bending stresses calculated for underground pipes at facilities
HODD, D. Licensing Branch 3 B0/12/31 9pp 07443 298

B101140815 Summary of B00731 meeting w/util, Bechtel Corp & Bechtel consultants in Bethesda, MD re request for addl soil borings & tests List of meeting attendees, agenda, summary & visual aids used during meeting encl.
HODD, D. Licensing Branch 3 B1/01/06 35pp. 07461 060

B101220109 Updates NRC B01110 ltr granting util request for re addl borings & soil penetration test requirements Detail of relaxation & changed boring locations listed
TEDESCO, R.L. Assistant Director for Licensing B1/01/00 07309 001

--B101220122 Concurs w/NRC B01110 ltr re util request for re making addl borings & testings of soil samples from site Forwards map showing borings in plant fill area & map showing relocated borings on cooling pond dikes.
MCALLISTER, P. Army, Dept of, Corps of Engineers B0/12/07309 001

B101190604 Forwards info package for independent piping analysis decay heat removal & core flooding sys info package updates B00612 submittal of piping design package
COOK, J.W. Consumers Power Co B1/01/12 22pp 07475 177

F Security, medical, emergency & fire protection plans

B101040387 Ltr to all licensees of operating reactor plants, CPs & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D.G. Division of Licensing B0/11/13 2pp.

B101070259 Requests that encl emergency planning info be made available w/o encl.
SOUVER, J.L. Division of Rules and Records B0/12/17 1p 07414 299

B101050116 Releases public version of util emergency plan, Rev to FSAR
FELTON, J.M. Division of Rules and Records B0/12/30 1p. 07375 001

--B101050132 Forwards public version of Amend B6 to application, containing Revision 31 to FSAR.
COOK, J.W. Consumers Power Co. B0/12/16 4pp 07375 001

--B101050145 Public version of Revision 31 to FSAR
* Consumers Power Co. B0/11/30 200pp 07375 006

B101270990 Requests that encl facility emergency planning info publicly available w/o encl
SOUVER, J.L. Division of Rules and Records B1/01/13 1p. 07540 361

G Adjudicatory correspondence

B101120444 Response to NRC Interrogatories 1-3 re plant fill & discrepancies in magnitude of loading stress Affidavits encl
SWANBERG, N. AFIF, S. Consumers Power Co. B0/12/16 7pp 07442 310.

B101050350 Advises of acceptance as intervenor in NRC hearing continuation of facility cost Also requests time to make presentation at B10128-29 prehearing conference.
MARSHALL, W.H. Mapleton Intervenor B0/12/22 2pp. 0737

B101050384 Forwards summary of B00730 conversation w/JO Keppl general NRC enforcement issues Because conversation could be considered as parta contact in plant proceeding, encl summary should be served on all parties.
QIDDOH, T.R. Commissioners, B0/12/29 2pp 07379 342

B101090084 Notice of F Rinaldi, JO Keppler, Hueng, J Kene, W Otto R Erickson, J Brammer, Ollray, Shoemaker, H Singh, A Ceppuchi & P Chen depositions on B10106, 07, 09 & 19-22 re issues set forth in order modifying CPs w/Certificate of Svc.
FARNELL, A.S. Consumers Power Co FARNELL, A.S. Iahem, Lin Deale. B0/12/29 4pp 07426 264

B101090421 Notice of C Gould, RD Peck & MT Devlesson deposition B10113-14 & 14-15, respectively, re issues set forth in ASLD 791206 order modifying CPs & Stamiris & Warren contentions. Certificate of Svc encl
PATON, W.O. Hearing Branch 4. B0/12/30 4pp. 07390 124.

B101050624 Memorandum summarizing B01229 telcon between ASLB, Cherry for intervenor HP Sinclair intervenors B Stamiris & SK Warren & WH Marshall for Mapleton intervenors.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. B0 Bpp. 07387 075.

Ctr.
FARNELL, A S Isham, Lincoln & Seale 80/12/31 1p 07413 297

8101090078 Notice of J Metre 810108 deposition in Bethesda, MD re 791206 order modifying CPs & 801024 contentions in app to prehearing conference order ruling on contentions Certificate of Ovc encl
FARNELL, A S Consumers Power Co. FARNELL, A S Isham, Lincoln & Seale 00/12/31 4pp 07426 260

8101300073 Interrogatories directed to licensee requesting info re piping & backfill matl Certificate of Svc encl
PATON, W O Hearing Branch 4 01/01/02 12pp 07376 070.

810120515 Forwards JO Kene 801202-04 depositions per 801204 motion for protective order & NRC 801205 ltr w/o encl
JONES, B W Hearing Branch 2 81/01/00 1p. 07307 001

8101140968 Request for correction of 801231 memorandum re 801229 telephone conference call Certificate of Svc encl
ZAHARIN, R O Consumers Power Co. ZAHARIN, R O Isham, Lincoln & Seale 01/01/09 3pp 07458 251

8101140972 Response opposing intervenor B Stamiris request to receive deposition copies ASLB is w/o authority per Comptroller General 001203 ltr Certificate of Svc encl
PATON, W D Hearing Branch 4 81/01/12 4pp 07458 214

0101140973 Reply opposing NRC 801204 motion for protective order prohibiting further deposition of J Kene NRC should be ordered to pay fees & costs incurred in responding to NRC motion & concluding Kane deposition Certificate of Svc encl
ZAHARIN, R Consumers Power Co. ZAHARIN, R Isham, Lincoln & Seale 81/01/12 34pp 07458 263

8101200154 Notice of Keppler & Nelder 810116 depositions in Olan Elynn, IL re 791206 order modifying CPs & contentions in 801024 prehearing conference order app Certificate of Svc encl
FARNELL, A S Consumers Power Co. FARNELL, A S Isham, Lincoln & Seale 81/01/14 4pp 07486 139

8101200210 Request for leave to file response to CPC 810109 reply to NRC 801204 motion for protective order. Transcripts not available when order was sought & time considerations noted Certificate of Svc encl
OLMSTEAD, W J Hearing Branch 4 81/01/16 4pp. 07476 337

8101260480 Motion to compel W Naidu deposition & for order directing NRC to pay util reasonable atty fees & costs Certificate of Svc encl
ZAHARIN, R O Consumers Power Co. ZAHARIN, R O Isham, Lincoln & Seale 81/01/16 3pp 07524 303

8101230164 Notice of Hendon 810127 deposition in Sevoy, IL re issues in ASLB 791206 order & contentions of intervenors Stamiris & Warren Certificate of Ovc encl
JONES, B W Hearing Branch 2 81/01/19 4pp. 07512 030

8101260273 Response to intervenor B Stamiris 801204 interrogatories & request for production of documents, ltr to Stamiris, affidavits & Certificate of Svc encl Related correspondence.
e Consumers Power Co 01/01/21 12pp 07523 336

8101280149 Order granting NRC 810116 motion to file reply to applicant 810109 response to NRC motion for protective order. Reply must be filed & delivered to ASLB & applicant by close of business on 810126. Certificate of Svc encl
OECHHOEFER, C Atomic Safety and Licensing Board Panel 81/01/22 3pp. 07536 102

8101270329 Ack receipt of mailgram re free transcripts for intervenor Stamiris under FOIA Request denied per encl ALAB-625
PATON, W D Hearing Branch 4 81/01/23 1p. 07546 075.

8101270394 Ack agreement re intervenor B Stamiris document request Record of CPC 781107 telcon w/NRC, IE Insp Repts 50-329/77-05 & 50-330/77-08, 790508-11 OA Insp rept, meeting summaries, B&W study & NRC policy to be given to LPDR.
PATON, W O Hearing Branch 4 81/01/23 2pp. 07544 097.

8101280279 Motion for order compelling O Fiorelli deposition & directing NRC to pay atty fees & costs incurred by util. Certificate of Svc encl.
FARNELL, A S Consumers Power Co. FARNELL, A S Isham, Lincoln & Seale 81/01/23 6pp. 07557 148.

evidentiary hearing & filing of proposed findings of fact
MILLER, M I Consumers Power Co MILLER, M I Isham, Lincoln & Seale 81/01/23 3pp. 07567 190

--8101290020 Requeste order compelling H Thornburg deposit NRC to pay atty fees & costs incurred by util
MILLER, M I Consumers Power Co. MILLER, M I Isham, Beebe 81/01/23 3pp. 07567 192

--8101290025 Forwards input for Midland order Certificate. SHEWMAKER, R E Division of Reactor Construction Insp 79/11/30. 3pp 07567 197

0101280593 Response to CPC 810109 reply to LRC motion for order. Oppose util claim for expense Length & method of questioning & Zamarin conduct justify protective order. Certificate of Svc encl.
JOER, O W Office of the Executive Legal Director 01/07557 222

8101200611 Response opposing CPC 810115 motion to compel W deposition Scheduled witnesses are equally knowledgeable exceptional circumstances exist Certificate of Svc encl
OLMSTEAD, W J Hearing Branch 4 01/01/27 6pp. 07537 121

H General correspondence

8101090314 Requests exception to NRC 801215 ltr re transcr facility proceedings LPDR is 15 miles from home & personal responsibilities do not allow library use during regular hours
STANIRIS, B Affiliation Unknown 80/12/22 1p 07379

M Utility Final Safety Analysis Report (FSAR) & amends

8101050116 Releasee public version of util emergency plan, to FSAR
FELTON, J M Division of Rules and Records 00/12/30.

--8101050132 Forwards public version of Amend 06 to applic DLs, containing Revision 31 to FSAR
COOK, J W Consumers Power Co 80/12/16 4pp

--0101050145 Public version of Revision 31 to FSAR
e Consumers Power Co 80/11/30 200pp

0101270385 Forwards Amend 07 to DL & CP applications, concls Revision 32 to FSAR, Vois 1-3
AULTOU, B L Bechtel Associates Professional Corp 81/07538 120

--8101270390 Revision 32 to FSAR, Vois 1-3.
e Consumers Power Co. 01/01/21 900pp 07558 121

P Operating license stago documents & correspondence

8101190577 Explains distribution list for two generic ltrs Feedwater nozzle cracking.
MIRAZLIA, F J Licensing Branch 3 01/01/06 2pp. 074

O Inspection reports, IE Bulletin & correspondence

8101050283 Forwards IE Info Notice 80-38, "Cracking in Casing Cladding." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 2pp 07389 240

8101060713 Forwards IE Bulletin 80-21, "Valve Yokes Suppl Helicon Foundry Co, Inc." Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 2pp. 07400 283

8101060371 Forwards IE Info Notice 80-41, "Failure of Swin Valve in Decay Heat Removal Sys at Davis Besse Unit 1." response required
KEPPLER, J O Region 3, Chicago, Office of the Director 2pp 07391 070.

8101070229 Forwards IE Insp Repts 50-329/80-31 & 50-330/80-30101-31 & notice of violation.
FIORELLI, O Region 3, Chicago, Reactor Construction & E Support Branch. 80/11/19 2pp. 07415 163

--B01070237 Notice of violation from insp on B01001-31
Region 3, Chicago, Office of the Director 80/11/18 1p
07415 169

--B01070236 IE Insp Repts 50-329/80-31 & 50-330/80-32 on B01001-31
noncompliance noted: failure to expedite 10CFR50.55
reportability determinations based on 10CFR21 info re
possible defects in engine link rods
CCKA, J. W. Region 3, Chicago, Office of the Director
80/11/18 0pp 07415 16A

B01100011 Forwards IE Insp Repts 50-329/80-30 & 50-330/80-31 on
B01027-10 & 15-23 No noncompliance noted
FIGRELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/21 2pp 07441 297

--B01100913 IE Insp Repts 50-329/80-30 & 50-330/80-31 on B01007-18 &
15-23 No noncompliance noted Major areas inspected training
records, audit activity & personnel ear locks
MAILED, R. W. Region 3, Chicago, Office of the Director
80/11/21 1pp 07441 299

B01050924 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor For Steam Discharge Vial at Dresden Unit 2" No
response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/05
2pp 07390 292

B01029009 Forwards IE Insp Repts 50-329/80-27 & 50-330/80-28 on
B00923-24 1103-04, 12-13 & 19 No noncompliance noted
FIGRELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/11 2pp 07567 267

--B01029012 IE Insp Repts 50-329/80-27 & 50-330/80-28 on B00923-24,
1103-04, 12-13 & 19 No noncompliance noted Major areas
inspected preservice insp procedures, personnel
certifications & data & IE Bulletin 80-00 activities
MAILED, R. W. Region 3, Chicago, Office of the Director
80/12/10 1pp 07567 267

B010210534 Forwards IE Insp Repts 50-329/80-34 & 50-330/80-35 on
B01101-30 No noncompliance noted
FIGRELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/12 2pp 07468 155

--B010210533 IE Insp Repts 50-329/80-34 & 50-330/80-35 on B01101-30 No
noncompliance noted Major areas inspected diesel generator
link rods, metal thickness requirements & licensee
performance assessment
CCKA, J. W. Region 3, Chicago, Office of the Director
80/12/11 2pp 07468 157

B01050407 Responds to NRC B00018 ltr & Investigation Repts
50-329/80-13 & 50-330/80-14 Util disagrees w/certain aspects
of rept Dechtel memo & ltr to util from B&W encl
CCKA, J. W. Consumers Power Co 80/12/16 11pp 07379 289

B01070079 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No written
response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/16
1p 07415 047.

B010290270 Forwards Mgt Meeting Repts 50-329/80-35 & 50-330/80-36 on
B01124
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/18,
2pp 07375 012

--B010290283 Mgt Meeting Repts 50-329/80-35 & 50-329/80-36 on B01124,
Major areas discussed regulatory performance of activities
as concluded in systematic assessment of licensee
performance program
FIGRELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/18, 7pp 07575 014

B01050595 Ack receipt of OCB025 & 1107 ltrs informing NRC of steps
taken to correct violations noted in IE Insp Repts
50-329/80-20 & 50-330/80-21.
FIGRELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/22 1p 07390 249

--B01050600 Responds to NRC B01000 ltr re violations noted in IE Insp
Repts 50-329/80-20 & 50-330/80-21 Corrective actions, all
mat through const phase is receipt inspected by CC
CCKA, J. W. Consumers Power Co 80/11/07 3pp 07390 250

B01060249 Ack receipt of B01217 ltr informing NRC of steps taken
to correct violations noted in IE Insp Repts 50-329/80-31 &
50-330/80-32
FIGRELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/30 1p 07392 010

--B01060272 Responds to NRC B01119 ltr re violations noted in IE Insp
Repts 50-329/80-31 & 50-330/80-32 Corrective actions
training sessions for key personnel to be conducted re
proper handling of Part 21 repts
CCKA, J. W. Consumers Power Co 80/12/17 1p 07392 011

B01160256 Forwards IE Insp Repts 50-329/80-33 & 50-330/80-34 on
B01201-04 No noncompliance noted
FIGRELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/30 2pp 07470 251

--B01160259 IE Insp Repts 50-329/80-33 & 50-330/80-34 on B01201-04
noncompliance noted Major areas inspected hardness results
of welded bolts for lateral snubbers attached to primary
coolant pumps
EGB, C. M. Region 3, Chicago, Office of the Director
04/11/80, D. H. Region 3, Chicago, Reactor Construction &
Engineering Support Branch 80/12/30 5pp 07470 293

B010200591 Responds to IE Bulletin 80-23 Valcor solenoid valves not
used as planned for use in safety-related functions
CCKA, J. W. Consumers Power Co 81/01/06 1p 07597 310

B010200586 Forwards notice of violation & notice of proposed imposition
of civil penalties re NRC B00306-0731 investigation
STELL, V. Director's Office, Office of Inspection and Enforcement
81/01/07 2pp 07477 290

--B010200590 Notice of violation from investigation on B00306-0731
& Director's Office, Office of Inspection and Enforcement
81/01/07 13pp 07477 292

--B010200595 Notice of proposed imposition of civil penalties in an
amount of \$28,000.00 for item of violation discovered during
investigation on B00306-0731
& Director's Office, Office of Inspection and Enforcement
81/01/07 1p 07477 305

R Periodic operating reports & related correspondence

B01050349 Forwards Rept 32 for Jan-Mar 1981 per Conditions 2F8 & 2
of Licensee CRR-81 & CRR-82 & 730326 Memorandum & Order
ALAB-106
CCKA, J. W. Consumers Power Co 80/12/30 24pp 07375 346.

B010250380 Forwards ALAB-106 monthly rept for Dec 1980, Bechtel
nonconformance repts, quality action requests, ngt corrective
action repts, repts of nonconformity, inservice insp
nonconformance repts & util nonconformance repts, encl.
CCKA, J. W. Consumers Power Co 81/01/23 400pp 07309 001.

S Reportable occurrences, LERs & related correspondence

B01070513 Interim deficiency rept re overstressed condition in hot
cooler supports Mod being evaluated Interim or final rept
will be submitted on or before 810130
CCKA, J. W. Consumers Power Co 80/12/30 2pp 07442 285

B01090594 Interim deficiency rept, originally reported on B00327, re
overstressed condition in shutdown cooler supports Mod intent
will be determined after analysis of actual nozzle loads &
existing supports is completed by AE.
CCKA, J. W. Consumers Power Co 80/12/30 2pp 07442 012.

B01090185 EN-80-050: on or about B0102, notice of violation & notice
of proposed imposition of civil penalties will be issued to
util Action based on 16 infractions re major deficiencies in
QA program for heating contractor
BROCKETT, T. J. THOMPSON, D. Office of Inspection & Enforcement, Office
of the Director 81/01/02 1p 07442 274

B01140653 Interim Deficiency Rept 1 re status of low alloy quencher
& tempered bolting 1.5 inches & greater in support of
safety-related sys Interim or final rept to be provided by
B01031, Description of investigation encl.
CCKA, J. W. Consumers Power Co 81/01/09 16pp 07308 001

B010230381 Interim deficiency rept re defective sway strut rod end
Initially reported on B01031 Solutions are being
investigated & will be coordinated w/all vendors to obtain
generic solution. Next rept will be forwarded by B01027
CCKA, J. W. Consumers Power Co RUTHERFORD, J. A. Bechtel Power Corp
1985, & P. Dechtel Corp 81/01/15 5pp 07511 220

Hearing transcripts on non-entitlement matters

090003 Proposed transcript corrections to DB Head 801229
position Certificate of Svc encl
TOM, W D Hearing Branch 4 80/12/29 6pp 03889 269

300745 Transcript of ASLB 801009 hearing in Flemington, NJ Pp 1-120
Atomic Safety and Licensing Board Penol. 81/01/08 121pp
582 001

E1 50-731 BUALE ARNOLD ENERGY CENTER

security, medical, emergency & fire protection plans

090397 Ltr to all licensees of operating reactor plants, CP holders
CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
0102 & by applicants as part of FSAR
SENHUT, D O Division of Licensing 80/11/13 2pp

140577 Advises that util will receive refund of Class 11f amend Fee
800425 revision to security plan
LLER, W O License Fee Management Branch 80/12/08 1p
460 291

200458 Releases public version of util emergency plan
LTON, J H Division of Rules and Records 81/01/14 1p
484 021

01200466 Forwards public version of emergency plan includes State of
IA emergency plan & Linn & Benton Counties, IA radiation
emergency response plans
RDOT, L D Iowa Electric Light & Power Co 80/12/31 1p
07484 023

01200475 Public version of emergency plan includes State of IA
emergency plan & Linn & Benton Counties, IA radiation
emergency response plans
Iowa Electric Light & Power Co 80/07/31 600pp. 07484 024

Judicatory correspondence

300417 Forwards NRC 801113 order granting extension to exemption
from General Design Criteria 50 & requiring licensee to
reassess containment design for suppression pool
hydrodynamic loading
TOLITO, T A Operating Reactors Branch 2 81/01/13 3pp
07586 255

01300430 Order granting extension to exemption from General Design
Criteria 50 & requiring licensee to reassess containment
design for suppression pool hydrodynamic loading
EISENHUT, D O Division of Licensing 81/01/13 7pp 07506 258

Insurance & indemnity information

070586 Forwards copy of 801111 util ltr & Netl Rural Util
Cooperative Finance Corp 801031 ltr in response to NRC
1219 ltr requesting guarantee of ability to pay
prospective premiums
LLAMB, E H Central Iowa Power Cooperative 80/12/29 1p
410 341

Operating license stage documents & correspondence

100254 Ltr to all licensees (except SEP licensees) forwarding
revision 1 of inservice surveillance requirements for
subbers under DBS License amend application editing model
ch Specs to App A should be submitted within 120 days
SENHUT, D O Division of Licensing 80/11/20 1p

01100271 Revised Pages 3/4 7-22 through 20, B 3/4 7-5 & 7-6 & 6-17 to
DBS snubber inservice insp requirements,
Division of Licensing. 80/11/20 10pp

050399 Intends to respond to NUREG-0737 requirement 11 K 3 30,
vised small break LOCA methods to show compliance
CFR 50 App K, through GE. Requests schedule & scope of
stations be directed to GE.
DT, L D Iowa Electric Light & Power Co 80/11/29 1p.
174 023

220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 retesting re implementation of guidance for
resolved Safety Issue A-12, "Potential for Low Fracture
 toughness & Lemelmer Testing on Component Supports "
SENHUT, D O Division of Licensing. 80/11/26 8pp

8101190113 Ltr to all BWR licensees forwarding 801201 generic safety
evaluation re BWR scum discharge sys. Recommends short-term
actions necessary to assure safe operation of GE BWRs
pending permanent design changes.
EISENHUT, D O Division of Licensing 80/12/09 2pp

--8101190141 Generic safety evaluation re short-term actions required to
assure continued safe operation of operating BWRs Continued
operation of plants is acceptable pending permanent design
modifications for implementing design mod encl
Division of Licensing 80/12/01 212pp. 07103 001

8101210445 Forwards responses to questions on Rule 50 71e, "Periodic
Updating of FSARs" & FR notice of final rule. SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/19 13pp

8101050273 Forwards responses to NRC positions re implementation info
required by NUREG-0737, Support. Infn encl.
RDOT, L D Iowa Electric Light & Power Co 80/12/31 70pp
07377 159

8101300417 Forwards NRC 801113 order granting extension to exemption
from General Design Criteria 50 & requiring licensee to
reassess containment design for suppression pool
hydrodynamic loading
TOLITO, T A Operating Reactors Branch 2 81/01/13 3pp
07586 255

--8101300430 Order granting extension to exemption from General Design
Criteria 50 & requiring licensee to reassess containment
design for suppression pool hydrodynamic loading
EISENHUT, D O Division of Licensing 81/01/13 7pp 07506 258

8101200300 Forwards re-evaluation of BWR scum sys. in response to NRC
801001 ltr.
RDOT, L D Iowa Electric Light & Power Co 81/01/14 4pp
07486 257

8101300849 "Safety Evaluation Rpt. Inservice Testing Program Duene
Arnold Energy Ctr."
ROCKWELL, H C, FERNINGEN, J M. EG&G Idaho, Inc FIN A-6258
8101300849 81/01/31 42pp. 07585 002

0 Inspection reports, IE Bulletins & correspondence

8101050270 Forwards IE Info Notice 80-30, "Cracking in Charging Pump
Casing Cladding " No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30
2pp 07397 193

8101060552 Forwards IE Circular 80-23, "Potential Defects in Refill
Power Sys Emergency Generators " No written response
required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/31
1p 07398 012

8101060658 Forwards IE Info Notice 80-39, "Malfunction of Solenoid
Valves Rfg by Valcor Engineering Corp " No written response
is required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/31
1p 07401 217

8101050545 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Steam Discharge Vut at Dresden Unit 2 " No
response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05
2pp. 07390 312

8101290444 Forwards IE Insp Rept 50-331/80-22 on 801101-20 No
noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support
Branch. 80/12/15 2pp 07570 334

--8101290449 IE Insp Rept 50-331/80-22 on 801101-30 No noncompliance
noted. Major areas inspected plant operations, maint.
procedures & documentation
CHRISTIANSON, W, CLARKE, L S, LITTLE, W S Region 3, Chicago,
Office of the Director. 80/12/12 4pp 07570 336

8101080646 Forwards IE Info Notice 80-45, "Potential Failure of BWR
Backup Manual Scum Capability " No written response
required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17,
2pp 07419 358

R101130631 Responds to IE Bulletin 80-23 re solenoid valves mfg by Valcor Engineering Corp. No valves mfg by vendor used
RQJTL, O. Iowa Electric Light & Power Co 80/12/18 1p
07453 282

B101150211 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR - No Written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/18
2pp 07462 196

B101050199 Forwards IE Bulletin 80-25. Operating Problems w/Target Rock Safety Relief Valves at BWRs - No response required.
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/19
2pp 07377 343

B101220386 Submits response to IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment - Significant closed CHS leakages have not occurred inside drywell.
RQJTL, D Iowa Electric Light & Power Co 81/01/05 8pp
07500 266

R Periodic operating reports & related correspondence

B101200280 Forwards monthly operating rept for Dec 1980
MINECK, D L Iowa Electric Light & Power Co 81/01/14 1p
07477 159.

--B101200284 Monthly operating rept for Dec 1980
VAN BICKEL, J Iowa Electric Light & Power Co 81/01/14 7pp
07477 160

R Reportable occurrences, LERs & related correspondence

B101060621 Forwards LER 80-062/01T-0
MINECK, D L Iowa Electric Light & Power Co 80/12/31 1p
07391 136

--B101060627 LER 80-062/01T-0 on 001217, during testing of suppression chamber level transmitters, personnel lowered level below Tech Specs min. Caused by personnel callibr error. Responsible individual retrained.
RAGER, M S Iowa Electric Light & Power Co 80/12/31 2pp
07391 137

B101120326 Forwards LER 80-063/03L-0
MINECK, D L Iowa Electric Light & Power Co 81/01/06 1p
07447 144

--B101120329 LER 80-063/03L-0 on 801212, solenoid valve in B containment oxygen analyzer failed causing loss of torus sampling.
Caused by faulty solenoid valve coil. Coil replaced & tested successfully.
VAN BICKEL, J O. Iowa Electric Light & Power Co 81/01/06 1p.
07447 145.

B101120334 Forwards LER 80-061/03L-0
MINECK, D L Iowa Electric Light & Power Co. 81/01/06 1p.
07447: 149

--B101120336 LER 80-061/03L-0 on 001207, drywell pressure & torus water level record PR/LR-4284 began giving erratic & unreliable data. Caused by poor ventilation in recorder cabinet resulting in excessive temp & varied power supply output.
RAGER, M S Iowa Electric Light & Power Co 81/01/06 1p.
07447 150

B101220335 Forwards LER 80-066/03L-0.
MINECK, D L Iowa Electric Light & Power Co 81/01/14 1p
07500 123

--B101220343 LER 80-066/03L-0 on 801215, surveillance testing required by Tech Spec 3.5.0.1 when one standby diesel generator is inoperable found not properly completed. Caused by operator error. Operations personnel retrained by meeting & memo.
RAGER, M S Iowa Electric Light & Power Co. 81/01/14 1p.
07500 124.

B101220381 Forwards LER 80-065/03L-0
MINECK, D L Iowa Electric Light & Power Co 81/01/14 1p.
07505 170

--B101220385 LER 80-065/03L-0 on 801216, suppression chamber surge inlet valve CV-1308 would not cycle. Caused by stuck Miller Fluid Power valve operator piston. Operator cleaned, lubricated & reassembled.
RAGER, M S Iowa Electric Light & Power Co 81/01/14 1p.
07505 171

B101220397 Forwards LER 80-064/03L-0
MINECK, D L Iowa Electric Light & Power Co 81/01/14 1p
07494 091.

--B101220401 LER 80-064/03L-0 on 801225, during surveillance testing standby diesel generator 10-21 failed to start using emergency air start sys. Caused by air start solenoid valve not opening properly. Valve filter cleaned & tested.
RAGER, M S Iowa Electric Light & Power Co 01/01/14 1p
07494 092

B101280550 Forwards LER 80-067/03L-0
MINECK, D L Iowa Electric Light & Power Co 81/01/21 1p
07557: 202

--B101280556 LER 80-067/03L-0 on 801226, reactor water cleanup eye condenser control valve CV-2729 found leaking. Caused by hole in body due to high velocity water flow through valve. Valve body was weld repaired & hydrostatically tested.
RAGER, M S Iowa Electric Light & Power Co. 81/01/21 1p
07557: 203

DOCKET 80-332 BARNWELL REPROCESSING PLANT

0 Adjudicatory correspondence

B101090779 Forwards memos re preliminary estimates of resource needs should "GESMO-type" proceeding be reinstituted. Info derived from discussion during 801201 meeting.
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 80/12/03 1p.

--B101090796 Submits estimated resource requirements for completing proceeding. Differences in estimates for original GESMO project & estimates to complete proceeding noted.
CUNNINGHAM, R E. Division of Fuel Cycle & Material Safety 80/09/13 3pp

--B101060606 Advises that GESMO 1976 study & rept should be revised pending congressional mandates to reopen hearings.
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 80/08/08 3pp.

0. Inspection reports, IE Bulletins & correspondence

B101090790 Forwards IE Insp Rept 80-332/80-03 on 801015-17. No noncompliance noted.
RENN, W B Region 2, Atlanta, Safeguards Branch 80/11/18 1p
07439 255

--B101090802 IE Insp Rept 80-332/80-03 on 801015-17. No noncompliance noted. Major areas inspected: internal reviews & audits, safety committees, IE bulletins & independent effort.
CORDYLL, D. P. Region 1, Philadelphia, Office of the Director
VALLE, J B. Region 2, Atlanta, Safeguards Branch. 00/11/18.
07430 256.

B101080189 Ack receipt of IE Insp Rept 80-332/80-03 on 801015-17. No proprietary info.
MOLLEN, R B Allied General Nuclear Services 80/12/10 1p.
07421: 359

DOCKET 80-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

B002050463 Forwards rept. "Evacuation Time Estimates for Areas Near Bites." In response to NRC 791129 request. Upgraded emergency plan will be provided by 800213.
SCHNEIDER, J R. Power Authority of the State of New York. 80/01/1p 01875 111.

--B002050467 "Evacuation Time Estimates for Areas Near Bites."
Persons, Brinkerhoff, Guade & Douglas, Inc. 80/01/31 27pp
01875 112

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D O. Division of Licensing. 80/11/13 2pp.

B101100081 Immediate Action Ltr 80-48, confirming agreements reached 801121 meeting w/Util List. Actions util will take in areas of radiation protection & emergency planning.
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/11/21 2pp 07445: 001

G. Adjudicatory correspondence

8101300753 Forwards NRC 810113 order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required
IPPOLITD.T.A. Operating Reactors Branch 2 81/01/13 3pp
07587-035

--8101300757 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required. Mods must be installed by 81031
EISENHUT.D.O. Division of Licensing 81/01/13 7pp 07587 038

P. Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except BEP licensees) forwarding Summary I of inservice surveillance requirements for snubbers under 818 License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT.D.O. Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-17 to 818 snubber inservice insp requirements.
* Division of Licensing 80/11/20 10pp

0101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT.D.O. Division of Licensing 80/11/26 6pp.

8101190113 Ltr to all BWR licensees forwarding 801201 generic safety evaluation re BWR steam discharge sys. Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes.
EISENHUT.D.O. Division of Licensing 80/12/09 2pp

--8101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs. Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp. 07183.001

8101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FBARs" & FR notice of final rule. BEP plants need not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame.
EISENHUT.D.O. Division of Licensing 80/12/15 13pp.

8101090604 Forwards application for amend to DL & statement of proposed changes to Tech Specs.
BAYNE.J.P. Power Authority of the State of New York 81/01/06 3pp. 07442.111.

--8101090611 Application for amend to License DPR-54, incorporating changes to Tech Specs Safety evaluation supporting proposed Tech Specs encl
BAYNE.J.P. Power Authority of the State of New York 81/01/06 1p. 07442.114

--8101090618 Proposed changes to Tech Specs 2 1-3 2-3 3-3 4-3 6-4 6-3.5 & 4-5 re updating & correcting miscellaneous technical matters.
* Power Authority of the State of New York 81/01/06 7pp
07442.115

--8101090694 Safety evaluation supporting proposed changes to Tech Specs, involving correction & updating of miscellaneous technical matters.
* Power Authority of the State of New York 81/01/06 2pp.
07442.124.

8101120200 Forwards application for amend to License DPR-59, revising App A Tech Specs to correct typographical errors & make editorial improvements & administrative changes. Class II amend fee encl.
BAYNE.J.P. Power Authority of the State of New York 81/01/06 2pp. 07309-001.

--8101120205 Application for amend to License DPR-59, revising App A Tech Specs & to typographical errors & make editorial improvements & administrative changes
BAYNE.J.P. Power Authority of the State of New York 81/01/06 1p. 07309-001

--8101120209 Proposed changes to App A Tech Specs Sections 3 correction of typographical errors & editorial improvements Safety evaluation encl
* Power Authority of the State of New York 81/01/06 07309-001

8101120215 Forwards application for amend to License DPR-59, App A Tech Specs & re steam discharge vol Class II amend fee encl
BAYNE.J.P. Power Authority of the State of New York 81/01/06 2pp 07446.292

--8101120220 Application for amend to License DPR-59, revising Specs re steam discharge vol
BAYNE.J.P. Power Authority of the State of New York 81/01/06 1p 07446.294

--8101120226 Proposed changes to App A Tech Specs Sections 3 discharge vol Provides surveillance requirements for vent drain valves & for reactor protection sys & control rod block SDIV limit switches. Safety evaluation encl
* Power Authority of the State of New York 81/01/06 07446.295

8101130308 Updates Mark I containment program mod schedule M to be completed during Fall 1981 refueling outage due to outstanding load info & attached piping analysis
Installation scheduled for 820601
WILVERDING.D.M. Power Authority of the State of New York 81/01/06 2pp. 07447:276

8101160441 Forwards info re post-TM1 requirements listed in 8101160441
BAYNE.J.P. Power Authority of the State of New York 81/01/06 3pp 07308-001

8101160459 Forwards responses to 800718 ltr re NUREG-0737 11.1 Mode will be delayed until Oct 1981 refueling outage. Addl info to be submitted
BAYNE.J.P. Power Authority of the State of New York 81/01/06 3pp. 07470-001

8101300753 Forwards NRC 010113 order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required
IPPOLITD.T.A. Operating Reactors Branch 2 81/01/13 3pp
07587-035

--8101300757 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required. Mods must be installed by 81031
EISENHUT.D.O. Division of Licensing 81/01/13 7pp

8101260504 Responds to NRC 800924 ltr re plans to upgrade reactor protection sys power supply Design providing for redundant Class IE protection is being developed. Info re design, proposed Tech Specs & Reload 3 will be submitted in 90 days
BAYNE.J.P. Power Authority of the State of New York 81/01/06 07532-062

8101260117 Forwards info clarifying util 800102 response to item 2 1.4, in response to concerns of resident insector re primary containment isolation sys. Nonessential sys automatically isolated upon containment isolation signal.
BAYNE.J.P. Power Authority of the State of New York 81/01/06 19pp 07557-063.

Q. Inspection reports, IE Bulletins & correspondence

8101090878 Forwards IE Insp Rept 50-333/80-18 on 800922-26 Noncompliance noted
HARTIN.W.D. Region 1, Philadelphia, Safeguards Branch 81/01/06 2pp. 03893.248

--8101090903 IE Insp Rept 50-333/80-18 on 800922-26 Noncompliance noted. Major areas inspected: physical security program re contingency security force. Details withheld (ref:OCFR2 7)
BAILLY.R.J., SMITH.M. Region 1, Philadelphia, Office of Director, DEVLIN.J.W. Region 1, Philadelphia, Safeguards Branch 80/10/29 1p 03893.250.

8101300060 Ack receipt of 801028 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/80-17.
CARLSON.R.T. Region 1, Philadelphia, Reactor Construction Engineering Support Branch 80/11/17 1p 07983-033

--B10130074 Responds to NRC B01001 ltr re violations noted in IE Insp Rept 50-333/80-17. Corrective actions, fire doors closed, density tests of sealing mats performed & stop work order issued on electrical penetration sealing work
PASTERNAK, R. J. Power Authority of the State of New York
80/10/23 4pp 07503 036

--B10130080 Forwards IE Insp Rept 50-333/80-17 on B00908-11 & notice of violation
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/01 2pp 07583 040.

--B10130087 Notice of violation from insp on B00900-11
* Region 1, Philadelphia, Office of the Director 80/10/01 2pp 07583 042

--B101300107 IE Insp Rept 50-333/80-17 on B00908-11 Noncompliance noted fire doors open & unattended, failures to inspect penetrations requiring permanent tamping & failure to issue work tracking forms on electrical penetration sealing work
MC TAV, P. S. Region 1, Philadelphia, Office of the Director
EBNETER, S. D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/10/01 7pp 07583 044

B101080129 Forwards omitted pages from U111 B01101 response to IE Bulletin 79-010, "Environ Qualification of Class 1E Equipment"
PASTERNAK, R. J. Power Authority of the State of New York 80/11/21 6pp 07416 352

B101100081 Immediate Action ltr B0-48, confirming agreements reached at B01121 meeting w/ U111 lists actions until take in areas of radiation protection & emergency planning.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/11/21 2pp 07445 001

B101070419 Forwards Suppl 1 to IE Info Notice B0-29, "Broken Studs on Jerry Turbine Steam Inlet Flange" No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/11/25 1p 07414 044

B101050142 Forwards IE Info Notice B0-43, "Failures of Continuous Water Level Monitor for Scram Discharge Vol at Dresden Unit 2" No response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/12/05 1p 07377 233

B101140766 Responds to IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Review of records will be completed by B10105 No valves w/ specified parts identified to date
PASTERNAK, R. J. Power Authority of the State of New York 80/12/10 1p 07497 105

B101080116 Forwards IE Info Notice B0-49, "Potential Failure of BWR Backup Manual Scram Capability." No response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/12/17 1p 07377 323

B101140975 Responds to IE Bulletin B0-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." No valves w/ specified parts in use at facility
PASTERNAK, R. J. Power Authority of the State of New York 80/12/17 1p 07457 106

B101070062 Forwards Suppl 4 to IE Bulletin B0-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR" No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/12/18 1p 07414 152

B101150090 Forwards IE Bulletin B0-25, "Operating Problems w/ Target Rod Safety-Relief Valves at BWRs" Written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/12/19 1p 07449 144.

R. Periodic operating reports & related correspondence

B101130552 Forwards monthly operating rept for Dec 1980.
PASTERNAK, R. J. Power Authority of the State of New York 81/01/07 1p 07454 158

--B101130558 Monthly operating rept for Dec 1980.
ZUFELT, E. Power Authority of the State of New York 81/01/07 4pp 07454 159

S. Reportable occurrences, IERs & related correspondence

B101120302 Forwards LER B0-093/03L-0
PASTERNAK, R. J. Power Authority of the State of New York 81/01/09 1p 07447 130

--B101120354 LER B0-093/03L-0 on B01212, reactor water level switch 02-3-DP18-101D exhibited erratic setpoint. Caused by stripped setpoint lock screw. Lock screw replaced & switch recalibr
CHILDS, W. V. Power Authority of the State of New York 81/01/07 1p 07447 131

B101120596 Forwards LER B0-092/03L-0
PASTERNAK, R. J. Power Authority of the State of New York 81/01/09 1p 07447 120

--B101120310 LER B0-092/03L-0 on B01210, heat detector associated w/ protection sys for reactor core isolation failed when required to be operable by Tech Spec. Caused by internal short. Detector replaced
CHILDS, W. V. Power Authority of the State of New York 81/01/09 1p 07447 121

B101140507 Forwards LER B0-066/03X-2
PASTERNAK, R. J. Power Authority of the State of New York 81/01/12 1p 07471 271.

--B101140564 LER B0-066/03X-2 on B00805, core spray sys pipe break detection switches 14-DP18-42A & 43D found set above Tech Spec level. Caused by instrument drift. Instrument calibr & returned to svc.
CHILDS, W. V. Power Authority of the State of New York 81/01/12 1p 07471 272

B101210492 Forwards LER B0-094/03L-0.
PASTERNAK, R. J. Power Authority of the State of New York 81/01/19 1p 07490 173

--B101210496 LER B0-094/03L-0 on B01216, water level switch 02-3-LIR-56 found set outside Tech Specs. Caused by instrument drift. Instrument recalibr
CHILDS, W. V. Power Authority of the State of New York 81/01/19 1p 07490 174

B101210499 Forwards LER B0-095/03L-0
PASTERNAK, R. J. Power Authority of the State of New York 81/01/19 1p 07490 175

--B101210506 LER B0-095/03L-0 on B01217, reactor core isolation cooling sys high steam flow switch 13-DP18-B4 found set outside Tech Specs. Caused by instrument drift. Switch recalibr
Power Authority of the State of New York 81/01/19 1p 07490 176

B101200136 Re B1-001 on B10117, foreign netl was found in SAV solenoid (spilot) valve 102-B0V-7101. Caused by excess adhesive & O-ring lubricant used by vendor during assembly. Insp of remaining nine solenoid valve pairs is in progress.
PASTERNAK, R. Power Authority of the State of New York 81/01/21 1p 07187 001.

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

B101090587 Ltr to all licensees of operating reactor plants. CP holders & CP Applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHART, D. O. Division of Licensing 80/11/13 2pp.

B101140836 Advise of provisions of 10CFR50, App R, that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open items encl. W/o encl.
EISENHART, D. O. Division of Licensing 80/11/24 3pp. 07461 032

B101190361 Notifies that until 781211 commitment to install addl hoses at host station is acceptable for setting concerns re item 3 C-7 of safety evaluation for Amend 1B to OL
VAROAS, S. A. Operating Reactors Branch 1. 80/12/23 2pp. 07476 077

B101160719 Requests that encl facility emergency planning info be made publicly available w/o encl.
SOUDEK, J. L. Division of Rules and Records 80/12/31 1p 07445 125

--801100622 Revised order amending License OPR-66 Info requested by IE Bulletin 79-010 must be submitted to IE by 801101
EISENHUT, O O Division of Licensing 80/07/19 6pp 07443 139

P Operating license stage documents & correspondence

801100617 Forwards revised order for mod of license, correcting refs in EC0829 order Hearing date also revised.
EISENHUT, O O Division of Licensing 80/09/19 3pp 07443 136

--801100622 Revised order amending License OPR-66 Info requested by IE Bulletin 79-010 must be submitted to IE by 801101.
EISENHUT, O O Division of Licensing 80/07/19 6pp 07443 139.

801100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under BTS License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing 80/11/20 1p

--801100271 Revised Pages 7/4 7-22 through 20.0 3/4 7-5 & 7-6 & A-17 to BTS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

8011220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar tearing on Component Supports."
EISENHUT, O O Division of Licensing 80/11/26 8pp

801160046 Confirms 801217 mgt meeting to discuss NRC assessment of regulatory performance at facility Agenda encl.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/10 2pp 07467 305.

801210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp

801090321 Forwards nonproprietary & proprietary versions of "Response to NUREG-0737 " Proprietary version available in Central Files only.
DUNN, C H Duquesne Light Co 80/12/31 2pp 07377 001

--801090327 Requests that proprietary info submitted as responses to NUREG-0737 re instrumentation for inadequate core cooling be withheld from public disclosure (ref 10CFR2 790) Affidavit encl.
NIEGEMANN, R A Westinghouse Electric Corp 80/12/23 7pp 07377:003.

--801090330 "Response to NUREG-0537 "
* Duquesne Light Co 80/12/30 200pp 07377:010

801300829 "Adequacy of Station Electric Distribution Sys Voltages. Beaver Valley Power Station, Unit 1." Informal rept
UDY, A C, EG&O Idaho, Inc FIN A-6256. 801300829 80/12/31 15pp 07584:079

801300731 Forwards corrections to revised Tech Specs transmitted per Amend 36 to facility BL OPR-66
VARQA, B A Operating Reactors Branch I. 81/01/06 2pp 07583 333

--801300738 Tech Spec 3/4 0 for inservice insp & testing activities surveillance requirements.
* Duquesne Light Co 81/01/06 1p 07583 335

801220571 Submits results of tests performed re util program to reduce leakage from sys outside containment that may contain highly radioactive fluids during transient or accident; per NUREG-0737, Item III O. I. 1 & NUREG-0378
DUNN, C Duquesne Light Co 81/01/15 2pp 07503 153

Q. Inspection reports, IE Bulletins & correspondence

801500059 Forwards IE Insp Rept 50-334/80-26 on 800810-22 No noncompliance noted.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/03 2pp 07583 207.

801080126 Submits supplemental response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " NAMCO 700 limit switches will be used inside containment temporarily, until qualified replacements are obtained
DUNN, C H Duquesne Light Co 80/11/21 5pp 07416 347

801050E88 Forwards Suppl 1 to IE Info Notice 80-29. "Broken Studs on Terry Turbine Steam Inlet Flange " No written response requested
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07396 345

801100781 Response to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co, Inc " Research effort initiated to contact valve suppliers. Extension requested until 801230 to provide info
DUNN, C H Duquesne Light Co 80/12/07 2pp 07444 039

801150933 Forwards supplemental response to IE Bulletin 79-010. "Environ Qualification of Class IE Equipment." Identifying procedures to provide addl guidance for coping w/environmentally unqualified electrical equipment
DUNN, C H Duquesne Light Co 80/12/12 14pp 07464 165

801100786 Response to IE Bulletin 80-23. "Failures of Solenoid Valve Mfg by Valcor Engineering Corp." No Valcor solenoid valves in use at facility
DUNN, C H Duquesne Light Co 80/12/15 1p 07444 041

801050877 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Unit Shutdown " No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/16 1p 07396:334

801230356 Summary of 801202 meeting w/util re deficiencies in licensee response to IE Bulletin 79-01 Agenda encl
RHEB, W J Operating Reactors Branch I 80/12/30 4pp 07512: 113.

801090548 Response to IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event) " Recirculation spray subsystem capable of keeping containment at subatmospheric pressure following accident.
DUNN, C H Duquesne Light Co 81/01/03 8pp 07442:097

R Periodic operating reports & related correspondence

801070426 Forwards NPDES monthly discharge monitoring rept for Nov 1980
HADDRE, G H Duquesne Light Co. 80/12/30 1p 07404 324

--801070439 Discharge NPDES monthly monitoring rept for Nov 1980
* Duquesne Light Co 80/11/30 12pp 07404 325

801160464 Forwards revised operating data rept sheets for Oct & Nov 1980 & monthly operating rept for Dec 1980.
DUNN, C H Duquesne Light Co. 81/01/06 1p 07471 225

--801160467 Revised operating data rept sheet for Oct 1980
TIMMO, D R Duquesne Light Co. 81/01/06 1p 07471 226.

--801160468 Revised operating data rept sheet for Nov 1980
TIMMO, D R Duquesne Light Co. 81/01/06 1p 07471 227

--801160470 Monthly operating rept for Dec 1980
TIMMO, D R Duquesne Light Co. 81/01/06 6pp 07471 228

S Reportable occurrences, LERs & related correspondence

801070524 Forwards LER 80-102/031-0.
MERLINO, J A Duquesne Light Co 80/12/26 2pp 07415 115

--801070531 LER 80-102/031-0 on 801129, all three chlorine detectors noted not dripping Caused by fluid leak being under slight vacuum & clogged wick. Vent & wick cleaned Engineering requested to evaluate.
LACEY, N R Duquesne Light Co 80/12/26 2pp 07415 117

801150421 Forwards LERs 80-104/03L-0, 80-106/03L-0, 80-107/03L-0, 80-108/03L-0 & 80-107/03L-0
MERLINO, J A Duquesne Light Co. 81/01/09 2pp 07434 050

--B101130425 LER 80-104/03L-0 on B01204.F-476 feed flow protection channel for IA steam generator failed surveillance test caused by bad circuit board allowing loop voltage drift on steam flow input circuit pulse adjusted
LACEY, W S Duquesne Light Co 81/01/05 2pp 07454 060

--B101130428 LER 80-104/03L-0 on B01204 inner door of containment air lock failed surveillance leakage test per Tech Spec Cause not stated O-rings greased & valves tightened
LACEY, W S Duquesne Light Co 81/01/05 2pp 07454 062

- B101130432 LER 80-107/03L-0 on B01206 electrolyte for detectors 101A & 101B found not dripping caused by clogged wick & glass orifice wick & orifice cleaned & top vent filter loosened
LACEY, W S Duquesne Light Co 81/01/05 2pp 07454 064

--B101130439 LER 80-108/03L-0 during maint surveillance procedure for calibr of hydrogen analyzer H2-HV-1003 failed function circuit card found caused by electronic circuit card failure function card replaced
LACEY, W S Duquesne Light Co 81/01/05 2pp 07454 065

--B101130443 LER 80-107/03L-0 on B01205.a1a1 flux difference increased above target band caused by high initial second fuel cycle 100% target flux value Target flux value lowered
LACEY, W S Duquesne Light Co 81/01/05 2pp 07454 068

B101130508 Forwards LER 80-105/03L-0
MERLING, J A Duquesne Light Co 81/01/05 2pp 07454 124

--B101130515 LER 80-105/03L-0 on B01205 thermocouple readings indicated temps below Tech Spec level around boron injection tank outlet isolation valves caused by thermocouples not in full contact w/pipes Heat tracing sys study is being conducted
LACEY, W S Duquesne Light Co 81/01/05 2pp 07454 126

B101130531 LER 81-001/01P-0 on B10106.IE Bulletin 79-14 evaluation & analysis of piping & supports revealed H-162,H-164 & H-165 to be less conservative than original design caused by DA breakdown
MERLING, J A Duquesne Light Co 81/01/07 3pp 07309 001

B101190467 Forwards LER 80-111/03L-0
MERLING, J A Duquesne Light Co 81/01/09 2pp 07474 060

--B101190470 LER 80-111/03L-0 on B01211 steam generator feed pump suction pressure low alarm was received caused by control rod insertion rods partially banded out of core restoring delta flux to within target band
LACEY, W S Duquesne Light Co 81/01/09 2pp 07474 062

B101190474 Forwards LER 80-112/03L-0
MERLING, J A Duquesne Light Co 81/01/12 2pp 07474 064

--B101190477 LER 80-112/03L-0 on B01213 sample pump for containment atmospheric gaseous & particulate radiation monitors failed Cause not stated Sample pump motor & drive pulley replaced
LACEY, W S Duquesne Light Co 81/01/12 2pp 07474 066

B101200382 Forwards LERs 80-113/03L-0, 80-114/03L-0 & 80-118/03L-0
MERLING, J A Duquesne Light Co 81/01/14 2pp 07500 243

--B101200384 LER 80-113/03L-0 on B01214 during surveillance testing several penetration fire barriers found lacking seals Cause not stated Fire watch posted & openings sealed
LACEY, W S Duquesne Light Co 81/01/15 2pp 07500 245

--B101200387 LER 80-114/03L-0 on B01215 during shift channel check of refueling water storage tank channel C level indicator found reading high caused by transmitter zero drift Transmitter recalibr & returned to svc
LACEY, W S Duquesne Light Co 81/01/14 2pp 07500 247

--B101200392 LER 80-118/03L-0 on B01217 during chlorine detection sys surveillance test 101A, B & C detectors electrolyte found not dripping caused by vacuum in fluid tanks & clogged glass orifices wicks replaced & orifices cleaned
LACEY, W S Duquesne Light Co 81/01/14 2pp 07500 249

B101230465 Forwards LERs 80-116/03L-0 & 80-117/03L-0
MERLING, J A Duquesne Light Co 81/01/15 2pp 07513 025

--B101230471 LER 80-116/03L-0 on B01217 degassifier A recovery heat exchanger BR-E-12A2 steam leak found to be cracked weld Cause unknown Exchanger isolated & drained Weld grounded out & temporary mod to seal weld performed
LACEY, W S Duquesne Light Co 81/01/15 2pp 07513 027

--B101230473 LER 80-117/03L-0 on B01218 during physics testing delta flux left low side of target band when power decreased rapidly caused by rapid insertion of control rods during power decrease Rods partially banded out of core
LACEY, W S Duquesne Light Co 81/01/15 2pp 07513 029

B101230475 Forwards LER 80-120/03L-0
MERLING, J A Duquesne Light Co 81/01/17 2pp 07513 031

--B101230478 LER 80-120/03L-0 on B01218 during hot standby containment air lock outer door failed seal leakage surveillance test Cause unstated Seals inspected, cleaned & greased
LACEY, W S Duquesne Light Co 81/01/19 2pp 07513 033

B101260548 Forwards LER 81-001/01T-0
MERLING, J A Duquesne Light Co 81/01/20 2pp 07531 142

--B101260634 LER 81-001/01T-0 on B10106 supports H-162,H-164 & H-166 reported not modified per IE Bulletin 79-14, caused by loss of pertinent drawings Work on supports completed
LACEY, W S Duquesne Light Co 81/01/20 3pp 07531 144

B101270550 Forwards LER 81-002/01T-0
MERLING, J A Duquesne Light Co 81/01/21 2pp 07548 334

--B101270593 LER 81-002/01T-0 on B10107 during shutdown, cool flow dropped below min on IC reactor coolant pump caused by sensitive valving Pump restarted within 20 minutes
LACEY, W S Duquesne Light Co 81/01/21 2pp 07548 336

BUCKET 90-335 GF LUCIE PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FEAR.
EISENHUT, D O Division of Licensing 80/11/13 2pp.

B101130134 Advice of provisions of 10CFR50, App B, that are applicable to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl
EISENHUT, D O Division of Licensing 80/11/24 9pp. 07308 001

B101280133 Releases public version of util draft emergency plan.
FELTON, J M Division of Rules and Records 80/12/01 1p. 07419 113

--B101080137 Forwards public version of draft emergency plan
WHRID, R E Florida Power & Light Co 80/07/23 1p. 07419 114

--B101080142 Public version of draft emergency plan
* Florida Power & Light Co 80/07/15 129pp 07419 115

B101190377 Requests response to encl comments from NRC review of util security plan Encl withheld (ref 10CFR2 7901
CLARK, R A Operating Reactors Branch 3 80/12/12 2pp. 07474 280

B101100404 Forwards request for addl info re util 800723 emergency plan Areas re assignment of responsibility, onsite emergency organization & emergency response support & resources must be clarified per NUREG-0654 criteria.
CLARK, R A Operating Reactors Branch 3 80/12/18 10pp. 07445 068

B101050402 Disagree w/items contained in Encl 2 to NRC B01124 ltr re requirements to resolve open items concerning fire protection Response to items will be submitted B10130
WHRID, R E Florida Power & Light Co 80/12/30 1p. 07375 340

B101210055 Releases public version of util revised emergency plan
FELTON, J M Division of Rules and Records 81/01/08 1p 07490 225

--B101210092 Forwards public version of revised emergency plan, State of FL draft radiological emergency plan encl
WHRID, R E Florida Power & Light Co 81/01/02 1p. 07490 226

--B101210098 Public version of revised emergency plan, State of FL draft radiological emergency plan encl.
* Florida Power & Light Co 81/01/02 200pp. 07490 227

DOCKETED ITEMS

8101300099 Forwards facility emergency planning info for placement in LPOR W/o 8101080137
SOUOER, J L Division of Rules and Records 81/01/19 1p
07593:079

Q Adjudicatory correspondence

8101160167 Response to Met Ed 801223 ten interrogatories on reactor vessel water level
CUICHEN, J M Hearing Branch 3 81/01/14 7pp 07470 006

--8101160175 "Rept on Saint Lucie 1 Natural Circulation Cooldown on 800611" Certificate of Ovc encl
IMBRO, E V. Director's Office. 81/01/14 20pp 07470:013

J Insurance & Indemnity Information

8101090457 Forwards Endorsement 4 to NELIA Binder EG-59.
FIELOER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/30 2pp 07430 040

8101090464 Forwards Endorsement 30 to NELIA Policy NF-227
FIELOER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/30. 3pp 07442 032

8101090556 Forwards Endorsement 37 to ANI Policy NF-227.
FIELOER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/30. 2pp 07427:343

P Operating license stage documents & correspondence

8101180254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under STB License amend application adding modal
Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 20, B 3/4 7-5 & 7-6 & 6-17 to
STB snubber inservice insp requirements
* Division of Licensing. 80/11/20 10pp.

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O. Division of Licensing. 80/11/26 8pp

8101210445 Forwards responses to questions on Rule 50.71e, "Periodic
Updating of FBARS" & FR notice of final rule. SEP plants need
not comply w/rule until program is complete. Non-SEP plants
must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15. 13pp.

8101100490 Forwards request for addl info re adequacy of station
electric distribution sys voltages to complete review of
util 800912 submittal Class 1E load terminal voltages are
required.
CLARK, R A Operating Reactors Branch 3 80/12/16. App. 07445:080

8101060288 Forwards "Analysis of Natural Circulation Cooldown W/o Upper
Head Voiding for St Lucie Unit 1," in response to NRC 801017
request for info re 800611 natural circulation cooldown
event.
UMRIO, R E. Florida Power & Light Co. 80/12/30. 2pp 07399:055

--8101060292 "Analysis of Natural Circulation Cooldown W/o Upper Head
Voiding for St Lucie Unit 1"
* Florida Power & Light Co 80/12/31 11pp 07399:057

8101190623 Forwards FR notice of proposed issuance of OL amend.
CLARK, R A Operating Reactors Branch 3 80/12/30. 2pp 07475:029.

--8101190626 Notice of proposed issuance of OL amend, upgrading rated
power from 2,560 MWt to 2,700 MWt.
CLARK, R A Operating Reactors Branch 3. 80/12/30 5pp
07475:032.

8101060374 Forwards repts on NUREG-0737 items in response to NRC 801031

8101270694 Application for amend to License DPR-67 revising T
to reflect new UMS flow barrier configuration
UMRIO, R E Florida Power & Light Co 81/01/08 1p 0754

--8101270700 Tech Spec 3/4 7 5 for ultimate heat sink Safety
encl
* Florida Power & Light Co 01/01/08 7pp 07548 085

8101120207 Advises of receipt of INPO/IRAC rept. "Analysis L
of St Lucie Unit 1 Natural Circulation Cooldown." dtd Dec
1980 Rept will be evaluated & forwarded w/comments by
810206
UMRIO, R E Florida Power & Light Co 01/01/09 1p 0744

8101210140 Advises that 800620 application for amend to licen
involves consideration of administrative issue Class 11 fee
is required
81005, R M License Fee Management Branch 81/01/09 1p
07491 392

8101285078 Submits fee per 800620 amend request re definition
operability in response to 810109 ltr
UMRIO, R E. Florida Power & Light Co 81/01/21 1p 0755

--8101280002 Ack receipt of ltr w/checks to be processed by L
Hgt Branch
81005, R M License Fee Management Branch 81/01/27 1p
07557:088

O Inspection reports, IE Bulletins & correspondence

8012160019 Forwards 1E Info Notice 80-37, "Containment Cooler
Reactor Cavity Flooding At Indian Point Unit 2." No written
response required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director M
1p 07261 179

8101140608 Requests extension until 810130 to respond to 1E B
80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc."
Addl time needed to contact all suppliers.
UMRIO, R E Florida Power & Light Co 80/12/11. 2pp 074

8101290357 Forwards 1E Insp Rept 50-335/80-35 on 800920-1107
noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear S
Branch 80/12/19 2pp 07575 116

--8101290361 1E Insp Rept 50-335/80-35 on 800920-1107 No nonc
noted. Major areas inspected compliance w/IE bulletins &
circulars. action on NUREG-0578/0660 & 801021 reactor trip
ETROD, S A Region 2, Atlanta, Office of the Director M
Region 2, Atlanta, Reactor Operations Nuclear Support Or
80/12/19 9pp 07575:118.

8101100695 Ack receipt of 801215 ltr informing NRC of steps to
correct violations noted in 1E Insp Rept 50-335/80-32
KENNA, W B Region 2, Atlanta, Safeguards Branch. 80/12/24
07443:181

--8101100702 Responds to NRC 801119 ltr re violations noted in
Rept 50-335/80-32. Corrective actions withheld (ref
10CFR2 790).
UMRIO, R E Florida Power & Light Co 80/12/15 1p 07

--8101100707 Forwards 1E Insp Rept 50-335/80-32 on 801014-17
violation Notice of violation withheld (ref 10CFR2 790)
KENNA, W B Region 2, Atlanta, Safeguards Branch 80/11/
07443 183

--8101100711 1E Insp Rept 50-335/80-32 on 801014-17 Noncompl
failure to maintain isolation cone clear of vegetation.
Details withheld (ref 10CFR2 790)
TILLMAHL, A Region 2, Atlanta, Office of the Director.
MCQUIRE, O R. Region 2, Atlanta, Safeguards Branch 80/1/
2pp. 07443:185.

8101210162 Responds to 1E Bulletin 80-24 re water damage insl
containment Three minor leakage incidents have occurred.
Leaking valves repaired & reset during subsequent refueling
outages
UMRIO, R E. Florida Power & Light Co 81/01/06 2pp 074

8101210445 Forwards monthly operating reports for Dec 1980
SCHEDULE A D Florida Power & Light Co 81/01/10 1p 07493 126

-8101210429 Monthly operating reports for Dec 1980
SCHEDULE A D Florida Power & Light Co 81/01/10 9pp
07493 127

F. Reportable occurrences, IERs & related correspondence

8101250310 Forwards IER 80-0547/011-0
SCHEDULE A D Florida Power & Light Co 80/11/20 1p 07379 301

--8101050349 IER 80-0147/011-0 on 801030 during normal operation, turbine
control sys malfunction caused unexpected load decrease
resulting in reactor cold leg temp briefly exceeding Tech
Spec limit for cause determined feedback re-established
PACE, P L Florida Power & Light Co 80/11/28 1p 07379 302

8101050344 Forwards IER 80-0532/011-0
SCHEDULE A D Florida Power & Light Co 80/12/05 1p 07390 135

--8101050344 IER 80-0532/011-0 on 801107, drifting pressure indication for
C pressurizer pressure channel was noted & channel bypassed
caused by faulty pressure signal transmitter on pressure
sensing instrument transmitter replaced & channel recalibr
PACE, P L Florida Power & Light Co 80/12/05 1p 07390 136

8101100341 Forwards IER 80-0577/011-0
SCHEDULE A D Florida Power & Light Co 80/12/15 1p 07451 350

--8101100355 IER 80-0677/011-0 on 801123, some reactor trip breakers found
not to trip on under voltage caused by inoperable
under voltage device in breaker device armature realigned
PACE, P L Florida Power & Light Co 80/12/15 1p 07451 361

8101100345 Forwards IER 80-0557/011-0
SCHEDULE A D Florida Power & Light Co 80/12/19 1p 07452 064

--8101100372 IER 80-0657/011-0 on 801121, containment fire protection zone
14A went into invalid alarm state caused by one detector
shorting out due to condensation detector removed
PACE, P L Florida Power & Light Co 80/12/19 1p 07452 065

V. Operator Examinations

8101060374 Forwards report on NUREG-0737 items in response to NRC 801031
Ltr includes info re shift technical advisor, auxiliary
feedwater sys evaluation & auxiliary feedwater sys
initiation & flow
WARRIOR E Florida Power & Light Co 81/01/02 28pp 07393 215

8101100333 Forwards 800801 revision to facility Administrative
Procedure 0005720, licensed operator requalification program
Requirement re instructor qualifications unattainable
Instruction to be supervised by licensed personnel
WARRIOR E Florida Power & Light Co 81/01/06 1p 07368 001

--8101100339 "Licensed Operator Requalification Program," Revision 8,
Administrative Procedure 0005720
* Florida Power & Light Co 80/08/21 16pp 07309 001

BECKE1 50-335 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

810120405 Releases public version of emergency plan
FELTON, J H Division of Rules and Records 80/11/19 1p
07437 011

- 8101100417 Forwards public version of draft Revision 7 to emergency
plan
COUNSEL, W G & FEE, W F Northeast Nuclear Energy Co (subs of
Northeast Utilities) 80/10/14 3pp 07437 013

8101090389 Discusses utility commitments re emergency phone Revised
emergency plans addressing Revision 1 to NUREG-0654/FEMA-
REF-1, App E to 10CFR50, will be submitted by 810216
COUNSEL, W G Connecticut Yankee Atomic Power Co COUNSEL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
80/12/31 4pp 07442 247

8101100734 Requests that each facility emergency planning info be made
publicly available w/o encl
SOLTER, J L Division of Rules and Records 81/01/23 1p
07443 128

8101270712 Responds to NRC 801124 ltr re fire protection features
Protection equivalent to NRC seismic criteria provided by
backfitting of seismic qualification of reactor coolant
pump lubrication oil sys
COUNSEL, W G Connecticut Yankee Atomic Power Co COUNSEL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
81/01/13 4pp 07545 269

8101290163 Forwards facility emergency planning info to be made
publicly available w/o encl
SOLTER, J L Division of Rules and Records 81/01/23 1p
07575 199

J. Insurance & Indemnity Information

8101270736 Forwards Endorsement 4 to NELA 010nders EU-15 & EU-16
IFFLAND, R R Northeast Utilities 81/01/22 3pp 07348 035

8101270744 Forwards Endorsements 45 & 66 to NELA Policy NF-173
IFFLAND, R R Northeast Utilities 81/01/22 4pp 07348 046

P. Operating Licensee stage documents & correspondence

8101100254 Ltr to all licensees (except BEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under BEP license amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 20, B 3/4 7-5 & 7-6 & 6-17 to
BEP snubber inservice insp requirements.
* Division of Licensing 81/01/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing 80/11/26 0pp

8101210445 Forwards responses to questions on Rule 30.710, "Periodic
Updating of FSARs" & FR notice of final rule. BEP plants need
not comply w/rule until program is complete. Non-BEP plants
must comply within specified time frame.
EISENHUT, D O Division of Licensing 80/12/19 13pp

8101160029 Notification of 801218 meeting w/BEP owners group in
Orthesda, MD re BEP program, schedule for licensee topic
completion & assignment of lead topics to plants
RUSSELL, W T Technical Support Branch 80/12/16 2pp

8101050468 Forwards facility electric distribution sys voltage info per
TM Hovak 800625 request
COUNSEL, W G Northeast Utilities 80/12/19 1p 07309 163

--8101050476 "Millstone Nuclear Power Station 2 Electric Distribution Sys
Voltages"
* Northeast Utilities 80/12/31 21pp 07388 164

8101050746 Submits daily notes for 801223 Status of facilities in five
IE regions encl
O'ACKS, W J Office of the Executive Director for Operations
80/12/24 3pp

8101050076 Provides refs to FSAR to assist NRC in obtaining info to
support containment sump evaluation program in response to
801106 request Also submits info re insulation utilized
within containment
COUNSEL, W G Northeast Nuclear Energy Co (subs of Northeast
Utilities) 80/12/29 3pp 07376 290

B101160248 Forwards rept on post-TMI requirements in response to NUREG-0737 & NRC 801031 ltr
COUNCIL, W. O. Connecticut Yankee Atomic Power Co. COUNCIL, W. O.
Northeast Nuclear Energy Co. (subs. of Northeast Utilities)
80/12/31 300pp 07468 014

B101150624 Submits info re justification of measurement uncertainty values for a) air, b) steam, c) pressure, temp, flow & power, in response to NRC 801006 request
COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 81/01/08 2pp 07462 116

B101290799 Forwards Amend 63 to License DPR-65, safety evaluation & notice of issuance & availability
CLARK, T. M. Assistant Director for Operating Reactors. 81/01/14 4pp 07568 075

--B101290802 Amend 63 to License DPR-65, adding operability, trip setpoint & surveillance requirements for automatic initiation of auxiliary feedwater sys
CLARK, R. A. Operating Reactors Branch 3 81/01/14. 21pp 07568 081.

--B101290804 Safety evaluation supporting Amend 63 to License DPR-65
* Office of Nuclear Reactor Regulation, Director 81/01/14 14pp. 07568 103

--B101290807 Notice of issuance & availability of Amend 63 to License DPR-65
CLARK, R. A. Operating Reactors Branch 3 81/01/14 2pp 07568 117

B101200293 Requests review of util basic safety rept so that potential for 10CFR50.59 reload for Cycle 5 can be realized at facility Request originally made on 800706, NRC 801006 response did not accept rept as ref document
COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/16 2pp 07486 238

0 Inspection reports, IE Bulletins & correspondence

B101050124 Requests existing data, summaries & records of inservice insp tests of containments w/greased prestressing tendons.
ORNL receiving contract to compile & review records of tendons
EISENHUT, O. O. Division of Licensing. 80/11/29. 3pp

B101070425 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required.
GRIFER, B. H. Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 035.

B101140718 Updates 800716 response to IE Bulletin 79-02 & 79-14 re as-built safety-related piping sys & pipe supports using concrete expansion anchor bolts, respectively No sys found to have loss of function as result of as-built deviations.
COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/12/02 2pp 07457 107

B101150028 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." No valves w/specifed part numbers in use at facilities
COUNCIL, W. O. Connecticut Yankee Atomic Power Co. COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/03 1p. 07462 205

B101100789 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." No sub j valves in use at facilities
COUNCIL, W. O. Connecticut Yankee Atomic Power Co. COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/12/05 1p 07444 042

B101060836 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown" No written response required
GRIFER, B. H. Region 1, Philadelphia, Office of the Director. 80/12/16. 1p. 07397 025

B101150936 Act receipt of 801016 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/80-11 & 50-336/80-07. Item E now considered as single item of noncompliance.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/12/16 1p. 07464 180.

--B101150540 Responds to NRC 800922 ltr re violations noted in IE Repts 50-245/80-11 & 50-336/80-09 Corrective actions advised personnel that partial sys lineups will be conducted following maint where appropriate
COUNCIL, W. O. , FEE, W. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/10/16 4pp 07464 181

--B101150542 Forwards IE Insp Repts 50-245/80-11 & 50-336/80-09 800706-0802 & notice of violation
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/22 2pp 07464 185

--B101150544 Notice of violation from insp on 800706-0802
* Region 1, Philadelphia, Office of the Director 80/09/16 07463 187

--B101150545 IE Insp Repts 50-245/80-11 & 50-336/80-09 on 800706-0802 Noncompliance noted failure to require restoration of equipment following maint & failure to require radiation work permit in accordance w/procedures
BRUNNER, E. J. , ZIMMERMAN, W. P. Region 1, Philadelphia, Office of the Director 80/09/16 10pp 07464 189

B101290776 Summary of 801216 meeting w/util re facility steam gen insp results. List of attendees & vignographs encl
CLARK, R. A. Operating Reactors Branch 3 81/01/08 42pp 07569 276

8 Periodic operating reports & related correspondence

B101230413 Forwards monthly operating rept for Dec 1980
MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/15. 1p 07512 134

- B101230413 Monthly operating rept for Dec 1980
MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/12. 5pp 07512 125

8 Reportable occurrences, LERs & related correspondence

B101050557 PNO-1-80-178 on 801222, Chen nuclear tractor trailer c low level radioactive from util was involved in traffic accident near Bordentown, NJ low visible damage to cask detected Shipmont proceeded to Bernville, GC
CAMPBELL, H. KINNEHAN, J. Region 1, Philadelphia, Office of the Director 80/12/23 2pp 07379 038

B101120351 Forwards LER 80-040/031-0
MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/12/31 1p 07447 167

--B101120355 LER 80-040/031-0 on 801206, control element assembly dropped to zero steps from 180 steps Cause not stated Power reduced & CEA realigned
REBEAR, J. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/31 1p 07447 168

B101270707 PNO-1-81-001 on 810102, power lost to one AC shutdown when turbine generator tripped after inadvertent opening of 125 volt DC breaker Caused by loss of spray flow from one loop when associated reactor coolant pump was secured
MCCANN, J. F. Director's Office, Office of Inspection and Enforcement 81/01/02 2pp 07550 112

B101160517 Forwards LER 80-041/031-0
MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/08 1p 07471 293

--B101160624 LER 80-041/031-0 on 801210, HPSI injection MVV 2-91 overtravelled 0.25 inch Cause unknown Valve stroked five times & traveled to correct position each time
BECKER, J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/08 1p 07471 294

B101280426 PNO-1-81-02 on 810107, during startup for restart, event occurred which resulted in introduction of reactor coolant into nitrogen gas supply sys Caused by two open valves in nitrogen supply line to RCS Valves left open during maint
MROCKA, E. J. , BRUNNER, E. J. Region 1, Philadelphia, Office of the Director 81/01/09 2pp. 07557 053

B101210592 RO on 801209, inservice insp revealed that required operability tests not performed during third calendar quarter 1980. Valves successfully tested Action taken to ensure timely review of valve test data
MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/13 2pp 07489 266

CLCPET 50-538 NORTH ANNA POWER STATION, UNIT 1

F. Security, residual, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101070434 Releases public version of util emergency plan
FELTON, J H Division of Rules and Records 80/12/02 1p
07415 346

--8101070440 Forwards public version of Revision 2 to emergency plan.
List of changes encl
BAUM, E A Virginia Electric & Power Co 80/06/20 2pp
07415 347

--8101070443 Public version of Revision 2 to emergency plan
* Virginia Electric & Power Co 80/06/18 28pp 07415 749

8101070452 Releases public version of util emergency plan
FELTON, J H Division of Rules and Records 80/12/02 1p
07416 014

--8101070454 Forwards public version of Revision 3 to emergency plan
BAUM, E A Virginia Electric & Power Co 80/06/25 1p 07416 015

--8101070457 Public version of Revision 3 to emergency plan
* Virginia Electric & Power Co 00/06/25 22pp 07416 016

8101120459 Releases public version of util emergency plan
FELTON, J H Division of Rules and Records 80/12/02 1p
07417 204

--8101120490 Forwards public version of Revision 1 to util emergency
plan State of VA 800920 confirmation ltr & list of
changes encl
BAUM, E A Virginia Electric & Power Co 80/06/06 5pp
07417 205

--8101120495 Public version of Revision 1 to util emergency plan
* Virginia Electric & Power Co 80/06/09 106pp, 07417 210.

8101060615 Requests that encl emergency planning info be made
publicly available. W/o encl
SJOGER, J L Division of Rules and Records 80/12/17 1p
07399 399

8101090146 Requests that encl emergency planning info be made publicly
available W/o encl
SJOGER, J L Division of Rules and Records 80/12/17 1p
07419 248

8101120280 Requests exclusion from submitting State of MD emergency
plan, since zone intrudes only 12 miles into area w/sparse
population & Farming Wind seldom blows toward area &
radiation levels would be minimal
BAUM, E A Virginia Electric & Power Co 81/01/08 2pp 07447: 113

O Adjudicatory correspondence

8101130304 Requests extension of license mod hearing request from
810108 to 810216 Hearing may still be requested but util
must review environ qualification matter before making final
decision re necessity of hearing.
CHRISTMAN, J H. Hutton & Williams 81/01/07 3pp, 07457: 020.

0101230103 Forwards "Turbine Missile Rept (NP296-LP281-LP281)," per NRC
request Rept section of info package to be submitted per
801106 ltr Related correspondence
* Hutton & Williams 81/01/14 1p 07511 341.

--8101230109 "Turbine Missile Rept (NP296-LP281-LP281)," CT-24821
Revision O Related correspondence.
* Westinghouse Electric Corp. NP296-LP281-LP281 80/08/31.
26pp 07511 342

M General correspondence

8101050488 Informs that appointment of JI Natts as senior vice
president of power operations, effective 010101, approved on
801219 by VEPCO Board of Directors Discusses util corporate
organization Tech Specs being revised for facilities
FERGUSON, J H Virginia Electric & Power Co 80/12/31 2pp
07385: 268

J. Insurance & indemnity information

8101130357 Forwards Endorsements 2, 3, 4, 4, 24, 33 & 31 to NELIA Policy
EB-70, EB-63, EB-28, EB-27, NS-316, NF-186 & NF-240, respectively
HAIRFIELD, K J Marsh & McLennan, Inc. M & M Nuclear Consultants,
Div. 81/01/09 16pp 07451 333

P Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under STS License amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 00/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 20, B 3/4 7-5 & 7-6 & 6-
STS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12: "Potential for Low Fracture
Toughness & Lateral Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp.

8101070129 Forwards Amend 22 to License NPF-4, safety evaluation &
notice of issuance & availability
CLARK, R A. Operating Reactors Branch 3 80/12/10 3pp 07419

--8101070134 Amend 22 to License NPF-4, changing axial power distrib
surveillance turn-on power & part power axial flux
difference limits
CLARK, R A. Operating Reactors Branch 3 80/12/10 17pp
07415 061

--8101070138 Safety evaluation supporting Amend 22 to License NPF-4
* Office of Nuclear Reactor Regulation, Director. 80/12/10
07415 071.

--8101070143 Notice of Issuance & availability of Amend 22 to License
NPF-4
CLARK, R A. Operating Reactors Branch 3 80/12/10 2pp
07415 073.

8101210445 Forwards responses to questions on Rule 80 71e, "Periodic
Updating of FSARs" & FR notice of final rule. SEP plants need
not comply w/rule until program is complete. Non-SEP plants
must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp.

8101150892 Updates developments in turbine missile issue at facilities
Based on conservatism for calculation of critical crack
ratio, continued operation until 801229 is justified. Licensees
will meet w/NRC on 801229 to present addl justification
NUVAK, J H Assistant Director for Operating Reactors 80/12/23.
3pp, 07308: 001

8101060349 Forwards rept, "Evaluation of Direct Measurement of
Differential Settlement Across BVC Meter Lines Expansion
Joints," in response to NRC 800912 request.
SYLVIA, B R. Virginia Electric & Power Co 80/12/29 20pp,
07393: 006.

8101050352 Forwards response to item 111.0.3.4 of NUREG-0737 Review
control room habitability conclude that requirements of Reg
Guide 1.7B & 1.95 & SRP Sections 2.2.1-2.2.2 & 2.2.3 have
been met.
SYLVIA, B R. Virginia Electric & Power Co 80/12/30 12pp,
07376: 206

0101190608 Forwards Amends 23 & 3 to Licenses NPF-4 & NPF-7,
respectively & notice of issuance.
CLARK, R A. Operating Reactors Branch 3. YOUNGBLOOD, B. J. License
Branch 1. 80/12/30 3pp, 07183: 001

--8101190617 Amends 23 & 3 to Licenses NPF-4 & NPF-7, respectively,
deleting water quality requirements for Unit 1 & adding
environ protection plan for Units 1 & 2
CLARK, R A. Operating Reactors Branch 3 80/12/30 83pp,
07182: 001

--0101190621 Notice of issuance of Amends 23 & 3 to Licenses NPF-4 & NPF-7, respectively
CLARK, R A Operating Reactors Branch 3 00/12/30 2pp
07183 001

0101060308 Forwards response to specified items of NUREG-0737 re shift technical adviser training program & ECCS outage rept of North Anna 1 & 2
SVLVIA, B R Virginia Electric & Power Co 00/12/31 37pp
07396 099

0101190379 Forwards safety evaluation supporting mechanical operability of purge & vent valves
CLARK, R A Operating Reactors Branch 3 01/01/06 2pp 07474 031

--0101190584 Safety evaluation supporting mechanical operability of purge & vent valves. Containment isolation capability of valves in closed position acceptable
a Office of Nuclear Reactor Regulation, Director 01/01/06 1p
07474 033

0101300024 Informs of transfer of licensing rgt responsibilities. Responsibilities for Unit 2 will fall under Assistant Director for Operating Reactors. Div of Licensing Licensing project manager for both units will be L Engle.
EISENHUT, D O Division of Licensing 01/01/13 2pp 07308 001

0101200218 Advises that data from pump tests will be used to determine if 340 gpm would be delivered to steam generator, per 001226 ltr. Results from final calculations will be forwarded.
SVLVIA, B R Virginia Electric & Power Co 01/01/19 1p
07407 027

0101200229 Forwards revised VEP-FRB-36, designated VEP-FRB-36A, "Control Rod Reactivity Worth Determination by Rod Swap Technique," per NRC 001107 ltr
THOMAS, W N Virginia Electric & Power Co 01/01/16 2pp
07470 001

--0101200235 "Control Rod Reactivity Worth Determination by Rod Swap Technique"
ROBB, T K, BECK, W C, BOWLING, M L Virginia Electric & Power Co
VEP-FRB-36A 00/12/31 61pp 07470 003

0101220328 Forwards Revision 0 to CT-24021, "Turbine Missile Rept (HP296-LP201-LP201)"
SVLVIA, B R Virginia Electric & Power Co 01/01/19 1p
07500 125

--0101220333 "Turbine Missile Rept (HP296-LP201-LP201)"
a Westinghouse Electric Corp. CT-24021 RD 00/08/31 26pp
07500 126

0101290757 Forwards info re containment base mat amplified response spectra per NRC verbal request Evaluation of safety-related components described in 001107 submittal completed for smooth ground response spectra w/o design mods
SVLVIA, B R Virginia Electric & Power Co 01/01/23 7pp
07309 001

0101300193 Expresses appreciation for 001203 meeting to discuss in-house licensing activities. Physics analysis methodology for reload safety evaluations will be discussed at 001220 meeting
THOMAS, W N Virginia Electric & Power Co 01/01/26 1p
07586 207

0101300180 Advises of plans for Cycle 3 reload core. Verification of reload core will be performed through startup physics testing program
THOMAS, W N Virginia Electric & Power Co 01/01/27 1p
07586 208

0. Inspection reports, IE Bulletins & correspondence

0101070294 Forwards supplemental response to violations noted in IE Insp Rept 00-338/79-47 Corrective actions, welder performance qualifications involving combined processes show separate thicknesses for each process of combined process weld.
SVLVIA, B R Virginia Electric & Power Co 00/10/14 2pp
07413 297

--0101070303 Forwards supplemental response to violations noted in IE Insp Rept 00-338/79-47 Corrective action determined that no multiple process procedures used to complete repairs since startup welding processes performed per weld manual.
SVLVIA, B R Virginia Electric & Power Co 00/10/02 2pp
07413 299

--0101070209 Forwards response to violations noted in IE Insp Rept 00-338/79-47 Corrective action welding procedures involving combination processes will be amended to include weld metal thickness range as deposited by each individual process
SVLVIA, B R Virginia Electric & Power Co 00/09/17 2pp
07413 301

0101150114 Responds to request for addl info re reply to IE Bulletin 79-02, "Pipe Support Baseplate Designs Using Concrete Expansion Anchor Bolts" for facility Sample calculations for typical baseplates & SW review procedure NA-EM 1 oncl
SVLVIA, B R Virginia Electric & Power Co 00/12/17 22pp
07308 001

010120120 Revises 001201 completion date for corrective actions F IE Bulletin 80-18 re maint of adequate min flow through centrifugal charging pumps Surry mods to be completed by 001203 & North Anna by 001203
SVLVIA, B R Virginia Electric & Power Co 00/12/22 1p
07446 121

010120519 Provides estimated schedule for completing masonry wall re-evaluation program required by IE Bulletin 80-11. Completion dates for Class 1 & 11 walls are 001315 & 0415, respectively
SVLVIA, B R Virginia Electric & Power Co 00/12/26 2pp
07447 172

0101290396 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)" No leakage in closed eye at North Anna 1 & 2 Summary of leakage at Surry 1 & 2 oncl
SVLVIA, B R Virginia Electric & Power Co 01/01/09 7pp
07575 133

R Periodic operating reports & related correspondence

0101300278 Forwards monthly operating repts for Dec 1980 & revised 1 monthly operating rept for Nov 1980.
SVLVIA, B R Virginia Electric & Power Co 01/01/15 1p
07477 146

--0101200265 Revised monthly operating rept for Nov 1980
ROBB, T K, BECK, W C, BOWLING, M L Virginia Electric & Power Co 00/12/26 2pp
07477 147

--0101200267 Monthly operating repts for Dec 1980
ROBB, T K, BECK, W C, BOWLING, M L Virginia Electric & Power Co 01/01/05 10pp
07477 149

B Reportable occurrences, LERs & related correspondence

0101060567 Forwards LER 80-104/991-0
CARTWRIGHT, W R Virginia Electric & Power Co 01/01/02 1p
07391 120

--0101060599 LER 80-104/991-0 on 001223, environ telemetry channel air temp found out of tolerance high during calibr. Caused by printed circuit card failure in transmitter multiplexer. Card removed & sent to manufacturer for repairs.
CARTWRIGHT, W R Virginia Electric & Power Co 01/01/02 2pp
07391 121

0101130454 Forwards LER 80-105/031-0
CARTWRIGHT, W R Virginia Electric & Power Co 01/01/06 1p
07454 100

--0101130342 LER 80-105/031-0 on 001218, level in IC safety inject accumulator dropped below Tech Spoc 3.5.1 min level. Caused by operator error during filling operation. Level restored.
CARTWRIGHT, W R Virginia Electric & Power Co 01/01/06 2pp
07454 101

0101120341 Forwards LER 80-102/031-0.
CARTWRIGHT, W R Virginia Electric & Power Co 01/01/07 1p
07447 160

--010120305 LER 80-102/031-0 on 001211, auto stop oil pressure switch calibr procedure would allow lower min valve than Tech Spoc. Caused by incorrect procedure. Calibr procedure changed.
CARTWRIGHT, W R Virginia Electric & Power Co 01/01/07 2pp
07447 161

0101200362 Forwards LER 80-106/031-0
CARTWRIGHT, W R Virginia Electric & Power Co 01/01/14 1p
07477 347

--B10120044 LER 80-105/03L-0 on B01221 fire door 594-6 found to be nonfunctional. Caused by ACIE in door & misaligned hardware. Cover plate installed over hole & hardware adjusted. CARLWRIGHT, W R Virginia Electric & Power Co. 81/01/14 2pp 07477 348

B101200431 Forwards LER 80-107/03L-0
CARLWRIGHT, W R Virginia Electric & Power Co. 81/01/14 1p 07476 331

--B101200437 LER 80-107/03L-0 on B01226 while operating at 59% power, steam generator ID steam pressure channel 11 observed indicating high, resulting in channel being locked in. Caused by sensing line for pressure transmitter 1483 freezing. CARLWRIGHT, W R Virginia Electric & Power Co. 81/01/14 2pp 07476 332

B101200434 Forwards LER 80-109/03L-0
CARLWRIGHT, W R Virginia Electric & Power Co. 81/01/15 1p 07493 150

--B101210446 LER 80-109/03L-0 on B01210, steam generator water level low-low reactor trip setpoint found at 15% narrow range instrument span on all generators rather than 18% level. Caused by oversight by administrative personnel. CARLWRIGHT, W R Virginia Electric & Power Co. 81/01/15 2pp 07493 151

B101220452 Forwards LER 81-002/03L-0
CARLWRIGHT, W R Virginia Electric & Power Co. 81/01/15 1p 07503 194

--B101220456 LER 81-002/03L-0 on B01231, pressurizer power operated relief valve declared inoperable because of low nitrogen gas supply tank pressure in J-GN-TK-A. Caused by excessive usage of nitrogen to cycle relief valves to reduce RCB pressure. CARLWRIGHT, W R Virginia Electric & Power Co. 81/01/15 3pp 07505 200

B101270452 Forwards LER 80-108/03L-0
CARLWRIGHT, W R Virginia Electric & Power Co. 81/01/21 1p 07546 323

--B101270458 LER 80-108/03L-0 on B01227, tests showed primary identified leakage was 17.73 gpm & primary unidentified leakage was 2.37 gpm. Caused by excessive leakage of RCP A seal 2 Seal will be replaced. CARLWRIGHT, W R Virginia Electric & Power Co. 81/01/21 3pp 07546 324

V. Operator Examinations

B101000308 Forwards response to specified items of NUREG-0737 re shift technical advisor training program & ECCS outage report of North Anna 1 & 2
SULLIVAN, B R Virginia Electric & Power Co. 80/12/31 37pp

DOCKET 80-039 NORTH ANNA POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

B101070434 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 80/12/02 1p 07415 346

--B101070446 Forwards public version of Revision 2 to emergency plan
List of changes encl
BAUM, E A Virginia Electric & Power Co. 80/06/20 2pp 07415 347

--B101070442 Public version of Revision 2 to emergency plan
* Virginia Electric & Power Co. 80/06/18 28pp 07415 349

B101070452 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 80/12/02 1p 07416 014

--B101070454 Forwards public version of Revision 3 to emergency plan
BAUM, E A Virginia Electric & Power Co. 80/06/25 1p 07416 015

--B101070457 Public version of Revision 3 to emergency plan
* Virginia Electric & Power Co. 80/06/25 22pp 07416 016

B10120459 Releases public version of util emergency plan.
FELTON, J M Division of Rules and Records 80/12/02 1p 07437 204

--B10120490 Forwards public version of Revision 1 to util emergency plan. State of VA 800520 confirmation ltr & list of changes encl
BAUM, E A Virginia Electric & Power Co. 80/06/08 5pp 07437 205

--B10120495 Public version of Revision 1 to util emergency plan
* Virginia Electric & Power Co. 80/06/09 106pp 07437 206

B101060615 Requests that encl emergency planning info be made publicly available w/o encl
SCUDER, J L Division of Rules and Records 80/12/17 1p 07399 359

B101080416 Requests that encl emergency planning info be made available w/o encl
SCUDER, J L Division of Rules and Records 80/12/17 1p 07419 248

B10120280 Requests exclusion from submitting State of MD emergency plan, since zone intrudes only 12 miles into area w/ sparse population & farming. Wind seldom blows toward area & radiation levels would be minimal.
BAUM, E A Virginia Electric & Power Co. 81/01/09 2pp

O. Adjudicatory correspondence

B101130384 Requests extension of license mod hearing request. B10108 to B10216. Hearing may still be requested but util must review environ qualification matter before making final decision re necessity of hearing.
CHRISTIAN, J M Hutton & Williams 81/01/07 3pp

B101230103 Forwards "Turbine Missile Rept (NP296)-(P261)-LP281" request Repl section of info package to be submitted per B01106 ltr. Related correspondence
* Hutton & Williams 81/01/14 1p 07511 341

X. General correspondence

B101050489 Informs that appointment of JI Oatts as senior vice president of power operations, effective B10101, approved on B01219 by NEPCO Board of Directors. Discusses util corporate organization Tech Specs being revised for facilities.
FERGUSON, J H Virginia Electric & Power Co. 80/12/31 2pp

J. Insurance & indemnity information

B101130397 Forwards Endorsements 2, 5, 4, 4, 24, 50 & 31 to NECLIA ED-70, ED-63, ED-28, ED-27, NS-316 MT-196 & NF-240, respectively.
HARRFIELD, A J Marsh & McLennan, Inc. M & M Nuclear Consulting 81/01/07 16pp

P. Operating license stage documents & correspondence

B1012300480 Forwards addl info re B01101 NUREG-0908 on safety electrical equipment environ qualification per NRC B01202-audit request. Response to Statement 10 to be submitted separately. Encl available in Central Files only.
SULLIVAN, B R Virginia Electric & Power Co. 80/12/23 2pp 07396 132

B101150892 Updates developments in turbine missile issue at Based on conservatons for calculation of critical crack ratio, continued operation until B01229 is justified. License will meet w/NRC on B01229 to present addl justification.
NOVAK, T M Assistant Director for Operating Reactors 80/12/23 3pp 07308 001

B101060439 Forwards rept. "Evaluation of Direct Measurement Differential Settlement Across Svc Water Lines Expansion Joints," in response to NRC 800912 request.
SULLIVAN, B R Virginia Electric & Power Co. 80/12/29 20p 07393 006

B101160417 Forwards Amend 2 to License NPF-7, FR notice & saf evaluation. No action taken on item re implementation date. Condition 2 C 21, Item J
YOUNG, L O B J Licensing Branch 1 80/12/29 2pp 07416 017

--B101160421 Amend 2 to License NPF-7, changing implementation certain post-TMJ requirements & revising implementation note re IE Bulletin 79-27
ETSEHUT, D O Division of Licensing 80/12/29 4pp

--B101160423 Notice of Issuance of Amend 2 to License NPF-7.
YOUNG, L O B J Licensing Branch 1 80/12/29 2pp 07416 018

--B101160424 Safety evaluation supporting Amend 2 to License NPF-7
• Office of Nuclear Reactor Regulation, Osceola 80/12/29
16pp 07471 009

B101090352 Forwards response to Item 111 D 3 4 of NUREO-0737 Reviews of
control room habitability conclude that requirements of Reg
Guide 1.7B & 1.95 & SRP Sections 2.2 1-2 2.2 & 2.2 3 have
been met
SYLVIA, B R Virginia Electric & Power Co 80/12/30 12pp
07376 206

B101190608 Forwards Amends 23 & 3 to Licenses NPF-4 & NPF-7,
respectively & notice of issuance
CLARK, R A Operating Reactors Branch 3 YOUNGBL, C. B. J Licensing
Branch 1 80/12/30 3pp 07183 001

--B101190617 Amends 23 & 3 to Licenses NPF-4 & NPF-7, respectively,
detailing water quality requirements for Unit 1 & adding
environmental protection plan for Units 1 & 2
CLARK, R A Operating Reactors Branch 3 00/12/30 85pp
07183 001

--B101190621 Notice of issuance of Amends 23 & 3 to Licenses NPF-4 &
NPF-7, respectively
CLARK, R A Operating Reactors Branch 3 80/12/30 2pp
07183 001

B101060308 Forwards response to specified items of NUREO-0737 re shift
technical advisor training program & ECCS outage rept of
North Anna 1 & 2
SYLVIA, B R Virginia Electric & Power Co 80/12/31 37pp

B101090988 Responds to Statement 10 of NRC B01202-04 audit of W111
NUREO-0588 review Program developed to re-evaluate equipment
qualification folders Outline of missing data will be
prepared by B10107
SYLVIA, B R Virginia Electric & Power Co 81/01/02 2pp
07472 351

B101160436 Application for amend to License NPF-7, allowing 90-day
extension for completion of piping reanalysis, including
seismic amplified response spectra evaluation, Class III fee
encl
FERDUSON, J H Virginia Electric & Power Co 81/01/09 3pp
07472 141

B101290478 Summary of B10107 meeting w/utill in Bethesda, MD re leak
testing of RCS isolation valves Tech Spec Page 3/4 4-18
encl
DRUMERICK, A W Licensing Branch 1 01/01/12 9pp 07575 147

--B101290482 Tech Specs Page 3/4 4-18, Section 4.4 & 2.2 re RCS
surveillance requirements
• Licensing Branch 1 01/01/12 1p 07575 152

B101300024 Informs of transfer of licensing mgt responsibilities
Responsibilities for Unit 2 will fall under Assistant
Director for Operating Reactors, Div of Licensing Licensing
project manager for both units will be L Engle
EISENHUT, D O Division of Licensing 81/01/13 2pp 07308 001

B101200229 Forwards revised VEP-FR0-36, designated VEP-FR0-36A, "Control
Rod Reactivity Worth Determination by Rod Swap Technique,"
per NRC B01107 1tr
THOMAS, W N Virginia Electric & Power Co 81/01/16 2pp

--B101200235 "Control Rod Reactivity Worth Determination by Rod Swap
Technique"
ROSS, I K Virginia Electric & Power Co VEP-FR0-36A 80/12/31
61pp

B101220369 Forwards VEP-FR0-39, "North Anna Unit 2, Cycle 1 Startup
Physics Test Rept."
THOMAS, W N Virginia Electric & Power Co 01/01/16 1p
07309 001

--B101220370 "North Anna Unit 2, Cycle 1 Startup Physics Test Rept."
ROTELLA, T. B., KUNSITIS, T. J., LOZITO, E. J Virginia Electric & Power
Co VEP-FR0-39 80/12/31 129pp 07309 001

B101220328 Forwards Revision 0 to CT-24821, "Turbine Missile Rept
(HP296-LP281-LP281)"
SYLVIA, B R Virginia Electric & Power Co 81/01/19 1p
07500:125

--B101220333 "Turbine Missile Rept (HP296-LP281-LP281)"
• Westinghouse Electric Corp CT-24821 RO 80/08/31 26pp
07500:126

B101230465 Advises that containment sump level processes move to
nonharsh environment has been completed Change will be reflected
in B10201 submittal for NUREO-0588 review
SYLVIA, B R Virginia Electric & Power Co 81/01/19 2pp
07510 308

B101290757 Forwards info re containment base mat amplified response
spectra per NRC verbal request Evaluation of safety-related
components described in B01107 submittal completed for
smooth ground response spectra w/o design mods
SYLVIA, B R Virginia Electric & Power Co 81/01/23 7pp
07309 001

B101300193 Expresses appreciation for B01203 meeting to discuss
in-house licensing activities Physics analysis methodology
for reload safety evaluations will be discussed at B01020
meeting
THOMAS, W N Virginia Electric & Power Co 81/01/26 1p

0 Inspection Reports, IE Bulletins & correspondence

B101120120 Revises B01201 completion date for corrective actions for
IE Bulletin B0-18 re maint of adequate min flow through
centrifugal charging pumps Surry mods to be completed by
B11205 & North Anna by B01203
SYLVIA, B R Virginia Electric & Power Co 80/12/22 1p

B101120519 Provides estimated schedule for completing masonry wall
re-evaluation program required by IE Bulletin B0-11
Completion dates for Class I & II walls are B10315 & 0415,
respectively
SYLVIA, B R Virginia Electric & Power Co 80/12/26 2pp

B101290396 Forwards response to IE Bulletin B0-24, "Prevention of
Damage Due to Water Leakage Inside Containment (Oct 17, 1980
Indian Point 2 Event)" • No leakage in closed sys at North
Anna 1 & 2 Summary of leakage at Surry 1 & 2 encl
SYLVIA, B R Virginia Electric & Power Co 81/01/05 9pp

R Periodic operating reports & related correspondence

B101200378 Forwards monthly operating repts for Dec 1980 & revised Un
1 monthly operating rept for Nov 1980
SYLVIA, B R Virginia Electric & Power Co 81/01/15 1p
07477 146

--B101200379 Monthly operating repts for Dec 1980
RIGGERS, L L Virginia Electric & Power Co 81/01/05 10pp
07477 149

8 Reportable occurrences, LERs & related correspondence

B101090530 Forwards LER B0-101/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 81/01/02 1p
07430 359

--B101090539 LER B0-101/03L-0 on B01211, nonconservative constants from
entered on B01129 into FO survey program used to verify FZ
within limits Caused by computer technician error after
disc changeout. Correction made
CARTWRIGHT, W R Virginia Electric & Power Co 81/01/02 2pp
07430 360

B101130468 Forwards LER B0-098/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 81/01/06 1p
07454 107

--B101130480 LER B0-098/03L-0 on B01208, individual rod position
indication for rod J-7 in shutdown bank B deviated from
demand position by more than 12 steps Caused by instrument
drift Rod position indicator channel recalibrate
CARTWRIGHT, W R Virginia Electric & Power Co 81/01/06 2pp
07454 108

B101130475 Forwards LER B0-097/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 01/01/06 1p
07454 115

--B101130488 LER B0-097/03L-0 on B01209 & 10, containment penetration
conductor for polar crane energized in mode for which
breaker overload protection not qualified Caused by closing
breaker 231-2A3 for insp & work completion
CARTWRIGHT, W R Virginia Electric & Power Co 81/01/06 2pp
07454 116

B101130493 Forwards LER B0-099/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 81/01/06 1p
07453 285

--B10113052B LER 80-099/03L-0 on 801210, overspeed trip of steam driven auxiliary feedwater pump occurred during post-maint testing. Probably caused by governor malfunction due to air entrapped. Air purged from governor oil.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/06 2pp
07453 286

B101130534 Forwards LER 80-096/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/06 1p
07454 136

--B101120539 LER 80-096/03L-0 on 801208, power supply to P0-247B on steam generator 1A steam pressure channel III reading low. Caused by instrument drift. Power supply recalibrated.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/06 2pp
07454 137

B101120582 Forwards LER 80-100/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/09 1p
07582 342

--B101130397 LER 80-100/03L-0 on 801211, with unit in Mode 3, RC Loop A gave protection annunciator locked in actual tripping. Indicating 347 F & protective Channel 1A gave TFI-241203 indicating 344 F. Cause unknown. Channel 1A recalibrated.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/09 2pp
07582 343

B101120393 Forwards LER 80-102/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 1p
07477 341

--B101120395 LER 80-102/03L-0 on 801218, axial flux difference deviated above target. Caused by increasing reactor power during startup w/ effects of xenon burnout. Rods borated out to restore axial flux difference to within target band.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 2pp
07477 342

B101200375 Forwards LER 80-103/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 1p
07477 352

--B101200383 LER 80-103/03L-0 on 801220, refueling water storage tank level transmitters LT-05-2000.C & O froze. Caused by cold outside temp along w/ improperly adjusted setpoint pots on heat tracing circuits. Transmitters thawed & pots adjusted.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 2pp
07477 353

B101200444 Forwards LER 80-104/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 1p
07476 334

--B101200452 LER 80-104/03L-0 on 801218, w/ unit in Mode 1, water was found leaking from weld joint connecting vent valve 2-CK-P-185 to piping into suction line of charging pump 2-CK-P-18. Caused by leak from weld at base of valve. Weld repaired.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 2pp
07476 335

B101200593 Forwards LER 81-001/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/15 1p
07512 292

--B101230601 LER 81-001/03L-0 on 810101, average RCS temp outside Tech Specs on two occasions. First caused by vol control tank being overborated, second by overcooling primary steam generator blowdown secured, rods withdrawn & RCS diluted.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/15 3pp
07512 293

B101300706 Forwards LER 81-007/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/26 1p
07183 001

--B101300714 LER 81-007/03L-0 on 801230, boron concentration in boron acid storage tank C & boron injection lent below Tech Spec. Probably caused by misleakage of unknown source. Boric acid transferred to tank C. Investigation of leak underway.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/26 3pp
07183 001

V Operator Examinations

B101060308 Forwards response to specified items of NUREG-0737 re shift technical advisor training program & ECCS outage rept of North Anna 1 & 2.
SYLVIA, B.R. Virginia Electric & Power Co. 80/12/31 37pp.

B101130210 Advises that four licensed reactor operators will not complete annual written exam by end of CY80, due to extensive startup test program outages & training & operator licensing requirements. Exam will be completed by 810331.
SYLVIA, B.R. Virginia Electric & Power Co. 81/01/08 1p
07457 024

DOCKET 80-341 EMBICO FERRI ATOMIC POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports".
EISENHUT, D.O. Division of Licensing 80/11/26 8pp

B101190505 Ltr to all BWR applicants for OL re BWR scram discharge safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge vol encl.
TEDESCO, R.L. Assistant Director for Licensing 80/12/22 2pp
07183 031

--B101190514 Forwards generic safety evaluation re BWR scram discharge sys. Review identified two addl requirements to those proposed by owners group re scram discharge vol designs. Rept should be transmitted to license applicants.
CHECK, P.B. Assistant Director for Plant Systems 80/12/01 2p
07183 031

B101140942 Summary of 801209 meeting w/Bachtel in Oaltersburg, MD re review.
KINTNER, L.L. Licensing Branch 2 80/12/30 3pp 07461 021

B101050077 Forwards Amend 32 to amended & substituted application for licenses, consisting of additions & mods to FBAR.
THOMAS, E.B. LeBoeuf, Lamb, Leiby & MacRae 80/12/31 1p
07380 191

--B101050000 Amend 32 to amended & substituted application for licenses, consisting of additions & mods to FBAR.
HEIDEL, C.M. Detroit Edison Co. 80/12/30 1p 07380 192

B101200316 Confirms B10115 meeting w/util in Glen Ellyn, IL to discuss status of project & topics re const activities.
HEPPLER, J.O. Region 3, Chicago, Office of the Director 81/01/12 1p 07487 024

B101210083 Informs that 801205 memo re meeting summary for Fermi 2 should read Parley 2. Copies of memo should be destroyed.
KINTNER, L.L. Licensing Branch 2 81/01/13 2pp 07489 322

B101210588 Forwards Certificate of BvC re Amend 32 to amended & substituted application for licenses.
MATTERS, B.R. Detroit Edison Co. 81/01/14 3pp 07489 010

B101290472 Summary of 801223 meeting w/util re scope & schedule for completion of Facility OL application review.
KINTNER, L.L. Licensing Branch 2 81/01/14 5pp 07571 037

B101300219 Requests commitment to special low power test program for facility to comply w/TMI task action item I.O.I.PWR test re simulated loss of ac power is feasible & should be performed on BWRs.
TEDESCO, R.L. Assistant Director for Licensing 81/01/14 3pp
07582 138

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FBAR.
EISENHUT, D.O. Division of Licensing 80/11/13 2pp

K Utility Final Safety Analysis Report (FSAR) & amendments

B101050077 Forwards Amend 32 to amended & substituted application for licenses, consisting of additions & mods to FBAR.
THOMAS, E.B. LeBoeuf, Lamb, Leiby & MacRae 80/12/31 1p
07380 191

--B101050080 Amend 32 to amended & substituted application for licenses, consisting of additions & mods to FBAR.
HEIDEL, C.M. Detroit Edison Co. 80/12/30 1p 07380 192

--B101090085 Amend 32 to Enrico Fermi Unit 2 FSAR
* Detroit Edison Co 80/12/30 131pp 07380 193

0. Inspection reports, IE Bulletins & correspondence

B101050274 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding" No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30 2pp 07389 209.

B101050590 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Bcam Discharge Val at Dresden Unit 2" No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05 2pp 07390 317

B101210656 Forwards IE Insp Rept 50-341/80-20 on 801112-14 & notice of violation
FIORRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/09 2pp 07408 147

--B101210699 Notice of violation from Insp on 001112-14
FIORRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/09 2pp 07488 149

--B101210662 IE Insp Rept 50-341/80-20 on 801112-14 Noncompliance noted: permitting cable installation activities to continue w/inadequate & not performing actual audits on electrical activities in plant
BARRETT, R A, KNOPF, R C Region 3, Chicago, Office of the Director 80/12/09 4pp 07480 151

B101150810 Forwards IE Insp Rept 50-341/80-21 on 001119-21 No noncompliance noted.
OAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/11 2pp 07464 287.

--B101150819 IE Insp Rept 50-341/80-21 on 801119-21 No noncompliance noted Major areas inspected radiation protection program
HUETER, L J Region 3, Chicago, Office of the Director
FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/09 5pp 07464 289

B101000041 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Bcam Capability" No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17 2pp 07419 354.

B101150220 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Bcam at BWR" No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/10 2pp 07465 332.

B101050193 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rod Safety Relief Valves at BWRs." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/19 2pp 07377 331

B101290768 Ack receipt of 801119 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/80-11.
FIORRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 81/01/14 1p 07568 330

--B101290770 Responds to NRC 801008 ltr re violations noted in IE Insp Rept 50-341/80-11. Corrective actions program instituted to assure design documents in use reflect current design status.
HINEB, E Detroit Edison Co 80/11/19 4pp 07568 331.

8. Reportable occurrences, LERs & related correspondence

B101290006 Interim deficiency rept re defective micro switches initially reported 801203 Six switch failures found out of 130 switches tested Caused by crushed internal parts Final rept will follow by 810310
HINEB, E Detroit Edison Co 80/12/23 1p 07568 339.

00CKEY 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101100061 Ltr to all power reactor licensees w/plants to 790101 Forwards revised Section 101FR50 48 & App fire protection features in nuclear power plants & 1 requirements for resolution of open issues
EISENHUT, D O Division of Licensing 80/11/24 20

B101140454 Responds to wsl 801023 ltr re mod to exist area boundary at facility during & after const of to support ctr Changes will not decrease safeguards effectiveness & do not require prior Commission approval
CLARK, R A Operating Reactors Branch 3 80/12/17

B101210840 Informs that licensee must conduct emergency one yr from 810401 or prior to issuance of GL Request schedule of drills & exercises
FENSELKEN, R H Region 5, San Francisco, Office of the 80/12/19 1p 07443 259

B101080440 Discusses emergency plan revision re effect eruptions from Mount St Helens FEA has been request NRC to consider effects of earthquake eruptions on communication networks & evacuation plans in site or CHA/VEV, H V. Federal Emergency Management Agency, 8 07420 336

G. Adjudicatory correspondence

B101128502 Order granting licensee & State of OR 00122 reopen record & receive stipulation & other document modify License Condition 2 C(12) Appeal not & dismi Certificate of Govt encl
OISENHUT, C J Atomic Safety and Licensing Appeal Panel 8pp 07447 213

H. General correspondence

B101140762 Responds to 801016 ltr re CA Snow 801007 ltr concerns about Mount St Helens & facility Util report finding little mud in plant intake structure Should have been more massive, plant could have shut down see DIRCKS, H J Office of the Executive Director for Op 80/12/03 4pp 07461 302

B101210318 Expresses concern re possible pyroclastic f facility resulting from Mt St Helens volcanic erupt Comments requested Search Technical Svcs evaluation newspaper article encl
STEINHART, K Physicians for Social Responsibility, 07490 133

J. Insurance & indemnity information

B101140218 Forwards Endorsement 42 to ANI Policy NF-22 36 & 35 to MAELU Policy NF-66 Endorsement 36 emends of Endorsement 35
WILBOH, F R Portland General Electric Co 80/12/04 07461 273

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) Revision 1 of inservice surveillance requirements for snubbers under BTR license amend application adding Tech Specs to App A should be submitted within 120 d
EISENHUT, D O Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28,8 3/4 7 BTR snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applic summary of 801112 meeting re implementation of guide Unresolved Safety Issue A-12: "Potential for Low Fra Toughness & Lamellar Tearing on Component Supports" EISENHUT, D O Division of Licensing 80/11/26 8p

B101090745 Forwards Amend 53 to License NPF-1 & notice availability.
CLARK, R A Operating Reactors Branch 3 80/12/11 07430 342

--B101090793 Amend 53 to License NPF-1, clarifying defl "operable."
CLARK, R A Operating Reactors Branch 3 80/12/11 07430 342

--B101090760 Notice of Issuance & availability of A-ran NPF-1.
CLARK, R A Operating Reactors Branch 3 80/12/11 07430 352

81010104035 Forwards Amend 54 to License NPF-1 & notice of issuance & availability
CLARK, R A Operating Reactors Branch 3 80/12/11 3pp 03893 292

--81010109038 Amend 54 to License NPF-1 restricting containment purger/exhaust fan operation & correcting error on min water level maint over reactor vessel during refueling
CLARK, R A Operating Reactors Branch 3 80/12/11 19pp
03893 295

--81010107039 Notice of issuance & availability of Amend 54 to License NPF-1
CLARK, R A Operating Reactors Branch 3 80/12/11 2pp
03893 314

81010105044 Notifies that util 801029 application to amend license, clarifying term "operation" requires Class III fee
WITHERS, B D License Fee Management Branch 80/12/15 1p
07389 347

81010121045 Forwards responses to questions on Rule 50.7(e). "Periodic updating of FLARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D G Division of Licensing 80/12/15 13pp

81010100590 Technical Evaluation Rept. Degraded Grid Protection for Class IE Power Sys. Trojan Nuclear Plant. technical evaluation rept
CLEVELAND, C W Idaho National Engineering Laboratory FIN A-6256
81010100590 80/12/31 13pp 07431 110

81010107046 Forwards supplemental info to 801223 response to MUREQ-0737 re post-TMI action items Includes info re shift technical division auxiliary feedwater sys automatic initiation & flow indication Aperture card in PDR
WITHERS, B D Portland General Electric Co. 81/01/02 37pp
17414 332

810101010271 Forwards Class III license amend fee in response to LRC 801215 ltr re util 801029 application
WITHERS, B D Portland General Electric Co 81/01/06 2pp
07447 221

81010129073 Summary of 801217 meeting w/ util & Westinghouse re final conclusions & lab examination results of steam generator row 1 U-bend tube samples removed from facility List of attendees & vignettes encl
TRAMMEL, C M Operating Reactors Branch 3 81/01/06 11pp
07569 107

81010121093 Forwards addl clarifying info re FIS in support of 800722 License Change Application 63 for amend of License NPF-1
WITHERS, B D Portland General Electric Co 81/01/13 5pp
07492 060

810101220270 Forwards proprietary & nonproprietary versions of "Improved BCL, HZP, Power Distribution Prediction," per 801118 request Requests withholding (ref 10CFR2 790)
WITHERS, B D Portland General Electric Co 81/01/13 2pp
07495 174

--810101220274 Nonproprietary version of "Improved BCL, HZP Power Distribution Prediction"
Portland General Electric Co. 81/01/13 8pp 07495 176

--810101220279 Requests that util startup & power escalation testing rept be withheld from public disclosure per 10CFR2 790 Original Affidavit AW-76-31 dtd 760703 encl
WIESEBACH, R A Westinghouse Electric Corp 81/01/07 10pp
07495 104

810101270503 Suppls 801112 License Change Application 67 requesting changes to Tech Specs re emergency bus undervoltage protection sys actuation logic Primary & secondary sys will consist of four solid state definite time delay relays
WITHERS, B D Portland General Electric Co 81/01/21 4pp
07543 012

0 Inspection reports, IF Bulletins & correspondence

810101050124 Requests existing data summaries & records of inservice insp tests of containment w/greased prestressing tendons ORNL receiving contract to compile & review records of tendons
EISENHUT, D G Division of Licensing 80/11/25 3pp

81010105020 Forwards IE Insp Rept 50-344/80-28 on 801103-07 No noncompliance noted
SPENCER, D S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/11/28 2pp 07488 068

--8101010624 IE Insp Rept 50-344/80-28 on 801103-07 No noncompliance noted Major areas inspected facility mod activities & followup on previously identified items
EISENHUT, D G Region 5, San Francisco, Office of the Director
WITHERS, B D Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/11/28 8pp 07488 070

81010106028 Responds to IE Bulletin 80-23 No Valcor Engineering Corp solenoid valves used at facility
WITHERS, B D Portland General Electric Co 80/12/02 1p
07399 157

81010105046 Forwards IE Info Notice 80-40, "Failures of Continuous Water Level Monitor Fuel Scream Discharge Val at Dresden Unit 2"
No response required
EISENHUT, R H Region 5, San Francisco, Office of the Director
80/12/05 1p 07487 282

81010120567 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc." No subg valve yokes in use at facility
WITHERS, B D Portland General Electric Co 80/12/10 1p
07339 001

81010106033 Forwards IE Insp Rept 50-344/80-23 on 801020-24, 28 & 29 noncompliance noted Major areas inspected activities re physical protection program against industrial sabotage & theft of BWR Insp rept withheld (ref 10CFR2 790)
HODGKINS, L R Region 5, San Francisco, Safeguards Branch 80/12/19 1p 07199 150

8101010825 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown" No response required
EISENHUT, R H Region 5, San Francisco, Office of the Director
80/12/16 1p 07308 001

810101270453 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event)" Safety-grade containment water level monitoring sys will be installed during next refueling outage.
WITHERS, B D Portland General Electric Co 81/01/06 1p
07549 059

810101270657 Responds to NRC 801125 ltr requesting info re inservice of containment structure ungrouted (greased) prestressing tendons Third surveillance program now being performed at plant & expected to continue through Mar 1981
WITHERS, B D Portland General Electric Co 81/01/21 5pp
07549 001

R Periodic operating reports & related correspondence

810101030564 Forwards monthly operating rept for Dec 1980
WILDT, C P Portland General Electric Co. 81/01/02 1p. 07493

--810101030572 Monthly operating rept for Dec 1980
WILDT, C P Portland General Electric Co. 81/01/02 5pp
07493 209

B Reportable occurrences, LERs & related correspondence

810101050311 Discusses fire suppression sys inoperability caused by in hydrant branch line due to excavation for technical support ctr Design completed shortening header branch line & relocating fire hydrant Completion scheduled for 801224
WILDT, C P Portland General Electric Co. 80/12/17 1p 07389

81010106043 Forwards LER B1-001/03L-0
WILDT, C P Portland General Electric Co 81/01/09 2pp.
07474 049

--81010106044 LER B1-001/03L-0 on 801212, blown fuse was found in br control power circuit for vent supply fan to turbine-driven auxiliary feedwater pump room Cause unknown Fuse replaced.
WILDT, C P Portland General Electric Co. 81/01/09 2pp
07474 051

810101290230 Part 21 rept re failure to provide proper Control Comp Intl valves supplying 2 gpm flow when in closed position. Caused by valve failure. Affected licensees notified & selection of alternative method underway.
TAYLOR, J H Babcock & Wilcox Co 81/01/09 2pp. 07308 001

0301060501 Forwards application for amend to License 12P-
Term Specs re fire detection sys, decay heat removal
capabilities, low temp RCS overpressure event, axial power
shaping rod insertion limits & util reorganization
(#CUSE, R P Toledo Edison Co 00/12/26 200 07395

--810106582 Application for amend of License NPF-3 change
re Fire detection sys. delay heat removal capabilities
temp RCS overpressure event, axial power shaping rod
insertion limits & until reorganization
CROUSE, R P Toledo Edison Co BO/12/26 1p 0739

--B101060597 Proposed Tech Specs 3 3 3 0.4 3 3 0 2.3 7 9
tables 3 3-14.3. 7-4 & 3 7 5 re fire detection & fire
suppression sys
* Tolson Edison Co. 80/12/26 16pp 07395 075

-B101060623 Proposed Tech Specs 3.4 1 1.3 4 1 2.3 9 8 1.
re decay heat removal capability Safety evaluation en
* Tolson Edison Co 80/12/25 1000 07395 091

--B101060610 Proposed Tech Specs 3 9 3,3 4 2.4 4 2. Figure
3 4 2-5 2 bases re delay heat removal sys relief valv
Modes 4 2 5 Safety evaluation encl.
* Tolpco Edison Co 8/12/26 ltr 07395 10)

--BIO1062614 Proposed Tech Specs d 1 3 9 re arrial power a
insertion limits Safety evaluation encl
* Toledo Edison Co 80/12/26 500 07399 112

--B101060524 Proposed Tech Specs & S. : re administrative
* Toledo Edison Co 80/12/26 1: 07395 119

D101060473 Responds to NUREG-0737 Util working w/WH State
feasibility evaluation of long-term program to phase out
need for shift technical advisor Commitment supersedes
previous commitments
RNUHFE:JP Toledo Edison Co. 02/12/90 1700 0739D

B101120253 Notification of B10105 meeting w/Util in Dethle
discuss proposed Tech Spec change re defeat of automatic
switchover of ECCS supply from borated water storage to
recirculation mode from containment sump
011AM-41.0 C Operating Reactors Branch 4 80/12/30
07435 359

8101070376 Forwards "Addendum 1 to Analysis of Adequacy of
Nuclear Power Station Onsite Electrical Auxiliary
Distribution Power Sys Voltages," in response to add M
801114 questions
* Telecon Edison Co. 81/01/01 1a 07414 110

--B101070393 "Addendum 1 to Analyses of Adequacy of Davis
Power Station Onsite Electrical Auxiliary Distribution
Power Bay Voltages "
* Tolson Editor Co 60/12/30 1200 07414 111

8101090027 Application to amend license HPF-3, changing to
Sections 3.1, 3.3, 3.4, 3.4.5, 2.4, 6 re borated water source
limiting condition for operation, surveillance requirements
& bases N2 Class fill amend fee
CROUSE, R P Toledo Edison Co 01/01/05 3pp 07441

... B101090029 Proposed Tech Spec Sections 3.1.3 3.3 5.4 3.5
changing treated water sources limiting conditions for
operation, surveillance requirements & bases
* Toledo Edison Co. 01/01/05 17:00 07441 161

010116090 Forwards Amend 35 to Lirenso NPF-3, safety eval
notice of issuance & availability
REID, R W Operating Reactors Branch 4 01/01/09 200

--B1011AC057 Amend US to License NPF-3, revising Tech Spec
continuous plant operation during first test following
refueling outage on pressure transmitters for contain-
high pressure channels
FIELD, R H Operating Reactor Branch 4 B1/01/05
07469 #73

-8101160051 Safety evaluation supporting Amend 39 to L1
• Office of Nuclear Reactor Regulation, Director
07468 277

--S19114C06-1 Notice of issuance & availability of Amend
HPP-3
REID, R W Operating Reactors Branch 4 S19/01/05
07369 279

BIO1100184 Discusses 801205 inadvertent safety features activation sys
 Level 1, 2, 3 & 5 activation while licensee & vendor were
 attempting to isolate electrical fault in sys 1E & 6R of
 Nuclear Reactor Regulation followup should suffice
 CHIRALAL, M. Director's Office 80/12/19 2pp. 07444.166

810122042 Forwards application to amend License NPF-3, marked-up Tech Spec changes & proposed procedure mods Encl available in Central Files only
 CRLUSE, R P Toledo Edison Co 01/01/09 2pg 07517 036

810160461 Forwards marked-up electrical drawings as update to 810105 request to deautomate Incident Level 5 of safety features activation sys Procedure mod details, license amend request & safety evaluation will follow N/A encl
 CRLUSE, R P Toledo Edison Co 01/01/09 3pg 07469 359

8101150503 Application to amend License NPF-3, changing Tech Spec to permit deautomation of valve shifts caused by Incident Level 5 of safety features activation sys
 CRLUSE, R P Toledo Edison Co 01/01/15 3pg 07475 075

8101190509 Proposed Tech Specs Sections 3.4 & 4. to permit deautomation of valve shifts caused by Incident Level 5 of safety features activation sys Draft emergency & sys operating procedures & functional description encl
 * Toledo Edison Co 01/01/15 10pg 07475 078

8101250575 Forwards application for amend of License NPF-3 re proposal of deautomation valve shifts caused by Incident Level 5 of safety features activation sys
 CRLUSE, R P Toledo Edison Co 01/01/15 2pg, 07502 270

8101250582 Application for amend of License NPF-3, changing Tech Specs Sections 3.4 & 4. re proposal to deautomate valve shifts caused by Incident Level 5 of safety features activation sys Draft proposed mods to operating procedures encl
 RICHLES, W C, CRLUSE, R P Toledo Edison Co 01/01/15 12pg 07502 272

8101260467 Revision to 810105 application to amend License NPF-3, changing Tech Specs Sections 3.4 & 4 to support deautomation of Incident Level 5 of safety features activation sys
 CRLUSE, R P Toledo Edison Co 01/01/15 3pg 07532 038

8101260493 Proposed Tech Specs Sections 3.4 & 4 to support deautomation of Incident Level 5 of safety features activation sys Description of electrical mods, safety evaluation & draft proposed emergency & sys operating procedures encl
 * Toledo Edison Co 01/01/15 20pg 07532 041

8101230495 Forwards response to NRC questions re 810115 ltr re deautomation of Incident Level 5 of safety features activation sys & long-term post LOCA core cooling removal action proposals
 CRLUSE, R P Toledo Edison Co 01/01/19 16pg 07511 130

8101270576 Forwards revision to Attachment C of 810119 ltr re present circuit configuration Calculation methodology for min contained vol discussed Approval of proposed Tech Spec changes re addl surveillance requested by 810123
 CRLUSE, R P Toledo Edison Co 01/01/22 4pg 07548 093

8101300605 Response to NRC safety evaluation requiring installation of addl 100% capacity auxiliary feedwater sys Proposes risk reduction comparison to provide evaluation of acceptable alternative
 CRLUSE, R P Toledo Edison Co 01/01/23 3pg

8101500404 Forwards amend fee for 801226 request for Tech Spec change re fire protection, decay heat removal capabilities, low temp RCS overpressure event, axial power shaping rods insertion limits & reorganization
 CRLUSE, R P Toledo Edison Co 01/01/26 1p, 07587 067

0 Inspection reports, IE Bulletins & correspondence

8101050218 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding" No response required
 HEPPLE, J G Region 3, Chicago, Office of the Director 80/10/30 2pg 07399 060

8101050402 Forwards IE Bulletin 80-21, Valve Yokes Supplied by Malcolm Foundry Co, Inc "Written response required
 HEPPLE, J G Region 3, Chicago, Office of the Director 80/11/05 2pg, 07390 264

8101080170 Responses to IE Bulletin 80-23 re Valve solenoid valves in safety-related functions No such valves used, Ten hours of manpower expended
 CRLUSE, R P Toledo Edison Co 80/11/25 1p 07420 358

8101350581 Forwards IE Info Notice 80-43, "Failures of Continuous Hot Level Monitor for Steam Discharge Vol at Dresden Unit 2" No response required
 HEPPLE, J G Region 3, Chicago, Office of the Director 80/12/05 2pg 07399 341

8101500626 Responses to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc" Specified valves are not installed at facility
 CRLUSE, R P Toledo Edison Co 80/12/05 1p 07391 063

8101290536 IE Investigation Rept 50-346/80-28 on 800929-1001 No noncompliance noted Major areas investigated allegations re improper welder qualification & welding documentation by personnel
 FOSTER, J E, SCHAPIER, J F, MORELIUS, C E Region 3, Chicago, Office of the Director 80/12/09 7pg 07573 339

8101260720 Forwards IE Insp Rept 50-346/80-31 on 801105-07 No noncompliance noted
 DAVID, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/10 2pg 07531 162

8101260729 IE Insp Rept 50-346/80-31 on 801105-07 No noncompliance noted Major areas inspected emergency exercise w/13 NRC representatives observing key functions & locations Exercise scenario encl
 AXELSON, W L, Region 3, Chicago, Fuel Facility & Materials Safety Branch, MICHAELSON, N A, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/12/09 13pg 07531 164

8101070200 Provide anticipated schedule for completion of pipe support/anchor mods required inside & outside containment by IE Bulletins 79-02 & 79-14 All IE Bulletin 79-02 mods inside containment completed
 CRLUSE, R P Toledo Edison Co 80/12/12 2pg, 07415 245

8101060456 Forwards revision to 800515 Inservice Insp program Changes reflect results of 801119 & 20 meetings w/NRC onsite re lower head addl insp & requirements in 1977 edition through summer 1978 addenda of Boiler & Pressure Vessel Code
 CRLUSE, R P Toledo Edison Co 00/12/15 2pg 07396 209

8101060457 Revision 1 to Inservice Insp program
 * Toledo Edison Co 80/11/30 60pg, 07396 211

8101070074 Forwards IE Info Notice 80-44, "Actuation of ECCS to Recirculation Mode While in Hot Shutdown" No written response required
 HEPPLE, J G Region 3, Chicago, Office of the Director 80/12/16 1p 07415 033

8101210630 Forwards IE Insp Rept 50-346/80-30 on 801112-14 & notice of violation
 HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/19 2pg 07488 140

8101210651 Notice of violation from Insp on 801112-14
 HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/10 1p, 07408 142

8101210654 IE Insp Rept 50-346/80-30 on 801112-14 Noncompliance noted trip chart recorders not calibr for rod drop time tests
 CHOLEN, N C, ROBINSON, D L Region 3, Chicago, Office of the Director, STREETER, J F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/17 4pg 07488 143

8101290499 Forwards IE Investigation Rept 50-346/80-28 on 800929-1001 No noncompliance noted
 HEPPLE, J G Region 3, Chicago, Office of the Director 80/12/19 2pg 07573 337

8101290506 IE Investigation Rept 50-346/80-28 on 800929-1001 No noncompliance noted Major areas investigated allegations re improper welder qualification & welding documentation by personnel
 FOSTER, J E Region 3, Chicago, Office of the Director, BAJILSON, D Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/09 7pg

8101210643 Forwards IE Insp Rept 50-346/80-29 on 801020-1126 & 1201-01 & notice of violation
 HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/23 2pg 07488 129

8101210646 Notice of violation from Insp on 801020-1126 & 1201-05
 * Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/23 1p 07488 131

--B101210548 IE Insp Rept 50-346/80-29 on 801020-1126 & 1201-03
Noncompliance noted containment pressure transmitters not
exercised during functional test
HEYES, L. A., ROGERS, W. C., WARMICK, R. F. Region 3, Chicago, Office of
the Director 80/12/18 8pp 07488 132

B101160579 Forwards list of NRC & contractor personnel for whom
nonemployees, no escort required, picture badges are required
for health physics appraisal beginning 810117
KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/12/29
3pp 07471 204

B101200185 Forwards response to IE Bulletin 80-24, "Prevention of
Damage Due to Water Leakage Inside Containment (801017
Indian Point 2 Event)." Containment vessel contains one open
cooling water sys Insp is performed during each startup
CROUSE, R. P. Toledo Edison Co 81/01/05 12pp 07486 214

B101280348 Forwards revision to 001125 response to IE Bulletin 80-06,
"Engineered Safety Feature (ESF) Reset Controls " Valves
which were not tested have safety feature actuation sys
logic identical to valves which were tested
CROUSE, R. P. Toledo Edison Co 81/01/07 5pp 07598 052

B101280348 Forwards revision to 001125 response to IE Bulletin 80-06,
"Engineered Safety Feature (ESF) Reset Controls " Valves
which were not tested have safety feature actuation sys
logic identical to valves which were tested
CROUSE, R. P. Toledo Edison Co 01/01/09 5pp

B101300551 Ack receipt of 810109 ltr informing NRC of steps taken to
correct violation noted in IE Insp Rept 50-346/80-30
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support
Branch 81/01/21 1p 07585 250

--B101300554 Responds to NRC 801219 ltr re violations noted in IE Insp
Rept 50-346/80-30 Corrective actions mod added requiring
brush recorder chart speed to be checked prior to control
rod drop test
CROUSE, R. P. Toledo Edison Co 81/01/07 3pp 07585 251

B101300566 Ack receipt of 801110 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-346/80-25
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support
Branch 81/01/21 1p 07586 324

--B101300571 Responds to NRC 801015 ltr re violations noted in IE Insp
Rept 50-346/80-25 Corrective actions current revisions of
operating procedures will be used
CROUSE, R. P. Toledo Edison Co. 80/11/10 2pp 07586 325

R Periodic operating reports & related correspondence

B101130521 Forwards monthly operating rept for Dec 1980.
MURRAY, T. D. Toledo Edison Co 81/01/00 1p 07454 130.

--B101130526 Monthly operating rept for Dec 1980
BARBOUR, B. Toledo Edison Co 81/01/08 3pp 07454 131

9 Reportable occurrences, LERs & related correspondence

B101060667 Forwards LER 80-006/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/02 1p 07395 050

--B101060680 LER 80-086/03L-0 on 801203, while performing BT 9030.12,
alligator clip slipped off terminal studs 3 & 4 causing
short circuit. Caused by design error. BT 9030.12
modified & F101 fuse replaced.
WERNER, B. J. Toledo Edison Co 81/01/02 3pp 07395 051.

B101060685 Forwards LER 80-089/03L-0.
MURRAY, T. D. Toledo Edison Co. 81/01/02 1p 07395 045.

--B101060692 LER 80-089/03L-0 on 801203, following reactor trip, RCB sample
revealed dose equivalent 1-131 level was greater than Tech
Specs. Caused by gas leakage through fuel cladding. Levels
monitored to ensure that gas decayed to below limits.
ESHELMAN, O., BYOTZ, J. Toledo Edison Co 81/01/02 4p.
07395 046

B101060698 Forwards LER 80-087/03L-0.
MURRAY, T. D. Toledo Edison Co. 81/01/02 1p 07395 038.

--B101060705 LER 80-087/03L-0 on 801206, while troubleshooting, control
room operator could not stroke valve CV5006 Valve declared
inoperable. Cause unknown. Corrective action will be conducted
under maint work order IC-B14-80 during next outage.
ISLEY, T. Toledo Edison Co 81/01/02 2pp 07395 039

B101060733 Forwards LER 80-069/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/02 1p 07395 041

--B101060745 LER 80-068/03L-0 on 801205, while troubleshooting for gro
problems in safety features actuation sys channel 3 cabinet.
Station experienced channel 1/3 simultaneous actuation of
levels 1, 2, 3 & 5 Caused by component failure PS-07 replaced
ISLEY, T. Toledo Edison Co 81/01/02 3pp 07395 042

B101060749 Forwards LER 80-090/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/02 1p 07395 035.

--B101060757 LER 80-090/03L-0 on 801205, during surveillance testing,
setpoint for borated water storage tank low level bistables
BA312 & BA307 found out of tolerance Caused by component
failure Bistables resistor
ISLEY, T. Toledo Edison Co 81/01/02 2pp 07395 036

B101130415 Forwards LER 80-091/01T-0
MURRAY, T. D. Toledo Edison Co 81/01/06 1p 07454 052

--B101130417 LER 80-091/01T-0 on 801223, during analysis per IE Bulletin
80-11, design for block wall between control room & stairway
A3-1 found to be less conservative than assumed in FSAR
Caused by outdated analytical const methods
HEMBEL, C. Toledo Edison Co 81/01/06 3pp 07454 053

B101220424 Forwards LER 80-092/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/16 1p 07505 193

--B101220429 LER 80-092/03L-0 on 001219, isolation valve from main steam
line to auxiliary feed pump turbine failed to close
unregulated low pressure Caused by failed touch relay R1
New relay installed
FRONHE, R. Toledo Edison Co 81/01/16 2pp 07505 194

B101220435 Forwards LER 80-093/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/16 1p 07505 196

--B101220440 LER 80-093/03L-0 on 801219, demineralized water contained
isolation valve DM66310 did not close in required time
Caused by dump solenoid orifice too small to allow adequate
bleedoff flow Solenoid to be replaced
TRAUTMAN, D. Toledo Edison Co 81/01/16 2pp 07505 197

B101270689 Forwards LER 81-001/01T-0
MURRAY, T. D. Toledo Edison Co 81/01/20 1p 07545 228

--B101270701 LER 81-001/01T-0 on 810107, analysis determined that
reportable condition had existed on 801204 when several pipe
supports on fuel lines to emergency diesel generators found
disassembled Caused by outside contractor personnel error
DIETERICH, M. Toledo Edison Co. 81/01/20 3pp 07545 229

B101270634 Forwards LER 80-094/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/21 1p 07546 336

--B101270636 LER 80-094/03L-0 on 801226, data from test performed on
auxiliary feed pump 1-2 indicated high bearing temp on
turbine outboard bearing Caused by low oil level Procedures
modified per M-957B to provide direction on oil levels
JOHNSON, J. Toledo Edison Co 81/01/21 3pp 07546 337

V Operator Examinations

B101060473 Responds to NUREG-0737 Util Working w/OH State Univ on
feasibility evaluation of long-term program to phase out
need for shift technical advisor Commitment supersedes all
previous commitments
CROUSE, R. P. Toledo Edison Co 80/12/30 17pp.

BUCKET 50-348 JOSEPH H. FARLEY NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

B101260358 Forwards proposed changes to Table 2 3-10 of FSAR, reflect
current instrumentation on meteorological tower Proposed
change will be incorporated into next amend to FSAR
CLAYTON, F. L. Alabama Power Co 81/01/20 3pp 07535 142.

B10102 & by applicants as part of FSAR
EISENHUT.D.G. Division of Licensing 80/11/13 2pp 07432 243

B101140822 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open items encl 4/0 encl
EISENHUT.D.G. Division of Licensing 80/11/24 3pp 07461 013

B101140201 Requests that encl facility emergency planning info be made publicly available 4/0 encl
SOUDEB J.L. Division of Rules and Records 80/12/31 1p
07461 263

G. Adjudicatory correspondence

B101100507 Forwards revised order for mod of license, correcting refs in B00829 order. Hearing date also revised
EISENHUT.D.G. Division of Licensing 80/09/19 3pp. 07443 238

--B101100595 Revised order attending License NPF-2 info requested by IE Bulletin 79-018 must be submitted to IE by 801101
EISENHUT.D.G. Division of Licensing 80/09/19. 6pp. 07443 260

J. Insurance & indemnity information

B101070601 Forwards Endorsement 4 to NELA Binder FD-62
FIELDER, J. Marsh & McLennan, Inc., H & M Nuclear Consultants, Inc.
Div. 80/12/30 2pp 07442 071

B101220595 Forwards Endorsements 30 & 31 to NELA Policy NF-238
JUCA, J.R. Marsh & McLennan, Inc., H & M Nuclear Consultants, Inc., Div.
81/01/16. 4pp 07503 058

P. Operating license stage documents & correspondence

B101100587 Forwards revised order for mod of license, correcting refs in B00829 order. Hearing date also revised
EISENHUT.D.G. Division of Licensing. 80/09/19 3pp 07443 258

--B101100595 Revised order attending License NPF-2 info requested by IE Bulletin 79-018 must be submitted to IE by 801101
EISENHUT.D.G. Division of Licensing. 80/09/19. 6pp. 07443 260

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS license amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT.D.G. Division of Licensing 80/11/20 1p 07443 274

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-9 & 7-b & d-17 to STS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp 07443 278.

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports."
EISENHUT.D.G. Division of Licensing. 80/11/26. 8pp

B101120228 Forwards Amend 17 to License NPF-2, safety evaluation & notice of issuance & availability
VARGA, S.A. Operating Reactors Branch 1 80/12/10 3pp. 07447 041

--B101120252 Amend 17 to License NPF-2, revising administrative controls Tech Specs for high radiation area entry & adding feedwater control sys bypass valve response times to Tech Specs.
VARGA, S.A. Operating Reactors Branch 1. 80/12/10 10pp
07447 344

--B101120235 Safety evaluation supporting Amend 17 to License NPF-2
* Office of Nuclear Reactor Regulation, Director. 80/12/10 3pp.
07447 054.

--B101120239 Notice of issuance & availability of Amend 17 to License NPF-2
* Office of Nuclear Reactor Regulation, Director 80/12/10 1p
07447 059

B101140831 Forwards request for addl info re calculations of fuel rod bow penalty.
VARGA, S.A. Operating Reactors Branch 1 80/12/12 3pp. 07461 327

B101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT.D.G. Division of Licensing 80/12/15 13pp 07489 0

B101090021 Forwards cross ref between Category A model spec provisions & sections in existing & proposed B01215 Tech Specs which show compliance Proposed Tech Spec Section 3.4.6 & 3 not required License condition re iodine monitoring encl
CLAYTON, F.L. Alabama Power Co 80/12/23 4pp 07379 340

B101140507 Forwards response to NRC B01212 request for addl info re facility rod bow penalty. Fuel rod bowing reduces value of BWI ratio. Sufficient credit exists to offset reduction.
CLAYTON, F.L. Alabama Power Co 81/01/05 9pp 07462 064

B101210402 Discusses containment purge valve operability at facility including use of solenoid valves & air actuators. Interim use of solenoid valves is acceptable. Actuator seal kits will be replaced on regular basis
CLAYTON, F.L. Alabama Power Co 81/01/05 2pp. 07489 080

B101220359 Forwards proposed changes to Tech Specs 3.4.9 & 4.4.9 re backup & cooldown limit curves necessary as result of Capsule Y analysis. Plant Operations Review Committee & Nuclear Operations Review Board safety evaluation encl
CLAYTON, F.L. Alabama Power Co 81/01/09 2pp 07496 358

--B101220363 Safety evaluation supporting proposed changes to Tech Specs 3.4.9 & 4.4.9 re startup & cooldown limit curves
* Alabama Power Co 81/01/09 2pp 07496 360

--B101220365 Proposed changes to Tech Specs 3.4.9 & 4.4.9 re startup & cooldown limit curves
* Alabama Power Co 81/01/09 13pp 07497 001

B101260360 Forwards response to NUREG-0737, in response to NRC B0111r items requiring followup by Unit 2 & corresponding SER are included in action item for requirement.
CLAYTON, F.L. Alabama Power Co 81/01/14 9pp. 07529 147

B101230428 Forwards proprietary & nonproprietary versions of low pressure turbine disc info for facility. Proprietary printout withheld from 10CFR2 7701 Affidavit & application for withholding encl
CLAYTON, F.L. Alabama Power Co 81/01/20 29pp 07308 001

B101270596 Comments on draft SER re auxiliary feedwater control s. Auxiliary feedwater sys design will be modified to remove power source dependence
CLAYTON, F.L. Alabama Power Co 81/01/22 2pp. 07543 016

B101270750 Submits info in clarification of multiple rod drop analyzer until B01212 ltr & B01116 telcon. Outlines policy to be implemented when Unit 1 returned to power & subsequent to exceeding 5% power for Unit 2
CLAYTON, F.L. Alabama Power Co 81/01/22 1p. 07548 045.

B101270514 Forwards WCAP-BB10, "Reactor Vessel Radiation Program" WCAP-9717, "Analysis of Capsule Y From AL Power Co Farley Unit 1 Reactor Vessel Radiation Surveillance Program," in response to NRC request.
CLAYTON, F.L. Alabama Power Co 81/01/23 1p. 07541 009

--B101270519 "Reactor Vessel Radiation Surveillance Program" DAVIDSON, J.A., PHILLIPS, J.H., YAMCHIKO, S.E. Westinghouse Electric Corp. WCAP-BB10 76/12/31 40pp. 07541 010.

--B101270526 "Analysis of Capsule Y From AL Power Co Farley Unit 1 Reactor Vessel Radiation Surveillance Program" YAMCHIKO, S.E., ANDERSON, S.L., KAISER, W.T. Westinghouse Electric Corp. WCAP-9717 80/06/30 78pp. 07541 050

O. Inspection reports, IE Bulletins & correspondence

B101290586 Submits amended response to IE Insp Repts 50-348/80-16 50-364/80-19. Contact made w/vendors to determine required installation torque for concrete expansion anchor bolts.
CLAYTON, F.L. Alabama Power Co 80/10/07 6pp. 07567 224.

8101220419 Forwards IE Insp Repts 50-348/80-35 & 50-364/80-46 on 801001-31 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/12/04 2pp 07500 213

--8101220427 IE Insp Repts 50-348/80-35 & 50-364/80-46 on 801001-31 No noncompliance noted Major areas inspected plant tours, pre-operational testing, open items & task action items
BRADFORD, W H, MURPHY, J P, MARTIN, R D Region 2, Atlanta, Office of the Director 80/12/05 11pp 07500 215

8101060239 Forwards IE Info Notice 00-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown - No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07391 345

8101100308 Ack receipt of 801210 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/80-31 & 50-364/80-42
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/22 1p 07443 313

--8101100319 Responds to NRC 801114 ltr re violations noted in IE Insp Repts 50-348/80-31 & 50-364/80-42 Corrective actions: comprehensive QA audit of fire protection const program initiated No proprietary info
CLAYTON, F L Alabama Power Co 80/12/10 2pp 07443 314

--8101100331 Forwards IE Insp Repts 50-348/80-31 & 50-364/80-42 on 801014-17 & notice of deviation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/14 2pp 07443 316

--8101100337 Notice of deviation from insp on 801014-17.
* Region 2, Atlanta, Office of the Director, 80/11/12 1p 07443 318

--8101100343 IE Insp Repts 50-348/80-31 & 50-364/80-42 on 801014-17 Noncompliance noted Inadequate fire protection QA program
MILLER, H II Region 2, Atlanta, Office of the Director
CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/12 7pp 07443 319

8101210226 Requests description of insps on turbine discs NRC is concerned that low pressure turbine disc cracks might result in rupture of more turbine discs Info should be provided 30 days prior to restart
VAROA, B A Operating Reactors Branch 1 81/01/05 2pp 07491 358

8101290363 Requests extension until 810115 to respond to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)" Extension necessitated by licensing & refueling activities
CLAYTON, F L Alabama Power Co 81/01/05 1p 07575 129

8101140554 Forwards "Low Pressure Disc Ultrasonic Insp Rept." in response to NRC 810105 request for results of insp conducted at facility Cracks were discovered in some discs. Refurbished rotors will be installed.
CLAYTON, F L Alabama Power Co. 81/01/12 2pp 07461 350

--8101140559 "Low Pressure Disc Ultrasonic Insp Rept."
* Alabama Power Co 81/01/08 13pp 07461 352

8101270406 Summarizes 810109 conference call re licensee evaluation of IE Bulletin 80-11, "Masonry Wall Design" Licensee should be requested to provide description of deficiencies, Bechtel wall evaluation & commitment to modify walls
REEVES, E Operating Reactors Branch 1, KINTNER, L Operating Reactors Branch 2, 81/01/13 3pp 07546 181

8101290334 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)" Bvc water sys is open sys supplying cooling water inside containment.
CLAYTON, F L Alabama Power Co. 81/01/15 8pp 07575 220

8101290728 Responds to IE Bulletin 80-11, "Masonry Wall Design." Required vertical reinforcing missing from both unit walls. Well w/safety-related equipment should conform w/requirements before criticality.
CLAYTON, F L Alabama Power Co. 81/01/15 2pp 07309 001

--8101210521 Monthly operating rept for Dec 1980
HAIRSTON, W G Alabama Power Co 81/01/01 7pp 07490 203

S Reportable occurrences, LERs & related correspondence

8101130502 Forwards LER 80-077/03L-0.
CLAYTON, F L Alabama Power Co 81/01/06 1p 07453 336

--8101130508 LER 80-077/03L-0 on 801128, loop suction valve for A train RHR closed, resulting in A train RHR being inoperable Caused by dirty contacts on circuitry card for pressure transmitter Card cleaned
HAIRSTON, W G Alabama Power Co. 81/01/06 1p 07453 337

8101300580 80: on 801227, one tube in steam generator IC satisfactorily plugged Defective tube located by pressurizing secondary side & performing visual insp for leaks tube plugging reported per Tech Spec 4.4.5.5 a
CLAYTON, F L Alabama Power Co 81/01/12 1p 07582 363

8101210426 Forwards LER 80-070/03L-0
CLAYTON, F L Alabama Power Co 81/01/13 1p 07493 146

--8101210430 LER 80-070/03L-0 on 801207, fusible links found missing Fire dampers between 139-ft & 121-ft penetration rooms Cause unknown Fusible links installed & dampers operational
HAIRSTON, W G Alabama Power Co 81/01/13 1p 07493 147

8101280268 Forwards LERs 80-077/03L-0 & 80-038/03L-1
CLAYTON, F L Alabama Power Co 81/01/23 1p 07557 144

--8101280291 LER 80-058/03L-1 on 801007, per discussion w/NRC, three containment tendon surveillance revealed tendon lift-off forces & record discrepancies Spring 1901 surveillance to be performed Rams calibr is suspected as primary cause
HAIRSTON, W G Alabama Power Co 81/01/23 2pp 07557 145

--8101280295 LER 80-074/03L-0 on 801108, main steam safety valve 801110/108 failed to meet Tech Spec 11F1 setting requirements Caused by setpoint drift Valve adjusted
HAIRSTON, W G Alabama Power Co 81/01/23 1p 07557 147

V Operator Examinations

8101260340 Forwards response to AUREO-0737, in response to NRC 0010: ltr items requiring followup by Unit 2 & corresponding SER are included in action item for requirement
CLAYTON, F L Alabama Power Co 81/01/14 99pp 07525 147

DOCKET 50-352 LIPERICK GENERAL INFORMATION UNIT 1

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarded summary of 801112 meeting re implementation of guidance for Unresolved Safety Issues A-14, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHAUER, D O Division of Licensing, 80/11/26 8pp

8101190505 Ltr to all OWR applicants for OL re BWR scram discharge safety evaluation & requirements Repl specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge val enc1
REDESEB, R L Assistant Director for Licensing 80/12/22 2pp

--8101190514 Forwards generic safety evaluation re BWR scram discharge sys Review identified two addl requirements to those proposed by owners group re scram discharge val designs Rept should be transmitted to license applicants.
CHECK, P S Assistant Director for Plant Systems 80/12/01 07183 031

8101200157 Summary of 801210 meeting w/Mark II owners re status of generic improved chugging load model thwns requested to justify delay in program & investigate alternatives
ANDERSON, C J Generic Issues Branch 80/12/22 4pp 07486 14

8101140955 Summary of Dec 1980 meeting w/Mark II owners group, OE, O MIT, B&W, Orchtel & Ebasco Svcs, Inc re suppression pool temp limits List of attendees & handouts enc1
SU, T M Generic Issues Branch 80/12/30 41pp 07457 063

B101160237 Requests substantial of risk assessment study final rept for
NRC to commence review of FSAR Areas for discussion should
include emergency preparedness re special institutions &
cooling water supply
TEDESCO, R. L. Assistant Director for Licensing 81/01/05 2pp
07471 161

D:01306037 Summary of 801209 meeting w/uttl in Pottstown, PA re risk
evaluation study for facility
SELLS, D. Licensing Branch 2 81/01/14 4pp. 07583 001.

B101300144 Requests review of Amend 24 to PSAR
SELLS, D. Licensing Branch 2 81/01/14. 1p 07582 122

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR
EISENHUT, D. G. Division of Licensing 00/11/13 2pp

G Adjudicatory correspondence

B101160211 Forwards City Council of Philadelphia 000529 Resolution 169
demanding const. on facility be halted CLs should be refused
due to water shortage & lack of safety guarantee
COHEN, D. Philadelphia, PA 81/01/08 3pp 07470 063.

H General correspondence

B101060909 Responds to 801215 ltr re preparation of EIS for facility
Applicants for CL must submit environ rept prior to OL
issuance
HANSLER, O. M. Assistant Director for Licensing 80/12/16. 2pp
07401.085

B101050059 Expresses gratitude for hearing arranged onsite & urges Div
of Licensing not to grant license as plant constitutes
health & safety hazard Editorials encl
ANTHONY, R. L. Friends of the Earth. 80/12/23 4pp 07376 282

B101070621 Responds to 801029 ltr re leakage of river water into unit
containment Long-term generic actions described in encl IE
Bulletin 80-24 will be taken to preclude recurrence at other
plants
EISENHUT, D. G. Division of Licensing. 80/12/23 1p. 07414 157

B101070372 Requests that OL be denied
WEILER, J. Affiliation Unknown 81/01/01 1p 07309 001

B101306021 Responds to 801121 ltr forwarding B Irvine & J Williams
800528 ltr opposing Point Pleasant Diversion Project pumping
station & operation of facilities Responsibility for DE
River water matters is vested in OE River Basin Commission
BIRKS, W. J. Office of the Executive Director for Operations
81/01/06 3pp 07579 310.

--8101300033 Forwards J Williams & B Irvine 800528 ltr opposing operation
of facilities, originally forwarded by 800702 ltr Requests
response
WILLIAMS, H. A. Senate. 80/11/21. 2pp. 07579.323

I Financial information

B012160144 Forwards SEC Form 10-Q, Quarterly Financial Rept & supporting
mgt comments, in response to NRC 790921, 1109 & 800811
requests for info re significant financial developments
affecting utility in respect proceeding
CONDOU, V. H. General Public Utilities 80/11/26. 3pp

--B012160154 Quarterly Financial Rept Sept 1980 & supporting mgt
comments
* General Public Utilities 80/11/14 44pp.

Q Inspection reports, IE Bulletins & correspondence

B101070398 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on
Terry Turbine Steam Inlet Flange" No written response
required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/11/26 1p 07414 080

B101050118 Forwards IE Info Notice 80-43, "Failures of Con
Level Monitor for Scram Discharge Val at Dresden Unit 2
response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/05 1p 07376 335

B101050123 Forwards IE Info Notice 80-45, "Potential Failure
Backup Manual Scram Capability" No response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/17 1p 07397 332

B101070055 Forwards Suppl 4 to IE Bulletin 80-17, "Failure
Control Rods to Fully Insert During Scram at BWR." No
written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/18 1p 07414 029.

B101190820 Forwards IE Bulletin 80-25, "Operating Problems
Rock Safety-Relief Valves at BWRs." No response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/19 1p 07469 317

B101210210 Responds to IE Bulletin 80-23, "Failures of Bol
Mfg by Velcor Engineering Corp." No Velcor valves used i
safety-related function OE review of NSSS sys has not be
completed Response will be delayed until 810228
KEMPER, J. B. Philadelphia Electric Co 80/12/26. 1p.

S. Reportable occurrences, LERs & related correspondence

B101070369 Final deficiency rept, originally reported on 80
bolts, nuts & studs obtained from unapproved sources Cause
by lack of proper QA review. Unacceptable bolting metl to
replaced
KEMPER, J. B. Philadelphia Electric Co 80/12/30 5pp.

B101230434 Deficiency Rept 29 re metal potential loss of a
grounding of flexible metal conduit, preventing reactor
protection sys proper operation. OE rept encl. Flexible
conduit to be properly grounded per OE instructions.
KEMPER, J. B. Philadelphia Electric Co 81/01/13. 3pp.

B101260500 Interim deficiency rept re Deficiency 27, improv
reactor pressure vessel safe ends, initially reported 801
OE evaluating weld acceptability. Final rept will be
submitted by 810415
KEMPER, T. B. Philadelphia Electric Co. 81/01/16. 2pp.

T Hearing transcripts on non-entitlement matters

B101070324 Forwards 801209 transcripts of public meeting &
technical presentation of facility risk assessment. Also
forwards 801209 videotape re technical presentation.
SELLS, D. E. Operating Reactors Branch 2. 81/01/05. 3pp

--B101070327 Transcript of 801209 afternoon technical pres
Pottstown, PA Presente facility risk assessment study b
util Pg 1-123.
* Commissioners 80/12/09 127pp 07411:190.

--B101070332 Transcript of 801209 evening public meeting
Pg 1-122.
* Commissioners. 80/12/09. 124pp. 07412:020.

DOCKET 90-353 LIMERICK GENERATING STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants
summary of B01112 meeting re implementation of guidance
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Laminar Tearing on Component Supports."
EISENHUT, D. G. Division of Licensing 80/11/26. 8pp.

B101200157 Summary of 801210 meeting w/Mark II owners re s
improved chugging load model. Owners requested to
justify delay in program & investigate alternatives.
ANDERSON, C. J. Generic Issues Branch. 80/12/22. 4pp.

B101140955 Summary of Dec 1980 meeting w/Mark II owners gr
MIT, S&M, Bachtel & Ebasco Svcs, Inc re suppression pool te
limits. List of attendees & handouts encl.
SU, T. H. Generic Issues Branch. 80/12/30 41pp. 07457

37 Requests submitted of risk assessment study final rept for
commence review of FSAR Areas for discussion should
emergency preparedness re special institutions &
ing water supply
O.R.L. Assistant Director for Licensing. 81/01/05 2pp
161.

37 Summary of 801209 meeting w/util in Pottstown, PA re risk
tion study for facility
0 Licensing Branch 2 81/01/14 4pp 07583 001

44 Requests review of Amend 24 to PSAR
0. Licensing Branch 2 81/01/14 1p 07502 122

ity, medical, emergency & fire protection plans

87 Ltr to all licensees of operating reactor plants, CP holders
applicants. Revised radiological emergency response
must be submitted by licensees within 60 days of
& by applicants as part of FSAR.
UT, D.G. Division of Licensing 80/11/13 2pp.

icatory correspondence

11 Forwards City Council of Philadelphia 800529 Resolution 169
inp cahst on facility be halted OLs should be refused
water shortage & lack of safety guarantee
D. Philadelphia, PA. 81/01/08. 5pp 07470 063

al correspondence

09 Responds to 801215 ltr re preparation of E18 for facility.
ents for OL must submit environ rept prior to OL
ce
R.Q.M. Assistant Director for Licensing 80/12/16 2pp
086

59 Expresses gratitude for hearing arranged onsite & urges Div
ensing not to grant license as plant constitutes
& safety hazard Editorials encl
Y.R.L. Friends of the Earth. 80/12/23 6pp. 07376 282

72 Requests that BL be denied
J Affiliation Unknown 81/01/01 1p. 07309 001

21 Responds to 801121 ltr forwarding B Irvine & J Williams
ltr appealing Point Pleasant Diversion Project pumping
n & operation of facilities. Responsibility for OE
water matters is vested in DE River Basin Commission
W.J. Office of the Executive Director for Operations
06. 5pp 07579 310

0033 Forwards J Williams & B Irvine 800320 ltr opposing operation
ilities, originally forwarded by 800707 ltr. Requests
ense
JAMS, H.A. Senate. 00/11/21. 2pp. 07579 323

cial information

44 Forwards SEC Form 10-0. Quarterly Financial Rept & supporting
ments. in response to NRC 790921, 1109 & 800811
ts for info re significant financial developments
ing utils in restart proceeding
V.H. General Public Utilities. 80/11/26. 3pp

0154 Quarterly Financial Rept Sept 1980 & supporting mgt
nts.
sheafal Public Utilities. 80/11/14 44pp

ction reports, IE Bulletins & correspondence

98 Forwards Suppl 1 to IE Info Notice 00-29, "Broken Studs on
Turbine Steam Inlet Flange." No written response
id
B.H. Region 1, Philadelphia, Office of the Director
26. 1p. 07414 080.

18 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Monitor for Scram Discharge Vol at Dresden Unit 2 " No
se required.
B.H. Region 1, Philadelphia, Office of the Director.
05 1p. 07376 335

23 Forwards IE Info Notice 80-49, "Potential Failure of BWR
Manual Scram Capability " No response required
B.H. Region 1, Philadelphia, Office of the Director
17. 1p. 07397 332

8101070055 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 185
Control Rods to Fully Insert During Scram at BWR " No
Written response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director
80/12/18. 1p 07414 023

8101150800 Forwards IE Bulletin 80-25, "Operating Problems W/Target
Rock Safety-Relief Valves at BWRs " No response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director
80/12/19 1p 07465 317

8101210210 Responds to IE Bulletin 00-23, "Failures of Solenoid Valves
Hfg by Valcor Engineering Corp." No Valcor valves used in
safety-related function GE review of NSSG sys has not been
completed Response will be delayed until 810220.
KEMPER, J.S. Philadelphia Electric Co 80/12/26 1p 07468 329

S Reportable occurrences, LEAs & related correspondence

8101070359 Final deficiency rept, originally reported on 800826, re ASME
bolts, nuts & studs obtained from unapproved sources Caused
by lack of proper QA review Unacceptable bolting matl to be
replaced
KEMPNER, J.B. Philadelphia Electric Co 00/12/30 5pp. 07414 127

8101230434 Deficiency Rept 29 re metal potential loss of solid metallic
grounding of flexible metal conduit, preventing reactor
protection sys proper operation GE rept encl Flexible
conduit to be properly grounded per OE instructions
KEMPER, J.B. Philadelphia Electric Co. 81/01/13 3pp. 07308 001

8101260900 Interim deficiency Rept re Deficiency 27, improper welding of
reactor pressure vessel safe ends, initially reported 801210.
GE evaluating weld acceptability. Final rept will be
submitted by 810415
KEMPER, J.B. Philadelphia Electric Co. 81/01/16 2pp. 07308 001

T Hearing transcripts on non-antitrust matters

8101070324 Forwards 801209 transcripts of public meeting & util
technical presentation of facility risk assessment Also
forwards 801209 viewgraphs re technical presentation
SELLS, D.E. Operating Reactors Branch 2 01/01/05 3pp. 07411 187

--8101070327 Transcript of 801209 afternoon technical presentation in
Pottstown, PA Presents facility risk assessment study by
util Pp 1-125
* Commissioners 80/12/09 127pp 07411 190

--8101070332 Transcript of 801209 evening public meeting in Pottstown, PA
Pp 1-122
* Commissioners 80/12/09 124pp 07412 020

DOCKET 50-334 HOPE CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issues A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D.G. Division of Licensing 80/11/26 8pp

8101190794 Forwards summary of 801210 meeting w/util re util mpt
reorganization List of attendees encl.
CARLEIGH, R.I. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/12/23 3pp 07473 078.

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR
EISENHUT, D.G. Division of Licensing. 00/11/13 2pp

J Insurance & indemnity information

8101270738 Forwards Endorsement 42 to HELIA Policy NF-230 &
Endorsement 34 to MAELU Policy NF-90
CORREA, H.A. Marsh & McLennan, Inc. H & M Nuclear Consultants, Inc
Div 81/01/22 3pp 07548 050

G Inspection reports, IE Bulletins & correspondence

B101270779 Ack receipt of B01014 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/77-04
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/23 1p 07368 335

--B101290781 Suppl response to NRC 500321 ltr re violations noted in IE Insp Rept 50-354/77-04 Corrective actions weld buildups being evaluated to determine required measures
MARTIN, T J Public Service Electric & Gas Co of New Jersey 80/10/14 1p 07563 336

B101070396 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Tocco Turbine Steam Inlet Flange " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 083

B101050121 Forwards IE Info Notice 80-43, "Failures of Continuous Meter Level Monitor for Boreen Discharge Vol at Oresden Unit 2 " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/03 1p 07376 339

B101060145 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07391 265

B101070050 Forwards Suppl 4 to IE Bulletin 00-17, "Failure of 76 of 105 Control Rods to Fully Insert During Scram at BWR " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/18 1p 07414 017

B101150795 Forwards IE Bulletin 00-25, "Operating Problems W/Target Rod Safety-Relief Valves at BWRs " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/19 1p 07465 312

R Periodic operating reports & related correspondence

B012190521 Forwards rept entitled "Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on OE River"
MITTL, R L Public Service Electric & Gas Co of New Jersey 80/12/15 2pp 07285 322

--B012190528 "Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on OE River "
Public Service Electric & Gas Co. of New Jersey 80/11/30, 56pp 07285 324

E Reportable occurrences, LERs & related correspondence

B101050491 Ack receipt of util B01024 interim deficiency rept re primary containment relief valves at facility
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/07 1p 07387 279

--B101050497 Interim deficiency rept re primary containment relief valves at facility, initially reported on B00326 Expected conclusion of investigation has been postponed until B01203
MARTIN, T J Public Service Electric & Gas Co. of New Jersey 80/10/24 2pp 07387 276

B101060400 Significant deficiency rept, originally reported on B00326, re primary containment vacuum relief valves Concludes that sub j bolting is designed within appropriate stress allowable & conforms w/spec 10855-M-150101
MARTIN, T J Public Service Electric & Gas Co. of New Jersey, 80/12/03 2pp 07396 316

BUCKET 50-355 MOPE CREEK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports "
EISENHUT, D O Division of Licensing 80/11/26 0pp

B101190794 Forwards summary of B01210 meeting w/util re util mgt reorganization List of attendees encl
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch, 80/12/23 3pp

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

J Insurance & indemnity information

B101270738 Forwards Endorsement 42 to NELIA Policy NF-230 & Endorsement 34 to MALLU Policy MF-90
CORREA, M A Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 81/01/22 3pp

D Inspection reports, IE Bulletins & correspondence

B101070396 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 083

B101050121 Forwards IE Info Notice 80-43, "Failures of Continuous Meter Level Monitor for Boreen Discharge Vol at Oresden Unit 2 " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/03 1p 07376 339

B101060145 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07391 265

B101070050 Forwards Suppl 4 to IE Bulletin 00-17, "Failure of 76 of 105 Control Rods to Fully Insert During Scram at BWR " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/18 1p 07414 017

B101150795 Forwards IE Bulletin 00-25, "Operating Problems W/Target Rod Safety-Relief Valves at BWRs " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/19 1p 07465 312

R Periodic operating reports & related correspondence

B012190521 Forwards rept entitled "Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on OE River "
MITTL, R L Public Service Electric & Gas Co. of New Jersey 80/12/15 2pp 07285 322

--B012190528 "Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on OE River, "
Public Service Electric & Gas Co. of New Jersey 80/11/30, 56pp 07285 324

B Reportable occurrences, LERs & related correspondence

B101050491 Ack receipt of util B01024 interim deficiency rept re primary containment relief valves at facility
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/07 1p 07387 279

--B101050497 Interim deficiency rept re primary containment relief valves at facility, initially reported on B00326 Expected conclusion of investigation has been postponed until B01203
MARTIN, T J Public Service Electric & Gas Co. of New Jersey 80/10/24 2pp 07387 276

BUCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR

D Inspection reports, IE Bulletins & correspondence

B101160368 Forwards IE Insp Repts 50-151/80-03 & 50-356/80-03 on B01117-19 & notice of violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Sup Branch, 80/12/10 2pp 07470 352

--B101160374 Notice of violation from Insp on B01117-19, HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/09, 1p 07470 354.

--B01160382 IE Insp Repts 90-151/80-03 & 90-756/00-03 on 801117-19
Noncompliance noted nuclear reactor committee meetings
exceeded specified frequency
RIGGWAY, K R. BOONE, J M. Region 3, Chicago, Office of the
Director B0YD, D C. Region 3, Chicago, Reactor Operations Nuclear
Support Branch 80/12/07 5pp 07470 359

CRCKET 90-350 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B008110130 Notification of B00806-07 meeting w/OE owners group, LaBalle
& Zimmer owners group representatives & GE in Bethesda, MD
for briefing on basis for symptom-oriented guidelines &
applicability in evaluating event procedures.
SIEGEL, B L. Procedures & Test Review Branch 80/07/28 2pp
06278 117

B01220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O. Division of Licensing. 80/11/26 0pp.

B01050549 Confirms B01216 meeting in Cincinnati, OH to discuss
evaluation of utility regulatory performance re facility
KEPPLER, J O. Region 3, Chicago, Office of the Director 80/12/10
1p 07387 177

B01190503 Ltr to all BWR applicants for OL re BWR steam discharge sys
safety evaluation & requirements Rept specifying acceptable
basis for continued BWR plant operation & design criteria
for steam discharge vol encl.
TEDESCO, R L. Assistant Director for Licensing 80/12/22 2pp

--B01190514 Forwards generic safety evaluation re BWR steam discharge
sys Review identified two addl requirements to those
proposed by owners group re steam discharge vol designs Rept.
should be transmitted to license applicants
CHECK, P S. Assistant Director for Plant Systems 80/12/01 2pp
07183 001

B01200157 Summary of B01210 meeting w/Mark 11 owners re status of
generic improved chugging load model. Owners requested to
justify delay in program & investigate alternatives
ANDERSON, C J. Generic Issues Branch 80/12/22 4pp 07486 143

B01140955 Summary of Dec 1980 meeting w/Mark 11 owners group, CE, ENL,
MIT, S&W, Bechtel & Babcock & Wilcox, Inc re suppression pool temp
limits. List of attendees & handouts encl.
BU, T M. Generic Issues Branch 80/12/30 41pp

B01200197 Advises of scheduled B11030 fuel load date, per NRC telcon
BORGSMANN, E A. Cincinnati Gas & Electric Co. 81/01/07 1p.
07445:261.

B01140272 Forwards proprietary & nonproprietary versions of "Environ
Qualification of Safety-Related Electrical Equipment," Vols
1-3 Affidavit for withholding encl. Proprietary info withheld
ref 10CFR2 7901
BORGSMANN, E A. Cincinnati Gas & Electric Co. 81/01/07. 4pp.
07537:164.

--B01140276 Nonproprietary version of "Environ Qualification of
Safety-Related Electrical Equipment," Vol 1-3
* Cincinnati Gas & Electric Co. 81/01/07. 1000pp. 07537 160.

B01210625 Forwards House Rept 96-1452, "Evaluating Nuclear Utility
Performance: NRC Oversight," W/o encl.
WEIDMANN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support
Branch. 81/01/08 1p 07407:249

B01270821 Forwards NRC position re toxic chemical traffic on US Route
52 near facility site. Position based on evaluation that
Revision 60 to FSAR is inadequate
TEDESCO, R L. Assistant Director for Licensing 81/01/14. 4pp.
07549:094

B01300602 Forwards request for addl info for NRC review of facility
water cleanup & condensate cleanup sys against Revision 1 of
Reg Guide 1.56, "Maint of Water Purity in BWRs."
TEDESCO, R L. Assistant Director for Licensing. 81/01/14. 3pp
07584 355

B01300751 Requests commitment to special low power test program for
facility to comply w/THI task action item 1 Q.1 PWR test re
simulated loss of ac power is feasible & should be
performed on BWRs
TEDESCO, R L. Assistant Director for Licensing. 81/01/14. 3pp
07587 032

B01270642 Forwards supplemental info re seismic qualification of
equipment
BERGMAN, J. E. A. Cincinnati Gas & Electric Co. 81/01/20 1p
07534 099

--B0127054b "Equipment Qualification"
* Sargent & Lundy, Inc. 81/01/20 375pp 07544 100

--B01270651 "Zimmer Seismic Qualification Review Team Evaluation/
Qualification Status Rept."
BROCATO, V J. MCCONAUGHY, W J. Nuclear Technology, Inc (Nutech)
CGE-03-144 80/12/10 29pp 07545 105

--B01270555 "Nuclear Safety-Related Equipment List for Zimmer Nuclear
Generating Station."
BROCATO, V J. MCCONAUGHY, W J. RICCARDELLA, P. Nuclear Technology,
Inc (Nutech) CGE-03-087 80/04/15 58pp 07545 134

F Security, medical, emergency & fire protection plans

B010690307 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B010102 & by applicants as part of FSAR
EISENHUT, D O. Division of Licensing 80/11/13. 2pp

B01070515 Releases public version of "Preliminary Evacuation Time
Study of Plume Exposure Emergency Planning Zone Around
WM Zimmer Nuclear Power Station, Unit 1."
FELTON, J H. Division of Rules and Records 80/12/01 1p
07309 001

--B01070529 Forwards public version of "Preliminary Evacuation Time
Study of Plume Exposure Emergency Planning Zone Around
WM Zimmer Nuclear Power Station, Unit 1."
FELTON, J H. Cincinnati Gas & Electric Co. 80/08/18 1p
07309 001

--B01070536 Public version of "Preliminary Evacuation Time Study of
Plume Exposure Emergency Planning Zone Around WM Zimmer
Nuclear Power Station, Unit 1."
* Stone & Webster Engineering Corp. 80/08/31 30pp 07309 001

O Adjudicatory correspondence

B01060913 Order granting applicant B01224 motion for extension until
810126 to file answers or objections to NRC B01209 second
interrogatories. NRC raised no objection
BECHTOLD, C. Atomic Safety and Licensing Board Panel 80/12/30
2pp 07401:090

B01230148 Order granting extension until 810120 to answer
interrogatories on Contention 13 intervenor Miami Valley
Power Project shall hand deliver answer & notify applicants
of identity of witnesses by telephone w/ Certificate of Svc
BECHTOLD, C. Atomic Safety and Licensing Board Panel 81/01/16
4pp 07512 022

B01290726 Answers of Miami Valley Power Project to applicant seventh
set of interrogatories re witnesses & decommissioning costs
Analysis of decommissioning & premature shutdown costs of
plants & certification of svc encl Related correspondence
FELDMAN, J H. Miami Valley Power Project 81/01/20 47pp
07567 117

B01280062 Forwards applicant responses to NRC second set of
interrogatories re evacuation time study. Offers to meet
w/ NRC to discuss emergency plan or any other questions.
CONNER, T B. Conner, Moore & Corber. 81/01/23 1p 07595 117

--B01280077 Response to NRC second second set of interrogatories re B&W
evacuation time study Prof qualifications & Certificate of
Svc encl.
WEISS, L S. Stone & Webster Engineering Corp. WEISS, L S.
Cincinnati Gas & Electric Co. 81/01/23 21pp. 07555:118

B01290740 Confirms agreement re potential witnesses R Estes & T Hernan
depositions to be given in Cincinnati, OH on 810204. Witness
prof qualifications & other documents to be provided. Related
correspondence
KETTERHAM, M J. Conner, Moore & Corber 81/01/27 2pp. 07567 340

B101070616 Forwards request for additional info to expedite public hearing. UG should provide detailed, itemized estimate of cost of constructing & installing items resulting from TMI accident.
TEDESCO, R L Assistant Director for Licensing 80/12/19 3pp
07419 315

B101290272 Forwards responses to financial questions per B01219 ltr
BORGMANN, E A Cincinnati Gas & Electric Co 81/01/26 7pp
07567 164

3. Inspection reports, IE Bulletins & correspondence

B101050289 Forwards IE Info Notice 80-38, "Cracking in Charging Pump
Casing Cladding." No response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/30
2pp 07389 268

B101060125 Forwards IE Circular 80-23, "Potential Defects in In Unit
Power Sys Emergency Generators." No written response
required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/31
1p 07397 335

B101060534 Forwards IE Info Notice 80-39, "Malfunction of Solenoid
Valves Mfg by Valcor Engineering Corp." No written response
is required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/31
2pp 07401 173

B101060356 Forwards IE Info Notice 80-41, "Failure of Swing Check
Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No
response required
KEPPLER, J G Region 3, Chicago, Office of the Director, 00/11/10
2pp 07392 076

B10120066 Forwards IE Insp Rept 50-398/80-23 on B01001-24. No
noncompliance noted
EISENHART, R F Region 3, Chicago, Reactor Operations Nuclear Support
Branch 81/11/13 2pp 07446 026

--B10120070 IE Insp Rept 50-398/80-23 on B01001-24. No noncompliance
noted. Major areas inspected previously identified items,
bulletin & circular followup & maint procedures review.
DANIELS, F T, GWYNN, T P, WERNICK, R F Region 3, Chicago, Office
of the Director, 80/11/10 5pp 07446 028

B101060497 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp." Written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/11/14
2pp 07391 226

B101090957 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for BWR Discharge Val at Oresden Unit 2." No
response required
KEPPLER, J G Region 3, Chicago, Office of the Director, 80/12/05
2pp 07390 327

B101290598 Forwards IE Insp Rept 50-398/80-24 on B01103-07, 12-14, 17-21,
24-26 & 28. No noncompliance noted
EISENHART, R F Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/12/16 2pp 07393 278

--B101290563 IE Insp Rept 50-398/80-24 on B01103-07, 12-14, 17-21, 24-26 &
28. No noncompliance noted. Major areas inspected: fuel receipt
& storage, design control & preoperational test program
implementation controls
DANIELS, F T, GWYNN, T P, WERNICK, R F Region 3, Chicago, Office
of the Director 80/12/10, 6pp, 07575 280.

entire Failure of BWR
response
to Director, 80/12/17.

ure of Control
nee
or 80/12/18

no W/Target
ed
r 80/12/19.

appealed. Approval is obtained
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/24
2pp 07443 245

B101150901 Responds to IE Bulletin 80-21 re valve yokes supplied by
Malcolm Foundry Co. Inc. Interim responses from vendors
indicate no mat'l from Malcolm Foundry Co. Inc was used at
facility
BORGMANN, E A Cincinnati Gas & Electric Co 80/12/29 1p
07464 143

B101150908 Responds to IE Bulletin 80-24, "Prevention of Damage Due
Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2
Event)." Facility does not have open cooling water sys
inside containment
BORGMANN, E A Cincinnati Gas & Electric Co 80/12/29 1p
07464 144

B101060278 Ack receipt of B01126 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-398/80-22
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/30 1p, 07392 017

--B101060201 Responds to NRC B01031 ltr re violations noted in IE Insp
Rept 50-398/80-22. Corrective actions INX support
implementation schedule established
BORGMANN, E A Cincinnati Gas & Electric Co, 80/11/26 4pp,
07392 018

B101210635 Ack receipt of B01204 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-398/80-16.
Requests schedule of anticipated completion of
review & mod of procedures
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering
Support Branch, 81/01/07 2pp 07488 114.

--B101210630 Updates response to IE Insp Rept 50-398/80-16. Twelve
procedures scheduled for revision completed & ready for
issuance. All revisions will be completed by B10113
BORGMANN, E A Cincinnati Gas & Electric Co 80/12/04 2pp
07488 116.

5 Reportable occurrences, LERs & related correspondence

B101210214 Ack receipt of util B00919 ltr informing of corrective
actions taken in response to NRC B00904 immediate action ltr
re mat'l mfg by Tech-Sil, Inc. Confirms B01218 telcon
authorizing resumption of work involving mat'l at facility
KEPPLER, J G Region 3, Chicago, Office of the Director 81/01/09
2pp 07408 333

B101230476 Interim deficiency rept re use of 1-inch diameter Hi-St
nut-bolt anchors. Forty-four supports identified as
utilizing 1-inch expansion anchors w/embedded lengths of 80
Review will be completed by mid-Mar. w/final rept by B10231.
BORGMANN, E A Cincinnati Gas & Electric Co 81/01/12 1p,
07511 127

DOCKET 50-361 BAW ONEFIRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarded
summary of B0112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHART, R F Division of Licensing, 80/11/26 6pp

B101070232 Requests addl info re util B01027 application for revisi
of proposed license for new fuel storage. Util should
describe controls used to assure conformance w/fuel storage
pattern & that subcritical conditions will be maintained.
STEVENS, R L Uranium Fuel Licensing Branch, 80/12/17 1p,
07414 295

B101140227 Approves B00903 request to withhold proprietary version
CEN-135 (s) -P (ref 10CFR2.7901
MIRACLIA, F Licensing Branch 3, 80/12/31 2pp, 07309 001

B101140234 Approves B01118 request to withhold proprietary version
CEN-1401S1-P, "Data Transmittal for Southern CA Edison Fuel
Audit Analysis," (ref 10CFR2.7901,
MIRACLIA, F Licensing Branch 3, 80/12/31 2pp, 07308 001

B101150024 Forwards safety evaluation & notice of issuance &
availability of BER.NUREG-0712
MIRACLIA, F Licensing Branch 3, 80/12/31 4pp, 07469 138.

--B101160030 Notice of issuance & availability of SER re geologic & seismic aspects, NUREG-0712
BUCKLEY, B Licensing Branch 3 80/12/31 1p 07469 142

B101190280 Approves 800913 request to withhold CEN-127(S)-P
(ref 10CFR2 790) Document contains trade secrets,
confidential, commercial & financial info
MIRAGLIA, F Licensing Branch 3 81/01/06 2pp 07476 091

B10130093 Forwards responses to numerous open items & questions
identified in NRC 801107 ltr & meetings w/NRC during wk of
801215 Direct distribution will be made as part of Amend 23
distribution per svc list provided in utl) 801029 ltr.
BASKIN, K P. Southern California Edison Co 81/01/09 200pp
07456 022.

B101200102 Notification of 810115 meeting w/utl), C-E & Bschtel in
Bethesda, MD to discuss explosion probabilities
RODD, H Licensing Branch 3 81/01/09 3pp 07486 357

B101160110 Forwards responses to open items & questions which will
become part of Amend 23 distribution, per 801107 ltr
BASKIN, K P Southern California Edison Co 81/01/14 54pp
07470 104

B101210621 Recommends that meeting w/utl) be held in mid-Mar 1901 to
discuss licensee qualification
TEDESCO, R L Assistant Director for Licensing 81/01/14 1p
07489 240

--B101210630 Recommends review of util mgt & use of consultants in
improving performance in areas of regulatory difficulty
MOSELEY, W C Division of Reactor Operations Inspections
80/12/31 2pp 07489 241

B101220187 Forwards proprietary version of CEN-148(S)-P, "Functional
Design Spec for Control Element Assembly Calculator" Rept
withheld (ref 10CFR2 790) Affidavit for withholding encl
BASKIN, K P Southern California Edison Co 81/01/19 6pp.
07500 022

B101220180 Forwards responses to open items & questions in NRC 801107
ltr re reactor internals analyses, preservice & inservice
insps, pump vortex test, snubber insp & engineered safety
features & auxiliary feedwater fracture toughness
BASKIN, K P Southern California Edison Co 81/01/20 58pp.
07493 284

C. Utility Environmental Report (ER), amendments & correspondence

B101300235 Forwards affidavit attesting to fact that direct
distribution of Amend 6 to environ rept 1e per modified svc
list Bvc list modified to include two members of ASLB.
Affidavit of Bvc encl
BASKIN, K P Southern California Edison Co 81/01/06 6pp.
07491 247

D. NRC Draft/Final Environmental Statements, supp & correspondence

B101270130 Forwards notice of availability of suppl to OES for
facilities Requests FR publication.
e Office of Nuclear Reactor Regulation, Director. 81/01/16 1p
07575 190

--B101290134 Notice of availability of suppl to OES for facilities
MIRAGLIA, F J. Licensing Branch 3 81/01/16 3pp 07579 191

B101270591 Verifies official filing of EIS for facility FR notice of
availability scheduled for 810123 Public review period will
terminate on 810309
WILSON, K L. Environmental Protection Agency. 81/01/21 1p
07549 064.

B101300408 Responds to NRC 810116 request for comments on OES suppl.
No significant impacts found to electric power, natural gas
& oil pipeline industries
HEINEMANN, J M. Federal Energy Regulatory Commission. 81/01/23 1p
07582 354.

B101290455 SUPPLEMENT TO DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE
OPERATION OF SAN ONOFRE NUCLEAR GENERATING STATION, UNITS 2 &
3
e Office of Nuclear Reactor Regulation, Director. NUREG-0490.
81/01/31 37pp

E. NRC Safety Evaluation Report (SER), supp & correspondence

B101060141 Informs of full power SER to be issued in Feb 1981
Geosciences Branch input scheduled for 801203 Competing
priorities for reviewers & mgt have caused delays in
completing facility input
RODD, H Licensing Branch 3 80/12/00 5pp 07391 254.

B101200514 Forwards draft SER for facilities re non-TM1 related
Outstanding items include seismic design & classification,
high energy line break, load combination methods &
independent piping analysis (1/2 encl)
TEDESCO, R L Division of Licensing 81/01/08 3pp 07486 357

B101140516 Forwards Revision 1 to listing of GER open items
open items resolved as of 810112
BASKIN, K P Southern California Edison Co 81/01/12 13p
07309 001

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, O
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 00/11/17 2pp

B101100079 Requests evaluation of potential effects of earth-
qu coastal responses, including earthquakes which either
initiate or follow initiation of accidents First instance
should be included in revised emergency plan
TEDESCO, R L Assistant Director for Licensing 80/12/17
07309 001

B101100838 Informs that licensee must conduct emergency exer-
cise on from 810401 or prior to issuance of O. Requests
schedule of drills & exercises
ERDELKEN, R H Region 3, San Francisco, Office of the Director
80/12/19 1p 07443 257.

B101290173 Forwards facility emergency planning info to be m-
publicly available w/o encl
SCUDER, J L Division of Rules and Records 81/01/23 1p
07575 202

G. Adjudicatory correspondence

B101140038 Forwards Commission 801218 memorandum & order & r-
statement of policy re litigation on TM-2 issues in CL
proceedings
CHANDLER, C J Licensing Branch 1. 80/12/29 1p 07460 230

--B101140046 Memorandum & order amending encl 800620 statement
"Further Commission Guidance for Power Reactor CLE"
CHILK, S J Office of the Secretary of the Commission
3pp 07460 235

--B101140053 "Further Commission Guidance for Power Reactor CLE"
statement of policy Ahearn dissenting views encl.
CHILK, S J Office of the Secretary of the Commission
14pp 07460 236

B101230128 Notice of CP Buckley 810212 deposition in Rosemead
seismology & geology of site
PIGOTT, D R Southern California Edison Co P108TT, D H
& Gregory 81/01/15 2pp 07512 015

--B101230137 Notice of J Drane 810309 deposition in San Diego
seismology & geology of site Certificate of Svc encl.
PIGOTT, D R Southern California Edison Co P108TT, D R
Chickering & Gregory 81/01/15 3pp 07512 017

H. General correspondence

B101090742 Requests reopening of safety licensing hearings P
in light of TM1 incident
REICHENBERG, B Affiliation Unknown 79/04/02 2pp 07486 357

B101300256 Responds to EK Johnson ltr re location of facility
Earthquake hazards are being re-reviewed in connection w/8
applications for Units 2 & 3 Facilities meet NRC siting
criteria
OJACKS, W J Office of the Executive Director for Operations
81/01/15 3pp 07586 129.

X Utility Final Safety Analysis Report (FSAR) & amendments

8101070325 Forwards affidavit of svc of Amend 22 to FSAR & Amend 4 to force analysis analysis per encl svc list
BASKIN, K P Southern California Edison Co 80/12/30 3pp
07442 060

O Advisory Committee on Reactor Safeguards reports & correspondence

8101190774 Forwards SER re geology & seismology for review & comment
Review will allow ALL2 leading to proceed II/O encl
TELFORD, R L Assistant Director for Licensing 80/12/31 1p
07476 115

P Operating license stage documents & correspondence

8101160024 Notification of 801218 meeting w/SEP owners group in
Bethesda MD re SEP program, schedule for licensee topic
completion & assignment of lead topics to plants
ROUSELL, W T Technical Support Branch 80/12/16 2pp

Q Inspection reports, IE Bulletins & correspondence

8101050459 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Steam Discharge Vol at Oriskany Unit 2"
No response required
ENGELKERN, R H Region 5, San Francisco, Office of the Director
80/12/05 1p 07387 271

8101210626 Forwards IE Insp Rept 50-361/80-20 on 801103-07 No
noncompliance noted
SCHEW, H E Region 5, San Francisco, Fuel Facility & Materials Safety
Branch 80/12/12 2pp 07488 078

--8101210627 IE Insp Rept 50-361/80-20 on 801103-07 No noncompliance
noted Major areas inspected licensee action on previous insp
findings & preoperational testing procedures
FISHER, F C, CHILDS, M., WENSLAWSKI, F A Region 5, San Francisco,
Office of the Director 80/12/12 6pp 07468 080

8101150932 Forwards IE Info Notice 80-44, "Activation of ECCS in
Recirculation Mode While in Hot Shutdown" No response
required
ENGELKERN, R H Region 5, San Francisco, Office of the Director
80/12/16 1p 07308 001

8101270517 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co. Inc." NRC will be notified if suspect
yokes were utilized upon written confirmation from
subvendor
BASKIN, K P Southern California Edison Co 81/01/05 1p
07543 352

8101300756 Ack receipt of 801223 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-361/80-18 &
50-362/80-11
SPENCER, Q S Region 5, San Francisco, Reactor Construction &
Engineering Support Branch 81/01/14 1p 07308 001

--8101300757 Responds to NRC 801202 ltr re violations noted to IE Insp
Repts 50-361/80-18 & 50-362/80-11. Corrective actions, work
plan procedure/OC Instruction 400 has been revised to
strengthen procedural controls
ARENAL, A Southern California Edison Co 80/12/23 4pp
07308 001

--8101300763 Forwards IE Insp Repts 50-361/80-18 & 50-362/80-11 on
800923-26 & notice of violation
SPENCER, Q S Region 5, San Francisco, Reactor Construction &
Engineering Support Branch 80/12/02 2pp 07308 001

--8101300766 Notice of violation from insp on 800923-26
SPENCER, Q S Region 5, San Francisco, Reactor Construction &
Engineering Support Branch 80/12/02 1p 07308 001

--8101300771 IE Insp Repts 50-361/80-18 & 50-362/80-11 on 800923-26
Noncompliance noted: stainless steel piping Spools 25-81-045
& 046 of safety injection sys insulated despite evidence on
external surfaces of piping
ECKHARDT, J H., HERNANDEZ, G Region 5, San Francisco, Office of the
Director HAYNES, R C Region 5, San Francisco, Reactor
Construction & Engineering Support Branch 80/12/01 7pp
07308 001

8101220180 Forwards responses to open items & questions in NRC 801107
ltr re reactor internals analyses, preserve & inservice
insp, surge vortex test, snubber insp & engineered safety
features & auxiliary feedwater fracture toughness.
BASKIN, K P Southern California Edison Co 81/01/28 58pp,
07495 204

S Reportable occurrences, IERs & related correspondence

8101210394 Final deficiency rept re ITE-0601d 400 V air circuit
breakers w/damaged trip coil wiring, initially reported on
801219 Licensee will tie-wrap wires near gear reducer or put
wires inside spiral wiring harness
PAPAY, L T Southern California Edison Co 81/01/12 3pp
07489 074

8101270507 Final deficiency rept, originally reported on 801226, re
inadequate design of fuel transfer tube Multiple
longitudinal stiffener plates added between interface &
adjacent circumferential interface stiffener rings
PAPAY, L T Southern California Edison Co 81/01/16 3pp,
07566 326

V Operator Examinations

8101050376 Submits addl info re description of shift technical advisor
training program & plans for requalification training per
791031 request
HAYNES, J O Southern California Edison Co 00/12/30 4pp
07395 285

8101060513 Forwards "Shift Technical Advisor Training & Requalification
Program" & related info. in response to NRC 801031 ltr re
TRI action plan requirement
HAYNES, J O Southern California Edison Co 80/12/30 5pp,
07396 040

--8101060523 "Shift Technical Advisor Training & Requalification
Program"
Southern California Edison Co. 80/12/31 31pp 07396 049.

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENBERG, D O Division of Licensing 80/11/26 0pp.

8101070232 Requests addl info re util 801027 application for revision
of proposed license for new fuel storage. Util should
describe controls used to ensure conformance w/fuel storage
pattern & that subcritical conditions will be maintained.
STEVENSON, R L Uranium Fuel Licensing Branch 80/12/17 1p,
07414 295

8101140227 Approves 800903 request to withhold proprietary version of
CEN-125 (s) -P (ref 10CFR2.790).
MIRAGLIA, F. Licensing Branch 3. 80/12/31 2pp 07309:001.

8101140234 Approves 801118 request to withhold proprietary version of
CEN-140(B)-P, "Data Transmittal for Southern CA Edison Fuel
Audit Analysis." (ref 10CFR2.790)
MIRAGLIA, F. Licensing Branch 3 80/12/31 2pp 07308:001

8101160024 Forwards safety evaluation & notice of issuance &
availability of SER, NUREG-0712
MIRAGLIA, F. Licensing Branch 3. 80/12/31 4pp 07469:138

--8101160030 Notice of issuance & availability of SER re geologic &
seismic aspects, NUREG-0712.
BUCKLEY, B. Licensing Branch 3. 80/12/31 1p. 07469:142.

8101190280 Approves 800813 request to withhold CEN-127(B)-P
(ref 10CFR2.790) Document contains trade secrets,
confidential, commercial & financial info
MIRAGLIA, F. Licensing Branch 3 81/01/06 2pp 07476:091.

8101130093 Forwards responses to numerous open items & questions
identified in NRC 801107 ltr & meetings w/NRC during wk of
001215 Direct distribution will be made as part of Amend 23
distribution per svc list provided in util 801029 ltr.
BASKIN, K P Southern California Edison Co 81/01/09 200pp,
07496:022

0101200102 Notification of B10115 meeting w/uttl, C-E & Bechtel in Bethesda, MD to discuss explosion probabilities
R006.H Licensing Branch 3. 01/01/09 5pp 07486 357

0101160110 Forwards responses to open items & questions which will become part of Amend 23 distribution, per B0107 ltr
BASKIN, K. P. Southern California Edison Co. 01/01/14 54pp 07470 104

010120621 Recommends that meeting w/uttl be held in mid-Mar 1981 to discuss licensee qualification
TEDESCO, R. L. Assistant Director for Licensing 01/01/14 1p 07489 240

-010120630 Recommends review of util mgt & use of consultants in improving performance in areas of regulatory difficulty
MOSELEY, H. C. Division of Reactor Operations Inspections 00/12/31. 2pp 07487 241

0101220187 Forwards proprietary version of CFN-140181-P: "Functional Design Spec for Control Element Assembly Calculator" Rpt withheld (ref 10CFR2 7901 Affidavit for withholding encl)
BASKIN, K. P. Southern California Edison Co. 01/01/19 6pp 07500 022

0101220180 Forwards responses to open items & questions in HRC B01107 ltr re reactor internals analysis, preservice & inservice insps, pump vortex test, snubber insp & engineered safety features & auxiliary feedwater fracture toughness
BASKIN, K. P. Southern California Edison Co. 01/01/20 58pp 07495 284

Utility Environmental Report (ER), amends & correspondence

010130235 Forwards affidavit attesting to fact that direct distribution of Amend 6 to environ rept is per modified svc list. Svc list modified to include two members of ASLB.
Affidavit of Svc encl
BASKIN, K. P. Southern California Edison Co. 01/01/06 6pp 07491 247

NRC Draft/Final Environmental Statements, supp's & correspondence

0101290130 Forwards notice of availability of suppl to DES for facilities. Requests FR publication
* Office of Nuclear Reactor Regulation, Director 01/01/16 1p 07573 190

0101290134 Notice of availability of suppl to DES for facilities.
MIRALIA, F. J. Licensing Branch 3. 01/01/16 3pp 07575 191

0101270591 Verifies official filing of EIS for facility FR notice of availability scheduled for B01023. Public review period will terminate on B10309
WILSON, K. L. Environmental Protection Agency 01/01/21. 1p 07549 064

0101300408 Responds to NRC B10116 request for comments on DES suppl. No significant impacts found to electric power, natural gas & oil pipeline industries.
HEINEHANN, J. M. Federal Energy Regulatory Commission 01/01/23 1p 07582 354

0101290459 SUPPLEMENT TO DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF SAN ONOFRE NUCLEAR GENERATING STATION, UNITS 2 & 3.
* Office of Nuclear Reactor Regulation, Director NUREG-0470. 01/01/31. 37pp.

NRC Safety Evaluation Report (SER), supp's & correspondence

0101060141 Informs of full power SER to be issued in Feb 1981. Final Observances Branch input scheduled for B01208. Competing priorities for reviewers & mgt have caused delays in completing facility input
RODD, H. Licensing Branch 3. 00/12/08 5pp. 07391 254

0101200514 Forwards draft SER for facilities re non-TMI related issues. Outstanding items include seawall design & classification, high energy line break, load combination methods & independent piping analysis. W/o encl
TEDESCO, R. L. Division of Licensing. 01/01/08 3pp 07487 048

010140516 Forwards Revision 1 to listing of SER open items identifying open items resolved as of B01012
BASKIN, K. P. Southern California Edison Co. 01/01/12 13pp. 07309 001

F Security, medical, emergency & fire protection plans

0101090397 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D. G. Division of Licensing 00/11/13 2pp

0101160075 Requests evaluation of potential effects of earthquakes on emergency responses, including earthquakes which either initiate or follow initiation of accidents. First instance should be included in revised emergency plan
TEDESCO, R. L. Assistant Director for Licensing 00/12/17 4pp 07309 601

0101100839 Informs that licensee must conduct emergency exercise within one yr from B10401 or prior to issuance of CL. Requests schedule of drills & exercises
EISENHUT, D. G. Region 5, San Francisco, Office of the Director 00/12/19 1p 07440 297

0101290173 Forwards facility emergency planning info to be made publicly available w/o encl
SOUDEK, J. L. Division of Rules and Records 01/01/23 1p 07575 202

G Adjudicatory correspondence

0101140038 Forwards Commission B01218 memorandum & order & revised statement of policy re litigation on TMI-2 issues in UL proceedings
CHANDLER, L. J. Hearing Branch 1. 00/12/29 1p 07460 234

0101230128 Notice of CP Buckley B10212 deposition in Rosemead, CA re seismology & geology of site
PIGOTT, D. R. Southern California Edison Co. PIGOTT, D. R. Chickering & Gregory 01/01/15 2pp. 07512 015

--0101230137 Notice of J. Brune B10209 deposition in San Diego, CA re seismology & geology of site. Certificate of Svc encl
PIGOTT, D. R. Southern California Edison Co. PIGOTT, D. R. Chickering & Gregory 01/01/15 5pp 07512 017

H General correspondence

0101090742 Requests reopening of safety licensing hearings for Facility in light of TMI incident.
REICHENBERG, S. Affiliation Unknown 79/04/02 2pp 07429 360

0101300256 Responds to RA Johnson ltr re location of facilities. Earthquake hazards are being re-reviewed in connection w/DL applications for Units 2 & 3. Facilities meet NRC siting criteria.
DIRKS, W. J. Office of the Executive Director for Operations 01/01/15 3pp 07586 129

K Utility Final Safety Analysis Report (FSAR) & amends

0101090625 Forwards affidavit of svc of Amend 22 to FSAR & Amend 4 to fire hazards analysis per encl svc list
BASKIN, K. P. Southern California Edison Co. 00/12/30 3pp 07442 060

O Advisory Committee on Reactor Safeguards reports & correspondence

0101190734 Forwards SER re geology & seismology for review & comment. Review will allow ASLB hearing to proceed w/o encl
TEDESCO, R. L. Assistant Director for Licensing 00/12/31 1p 07476 119

P. Operating license stage documents & correspondence

0101160029 Notification of B01218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants
RUSSELL, W. F. Technical Support Branch. 00/12/16 2pp.

Q Inspection reports, IE Bulletins & correspondence

0101050489 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for B-Cram Discharge Val at Dresden Unit 2." No response required
EISENHUT, D. G. Region 5, San Francisco, Office of the Director 00/12/05. 1p 07387 271

B101150832 Forwards IE Info Notice 80-44. "Actuation of ECCB in Recirculation Mode While in Hot Shutdown " No response required
ENCKELKEH, R H Region 3, San Francisco, Office of the Director
80/12/16 1p 07308 001

B101276517 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc " NRC J171 to notified if suspect yokes were utilized upon written confirmation from subvondor
BASKIN, K P Southern California Edison Co 81/01/05 1p
07543 352

B101300756 Ack receipt of B01223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/80-18 & 50-362/80-11.
SPENCER, S S Region 3, San Francisco, Reactor Construction & Engineering Support Branch 81/01/14 17 07308 001

--B101300759 Responds to LTRC 801202 ltr re violations noted in IE Insp Repts 50-361/80-18 & 50-362/80-11 Corrective actions work plan procedure/GC instruction 400 has been revised to strengthen procedural controls
ARENAL, A Southern California Edison Co 80/12/23 4pp
07300 401

--B101300763 Forwards IE Insp Repts 50-361/80-18 & 50-362/80-11 on 800923-26 & notice of violation
SPENCER, S S Region 3, San Francisco, Reactor Construction & Engineering Support Branch 00/12/02 2pp 07308 001

--B101300766 Notice of violation from insp on 800923-26.
SPENCER, S S Region 3, San Francisco, Reactor Construction & Engineering Support Branch 80/12/02 1p. 07308 001

--B101300771 IE Insp Repts 50-361/80-18 & 50-362/80-11 on 800923-26 Noncompliance noted stainless steel piping Spools 28-81-043 & 046 of safety injection sys insulated despite residue on external surfaces of piping
ECHARDI, J H, HERNANDEZ, C Region 3, San Francisco, Office of the Director HAYNES, R C Region 3, San Francisco, Reactor Construction & Engineering Support Branch 80/12/01 7pp
07308 001.

B101220180 Forwards responses to open items & questions in NRC 801107 ltr re reactor internals analysis, preservice & inservice insps, sump vortex test, snubber insp & engineered safety features & auxiliary feedwater fracture toughness
BASKIN, K P Southern California Edison Co 81/01/20 50pp

9 Reportable occurrences, LERs & related correspondence

B101210384 Final deficiency rept re ITE-00015 480 V air circuit breakers w/damaged trip coil wiring, initially reported on B01219 licensee will tie-trip wires near gear reducer or put wires inside spiral wiring harness
PAPAY, L T Southern California Edison Co 81/01/12 3pp
07489 074

B101296507 Final deficiency rept, originally reported on B01226, re inadequate design of fuel transfer tube Multiple longitudinal stiffener plates added between interface & adjacent circumferential interface stiffener rings
PAPAY, L T Southern California Edison Co 81/01/16 3pp.
07566 326

V. Operator Examinations

B101050376 Submits addl info re description of shift technical advisor training program & plans for requalification training per 791031 request
HAYNES, J O Southern California Edison Co 80/12/30 4pp.
07389:285

B101060513 Forwards "Shift Technical Advisor Training & Requalification Program," & related info in response to NRC 801031 ltr re TMI action plan requirement
HAYNES, J O Southern California Edison Co 80/12/30 3pp.
07396 040

--B101060523 "Shift Technical Advisor Training & Requalification Program"
e Southern California Edison Co 80/12/31 31pp. 07396.043.

DOCKET 50-363 FORKED RIVER NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lemiclar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

B101890387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

I Financial information

B012616144 Forwards BEC Form 10-0, Quarterly Financial Rept & supporting mgt comments in response to NRC 790921, 1109 & 800811 requests for info re significant financial developments affecting utility in retest proceeding
CONDEEN, V H General Public Utilities 80/11/26 3pp

--B012616154 Quarterly Financial Rept Sept 1980 & supporting mgt comments
e General Public Utilities 80/11/14 44pp

O Inspection reports, IE Bulletins & correspondence

B101070469 Forwards Suppl 1 to IE Info Notice 80-29. "Broken Stude Terry Turbine Steam Inlet Flange." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director.
80/11/26 1p 07414 062

B101060840 Forwards IE Info Notice 00-44. "Actuation of ECCB in Recirculation Mode While in Hot Shutdown " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director.
80/12/16 1p 07397 021

DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101090828 Forwards for review. "Radiation Control & Protection Procedure FNP-O-RCP-000, Mobile Cement Solidification Operation (Hittman)"
CLAYTON, F L Alabama Power Co 81/01/06 2pp. 07424 211

--B101090830 "Radiation Control & Protection Procedure FNP-O-RCP-000 Mobile Cement Solidification Operation (Hittman)."
e Alabama Power Co 80/12/15 30pp 07424 213.

--B101090832 "Process Control Program for Sample Collection, Analysis & Test Solidification Using Cement."
e Alabama Power Co 80/11/28 11pp 07424 242.

B101160017 Notification of B10107-09 meeting w/util et alite to audit records on environ qualification of selected safety-related equipment
WINTNER, L L Licensing Branch 2 81/01/07 4pp. 07469:257

B101300054 Summary of B01022 meeting w/util to review design of flow control valves in auxiliary feedwater sys. as part of OL review
WINTNER, L L Licensing Branch 2 81/01/14 15pp 07583:017.

B101260350 Forwards proposed changes to Table 2.3-16 of FSAR, reflecting current instrumentation on meteorological tower. Proposed change will be incorporated into next amend to FSAR
CLAYTON, F L Alabama Power Co 81/01/20 3pp 07525.142

F Security, medical, emergency & fire protection plans

B101140301 Requests that ancil facility emergency planning info be made publicly available w/o encl.
SOUDER, J L Division of Rules and Records 80/12/31 1p.
07461 263

DOCKETED ITEMS

J Insurance & indemnity information

8101090601 Forwards Endorsement 4 to NELA Binder EB-62
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/30 2pp 07442 071

8101220345 Forwards Endorsements 30 & 31 to NELA Policy KF-230
DUCK, J. R. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc. Div
81/01/16 4pp 07503 098

P Operating license stage documents & correspondence

810120106 Forwards Amend 1 to License NPF-B, safety evaluation & notice
of issuance & availability
SCHWENGER, A Licensing Branch 2 80/12/24 2pp 07446-122

--810120111 Amend 1 to License NPF-B, granting relief from diesel
generator surveillance Requirements 4 B 1.1 2 C 7 & part of
4 B 1.2 from initial fuel loading to initial criticality.
SCHWENGER, A Licensing Branch 2 80/12/24 7pp 07446 125

--810120114 Notice of issuance & availability of Amend 1 to License
NPF-B
SCHWENGER, A Licensing Branch 2 80/12/24 2pp 07446 132

--810120116 Safety evaluation supporting Amend 1 to License NPF-B
* Office of Nuclear Reactor Regulation, Director 80/12/24 3pp
07446 134

8101190101 Application to amend License NPF-B, granting temporary relief
from certain Tech Spec items in order to perform augmented
low power testing program
CLAYTON, F. L. Alabama Power Co 81/01/05 2pp 07476 004

8101210402 Discusses containment purge valve operability at facility,
including use of solenoid valves & air actuators. Interim use
of solenoid valves is acceptable. Actuator seal kites will be
replaced on regular basis
CLAYTON, F. L. Alabama Power Co 81/01/05 2pp 07409-080.

8101270179 Notification of 810112 meeting w/util in Gaithersburg, MD re
identifying specific info for piping sys that penetrate
containments, as part of OL review
KINTNER, L. Licensing Branch 2 81/01/09 2pp. 07544-004

8101210411 Responds to 001230 request for addl info re NRC Position
040 15E on external control power for primary & backup
breakers associated w/reactor coolant pumps. Postulated
failure analyses & control power sources provided.
CLAYTON, F. L. Alabama Power Co 81/01/12 5pp 07489-082

8101210083 Informs that 801205 memo re meeting summary for Farm 2
should read Farley 2. Copies of memo should be destroyed.
KINTNER, L. Licensing Branch 2 81/01/13 2pp 07489-322

8101260360 Forwards response to NUREG-0737, in response to NRC 801031
ltr items requiring followup by Unit 2 & corresponding BER
are included in action item for requirement.
CLAYTON, F. L. Alabama Power Co. 81/01/14 9pp 07525-147

8101220344 Forwards Westinghouse "Special Low Power Tests-Safety
Evaluation." Revision 2, providing justification for
performing Tests 4 & 5 re natural circulation & forced
circulation, respectively
CLAYTON, F. L. Alabama Power Co. 01/01/16 1p. 07496-347.

--8101220349 Revision 2 to "Farley Unit 2 Special Low Power Tests-Safety
Evaluation."
* Westinghouse Electric Corp. 81/01/31 3pp. 07496 348

8101270696 Comments on draft BER re auxiliary feedwater control sys
Auxiliary feedwater sys design will be modified to remove
power source dependence.
CLAYTON, F. L. Alabama Power Co. 01/01/22 2pp. 07543-014

8101270790 Submits info in clarification of multiple rod drop analysis,
per util 801212 ltr & 810116 telcon. Outlines policy to be
implemented when Unit 1 returned to power & subsequent to
exceeding 5% power for Unit 2
CLAYTON, F. L. Alabama Power Co. 81/01/22 1p. 07548-045

8101280164 Forwards list of radioactive liquids, resins & slimes sys
beds which must be processed for facility process control
program. Info supply util 801203 & 810106 ltrs. End product
handled util 81/01/16 in accordance w/requirements.

O Inspection reports, IF Bulletins & correspondence

8101290086 Submits amended response to IE Insp Repts 50-348/80-16 &
50-364/80-19 Contact made w/vendors to determine required
installation torques for concrete expansion anchor bolts
CLAYTON, F. L. Alabama Power Co 80/10/07 6pp 07567 234

8101050124 Requests existing data, summaries & records of inservice
tests of containment w/greatest prestressing tendons
ORNL receiving contract to compile & review records of
tendons.
EISENHART, D. O. Division of Licensing 80/11/25 3pp

8101220419 Forwards IE Insp Repts 50-348/80-35 & 50-364/80-46 on
001091-31 No noncompliance noted
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch. 80/12/04 2pp 07560 213

--8101220427 IE Insp Repts 50-348/80-35 & 50-364/80-46 on 001001-31
noncompliance noted. Major areas inspected plant tours,
pre-operational testing, open items & task action items
BRADFORD, W. H., MURPHY, J. P., MARTIN, R. D. Region 2, Atlanta, Office
of the Director 80/12/05 11pp 07503 215

8101070856 Confirms 801209 telcon advising of design deviations in
2 auxiliary bldg concrete block walls discovered as result
of evaluations required by IE Bulletin 80-11, "Masonry Wall
Design."
HARRISON, W. O. Alabama Power Co 80/12/09 1p. 07428 358

810140035 Submits 801210 daily staff notes IE informs of concrete
block wall deviations at Farley 2 & breach of radwaste
package integrity at Turkey Point 3 & 4 Plant status encl
DIRCKS, W. J. Office of the Executive Director for Operations
80/12/11 3pp

8101060239 Forwards IE Info Notice 80-44, "Actuation of ELCS in
Recirculation Mode While in Hot Shutdown." No written
response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/12/11
1p 07391 343

8101100300 Ack receipt of 801210 ltr informing IIRC of steps taken to
correct violations noted in IE Insp Repts 50-348/80-31 &
50-364/80-42
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/12/22 1p 07443 313

--8101100319 Responds to NRC 801114 ltr re violations noted in IE
Repts 50-348/80-31 & 50-364/80-42 Corrective actions
comprehensive QA audit of fire protection const program
initiated. No proprietary info
CLAYTON, F. L. Alabama Power Co 80/12/10 2pp 07443 314

--8101100331 Forwards IE Insp Repts 50-348/80-31 & 50-364/80-42 on
801014-17 & notice of deviation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch. 80/11/14 2pp 07443-316

--8101100337 Notice of deviation from insp on 801014-17
* Region 2, Atlanta, Office of the Director 80/11/12 1p.
07443 318

--8101100343 IE Insp Repts 50-348/80-31 & 80-364/80-42 on 001014-17
Noncompliance noted inadequate fire protection QA program
HILLER, W. H. Region 2, Atlanta, Office of the Director
CONLON, Y. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/11/12 7pp 07443-319

8101290363 Requests attention until 810115 to respond to IE Bulletin
80-24, "Prevention of Damage Due to Water Leakage Inside
Containment." Oct 17, 1980 Indian Point 2 Event 1. Emission
necessitated by licensing & refueling activities
CLAYTON, F. L. Alabama Power Co 81/01/05 1p 07575 129

8101270406 Summarizes 810109 conference call re licensee evaluation
IE Bulletin 80-11, "Masonry Wall Design." Licensee should be
requested to provide description of deficiencies, Bechtel
wall evaluation & commitment to modify walls.
REEVES, E. Operating Reactors Branch 1 KINTNER, L. Operating
Reactors Branch 2. 81/01/13 3pp 07546 101

8101300062 Summary of 801205 meeting w/util in Gaithersburg, MD to
review drawings & other design info re piping sys that
penetrate containment, as part of OL review
KINTNER, L. L. Licensing Branch 2. 81/01/14 4pp. 07583 032

012990334 Forwards response to IE Bulletin 80-11, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)". - SWC water sys is open sys supplying cooling water inside containment
CLAYTON F L Alabama Power Co 81/01/15 8pp 07573 220

8101290728 Responds to IE Bulletin 80-11, "Masonry Wall Design - Required vertical reinforcing missing from both unit walls. Wall is safety-related. Equipment should conform to requirements before criticality
CLAYTON F L Alabama Power Co 81/01/15 2pp 07309 001

P Periodic operating reports & related correspondence

8101210481 Forwards monthly operating rept for Dec 1980
CLAYTON F L Alabama Power Co 81/01/14 1p 07490 156

--8101210485 Monthly operating rept for Dec 1980
CLAYTON F L Alabama Power Co 81/01/01 4pp 07490 157

Q Reportable occurrences, LERs & related correspondence

8101300589 RO on 801227, one tube in steam generator IC satisfactorily plugged. Defective tube located by pressurizing secondary side & performing visual insp for leaks. Tube plugging reported per Tech Specs 4.4.3.5.a
CLAYTON F L Alabama Power Co 81/01/12 1p 07582 263

R Operator Examinations

8101260360 Forwards response to NUREG-0737, in response to HRC 801031 for items requiring followup by Unit 2 & corresponding SER are included in action item for requirement
CLAYTON F L Alabama Power Co 81/01/14 79pp

8101260365 Forwards addl info re shift technical advisor per NUREG-0737
CLAYTON F L Alabama Power Co 81/01/20 6pp 07525 246

S Security, medical, emergency & fire protection plans

8101090397 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101070518 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 80/12/01 1p 07403 237

--8101070522 Forwards public version of Revision 3 to emergency plan
WIDNER, W A Georgia Power Co 80/01/31 1p 07403 239

--8101070526 Public version of Revision 3 to emergency plan
* Georgia Power Co 80/01/31 89pp 07403 240

8101140551 Requests to be relieved of constraint to install sprinkler sys for facility recirculation pumps due to recently issued App B to 10CFR50. Forwards proposed revision to fire protection evaluation rept for NRC review & approval
WIDNER, W A Georgia Power Co 80/12/29 3pp 07462 003

8101260714 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 81/01/16 1p 07534 237

--8101260718 Forwards public version of emergency plan
WIDNER, W A Georgia Power Co 81/01/02 1p 07534 028

--8101260724 Public version of emergency plan
* Georgia Power Co 81/04/30 100pp 07534 030

T Insurance & indemnity information

8101090550 Forwards Endorsement 97 to ANF Policy NF-215
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc
Div 80/12/31 3pp 07442 050

8101090630 Forwards Endorsement 4 to NELA Binder EB-51
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc
Div 80/12/31 3pp 07442 058

P Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--8101160271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-17 to STS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101190113 Ltr to all BWR licensees forwarding 801201 generic safety evaluation re BWR scram discharge sys. Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes
EISENHUT, D O Division of Licensing 80/12/09 2pp

--8101190141 Generic safety evaluation re short-term actions required to ensure continued safe operation of operating BWRs. Continued operation of plants is acceptable pending permanent design rods. Criteria for implementing design mods uncl
* Division of Licensing 80/12/01 212pp 07183 001

8101210445 Forwards response to questions on Rule 50.71c, "Periodic Updating of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing 80/12/15 13pp

8101090770 Forwards request for addl info to complete review of OA program. Shipping damage insps should be implemented & performed for all safety-related items upon delivery.
REID, R W Operating Reactors Branch 4 80/12/24 4pp 07442 026

8101190351 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network. W/O encls
BIDLER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07476 083

8101060564 Forwards info for requirements of NUREG-0737, as of 810101.
WIDNER, W A Georgia Power Co 80/12/31 267pp 07395 120

--8101060573 Tech Specs 3/4 & 7 & 3/4 7.2 re chlorine detectors & main control room environ control sys for Unit 2
* Georgia Power Co 80/12/31 11pp 07396 023

8101220553 Forwards "Operability Review of ECCS at Plant Hatch Unit 1 & 2," in response to NUREG-0737, item 11 K 3.17.
WIDNER, W A Georgia Power Co 81/01/16 1p 07503 077

--8101220569 "Operability Review of ECCS at Plant Hatch Unit 1 & 2"
* General Physics Corp OP-R-33009 80/12/22 75pp 07503 070

8101290578 Responds to NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Mods will be performed during 1982 refueling outages. Feedwater & control rod drive cpts will be submitted within time limits specified
WIDNER, W A Georgia Power Co 81/01/22 3pp 07575 003

G Inspection reports, IE Bulletins & correspondence

8012240275 Responds to IE Bulletin 80-17. Ultrasonic transducers will not be installed as previously reported in 800819 ltr. Devices found unreliable in environ. Cause of float failures under investigation
WIDNER, W A Georgia Power Co 80/11/18 1p 07328 211

8101100682 Forwards IE Insp Repts 50-321/80-43 & 50-366/80-43 on 801104-07 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/25 2pp 07443 167

--B01100689 IE Insp Repts 90-321/80-43 & 90-366/00-43 on B01104-07 No noncompliance noted Major areas inspected installed equipment review per IE Bulletin 79-01B
O'CONNOR, T B. CONLON, T E Region 2, Atlanta, Office of the Director 80/11/25 4pp 07443 164

B01080202 Responds to IE Bulletin 80-21 re valve yokes supplied by Malcolm Foundry Co. Inc. No such yokes used in facility Valve documentation indicates other foundries made valve yokes in use
WIBNER, W A Georgia Power Co. 80/11/26 1p 07420 359

B01090602 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Val at Oresden Unit 2 " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/05 1p 07391 010

B01070331 Ack receipt of B01008 ltr requesting re-evaluation & dismissal of apparent noncompliance item contained in Waste Packaging Insp Repts 90-321/80-32 & 90-366/80-32 item withdrawn
STCHAR, J P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/11 1p 07408 124

--B01070334 Responds to NRC 800917 ltr re violations noted in Waste Packaging Repts 90-321/80-32 & 90-366/80-32 Requests re-evaluation & dismissal of cited noncompliance All shipment regulations properly followed
WIDNER, W A Georgia Power Co 80/10/08 2pp 07408 123

--B01070336 Forwards Waste Packaging Insp Repts 90-321/80-32 & 90-366/80-32 on 800731 & notice of violation
STCHAR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/17 2pp 07408 127

--B01070338 Notice of violation from Insp on 800731 e Region 2, Atlanta, Office of the Director 80/09/13 1p 07408 129

--B01070342 Waste Packaging Insp Repts 90-321/80-32 & 90-366/80-32 on 800731 Noncompliance noted radwaste shipment not properly placarded
MACARTHUR, T C Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/15 3pp 07408 130

B01060126 Forwards IE Info Notice 90-45, "Potential Failure of BWR Backup Manual Scram Capability " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/17 1p 07397 339

B01070033 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 75 of 185 Control Rods to Fully Insert During Scram at BWR " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/10 1p 07413 329

B01090159 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rod Safety Relief Valves at BWRs " No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/19 2pp 07377 259

B01290185 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment Oct 17, 1980 Indian Point 2 Event " Bryquell cooling sys composed of six cooling units each w/ two fans Normally only one fan per unit is operating
WIDNER, W A Georgia Power Co 81/01/05 7pp 07569 346

B01290376 Responds to IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " No abnormal wear, stress or failed welds discovered during visual exams of Unit 2 assemblies by remote underwater television cameras Insp of Unit 1 scheduled
WIDNER, W A Georgia Power Co 81/01/13 1p 07575 131

B01290385 Responds to IE Bulletin 80-13, "Cracking in Core Spray Spargers " No cracking of core spray spargers or piping between inlet nozzle & vessel shroud was identified in Unit 2, Insp for Unit 1 scheduled during Winter 1981.
WIDNER, W A Georgia Power Co 81/01/13 1p 07575 132

B01300374 Responds to request for confirmation of response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Tests will be completed by Feb 1981 & June 1981 for Units 1 & 2, respectively
WIDNER, W A Georgia Power Co 81/01/26 2pp 07586 350

A Periodic operating reports & related correspondence

B01260329 Forwards monthly operating rept for Der 1980.
MANN, M Georgia Power Co 81/01/10 1p 07529 257

--B01260327 Monthly operating rept for Der 1980
MANN, M Georgia Power Co. 81/01/10 1pp 07529

B Reportable occurrences, IERs & related correspondence

B01050455 Forwards LER 80-163/01T-1
MANN, M Georgia Power Co. 80/12/23 1p 07390 193

--B01060460 LER 80-163/01T-1 on B01215, util notified that rect lead insulation structure did not conform to seismic Class 1 requirements Caused by failure to incorporate rods during const. Insulation structure will be modified
CROSSIN, C L Georgia Power Co 80/12/23 2pp 07390 194

B01060559 Forwards LER 80-164/03L-0
MANN, M Georgia Power Co 80/12/30 1p 07391 114

--B01060566 LER 80-164/03L-0 on B01210, attempt to pressurize dr equipment drain sump to radiaste discharge piping failed due to excessive leakage past outboard isolation valve 2011-F004, Caused by valve gate not seating properly Gate lapped
CROSSIN, C L Georgia Power Co 80/12/30 2pp 07391 115

B01060572 Forwards LER 80-162/03L-0
MANN, M Georgia Power Co 80/12/30 1p 07391 123

--B01060579 LER 80-162/03L-0 on B01209, review of B01203 local 1 test revealed leakage for vent purge outlet isolation valve 2748-F318 would have exceeded Tech Specs Cause unknown Valve will be repaired prior to startup
CROSSIN, C L Georgia Power Co. 80/12/30 2pp 07391 124

B01060648 Forwards LER 80-121/02L-0.
MANN, M Georgia Power Co. 80/12/30 1p 07392 183

--B01060669 LER 80-121/03L-0 on B01211, all points of 1747-RU11 temp recorder were reading higher than redundant recorder 1747-R612 Caused by faulty slide wire contacts & pinthead mechanism New parts installed
RICK, R T Georgia Power Co 80/12/30 2pp 07392 184

B01060514 Special Rept 3-sp-80-3 on B01206, during routine survey waste oil drums, several areas on ground were found to be contaminated Caused by storage of previous waste oil drums Addl controls re release of contaminated oil under review
MANN, M Georgia Power Co 80/12/31 4pp 07392 189

B01120312 Forwards LER 80-157/03L-0
MANN, M Georgia Power Co 81/01/06 1p 07447 133

--B01120344 LER 80-157/03L-0 on B01223, control rod removed & pool for Insp Monorail hoist used w/c performing hoist operability Caused by inadequate procedure Procedure revised
BAXLEY, S X Georgia Power Co. 81/01/06 2pp 07447 136

B01230466 Forwards LER 80-160/03L-0
MANN, M Georgia Power Co 81/01/13 1p 07511 126

--B01230469 LER 80-160/03L-0 on B01216, during refueling, local 1 test performed on fire protection isolation valve 2743-F159 revealed leakage would have exceeded acceptance criteria since test val could not be pressurized
CROSSIN, C L Georgia Power Co 81/01/13 2pp 07511 127

DDCKET 80-367 BAILY GENERATING STATION

A Application/construction stage documents & correspondence

B01220466 Ltr to all power reactor licensees & applicants for summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports"
EISENHART, D O Division of Licensing, 80/11/26 8pp

B01050369 Forwards final panel rept: "Effects of Doubling on Dune Natl Lakeshore "
WHITEHOUSE, J R Interior, Dept of, National Park Service 80/12 07378 358

B01070317 Notification of contract execution "Div of Engineers Review Support on Daily Pile Foundations." awarded to M Davidson
FLENNOR, C M Administrative Contracts Branch FIN 8-7536 80/12/17 1p 07415 217

--0101070319 Contract "Div of Engineering Review Support on Bailly File Foundations. awarded to H. Davison. OAVISSON, H. T. Davison, H. T. PERLMAN, J. Administrative Contracts March F14 G-7536 B012/17 3pp 07419-218

B0101050426 Forwards response to questions to aid in evaluation of CP extension request, per B01121 ltr Certificate of Svc encl
SHORR, E. M. Northern Indiana Public Service Co. B012/18 59pp
07380 128

B0101050079 Forwards records of three wells in IN Dunes Natl Lakeshore, near facility Wells 26, 0-7A & 23-A were pumped w/hand pump to develop wells. All three wells are open to aquifer in which they are screened
WATSON, L. R. Interior, Dept of B012/22 7pp 07376 292

B0101200157 Summary of B01210 meeting w/Mark II owners re status of generic improved chugging load model. Owners requested to justify delay in program & investigate alternatives
NIDERBOM, C. J. Generic Issues Branch B012/22 4pp.

B010140955 Summary of Dec 1980 meeting w/Mark II owners group. GE, BNL, MIT, SGM, Rashtel & Ebasco Svcs. Inc re suppression pool temp limits List of attendees & handouts encl
SU, T. M. Generic Issues Branch B012/30 41pp.

B0101060470 Comments on Natl Park Svc rept. "Effects of Dewatering on IN Dunes Natl Lakeshore." USGS prediction of groundwater changes are wrong & unreliable (raf B01120 ltr & encl B01208 ltr to members of wetlands panel)
SHORR, E. M. Northern Indiana Public Service Co. B012/31 18pp
07378 146

B0101090720 Responds to B01212 transmittal of Wetland ecologists "Effects of Dewatering on IN Dunes Natl Lakeshore" Rept provides no useful info to NRC preparation of EIA re request for CP extension Certificate of Svc encl
SHORR, E. M. Northern Indiana Public Service Co. B012/31 20pp
07442 126

F. Security, medical, emergency & fire protection plans

B0101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01102 & by applicants as part of FSAR
EISENHUT, O. O. Division of Licensing B011/13 2pp

G. Adjudicatory correspondence

B010100049 Forwards correspondence w/City of Gary, IN re requests for action under 10CFR2 206, in response to B01031 request Util will be notified of meeting w/o encls.
OIRCKS, W. J. Office of the Executive Director for Operations B012/12 1p 07442-291.

--B010100091 Forwards draft response to util B01031 ltr re requests for action concerning facility Requests blind copy of final version of response.
MOUNT, R. Rulemaking & Enforcement Division. B011/17. 3pp.
07442 292

--B010100095 Requests that util be furnished on contemporaneous basis w/all correspondence between NRC & parties to extension proceeding &/or petitioners under 10CFR2 206
SHORR, E. M. Northern Indiana Public Service Co. B010/31. 3pp
07442 295

B0101050004 Responds to B01212 request for NRC response to B01202 ltr from RE Dickinson, Natl Park Svc. Copy will be forwarded when available
GOLDBERG, S. C. Hearing Branch 2 B012/30 1p. 07377:360

B0101060629 Informs that Director's decision under 10CFR2 206 re State of IL & City of Gary B01231 request is unachievable by B01231 Determination anticipated in early Jan 1981.
GOLDBERG, S. C. Hearing Branch 2 B012/31 1p 07387 263

B0101090102 Motion for extension until B010109 to file response to ABLB B01224 memorandum & order. Intervenor believes order contains misunderstandings of law & misconceptions re position Certificate of Svc encl
WILCHER, J. H. Isaac Walton League of America, Porter County Chapter B012/31 4pp 07426:294

B010130606 Requests response by B01019 that Commission will insure adequate emergency planning for potential accidents at site before further const permitted
MCFEET, T. J. House of Rep. Government Operations B1/01/03 1p 07453 331

--B010130613 Extract of staff requirements memo advising that Director of Nuclear Reactor Regulation must hold action on 10CFR2 206 requests by State of IL & City of Gary until further notice from Commission. Certificate of Svc encl
CHILK, S. J. Office of the Secretary of the Commission B1/01/09 4pp. 07453 332

B010120449 Order granting extension until B010128 for Commission to review ALAB-619 Certificate of Svc encl.
CHILK, S. J. Office of the Secretary of the Commission. B1/01/07. 4pp 07442 317

B010120232 Motion for extension until B010116 to respond to ABLB B01224 memorandum & order Certificate of Svc encl
FAHNER, T. C., RAPKIN, A., MURRAY, M. J. Illinois, State of B1/01/08 4pp 07450 097

B010150008 Order granting extension until B010109 for any party to file pleadings pursuant to ASLO B01224 memorandum & order Certificate of Svc encl
GROSSMAN, H. Atomic Safety and Licensing Board Panel B1/01/09. 4pp. 07462 137.

B010160242 Response in opposition re admissibility of newly filed & short piling contentions in issues to ASLAB Certificate of Svc encl
VOLLEN, R. J. Isaac Walton League of America, Porter County Chapter. VOLLEN, R. J. Vollen, R. J. B1/01/09 12pp. 07470 216

B010140230 Forwards HR Denkin B01230 ltr to RE Dickinson in response B01292 ltr to J Ahearn
GOLDBERG, S. C. Hearing Branch 2 B1/01/12. 1p 07309:001

--B010140237 Advises that Ahearn response to B01202 ltr re dewatering procedure would be inappropriate since subj is similar to contention admitted by ABLB. Proposed plan constitutes reasonable approach w/one exception.
BEUTLER, R. R. Office of Nuclear Reactor Regulation, Director B012/30 2pp 07309 001

B010260216 Requests notification of any proceedings re facility
DOUGHERTY, M. R. Affiliation Unknown. B1/01/12 1p. 07523 307

--B010260224 Memorandum & order denying Porter County Chapter Intervenor B01017 motion to compel MD Lynch deposition in Chicago. Deposition to be restricted to Bethesda, MO or metropolitan Washington, DC area Certificate of Svc encl
GROSSMAN, H. Atomic Safety and Licensing Board Panel B1/01/19. 3pp 07523 308

B010160726 Order granting another extension until B010116 for any party to file pleading re ABLB B01224 memorandum & order. Certificate of Svc encl
GROSSMAN, H. Atomic Safety and Licensing Board Panel. B1/01/14 4pp 07472 057

B010200045 Objections to ASLB B01224 memorandum & order. Requests revision of order or certification to ASLAB of admissibility of short piling contentions. Certificate of Svc encl.
RAPKIN, A., FAHNER, T. C., MURRAY, M. J. Illinois, State of. B1/01/14 8pp. 07477-322

B010216200 Informs that EIA will not be completed by B010115 as B01030 1 advised NRC will inform ABLB & parties when realistic date for EIA issuance is known
GOLDBERG, S. C. Hearing Branch 2 B1/01/16 1p 07490 044.

B010230437 Advises that util will respond to Porter County Chapter Intervenor B01019 objections to ABLB B01224 memorandum & order & to B01019 motion for certification or referral. Certificate of Svc encl.
SHEA, K. H. Lowenstein, Newman, Reis, Aselrad & Toll. B1/01/16. 3pp. 07512 130

B010280031 Order granting extension until B010206 for Commission to review ALAB-619 Certificate of Svc encl
CHILK, S. J. Office of the Secretary of the Commission B1/01/22 4pp. 07555 111

B010270378 Informs that Director of Nuclear Reactor Regulation instructed not to act on State of IL & City of Gary 10CFR2 206 request until further advised
GOLDBERG, S. C. Hearing Branch 2 B1/01/26. 1p 07344 096

8101280441 Response opposing Porter County Chapter of Isaac Walton League of America, Inc 801224 motion for reconsideration & admission of denied contentions or certification to ASLAP Certificate of BvC encl
SHEA, K.H. Northern Indiana Public Service Co. SHEA, K.H.
Lovenstein, Neuman, Reis, Aselrad & Toll * Eichborn, Eichborn & Link
81/01/26 10pp 07550 216

0 Inspection reports, IE Bulletins & correspondence

8101050206 Forwards IE Info Notice 80-30, "Cracking in Charging Pump Casing Cladding " No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/30
2pp 07389 013.

8101060662 Forwards IE Info Notice 80-39, "Misfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/31.
1p 07401 129

8101100785 Forwards IE Circular 80-23, "Potential Defects in Solidt Power Sys Emergency Generators " No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/31
2pp. 07444:075

8101030479 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc " Written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/06
2pp 07390 061

8101060623 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Activates Safety-Relief Valve Operation to Cause Reactor Overpressurization." No written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/07.
1p 07400 161

8101060362 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1 " No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/10
2pp. 07391:064

8101060525 Forwards IE Bulletin 00-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp " Written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/14.
2pp. 07391 244

8101070576 Responds to IE Bulletin 80-23 No Valcor solenoid valves.
V70900-21-1 or V709000-21-3, used in safety-related sys at facility Complete response will be provided by 820129
SHORR, E. M. Northern Indiana Public Service Co. 80/12/04 1p.
07415:277

8101030568 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for BWRm Discharge Val at Dresden Unit 2 " No response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/12/05
2pp 07388 359

8101080048 Forwards IE Info Notice 80-49, "Potential Failure of BWR Backup Manual Scram Capability " No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/17
2pp. 07420:317

8101150225 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 00/12/18
2pp. 07465:340

8101050210 Forwards IE Bulletin 80-25, "Operating Problems w/Target Rod Safety Relief Valves at BWRs." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/19
2pp 07389 007

R. Periodic operating reports & related correspondence

8101050395 Forwards well charts for 801210-1217 & Bailey Wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & UGOS wells for 801217.
BOHN, R. J. Northern Indiana Public Service Co 80/12/24 33pp
07380:335

8101050336 Forwards well charts for 801217-14 & Bailey Wells w/o recorders, pond levels, pneumatic pressure transducers & water meter readings for 801224 Well readings for 518 & 558 unavailable
BOHN, R. J. Northern Indiana Public Service Co 80/12/31 32pp.
07430 016.

8101130457 Forwards Well charts for 801224-31, Bailey Wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & UGOS wells for 801231 Well 518 float froze
BOHN, R. J. Northern Indiana Public Service Co 81/01/09 32pp
07432 113

8101210320 Forwards Well charts for 801230-810107 & Bailey wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & UGOS wells for 810107 Clock on Wells 14 & 57C stopped float on Well 350 froze
BOHN, R. J. Northern Indiana Public Service Co 81/01/16 32pp
07187 001

8101230552 Forwards well charts for 810107-14, Bailey Wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & UGOS wells for 000114 & rainfall data for 801101-1230 Head hung up on Well 14
BOHN, R. J. Northern Indiana Public Service Co 81/01/20 33pp
07511 157

U Congressional/Executive Correspondence

8101130605 Requests response by 810119 that Commissioners will ins adequate emergency planning for potential accidents at site before further const permitted
MCFFETI, T House of Rep., Government Operations 81/01/03. 1p
07453 331

--8101130613 Extract of staff requirements memo advising that Dire of Nuclear Reactor Regulation must hold action on 10CFR2 206 requests by State of IL & City of Oary until further notice from Commission Certificate of BvC encl
CHILK, B. J. Office of the Secretary of the Commission. 81/01/4pp. 07453:332.

DOCKET 90-368 ARKANSAS NUCLEAR ONE, UNIT 2

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP hol & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D. G. Division of Licensing 80/11/13 2pp

8101130142 Advises of provisions of 10CFR50, App R, that are applica to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl
EISENHUT, D. G. Division of Licensing 80/11/24 7pp 07308 03

8101070460 Forwards proprietary comments on necessary revisions to add info needed re util 800909 revised security training & qualification plan Comments withheld (ref 10CFR2 790).
REID, R. W. Operating Reactors Branch 4 80/12/17 2pp. 07415

8101140215 Informs that licensee should conduct emergency exercise within one yr from 800401 or prior to issuance of DL.
Schedule of drills should be provided
SEYFRID, K. V. Region 4, Dallas, Office of the Director 00/12/21p 07461 256

8101080434 Forwards revisions & proposed changes to industrial sec plan Revisions withheld (ref 10CFR2 790)
TRIMBLE, D. C. Arkansas Power & Light Co 81/01/02 2pp 07415

8101200394 Requests that encl facility emergency planning info be publicly available w/o encl.
SOUDEK, J. L. Division of Rules and Records. 81/01/09. 1p
07486 313

8101260673 Releases public version of util upgraded emergency plan
FELTON, J. M. Division of Rules and Records 81/01/16 1p
07533:015

--8101260678 Forwards public version of upgraded emergency plan to State of AR radiological incident response plan & Pope, Johnson, Yell & Logan Counties, AR emergency plans
TRIMBLE, D. C. Arkansas Power & Light Co 81/01/02 1p.
07533 016

--B01200693 Public version of Upgrade of Emergency plan Includes State of AR radiological incident response plan & Pope, Johnson, Yell & Logan Counties. AR emergency plans
Arkansas Power & Light Co B1/01/01 800pp 07533 017.

J Insurance & indemnity information

B01207042 Forwards Endorsement CB to RELIA Policy MF-74 & Endorsement 43 to RELIA Policy MF-210
TRIMBLE, D C Arkansas Power & Light Co B1/01/21 4pp 07369 001

P Operating license stage documents & correspondence

B01201050 Clarifies intent of plans for position task analysis of general ops personnel interviews w/personnel in positions w/nuclear responsibilities will not be complete until
B0101
CAVANAU, M Arkansas Power & Light Co B0/11/19 4pp 07446 152

B01200254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS license amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D C Division of Licensing B0/11/20 1p

--B01200227 Revised Pages 3/4 7-22 through 28.B 3/4 1-5 & 7-6 & 6-17 to STS snubber inservice insp requirements
Division of Licensing B0/11/20 10pp

B01220465 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D C Division of Licensing B0/11/26 8pp

B01201045 Forwards responses to questions in Rule 50.71e. "Periodic Updoling of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D C Division of Licensing B0/12/15 13pp

B01200246 Informs that B00911 application for changes to Tech Specs re containment cooling sys svc water requirements only requires Class II, not Class III fee as permitted Refund will be made
MILLER, W D License Fee Management Branch B0/12/22 1p 07445 219.

B01050418 Advises that NRC B01113 ltr re NUREG-0519, "OWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking," does not pertain to facilities Facilities w/ PHRs No response action will be taken
TRIMBLE, D C Arkansas Power & Light Co B0/12/29 1p 07389 329

B01060255 Forwards info re NUREG-0737, in response to NRC B01031 ltr Includes info re shift technical advisor procedures for transients & accidents, plant shielding & thermal shock rept
TRIMBLE, D C Arkansas Power & Light Co. B0/12/31 9pp 07393 340

B0120406 Responds to NUREG-0737, "Reporting Safety Valve & Relief Valve Failures & Challenges" One challenge to electromechanical relief valve occurred at Unit 1 from Apr-Dec 1980 No challenges to primary sys code occurred at Unit 2
TRIMBLE, D C Arkansas Power & Light Co. B1/01/08 1p 07470 167

B01220414 Forwards CEN-143(A)-P & CEN-143(A)-NP, proprietary & nonproprietary versions, respectively of "CPC/CEAC Software Mode for AR Nuclear One, Unit 2" Requests withholding of CEN-143(A)-P (ref 10CFR2 790). Applicant encl
TRIMBLE, D C Arkansas Power & Light Co B1/01/09 5pp 07493 253

--B01220417 Nonproprietary version of "CPC/CEAC Software Mode for AR Nuclear One, Unit 2"
Corbation Engineering, Inc CEN-143(A)-NP B0/12/31 109pp. 07493 259

B01200298 Forwards evaluation of HPS1 pump operability w/o svc water cooling.
TRIMBLE, D C Arkansas Power & Light Co. B1/01/13 13pp 07486 242

B01200256 Forwards detailed plan, discussed in B01217 meeting w/NRC, describing proposed analysis method to demonstrate adequate fracture toughness characteristics for snubber attachment lug to reactor coolant pump, in response to NRC B00805 ltr
TRIMBLE, D C Arkansas Power & Light Co B1/01/15 2pp 07486 233

B01270356 Requests clarification of position re Items 11 B 1 & 11 B 4 to NUREG-0737, re reactor coolant sys vents & training for mitigating core damage
TRIMBLE, D C Arkansas Power & Light Co B1/01/19 3pp 07543 090

Q Inspection reports, IE Bulletins & correspondence

B01200466 Responds to IE Bulletin 79-17 re pipe cracks in stagnated bled water sys at PHRs Cracks discovered in heat affected zones of three welds in reactor bldg spray sys on B00121
TRIMBLE, D C Arkansas Power & Light Co B0/11/11 4pp 07446 162

B01200217 Forwards IE Insp Repts 50-313/80-21 & 50-368/80-21 on B00922-1021 & notice of violation
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch B0/11/19 2pp 07431 350

--B01200225 Notice of violation from Insp on B00922-1021
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch B0/11/18 3pp 07431 352

--B01200236 IE Insp Repts 50-313/80-21 & 50-368/80-21 on B00922-1021 Noncompliance noted inoperability of high pressure safety injection pump & failure to sample reactor coolant sys as required
JOHNSON, W D, CALLAN, L J, HUNNICUTT, B M Region 4, Dallas, Office of the Director B0/11/18 7pp 07431 355

B01090285 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment October 17, 1980 Indian Point Event" Written response required.
SEYFRIT, W V Region 4, Dallas, Office of the Director B0/11/21 1p 07425 250

B01050318 Forwards IE Info Notice 80-42, "Effluent of Radiation on Hydraulic Snubber Fluid" No response required
SEYFRIT, W V Region 4, Dallas, Office of the Director B0/11/24 1p 03998 308

B01201055 Responds to IE Bulletin 80-23 re Valcor solenoid valves No such valves installed at Facilities Three manhours expended
TRIMBLE, D C Arkansas Power & Light Co B0/11/24 1p 07446 156

B01060490 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Blade on Terry Turbine Steam Inlet Flange" No written response required
SEYFRIT, W V Region 4, Dallas, Office of the Director B0/11/24 1p 07391 109

B01060884 Forwards corrected Pages 6 & 7 of IE Insp Repts 50-313/80-21 & 50-368/80-21
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch B0/11/26 1p 07401 050

--B01060587 Corrected Pages 6 & 7
Region 4, Dallas, Office of the Director B0/11/26 2pp 07401 051

B01090214 Ack receipt of B00924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-368/80-13 & 50-313/80-13 Addl info required within 20 days.
KELLY, J A Region 4, Dallas, Office of the Director B0/11/20 3pp 07425 271

--B01090225 Responds to NRC ltr re violations noted in IE Insp Repts 50-368/80-13 & 50-313/80-13 Corrective actions withheld (ref 10CFR2 790).
TRIMBLE, D C Arkansas Power & Light Co B0/09/24 1p 07425 273

B0120044 Informs of progress since B00731 ltr re IE Bulletin 80-09 concerning hydramotor actuator deficiencies. Vendor rapte detailed
TRIMBLE, D C Arkansas Power & Light Co. B0/12/04 3pp 07446 25

B0107015B Ack receipt of B0/010 & 1112 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-16 & 50-368/80-16
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch B0/12/05 1p 07415 119

--B01070164 Responds to NRC B01023 ltr re violations noted in IE Insp Repts 50-313/80-16 & 50-368/80-16 Corrective actions: site QA audit repts will be reviewed by plant safety committee.
TRIMBLE, D C Arkansas Power & Light Co. B0/11/12 2pp 07415 120

8101050607 Forwards IE Info Notice 80-43. "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Bresden Unit 2" No response Required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/08.
1p 07391 026

810120174 Responds to IE Bulletin 80-21 re valve galls cast by Malcolm Foundry Co. Inc No valve parts in safety-related sys cast by Malcolm Foundry Co. Inc
TRIMBLE, B C Arkansas Power & Light Co 80/12/08 1p 07446 167

8101860192 Forwards IE Info Notice 80-44. "Actuation of ECCB in Recirculation Mode While in Hot Shutdown" No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/16
1p 07391 300

8101100005 Forwards IE Insp Repts 80-313/80-19 & 80-368/80-19 on 801006-09 & notice of violation Notice of violation withheld (ref 10CFR2 7901)
KELLY, J A Region 4, Dallas, Office of the Director 80/12/19
2pp 07443 057

--8101100008 IE Insp Repts 80-313/80-19 & 80-368/80-19 on 801006-09 Noncompliance noted: guards w/o continuous communication & excess authorization lists not prepared Details withheld (ref 10CFR2 7901)
EVANS, C A, KELLY, J A Region 4, Dallas, Office of the Director 80/10/31. 2pp 07443 059

R Periodic operating reports & related correspondence

8101210509 Forwards monthly operating rept for Dec 1980
TRIMBLE, D C Arkansas Power & Light Co 81/01/15 1p 07490 192.

--8101210514 Monthly operating rept for Dec 1980
PENBERGRAFT, R Arkansas Power & Light Co 81/01/15 5pp
07490 193

B Reportable occurrences, LERs & related correspondence

8101870399 RB 80-91 on 801220, channel checks on refueling water tank level indication revealed that Channels A, C & D indicated 180% & Channel B 82% Caused by frozen refueling water tank level transmitters
D'HANLON, J P Arkansas Power & Light Co 80/12/22 1p 07415 290

8101030361 Forwards LER 80-088/03L-0
TRIMBLE, D C Arkansas Power & Light Co 80/12/26 1p 07385 092

--8101050367 LER 80-088/03L-0 on 801201, core protection computer A & CEAC 1 failed CEAC 2 & PPS channels B, C & D were inoperable Caused by maint personnel working on ZFI-8224-1 in cabinet 2633. Bypass indicators will be replaced
PENBERGRAFT, R Arkansas Power & Light Co 80/12/26 2pp
07385 093.

8101050373 Forwards LER 80-087/03L-0
TRIMBLE, B C Arkansas Power & Light Co. 80/12/26 1p 07385 095

--8101050377 LER 80-087/03L-0 on 801229, high pressure safety injection valve ZCV-5056 failed to close Caused by control circuit fuse failure Fuse replaced, valve drained & declared operable
SHIVELY, C N Arkansas Power & Light Co 80/12/26 1p.
07385 096

8101050381 Forwards revised LER 80-064/03X-1.
TRIMBLE, B C Arkansas Power & Light Co. 80/12/26 1p. 07385 097.

--8101050387 Revised LER 80-064/03X-1 on 800810, high containment pressure trip refueling water tank level Caused by frozen level low level trip circuit for PPS A was inoperable Caused by bistable comparator card power supply failures
SHIVELY, C N Arkansas Power & Light Co 80/12/26 1p
07385 098

8101050422 Forwards LER 80-091/01T-0
TRIMBLE, B C Arkansas Power & Light Co 80/12/26 1p 07390 189

--8101050501 LER 80-091/01T-0 on 801220, Channel B instruments indicated low refueling water tank level Caused by frozen level transmitters Replaced fuse
SHIVELY, C N Arkansas Power & Light Co. 80/12/26 5pp.
07390 186

8101050440 Forwards LER 80-090/03L-0
TRIMBLE, D C Arkansas Power & Light Co 80/12/26 1p 07390 191

--8101050509 LER 80-090/03L-0 on 801205, increased accumulation of wastes found in waste tanks Caused by vibration induced cracking on changing pump suction header at junction of reactor makeup water tank supply Pipe spool piece replaced
SHIVELY, C N Arkansas Power & Light Co 80/12/26 1p
07390 192

8101050452 Forwards LER 80-089/03L-0
TRIMBLE, D C Arkansas Power & Light Co 80/12/26 1p 07390 193

--8101050519 LER 80-089/03L-0 on 801205, steam generator levels dropping less of feedwater flow found in electric driven emergency feedwater pump 2P7H. Caused by radial & thrust bearing failure in pump shaft Pump assembly rebuilt
SHIVELY, C N Arkansas Power & Light Co 80/12/26 1p
07390 235.

8101120344 Forwards updated LER 80-060/03X-2
TRIMBLE, D C Arkansas Power & Light Co 81/01/07 1p 07447 164

--8101120389 Updated LER 80-060/03X-2 800730 & 1202, B core protection calculator failed C core protection calculator failed on 801120 Watchdog timer timed out preventing console communications Core protection calculator sys reinitialized
BRANLETT, L S Arkansas Power & Light Co 81/01/07 1p
07447 164

8101130474 Forwards updated LER 80-081/03L-1
TRIMBLE, D C Arkansas Power & Light Co 81/01/07 1p 07447 164

--8101130484 Updated LER 80-081/03L-1 on 801030 & 1212, during reactor fire bacrier not maintained Caused by inadequate instructions Contractor instructed to maintain firewatch when penetrations are open & to seal penetrations quickly
BRANLETT, L S Arkansas Power & Light Co 81/01/07 1p
07454 113

8101130439 Forwards updated LER 80-056/03X-1
TRIMBLE, D C Arkansas Power & Light Co 81/01/09 1p 07454 113

--8101130452 Updated LER 80-056/03X-1 on 800720, A core protection calculator received three auto restarts & on 801218, calculator C failed causing BDR/LPO trip Probably caused by malfunction of normal room cooler increasing air temp.
BRANLETT, L S Arkansas Power & Light Co 81/01/09 1p
07454 099

8101190448 Forwards updated LER 80-060/03X-3
TRIMBLE, D C Arkansas Power & Light Co 81/01/13 1p 07454 099

--8101190491 Updated LER 80-060/03X-3 on 800730, core protection calculator channel failed, causing trip sequence Cause under investigation Watch dog time timed out, rendering channel inoperable Sys reinitialized & bypasses removed
SHIVELY, C N Arkansas Power & Light Co 81/01/13 2pp
07474 053

8101200411 Forwards LER 80-092/03L-0
TRIMBLE, D C Arkansas Power & Light Co 81/01/14 1p 07477 361

--8101200416 LER 80-092/03L-0 on 801222, emergency control room ZVE-1A compressor failed to start. Caused by frozen migration due to cold ambient temp affect on sys Had being evaluated to add time delay on interlocks to allow low temp starts
SHIVELY, C N Arkansas Power & Light Co. 81/01/14 1p
07487 038

8101200399 Forwards LER 80-093/03L-0
TRIMBLE, D C Arkansas Power & Light Co 81/01/15 1p 07477 361

--8101200406 LER 80-093/03L-0 on 801220, emergency diesel generator tripped on reverse power on breaker closure Caused by operator applying manual generator load increased too slowly Operators instructed on importance of applying load quickly
SHIVELY, C N Arkansas Power & Light Co 81/01/15 1p
07477 361

8101270577 Forwards updated LER 80-039/03X-1
TRIMBLE, D C Arkansas Power & Light Co 81/01/19 1p 07541 139

--8101270585 Updated LER 80-037/03X-1 on 800727 & 1231, during M operation, core operating limits supervisory sys declared inoperable Caused by integrated detector flux array becoming altered on 800727 & sig input/output failure on 801231
SHIVELY, C N Arkansas Power & Light Co 81/01/19 1p
07541 139

V Operator Examinations

8101060359 Forwards info re NUREG-0737, in response to NRC 80103t ltr. Includes info re staff technical advisor procedures for transients & accidents, plant shielding & thermal shock report, TRIMBLE, D C Arkansas Power & Light Co. 80/12/31 9pp

8101270356 Requests clarification of position re items 11 B 1 & 11 B 4 to NUREG-0737, re reactor coolant sys vents & training for mitigating core damage
TRIMBLE, D C Arkansas Power & Light Co 81/01/19 3pp

DOCKEY 50-359 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness / Lateral Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

8101050107 Forwards nonradiological environ protection plan for Facility. Certain portions of plan revised to comply w/NRC efforts to standardize environ programs
YOUNG, G L J Licensing Branch 1 80/12/10 3pp 07379 307

--8101050105 Environ protection plan (nonradiological) for Facility
Commissioners 80/12/10 11pp 07379 310

8101070624 Ack receipt of 801112 re hydrogen control measures. Addl info requested re all recently developed info pertinent to evaluation of hydrogen control measure
TERDESCO, R L Assistant Director for Licensing 80/12/19 2pp 07414 129

810120271 Forwards summary of 001217 meeting w/util in Bethesda, MD re auxiliary feedwater sys reliability evaluation
KUNIN, L D J Licensing Branch 1 80/12/27 2pp 07446 319

--8101060350 Summary of 801217 meeting w/util in Bethesda, MD re improving reliability of auxiliary feedwater sys
PARKER, W D Auxiliary Systems Branch 80/12/19 3pp 07446 326

8101190220 Forwards list of 1LD station locations near facility & proposed rule for exchanging ILOs (re NRC direct radiation monitoring network w/o encls)
SICHEL, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07475 309

8101150911 Notification of 810108 meeting w/util in Bethesda, MD to discuss surveillance requirements for piping sys snubbers & exemption request (waived) from mechanical snubber requirements.
BIRKEL, R A Licensing Branch 1 81/01/02 3pp 07464 360

8101220133 Forwards "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," Vol 1
PARKER, W D Duke Power Co 81/01/05 1p 07474 010

--8101220138 "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," Vol 3
Duke Power Co 81/01/05 78pp 07474 011

8101230493 Forwards proposed Tech Specs, changing explosive gas mixtures in tanks w/radioactive effluents & detoting hydrogen monitor requirement for waste gas holdup sys
PARAER, W D Duke Power Co 81/01/12 1p 07511 149

--8101230496 Proposed Tech Specs Sections 3 & 4 changing explosive gas mixtures in tanks w/radioactive effluents & detoting hydrogen monitor requirement for hydrogen monitor in waste gas holdup sys
Duke Power Co 81/01/12 9pp 07511 150

8101200160 Requests amend to License NPF-9, changing wording of Section 2 C. (12). Design of engineered safety features sys provides that all safety-related equipment will remain in emergency mode when actuations signal is reset
PARKER, W D Duke Power Co 81/01/27 1p 07309 031

E NRC Safety Evaluation Report (SER), suppls & correspondence

8101270931 SAFETY EVALUATION REPORT RELATED TO OPERATION OF MCQUIRE NUCLEAR STATION, UNITS 1 AND 2
Office of Nuclear Reactor Regulation, Director NUREG-0422 504 81/01/31 100pp Available at NTIS \$6.00 07541 252

F Security, medical, emergency & fire protection plans

8101090287 Ltr to all licensees of operating reactor plants. CP held by CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FEAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

8101150169 Forwards safeguards contingency plan. Revision 1. Revision withheld (ref 10CFR2 790)
PARKER, W D Duke Power Co 80/12/17 1p 07462 213

8101100753 Requests that encl facility emergency planning info be made publicly available w/o encl
SCUDER, J L Division of Rules and Records 80/12/31 1p 07443 357

8101150462 Informs that NRC approved guard training & qualification plan will be implemented. Security plan revision deleting att commitments not included. Approved plan will be submitted
PARKER, W D Duke Power Co 81/01/02 1p 07463 003

8101160443 Outlines util actions & schedule for implementing amended NRC fire protection regulations. NRC consideration of proposed schedule as license condition or Unit 1 requested. Schedule will be incorporated into Unit 2 const schedule
PARKER, W D Duke Power Co 81/01/09 2pp 07470 082

8101190689 Requests that encl facility emergency planning info be made publicly available w/o encl
SCUDER, J L Division of Rules and Records 81/01/09 1p 07472 319

8101290158 Forwards facility emergency planning info to be made publicly available w/o encl
SCUDER, J L Division of Rules and Records 81/01/23 1p 07575 158

8101300436 Advises that util purchased Class 350 file cabinets & flammable liquid storage cabinets for use in interior rooms of control room area. Class C doors installed. Additions should provide 1 1/2-h fire rating.
PARKER, W D Duke Power Co 81/01/27 1p 07582 393

G Adjudicatory correspondence

8101050372 Request, submitted by Board of Commissioners, to participate as official observer in reopened hearings re facility
Pertinent documents requested
FOX, D D Mecklenburg County, NC 80/12/23 1p 07376 289

8101090062 Notice of JL Riley 010114 deposited in Charlotte, NC to ascertain extent of Carolina Environ Study Group case re upcoming administrative hearing. Certificate of Evc encl.
POTTER, W L Duke Power Co 80/12/31 2pp 07427 303

8101090341 Notice of ASLAB constitution AS Resenthal, chairman & JL Riley & AS Salzman, members
TOMPKINS, D A Atomic Safety and Licensing Appeal Panel 81/01/01 1p 07423 283

8101090264 Memorandum & order concluding stay of ASLB 801125 order re warranted, affirming order to extent reviewed & advising Commission that order raises no issues requiring preempt policy guidance
BISHOP, C J Administrative Branch 81/01/06 4pp 07424 039

8101200395 Responds to Intervenor Carolina Environ Study Group 801122, 28 & 810108 interrogatories & requests for documents. Certificate of Evc encl.
ISRAEL, B Reliability & Risk Assessment Branch JOHNSTON, W V Performance Branch CURTIS, J R Regulations Division 81/01/13 38pp 07486 276

8101090485 Informs of retainerment as co-counsel w/JL Riley for Intervenor Carolina Environ Study Group. Requests all documents re hearings. Appointment should enable advancement of intervenors position. Affirmation of Evc encl.
BLUM, S Blum, S 81/01/07 2pp 07309 001

8101140958 Motion to suppl 801107 Contentions 5 & 6 w/memorandum of Evc. No objection to extension for reply. Certificate of Evc encl.
COHN, D B Public Citizen Litigation Group COHN, D B Carolina Environmental Study Group 81/01/08 4pp 07458 247

B101220210 Requests participation as interested govt body due to involvement in emergency planning
K13X.E Charlotte, NC 01/01/13 1p 0750J 250

B101220910 Refuses request for addl documents Atty not retained by Carolina Environ Study Group, as previously stated & group has been furnished documents w/o encl of Comptroller General decision re procedural assistance
METCHELLEN, E O Hearing Branch 4 01/01/16 1p 0750I 337

B101260209 Response to Mocklenburg County Board of Commissioners & City of Charlotte 801231 & 801113 requests to participate Applicant has no objection Certificate of Evc encl
FORTER, W L, MCCAHRY, J M Duke Power Co 01/01/19 3pp 07523 304

B101260711 Memorandum supporting Carolina Environ Study Group Motion to add Contentions 5 & 6 advanced in 801107 reply to applicant motion for summary disposition Notice of appearance & Certificate of Evc encl
COMB, B B Carolina Environmental Study Group 01/01/21 23pp 07536 034

H General correspondence

B101050371 Expresses concern that containment bldg at facility does not have enough strength to hold pressure during accident akin to that of TMI Mock evacuation needed in Charlotte, NC
SHIELDS, J Affiliation Unknown 00/12/15 2pp 07309 001

B101100119 Responds to 800910 ltr expressing concern re implementation of emergency plan for facility Plans are currently under review & must meet NRC criteria prior to issuance of PL
METCHELLEN, E O Hearing Branch 4 00/12/15 1p 07445 013

B101230629 Responds to 801002 ltr re emergency & evacuation plans for facility GL hearings will address issue of emergency plans NRC will determine if evacuation plans meet requirements
METCHELLEN, E O Hearing Branch 4 00/12/15 1p 07512 275

B101050378 Expresses concern re water problems generated by facility urges NRC to reopen licensing hearings
ELLIS, B Affiliation Unknown 00/12/20 2pp 07309 001

B101090680 Demands licensing hearing be reopened Cites NRC 800626 rept. BECY-90-107, showing facility containment pressure stds to be less stringent than TMI stds
HEST, S P., HODGES, J M Affiliation Unknown 01/01/01 1p 07442 067

B101090680 Comments that facility is not safe, since hydrogen pressure equal to that of TMI accident could not be held by containment walls Certificate of Evc encl
UNDERWOOD, M A Affiliation Unknown 01/01/01 3pp 07309 001

B101090514 Requests that public hearings re facility licensing be reopened Until containment integrity is inadequate for withstanding hydrogen pressure event similar to TMI incident
UNDERWOOD, M A Affiliation Unknown 01/01/07 1p 07309 001

B101220216 Requests that licensing hearings be reopened to resolve health & safety issues Certificate of Evc encl
GUYTON, W M Affiliation Unknown 01/01/11 3pp 07503 291

J Insurance & Indemnity Information

B101290419 Confirms increase in liability limit under Policy MF-248 under EB-67 providing coverage under secondary financial protection policy has been executed & becomes effective on licensing date
WAINES, H American Nuclear Insurers 01/01/23 1p 07309 001

B101290591 Confirms MAELU Policy MF-101 coverage
ROBERTS, D Duke Power Co 01/01/23 1p 07103 001

Q Inspection reports, IE Bulletins & correspondence

B101070320 Forwards supplemental responses to NRC 801016 ltr re violations noted in IE Insp Repts 50-369/80-08, 50-370/80-03, 50-413/80-09, 50-414/80-09, 50-491/80-02, 50-492/80-06 & 50-493/80-06 Final rept to be submitted by 801131
PARKER, W O Duke Power Co 00/11/11 2pp 07413 305

B101150015 Forwards IE Insp Rept 50-369/80-74 on 801103-06 No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 00/12/05 2pp 07462 153

B101150017 IE Insp Rept 50-369/80-74 on 801103-06 No noncompliance noted Major areas inspected: 1) radioactive material radiation protection & ALARA considerations.
IRAMP, G L Region 2, Atlanta, Office of the Director 0185
Region 2, Atlanta, Fuel Facility & Materials Safety Branch
00/12/03 2pp 07452 155

B101070145 Ack receipt of IE Insp Rept 50-369/80-74 on 800804-07 proprietary info
PARKER, W O Duke Power Co 00/12/11 1p 07469 020

--B101070152 Forwards IE Insp Rept 50-369/80-74 on 800804-0730 No noncompliance noted
LEWIS, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 00/11/11 2pp 07409 021

--B101070159 IE Insp Rept 50-369/80-74 on 800804-0730 No noncompliance noted Major areas inspected: preoperational test witnessing, procedure review & previous Insp Findings Followup
BOWEN, T J, SMITH, C M II, SAINTECH, P Region 2, Atlanta, Office of the Director 00/11/10 2pp 07409 023

B101060223 Forwards IE Info Notice 80-44, "Activation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
B GELLY, J P Region 2, Atlanta, Office of the Director 00/11/10 1p 07391 034

B101150987 Forwards Revision 4 of response to IE Bulletin 79-02, documenting commitment to complete necessary repairs prior to fuel load
PARKER, W O Duke Power Co 00/12/16 6pp 07465 001

B101150765 Ack receipt of IE Insp Rept 50-369/80-36 on 801103 No noncompliance noted
PARKER, W O Duke Power Co 00/12/23 1p 07465 380

--B101150769 Forwards IE Insp Rept 50-369/80-36 on 801107 No noncompliance noted
MUMFORD, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/11/05 2pp 07465 301

--B101150773 IE Insp Rept 50-369/80-36 on 801103-06 No noncompliance noted Major areas inspected: preservice insp data review & evaluation
ECCLES, D S Region 2, Atlanta, Office of the Director 00/11/05 4pp 07465 303

B101160725 Ack receipt of IE Insp Repts 50-369/80-33 & 50-370/80-10 on 801104-07 No proprietary info
PARKER, W O Duke Power Co 00/12/31 1p 07472 047

--B101160720 Forwards IE Insp Repts 50-369/80-33 & 50-370/80-10 on 801104-07 No noncompliance noted
MUMFORD, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/12/12 2pp 07472 041

--B101160734 IE Insp Repts 50-369/80-33 & 50-370/80-10 on 801104-07 No noncompliance noted Major areas inspected: IE bulletins & licensee identified items
KCFARLAND, C R Region 2, Atlanta, Office of the Director 00/12/11 7pp 07472 050

B101290404 Responds to IE Bulletin 80-21, "Valve Yokes Supplied Malcolm Foundry Co, Inc." No valves have been identified from Malcolm Foundry One manufacturer has not responded
PARKER, W O Duke Power Co 01/01/09 1p 07573 357

B101290492 Ack receipt of IE Insp Rept 50-369/80-34 No proprietary info
PARKER, W O Duke Power Co 01/01/09 1p 07575 169

S Reportable occurrences, EIRs & related correspondence

B101260513 Suppl 1 to Significant Deficiency Repts 50-369/80-21 80-16 re failure to consider containment vessel dynamic movements due to postulated LOCA, initially reported 801126 Analysis revised
PARKER, W O Duke Power Co 01/01/09 3pp 07529 278

DOCKETED ITEMS

8101260311 Memorandum supporting Carolina Environ Study Group Motion to add Contentions 5 & 6 advanced in 801107 reply to applicant motion for summary disposition Motion of appearance & Certificate of Hvc enrl
CHAMBERS, B Carolina Environmental Study Group 81/01/21 23pp
07536:034

II General correspondence

8101050371 Expresses concern that containment bldg at facility does not have enough strength to hold pressure during accident akin to that of TMI Mock evacuation needed in Charlotte, NC
SHELDON, J Affiliation Unknown 80/12/15 2pp 07309 001

8101100119 Responds to 800930 ltr expressing concern re implementation of emergency plan for facility Plans are currently under review & must meet NRC criteria prior to issuance of OL
VEICHEN, E G Hearing Branch 4 80/12/15 1p 07445 015

8101230629 Responds to 801002 ltr re emergency & evacuation plans for facility OL hearings will address issue of emergency plans NRC will determine if evacuation plans meet requirements
VEICHEN, E G Hearing Branch 4 80/12/15 1p 07512 275

810105037B Expresses concern re water problems generated by facility Urges NRC to reopen licensing hearings
ETLIS, B Affiliation Unknown 80/12/20 2pp 07309 001

8101090600 Demands licensing hearing be reopened Cites NRC 800626 repts. 6ECY-80-107, showing facility containment pressure aids to be less stringent than TMI stds
MCST, S P., HODGES, J M Affiliation Unknown 81/01/01 1p 07442 067

8101090690 Comments that facility is not safe, since hydrogen pressure equal to that of TMI accident could not be held by containment walls Certificate of Hvc enrl
UNDERWOOD, M A Affiliation Unknown 81/01/01 3pp 07309 001

8101090514 Requests that public hearings re facility licensing be reopened. OL11 containment integrity is inadequate for withstanding hydrogen pressure event similar to TMI incident
UNDERWOOD, M A Affiliation Unknown 81/01/07 1p 07309 001

8101220216 Requests that licensing hearings be reopened to resolve health & safety issues Certificate of Hvc enrl
CUPION, W H Affiliation Unknown 81/01/11 3pp 07503 251

III Insurance & Indemnity information

8101290419 Confirms increase in liability limit under Policy NF-248 Binder EB-69 providing coverage under secondary financial protection policy has been executed & becomes effective on licensing date
MAINES, H American Nuclear Insurers 81/01/23 1p 07309 001

8101290591 Confirms MAELU Policy MF-101 coverage.
ROBERTS, D Duke Power Co. 81/01/23 1p 07183 001.

IV Inspection reports, IE Bulletins & correspondence

8101070320 Forwards supplemental responses to NRC 801016 ltr re violations noted in IE Insp Repts 50-369/80-03 & 50-370/80-03, 50-413/80-07, 50-414/80-09, 50-491/80-02, 50-492/80-06 & 50-493/80-06. Final rept to be submitted by 010131
PARKER, W D Duke Power Co 80/11/11 2pp 07413 305.

8101060225 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07391:334

810110907 Forwards Revision 4 of response to IE Bulletin 79-02, documenting commitment to complete necessary repairs prior to fuel load.
PARKER, W D Duke Power Co 80/12/16 5pp 07465 001

8101160724 Ack receipt of IE Insp Repts 50-369/80-03 & 50-370/80-18 on 801104-07 No proprietary info
PARKER, W D Duke Power Co 80/12/31 1p 07472:047.

8101160728 Forwards IE Insp Repts 50-369/80-03 & 50-370/80-18 on 801104-07. No noncompliance noted
PARKER, W D Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/11 7pp 07472:050

8101160724 IE Insp Repts 50-369/80-03 & 50-370/80-18 on 801104-07. No noncompliance noted Major areas inspected IE bulletins & licensee identified items
PARKER, W D Region 2, Atlanta, Office of the Director 80/12/11 7pp 07472:050

8101290404 Responds to IE bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No valves have been identified from Malcolm Foundry Co. manufacturer has not responded
PARKER, W D Duke Power Co 81/01/05 1p 07573 357

V Reportable occurrences, TFRs & related correspondence

8101260513 Suppl 1 to Significant Deficiency Repts 50-369/80-21 & 50-16 re failure to consider containment vessel dynamic movements due to postulated LOCA. Initially reported 801126
Analysis revised
PARKER, W D Duke Power Co 81/01/09 3pp 07529 238

DOCKET 80-373 LASALLE COUNTY STATION, UNIT 1

A Application/Construction stage documents & correspondence

8101300297 Forwards "LaSalle County Units 1 & 2 Equipment Qualification" Vol 1-3 & "LaSalle 1 & 2 NSSS Safety-Related Equipment List" Revision 1 Repts available in Central Files only
SINKAPAL, J Sergeant & Lundy, Inc 80/10/30 1p 07183 001

8101220466 Ltr to all power reactor licensees & applicants forwards summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar tearing on Component Supports"
TEDESCO, R L Division of Licensing 80/11/26 8pp

8101190505 Ltr to all BWR applicants for FL re BWR scram discharge safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge vol enrl
TEDESCO, R L Assistant Director for Licensing 80/12/22 2pp

8101190514 Forwards generic safety evaluation re BWR scram discharge Repts identified two additional requirements to those proposed by owners group re scram discharge vol designs Rept should be transmitted to license applicants
CHEN, P S Assistant Director for Plant Systems 80/12/01 2p 07183 001.

8101200157 Summary of 801210 meeting w/Mark II owners re status of generic improved chugging load model Owners requested to justify delay in program & investigate alternatives
ANDERSON, C J Generic Issues Branch 80/12/22 4pp

8101100283 Forwards trip rept of 801024-31 site visit to perform drawing review
BRUNHA, A Licensing Branch 1 80/12/29 3pp 07444 203

8101110955 Summary of Dec 1980 meeting w/Mark II owners group, GE, BN, MIT, RW, Buchtel & Ebasco Svcs. Inc re suppression pool temp limits list of attendees & handouts enrl
EUTN Generic Issues Branch 80/12/10 11pp

8101140512 Forwards suppl info re valve discharge case design basis Frequency range & air clearing load assessment per 801120 telcon
DELGECRE, L O Commonwealth Edison Co 81/01/08 5pp 07461 1

8101200245 Forwards Licensing topical Rept KEOB-24057A, "Assessment Reactor Internals Vibration in BWR/4 & BWR/5 Plants," & NRC evaluation
DELGECRE, L O Commonwealth Edison Co 81/01/15 2pp 07407 0

8101290794 Forwards floodplain aspects Plant structures will have negligible effect on post-onset water levels during flood
VIGOR, B J Licensing Branch 1, 81/01/16 4pp 07569 001

8101300818 Requests commitments to special low power test program for facility & augmented operator training for compliance w/TMI test action item 1.0
TEDESCO, R L Assistant Director for Licensing 81/01/16 3pp 07183 001

8101220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task 111 A 2
DELGECRE, L O Commonwealth Edison Co 81/01/19 1p

- 610123174 Offsite Dose Calculation Sys Teleological Monitoring,
Offsite Dose Calculation Program For Emergency Preparedness
at Operating Nuclear Power Plants, Revisior 2
COMMONWEALTH Edison Co 60/07/31 120pp

--610123279 Study of Low Level Dispersion Over Northern IL
* Murray S Treitel, Inc 74/06/30 106pp

F. Security, medical, emergency & fire protection plans

6101290257 Ltr to all licensees of operating reactor plants, CP holders
A CP applicant's Revised radiological emergency response
plans must be submitted by licensees within 60 days of
610107 & by applicants as part of FSAR
EDISON, J. D. Division of Licensing, 80/11/12 2pp

J. Insurance & liability information

610127014 Forwards Endorsements 125 & 126.65 & 66.53 & 94, & 13 & 14
to MELA Policies NF-43, NF-107, NF-201 & NF-253, respectively
OSTEP, J. Commonwealth Edison Co 81/01/21 13pp

Utility Final Safety Analysis Report (FSAR) & amendments

6101190352 Forwards affidavit stating that distribution of FSAR
Amend 53 has been made
DELGEOGE, L. D. Commonwealth Edison Co 60/12/30 2pp 07476 037

P. Operating license stage documents & correspondence

6101290601 Forwards Revision 15 pages to CE-1-A-04 program topical
rept. Revisions reflect Section 1980 addenda to Section III of
ASPE code & recent ASPE survey for renewal of ASPE
corporate certifications
ABEL, J. S. Commonwealth Edison Co 81/01/02 1p

- 6101290605 Revision 15 pages to OA program topical rept
* Commonwealth Edison Co CE-1-A R15 81/01/02 57pp

Q. Inspection reports, IL Bulletins & correspondence

6101290749 Forwards IF Info Notice 80-18, "Cracking in Charging Pump
Casing Cladding." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director, 60/10/30
2pp

6101290462 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm
Foundry Co, Inc." Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 03/11/06
2pp

6101130574 Forwards IF Insp Rept 50-373/80-43 on 800915-1020 & notice
of violation
KEPPLER, J. G. Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/11/12 2pp 07453 214

--6101130593 Notice of violation from insp on 800915-1020
* Region 3, Chicago, Office of the Director 80/11/10 1p
07453 216

--6101130592 IE Insp Rept 50-373/80-43 on 800915-1020 Noncompliance
noted, failure to notify NRC of each design & const
deficiency
WALKER, R. O., SHEPLEY, S. E., SPESSARD, R. L. Region 3, Chicago, Office
of the Director 80/11/10 13pp 07453 217

6101140847 Forwards IE Insp Repts 50-373/80-47 & 50-374/80-29 on
801027-31 No noncompliance noted
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety
Branch 80/12/04 2pp 07461 040

--6101140853 IE Insp Repts 50-373/80-47 & 50-374/80-29 on 801027-31. No
noncompliance noted. Major areas inspected: emergency
planning, coordination w/ offsite agencies & emergency
planning exercise discussion
DERSTHAM, M. J., AYLESCH, W., PAPERIE, L. D. C. J. Region 3, Chicago,
Office of the Director 80/12/05 9pp 07461 042

6101030930 Forwards IF Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Steam Discharge Vol at Brecken Unit 2." No
response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director, 80/12/05
2pp

6101150779 Forwards IF Insp Rept 50-373/80-51 on 801125-26 No
noncompliance noted
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety
Branch 80/12/09 2pp 07465 307

- 6101150787 IE Insp Rept 50-373/80-51 on 801125-26 No noncompliance
noted. Major areas inspected: radwaste mgmt program & FSAR
commitment conformance
OVERBALE, P. C. Region 3, Chicago, Office of the Director
FISHBURN, R. L. Region 3, Chicago, Fuel Facility & Materials Safety
Branch 80/12/08 3pp 07465 309

6101150634 Forwards IE Insp Repts 50-373/80-50 & 50-374/80-31 on
801119-21 & notice of violation
KEPPLER, J. G. Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/12/12 2pp 07465 280

--6101150658 Notice of violation from insp on 801119-21
KEPPLER, J. G. Region 3, Chicago, Reactor Operations Nuclear
Support Branch 80/12/11 2pp 07465 282

--6101150653 IE Insp Repts 50-373/80-50 & 50-374/80-31 on 801119-21
Noncompliance noted: various fire fighting hose mounts
constructed by const. mfg.; several counts damaged or
improperly made up & several isolation valves inoperable
BUONICCONTI, S. G., SPESSARD, R. L. Region 3, Chicago, Office of the
Director, 80/12/11 5pp 07465 284

6101080368 Forwards IE Info Notice 80-45, "Potential Failure of DWR
Startup Manual Start Capability." No written response
required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/17
2pp

6101150230 Forwards Suppl. 4 to IE Bulletin 80-17, "Failure of Control
Rods to Insert During Scram at BWR." No written response
required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/18
2pp 07465 345

6101050186 Forwards IE Bulletin 80-25, "Operating Problems w/ Target
Rod Safety Relief Valves at DWRs." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director, 80/12/17
2pp 07377 319

6101130657 Responds to 801114 ltr re IE Bulletin 80-23 No Velco
solenoid valves V70900-21-1 or V70900-21-3 are in use at
LaSalle County Station. Dept. addressing affected valves at
Fernald & Braidwood Stations to be submitted by 810212
PAUSCILLI, J. Commonwealth Edison Co 80/12/29 2pp 07454 033

6101290528 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co, Inc." LaSalle County Station contains 138
safety-related valves cast by Malcolm & mfg by Anchor-
Darling Valve Co. Valves will be replaced
MAUSCILLI, J. Commonwealth Edison Co 81/01/06 2pp 07487 046

6101270851 Ack receipt of 801215 ltr in response to item of
noncompliance noted in IE Insp Rept 50-373/80-43. Improper
tagging wiring on Control Room Panel H13-P603 must be
reported as significant deficiency per 10CFR50.55(a)
KEPPLER, J. G. Region 3, Chicago, Office of the Director 81/01/01
2pp 07549 122

6101230339 Forwards request for addl info re 800708 response to IE
Bulletin 80-11, "Masonry Wall Design." Info is needed on how
loads are transferred from walls to columns & design
adequacy of walls w/o relying on tensile stresses.
TEDESCO, R. L. Assistant Director for Licensing, 81/01/19 4pp
07575 228

S. Reportable occurrences, IERs & related correspondence

6101050415 Provides 30-day notification of possible deficiency re
incorrect suppression pool water vol in FSAR, initially
reported 801126. Caused by diffused responsibility for
calculation. Pool temp transient will be reanalyzed.
DELGEOGE, L. D. Commonwealth Edison Co 80/12/24 2pp 07379 20

6101230417 Final deficiency rpt re electrical termination lug dosing
Insp of control room panels & replacement of improper lugs
completed.
ABEL, J. S. Commonwealth Edison Co 81/01/19 2pp 07611 118

6101230433 Final deficiency rpt re valve yoke matl in Anchor/Darling
Valves, initially reported on 801218. Schedule has been
established for shipment of 138 new yokes between 810227 &
0424. Defective yokes will be replaced & destroyed.
DELGEOGE, L. D. Commonwealth Edison Co 81/01/19 2pp 07611 118

V Operator Examinations

B010300810 Requests commitments to special low power test program for facility & augmented operator training for compliance w/THI task action item 1.0 1
 TEDESCO, R.L. Assistant Director for Licensing B1/01/16 3pp
 07183 001

DOCKEY 90-374 LASALLE COUNTY STATION, UNIT 2

A Application/construction stage documents & correspondence

B010300297 Forwards "LaSalle County Units 1 & 2 Equipment Qualification," Vols 1-3 & "LaSalle 1 & 2 NSSS Safety-Related Equipment List." Revision 1 Repts available in Central Files only
 SINRIAN, J. Bargon & Lundy, Inc B0/10/30 1p 07103 001

B010220464 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
 EISENHUT, D.O. Division of Licensing B0/11/26 0pp

B010200157 Summary of B01210 meeting w/Mark II owners re status of generic improved chugging load model. Owners requested to justify delay in program & investigate alternatives
 ANDERSON, C.J. Generic Issues Branch 00/12/22 4pp.

B010100263 Forwards trip rept of B01024-31 site visit to perform drawing review
 BURNIA, A. Licensing Branch 1 B0/12/27 3pp 07444 233

B010100955 Summary of Dec. 1980 meeting w/Mark II owners group, OE, BNL, MIT, BWH, Bachtel & Esasco Svcs, Inc re suppression pool temp limits list of attendees & handouts and
 EU, T.M. Generic Issues Branch 00/12/30 4pp

B010100512 Forwards suppl info re valve discharge case design basis frequency range & air clearing load assessment per B01120 telcon
 DELGEORGE, L.D. Commonwealth Edison Co B1/01/08 3pp 07461 162

B010200243 Forwards Licensing Topical Rept NEDU-24057A, "Assessment of Reactor Internals Vibration in BWR/4 & BWR/5 Plants." & NRC evaluation
 DELGEORGE, L.D. Commonwealth Edison Co B1/01/15 2pp 07407 001

B010200394 Forwards floodplain aspects Plant structures will have negligible effect on post-consol water levels during flood
 YOUNGBLOOD, B.J. Licensing Branch 1 01/01/16 4pp. 07569 001

B010300818 Requests commitments to special low power test program for facility & augmented operator training for compliance w/THI task action item 1.0 1
 TEDESCO, R.L. Assistant Director for Licensing B1/01/16 3pp
 07183 001

B010220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task III, A.2
 DELGEORGE, L.D. Commonwealth Edison Co B1/01/19 1p

--B010220374 "Offsite Dose Calculation Sys Meteorological Monitoring, Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants," Revision 2
 BOLOEN, J.C. Commonwealth Edison Co 00/07/31 130pp

--B010220379 "Study of Low Level Dispersion Over Northern IL."
 * Murray & Trattel, Inc 74/06/30. 106pp

F Security, medical, emergency & fire protection plans

B010200387 Ltr to all licensees of operating reactor plants. CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B010102 & by applicants as part of FBAR
 EISENHUT, D.O. Division of Licensing B0/11/13 2pp

A Utility Final Safety Analysis Report (FSAR) & amends

B010100352 Forwards affidavit stating that distribution of FBAR Amend 53 has been made
 DELGEORGE, L.D. Commonwealth Edison Co B0/12/30, 2pp 07476 027.

F Operating license stage documents & correspondence

B010C90003 Forwards Revision 15 pages to CE-1-A.0A program topical rept. Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
 ASSEL, J.S. Commonwealth Edison Co 01/01/02 1p

--B010C90603 Revision 15 pages to QA program topical rept
 * Commonwealth Edison Co CE-1-A R15 B1/01/02. 37pp

O Inspection reports, IF Bulletins & correspondence

B010506249 Forwards IE Info Notice 00-38. "Cracking in Charging Pump Casing Cladding." No response required
 KEPLER, J.G. Region 3, Chicago, Office of the Director B0/10/30 2pp

B01050462 Forwards IF Bulletin 80-21. "Valve Voles Supplied by Mol Founary Co, Inc." Written response required
 KEPLER, J.G. Region 3, Chicago, Office of the Director B0/11/00 2pp

B010100847 Forwards IE Insp Repts 90-373/80-47 & 90-374/80-29 on B01029-31 No noncompliance noted
 DAVIS, A.H. Region 3, Chicago, Fuel Facility & Materials Safety Branch B0/12/04. 2pp 07461 040

--B010100858 IE Insp Repts 90-373/80-47 & 90-374/80-29 on B01029-31 noncompliance noted. Major areas inspected: emergency planning, coordination w/offsite agencies & emergency planning exercise discussion
 CEBTHAN, H.J., AXELSON, W., PAPERIELLO, C.J. Region 3, Chicago, Office of the Director B0/12/05 7pp 07461 042

B01050530 Forwards IE Info Notice 00-43. "Failures of Continuous Level Monitor for Scram Discharge Val at Dresden Unit 2." No response required
 KEPLER, J.G. Region 3, Chicago, Office of the Director B0/12/00 2pp

B010100651 Forwards IE Insp Repts 90-373/80-50 & 90-374/80-31 on B01119-21 & notice of violation.
 HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/12/12. 2pp 07465 280

--B010100695 Notice of violation from Insp on B01119-21
 HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. B0/12/11 2pp 07465 202

--B010100663 IE Insp Repts 90-373/80-50 & 90-374/80-31 on B01119-21 Noncompliance noted various fire fighting hose mounts obstructed by const motifs, several mounts damaged or improperly rated up & several isolation valves inoperable
 DUPONT, S.O., SPESBARO, R.L. Region 3, Chicago, Office of the Director B0/12/11 3pp 07465 284.

B010200670 Forwards IE Insp Rept 90-374/00-32 on B01117-20 No noncompliance noted
 FIGRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/12/12 2pp. 07512 357

--B010200687 IE Insp Rept 90-374/80-32 on B01117-20 No noncompliance noted. Major areas inspected work activities & nondestructive testing, records & control of equipment & mat'l re installation & welding of safety-related piping
 MEY, W.J. Region 3, Chicago, Office of the Director DANIELSON, D.H. Region 3, Chicago, Reactor Construction & Engineering Support Branch B0/12/10 7pp. 07512 355

B01080060 Forwards IE Info Notice 80-45. "Potential Failure of UW Backup Manual Scram Capability." No written response
 KEPLER, J.G. Region 3, Chicago, Office of the Director B0/12/00 2pp

B010100230 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of Cont Rods to Insert During Scram at BWR." No written response required
 KEPLER, J.G. Region 3, Chicago, Office of the Director B0/12/00 2pp 07465 345.

B01050106 Forwards IE Bulletin 80-25. "Operating Problems w/Target Rod Safety Relief Valves at OHRs." No response required.
 KEPLER, J.G. Region 3, Chicago, Office of the Director. B0/12/00. 07377 319

B101130667 Responds to B01114 ltr re IE Bulletin 80-23 Re Valcor
solenoid valves V70900-21-1 or V70900-21-3 are in use at
LaSalle County Station Repl addressing affected valves at
Byron & Breddood Stations to be submitted by B10212
RAUSCH, T J Commonwealth Edison Co 80/12/29 2pp 07454 833

B101203528 Responds to IE Bulletin 80-21, Valve Yokes Supplied by
Malcolm Foundry Co. Inc. LaSalle County Station contains 138
safety-related valves cast by Malcolm & mfg by Anchor-
Darling Valve Co Valves will be replaced
RAUSCH, T J Commonwealth Edison Co 81/01/06 2pp 07407 846

B101270337 Forwards request for addl info re B030708 response to IE
Bulletin 80-11, "Masonry Wall Design." Info is needed on how
loads are transferred from walls to columns & design
adequacy of walls w/o relying on torsion stresses
IEDESCO, R L Assistant Director for Licensing 81/01/19 4pp
07579 228

R Reportable occurrences, LTRs & related correspondence

B101050415 Provides 30-day notification of possible deficiency re
Incorrect suppression pool water vol in PSAR, initially
reported B01126 Caused by diffused responsibility for
calculation. Pool temp transient will be reanalyzed
DEIGEORCE, L O Commonwealth Edison Co 80/12/24 2pp 07379 287

B101230417 Final deficiency rept re electrical termination lug design
resp of control room panels & replacement of improper lugs
completed
ABEL, J S Commonwealth Edison Co 81/01/19 2pp 07511 118

B101230433 Final deficiency rept re valve yoke matl in Anchor/Darling
Valves, initially reported on B01218 Schedule has been
established for shipment of 138 new yokes between B10227 &
0424 Defective yokes will be replaced & destroyed.
DEIGEORCE, L O Commonwealth Edison Co 81/01/19 2pp 07511 122

V Operator Examinations

B101300810 Requests commitments to special low power test program for
facility & augmented operator training for compliance w/FM
task action item 1 Q 1
IEDESCO, R L Assistant Director for Licensing 81/01/16 3pp

POCKET LO-376 NORTH COAST NUCLEAR PLANT

G Adjudicatory correspondence

B101050632 Response to ASLB B01216 order, supporting applicant B00911
motion for termination of proceeding & withdrawal of
application w/o prejudice, Notice of appearance & Certificate
of Bvc encl
GUTHRIER, J H Hearing Branch 3 80/12/31 14pp 07387 093

B101090094 Reply to intervenor B01203 submittal stating withdrawal
application should be dismissed w/prejudice Accusation of
hidden, deceitful action is unsubstantiated Preceding
should be terminated w/o prejudice W/Certificate of Bvc
AXELRAD, M Puerto Rico Electric Power Authority AXELRAD, M
Lewenstein, Newman, Reiss, Axelrad & Toll 80/12/31 22pp 07426 271

BUCKET 80-382 WATERFORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

B101720465 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issues A-12, "Potential for Low Fracture
Toughness & Laminar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101060728 Notification of changed room assignment for B01223 meeting
w/C-E in Bethesda, MD to receive presentation on proposed
demonstration irradiation of experimental test assemblies
for H1-burnup
TAKAR, M Core Performance Branch 80/12/19 2pp 07401 104

B101070359 Responds to DG Eisenhower 801001 ltr re environ qualification
of safety-related equipment Listing of identified class IE
equipment for which qualification testing has not been
completed encl
MAURIN, L V Louisiana Power & Light Co 00/12/26 3pp 07410 336

B101160025 Notification of B10113-15 meeting w/util in Teft, LA re
performance of caseload forecast to determine priorities for
allocating NRC manpower. Proposed agenda encl
KEG, USEK, S Licensing Branch 2 81/01/05 4pp 07469 262

B101270413 Summary of B01223 meeting w/util & C-E in Bethesda, MD to
discuss demonstration fuel assemblies NRC encourages use of
small numbers of assemblies w/experimental fuel designs
Recommendations to be yield info re safety analysis
PICKERS, O A Core Performance Branch 81/01/14 3pp 07549 039

B101220532 Concurrs w/Oct 1982 fuel load data as determined at NRC
B10113-15 case load forecast panel meeting Applicant
advocates status rept approach to SER, fire protection &
structural engineering reviews
LYATT, J C Louisiana Power & Light Co 81/01/19 2pp 07502 265

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of PSAR
EISENHUT, D O Division of Licensing 00/11/13 2pp

B101100034 Amended notification of B10107 meeting w/util in Bethesda, MD
to discuss physical security plan & operator training
MAHE, W F Licensing Branch 2 80/12/24 3pp 07443 028

B101140473 Notification of B10107 meeting w/util in Bethesda, MD to
discuss physical security plan
MAHE, W F Licensing Branch 2 80/12/24 3pp 0745B 144

M Antitrust correspondence

B101140893 Requests that files on util activities be made available to
NRC for CL antitrust review
RUTHERFORD, J Antitrust Division 81/01/09 1p 07308 001

Q Inspection reports, IE Bulletins & correspondence

B101070257 Forwards IE Mgt Meeting Rept 90-332/80-29 on B01027
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/11/14 1p 07415 108

--B101070261 IE Mgt Meeting Rept 90-382/80-29 on B01027 Mejer area
discussed licensee performance evaluation.
SEYFRIT, K V, CRUSMAN, W A Region 4, Dallas, Office of the
Director, SEIDLE, W C, Region 4, Dallas, Reactor Construction &
Engineering Support Branch 80/11/07 9pp 07415 109

B101070247 Forwards IE Insp Rept 90-382/80-25 on B00916-1015 No
noncompliance noted
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 80/11/19 2pp 07415 183

--B101070252 IE Insp Rept 90-382/80-25 on B00916-1015 No noncompliance
noted. Major areas inspected operational staffing, overall
proportional test program & plant tours
CONSTABLE, Q L, GUBOIS, D L, WESTERMAN, R F Region 4, Dallas,
Office of the Director 80/11/10 3pp 07415 185

B101120093 Forwards IE Insp Rept 90-382/80-28 on B01021-24 No
noncompliance noted.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/11/24 2pp 07446 052

--B101120096 IE Insp Rept 90-382/80-28 on B01021-24 No noncompliance
noted. Major areas inspected safety-related const activities
pertaining to electrical cable installation, insp &
documentation
JOHNSON, A R Region 4, Dallas, Reactor Construction & Engineering
Support Branch, MARTIN, L E, STEWART, R C Region 4, Dallas,
Office of the Director 80/11/21 6pp 07446 054

B101140495 Forwards IE Insp Rept 90-382/80-31 on B01117-20 No
noncompliance noted.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/05 2pp 07461 282

--B101140500 IE Insp Rept 90-382/80-31 on B01117-20 No noncompliance
noted. Major areas inspected safety-related electrical cable
& penetration assembly installation const activities.
MARTIN, L E, STEWART, R C, CRUSMAN, W A Region 4, Dallas, Office
of the Director 80/12/05 4pp 07461 284

B101050621 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Scram Discharge Vol at Dresden Unit 2." No
response required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/08
1p 07391 055

8101209502 Forwards IE Investigation Rpt 50-382/80-17 on 800731-0801.
21.0918 & 1119-21 No noncompliance noted
SEIDLE, W. C. Region 4, Dallas. Reactor Construction & Engineering
Support Branch 80/12/09 2pp 07477 330

--8101200508 IE Investigation Rpt 50-382/80-17 on 800731-0901.21.0918 &
1119-21 No noncompliance noted Major areas investigated
allegations re possible const deficiencies
STEWART, R. C., CROSSMAN, W. A. Region 4, Dallas. Office of the
Director 1041 INSON, O. P. Region 4, Dallas. Reactor Construction &
Engineering Support Branch 80/12/09 9pp 07477 332

--8101200508 IE Investigation Rpt 50-382/00-17 on 800731-0801.21.0918 &
1119-21 No noncompliance noted Major areas investigated
allegations re possible const deficiencies
STEWART, R. C. Region 4, Dallas. Office of the Director HALL, R. E.
Region 4, Dallas. Reactor Construction & Engineering Support
Branch 00/12/09 9pp

8101060187 Forwards IE Info Notice 80-44. "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown." No written
response required
SEYFRIT, K. V. Region 4, Dallas. Office of the Director 80/12/16
1p 07391 296

0101100748 Ack receipt of 801128 ltr informing LRC of steps taken to
correct violations noted in IE Insp Rpt 90-382/80-26
SEIDLE, W. C. Region 4, Dallas. Reactor Construction & Engineering
Support Branch 80/12/23 1p 07444 130

--8101100752 Responds to NRC 801031 ltr re violations noted in IE Insp
Rpt 50-382/80-26 Corrective actions lines blown out w/air
& valves capped off
ASHELL, D. L. Louisiana Power & Light Co 80/11/28 3pp
07444 131

S Reportable occurrences, LERs & related correspondence

0101070384 Final Significant Const Deficiency Repts & 10 re emergency
diesel generator defective shafts & springs & defective
emergency diesel generator roller pins. Initially reported
780725 & 1103, respectively. Shafts replaced & pins repaired
ASHELL, D. L. Louisiana Power & Light Co 00/09/23 7pp 07414:099

0101090500 Interim rpt of Significant Const Deficiency 20 re
inadequate design & review of instrumentation seismic
support drawings. Results of review & analysis of drawings
provided. Design change or field change request issued
MCLENNAN, G. O., MILLISER, R. J., WILLO, J. Louisiana Power & Light Co
81/01/09 4pp 07442 079

V. Operator Examinations

8101100034 Amended notification of 010107 meeting w/util in Bethesda, MD
to discuss physical security plan & operator training
KAINE, W. F. Licensing Branch 2 80/12/24 3pp 07443 028

DOCKET 90-367 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

A. Application/construction stage documents & correspondence

8101090067 Releases public version of util emergency plan
FELTON, J. M. Division of Rules and Records 00/11/13 1p
07440 001

--8101090071 Forwards public version of request for Amend 25 to
application for DL, consisting of Revision 2 to emergency
plan
CURTIS, N. H. Pennsylvania Power & Light Co. 80/10/31 1p
07440:003

--0101090075 Public version of Amend 25 to application for CL, consisting
of Revision 2 to util emergency plan
CURTIS, N. H. Pennsylvania Power & Light Co. 80/10/31 1p.
07440:004

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 001112 meeting re implementation of guidance for
Unresolved Safety Issue A-12. "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing 80/11/26 8pp.

8101220069 Notification of rescheduling of 010127-29 meeting to
810303-05 w/util in Allentown, PA re mgt structure &
technical resources.
STARKE, R. M. Licensing Branch 1 80/12/16 3pp 07502 007

8101090902 Forwards request for addl info per review of OL application
in reactor sys area & in procedures & test review branches
TEDESCO, R. L. Assistant Director for Licensing 80/12/22 13pp
07693 266

0101105035 Ltr to all BWR applicants for OL re BWR steam discharge
safety evaluation & requirements Rpt specifying acceptable
basis for continued BWR plant operation & design criteria
for steam discharge vol encl
TEDESCO, R. L. Assistant Director for Licensing 80/12/22 2pp

--8101105034 Forwards generic safety evaluation re BWR steam discharge
sys Review identified two addl requirements to those
proposed by owners group re steam discharge vol designs Rpt
should be transmitted to license applicants
CHICK, P. S. Assistant Director for Plant Systems 80/12/01 1p
07183 001

8101200157 Summary of 801210 meeting w/Mark 11 owners re status of
generic improved chugging load model Owners requested to
justify delay in program & investigate alternatives
ANDERSON, C. J. Generic Issues Branch 00/12/22 4pp

8101080196 Notification of 010115 meeting w/util in Bethesda, MD to
discuss applicant responses to NRC questions & positions
concerning initial test program
STARKE, R. M. Licensing Branch 1 80/12/23 3pp 07421 032

0101210297 Summary of 801110-19 meeting w/PNL in Bethesda, MD re
control room habitability
WILCOX, H. E. Accident Evaluation Branch 80/12/24 4pp 07493 01

8101109555 Summary of Dec 1980 meeting w/Mark 11 owners group, GE, B
MIT, SSW, Jochtel & Ebasco Svcs, Inc re suppression pool temp
limits List of attendees & handouts encl
EAST, M. Generic Issues Branch 80/12/30 41pp

8101104466 Forwards slides presented during 801218 meeting
CURTIS, N. H. Pennsylvania Power & Light Co 81/01/02 1p
07308 001

8101103020 Forwards info re fish impingement & entrainment in respo
to AEL request concerning input to FES Final & operations
phase NPDES permit encl
CURTIS, N. H. Pennsylvania Power & Light Co 01/01/05 44pp
07308 001

8101270482 Guarantees info re facility operations during low river fl
conditions, in response to NRC request Util plans to replace
water taken from Susquehanna River during low flow by
using water from existing reservoir or Pond Hill Reservoir
CURTIS, N. H. Pennsylvania Power & Light Co 01/01/07 1p.
07349 063

8101120189 Forwards Amend 27 to util 790731 application for OLE,
containing Revision 19 to PSAR
CURTIS, N. H. Pennsylvania Power & Light Co. 01/01/09 2pp
07436 001

8101190367 Forwards "Seismic Category 1 Essential Components for
Susquehanna 1 & 2 BWRB Equipment Only," supplementing 001216
equipment qualification info package
CURTIS, N. H. Pennsylvania Power & Light Co 81/01/09 1p
07474 185

--8101190390 "Seismic Category 1 Essential Components for Susquehanna
& 2 BWRB Equipment Only"
Pennsylvania Power & Light Co 81/01/09 88pp 07474 186

8101206825 Requests commitments to spatial low power test program
facility & augmented operator training, for compliance w/THI
test action item 10-1
TEDESCO, R. L. Assistant Director for Licensing 81/01/16 3pp
07183 001

8101260370 Forwards util response to NUREG-0737 THI-related
requirements. Meeting to discuss response requested
CURTIS, N. H. Pennsylvania Power & Light Co 81/01/22 87pp
07525 252

8101260151 Forwards application for amend of CPRR-101 & CPRR-102,
extend const completion dates, Class 1 & Class 11 fee encl
SNAPP, R. A. Pennsylvania Power & Light Co 81/01/23 2pp
07598 042

--8101260158 Application for amend of CPRR-101 & CPRR-102 to extend
completion dates to 820231 for CPRR-101 & 040331 for
CPRR-102
CURTIS, N. H. Pennsylvania Power & Light Co 81/01/23 3pp
07598 014

8101030500 Submits update on farm survey in vicinity of facility
CURTIS, N W Pennsylvania Power & Light Co 81/01/27 2pp
07587 072

D NRC Draft/Final Environmental Statements, suppis & correspondence

8101130320 Forwards info re fish impingement & entrainment in response
to ALE request concerning input to FES Final & operations
phase NPDES permit encl
CURTIS, N W Pennsylvania Power & Light Co 81/01/05 44pp
07388 001

F NRC Safety Evaluation Report (SER), suppis & correspondence

8101050502 Requests schedule of completion for organizational changes
at facility prior to proposed NRC 810127-29 visit re SER
preparation
EISENHART, D G Division of Licensing 80/12/15 2pp 07337 206

F Security, medical, emergency & fire protection plans

8101050367 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 80/11/13 1p
07440 001

8101090071 Forwards public version of request for Amend 25 to
application for DL consisting of Revision 2 to emergency
plan
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p
07440 003

8101090079 Public version of Amend 25 to application for DL consisting
of Revision 2 to util emergency plan
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p
07440 004

8101090060 Public version of util emergency plan, Revision 2
w Pennsylvania Power & Light Co 80/10/31 150pp 07440 005

8101090087 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR.
EISENHART, D G Division of Licensing 80/11/13 2pp

8101140801 Forwards applicant emergency plan per request w/o encl.
Related correspondence.
SNAPP, B A Pennsylvania Power & Light Co 81/01/08 1p
07458 213

8101290146 Notification of 810121 meeting w/util in Bethesda, MD re
facilities emergency, offsite facilities design & applicable
NRC requirements
STARK, R M Licensing Branch 1 81/01/08 3pp 07567 331.

8101210649 Forwards Chemical Engineering Branch request for addl info
re fire protection
TEDESCO, R L Assistant Director for Licensing 81/01/13 12pp
07448 348

8101290154 Forwards facility emergency planning info to be made
publicly available w/o encl.
SOURER, J L Division of Rules and Records 81/01/23 1p
07575 197

G Adjudicatory correspondence

8101120225 Forwards statement of qualifications & affidavit of
CL Miller re Contention 16 Prof qualifications encl
KREGER, W E Assistant Director for Radiation Protection 80/12/04
6pp 07446 137

8101140900 Requests to make limited appearance statement at licensing
hearings Certificate of Svc encl
NOTERMANN, J P Affiliation Unknown 80/12/27 3pp 07438 219.

8101050620 Order granting NRC 801224 motion for extension until 810109
to respond to applicants' motion for partial summary
disposition of Contention 17
BECHTOLD, C Atomic Safety and Licensing Board Panel 80/12/30
2pp 07387 073

8101070202 Notice of RW Adler appearance in & KW Carter notice of
withdrawal from proceeding Certificate of Svc encl
ADLER, R W, CARTER, K W Pennsylvania, State of 80/12/30 4pp
07415 151

8101070527 Order granting intervenor Busquehanna Environ Advocate
801213 motion for extension until 810223 to respond to
Contention & discovery requests
BECHTOLD, C Atomic Safety and Licensing Board Panel 81/01/0
2pp 07406 361

8101090033 Requests time to make limited appearance statement at
hearing in Deloit, PA Certificate of Svc encl
MCLELLAN, R M Affiliation Unknown 81/01/05 1p 07441 178

8101140561 Forwards applicant emergency plan per request w/o encl.
Related correspondence
SNAPP, B A Pennsylvania Power & Light Co 81/01/08 1p
07458 213

8101140611 Response to applicants' 801208 motion for partial summary
disposition of Contention 17 Motion should be granted except
for part re human health effects of electric fields Suppl to
applicants' statement of mat facts encl
LAVERY, J H Hearing Branch 1 81/01/09 12pp 07309 001

8101140017 Affidavit re likely levels & potential impact of aud
noise possibly resulting from transmission lines associated
w/facility Potential for speech interference & activity
interference very low
LEHR, J C Environmental Engineering Branch 81/01/07 9pp
07309 001

8101140028 Affidavit re radio & television interference, shock &
flashover, magnetic field & electric field effects on human
health Magnetic fields will not cause adverse biological
effects Certificate of Svc encl
GEARS, G Environmental Engineering Branch 81/01/08 9pp
07309 001

8101200023 Requests that ASLD formally recognize withdrawal of
Contention 13 C Marsh expressly withdrew contention on Page
13 of 770720 answers to NRC first round interrogatories
LAVERY, J H Office of the Executive Legal Director 81/01/14
2pp 07477 314

8101280628 Informs that action on encl 801216 application for 844
license expected by Jan 1981 Submittal supercedes 801016
application
LAVERY, J H Office of the Executive Legal Director 81/01/14
2pp 07107 001

8101220004 Memorandum & order stating no formal request received
withdraw Marsh Contention 13 Parties may reply by 810130 to
NRC 810109 response to applicants' motion for partial
summary disposition of Contention 17 w/Certificate of Svc
BECHTOLD, C Atomic Safety and Licensing Board Panel 81/01/
4pp 07501 315

8101270298 Response stating that NRC & applicant interrogatories
burdensome & that intervenor lacks resources to reply
Requests GE Revid rept Certificate of Svc encl
JOHNSON, J H Environmental Coalition on Nuclear Power 81/01/
3pp 07546 463

H General correspondence

8101090703 Notifies that on 810108 telephone prefix 821 replaced
for all util general ofc complex telephone numbers. Prefix
change will not affect 4-digit extension numbers.
CURTIS, N W Pennsylvania Power & Light Co 81/01/02 1p
07424 350

K Utility Final Safety Analysis Report (FSAR) & amends

8101120159 Forwards Amend 27 to util 790731 application for DLs,
containing Revision 17 to FSAR
CURTIS, N W Pennsylvania Power & Light Co 81/01/09 2pp
07436 001

8101120194 Amend 19 to FSAR
w Pennsylvania Power & Light Co 81/02/09 175pp 07436 0

L Inspection reports, IE Bulletins & correspondence

8101090553 Ack receipt of 800910 ltr informing NRC of steps taken
correct violations noted in IE Insp Rept 80-387/80-14
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/11/10 1p 07430 225

01090857 Responds to NRC 800818 ltr re violations noted in IE Insp Rept 50-387/80-14 Corrective actions procedures replaced w/procedures having proper approval signature
CURTIS, N W Pennsylvania Power & Light Co 80/09/10 5pp
07439 226

01090862 Forwards IE Insp Rept 50-387/80-14 on 800602-27 & notice of violation
BRUNIER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/18 2pp 07430 231

01090865 Notice of violation from insp on 800602-27
* Region 1, Philadelphia, Office of the Director 80/08/18 2pp
07430 233

01090869 IE Insp Rept 50-367/80-14 on 800602-27 Noncompliance noted use of unapproved plant maint procedure MT-64-003 & failure to follow approved procedures for reporting nonconforming items
GALLD, R H, RHADS, G C Region 1, Philadelphia, Office of the Director MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/18 10pp 07430 235

12310303 Responds to IE Bulletin 80-03, "Loss of Charcoal from Old Type II, Two-Inch Tray Adsorber Cells - One type of cell is used Insp rept results showed no signs of screen casing separation Rept enrl
CURTIS, N W Pennsylvania Power & Light Co 80/11/19 2pp

01070400 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Merry Turbine Steam Inlet Flange " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 077

01050120 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2 " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07376 351

01150041 Ack receipt of 801202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/80-24
BRUNIER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/10 1p 07464 315

0101190846 Responds to NRC 801103 ltr re violations noted in IE Insp Rept 50-387/80-24 Corrective actions Preoperational Test Procedure PIC 1, Revision 1, Test Review Board approval rescinded for procedure revision
CURTIS, N W Pennsylvania Power & Light Co 80/12/02 2pp
07464 316

0101150850 Forwards IE Insp Rept 50-387/80-24 on 800708-1010 & notice of violation
BRUNIER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/03 2pp 07464 318

0101150854 Notice of violation from Insp on 800908-1010
* Region 1, Philadelphia, Office of the Director 80/10/30 1p
07464 320

0101190861 IE Insp Rept 50-387/80-24 on 800908-1010 Noncompliance noted PIC 1, Revision 1 reviewed & approved w/o resolution of comments made by util fire protection engineer
GALLD, R H, RHADS, G C Region 1, Philadelphia, Office of the Director MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/30 16pp 07464 321

01140824 Forwards results of independent teardown analysis/Insp of nine samples of cable w/o encl
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/11 2pp 07461 325

01060138 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07397 354

01070058 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/18 1p 07415 008

01190863 Forwards IE Bulletin 80-25, "Operating Problems w/Target Rod Safety-Relief Valves at BWRs " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/19 1p 07465 322

5 Rectifiable occurrences, LERs & related correspondence

8010100071 Ack receipt of 801020 ltr forwarding interim deficiency rept re excessive voltage drops in ac motor operated valve control circuits Rept will be reviewed & evaluated
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/11 1p 07444 316

--8010100076 Interim deficiency rept re excessive voltage drops in ac motor operated valve control circuits, initially reported on 800918 Util is evaluating alternatives to determine course of action Final rept will be provided in Jan 1981
CURTIS, N W Pennsylvania Power & Light Co 80/10/20 2pp
07444 317

8010503117 Ack receipt of 801028 deficiency rept re loose contact modules on GE Type CR 294C solenoid switches
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 02/11/25 1p 07303 016

801090474 Ack receipt of util 801121 interim deficiency rept re separation criteria for electrical equipment Matter will be reviewed following receipt of final rept
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/09 1p 07337 311

801050398 Ack receipt of util 801121 final deficiency rept re Mill's shell-type expansion anchors Matter will be reviewed during subsequent insp
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/11 1p 07387 314

801090616 Ack receipt of 801121 ltr forwarding final rept re Limiting torque switch deficiencies
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/17 1p 07309 001

801050332 Revised final deficiency rept re improper studding of piping & tubing lines for GE instrumentation Lines will be installed with slogs 1/2 inch per ft
CURTIS, N W Pennsylvania Power & Light Co 80/12/27 3pp
07399 285

8010160550 Ack receipt of util 801117 interim deficiency rept re excessive voltage drops in power supplies to dc motor-operated valves Matter will be reviewed following receipt of final rept
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/23 1p 07471 103

8010160553 Ack receipt of util 801119 final deficiency rept re limit torque limit switch rotors Matter will be reviewed during subsequent insp
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/24 1p 07471 101

8010190779 Ack receipt of util 801209 interim deficiency rept re shimming of base plates
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/24 1p 07473 044

--8010190783 Interim deficiency rept re use of pipe shims around and between equipment floors & equipment base plates, initially reported on 801107 Evaluation underway to determine scope of problem & resolution, including removal of pipe shims
CURTIS, N W Pennsylvania Power & Light Co 80/12/09 6pp
07473 045

8010120362 Interim deficiency rept re use of improperly grounded flexible conduit on safety-related circuits, initially reported on 801210 Caused by manufacturer failure to remove paint from termination module Next rept by Apr 1981
CURTIS, N W Pennsylvania Power & Light Co 81/01/14 4pp
07493 079

8010120425 Final deficiency rept re unauthorized welding of pipe hanger to reactor pressure vessel, initially reported on 800201 All necessary rework has been completed Reactor pressure vessel is in acceptable state
CURTIS, N W Pennsylvania Power & Light Co 81/01/22 6pp
07549 041

V Operator Examinations

8010300825 Requests commitments to special low power test program for facility & augmented operator training for compliance w/MI test action item 1 O 1
TEDESCO, R L Assistant Director for Licensing 81/01/16 1pp
07163 001

8101260370 Forwards util response to NUREG-0737 TMI-related requirements Meeting to discuss response requested
CURTIS, H W Pennsylvania Power & Light Co 81/01/22 87pp
07525 252

007ME1 50-268 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

A Application/construction stage documents & correspondence

8101090067 Releases public version of util emergency plan
FELTCH, J H Division of Rules and Records 80/11/13 1p.

--8101090071 Forwards public version of request for Amend 25 to application for OL consisting of Revision 2 to emergency plan
CURTIS, H W Pennsylvania Power & Light Co 80/10/31 1p

--8101090075 Public version of Amend 25 to application for OL consisting of Revision 2 to util emergency plan
CURTIS, H W Pennsylvania Power & Light Co 80/10/31 1p.

81220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Corrosion Leading to Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

810122069 Notification of rescheduling of 810127-29 meeting to 810303-05 w/util in Allentown, PA re mgt structure & technical resources
STARKE, R M Licensing Branch 1 80/12/16 3pp 07502 007

8101090032 Forwards request for addl info per review of OL application in power sys area & in procedures & test review branches
TEDESCO, R L Assistant Director for Licensing 80/12/22 15pp.
03893 265

8101200157 Summary of 801210 meeting w/Mark 11 owners re status of generic improved chugging load model Owners requested to justify delay in program & investigate alternatives
ANDERSEN, C J Generic Issues Branch 80/12/22 4pp

8101080176 Notification of 810115 meeting w/util in Bethesda, MD to discuss applicant responses to NRC questions & positions concerning initial test program
STARKE, R M Licensing Branch 1 80/12/23 3pp 07421 032

8101210747 Summary of 801118-19 meeting w/PNL in Bethesda, MD re control room habitability
HRCO, H E Accident Evaluation Branch 80/12/29 6pp. 07473 088

810110755 Summary of Dec 1980 meeting w/Mark 11 owners group, GE, BNL, HTR, GTH, Bechtel & Babcock & Wilcox, Inc re suppression pool temp limits List of attendees & handouts encl
SU, I K Generic Issues Branch 80/12/30 41pp

810110446 Forwards slides presented during 801218 meeting
CURTIS, H W Pennsylvania Power & Light Co 81/01/02 1p
07308 001

810130320 Forwards info re fish impingement & entrainment in response to AML request concerning input to FES Final & operations phase NPDES permit encl
CURTIS, H W Pennsylvania Power & Light Co 81/01/05 44pp.
07308 001

8101270482 Submits info re facility operations during low river flow conditions in response to NRC request Util plans to replace water taken from Susquehanna River during low flow by using water from existing reservoir or Pond Hill Reservoir
CURTIS, H W Pennsylvania Power & Light Co 81/01/07 1p
07549 063

810120189 Forwards proposed Amend 27 to util 790731 application for OLs, containing Revision 17 to FEAR
CURTIS, H W Pennsylvania Power & Light Co 81/01/07 2pp

810120387 Forwards "Seismic Category I Essential Components for Susquehanna 1 & 2 NSSS Equipment Only," supplementing 801216 equipment qualification info package
CURTIS, H W Pennsylvania Power & Light Co 81/01/09 1p
07474 185

8101190390 "Seismic Category I Essential Components for Susquehanna 1 & 2 NSSS Equipment Only"
* Pennsylvania Power & Light Co 81/01/07 88pp 07474: 185

8101300825 Requests commitments to special low power test program & facility 3 augmented operator training for compliance w/TMI task action item 1 G I
TEDESCO, R L Assistant Director for Licensing 81/01/16 3pp
07153 001

8101260370 Forwards util response to NUREG-0737 TMI-related requirements Meeting to discuss response requested
CURTIS, H W Pennsylvania Power & Light Co 81/01/22 87pp
07525 252

8101280151 Forwards application for amend of CPPR-101 & CPPR-102, to extend const completion dates Class I & Class II fees encl
SNAPP, R A Pennsylvania Power & Light Co 81/01/23 2pp
07558 042

--8101200158 Application for amend of CPPR-101 & CPPR-102 to extend completion dates to 820231 for CPPR-101 & 840331 for CPPR-102
CURTIS, H W Pennsylvania Power & Light Co 81/01/23 3pp
07558 044

8101300500 Submits update on farm survey in vicinity of facility
CURTIS, H W Pennsylvania Power & Light Co 81/01/27 2pp
07587 072

B NRC Draft/Final Environmental Statements, suppl & correspondence

810130320 Forwards info re fish impingement & entrainment in response to AML request concerning input to FES Final & operations phase NPDES permit encl
CURTIS, H W Pennsylvania Power & Light Co 81/01/05 44pp
07308 001

E NRC Safety Evaluation Report (SER), suppl & correspondence

8101050502 Requests schedule of completion for organizational changes at facility prior to proposed NRC 810127-29 visit re SER preparation
EISENHUT, D G Division of Licensing 80/12/19 2pp. 07387 281

F Security, medical, emergency & fire protection plans

8101090067 Releases public version of util emergency plan
FELTCH, J H Division of Rules and Records 80/11/13 1p
07440 691

--8101090071 Forwards public version of request for Amend 25 to application for OL consisting of Revision 2 to emergency plan
CURTIS, H W Pennsylvania Power & Light Co 80/10/31 1p
07440 003

--8101090075 Public version of Amend 25 to application for OL consisting of Revision 2 to util emergency plan
CURTIS, H W Pennsylvania Power & Light Co 80/10/31 1p
07440 004

--8101090080 Public version of util emergency plan, Revision 2
* Pennsylvania Power & Light Co 80/10/31 150pp. 07440 000

8101090307 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D G Division of Licensing 80/11/13 2pp

8101140861 Forwards applicant emergency plan per request. W/o encl
Related correspondence
SNAPP, R A Pennsylvania Power & Light Co 81/01/08 1p.
07458 213

8101290146 Notification of 810121 meeting w/util in Bethesda, MD re facilities emergency offsite facilities design & applicable NRC requirements.
STARKE, R M Licensing Branch 1 81/01/08 3pp 07567 351

8101210649 Forwards Chemical Engineering Branch request for addl info re fire protection
TEDESCO, R L Assistant Director for Licensing 81/01/13 12pp
07448 348

8101290154 Forwards facility emergency planning info to be made publicly available. W/o encl
SOLIDER, J L Division of Rules and Records 81/01/23 1p.
07575 197.

D Adjudicatory correspondence

810120225 Forwards statement of qualifications & affidavit of C. Miller re Contention 16 Prof qualifications encl.
WREGER, W E Assistant Director for Radiation Protection 80/12/04
6pp 07446:137

810140900 Requests to make limited appearance statement at licensing hearings Certificate of Svc encl
NOTERMAN, J.P Affiliation Unknown 80/12/27 3pp 07458:219

810150620 Order granting NRC 001224 motion for extension until 810109 to respond to applicants' motion for partial summary disposition of Contention 17
EETCHHOEFER, C Atomic Safety and Licensing Board Panel 80/12/30
2pp 07387:073

8101070202 Notice of RW Adler appearance in & KW Carter notice of withdrawal from proceeding Certificate of Svc encl
ADLER, R W , CARTER, K W Pennsylvania, State of 80/12/30 4pp
07415:151

8101070527 Order granting intervenor Susquehanna Environ Advocates 8101213 motion for extension until 810223 to respond to Contention & discovery requests.
EETCHHOEFER, C Atomic Safety and Licensing Board Panel 81/01/02
2pp 07406:361

8101090033 Requests time to make limited appearance statement at hearing in Berwick, PA Certificate of Svc encl.
MOHALL, R.M. Affiliation Unknown 81/01/03 1p 07441:178

8101140061 Forwards applicant emergency plan per request, w/o encl
Related correspondence
SNAPP, B A Pennsylvania Power & Light Co. 81/01/08 1p
07458:213

8101140011 Response to applicants' 801208 motion for partial summary disposition of Contention 17 Motion should be granted except for part re human health effects of electric fields Suppl to applicants' statement of metl facts encl
LAVERY, J.H. Hearing Branch 1 81/01/09 12pp 07309:001

--8101140017 Affidavit re likely levels & potential impact of audible noises possibly resulting from transmission lines associated w/facility Potential for speech interference & activity interference very low
LEHR, J C Environmental Engineering Branch 81/01/07 9pp
07309:001

--8101140028 Affidavit re radio & television interference, shock from flashover, magnetic field & electric field effects on human health Magnetic fields will not cause adverse biological effects Certificate of Svc encl.
GEARS, Q Environmental Engineering Branch 81/01/08 9pp
07309:001

8101200023 Requests that ASLB formally recognize withdrawal of Contention 13 C Marsh expressly withdrew contention on Page 11 of 790720 answers to NRC first round interrogatories
LAVERY, J.H Office of the Executive Legal Director 81/01/14
2pp 07477:314

8101280628 Informs that action on encl 801216 application for DNR license expected by Jan 1981 Submittal supercedes 001016 application
LAVERY, J.H Office of the Executive Legal Director 81/01/14
2pp 07187:001

8101220004 Memorandum & order stating no formal request received to withdraw Marsh Contention 13 Parties may reply by 810130 to NRC 810109 response to applicants' motion for partial summary disposition of Contention 17 w/certificate of Svc.
EETCHHOEFER, C Atomic Safety and Licensing Board Panel 81/01/15
4pp 07501:313

8101270298 Response stating that NRC & applicant interrogatories are burdensome & that intervenor lacks resources to reply.
Requests GE Reed rept Certificate of Svc encl.
JOHNSRUO, J.H Environmental Coalition on Nuclear Power 81/01/13
3pp 07546:063

H General correspondence

8101090703 Notifies that on 810108 telephone prefix 821 replaced by 770 for all util general ofc complex telephone numbers Prefix change will not effect 4-digit extension numbers
CURTIS, H H Pennsylvania Power & Light Co. 81/01/02 1p
07424:362

K Utility Final Safety Analysis Report (FSAR) & amends

8101140164 Forwards Amend 27 to util 790731 application for DLR containing Revision 19 to FSAR
CURTIS, H H Pennsylvania Power & Light Co 81/01/09 2pp
07436:001

--810120174 Amend 19 to FSAR
" Pennsylvania Power & Light Co 81/02/07 175pp 07458:219

L Inspection reports, IE Bulletins & correspondence

8101070400 Forwards Suppl 1 to IE Info Notice 80-29, "Broken S Terry Turbine Steam Inlet Flange " No written response required
GRIER, B.H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414:077

8101050150 Forwards IE Info Notice 80-43, "Failures of Continuous Monitor for Scram Discharge Vol at Dresden Unit 2 " No response required
GRIER, B.H Region 1, Philadelphia, Office of the Director 80/12/03 1p 07376:351

8101140024 Forwards results of independent teardown analysis of nine samples of cable w/o encl
CARLSCHIR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/11 2pp 07461:329

8101060138 Forwards IE Info Notice 80-45, "Potential Failure of Backup Manual Scram Capability " No response required
GRIER, B.H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07397:354

8101070058 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Fully Insert During Scram at DWR " No written response required.
GRIER, B.H Region 1, Philadelphia Office of the Director 80/12/18 1p 07415:008

8101150005 Forwards IE Bulletin 80-29, "Operating Problems w/ Rock Safety-Relief Valves at BWRs." No response required
GRIER, B.H Region 1, Philadelphia, Office of the Director 80/12/19 1p 07465:322

M Reportable occurrences, LERs & related correspondence

8101080071 Ack receipt of 801020 ltr forwarding interim deficiency re excessive voltage drops in ac motor operated valve control circuits Rept will be reviewed & evaluated
CARLSCHIR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/13 1p 07444:316

--8101100876 Interim deficiency rept re excessive voltage drops in ac motor operated valve control circuits, initially reported on 800718 Util is evaluating alternatives to determine course of action Final rept will be provided in Jan 1981.
CURTIS, H H Pennsylvania Power & Light Co 80/10/20 2pp
07444:317

8101300113 Ack receipt of 801028 deficiency rept re loose contact reeds on GE Type CR 2940 selector switches.
CARLSCHIR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/25 1p 07583:086

8101050394 Ack receipt of util 801121 interim deficiency rept re separation criteria for electrical equipment Matter will be reviewed following receipt of final rept
CARLSCHIR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/09 1p 07389:311

8101050390 Ack receipt of util 801121 final deficiency rept re shell-type expansion anchors Matter will be reviewed during subsequent insp
CARLSCHIR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/11 1p 07389:314

8101090616 Ack receipt of 801121 ltr forwarding final rept re Limitorque torque switch deficiencies
CARLSCHIR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/17 1p 07309:001

8101090302 Revised final deficiency rept re improper sloping of piping & tubing lines for GE instrumentation Lines will be installed which slope 1/2 inch per ft
CURTIS, H H Pennsylvania Power & Light Co 80/12/23 3pp
07389:284

810112058 Ack receipt of Util 80117 interim deficiency rept re excessive voltage drops in power supplies to dc motor-operated valves Matter will be reviewed following receipt of final rept
CARLSON R L Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/23 1p 07471 183

810112059 Ack receipt of Util 80119 final deficiency rept re 1-110KV limit switch rotors Matter will be reviewed during subsequent insp
CARLSON R L Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/24 1p 07471 181

810112079 Ack receipt of Util 80120 interim deficiency rept re shimming of base plates
CARLSON R L Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/24 1p 07473 044

810112085 Interim deficiency rept re use of pipe shims around anchors between equipment floors & equipment base plates. Initially reported on 801107 Evaluation underway to determine scope of problem & resolution, including removal of pipe shims
CARLSON R L Pennsylvania Power & Light Co 80/12/09 6pp 07473 045

810112086 Interim deficiency rept re use of improperly grounded flexible conduit on safety-related circuits. Initially reported on 801210 Caused by manufacturer failure to remove paint from termination module Next rept by Apr 1981
CARLSON R L Pennsylvania Power & Light Co 81/01/14 4pp 07473 079

810270425 Final deficiency rept re unauthorized welding of pipe hanger to reactor pressure vessel. Initially reported on 800201 All necessary control has been completed Reactor pressure vessel is in acceptable state
CARLSON R L Pennsylvania Power & Light Co 81/01/22 6pp 07549 044

Operator Examinations

81020825 Requests commitments to special low power test program for facility 1, augmented operator training, for compliance w/IKI test action item 1 & 1
WEISSER R L Assistant Director for Licensing 81/01/16 3pp

81020370 Forwards Util response to NUREG-0727 IKI-related requirements Meeting to discuss response requested
CARLSON R L Pennsylvania Power & Light Co 81/01/22 87pp

NET 30-389 SI LOGIC PLANN. UNIT 2

Security, medical, emergency & fire protection plans

81090327 Ltr to all licensees of operating reactor plants, CP holders, CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of PSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

Adjudicatory correspondence

81090306 Order granting extension until 810115 for Commission to review Director's decision 80-80-33 Certificate of Svc encl
MILK, S J Office of the Secretary of the Commission 81/01/09 6p 07462 134

8110956 Response to Commission 801212 memorandum & order recommends affirmation of ALAB-603 & acceptance of ASLAS certification GRP Section 2 2 3 should not be used to determine DOE Certificate of Svc encl
MSTEAAD, W J Hearing Branch 4 81/01/12 11pp. 07458 302

810217 Response recommending Commission affirm ALAB-603 & except certification of ASLAS ASLAS requirements re station action etc appropriate pending completion of Test Action an A-44
MSTEAAD, W J Hearing Branch 4 81/01/12 11pp. 07470 068

810261 Response opposing 801212 Commission memorandum & order, 1-80-41, announcing sua sponte review of 800730 ALAB-603 Commission letter jurisdiction Certificate of Svc encl
EISENHUT, D O, COLLINS, A Florida Power & Light Co BAUBER, M A, Weinstein, Hauman, Reis, Atwood & Toll 81/01/12 8pp 07470 239

8101260321 Informs that time for Commission to act to review Director's decision 80-80-33, has expired Commissioner Dillinsky in voting for no review stated Class 9 accidents should be considered in suppl to CP review Certificate of Svc encl
CHILDS, J Office of the Secretary of the Commission 81/01/21 4pp 07529 250

J Insurance & indemnity information

8101096457 Forwards Endorsement 4 to HELIA Binder 80-59
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc
Div 80/12/30 2pp 07430 048

8101096464 Forwards Endorsement 38 to HELIA Policy NF-227
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc
Div 80/12/30 3pp 07442 032

8101097556 Forwards Endorsement 37 to ANI Policy NF-227
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc
Div 80/12/30 2pp 07427 343

M Antitrust correspondence

8101140915 Order scheduling 810202 prehearing conference in Bethesda, MD re joint motion to approve & authorize implementation of settlement agreement Certificate of Svc encl
LATO, R H Atomic Safety and Licensing Board Panel 81/01/07 5pp 07458 236

8101090348 FL Cities motion to file encl reply to applicant 801203 brief which raises new questions & new statements of law
JABLON, R A Affiliation Unknown JABLON, R A Spiegel & McDiarmid 81/01/08 2pp 07424 039

--8101090360 FL Cities reply brief to applicant 801203 response to FL Cities answer to joint motion Supports prehearing conference & contends license condition clause contrary to public policy Certificate of Svc encl
JABLON, R A Affiliation Unknown JABLON, R A Spiegel & McDiarmid 81/01/08 173pp 07424 041

8101280599 Answer opposing intervening Cities 810108 reply to Util 8003 & NRC 800912 joint motion Addresses arguments re liability provisions & settlement license conditions Certificate of Svc & supportive documentation encl
DYER, H, BOUQUIDON, J A Florida Power & Light Co, DYER, H Covington & Durling 81/01/27 32pp 07557 253

P Operating license stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issues A-12, "Potential for Low Fracture Toughness & Lateral Tear on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp.

O Inspection reports, IE Bulletins & correspondence

81012160019 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/24 1p

8101290365 Forwards IE Insp Rept 80-389/80-16 on 801118-20. No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/15 2pp. 07571 356

--8101290367 IE Insp Rept 80-389/80-16 on 801118-20. No noncompliance noted Major areas inspected followup items, licensee identified items & IE bulletins, circulars & info notices.
MCFARLAND, C R Region 2, Atlanta, Office of the Director BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/15 4pp 07571 358

8101270008 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Util Util fully respond to bulletin by 810116
WRIGHT, R E Florida Power & Light Co 80/12/29 1p. 07547:019

8101270043 Responds to IE Bulletin 80-21 re Malcolm Foundry Co valve gaskets Util waiting for vendor response
WRIGHT, R E Florida Power & Light Co 80/12/30 1p. 07547:022

810190990 Ack receipt of 801215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-369/80-13
MARSH, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/01/06 1p 07464 284

--810190995 Response to NRC 801010 ltr re violations noted in IE Insp Rept 50-369/80-13 Corrective actions Quality Procedure & re storage & distribution of welding filler metal revised.
WIRIG, R. E. Florida Power & Light Co 80/12/15 2pp 07464 285

R Periodic operating reports & related correspondence

8101220172 Forwards monthly status rept of const/startup progress for Dec 1980
WATKINS, R. E. Florida Power & Light Co 81/01/14 2pp 07495 282

DCWET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Uninvolved Safety Issue A-12: "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports"
EISENHUT, D. Q. Division of Licensing 80/11/26 8pp

8101050552 Forwards requests for clarification of responses to questions re containment vessel bldg analysis
TEDESCO, R. L. Assistant Director for Licensing 80/12/05 4pp 07387 178

8101070968 Summary of 801208-12 meetings w/caseload forecast panel Earliest projected fuel load date for facilities is 810601 for Sequoyah Unit 2 & Aug 1982 for Watts Bar Unit 1
KENYON, T. J. Licensing Branch 2 80/12/16 5pp 07429 356

8101140810 Requests ultimate capacity analysis of ice condenser containments, re NRC review of effects of hydrogen evolving from postulated accident Analysis guidelines encl
TEDESCO, R. L. Assistant Director for Licensing 80/12/10 3pp 07461 316

8101210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mods NRC will not comment on until 800917 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT, D. Q. Division of Licensing 80/12/29 2pp

8101190228 Forwards list of TLO station locations near facility & proposed route for exchanging TLOs for NRC direct radiation monitoring network w/o encls
STOKER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07473 305

8101160418 Responds to NRC 800924 request for results of preliminary design review of control room Results encl
MILLS, L. M. Tennessee Valley Authority 81/01/13 9pp 07470 158

8101290497 Summary of 801208 meeting w/util & AML at site re safety & relief valve piping of primary coolant sys List of attendees encl
KENYON, T. Operating Reactors Branch 2 81/01/15 4pp 07575 170

8101300097 Notification of contract execution-Med 3 to "Evaluation of Buckling Stress Criteria for Steel Containment of Watts Bar" Contractor Intl Structural Engineers
FLEENOR, C. M. Administrative Contracts Branch FIN 8-6581 81/01/26 1p 07583 077

--8101300104 Med 3, extending period of performance to 810630 to "Evaluation of Buckling Stress Criteria for Steel Containment of Watts Bar"
MOSCHER, B. A. International Structural Engineers, Inc PERLMAN, J. Administrative Contracts Branch FIN 8-6581 81/01/26 1p 07583 078

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D. Q. Division of Licensing 80/11/13 2pp

8101210607 Transcript of 801217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45
Commissioners 80/12/17 49pp

8101300238 Forwards request for addl info & revisions to util 801010 guard training & qualification program Section 1.3 must be revised to conform to physical exam within 30-day period preceding demonstration of physical fitness
TEDESCO, R. L. Assistant Director for Licensing 81/01/15 4pp 07582 141

J Insurance & indemnity information

8101070555 Forwards Endorsement 11 to ANI Policy NF-256
FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/12/29 2pp 07427 335

8101090658 Forwards Endorsement 12 to HELIA Policy NF-256
FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/12/29 3pp 07442 053

G Inspection reports, IE Bulletins & correspondence

8101140619 Updates licensee corrective actions following NRC 800701 insp of util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to mgmt
KIM, J. S. G. H. Tennessee Valley Authority 80/10/08 3pp 07462 012

8101290373 Forwards IE Insp Repts 50-390/80-34 & 50-391/80-27 on 801020-31 No non-compliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/09 2pp 07572 336

--8101290378 IE Insp Repts 50-390/80-34 & 50-391/80-27 on 801020-31 non-compliance noted Major areas inspected SNM license amend & licensee action on previous insp findings
MCEDMUND, J. A. Region 2, Atlanta, Office of the Director, DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/09 3pp 07572 338

8101202340 Forwards response to IE Bulletin 80-20 re Westinghouse 1 W-2 control switches & spring return to neutral position Switches used in all facilities except Yellow Creek Lists sys in which switches are employed
MILLS, L. M. Tennessee Valley Authority 80/12/12 2pp 07447 6

8101060203 Forwards IF Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director 80/12/12 1p

8101270030 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Valcor solenoid valves V70900-21-1 & V70900-21-3 not used Util waiting for vendor response on valves to package components
MILLS, L. M. Tennessee Valley Authority 80/12/30 1p 07547 01

8101210239 Responds to IE Bulletin 80-71, "Valve Yokes Supplied by Malcolm Foundry Co, Inc" Util is in process of obtaining assurance from valve supplier that no Malcolm Foundry yokes are contained in furnished valves
MILLS, L. M. Tennessee Valley Authority 81/01/06 1p 07490 01

8101230468 Responds to NRC 801121 ltr re violations noted in IE Insp Rept 50-390/80-30 & 50-391/80-23 Corrective action still has not all reporting requirements of 10CFR50.55(e) & is in full compliance
MILLS, L. M. Tennessee Valley Authority 81/01/14 5pp 07510 1

S Reportable occurrences, LCRs & related correspondence

8101090497 Final interim deficiency rept, originally reported on 8010 re unacceptable welds on duct supports in auxiliary bldg Program implemented to re-inspect welds on duct supports in auxiliary bldg Welds to be repaired
MILLS, L. M. Tennessee Valley Authority 80/12/31 2pp 07380

8101070432 First interim deficiency rept re design of self-drilling expansion anchors initially reported on 801204 Util is evaluating adequacy of design to determine impact of error Next rept will be forwarded by 810308
MILLS, L. M. Tennessee Valley Authority 81/01/02 2pp 07415

8101140985 Second interim deficiency rept initially reported 801001 seismic analysis of check valves in chemical & vol control sys Loads from 3-inch check valve are not significant Next rept will be submitted by 810210
MILLS, L. M. Tennessee Valley Authority 81/01/06 1p 07461 2

8101140592 First interim deficiency rept. originally reported on 800325. re upper head injection hydraulic isolation valve accumulator weighing sys Westinghouse agreed to submit revised drawings. Next rept will be submitted by 810310
MILLS, L. M. Tennessee Valley Authority 81/01/06 1p 07461 235

8101260427 Second interim deficiency rept. originally reported on 801002. re seismic analysis of check valve in chemical & val control sys loads from 3-inch check valve at Sequoyah insignificant hard-are changes not required
MILLS, L. M. Tennessee Valley Authority 81/01/06 1p 07531 175

8101140618 Final interim deficiency rept. originally reported on 800818. re discrepancy in two EM-71 embedded plates. Plates reanalyzed for related loads assuming none of embedment anchors are double studed. Embedded plates acceptable
MILLS, L. M. Tennessee Valley Authority 81/01/08 2pp 07461 236

8101270245 Part 21 rept re discovery of surface indications in loop 1 steam generator. Caused by delayed hydrogen cracking. Due to welding surface indications removed by grinding.
MILLS, L. M. Tennessee Valley Authority 81/01/08 3pp 07547 114

8101140616 Final deficiency rept re diesel generator interlock design. Interlocks will be added to emergency feeder breaker automatic close circuit before fuel load. Originally reported on 801209
MILLS, L. M. Tennessee Valley Authority 81/01/09 2pp 07461 120

8101160462 Final deficiency rept. originally reported 801027 re interaction areas in reactor bldg annulus not covered by automatic fixed water spray sys. Fire protection sys is being modified to encompass addl interaction areas identified.
MILLS, L. M. Tennessee Valley Authority 81/01/09 2pp 07471 223

8101190405 Interim deficiency rept. originally reported on 811210 re fillet weld misspecification. Util in process of evaluating American Iron & Steel Inst Stds. Next rept will be sent 810303
MILLS, L. M. Tennessee Valley Authority 81/01/09 2pp 07475 249

8101190391 First interim deficiency rept. initially reported on 801212. re nonrandom testing of expansion anchor bolts. Deficiency under investigation to determine corrective action.
MILLS, L. M. Consumers Power Co. 81/01/12 2pp 07475 245

8101210421 Second interim deficiency rept re valve accelerations for piping analysis. Initially reported on 801002. Util is still evaluating interpretation of design criteria re valve seismic accelerations. Addl info will be provided by 810220
MILLS, L. M. Tennessee Valley Authority 81/01/13 1p 07448 362

8101260409 Second interim deficiency rept. first reported on 801002. re valve accelerations for piping analysis. Design criteria interpretation re valve seismic accelerations being evaluated. Addl info scheduled for 810220
MILLS, L. M. Tennessee Valley Authority 81/01/13 1p 07531 216

8101290311 Forwards first interim rept re potential flammability of suspended ceiling tile in control room in response to 801104 ltr. Addl info to be provided by 810211
MILLS, L. M. Tennessee Valley Authority 81/01/14 3pp

8101230542 Fourth interim deficiency rept. initially submitted 800501. re safety injection sys B flow deficient. No further testing performed. Further info to be provided by 810314
MILLS, L. M. Tennessee Valley Authority 81/01/15 1p 07308 001

8101230953 First interim deficiency rept. originally reported 801216. re loose electrical terminations on diesel generator control panels. Investigation committee formed to evaluate deficiency. Loose terminations tightened.
MILLS, L. M. Tennessee Valley Authority 81/01/15 2pp 07510 286

8101230608 Sixth interim deficiency rept. originally submitted 790902. re steam generator water level ref column error. Microprocessors provide temp compensation for errors caused by water density changes. Addl info to be submitted 810515.
MILLS, L. M. Tennessee Valley Authority 81/01/15 1p 07308 001

8101260438 Final deficiency rept. originally reported on 801217. re spring from ITI actuator rfg from incorrect matl. Investigation revealed Post-Seal uses NH 90 series hydrometers. Post-Seal verified safe performance of actuator.
MILLS, L. M. Tennessee Valley Authority 81/01/15 2pp 07531 221

8101260418 First interim deficiency rept. originally reported on 801219. re current control problems w/diesel generators 1A-A & 1B-B. Caused by incorrect wiring of voltage regulator wiring. Corrected. A preoperational testing complete.
MILLS, L. M. Tennessee Valley Authority 81/01/19 3pp 07531 217

8101260436 First interim deficiency rept. originally reported on 801219. re inadequate steel containment penetration assembly. Affected piping will be reanalyzed to determine adequacy of assembly & pipe rupture restraint design.
MILLS, L. M. Tennessee Valley Authority 81/01/19 2pp 07531 219

8101270732 Final deficiency rept. originally reported on 800918. re shifting of intermediate pipe break locations w/o notifying NRC. Safety, injection & resistance temp device lines have been re-evaluated & no unacceptable interactions found.
MILLS, L. M. Tennessee Valley Authority 81/01/21 2pp 07545 290

8101300483 Final deficiency rept. originally reported on 801030. re improper weld attachment of shear lugs. Caused by improper design & installation. Lugs will be removed & reinstalled w/1/4 inch fillet weld. Mods to be completed by May 1982.
MILLS, L. M. Tennessee Valley Authority 81/01/26 2pp 07586 103

DOCKET 50-391 WAFIR 849 NUCLEAR PLANT, UNIT 2
A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. Q. Division of Licensing 80/11/26 8pp

8101050552 Forwards requests for clarification of responses to questions re containment vessel bldg analysis.
TEDESCO, R. L. Assistant Director for Licensing 80/12/05 4pp 07387 178

8101090968 Summary of 801208-12 meetings w/case load forecast panel. Earliest projected fuel load date for facilities is 810601 for Sequoyah Unit 2 & Aug 1982 for Watts Bar Unit 1.
KENNY, J. J. Licensing Branch 2 80/12/16 5pp 07429 356

8101140810 Requests ultimate capacity analysis of ice condenser containments. re NRC review of effects of hydrogen evolving from postulated accidents. Analysis guidelines encl.
TEDESCO, R. L. Assistant Director for Licensing 80/12/18 3pp 07461 316

8101210642 Advises that ATWS issue will be sub of future rulemaking to determine requirements & schedules for plant mods. NRC will not comment on util 800917 ltr describing program for resolving issue until rulemaking is finalized.
EISENHUT, D. Q. Division of Licensing 80/12/29 2pp

8101190228 Forwards list of TLO station locations near facility & proposed route for exchanging ILDs for NRC direct radiation monitoring network w/o oncls.
STONER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07475 305

8101160418 Responds to NRC 800924 request for results of preliminary design review of control room. Results encl.
MILLS, L. M. Tennessee Valley Authority 81/01/13 9pp 07470 158

8101290497 Summary of 801208 meeting w/util & ANL at site re safety & relief valve piping of primary coolant sys. List of attendees encl.
KENNY, J. J. Operating Reactors Branch 2 81/01/15 4pp 07575 170

8101300097 Notification of contract execution. Mod 3 to "Evaluation of Buckling Stress Criteria for Steel Containment of Watts Bar." Contractor Intl Structural Engineers.
FLEENOR, C. M. Administrative Contracts Branch, FIN B-6581 81/01/26 1p 07583 077

--8101300104 Mod 3, extending period of performance to 810630 to "Evaluation of Buckling Stress Criteria for Steel Containment of Watts Bar."
MCSEBRO, J. A. International Structural Engineers, Inc. PERLMAN, J. Administrative Contracts Branch, FIN B-6581 81/01/26 1p 07583 078

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D. Q. Division of Licensing 80/11/13 2pp

8101210637 Transcript of 801217 briefing on TVA emergency offsite facilities in Washington, DC. Pp 1-45
* Commissioners 80/12/17 49pp

8101300230 Forwards request for addl info & revisions to util 801001 guard training & qualification program Section 1.3 must be revised to permit to physical exam within 30-day period preceding demonstration of physical fitness
TEECSCO, R L Assistant Director for Licensing 81/01/15 4pp
07382 141

J Insurance & indemnity information

8101070535 Forwards Endorsement 11 to ANI Policy NF-256
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/29 2pp 07427 339

8101090658 Forwards Endorsement 12 to MELIA Policy NF-256
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/29 3pp 07442 037

K Inspection reports, IE Bulletins & correspondence

8101140619 Updates licensee corrective actions following NRC 800707-11 insp of util Div of Engineering Design UA organization restructured to provide sufficient organizational freedom, authority & access to mgmt
XIMONS, G H Tennessee Valley Authority 80/10/08 3pp

8101290373 Forwards IE Insp Repts 90-390/80-34 & 90-391/80-27 on 801020-31 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/09 2pp 07572 336

--8101290378 IE Insp Repts 90-390/80-34 & 90-391/80-27 on 801020-31 No noncompliance noted Major areas inspected BWM license amend & licensee action on previous insp findings
MCGLAD, D J A Region 2, Atlanta, Office of the Director
DAVCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/09 3pp 07572 350

8101120210 Forwards response to IE Bulletin 80-20 re Westinghouse Type W-2 control switches w/spring return to neutral position
Switches used in all facilities except Yellow Creek Lists
eye in which switches are employed
MILLS, L M Tennessee Valley Authority 80/12/12 2pp

8101060203 Forwards IE Info Notice 80-41, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown - No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/16 1p

8101270030 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Valcor solenoid valves V70900-21-1 & V70900-21-3 not used Util waiting for vendor response on valves in package components.
MILLS, L M Tennessee Valley Authority 80/12/30 1p 07547 021

8101210239 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co., Inc." Util is in process of obtaining assurance from valve suppliers that no Malcolm Foundry yokes are contained in furnished valve
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07490 057

8101230468 Responds to NRC 801121 ltr re violations noted in IE Insp Repts 90-390/80-30 & 90-391/80-23 Corrective action-util has met all reporting requirements of 10CFR50.55(e) & is in full compliance
MILLS, L M Tennessee Valley Authority 81/01/14 5pp 07510 303

L Reportable occurrences, IERs & related correspondence

8101050439 Final interim deficiency rept. originally reported on 801201, re unacceptable welds on duct supports in auxiliary bldg. Program implemented to re-inspect welds on duct supports in auxiliary bldg Welds to be repaired
MILLS, L M Tennessee Valley Authority 80/12/31 2pp 07380 166

8101070432 First interim deficiency rept re design of self-drilling expansion anchors, initially reported on 801204 Util is evaluating adequacy of design to determine impact of error. Next rept will be forwarded by 810308
MILLS, L M Tennessee Valley Authority 81/01/02 2pp 07419 306

8101140485 Second interim deficiency rept initially reported 801002 re seismic analysis of check valves in chemical & vol control sys Loads from 3-inch check valve are not significant Next rept will be submitted by 810210
MILLS, L M Tennessee Valley Authority. 81/01/06 1p 07461 281

8101140593 Fifth interim deficiency rept. originally reported on 800325, re upper head section hydraulic isolation valve accumulator weighing sys Westinghouse agreed to submit revised drawings Next rept will be submitted by 810310
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07461 239

8101260427 Second interim deficiency rept. originally reported on 801002, re seismic analysis of check valve in chemical & vol control sys Loads from 3-inch check valve at Sequoyah insignificant Hardware changes not required
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07531 179

8101140618 Final interim deficiency rept. originally reported on 800818, re discrepancy in two MA-71 embedded plates Plates reanalyzed for related loads assuming none of embedment anchors are double studied Embedded plates acceptable
MILLS, L M Tennessee Valley Authority 81/01/08 2pp 07461 236

8101290672 Final deficiency rept. originally reported on 800818, re discrepancy in two MA-71 embedded plates Caused by lack of double studied anchors & insufficient number of horizontal rows Embedded plates replaced & ultrasonically tested
MILLS, L M Tennessee Valley Authority 81/01/08 2pp 07565 327

8101140616 Final deficiency rept re diesel generator interlock design Interlocks will be added to emergency feeder breaker automatic close circuit before fuel load Originally reported on 801209
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07461 128

8101160462 Final deficiency rept originally reported 801027 re interaction areas in reactor bldg annulus not covered by automatic fixed water spray sys Fire protection sys is being modified to encompass addl interaction areas identified
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07471 223

8101190405 Interim deficiency rept. originally reported on 811210 re fillet weld misspecification Util in process of evaluating American Iron & Steel Inst Stds Next rept will be sent
810303
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07475 249

8101190391 First interim deficiency rept. initially reported on 801212, re nonrandom testing of expansion anchor bolts Deficiency under investigation to determine corrective action
MILLS, L M Consumers Power Co 81/01/12 2pp 07475 245

8101230296 Final Part 21 rept re installation of compression type terminals on single-phase static inverters, first reported 801212 Insufficient number of or improper crimps made Vendor approval for mod obtained Mods to be completed 810201
MILLS, L M Tennessee Valley Authority 81/01/12 3pp 07187 001

8101210421 Second interim deficiency rept re valve accelerations for piping analysis, initially reported on 801002 Util is still evaluating interpretation of design criteria re valve seismic accelerations Addl info will be provided by 810220
MILLS, L M Tennessee Valley Authority 81/01/13 1p 07440 362

8101260405 Second interim deficiency rept. first reported on 801002, re valve accelerations for piping analysis Design criteria interpretation re valve seismic accelerations being evaluated Addl info scheduled for 810220
MILLS, L M Tennessee Valley Authority 81/01/13 1p 07531 216

8101220311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to 801104 ltr Addl info to be provided by 810211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

8101230593 First interim deficiency rept. originally reported 801216, re loose electrical terminations on diesel generator control panels Investigation committee formed to evaluate deficiency Loose terminations tightened
MILLS, L M Tennessee Valley Authority 81/01/15 2pp 07510 286

8101230608 Sixth interim deficiency rept. originally submitted 790906, re steam generator water level ref column error Microprocessors provide temp compensation for errors caused by water density changes Addl info to be submitted 810515
MILLS, L M Tennessee Valley Authority 81/01/15 1p 07308 001

8101280438 Final deficiency rept. originally reported on 801217, re spring from ITR actuator mfg from incorrect mill Investigation revealed Posi-Seal uses M4 90 series hydramtors Posi-Seal verified safe performance of actuator
MILLS, L M Tennessee Valley Authority 81/01/15 2pp 07531 221

B01260475 Final interin deficiency rept. originally reported on B01219. re inadequate steel containment penetration assembly. Affected piping will be re-analyzed to determine adequacy of asse-bly & pipe rupture restraint design
MILLS L M Tennessee Valley Authority 81/01/19 2pp 07531 219

B01270732 Final deficiency rept. originally reported on B00918. re shifting of intermediate pipe break locations w/o notifying I&C Safety Injection & resistance temp device lines have been re-evaluated & no unacceptable interactions found
MILLS L M Tennessee Valley Authority 81/01/21 2pp 07543 290

B01330463 Final deficiency rept. originally reported on B01030. re improper weld attachment of shear lugs caused by improper design & installation lugs will be removed & reinstalled w/1/4 inch Pallet weld rods to be completed by May 1982
MILLS L M Tennessee Valley Authority 81/01/26 2pp 07584 103

DOCKET 80-092 CHD-GHAW POWER REACTOR

B Reportable occurrences, LERs & related correspondence

B01290672 Final deficiency rept. originally reported on B00818. re discrepancy in two MA-71 embedded plates caused by lack of double studed anchors & insufficient number of horizontal rows Embedded plates replaced & ultrasonically tested
MILLS L M Tennessee Valley Authority 81/01/08 2pp 07566 329

DOCKET 80-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B01140251 Advises that branch will review adequacy of cable separation inside Westinghouse 7300 series process control cabinet during B01112-14 site visit Review conducted in response to B01429 memo
PATTENFIELD E Instrumentation & Control Systems Branch 80/11/06 1p 07461 259

B01220464 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unsolved Safety Issue A-12. Potential for Low Fracture Toughness & Lateral Fracturing on Component Supports
EISENHUT D O Division of Licensing 80/11/24 8pp

B01050149 Requests addl info by B01219 re RCS vents.
TEDESCO R L Assistant Director for Licensing 80/12/05 8pp 07399 678

B01080644 Forwards request for addl info re identification of high strength welds joining component parts & provision of impact energy data necessary to demonstrate fracture toughness adequacy
TEDESCO R L Assistant Director for Licensing 80/12/22 3pp 07421 085

B01090915 Forwards response to questions re containment sump & effect on long term cooling following LOCA Full flow testing performed as part of startup testing procedures. Alden Lab proposal concerning model test encl
NICHOLS T C South Carolina Electric & Gas Co 80/12/29 28pp 07399 001

B01050337 Forwards proprietary & nonproprietary "Summary Rept. Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling. 17300 Sys." dtd Dec 1980 in response to NUREG-0737, Part 11 F 2
NICHOLS T C South Carolina Electric & Gas Co 80/12/30 2pp 07394 159

- B01050047 Requests "Summary Rept. Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling. 17300 Sys." dtd Dec 1980 be withheld (ref 10CFR2.790) per previously submitted application AM-77-18 approved 771028
EISENHUT R A Westinghouse Electric Corp 80/12/23 7pp 07354 161

B01060577 Responds to NRC request for updated info re occurrence of earthquakes similar to 1824 event in Charleston, SC. Similar earthquakes have potential to occur in vicinity. Seismic engineering parameters should be carefully considered
DEVLIN E J Interior Dept of Geological Survey 80/12/30 4pp 07399 171

B01190234 Forwards list of 3LD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encls
STOHR J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07475 301

B01270217 Identification of B01017 meeting w/Util in Bethesda, MD re outstanding issues in Instrumentation & Control Sys Branch safety evaluation
NICHOLS T C South Carolina Electric & Gas Co 80/12/31 3pp 07546 016

B01080417 Requests authorization to utilize Code Case N-282 during re-starting of Sys Code reviewed by I&C & will be included in revision to Reg Guide 1.84
NICHOLS T C South Carolina Electric & Gas Co 81/01/02 2pp 07420 313

B01099503 Advises that estimated fuel load readiness date is Aug. Projection is based on engineering, preoperational testing & const work remaining
NICHOLS T C Southern California Edison Co 81/01/06 1p 07426 362

B01130102 Forwards "Separation Audit of Class 1E Electric Equipment & Circuits Rept." & "Procedure to Audit Separation of Class 1E Electric Equipment & Circuits." Results indicate FSAR separation criteria effectively implemented
NICHOLS T C South Carolina Electric & Gas Co 81/01/06 1p 07447 174

-B01130107 "Separation Audit of Class 1E Electric Equipment & Circuits"
* Commonwealth Cos 81/01/06 10pp 07447 175

-B01130112 "Procedure to Audit Separation of Class 1E Electric Equipment & Circuits" List of audited Class 1E & associated circuits & equipment & summary of discrepancy types encl
POANWILLI J, THOMAS W D, DELP G A South Carolina Electric & Gas Co 80/09/22 30pp 07449 185

B01130121 Responds to NUREG-0737, Items 11 K 2 & 11 K 3 Westinghouse owners group is performing blind post-test predictions of LOFT Experiment L3-6
NICHOLS T C South Carolina Electric & Gas Co 81/01/06 4pp 07449 230

B01130126 Forwards revised data for Tech Spec Table 3.4-1 & disc leak tight integrity of primary coolant sys pressure isolation valves
NICHOLS T C South Carolina Electric & Gas Co 81/01/06 3pp 07449 234

B01200582 Authorizes use of bellows assembly not in full accordance w/ASME code requirements in response to B01031 request Assembly will replace damaged assembly in reactor bldg steam generator blowdown penetration
TEDESCO R L Assistant Director for Licensing 81/01/07 3pp 07477 287

B01130889 Responds to Question 211 133 re reactor vessel vent system removes noncondensable gases from reactor vessel head. Info will be incorporated into FSAR Amend 23
NICHOLS T C South Carolina Electric & Gas Co 81/01/09 10pp 07456 001

B01130293 Forwards "Comparison of Mgt/Technical Resources to Regulatory Guidance"
NICHOLS T C South Carolina Electric & Gas Co 81/01/09 1p 07447 225

-B01130296 "Comparison of Mgt/Technical Resources to Regulatory Guidance"
* South Carolina Electric & Gas Co 81/01/31 49pp 07447 225

B01150183 Forwards design review of plant shielding & environmental qualification of equipment for spaces/sys which may be used in post-accident operations outside reactor bldg info will be incorporated in Amend 23 of FSAR
NICHOLS T C South Carolina Electric & Gas Co 81/01/09 46pp 07208 001

B01160290 Submits info addressing NUREG-0737, 11 K 3.17. "Rept on Outage of ECCS Licensee Rept & Proposed Tech Specs Changes" Administrative Procedure AP-217 written establishing program for equipment removal from & restoration to svc
NICHOLS T C South Carolina Electric & Gas Co 81/01/12 2pp 07470 169

B01160395 Informs that licensee has submitted electrical schematic for acoustic leak monitor to NRC project manager W Kane per requirements of TMI Item 11 D 3
NICHOLS T C South Carolina Electric & Gas Co 81/01/13 1p 07470 168

101220262 Forwards human factors engineering evaluation & improvement of control room Rept describes backfits being implemented to correct discrepancies noted in NRC audit & Essex preliminary evaluation

NICHOLS, T C South Carolina Electric & Gas Co 01/01/15 1p 07496 131

-101220265 Human Factors Engineering Evaluation & Improvement of VC Summer Nuclear Station Control Room, Phase 1 - Prepared for util
JEDRLING, D H, STEELE, E H, VERDOL, A P Essex Corp 01/01/31 214pp 07496 132

101230405 Forwards proprietary & nonproprietary versions of Revision 1 to 'Environ Qualification of Safety-Related Electrical Equipment/NUREG-0508' Proprietary version withheld (ref 10CFR2 7901 Westinghouse affidavit encl)
NICHOLS, T C South Carolina Electric & Gas Co 01/01/15 9pp 07536 093

-101230410 Nonproprietary version of Revision 1 to 'Environ Qualification of Safety-Related Electrical Equipment/NUREG-0508'
* South Carolina Electric & Gas Co 01/01/15 303pp 07536 092

101290775 Forwards summary of major points of instrumentation & Control Sys Branch 001112-14 audit drawing review Addl info requested to complete evaluation file visit summary & list of attendees encl
TEDESCO, R L Assistant Director for Licensing 01/01/15 17pp 07308 001

101200258 Provides proposed survey program for verification of svc water intake line location & structural integrity in response to IIRC request at 001119 meeting.
NICHOLS, T C South Carolina Electric & Gas Co 01/01/16 3pp 07486 235

101280119 Responds to comments received at 010107 meeting in Bethesda, MD re NRC 001112-14 site visit Manual closure capability to effect valve closure w/accumulator air source to be provided in control room Reset capability to be added to panels
NICHOLS, T C South Carolina Electric & Gas Co. 01/01/23 3pp 07358 039

UIC Draft/Final Environmental Statements, supp's & correspondence

101930017 Forwards NABA comments on draft EIS for facility Questions why wind rose data was not taken into account in determining probability of total population exposure. Ten copies of final EIS requested
MINK, R T Commerce Dept of 00/12/24 2pp 07379 344

101060471 Forwards responses to questions re Section 7 of DES per IFC 001201 telecopy request
NICHOLS, T C South Carolina Electric & Gas Co 00/12/31 6pp 07398 122

101090497 Ack receipt of 001110 ltr transmitting suppl to draft EIS Provides detailed comments on sections re groundwater & uncertainties Finding of Lewis Rept w/respect to uncertainty in risk of reactor accidents should be discussed in FEB
RATHLEBERGER Interior Dept of 01/01/05 2pp 07427 333

101210590 Applauds NRC decision to prepare suppl to OES for evaluation of environ impacts from different LIR accident scenarios including Class 9 accidents. Technical comments on DES encl
HAYMER, R W Environmental Protection Agency 01/01/12 3pp 07409 253

101260593 Comments on OES for facility re possible impacts of Class 9 accidents in response to NRC request. Discussion of probabilities of occurrence, magnitude of consequences & risk considerations should be given separate attention
MILLS, W A Environmental Protection Agency. 01/01/12 2pp 07532 087

101270743 Comments on OES suppl re facility operation. Exposure area of 500 miles is not required by NRC policy statement. Practically all health-related exposures would occur within 50-mile radius
BUCHEV, Q D Washington Public Power Supply System 01/01/19 1p 07548: 273

Security, medical, emergency & fire protection plans

101070387 Ltr to all licensees of operating reactor plants. CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 010102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 00/11/13 2pp

0101090123 Releases public version of util radiation emergency plan
FELTON, J B Division of Rules and Records 00/12/01 1p 07428 226

--0101090125 Forwards public version of radiation emergency plan. Revision 2
NICHOLS, T C South Carolina Electric & Gas Co 00/10/13 1p 07428 227

--0101090127 Public version of radiation emergency plan. Revision 2
* South Carolina Electric & Gas Co 00/10/31 150pp 07428 228

0101200001 Forwards request for addl info & comments re 790820 training & qualification plan & 790821 safeguards contingency plan Encl withheld (ref 10CFR2 7901)
TEDESCO, R L Assistant Director for Licensing 00/12/19 2pp 07307 029

0101140332 Requests that encl facility emergency planning info be made publicly available w/o encl
BOUDER, J L Division of Rules and Records 00/12/31 1p 07308 301

0101270955 Forwards request for addl info resulting from review of v 010103 emergency plan. Revised plan due by 010116
TEDESCO, R L Assistant Director for Licensing 01/01/14 10pp 07183 001

0101300857 Forwards facility emergency planning info to be made publicly available w/o encl
BOUDER, J L Division of Rules and Records 01/01/23 1p 07507 027

0101290129 Forwards Revision 1 to safeguards contingency plan Plan withheld (ref 10CFR2 7901)
NICHOLS, T C South Carolina Electric & Gas Co 01/01/26 1p 07566 363

0 Adjudicatory correspondence

0101070010 Memorandum P. order following 001125 third prehearing conference Reaffirms that intervenor must submit final list of intended witnesses, documents & summaries of testimonies by 010131
GROSSHART, H Atomic Safety and Licensing Board Panel 00/12/30 8pp 07413 307

--0101070017 Directs Dfc of Secretary & NRC staff to cease using FY80 funds for procedural assistance program per encl Comptroller General 001203 ltr
WEAR, E J Commissioners 00/12/04 1p 07413 315

0101060431 Forwards addl financial qualifications requested in 001201 ltr
NICHOLS, T C South Carolina Electric & Gas Co 00/12/31 14pp 07394 001

--0101060430 Order by Public Svc Commission of SC approving util req for adjustments in electric rates & charges.
YANCE, H Q South Carolina Electric & Gas Co STILL, J H South California Edison Co 00/06/30 94pp 07394 105

1 Financial information

0101060431 Forwards addl financial qualifications requested in 001201 ltr
NICHOLS, T C South Carolina Electric & Gas Co. 00/12/31 14pp 07394 001

--0101060434 Annual Rept 1979
* South Carolina Electric & Gas Co 00/02/00 140pp 07394 002

--0101060438 Order by Public Svc Commission of SC approving util req for adjustments in electric rates & charges.
YANCE, H Q South Carolina Electric & Gas Co STILL, J H South California Edison Co 00/06/30 94pp 07394 105

--0101060441 Direct testimony of OS Notten supporting util request for rate relief
MORTEN, Q S South Carolina Electric & Gas Co 79/08/31 22pp 07394 199

--0101060445 Rate of return testimony of SF Sherwin on 790831 Financial statements encl
SHERWIN, S F South Carolina Electric & Gas Co. SHERWIN, S F Foster Associates, Inc 79/08/31 195pp 07394 221

J. Insurance & indemnity information

B101090463 Forwards Endorsement 14 to LELIA Policy NR-252
FELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/31 2pp 07442 030

B101090542 Forwards Endorsement 15 to Ait Policy LF-252
FELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/31 2pp 07427-337

K. Utility Final Safety Analysis Report: FSARs & amends

B101090487 Forwards revised pages to FSAR, reflecting seismic monitoring
program status, in response to NRC request Changes will be
incorporated in Amend 23 by late Jan 1981
NICHOLS, T C South Carolina Electric & Gas Co 81/01/07 3pp
07427 328

B101210351 Forwards Amend 23 to FSAR, addressing NUREG-0737 criteria
NICHOLS, T C South Carolina Electric & Gas Co 81/01/19 2pp
07472 071

--B101210350 Amend 23 to FSAR, addressing NUREG-0737 criteria
South Carolina Electric & Gas Co 81/01/31 700pp 07492 073

L. Antitrust correspondence

B101190458 Forwards joint sys coordination & integration agreement
between SC Public Svc Authority & Central Electric Power
Cooperative, Inc Certificate of Svc encl
MORRISON, H P Cahill, Gordon & Reindel 81/01/14 99pp
07473 061

B10120062 Order scheduling filing of comments from Central Electric
Cooperative, SC Public Svc Authority, LSC Electric & Gas Co
by 810173, from DOJ by 810130 & from AEC by 810205
Certificate of Svc encl
MORRISON, H P Office of the Secretary of the Commission 81/01/15
4pp 07538 116

B101210349 Response to Commission B10115 order requesting comments on
effect of agreement between Central Electric Power
Cooperative, Inc & PSC of SC Antitrust review should be
denied Certificate of Svc & supportive documents encl
BRAND, W E, HALL, E E, UELLY, R T Central Electric Power
Cooperative, Inc 81/01/23 47pp 07546-351

B101280161 Response to B10115 order for comment on agreement between
SC Public Svc Authority & Central Electric Cooperative Addl
antitrust review unnecessary Petition for significant change
finding should be denied w/ Certificate of Svc
MORRISON, H O South Carolina Public Service Authority 81/01/23
14pp 07556 106

B101280331 Comments in response to B10115 order re agreement between
SC Public Svc Authority & Central Electric Power
Cooperative. No further antitrust review warranted
Certificate of Svc encl
MORRISON, J B South Carolina Electric & Gas Co, KNOTTS, J B
Debevoise & Liberman 81/01/23 12pp 07557 186

M. Inspection reports, IE Bulletins & correspondence

B101060196 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No written
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16
1p 07391 308

B101060212 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No written
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16
1p 07391 317

B101080217 Ack receipt of B01124 ltr informing AEC of steps taken to
correct violations noted in IE Insp Rept 50-395/80-25
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/12/16 1p 07421 041

--B101080227 Responds to AEC B01006 ltr re violations noted in IE Insp
Rept 50-395/80-25 Corrective actions issued special
instructions re valve lineup operations.
NICHOLS, T C South Carolina Electric & Gas Co 00/11/24 3pp
07421:042

--B101080233 Forwards IE Insp Rept 50-395/80-25 on B00721-0831 & net
of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/10/06 2pp 07421 045

--B101080239 Police of violation from Insp on B00721-0831
Region 2, Atlanta, Office of the Director 80/10/06 1p
07421 047

--B101080248 IE Insp Rept 50-395/80-25 on B00721-0831 Noncompliance
noted failure to follow procedure re valve lineup
SADLOS, J L Region 2, Atlanta, Office of the Director
WELLS, P J Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/10/06 13pp 07421 048

B101090385 Responds to IE Bulletin 80-23 No Valcor solenoid valves,
V70900-21-1 or 3 used Twenty manhours expended on bulletin
review
NICHOLS, T C Southern California Edison Co 80/12/29 1p
07378 360

B101270011 Responds to IE Bulletin 80-23 re Valcor Engineering Corp
solenoid valve failure Valcor solenoid valves V70900-21-1 &
V70900-23-3 not used
NICHOLS, T C South Carolina Electric & Gas Co 80/12/29 1p
07547 020

B101290194 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co, Inc." No active valves supplied w/Malcolm
Foundry yokes Westinghouse is conducting generic review
Study will not be complete until mid Feb 1981
NICHOLS, T C South Carolina Electric & Gas Co 80/12/31 1p
07569 353

B101220091 Forwards IE Insp Rept 50-395/80-36 on B01119-21 No
noncompliance noted
KENNA, W B Region 2, Atlanta, Safeguards Branch 81/01/02 2pp
07502 001

--B101220095 IE Insp Rept 50-395/80-36 on B01119-21 No noncompliance
noted Major areas inspected preoperational status of
physical security program Details withheld (ref IOCFR2 7901
PERNEY, C D, HILL, A O Region 2, Atlanta, Office of the Director
MCQUIRE, D R Region 2, Atlanta, Safeguards Branch 80/12/31
07502 003

B101130092 Responds to IE Bulletin 80-06 All engineering safety
features control circuits will be reviewed re deficiencies
in bypass, override & reset of engineering safety features
action Deviations from criteria will be corrected
NICHOLS, T C South Carolina Electric & Gas Co 81/01/09 1p
07457 022

N. Reportable occurrences, LERs & related correspondence

B101220559 Final deficiency rept re unauthorized hanger work, initially
reported on B01216 Caused by human error & lack of knowledge
of program requirements Insp program is being performed to
monitor installed hangers
NICHOLS, T C South Carolina Electric & Gas Co 81/01/13 3pp
07503 074

B101260491 Deficiency rept re presence of Train A red cable in Chem
IV yellow protection control cabinet. No credible fault of
failure exists which could degrade min degree of channel or
train redundancy Westinghouse evaluation encl
NICHOLS, T C South Carolina Electric & Gas Co 81/01/16 6pp
07529 215

B101260607 Interim deficiency rept, originally reported on B01024, re
adherent boron dilution event at shutdown conditions on RHR
sys Final rept will be issued after Westinghouse complete
investigation & long-term solution has been evaluated.
NICHOLS, T C South Carolina Electric & Gas Co 81/01/16 2pp
07531 225

B101260693 Final interim deficiency rept, originally reported on B00
re violation of Westinghouse separation criteria, for
separation of field run protection & control circuits
Thirty-Four circuits routed in cable trays
NICHOLS, T C South Carolina Electric & Gas Co 81/01/16 3pp
07531 227

B101280257 Final deficiency rept re failure to install insulation on
pipes of penetration assemblies, initially reported in B01224
Telcon insulation omission found not reportable condition
NICHOLS, T C South Carolina Electric & Gas Co 81/01/23 2pp
07559 002

1 Hearing transcripts on non-antitrust matters

8101060431 Forwards addl financial qualifications requested in 801208 ltr
NICHOLAS, T C South Carolina Electric & Gas Co 80/12/31 14pp
07394 001

--8101060441 Direct testimony of OS Hooten supporting util request for rate relief
HOOTEN, O S South Carolina Electric & Gas Co 79/08/31 22pp
07394 199

--8101060445 Rate of return testimony of SF Sherwin on 790831 Financial statements encl
SHERWIN, S F South Carolina Electric & Gas Co SHERWIN, S F
Foster Associates, Inc 79/08/31 199pp 07394 221

V Operator Examinations

8101060380 Forwards 5-yr projection of licensed operators at plant, per FJ Williams of Licensee Qualification Branch request
NICHOLAS, T C South Carolina Electric & Gas Co 80/12/30 14pp
07392 079.

8101090013 Discusses util position on TMI items re training & qualifications for shift technical advisors & independent safety engineering group
NICHOLAS, T C South Carolina Electric & Gas Co 81/01/02 2pp
07442 237.

8101270496 Forwards revised Attachment V re total licensed operators vs required licensed operators, per 801230 ltr Fifth shift to be added in June 1982
NICHOLAS, T C South Carolina Electric & Gas Co 81/01/22 3pp
07543 007.

DOCKET 50-396 UNIV OF VIRGINIA CAVALIER REACTOR

R. Periodic operating reports & related correspondence

8101300382 Submits annual operating rept for 1980, per Section 4.2.e of Tech Specs
FARRAR, J O Virginia, Univ of 81/01/09 14pp, 07581 336

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101190505 Ltr to all BWR applicants for OL re BWR scram discharge sys safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge vol encl
TEDESCO, R L Assistant Director for Licensing 80/12/22 2pp

--8101190514 Forwards generic safety evaluation re BWR scram discharge sys. Review identified two addl requirements to those proposed by owners group re scram discharge vol designs Rept to be transmitted to license applicants.
CHECK, P B Assistant Director for Plant Systems 80/12/01 2pp
07183 001

8101200157 Summary of 801210 meeting w/Mark II owners re status of generic improved chugging load model Owners requested to justify delay in program & investigate alternatives
ANDERSON, C J Generic Issues Branch 80/12/22 4pp.

8101140959 Summary of Dec 1980 meeting w/Mark II owners group, GE, BNLL, MIT, B&W, Bachtel & Ebasco Svcs, Inc re suppression pool temp limits List of attendees & handouts encl
SUTHERLAND, M Generic Issues Branch 80/12/30 4pp

8101190423 Forwards Instrumentation & Control Sys Branch addl Round 2 questions Applicant required to describe liquid level measuring sys within containment used to initiate safety-related actions
TEDESCO, R L Assistant Director for Licensing 80/12/30 7pp
07475 164

8101190427 Responds to NRC 800421 ltr requesting info on use of Category 1 masonry walls No Category 1 masonry walls exist at facility
BOUCHER, O D Washington Public Power Supply System 81/01/08
07476 085

8101190496 Advises that updated QA const program description will be issued as amend to FSAR to reflect project organization changes Meeting to discuss changes tentatively scheduled for 810225
BOUCHER, O D Washington Public Power Supply System 81/01/08
07475 330

8101210561 Notifies that util confirms request for meeting w/Mattie Branch on 810121 to discuss review of Unit 2 sacrificial shield wall, per telcon w/MI Lynch of LRC
BOUCHER, O D Washington Public Power Supply System 81/01/12
07489 297

8101230511 Notification of 810121 meeting w/util in Bethesda, MD re geological investigation program being conducted on faulting on Cable Mountain
LYNCH, M D Licensing Branch 1 81/01/12 3pp 07512 206

8101230512 Notification of 810121 meeting w/util in Bethesda, MD re developments by util in defining pool dynamic loads
LYNCH, M D Licensing Branch 1 81/01/12 3pp 07512 209

8101270669 Forwards summary of facility geology program in support of 810121 meeting w/LRC in Bethesda, MD
BOUCHER, O D Washington Public Power Supply System 81/01/21 12pp 07543 075

F Security, medical, emergency & fire protection plans

8101070287 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & b; applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

8101050510 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor For Steam Discharge Vol at Dresden Unit 2"
No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/12/05 1p 07390 277

8101290643 Forwards IE Insp Rept 50-397/80-18 on 801001-31 No noncompliance noted
SPENCER, G B Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/12/16 2pp 07566 131

--8101290646 IE Insp Rept 50-397/80-18 on 801001-31 No noncompliance noted Major areas inspected licensee & contractor activities to re-evaluate & improve methods of installing safety-related equipment
DILL, A O Region 5, San Francisco, Office of the Director HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/12/11 10pp 07566 133

8101130110 Forwards IE Info Notice 80-45, "Potential Failure of OWH Backup Manual Scram Capability." No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/12/17 1p 07439 223.

8101090784 Forwards Snpp 4 to IE Bulletin 80-17, "Failure of 76 o Control Rods to Fully Insert During Scram at BWR." No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/12/18 1p 07430 253

8101030164 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rod Safety Relief Valves at BWRs." No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/12/19 2pp 07377 269

8101210110 Forwards IE Insp Rept 50-397/80-21 on 801202-04 No noncompliance noted
CRENSHAW, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/12/24 2pp 07489 350

--8101210119 IE Insp Rept 50-397/80-21 on 801202-04 No noncompliance noted Major areas inspected: low pressure core spray preoperational test, flushing program & results of control rod hydraulic sys flush.
STEINBERG, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch CARLSON, J D Region 5, San Francisco, Office of the Director 80/12/23 3pp 07489 352

Amend 2 Amend includes drawing A title changes reflective of as-built conditions & description of mechanized equipment used for examination of reactor pressure vessel
BOUCHER, D D Washington Public Power Supply System 80/12/31 2pp
07517 649

- B10104021 Preservice Insp Program Plan & Revisions, Amend 2
Washington Public Power Supply System 80/12/18 300pp
07517 651

B101270484 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves
mfg by Valcor Engineering Corp. Specified valves are not
used at facility
MADUR, D H Washington Public Power Supply System 80/12/31 1p
07545 061

B101276505 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co. Inc. " Manufacturers have been contacted
Supplemental report will be sent during Feb 1981
MATLOCK, R G Washington Public Power Supply System 81/01/02 2pp
07543 349

B101270459 Confirms 801223 letter approving 30-day extension to respond
to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm
Foundry Co. Inc."
MADUR, D H Washington Public Power Supply System 81/01/06 1p
07543 348

5 Reportable occurrences, IERs & related correspondence

B101340518 Final deficiency report re fuel pool boiling prevention.
Initially, reported 770918 Addl cooling coils will not be
placed in standby gas treatment sys. Corrective action
fuel pool cooling sys upgraded to safety grade status
MATLOCK, R G Washington Public Power Supply System 80/12/03 2pp
07452 653

B101050013 Interim deficiency report, originally reported on 801114, re
overload on supports for spray pond piping. Caused by
hardware design error. Review of original design margins to
be completed by 801212
MATLOCK, R G Washington Public Power Supply System 80/12/15 2pp
07385 274

B101050089 Interim deficiency report re nonseismic Class 1 const &
installation of control room cabinet for digital electro-
hydraulic turbine generator. Failure during seismic event
could cause damage to safety-related equipment
MATLOCK, R G Washington Public Power Supply System 80/12/15 2pp
07376 229

B101140497 Interim deficiency report re wiring interfaces on motor
operators. Conflict discovered between electrical const
drawings & info provided by subcontractor. Followup report to
be submitted by 810316
MATLOCK, R G Washington Public Power Supply System 81/01/07 3pp
07461 157

B101230730 Part 2) report re failure to provide proper control components
Intl valves supplying 2 gpm flow when in closed position
Caused by valve failure. Affected licensees notified &
selection of alternative method underway
TAYLOR, J H Batcock & Wilson Co 81/01/09 2pp 07308 001

DOCKET 80-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101050325 Informs of Unit 1 const schedule revision, changing
commercial operation date from Mar to Sept 1985. New schedule
requires timely DL issuance for Dec 1984 fuel loading. Future
FSAR amend will reflect const change. Other units unchanged.
JOHNS, J A Carolina Power & Light Co 80/12/30 1p 07385 279

3 Inspection reports, IE Bulletins & correspondence

B101060233 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No written
response required
O'REILLY, J R Region 2, Atlanta, Office of the Director 00/
1p 07391 341

B101040200 Responds to IE Bulletin 80-23 re failures of solenoid
mfg by Valcor Engineering Corp. No valves mfg by vendor used.
MCUFFIE, M A Carolina Power & Light Co 80/12/24 1p 074

B101210217 Responds to IE Bulletin 80-21, "Valve Yokes Supplied
Malcolm Foundry Co. Inc." Any valve parts having properties
not in accordance w/ASTM matl spec will be replaced by
affected vendor
MCUFFIE, M A Carolina Power & Light Co 81/01/05 2pp
07493 047

B101270353 Ack receipt of 801223 ltr forwarding revised response
Insp Repts 50-400/80-15, 90-401/80-13, 90-402/80-13 &
50-403/80-13
KARNPH, C E Region 2, Atlanta, Reactor Construction & Engineer
Support Branch 81/01/13 1p 07571 355

5 Reportable occurrences, IERs & related correspondence

B101070437 Interim deficiency report re deficiencies in procurement
fabrication & insp of engineered plates for safety-related
load concrete embedment & support. Addl ultrasonic exams
being performed. Re-evaluation/correction completion 810301
CHIANQI, H J Carolina Power & Light Co 80/12/30 1p 0741

B101130225 Interim deficiency report re loading of cadweld sleeves
nonqualified procedures, originally reported on 801205
Procedures have been qualified. Requests extension to 810202
for evaluation
CHIANQI, H J Carolina Power & Light Co 81/01/05 2pp 07

DOCKET 80-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101050325 Informs of Unit 1 const schedule revision, changing
commercial operation date from Mar to Sept 1985. New schedule
requires timely DL issuance for Dec 1984 fuel loading. Future
FSAR amend will reflect const change. Other units unchanged.
JOHNS, J A Carolina Power & Light Co 80/12/30 1p 07385

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

3 Inspection reports, IE Bulletins & correspondence

B101060233 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No written
response required
O'REILLY, J R Region 2, Atlanta, Office of the Director 80/
1p 07391 341

B101140200 Responds to IE Bulletin 80-23 re failures of solenoid
mfg by Valcor Engineering Corp. No valves mfg by vendor used.
MCUFFIE, M A Carolina Power & Light Co 80/12/24 1p 07

29C353 Act receipt of B01223 ltr forwarding revised response to IE
sp Rpts: 50-400/B0-15, 50-401/B0-13, 50-402/B0-13 &
-403/B0-12
RPLY: C E Region 2: Atlanta: Reactor Construction & Engineering
port Branch B1/01/13 1p 07571 359

reportable occurrences, LERs & related correspondence

070437 Interim deficiency rept re deficiencies in procurement
of concrete embedment & support Addl ultrasonic exam-
ing performed Re-evaluation/correction completion 810301
[AN91.N J. Carolina Power & Light Co 80/12/30 1p 07414 143

ET 50-402 BHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

application/construction stage documents & correspondence

220466 ltr to all power reactor licensees & applicants forwarding
 copy of B01112 meeting re implementation of guidance for
 resolved Safety Issue A-12. "Potential for Low Fracture
 Toughness & Low Fatigue Tearing on Component Supports"
 BENHUT, D. G. Division of Licensing B0/11/26 Bpp

050325 informs of Unit 1 const schedule revision, changing
commercial operation date from Mar to Sept 1985 New schedule
guarantees timely OL issuance for Dec 1984 fuel loading Future
AR spend will reflect const change Other units unchanged

NE5, J A Caroline Power & Light Co 80/12/30 1p 07285 279

security, medical, emergency & fire protection plans

090387 Ltr to all licensees of operating reactor plants. CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 0102 & by applicants as part of FSAR
GEN-HUT, D. G Division of licensing 80/11/13 2pp.

nspection reports. IE Bulletins & correspondence

060233 Forwards IE Info Notice 80-44, "Actuation of ECCB in
circulation Mode While in Hot Shutdown " No written
response required
REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/16

140200 Response to IE Bulletin 80-23 re failures of solenoid valves
g by Valcor Engineering Corp No valves mfg by vendor used
DUFFIE, M A Carolina Power & Light Co. 80/12/24 1p 07461 252

210217 Responses to IE Bulletin 00-21, "Valve Yokes Supplied by
 nicolm Foundry Co. Inc " Any valve parts having properties
 t in accordance w/ASTM matl spec will be replaced by
 fected vendor
 OFFICE M A Carolina Power & Light Co. 01/01/09 2pg
 490-047

290353 Ack receipt of 801223 ltr forwarding revised response to IE
 Resp Rpts 90-400/80-15, 90-401/80-13, 90-402/80-13 &
 90-403/80-13
 RPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 8J/01/13 1p 07571 355

reportable occurrences, LERs & related correspondence

070237 Interim deficiency rept re deficiencies in procurement
fabrication & insp of engineered plates for safety-related
and concrete embedment & support Addl ultrasonic exams
being performed. Re-evaluation/correction completion 8/0301.
#ANQ1.12 J. Carolina Power & Light Co 80/12/30 1p 07414-143

SET 50-403 BPEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

Application/construction stage documents & correspondence

220446 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" (B6NHUT, D O Division of Licensing, B0/11/26 Bpp

F Security, medical, emergency & fire protection plans

B101090397 Ltr to all licensees of operating reactor plants. CP holders
 & CP applicants Revised radiological emergency response
 plans must be submitted by licensees within 60 days of
 B10102 to CP applicants as part of FSAR
 E15FHWJ.D G Division of Licensing 80/11/13. 200

Q Inspection reports, IF Bulletins & correspondence

DISPATCHED Forward JE Info Notice BD-44, 'Activation of ECCS in
Recirculation Mode While in Hot Shutdown.' No written
response required.
D'REILLY, J P Region 2, Atlanta, Office of the Director EO/12/16
lf

6101140203 Response to H. Bulletin 80-23 re failures of solenoid valves
mfg by Valcor Engineering Corp No valves mfg by vendor used
MCDUFFIE, M A Carolina Power & Light Co 80/12/24 1p

910120217 Response to JF Bulletin 60-21, 'Valve Yokes Supplied by
Malcolm Foundry Co. Inc.' Any valve parts having properties
not in accordance w/ASTM mat'l spec will be replaced by
affected vendor
McDUFFIE, M A Carolina Power & Light Co B1/01/05 2pp

B101290353 Act receipt of B01223 ltr forwarding revised response to IE
 Insp Repts 50-400/B0-15, 50-401/B0-13, 50-402/B0-13 &
 50-403/B0-13
 WARRPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 6/10/13 lc

S. Reportable occurrences, IERs & related correspondence

Q101070437 Interim deficiency report re deficiencies in procurement fabrication & insp of engineered plates for safety-related load concrete embedment & support Add'l ultrasonic exams being performed R-evaluation/correction completion 010301 CHIA491 H J Caroline Power & Light Co. 80/12/30 1p

DOCNET 50-404 NORTH ANNA POWER STATION, UNIT 3

F Security, radical, emergency & fire protection plans

B01060615 Requests that encl emergency planning info be made
publicly available N/A encl
GUYDER, J L. Division of Rules and Records B0/12/17 lp
07399 359

B101080146 Requests that encl emergency planning info be made publicly available w/a encl.
SOUPEL J L Division of Rules and Records 80/12/17 lp
07419 24B.

Insurance & indemnity information

010100357 Forwards Endorsements 2, 5, 4, 4, 24, 58 & 31 to NELA Policies
EB-70, EB-63, EB-28, EB-27, NG-316 NF-184 & NF-240, respectively.
WARRFIELD, K. J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc.
Biv. 81/01/09 16pp

8 Reportable occurrences, LERs & related correspondence

B101270707 Interim deficiency rept re apparent disparity between B&W
mathematical model of upper steam generator support sys &
actual hardware. Initially reported B01223 Caused by manner
in which forces were reported Final rept expected by B10223
SPENCER:W C Virginia Electric & Power Co B1/01/82 6pp
07545 243.

DOCKET 90-405 NORTH ANNA POWER STATION, UNIT 4

F Security, medical, emergency & fire protection plans

8101060515 Requests that encl emergency planning info be made
publicly available. N/O encl
SPUDER, J L Division of Rules and Records. 80/12/17 1p

B101CB0146 Requests that encl emergency planning info be made publicly available 11/3 encl
SANDER, J L Division of Rules and Records 80/12/17 1p

J Insurance & indemnity information

B101130357 Forwards Endorsements 2, 5, 4, 4, 24, 50 & 31 to HELIA Policies EB-73, EB-63, EB-28, EB-27, NS-316, NF-186 & NF-240, respectively.
HAIRFIELD, K J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
D1, B1/01/09 16pp

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FBA9
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101050326 Forwards revisions to physical security plan for facility Revisions withheld (ref 10CFR2 790)
LINDER, F Dairyland Power Cooperative 00/12/29 2pp 07387 284

B101220025 Forwards training & qualification plan revisions Plan withheld (ref 10CFR2 790)
LINDER, F Dairyland Power Cooperative B1/01/15 2pp 07501 343.

G Adjudicatory correspondence

B101120524 Prehearing conference memorandum from B01217 hearing which established proposed findings & conclusions schedule & SSE phase discovery schedule
DECHHOEFER, C Atomic Safety and Licensing Board Panel. B1/01/06 3pp 07445 176

--B101120528 Supports nuclear power Certificate of Bvc encl.
VASLOW, C Affiliation Unknown 80/12/16 3pp 07445 178

B101140983 Order granting extension until B10123 for Commission to review ALAB-b1B
CHILK, S J Office of the Secretary of the Commission B1/01/09 3pp 07456 299

B101200034 Motion that listed corrections be made to transcript of B01216-17 evidentiary hearing in LaCrosse, WI Certificate of Bvc encl
BURNS, S G Rule-making & Enforcement Division B1/01/26 10pp 07555 093

H General correspondence

B101090577 Comments that nation needs nuclear power for economic political & moral reasons
VASLOW, C Affiliation Unknown 80/12/16 1p 07428 353

B101050307 Comments by WXXM-TV/HSDM-TV on ASLB review of facility. Power supplied by plant is necessary for station to perform per FCC license requirements Recommends that NRC approve continued operation of facility
PESCHAU, D F Affiliation Unknown 80/12/19 1p 07379 306

J Insurance & indemnity information

B101140225 Forwards Endorsements 38 & 39 to HELIA Policy NF-217
PAULY, S A Hobbs Brook Agency, Inc B1/01/06 4pp 07461 267

P. Operating license stage documents & correspondence

B011190112 Submits list of topics that should be added to 791116 listing for deletion from SEP review Revised list of DBE accident & transient groups applicable to BWRs encl.
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/26 5pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01111 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 4pp.

060836 Requests invoice be sent to licensee for review of route proposal
LLER, W G License Fee Management Branch 80/12/08 1p 400 127.

--B101060361 Forwards data re tests & manpower incurred in review of licensee request for route approval
MCDONALD, J W Physical Security Licensing Branch PARTLOW, J O Material Control Licensing Branch 80/11/05 2pp 07400 120

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR steam discharge sys Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes
EISENHUT, D O Division of Licensing 80/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions required assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl.
* Division of Licensing 80/12/01 212pp. 07183 001.

B101140377 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures Info should be provided within 90 days of receipt of ltr
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 4pp 07458 189

B101216322 Ltr for all BEP licensees forwarding guidelines for performing soil-structure interaction reviews for SEP facilities & simplified analytical approach for evaluating soil-structure interaction using lumped parameter model.
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 2pp 07491 348

B101210445 Forwards responses to questions on Rule 50 71e. "Periodic Updating of FBARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-BEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 00/12/15 13pp

B101270130 Forwards safety evaluation of BEP Topic 11-2, A. "Severe Weather Phenomena" & TX Tech Univ rept. "Tornado & Straight Wind Hazard Probability for LaCrosse Nuclear Power Reactor Site, WI"
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 7pp 07547 221

--B101270141 "Tornado & Straight Wind Hazard Probability for LaCrosse Nuclear Power Reactor Site, WI"
MCDONALD, J W Texas Tech Univ NRC-04-76-345 80/05/31 26pp 07367 228

B101160329 Notification of B01218 meeting w/BEP owners group in Bethesda, MD re BEP program schedule for licensee topic completion & assignment of lead topics to plants
RUESELL, M T Technical Support Branch 00/12/16 2pp.

B101080099 Informs of 24-h load test performed B01127 on emergency Diesel Generator 13 at connected load of 300 kW in accordance w/resident inspector request & IE Bulletin 79-23.
LINDER, F Dairyland Power Cooperative 80/12/17 2pp 07420 34

B101230343 Forwards listing of all BEP correspondence re facility per BEP owners group B01202 meeting List provides basis upon which to determine plant status Review & comments requested.
W/o encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/22 2pp 07512 104

B101090342 Provides extended schedule for response to NUREG-0737 requirements Delay due to refueling outage & ASLB hearings on site liquefaction Extensions do not represent delay in completion of mods
LINDER, F Dairyland Power Cooperative. 80/12/31 2pp 07442 20

B101100804 Adequacy of Station Electric Distribution Sys Voltage, LaCrosse, " Informal preliminary rept
UDY, A C Idaho National Engineering Laboratory. B101100804 80/12/31 14pp 07444 045

B101300508 Advises that evaluation of SEP Topic V-10 A. "RHR Bye Pass Exchanger Tube Failures," is considered complete since util did not comment on NRC 790111 draft evaluation.
CRUTCHFIELD, D Operating Reactors Branch 5 B1/01/07 2pp. 07586 268

B101300181 Forwards info re NUREG-0737 clarification items requested in NRC B01031 Ltr. Comparison of facility shift technical advisor program to Institute of Nuclear Power Operations program encl
LINDER, F Dairyland Power Cooperative. B1/01/16 18pp. 07586:2

8101270345 Submits info re injection of grout into voids under turbine
bldg that two 94 lb bags of cement used instead of two 49 lb
bags as stated in 801126 ltr
LINDER, F Dairyland Power Cooperative 81/01/21 1p 07543 094

Q Inspection reports, IE Bulletins & correspondence

8101030279 Forwards IE Info Notice 80-30, "Cracking in Charging Pump
Casing Cladding " No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30
2pp 07389 223

8101060109 Forwards IE Circular 80-23, "Potential Defects in Relief
Power Sys Emergency Generators " No written response
required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/31
1p 07397 320

8101060522 Forwards IE Info Notice 80-37, "Malfunction of Solenoid
Valves Mfg by Valcor Engineering Corp " No written response
is required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/31
2pp 07401 195

8101050471 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co. Inc " Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/06
2pp 07390 032

8101060631 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply
Pressure Actuates Safety-Relief Valve Operation to Cause
Reactor Depressurization " No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/07
2pp 07392 170

8101060390 Forwards IE Info Notice 80-41, "Failure of Swing Check
Valve in Decay Heat Removal Sys at Davis Besse Unit 1 " No
response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/10
2pp 07391 085

8101060495 Forwards IE Bulletin 80-23, "Failures of Solenoid Valve
Mfg by Valcor Engineering Corp " Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/14
2pp 07391 223

8101050520 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Scram Discharge Vol at Dresden Unit 2 " No
response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05
2pp 07390 207

8101230667 Forwards IE Insp Rept 50-409/80-16 on 801202 No
noncompliance noted
FICRELLI, G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/11 2pp 07512 346

--8101230672 IE Insp Rept 50-407/80-16 on 801202 No noncompliance noted
Major areas inspected review of inservice procedures, work
activities, personnel certification & data & IE Bulletins
79-03A & 80-00 activities
WARD, K D Region 3, Chicago, Office of the Director
DANIELSON, D H Region 7, Chicago, Reactor Construction &
Engineering Support Branch 80/12/10 5pp 07512 348

8101210640 Forwards IE Insp Rept 50-409/80-13 on 801001-31 & notice of
violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/12/16 2pp 07488 118

--8101210641 Notice of violation from Insp on 801001-31.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear
Support Branch 80/12/12 2pp 07488 120

--8101210643 IE Insp Rept 50-409/80-13 on 801001-31 Noncompliance noted:
use of unqualified guard as armed responder & failure of
shift supervisor to make required tours
FORNEY, W L, DRANCH, M W, RIDGWAY, K R Region 3, Chicago, Office
of the Director 80/12/12 7pp 07480 122

8101070627 Forwards IE Info Notice 80-45, "Potential Failure of BWR
Backup Manual Scram Capability " No written response
required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17
2pp 07414 172

8101080099 Informs of 24-h load test performed 801127 on emergency
Diesel Generator 1B at connected load of 300 kW in
accordance w/resident inspector request & IE Bulletin 79-23
LINDER, F Dairyland Power Cooperative 80/12/17 2pp 07420 345

8101050182 Forwards IE Bulletin 80-25 "Operating Problems w/Target
Rock Safety Relief Valves at 3WRs " No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/19
2pp 07377 313

8101080109 Responds to IE Bulletin 80-21 re valve yokes supplied by
Malcolm Foundry Co. Inc No valves in safety-related sys have
parts cast by manufacturer Total manpower expended was 46-h
LINDER, F Dairyland Power Cooperative 80/12/19 1p 07420 359

8101300636 Responds to IE Bulletin 80-25, "Operating Problems w/Target
Rock Safety-Relief Valves at 3WRs " Pneumatic operated
safety valves not used or planned for use at facility
LINDER, F Dairyland Power Cooperative 80/12/31 3pp 07587 077

8101200170 Responds to IE Bulletin 80-24, "Prevention of Damage Due to
Water Leakage Inside Containment (801017 Indian Point 2
Event)" Facility has no open cooling water sys in operation
inside containment matching bulletin description
LINDER, F Dairyland Power Cooperative 81/01/06 4pp 07486 210

8101280515 Responds to IE Bulletin 80-13, "Cracking in Core Spray
Spargers " Facility does not utilize core spray spargers of
type in which cracks were detected No indication of defects
found in inspected components
LINDER, F Dairyland Power Cooperative 81/01/13 2pp 07590 326

R Periodic operating reports & related correspondence

8101100491 Forwards monthly operating rept for Dec 1980
LINDER, F Dairyland Power Cooperative 81/01/09 1p 07450 157

--8101100494 Monthly operating rept for Dec 1980
GORDMAN, L S Dairyland Power Cooperative 81/01/09 12pp
07458 158

S Reportable occurrences, IERs & related correspondence

8101050374 Forwards IER 80-013/03L-0
LINDER, F Dairyland Power Cooperative 80/12/22 2pp 07389 300

--8101050388 IER 80-013/03L-0 on 801127 during periodic leakage rate
testing, electrical penetration unit 6 was determined to
exceed Tech Specs limits Caused by cracked gland on
individual penetration 29A Gland was soldered
GORDMAN, L S Dairyland Power Cooperative 80/12/22 2pp
07389 302

8101050383 Forwards IER 80-012/03L-0
LINDER, F Dairyland Power Cooperative 80/12/26 6pp 07389 304

--8101050391 IER 80-012/03L-0 on 801124 soil sample under feedwater
heater area of turbine bldg found slightly contaminated
Caused by drilling hole in bldg floor on when Ploot was
washed prior to grouting Surveillance program established.
GORDMAN, L S Dairyland Power Cooperative 80/12/23 1p
07389 310

8101060561 Forwards IER 80-017/01T-0
LINDER, F Dairyland Power Cooperative 80/12/30 2pp 07391 117

--8101060583 IER 80-017/01T-0 on 801216 crane reactor cavity purge ch
valve & 251B reactor vent header valve found leaking Caused
by rust & debris Valves replaced.
GORDMAN, L S Dairyland Power Cooperative 80/12/30 1p
07391 119

8101160433 Special rept on 801201 during refueling outage high pressure
svc water diesel pump 1B was removed from normal standby
condition to perform 9-yr preventative maint program &
remained inoperable for 8 days Pump returned to svc 801209
LINDER, F Dairyland Power Cooperative 81/01/06 2pp 07472 147

T Hearing transcripts on non-antitrust matters

8101280320 Proposed corrections to transcript of 801216-17 evidential
hearing in Le Grasse, WI Certificate of Svc encl
HEISTAND, D S Dairyland Power Cooperative 81/01/13 11pp
07557 175

V Operator Examinations

8101300101 Forwards info re NUREG-0737 clarification items requested
in ARC 801031 ltr Comparison of facility shift technical
advisor program to Institute of Nuclear Power Operations
program encl
LINDER, F Dairyland Power Cooperative 81/01/16 18pp 07586 20

Application/construction stage documents & correspondence

101120345 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" EISENHUT.D.G. Division of Licensing 80/11/26 8pp

101120157 Summary of B01110 meeting w/Mark II owners re status of generic improved chugging load model. Owners requested to justify delay in problem & investigate alternatives. ALDERSON.C.J. Generic Issues Branch 80/12/22 4pp

101140355 Summary of Dec 1980 meeting w/Mark II owners group. CE, B.L. MIT, S.W. Reichtel & Etasen Svcs. Inc re suppression pool temp limits list of attendees & handouts sent. SW, T.H. Generic Issues Branch 80/12/30 4pp

101140590 Responses to Util: 790403 & 0908 ltrs requesting approval of design change re main steam isolation valves. Licensee may proceed w/procurement & installation, but should reserve space to provide for potential backfitting. TEDESCO.R.L. Assistant Director for Licensing 81/01/02 3pp 07471 207

101130239 Responses to NRC 800610 ltr requesting info re jet pump supports. Beam design used at facility operates at peak stress less than BWR/3 beams. Preload on beams will be reduced from 30,000 to 25,000 lbs. RUDOLF.G.W. Niagara Mohawk Power Corp 81/01/09 1p 07457 028

Security, medical, emergency & fire protection plans

101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of FEAR. EISENHUT.D.G. Division of Licensing 80/11/13 2pp

Inspection reports, IE Bulletins & correspondence

101070403 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 074

101050128 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Val at Oresden Unit 2." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/12/05 1p 07376 347

101060142 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/12/17 1p 07391 259

101070047 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 189 Control Rods to Fully Insert During Scram at BWR." No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/12/18 1p 07414 011

101130838 Forwards IE Bulletin 80-25, "Operating Problems w/Target Rod Safety-Relief Valves at BWRs." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/12/17 1p 07458 327

Reportable occurrences, IERs & related correspondence

101190336 Ack receipt of Util B01201 interim deficiency rept re spent fuel pool cooling water heat exchangers. Matter will be reviewed pending receipt of final rept. CARLSOHL.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/18 1p 0747A 034

132 Final interim deficiency rept. originally reported on B01205, re rigging of safety-related equipment. Site re input requirements for handling & rigging related equipment inadequate. Niagara Mohawk Power Corp 81/01/26 3pp 07586 094

B01050465 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." EISENHUT.D.G. Division of Licensing 80/11/26 8pp

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of FEAR. EISENHUT.D.G. Division of Licensing 80/11/13 2pp

B01105737 Requests that each facility emergency planning info be made publicly available. W/ enc. SUGGER.J.L. Division of Rules and Records 80/12/31 1p 07453 125

A. Inspection reports, IE Bulletins & correspondence

8101070411 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 059

B01060824 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/12/16 1p 07397 037

B. Reportable occurrences, IERs & related correspondence

B01030109 Ack receipt of B01114 Significant Deficiency Rept 80-08 re inferior welds on cable tray fittings. CARLSOHL.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/25 1p 07583 082

B01050404 Interim Rept 3 re Significant Deficiency 80-03 concerning linear indications in girth gasket welds in reactor vessel structural support. Support will be repaired at B&W Mt Vernon, Ill facility. WOLFEVER.E.J. Duquesne Light Co 80/12/12 2pp 07389 316

B01190272 Ack receipt of B01120 interim deficiency rept on 3-inch motor operated valves in safety injection & chemical & vol control sys. CARLSOHL.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/18 1p 07475 063

B01190279 Interim deficiency rept re failure of Westinghouse 3-inch motor operated valves in safety injection & chemical & vol control sys. Initially reported on B01029. Corrective action is under investigation. WOLFEVER.E.J. Duquesne Light Co 80/11/20 4pp 07475 064

B01070390 Ack receipt of B01120 ltr forwarding interim rept re 3-inch gate valves in safety injection & chemical & vol control sys. CARLSOHL.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/24 1p 07414 180

B0106045D Initial interim deficiency rept re seismic calculations for Category 1 structures. Calculations, drawings & other design considerations will be corrected as required. Next interim rept will be issued by B01022. WOLFEVER.E.J. Duquesne Light Co. 81/01/02 2pp 07396 088

DOCKET 80-413 CATAWBA NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

B01220455 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." EISENHUT.D.G. Division of Licensing 80/11/26 8pp

B101120265 Requests util perform ultimate capacity analysis of Mark 111 containment for NRC generic review re effects of hydrogen evolving from postulated accident
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp
07446 273

B10150163 Forwards Amend 1 to CPPR-116, safety evaluation, EIA, negative declaration & notice of issuance & availability
EISENHUT, D O Division of Licensing 80/12/23 5pp 07300 001

--B10150171 Amend 1 to CPPR-116, adding KC Electric Membership Corporation & Saluda River Electric Cooperative, Inc as co-owners of facility
EISENHUT, D O Division of Licensing 80/12/23 1p 07300 001

--B10150176 Safety evaluation supporting Amend 1 to CPPR-116.
TEDESCO, R L Assistant Director for Licensing 80/12/23 10pp
07300 001

--B10150180 EIA supporting Amend 1 to CPPR-116
• Division of Licensing 80/12/23 2pp 07300 001

--B10150186 Negative declaration re Amend 1 to CPPR-116
MIRALJA, F J Licensing Branch 3 80/12/23 2pp 07300 001

--B10150189 Notice of issuance & availability to Amend 1 to CPPR-116
MIRALJA, F J Licensing Branch 3 80/12/23 2pp 07300 001

B101500836 Forwards test plan for next series of tests re Commission-directed electrical connector test program Requests review
FEIT, R Qualification Testing Evaluation Review Group 81/01/14 2pp 07586 021

--B101500841 Forwards Draft 3 of 'Connector Assembly Test Plan for Duke Power, Catauba 1 & 2 Connectors'
BUCKALEW, H H Sandia Laboratories 80/12/22 16pp 07586 023

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

O Adjudicatory correspondence

B101290011 Forwards Director's decision under 10CFR2 206 denying 790128 petition for reopening safety phases of licensing proceeding & notice of issuance
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/09 3pp 07573 295

--B101290017 Director's decision under 10CFR2 206, denying Carolina Environ Study Group 790128 petition for reopening safety phases of licensing proceeding
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/09 20pp 07573 298

--B101290022 Notice of issuance of B00109 Director's decision under 10CFR2 206, denying Carolina Environ Study Group 790128 petition for reopening safety phases of licensing proceeding
CASE, E O Office of Nuclear Reactor Regulation, Director 81/01/09 2pp

M Antitrust correspondence

B101120503 Response opposing B01215 HQ Ayers antitrust hearing request Ltr fails to establish standing or satisfy antitrust criteria Discretionary intervention not warranted
Certificate of Svc encl
CHANANIA, F O Antitrust Division 81/01/09 18pp 07440 325

B101160189 Notice of ASI, B constitution ME Miller, chairman & PB Carter & RM Lazo, members Certificate of Svc encl
COTTER, B P Atomic Safety and Licensing Board Panel 81/01/09 4pp 07470 044

B101160220 Response of Duke Power Co, KC Electric Membership Corp & Saluda River Electric Cooperative in opposition to HQ Ayers B01215 ltr request to Intervene & for antitrust proceeding
Certificate of Svc encl
PORTER, W L Duke Power Co, MCARRY, J M Debevoise & Liberman 81/01/12 9pp 07470 171

B101160241 Memorandum & order denying HQ Ayers B01215 request for antitrust hearing Also grants Ayers leave to file amended petition for leave to intervene & request for antitrust hearing by B10131 Certificate of Svc encl
MILLER, M E, LAZO, R M, COTTER, B P Atomic Safety and Licensing Board Panel 81/01/12 12pp 07472 048

O Inspection reports, IE Bulletins & correspondence

B101070320 Forwards supplemental responses to HRC B01016 ltr re violations noted in IE Insp Repts 50-413/80-08, 50-367/80-08, 50-413/80-09, 50-413/80-09, 50-413/80-09, 50-492/80-06 & 50-493/80-06 Final report to be submitted by B10131
PARKER, W D Duke Power Co 80/11/11 2pp 07413 305

B101070313 Responds further to HRC B01010 ltr re violations noted Insp Repts 50-413/80-16 & 50-414/80-16 Corrective action all cable tray installation drawings showing proper weld symbols revised & released
PARKER, W D Duke Power Co 80/12/03 1p 07413 303

--B101070316 Response further to HRC B01010 ltr re violations noted Insp Repts 50-413/80-16 & 50-414/80-16 Corrective action all cable tray installation drawings will be reviewed, revised & released as required by B01201
PARKER, W D Duke Power Co 80/10/22 1p 07413 309

B101060225 Forwards IE Info Notice B0-41, "Activation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/11/12 1p

B101160562 Ack receipt of B01218 ltr informing HRC of steps taken correct violations noted in IE Insp Repts 50-413/80-33 & 50-414/80-33
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/01/02 1p 07472 020

--B101160568 Responds to HRC B01210 ltr re violations noted in IE Repts 50-413/80-33 & 50-414/80-33 Corrective actions engineers involved will be retrained in requirements of procedure.
PARKER, W D Duke Power Co 80/12/18 2pp 07472 021

--B101160671 Forwards IE Insp Repts 50-413/80-33 & 50-414/80-33 B01027-31 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/02 2pp 07472 023

--B101160679 Notice of violation from Insp on B01027-31
• Region 2, Atlanta, Office of the Director 80/12/02 1p 07472 023

--B101160684 IE Insp Repts 50-413/80-33 & 50-414/80-33 on B01027 Noncompliance noted failure to follow procedure for reporting cracks in auxiliary hldg concrete
MURPHY, C E Region 2, Atlanta, Office of the Director 80/12/02 4pp 07472 026

B101290400 Responds to IE Bulletin B0-21, "Valve Yokes Supplied Malcolm Foundry Co, Inc" No active valves cast by Malcolm Foundry are in use at facilities
PARKER, W D Duke Power Co 81/01/05 1p 07573 358

S Reportable occurrences, LERs & related correspondence

B101140600 Final deficiency rept 50-413/414/80-08 originally rep on B03617, re inadequate min flow through centrifugal charging pump Util will implement Westinghouse interim Mod 2 transmitted on B00714
PARKER, W D Duke Power Co 81/01/07 2pp 07461 245

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants for summary of B01312 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101120265 Requests util perform ultimate capacity analysis of containment for NRC generic review re effects of hydrogen evolving from postulated accident
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp 07446 273

B10120036 Forwards test plan for next series of tests re Commission-directed electrical connector test program Request received
FEITH, Qualification Testing Evaluation Review Group. 8/10/14
2pp 07585 021

--B10137084: Forwards Draft 3 of Connector Assembly Test Plan for Duke Power, Atlanta 1 & 2 Connectors
BUCHANAN, W. H. Sandia Laboratories 8/12/22 16pp 07586 023.

F. Security, medical, emergency & fire protection plans

B101090367 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Requested radiological emergency response plans must be submitted by licensee within 60 days of B10102 & by applicants as part of FBAR
EISENHUT, D. D. Division of Licensing 8/11/13 2pp

G. Adjudication, correspondence

B101290011 Forwards Director's decision under 10CFR2.206 denying 790128 petition for reopening safety phases of licensing proceeding & notice of issuance
DEITCHER, R. Office of Nuclear Reactor Regulation, Director 8/10/09 3pp 07573 295

--B101290017 Director's decision under 10CFR2.206 denying Carolina Environ. Study Group 790128 petition for reopening safety phases of licensing proceeding
DEITCHER, R. Office of Nuclear Reactor Regulation, Director 8/10/09 28pp 07573 298

--B101290022 Notice of issuance of B00109 Director's decision under 10CFR2.206 denying Carolina Environ. Study Group 790128 petition for reopening safety phases of licensing proceeding
CASE, F. G. Office of Nuclear Reactor Regulation, Director 8/10/09 2pp

H. Antitrust correspondence

B101160189 Notice of AS-B constitution PE Miller, chairman & PB Cottor & RM Laco, members Certificate of Svc encl
DEITCHER, R. P. Atomic Safety and Licensing Board Panel 8/10/09 4pp 07470 044

B101160741 Memorandum & order denying RO Ayers B01215 request for antitrust hearing Also grants Ayers leave to file amended petition for leave to intervene & request for antitrust hearing by B10131 Certificate of Svc encl
MILLER, M. E., LAZOR, M. DEITCHER, R. P. Atomic Safety and Licensing Board Panel 8/10/13 12pp 07472 068

I. Inspection reports, IE Bulletins & correspondence

B101070320 Forwards supplemental responses to NRC B01016 ltr re violations noted in IE Insp Repts 50-413/80-09, 50-414/80-09, 50-414/80-02, 50-492/80-06 & 50-493/80-06 Final rept to be submitted by B10131.
PARKER, W. D. Duke Power Co 8/11/11 2pp.

B101070313 Responds further to NRC B01010 ltr re violations noted in IE Insp Repts 50-413/80-16 & 50-414/80-16, Corrective action: all cable tray installation drawings showing proper weld symbols received & released
PARKER, W. D. Duke Power Co 8/12/03 1p 07413 303.

--B101070316 Responds further to NRC B01010 ltr re violations noted in IE Insp Repts 50-413/80-16 & 50-414/80-16, Corrective action: all cable tray installation drawings will be reviewed, revised & released as required by B01201
PARKER, W. D. Duke Power Co 8/10/22 1p. 07413 304

B101060225 Forwards IE Info Notice B0-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 8/12/16 1p

B101160662 Act receipt of B01218 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-33 & 50-414/80-33
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 8/10/02 1p 07472:020

--B101160668 Responds to NRC B01210 ltr re violations noted in IE Insp

--B101160671 Forwards IE Insp Rept 50-413/80-33 & 50-414/80-33 on B01027-31 & notice of violation
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 8/12/02 2pp 07472 023

--B101160679 Notice of violation from Insp on B01027-31
* Region 2, Atlanta, Office of the Director 8/12/02 1p 07472 025

--B101160684 IE Insp Rept 50-413/80-33 & 50-414/80-33 on B01027-31 Noncompliance noted failure to follow procedure for exporting cracks in auxiliary tide concrete
MARRIS, J. R. Region 2, Atlanta, Office of the Director
CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 8/12/02 4pp 07472 026

B101290408 Responds to IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No active valves cast by Malcolm Foundry are in use at facilities
PARKER, W. D. Duke Power Co 8/10/05 1p 07573 358

S. Reportable occurrences, LERs & related correspondence

B101160605 Final deficiency rept 50-413/414/80-08 originally reported on B00617, re inadequate min flow through centrifugal charging pump. Ull will implement Westinghouse Interim Mod 2 transmitted on B00714
PARKER, W. D. Duke Power Co 8/10/07 2pp 07461 245

DOCKET 50-416 GRAND OULF NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 dealing re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. D. Division of Licensing. 8/11/26 0pp

B101060907 Informs that more appropriate data for control room visit will be used of B10309, rather than wk of B10109 info requested in B01204 ltr should be provided by B10206.
MARTORE, J. A. Licensing Branch 3 8/12/12 2pp. 07401:084

B101160520 Provides guidance re determination of acceptability of O-level for Facility Reviewers should identify safety-related structures, sys & components within areas of responsibility
HAASS, W. P. Quality Assurance Branch MARTORE, J. A. Licensing Branch 3 8/12/16 3pp 07445 201

B101070456 Requests postponement until B10309-13 re Human Factors Engineering Branch visit to control room at facility.
MIRAGLIA, F. J. Licensing Branch 3. 8/12/19 1p. 07415 310.

B101120257 Requests will perform ultimate capacity analysis of Mark I containment for NRC generic review re effects of hydrogen evolving from postulated accident Test description encl
TEDESCO, R. L. Assistant Director for Licensing 8/12/19 4pp. 07446 266

B101190535 Ltr to all BWR applicants for OL re BWR scram discharge sys safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge vol encl
TEDESCO, R. L. Assistant Director for Licensing 8/12/22 2pp

--B101190534 Forwards generic safety evaluation re BWR scram discharge sys Review identified two addl requirements to those proposed by owners group re scram discharge vol designs. Rept should be transmitted to license applicants
CHECK, P. S. Assistant Director for Plant Systems. 8/12/01 2pp 07183 001

B101090100 Submits results of reanalysis of cooling tower drift
DALE, L. F. Mississippi Power & Light Co. 8/12/23 2pp 07375:31

B101060435 Forwards Esser Corp human factors design engineering evaluation of control room per NUREG-0660, Task 1. D. 1. Review conducted from B00617-1001, using criteria from NUREG-1580, "Human Engineering Guide to Control Room Evaluation."
DALE, L. F. Mississippi Power & Light Co. 8/12/29 2pp. 07309:00

--B101060442 "Human Factors Engineering Evaluation of Grand Gulf Unit Control Room"

B101050329 Forwards amend to application for CL submitted as Amend 43 to FSAR & revised P&ID Aperture cards available in PDR only
MCGAUGHY, J P Mississippi Power & Light Co 80/12/31 1p
07383 297

--B101050335 Amend to application for OL submitted as Amend 43 to FSAR
MCGAUGHY, J P Mississippi Power & Light Co 80/12/31 2pp.
07303 298

B101070445 Reiterates B00926 request that requirements re sediment testing be deleted from environ protection plan Sediment testing adequately regulated by NPDES Permit MS0029521.
MCGAUGHY, J P Mississippi Power & Light Co 80/12/31 2pp
07403, 360

B101140222 Approves 001125 request to withhold rept entitled "Containment Bldg Response Spectra, OSE, 7% Dumping, North-South, East-West Vertical Mass Points, 7, 14, 15, 21 & 23; Containment Structure Mathematical Model;" (ref 10CFR2 7901 MIRA9LIA.F Licensing Branch 3 00/12/31 2pp 07309:001

B101130226 Forwards informal comparison between constituent sys of facility & generic design plant described in CESSAR-11. Designs fundamentally similar, though not identical. Designs differ in area of instrumentation.
DALE, L F. Mississippi Power & Light Co 01/01/09 3pp. 07449 357

B101150499 Advises that review of archaeological survey rept re R Braswell transmission line route shows no cultural sites eligible for listing on Natl Register of Historic Places will be affected.
KILLIARD, E R Mississippi, State of 81/01/12 1p. 07463 153.

B101220294 Forwards addl info re INEL structural audit action items per NRC request Remaining items will be submitted by Feb 1981
DALE, L F. Mississippi Power & Light Co 81/01/16 49pp
07495: 126

B101220337 Provides revised fuel load & commercial operation dates. Unit 1 fuel load & commercial operation dates are Dec 1981 & Aug 1982, respectively. Unit 2 fuel load & commercial operation dates are Aug 1985 & Apr 1986, respectively.
DALE, L F. Mississippi Power & Light Co 01/01/16 1p 07494 093.

B101230498 Forwards updated Unit 1 const network info for period ending B101231. Unit 2 const was halted on 7/12/81. Projected fuel load dates for Units 1 & 2 are Dec 1981 & Aug 1985, respectively.
DALE, L F. Mississippi Power & Light Co 01/01/16 8pp. 07511 195

B101290451 Forwards proprietary info re NRC/INEL audit action items, based on NRC 000317-21 structural audit of facilities info available in Central Files
ZACCARIA, A. Bechtel Power Corp (subs of Bechtel Corp.) 81/01/19 1p 07573 361.

B101270843 Responds to NRC B01219 request for Mark III containment analysis. Containment analysis does not consider dynamic pressure effects due to design criteria which prohibit conditions leading to hydrogen explosion.
MCGAUGHY, J P Mississippi Power & Light Co. 01/01/21 2pp
07545: 281

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants. CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 00/11/13 2pp

K Utility Final Safety Analysis Report (FSAR) & amends

B101050329 Forwards amend to application for OL submitted as Amend 43 to FSAR & revised P&ID Aperture cards available in PDR only
MCGAUGHY, J P Mississippi Power & Light Co. 80/12/31 1p
07383 297.

--B101050335 Amend to application for OL submitted as Amend 45 to FSAR
MCGAUGHY, J P. Mississippi Power & Light Co 00/12/31 2pp.
07383: 298.

--B101050341 Amend 45 to FSAR
* Mississippi Power & Light Co. 80/12/31. 250pp 07383. 300.

B101150639 Forwards affidavit of svc re Amend 45 to FSAR.
DALE, L F. Mississippi Power & Light Co 81/01/09. 2pp 07462 127

U. Inspection reports, IE Bulletins & correspondence

B101050283 Forwards IE Info Notice B0-43. "Failures of Contin Level Monitor for Steam Discharge Vpl at Dresden Unit 2 " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 1p 07391 022

B101060365 Requests addl info for licensing review Responses Bulletin 79-27 & B0-06 re instrument bus failures & engineered safety feature controls, respectively, are required.
TEDESCO, R L Assistant Director for Licensing 80/12/12 07422 233

B101120039 Suppls B00206 response to IE Bulletin 79-23 Three switches identified by Bechtel Eight subv switches exposed to temps above 175 F during LOCA Unit repairing all eight switches
DALE, L F Mississippi Power & Light Co 80/12/12 3pp

B101040162 Forwards IE Info Notice B0-45. "Potential Failure Backup Manual Steam Capability " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 1p 07391 278

B101070037 Forwards Suppl 4 to IE Bulletin B0-17. "Failure of Control Rods to Fully Insert During Scram at BWR " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 1p 07413 344

B101050156 Forwards IE Bulletin B0-25. "Operating Problems w/ Rod Safety Relief Valves at BWRs " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 2pp 07377. 254

B101120125 Responds to IE Bulletin B0-16 re potential misapp of Resomount Inc pressure transmitters Ten such transmitter used in safety-related applications. OE working w/util to correct problem prior to fuel loading.
DALE, L F Mississippi Power & Light Co 00/12/19. 3pp

B101120074 Ack receipt of B01215 ltr informing NRC of steps to correct violations noted in IE Insp Repts 90-416/00-25 & 90-417/00-15
MURPHY, C E Region 2, Atlanta, Reactor Construction & Eng Support Branch. 80/12/24 1p 07446 037.

--B101120077 Responds to NRC B0121 ltr re violations noted in Repts 90-416/00-25 & 90-417/00-15 Corrective actions: safety evaluation implemented to determine reportability of nonconformance
MCGAUGHY, J P Mississippi Power & Light Co 00/12/19 07446 030

--B101120081 Forwards IE Insp Repts 90-416/00-25 & 90-417/00-15 B101028-31, notice of violation & notice of deviation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Eng Support Branch 00/11/21 2pp 07446. 040

--B101120084 Notice of violation from Insp on B01028-31
* Region 2, Atlanta, Office of the Director 80/11/20 07446: 042

--B101120086 Notice of deviation from Insp on B01028-31
* Region 2, Atlanta, Office of the Director 80/11/20. 07446 043

--B101120090 IE Insp Repts 90-416/00-25 & 90-417/00-15 on B01028-31 Noncompliance noted subsl fire damper installation Power supply for electric fire pump not designed for locked not current.
MILLER, D H Region 2, Atlanta, Office of the Director
CONLON, T E Region 2, Atlanta, Reactor Construction & Eng Support Branch 00/11/20 8pp 07446 044

B101290367 Requests 60-day extension in responding to IE Bull B0-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc " Time needed to contact suppliers
DALE, L F. Mississippi Power & Light Co. 81/01/05 1p 0

B101220474 Submits addl info re IE Bulletin B0-07. "BWR Jet A Assembly Failure," in response to NRC request Describes actions to preclude recurrence of jet pump cracking & commitment for long-term solution
DALE, L F Mississippi Power & Light Co 81/01/14 3pp

ur inlet desper initially reported on 800730 Caused by
failure to see actuator cans properly Manufacturer untitled
Final rept will be issued by 810517
MCGAUGHY, J P Mississippi Power & Light Co 80/12/19 2pp
07588 001

B101050139 Status Rept 6 re Potential Reportable Deficiency 79/05
concerning discrepancies in design documentation for power
generation control complex panels Corrective actions by
supplier are not finalized Final rept scheduled by 810324
MCGAUGHY, J P Mississippi Power & Light Co 80/12/30 2pp
07339 291

B101050346 Status Rept 4 re Potential Reportable Deficiency 80/04
concerning loss of site power on rod position indication &
neutron monitoring Matter is under review Determination of
reportability & final rept due by 810421
MCGAUGHY, J P Mississippi Power & Light Co 80/12/30 2pp
07399 243

B101260019 Interim Deficiency Rept 2 re standby svc water basin fans.
Initially reported 800826 Fan pillow block bearings failed
after 330-h of operation Constructor & supplier conducting
evaluations Final rept will be filed by 810922
MCGAUGHY, J P Mississippi Power & Light Co 81/01/06 7pp
07529 248

B101270080 Part 21 rept re failure of pillow block bearings on standby
svc water cooling tower fans. Initially reported on 800826
Cause unknown Replacement of damaged bearings recommended
Final rept will be available on 810422
MCGAUGHY, J P Mississippi Power & Light Co 81/01/06 3pp
07183 001

B101490147 Final rept for Potentially Reportable Deficiency 80/53 re
oil level indicator lines outside missile barriers Missile
shielding of exposed oil lines has been coordinated
w/Genomic Cooling Tower Co for completion by 810421
MCGAUGHY, J P Mississippi Power & Light Co 81/01/07 2pp
07475 217

B101270341 Deficiency Status Rept 1 re loss of solid metallic grounding
of flexible conduit used in power generation control complex
equipment Ground to be attached at both ends of conduit
Final rept to be issued by 810319
MCGAUGHY, J P Mississippi Power & Light Co 81/01/09 2pp
07505 168

B101270104 Part 21 rept. Initially reported on 791205 re failure to
provide seismically & environ qualified instruments for use
in nuclear safety sys in ROP control complex Caused by GE
misinterpretation of Dechtel requirements
MCGAUGHY, J P Mississippi Power & Light Co 81/01/09 6pp
07183 001

B101230330 Interim deficiency rept. originally reported on 800905 re
seismic hangers w/incomplete welds at member connection
goints Insp to be completed by 810227 Final rept expected
by 810528
MCGAUGHY, J P Mississippi Power & Light Co 81/01/15 2pp
07510 024

B101230599 Interim Deficiency Rept 1. originally reported on 800319 re
pipe hanger nonconformances Nonconformances attributed to
failure of const to follow installation instructions &
proper insp procedures Insp program initiated
MCGAUGHY, J P Mississippi Power & Light Co 81/01/15 4pp
07510 020

B101230607 Interim deficiency rept. originally reported on 801216 re
unapproved mods to control room fire dangers Caused by A/E
error Vendor investigation re possible effects on UL
classification & air flow testing in progress.
MCGAUGHY, J P Mississippi Power & Light Co 81/01/15 2pp
07510 031

B101230482 Final deficiency rept. originally reported on 800314 re
limbtorque valve operator malfunctions Testing results
determined that problem was isolated incident on non-safety
related equipment & not reportable per 10CFR50.55(c).
MCGAUGHY, J P Mississippi Power & Light Co 81/01/16 2pp
07510 015

B101300388 Interim deficiency rept. first reported on 800922 re
incorrectly ordered throttling valves for RHRA sys Four
valves suitable w/mods by manufacturer Constructor
evaluation to be reviewed to determine corrective action
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 3pp
07580 358

MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 5pp
07586 088

B101300455 Interim deficiency rept. originally reported on 800912 re
nonconforming Reactor Controls, Inc seismic piping supports
Constructor QA manual approval pending & all future work will
conform to revised QA program
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 4pp.
07586 097

B101300475 Second interim deficiency rept. originally reported on
800806 re inadequate control of supplier drawing revision
notices program Nonconforming conditions under scrutiny &
procedural controls being revised
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 2pp
07586 101

SECRET 50-417 GRAND OULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Low-Stellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp.

B101020937 Informs that more appropriate date for control room visit
will be wk of 810309 rather than wk of 010105 Info
requested in 801204 ltr should be provided by 810206
MARTORE, J A Licensing Branch 3 80/12/12 2pp 07401 084

B101100020 Provides guidance re determination of acceptability of
Q-list for facilities Reviewers should identify safety-
related structures, sys & components within areas of
responsibility
MANSSE, W P Quality Assurance Branch MARTORE, J A Licensing Branch
3 80/12/18 3pp 07445 201

B101070456 Requests postponement until 810309-13 re Human Factors
Engineering Branch visit to control room at facility
MIRACLIA, F J Licensing Branch 3 80/12/19 1p 07415 310

B101120257 Requests util perform ultimate capacity analysis of Mark
containment for NRC generic review re effects of hydrogen
evolving from postulated accident Test description encl
TEDESICO, R L Assistant Director for Licensing 00/12/19 4pp
07446 266

B101050100 Submits results of reanalysis of cooling tower drift
DALE, L F Mississippi Power & Light Co 80/12/23 2pp 07375 1

B101050329 Forwards amend to application for DL submitted as Amend
to FSAR & revised P&ID
MCGAUGHY, J P Mississippi Power & Light Co 80/12/31 1p

--B101050335 Amend to application for DL submitted as Amend 45 to FSAR
MCGAUGHY, J P Mississippi Power & Light Co 80/12/31 2pp

B101070445 Reiterates 800926 request that requirements re sediment
basins be deleted from environ protection plan Sediment
basins adequately regulated by NPOES Permit MS0029921.
MCGAUGHY, J P Mississippi Power & Light Co 80/12/31 2pp.
07403 360

B101140222 Approves 801125 request to withhold rept entitled
"Containment Bldg Response Spectra, SSE, 7% Damping, North-
South-East-West Vertical Mass Points 7, 14, 15, 21 & 23-
Containment Structure Mathematical Model." ltr 10CFR2 7901.
MIRACLIA, F J Licensing Branch 3 80/12/31 2pp 07309 001.

B101130226 Forwards informal comparison between constituent sys of
facility & generic design plant described in CESSAR-11
Designs fundamentally similar though not identical Designs
differ in area of instrumentation
DALE, L F Mississippi Power & Light Co 81/01/09 3pp. 07449:

B101150499 Advises that review of archaeological survey rept re
R Braswell transmission line route shows no cultural sites
eligible for listing on Natl Register of Historic Places
will be affected
HILLIARD, E R Mississippi, State of 81/01/12 1p. 07463 153

DOCKETED ITEMS

810120294 Forwards addl info re INEL structural audit action items per NRC request. Remaining items will be submitted in Feb 1981.
DALE, L. F. Mississippi Power & Light Co 01/01/16. 49pp
07493 126

8101220337 Provides revised fuel load & commercial operation dates Unit 1 fuel load & commercial operation dates are Dec 1981 & Aug 1982, respectively. Unit 2 fuel load & commercial operation dates are Aug 1985 & Apr 1986, respectively.
DALE, L. F. Mississippi Power & Light Co 01/01/16 1p 07454 093

8101230498 Forwards updated Unit 1 const network info for period ending 801231. Unit 2 const was halted on 791221. Projected fuel load dates for Units 1 & 2 are Dec 1981 & Aug 1985, respectively.
DALE, L. F. Mississippi Power & Light Co 01/01/16. 8pp 07511 159

8101295451 Forwards proprietary info re LRC/INEL audit action items, based on NRC BC0317-21 structural audit of facilities info available in Central Files.
ZACCAIRIA, A. Bechtel Power Corp (subs of Bechtel Corp) 01/01/19 1p 07573 361

8101270843 Responds to NRC 801219 request for Mar 111 containment analysis. Containment analysis does not consider dynamic pressure effects due to design criteria which prohibit conditions leading to hydrogen explosion.
MCGAUGHY, J. P. Mississippi Power & Light Co 01/01/21 2pp
07543 281

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D. Q. Division of Licensing 00/11/13 2pp

A Utility Final Safety Analysis Report (FSAR) & amends

8101050329 Forwards amend to application for OL submitted as Amend 45 to FSAR & revised PAID Aperture cards available in PBR only.
MCGAUGHY, J. P. Mississippi Power & Light Co 00/12/31 1p
07387 297

--8101050335 Amend to application for CL submitted as Amend 45 to FSAR.
MCGAUGHY, J. P. Mississippi Power & Light Co 00/12/31 2pp
07383 298

--8101050341 Amend 45 to FSAR
* Mississippi Power & Light Co 00/12/31 250pp 07383 303

8101150639 Forwards affidavit of svc re Amend 45 to FSAR.
DALE, L. F. Mississippi Power & Light Co 01/01/09 2pp 07462 127

Q Inspection reports, IE Bulletins & correspondence

8101050503 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2." No response required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 00/12/09 1p 07391 022

8101080066 Requests addl info for licensing review. Responses to IE Bulletin 79-27 & 80-06 re instrument bus failures & engineered safety feature controls, respectively, are required.
TEDECO, R. L. Assistant Director for Licensing 00/12/12 7pp
07422 233

8101120009 Suppls B00206 response to IE Bulletin 79-20 Thirteen NAMCO switches identified by Bechtel. Eight subg switches exposed to temps above 175 F during LOCA Util repairing all eight switches.
DALE, L. F. Mississippi Power & Light Co 00/12/12 3pp. 07447 095

8101060162 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/12/17 1p. 07391 278

8101090156 Forwards IE Bulletin 80-25, "Operating Problems w/Targe Rock Safety Relief Valves at NPPs." No response required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 00/12/24 2pp 07377 254

810120125 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount, Inc. pressure transmitters. For such transmitters used in safety related applications OE working w/Util to correct problem prior to fuel loading.
DALE, L. F. Mississippi Power & Light Co 00/12/19 3pp 07446 037

810120374 Ack receipt of 801215 ltr informing NRC of steps taken correct violations noted in IE Insp Repts 90-416/80-25 & 90-417/80-15.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/12/24 1p 07446 037

--810120077 Responds to NRC 80121 ltr re violations noted in IE Repts 90-416/80-25 & 90-417/80-15. Corrective actions safety evaluation implemented to determine reparability of nonconformance.
MCGAUGHY, J. P. Mississippi Power & Light Co 00/12/15 2pp
07446 038

--810120081 Forwards IE Insp Repts 90-416/80-25 & 90-417/80-15 on 810102B-31, notice of violation & notice of deviation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/11/21 2pp 07446 040

--810120094 Notice of violation from insp on 80102B-31
* Region 2, Atlanta, Office of the Director 00/11/20 1p
07446 042

--810120086 Notice of deviation from insp on 80102B-31
* Region 2, Atlanta, Office of the Director 00/11/20 1p
07446 043

--810120090 IE Insp Repts 90-416/80-25 & 90-417/80-15 on 80102B-31. Noncompliance noted subd Fire damper installation. Power supply for electric fire pump not designed for locked rotor current.
MILLER, W. H. Region 2, Atlanta, Office of the Director
CHILCH, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/11/20 8pp 07446 044

8101290367 Requests 60-day extension in responding to IE Bulletin 80-21, "Valve Vexes Supplied by Malcolm Foundry Co. Inc." Time needed to contact suppliers.
DALE, L. F. Mississippi Power & Light Co 01/01/05 1p 07575

8101220474 Submits addl info re IE Bulletin 80-07, "BWR Jet Pump Assembly Failure." In response to NRC request. Describes actions to preclude occurrence of jet pump cracking & commitment for long-term solution.
DALE, L. F. Mississippi Power & Light Co 01/01/14 3pp 07501

S. Reportable occurrences, LERs & related correspondence

8101260763 Part 21 repl re defective Pacific Air Products Co actuator in let damper. Initially reported on 800730. Caused by failure to set actuator cams properly. Manufacturer notified. Final repl will be issued by 810617.
MCGAUGHY, J. P. Mississippi Power & Light Co 00/12/19 2pp
07388 001

8101050739 Status Rpt 0 re Potential Reportable Deficiency 79/05 concerning discrepancies in design documentation for power generation control compo panels. Corrective actions by supplier are not finalized. Final repl scheduled by 810724.
MCGAUGHY, J. P. Mississippi Power & Light Co 00/12/30 2pp
07387 291

8101050346 Status Rpt 4 re Potential Reportable Deficiency 80/04 concerning loss of site power on rod position indication & neutron monitoring Matter is under review. Determination of reparability & final repl due by 810421.
MCGAUGHY, J. P. Mississippi Power & Light Co 00/12/30 2pp
07389 293

8101260519 Interim Deficiency Rpt 2 re standby svc water basin. Initially reported 800826. Fan pillow block bearings failed after 300-h of operation. Constructor & supplier conducting evaluations. Final repl will be filed by 810422.

DOCKETED ITEMS

810121070 Part 21 rept re failure of pillow block bearings on standby
w/c water cooling tower fans. Initially reported on 800826
Cause unknown. Replacement of damaged bearings recommended
Final rept will be available on 810422
MCGAUGHY, J P Mississippi Power & Light Co 81/01/06 3pp
07183 001

8101210447 Final rept for Potentially Reportable Deficiency 80/53 re
211 level indicator lines outside missile barriers. Missile
scrambling of exposed oil lines has been coordinated
w/General Locking Tower Co for completion by 810421
MCGAUGHY, J P Mississippi Power & Light Co 81/01/07 2pp
07475 217

8101220341 Deficiency Status Rept re loss of solid metallic grounding
of flexible conduit used in power generation control complex
equipment. Grounds to be attached at both ends of conduit
Final rept to be issued by 810319
MCGAUGHY, J P Mississippi Power & Light Co 81/01/09 2pp
07505 128

8101270104 Part 21 rept. Initially reported on 791205, re failure to
provide seismically & environ. qualified instruments for use
in nuclear safety sys in BCP control complex. Caused by GE
misinterpretation of Bechtel requirements
MCGAUGHY, J P Mississippi Power & Light Co 81/01/09 6pp
07182 001

8101210500 Interim deficiency rept. originally reported on 800905, re
seismic damage w/incomplete welds at member connection
points. Insp to be completed by 810227. Final rept expected
by 810528
MCGAUGHY, J P Mississippi Power & Light Co 81/01/15 2pp
07510 024

8101230559 Interim Deficiency Rept 1, originally reported on 800319, re
pipe hanger nonconformances. Nonconformances attributed to
failure of coast to follow installation instructions &
proper insp procedures. Insp program initiated
MCGAUGHY, J P Mississippi Power & Light Co 81/01/15 4pp
07510 028

8101230607 Interim deficiency rept. originally reported on 801216, re
unapproved mods to control room fire dampers. Caused by A/E
error. Vendor investigation re possible effects on UL
classification & air flow testing in progress
MCGAUGHY, J P Mississippi Power & Light Co 81/01/15 2pp
07510 031

8101230482 Final deficiency rept. originally reported on 800314, re
Limitation valve operator malfunctions. Testing results
determined that problem was isolated incident on non-safety
related equipment & not reportable per 10CFR50.55(a)
MCGAUGHY, J P Mississippi Power & Light Co 81/01/16 2pp
07510 015

8101300288 Interim deficiency rept. first reported on 800912, re
incorrectly ordered throttling valves for RHR sys. Four
valves suitable w/mods by manufacturer. Constructor
evaluation to be reviewed to determine corrective action
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 3pp
07580 358

8101300424 Interim deficiency rept. originally reported on 810116, re
RHR B pump damage during const. testing. Damaged parts being
returned to manufacturer for repairs & Unit 2 parts
installed in Unit 1. Final rept scheduled for 810827
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 5pp
07586 089

8101300455 Interim deficiency rept. originally reported on 800912, re
nonconforming Reactor Controls, Inc. seismic piping supports.
Constructor QA manual approval pending & all future work will
conform to revised QA program
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 4pp
07586 097

8101300475 Second interim deficiency rept. originally reported
on 800804, re inadequate control of supplier drawing revision
notice program. Nonconforming conditions under scrutiny &
procedural controls being revised
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 2pp
07586 101

DOCKET 50-423 HILLSTONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8101220465 Ltr to all power reactor licensees & applicants for
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101000734 Requests that encl facility emergency planning info be
publicly available w/o encl
SOUDEK, J L Division of Rules and Records 80/12/31 1p
07445 128

J Insurance & indemnity information

8101270736 Forwards Endorsement 4 to NELIA Binders EB-15 & EB-16
IFFLAND, R R Northeast Utilities 81/01/22 3pp 07548 055

8101270744 Forwards Endorsements 65 & 66 to NELIA Policy NF-173.
IFFLAND, R R Northeast Utilities 81/01/22 4pp 07548 046

P Operating license stage documents & correspondence

8101150029 Notification of 801218 meeting w/SEP owners group in
Bethesda, MD re SEP program, schedule for licensee topic
completion & assignment of lead topics to plants
RUSSELL, W T Technical Support Branch 80/12/16 2pp

Q Inspection reports, IE Bulletins & correspondence

8101070425 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Stop
Terry Turbine Steam Inlet Flange." No written response
required
GRIER, S H Region 1, Philadelphia, Office of the Director
80/11/26 1p 07414 035

8101060836 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No written
response required
GRIER, S H Region 1, Philadelphia, Office of the Director
80/12/16 1p 07397 025

S Reportable occurrences, LERs & related correspondence

8101000033 Ack receipt of 801009 ltr forwarding interim deficiency
re reduced cooling to main steam generator.
CARLSON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/11/20 1p 07444 301

--8101000038 Interim deficiency rept re reduced cooling to main
generator. Initially reported on 800924. Problem is being
reviewed w/SEW Engineering Corp. Review results will be
provided
COUNSEL, W O Northeast Nuclear Energy Co (subs. of Northeast
Utilities), 80/10/09 1p 07444 302

DOCKET 50-424 ALVIN W VOISLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants for
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101050253 Summary of 801201 meeting w/utl in Bethesda, MD re d
of containment encl bldg.
RUSSELL, S B Licensing Branch 2 80/12/22 7pp 07384 250

B01160104 Forwards fee for amend of CPPR-10B & CPPR-109 inadvertently omitted from B01219 application
MOORE, W M Georgia Power Co 81/01/14 1p 07466 261

B011300398 Forwards 'Savannah River Fish Population Study & Impingement Prediction For Plant Vogtle, Burke County, GA.' Sept 1977-Dec 1978 Const scheduled for B10301 Expeditious review requested
HEAD, G F Georgia Power Co 81/01/28 1p 07595 024

--B011300429 'Savannah River Fish Population Study & Impingement Prediction For Plant Vogtle, Burke County, GA.' Sept 1977-Dec 1978
WILTZ, J W Georgia Power Co 81/01/31 34pp 07595 025

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensee within 60 days of B0102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

G Adjudicatory correspondence

B01140752 Forwards request for info to assess intervenor Georgiana Against Nuclear Energy 800925 petition for proceeding to assess need for power at facilities Latest official capital cost estimate & expenditures to date required
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp 07461 310

I Financial information

B01140752 Forwards request for info to assess intervenor Georgiana Against Nuclear Energy 800925 petition for proceeding to assess need for power at facilities Latest official capital cost estimate & expenditures to date required
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp 07461 310

B01260396 Forwards assessment of need for power from facilities per B01219 request for info Discusses scheduled on-line operating dates, capital cost estimates, expenditures to date, integrated hour peak demand & sys expansion plan
EISENSPERGER, W Georgia Power Co 81/01/22 34pp 07531 182

Q Inspection reports, IE Bulletins & correspondence

B01060247 Forwards IE Info Notice 80-44, "Activation of ECCB in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07391 353

B01190336 Responds to IE Bulletin 80-21 re Malcolm Foundry Co valve yokes Util has no Malcolm Foundry Co valve parts in safety-related sys.
DUTTON, D Georgia Power Co 80/12/30 2pp 07475 219

B01190342 Responds to IE Bulletin 80-23 re Valcor solenoid valve failure Util has no Valcor solenoid valves V70900-21-1 or V70900-21-3 for safety-related functions
DUTTON, D Georgia Power Co 80/12/30 2pp 07475 221

DCCAE1 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

B01220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B01140752 Forwards request for info to assess intervenor Georgiana Against Nuclear Energy 800925 petition for proceeding to assess need for power at facilities Latest official capital cost estimate & expenditures to date required
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp 07461 310

B01090293 Summary of 80201 meeting w/util in Bethesda, MD re deletion of containment encl bldg.
BURWELL, S B Licensing Branch 2 80/12/22 7pp 07384 250

B01260396 Forwards assessment of need for power from facilities per B01219 request for info Discusses scheduled on-line operating dates, capital cost estimates, expenditures to date, integrated hour peak demand & sys expansion plan
EISENSPERGER, W Georgia Power Co 81/01/22 34pp 07531 182

B01160104 Forwards fee for amend of CPPR-10B & CPPR-109 inadvertently omitted from B01219 application
MOORE, W M Georgia Power Co 81/01/14 1p 07466 261

B011300398 Forwards 'Savannah River Fish Population Study & Impingement Prediction For Plant Vogtle, Burke County, GA.' Sept 1977-Dec 1978 Const scheduled for B10301 Expeditious review requested
HEAD, G F Georgia Power Co 81/01/28 1p 07595 024

--B011300429 'Savannah River Fish Population Study & Impingement Prediction For Plant Vogtle, Burke County, GA.' Sept 1977-Dec 1978
WILTZ, J W Georgia Power Co 81/01/31 34pp 07595 025

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensee within 60 days of B0102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

I Financial information

B01140752 Forwards request for info to assess intervenor Georgiana Against Nuclear Energy 800925 petition for proceeding to assess need for power at facilities Latest official capital cost estimate & expenditures to date required
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp

B01260396 Forwards assessment of need for power from facilities per B01219 request for info Discusses scheduled on-line operating dates, capital cost estimates, expenditures to date, integrated hour peak demand & sys expansion plan
EISENSPERGER, W Georgia Power Co 81/01/22 34pp

Q Inspection reports, IE Bulletins & correspondence

B01060247 Forwards IE Info Notice 80-44, "Activation of ECCB in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07391 353

B01190336 Responds to IE Bulletin 80-21 re Malcolm Foundry Co valve yokes Util has no Malcolm Foundry Co valve parts in safety-related sys.
DUTTON, D Georgia Power Co 80/12/30 2pp 07475 219

B01190342 Responds to IE Bulletin 80-23 re Valcor solenoid valve failure Util has no Valcor solenoid valves V70900-21-1 or V70900-21-3 for safety-related functions
DUTTON, D Georgia Power Co 80/12/30 2pp 07475 221

DCCAE1 50-425 ALVIN W VOOTLE NUCLEAR PLANT, OFFSHORE POWER SYSTEM

A Application/construction stage documents & correspondence

B01220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B01270555 FOIA request for all documents re OPG application for license to mfg floating nuclear plants containing etatements re alternate land uses
BRYAN, L L Jacksonville, FL 80/12/16 2pp 07541 129

B01090891 Requests detailed analyses that assess effect of pol Hydrogen burn on floating nuclear plant containment integrity Info should include design pressure, calculated static pressure containing capacity & general results
TEDESCO, R L Assistant Director for Licensing 80/12/17 5pp 07430 156

B101270551 Responds to FOIA request for all documents re CPS application for license to mfg floating nuclear plants containing statements re alternate land uses. NRC can locate no documents subj to Request
ELLISON, M. Division of Rules and Records 81/01/13 1p
07541 123

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

B101050260 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
D'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07362 004

I Hearing transcripts on non-antitrust matters

B101260355 Unofficial transcript of 781201 Affirmation Session 78-30 in Washington, DC re UPS order Ps 1-3
Commissioners 78/12/01 App 07308 001

DOCKET 50-438 BULLDOCK RE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

B101220460 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

B101210442 Advises that ATWS Issue will be subj of future rulemaking to determine requirements & schedules for plant mods NRC will not comment on until B00917 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT, D G Division of Licensing 80/12/29 2pp

B101260772 Forwards repts re post-tensioned anchor tendons in rock installation & testing of tendons by Inland-Ryerson Const Co & Strossteel Corp. "Analysis of tendon Jacking Tests for Behavior of Rock Foundation"
MILLS, L M Tennessee Valley Authority 81/01/15 1p 07183 001

--B101220173 Post-tensioned Anchor Tendons in Rock Installation & Testing of Tendons by Inland-Ryerson Const Products Co -
BULLDOCK, R E Tennessee Valley Authority 73/12/19 8pp
07183 001

- B101220773 "Post-tensioned Anchor Tendons in Rock Installation & Testing of Tendons by Inland-Ryerson Const Products Co"
BULLDOCK, R E Affiliation Unknown 73/12/19 8pp

--B101220375 Post-tensioned Anchor Tendons in Rock Installation & Testing of Tendons by Strossteel Corp -
BULLDOCK, R E Tennessee Valley Authority 73/12/11 8pp
07183 001

--B101220775 Post-tensioned Anchor Tendons in Rock Installation & Testing of Tendons by Strossteel Corp -
BULLDOCK, R E Affiliation Unknown 73/12/11 8pp

--B101220377 Analysis of tendon Jacking Tests for Behavior of Rock Foundation
CCU SOK, J H Tennessee Valley Authority 73/11/06 29pp
07183 001

B101230384 Forwards application for reissuance of NPDES Permit AL0074675 Preliminary draft permit will be submitted by B101220 Overstate maps encl
EL-ASHRY, M I Tennessee Valley Authority 81/01/20 82pp
07187 001

F Security, medical, emergency & fire protection plans

B101050387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response

B10110607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington, DC Ps 1-45
Commissioners 80/12/17 49pp

B101230580 Forwards request for addl info re B01001 guard training qualification plan
TEDESCO, R L Assistant Director for Licensing 81/01/06 3pp
07487 313

B101130013 Forwards request for addl info re guard training & qualification plan. Requests resubmittal of revised plan within 30 days
TEDESCO, R L Assistant Director for Licensing 81/01/08 3pp
07448 260

J Insurance & indemnity information

B101090469 Forwards Endorsement 10 to ANI Policy NF-288
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 80/12/20 3pp 07442 038

B101090517 Forwards Endorsement 7 to ANI Policy NF-288
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 80/12/28 2pp 07442 263

K Utility Final Safety Analysis Report (FSAR) & amends

B101220043 Forwards Amend 20 to FSAR
MILLS, L M Tennessee Valley Authority 81/01/16 2pp

--B101220044 Amend 20 to FSAR
Tennessee Valley Authority 81/01/12 1000pp

B101270654 Forwards affidavit certifying that Amend 20 to FSAR was served upon individuals identified on B10123
MILLS, L M Tennessee Valley Authority 81/01/23 2pp 07430

O Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC B0071 Insp of Unit Biv of Engineering Design QA organization restructured to provide sufficient organizational Freedom, authority & access to mgt
MURPHY, C E Tennessee Valley Authority 80/10/08 3pp

B101090112 Ack receipt of B01024 ltr informing NRC of steps taken correct violations noted in IE Insp Repts 50-438/80-14 & 50-439/80-14 Disagrees w/response refuting items of noncompliance
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/05 4pp 07426 325

--B101090121 Responds to NRC B00912 ltr re violations noted in IE Repts 50-438/80-14 & 50-439/80-14 Disagrees that visual examination program & magnetic particle examination procedure do not meet ASME requirements
MILLS, L M Tennessee Valley Authority 80/10/24 3pp
07426 329

--B101090721 Forwards IE Insp Repts 50-438/80-14 & 50-439/80-14 on B00721-25 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/09/12 2pp 07426 336

--B101090727 Notice of violation from Insp on B00721-25
Region 3, Chicago, Office of the Director 80/09/08 2pp
07426 338

--B101090775 IE Insp Repts 50-438/80-14 & 50-439/80-14 on B00721-25 Noncompliance noted inadequate visual insp program & magnetic particle examination procedures.
BLAKE, J, KLEINSORGE, W, ZAJAC, L Region 2, Atlanta, Office of the Director 80/09/08 15pp 07426 340

B101120240 Forwards response to IE Bulletin 80-20 re Westinghouse M-2 control switches w/spring return to neutral position. Switches used in all facilities except Yellow Creek Units 3 & 4 in which switches are employed
MILLS, L M Tennessee Valley Authority 80/12/12 2pp

B101060203 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required
D'REILLY, J P Region 2, Atlanta, Office of the Director 80/11/13 07391:312

receipt of B01212 ltr informing NRC of steps taken to
actions noted in IE Insp Repts 50-438/B0-19 &

Region 2, Atlanta, Reactor Construction & Engineering
B0/12/22 1p 07443 293

responds to NRC B01014 ltr re violations noted in IE Insp
B0/00-19 & 50-439/B0-19 Corrective actions
supports reinspected & drawing changed to reflect
configuration

Tennessee Valley Authority B0/12/12 2pp

responds to IE Bulletin B0-23 re Valcor Engineering Corp
failure Valcor solenoid valves V70900-21-1 &
not used Util Laiting for vendor response on
package components

Tennessee Valley Authority B0/12/30 1p

responds to IE Bulletin B0-21, "Valve Yokes Supplied by
Jry Co. Inc." Util is in process of obtaining
from valve suppliers that no Malcolm Foundry
obtained in furnished valves

Tennessee Valley Authority B1/01/06 1p

Drating reports & related correspondence

wards "Environ Radioactivity Levels - Bellefonte Nuclear
il Rept - 1979" Rept presents results obtained
ditional environ radiological monitoring program
Tennessee Valley Authority B1/01/22 3pp 07976:146

Environ Radioactivity Levels - Bellefonte Nuclear Plant -
- 1979

Tennessee Valley Authority BA-B0-9-BL1 B1/01/22 3pp

occurrences, LERs & related correspondence

rd interim deficiency rept. originally reported B00907, re
illet welds Reinsp of socket welds continuing
documentation sys being developed to identify
dc Next rept will be submitted by B10309

Tennessee Valley Authority 00/12/15 1p 07566 349

ond interim deficiency rept. originally reported on
ised buttonheads on rock anchor tendons Insp
in Group 1 tendon overstressed & buttonheads
verified Next rept to be submitted by B10420.

Tennessee Valley Authority B0/12/29 3pp 07383 282

rd interim deficiency rept. originally reported B00319 re
sin steam line breaks because of feedwater
ivation of dynamic loading effects on main steam
ing Next rept will be submitted by B10625.

Tennessee Valley Authority B0/12/29 1p 07566 352

st interim deficiency rept re Consolidated Control Corp
cards, initially reported on B01203 Util is
y method of verifying adequacy of all field
Next rept will be forwarded by B10521

Tennessee Valley Authority B1/01/02 2pp 07415 300

st interim deficiency rept re automatic switchover of
storage tank, initially reported on B01203 Util
control documents providing for automatic
Next rept will be forwarded by B10210

Tennessee Valley Authority B1/01/02 2pp 07413 302

rim Deficiency Rept 1 re essential raw cooling water sys
Design of essential raw cooling water piping is
ad to incorporate ability to deal w/wide

fouling factors Originally reported on B01207

Tennessee Valley Authority B1/01/07 2pp 07461 130.

st interim rept. originally reported on B01208, re low
chgear installation seismic mounting
y not welded per design drawings OA auditing
ars investigation to be completed by B10423.

Tennessee Valley Authority B1/01/06 2pp 07461 238

rd interim deficiency rept. originally reported on B00709,
svc factors on Westinghouse motor nameplates
to be changed to reflect vendor-documented svc

Tennessee Valley Authority B1/01/09 2pp 07475 238

B101210327 Final deficiency rept. originally reported B01212, re threaded
piper qualification w/1.1/2 pipets identified, analyzed &
accepted per design procedures. Remainder will be analyzed
for stress intensity factors by B10396

MILLS, L. M. Tennessee Valley Authority B1/01/13 2pp 07490 131

B101220311 Forwards first interim rept re potential flammability of
suspended ceiling tile in control rooms in response to
B01104 ltr Addl info to be provided by B10211

MILLS, L. M. Tennessee Valley Authority B1/01/14 3pp

B101230498 Fourth interim deficiency rept re failed motor operated
valves mfg by Acta Actuators, Inc & defective limit switches,
initially reported on B00611 Actuators were returned to
factory for repairs Next rept by B10325

MILLS, L. M. Tennessee Valley Authority B1/01/14 2pp 07511 147

B101260446 Fifth interim deficiency rept. originally reported on
771:25, re purchase requests issued w/o specified IEEE
qualifications All deficient requests revised to include
proper qualifications Next rept will be submitted by B10422

MILLS, L. M. Tennessee Valley Authority B1/01/15 2pp 07931 223

B101270419 Second interim deficiency rept re fillet weld
suspectification, initially reported on B01107, Design review
repeats discrepancies in early TVA Facility Util will
evaluate variances Next rept will be submitted by B10409

MILLS, L. M. Tennessee Valley Authority B1/01/19 2pp 07549 042

B101270622 Second interim deficiency rept re 11T Grinnel welded
supports, initially reported B00905 Detail sheets w/
discrepancies in weld designations will be revised by 11T
Grinnel for use in insp of fabricated welds

MILLS, L. M. Tennessee Valley Authority B1/01/22 2pp 07540 339

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-15, "Potential for Low Fracture
Toughness & Lateral Tearing on Component Supports"
EISENBERG, D. O. Division of Licensing B0/11/26 8pp

B101270642 Advises that AT&B issue will be cuty of future rulemaking to
determine requirements & schedule for plant mods. NRC will
not comment on util B00917 ltr describing program for
resolving issue until rulemaking is finalized
EISENBERG, D. O. Division of Licensing B0/12/29 2pp

B101220472 Forwards repts re post-tensioned anchor tendons in rock,
Installation & testing of tendons by Inland-Ryerson Const
Co & Streasteel Corp & "Analysis of Tendon Jacking
Tests for Behavior of Rock Foundation"

MILLS, L. M. Tennessee Valley Authority B1/01/19 1p 07183 001

--B101220373 Post-tensioned Anchor Tendons in Rock, Installation &
Testing of Tendons by Inland-Ryerson Const Products Co."
MULLICK, R. E. Tennessee Valley Authority 73/12/19 8pp
07183 031

--B101220375 Post-tensioned Anchor Tendons in Rock, Installation &
Testing of Tendons by Streasteel Corp."
MULLICK, R. E. Tennessee Valley Authority 73/12/11 8pp
07183 001

--B101220377 Analysis of Tendon Jacking Tests for Behavior of Rock
Foundation"
MULLICK, R. E. Tennessee Valley Authority 73/11/06 29pp
07183 001

B101230384 Forwards application for reissuance of NPDES Permit
ALC021635 Preliminary Draft permit will be submitted by
B10220 Oversight repts encl
EL-AISHRY, M. T. Tennessee Valley Authority B1/01/20 62pp
07187 001

F Security, medical, emergency & fire protection plans

B101270387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of PSAR
EISENBERG, D. O. Division of Licensing B0/11/13 2pp

B101210607 Transcript of B01217 briefing on TVA emergency offsite
facilities in Washington, DC Pp 1-49
e Commissioners, B0/12/17 49pp.

810107589 Forwards request for addl info re guard training & qualification plan
ELESICO, R L Assistant Director for Licensing 81/01/06 3pp
07487 113

8101130013 Forwards request for addl info re guard training & qualification plan Requests resubmittal of revised plan within 30 days
ELESICO, R L Assistant Director for Licensing 81/01/08 3pp
07440 288

J Insurance & indemnity information

8101070465 Forwards Endorsement 10 to ANI Policy NF-258
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/26 3pp 07442 039

8101070517 Forwards Endorsement 9 to ANI Policy NF-258
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/26 2pp 07442 203

K Utility Final Safety Analysis Report (FSAR) & amends

8101270413 Forwards Amend 20 to FSAR
MILLS, L M Tennessee Valley Authority 81/01/16 2pp

--8101270411 Amend 20 to FSAR
* Tennessee Valley Authority 81/01/12 1060pp

8101270659 Forwards affidavit certifying that Amend 20 to FSAR was served upon individuals identified on 810123
MILLS, L M Tennessee Valley Authority 81/01/23 2pp 07550 140.

3 Inspection reports, IE Bulletins & correspondence

8101140619 Updates licensee corrective actions following NRC 800707-11 Insp of Util Div of Engineering Design OA organization restructured to provide sufficient organizational freedom, authority & access to regt
KIMMORNS, G M Tennessee Valley Authority 80/10/08 3pp

8101090112 Ack receipt of 801024 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-14 & 50-439/80-14 Disagrees w/response refuting items of noncompliance
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/05 4pp 07426 325

--8101090121 Responds to NRC 800912 ltr re violations noted in IE Insp Repts 50-438/80-14 & 50-439/80-14 Disagrees that visual examination program & magnetic particle examination procedure do not meet ASME requirements
MILLS, L M Tennessee Valley Authority 80/10/24 5pp.
07426 329

--8101090721 Forwards IE Insp Repts 50-438/80-14 & 50-439/80-14 on 800721-25 & notice of violation.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/17 2pp. 07426 336.

--8101090727 Notice of violation from Insp on 800721-25
* Region 3, Chicago, Office of the Director 80/09/08 2pp.
07426 338

--8101090735 IE Insp Repts 50-438/80-14 & 50-439/80-14 on 800721-25 Noncompliance noted inadequate visual insp program & magnetic particle examination procedures.
BLAKE, J. W. KLINSORGE, W. ZAJAC, L. Region 2, Atlanta, Office of the Director 80/09/08 19pp. 07426 340

8101120240 Forwards response to IE Bulletin 80-20 re Westinghouse Type W-2 control switches w/spring return to neutral position. Switches used in all facilities except Yellow Creek Units sys in which switches are employed
MILLS, L M Tennessee Valley Authority 80/12/12 2pp.

8101060203 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/16. 1p 07391 312

8101100279 Ack receipt of 801212 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-19 & 50-437/80-19.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/22 1p 07443 295

--8101060287 Responds to NRC 801014 ltr re violations noted in IE 1 Repts 50-438/80-19 & 50-439/80-19 Corrective actions generator supports reinspected & drawing changed to reflect as-built configuration
MILLS, L M Tennessee Valley Authority 80/12/12 2pp
07443 276

8101270650 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Valcor solenoid valves V70900-21-1 & V70900-21-3 not used Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/30. 1p.

8101210237 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Melcoln Foundry Co. Inc." Util is in process of obtaining assurance from valve suppliers that no Melcoln Foundry yokes are contained in furnished valves
MILLS, L M Tennessee Valley Authority 81/01/06. 1p

R Periodic operating reports & related correspondence

8101290262 Forwards "Environ Radioactivity Levels - Bellefonte Nuclear Plant - Annual Rept - 1979" Rept presents results obtained from preoperational environ radiological monitoring program
MILLS, L M Tennessee Valley Authority 81/01/22 3pp 07576 1

--8101290269 "Environ Radioactivity Levels - Bellefonte Nuclear Plant - Annual Rept - 1979"
* Tennessee Valley Authority 8A-80-9-0L1 81/01/22 37pp
07554 039

5. Reportable occurrences, LERs & related correspondence

8101290651 Third interim deficiency rept. originally reported 800502 deficient fillet welds Reinsp of socket welds continuing Weld history documentation sys being developed to identify deficient welds. Next rept will be submitted by 810309
MILLS, L M Tennessee Valley Authority 80/12/13 1p. 07566 3

8101050325 Second interim deficiency rept. originally reported on 800923 re raised buttonheads on rock anchor tendons Insp revealed wire in Group 1 tendons overstressed & buttonheads in Group 2 overstressed Next rept to be submitted by 810428.
MILLS, L M Tennessee Valley Authority 80/12/29 3pp 07385 2

8101290350 Third interim deficiency rept. originally reported 800319 failure of main steam line breaks because of feedwater overflow. Evaluation of dynamic loading effects on main steam lines continuing Next rept will be submitted by 810625
MILLS, L M Tennessee Valley Authority 80/12/29 1p. 07566 3

8101070417 First interim deficiency rept re Consolidated Control C field buffer cards, initially reported on 801203 Util is investigating method of verifying adequacy of all field buffer cards Next rept will be forwarded by 810521
MILLS, L M Tennessee Valley Authority 81/01/02 2pp 07415

8101070424 First interim deficiency rept re automatic switchover d borated water storage tank, initially reported on 801203 Util will reissue control documents providing for automatic switchover Next rept will be forwarded by 810218
MILLS, L M Tennessee Valley Authority 81/01/02. 2pp. 07415.

8101140611 Interim Deficiency Rept 1 re essential raw cooling water steam flash. Design of essential raw cooling water piping is being evaluated to incorporate ability to deal w/wide spectrum of fouling factors. Originally reported on 801209.
MILLS, L M Tennessee Valley Authority 81/01/07. 2pp. 07461.

8101140627 First interim rept. originally reported on 801208 re low voltage switchgear Installation seismic mounting configuration not welded per design drawings. OA auditing all switchgears. Investigation to be completed by 810423
MILLS, L M Tennessee Valley Authority 81/01/08 2pp. 07461.

8101190362 Third interim deficiency rept. originally reported on 801208 re incorrect svc factors on Westinghouse motor nameplates. Nameplates to be changed to reflect vendor-documented svc factor
MILLS, L M Tennessee Valley Authority 81/01/09 2pp. 07475.

8101230311 Interim Part 21 rept re Atwood & Morrill valve deficient Initially reported 801212 Decay heat removal valve 3800413-KO-3D S/N 142-13894 has 2-inch surface crack in upper body Investigation continuing
MILLS, L M Tennessee Valley Authority. 81/01/12 3pp. 07187.

DOCKETED ITEMS

810120327 Final deficiency rept. originally reported 801212 re threaded
 pipet qualification WFL Inc pipet identified, analyzed &
 accepted per design procedures Remainder will be analyzed
 for stress intensity factors by 810306
 MILLS, L.M. Tennessee Valley Authority 81/01/13 2pp. 07490 131.

8101220311 Forwards first interim repl re potential flammability of
 suspended ceiling tile in control rooms in response to
 801104 ltr Addl info to be provided by 810211
 MILLS, L.M. Tennessee Valley Authority 81/01/14 3pp

8101230458 Fourth interim deficiency repl re failed motor operated
 valves mfg by Amp Actuators, Inc & defective limit switches.
 Initially reported on 800611 Actuators were returned to
 factory for repairs Next repl will be submitted by 810325
 MILLS, L.M. Tennessee Valley Authority 81/01/14 2pp 07511 147.

8101260446 Fifth interim deficiency rept. originally reported on
 771125 re purchase requests issued w/o specified IEEE
 qualifications All deficient requests revised to include
 proper qualifications Next repl will be submitted by 810422
 MILLS, L.M. Tennessee Valley Authority 81/01/15 2pp 07531 223

8101270419 Second interim deficiency repl re fillet weld
 misapplication, initially reported on 801107 Design review
 repeats discrepancies in each IVA facility Util will
 evaluate facilities Next repl will be submitted by 810409
 MILLS, L.M. Tennessee Valley Authority 81/01/19. 2pp 07549 042

8101270422 Second interim deficiency repl re ITT Grinnell welded
 supports, initially reported 800903 Detail sheets w/
 discrepancies in weld designations will be revised by ITT
 Grinnell for use in insp of fabricated welds
 MILLS, L.M. Tennessee Valley Authority 81/01/22 2pp 07548 358.

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants Forwarding
 summary of 801112 meeting re implementation of guidance for
 Unresolved Safety Issue A-12, "Potential for Low Fracture
 Toughness & Lemeiler Tearing on Component Supports"
 EISENHUT, D.O. Division of Licensing 80/11/26 8pp.

810120710 Forwards request for addl info re ultimate capacity analysis
 of ice condenser & Mark III containments
 TEDESCHI, R.L. Assistant Director for Licensing 80/12/18 3pp
 07494 040.

8101190305 Ltr to all BWR applicants for OL re BWR scram discharge eye
 safety evaluation & requirements Rept specifying acceptable
 basis for continued BWR plant operation & design criteria
 for scram discharge vol encl
 TEDESCHI, R.L. Assistant Director for Licensing 80/12/22 2pp
 07183 001

--8101190514 Forwards generic safety evaluation re BWR scram discharge
 sys. Review identified two scd1 requirements to these
 proposed by owners group re scram discharge vol designs Rept
 should be transmitted to license applicants.
 CHECK, P.B. Assistant Director for Plant Systems. 80/12/01. 2pp
 07183 001.

8101200498 Responds to NRC 801226 ltr requesting schedule for
 performing ultimate capacity analysis for Mark III
 containment design Static pressure analysis for surface
 w/min sectional strength may be completed by Nov 1981
 DAVIS, D.R. Cleveland Electric Illuminating Co. 81/01/22 1p.
 07582 352

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders &
 CP applicants Revised radiological emergency response
 plans must be submitted by licensees within 60 days of
 810102 & by applicants as part of PSAR
 EISENHUT, B.O. Division of Licensing. 80/11/13. 2pp.

G Inspection reports, IE Bulletins & correspondence

8101050244 Forwards IE Info Notice 80-38, "Cracking in Charging Pump
 Casing Cladding." No response required
 KEPLER, J.O. Region 3, Chicago, Office of the Director. 80/10/30.
 2pp. 07337 116

8101040110 Forwards IE Circular 80-23, "Potential Defects in Below
 Power Sys Emergency Generators." No written response
 required
 KEPLER, J.O. Region 3, Chicago, Office of the Director 80/10/
 1p 07377 723

810130264 Forwards IE Insp Repts 50-440/80-25 & 50-441/80-23 on
 201001-21 & notice of violation
 FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineer
 Support Branch 80/11/19 2pp 07421 289

--8101080271 Notice of violation from insp on 801001-31
 "Region 3, Chicago, Office of the Director 80/11/17 1p
 07421 291

--8101080284 IE Insp Repts 50-440/80-25 & 50-441/80-23 on 801001-
 Noncompliance noted failure to follow engineer drawings &
 fabricated pool pieces 1-E13-32 & 1-E13-33 being cold-
 pulled into position
 HUGHES, J., WILLIAMS, C.C. Region 3, Chicago, Office of the
 Director 80/11/17 1pp 07421 292

8101050526 Forwards IE Info Notice 80-43, "Failures of Continuous
 Level Monitor for Scram Discharge Vol at Oresden Unit 2." No
 response required.
 KEPLER, J.O. Region 3, Chicago, Office of the Director 80/12/
 2pp 07390 297

8101080556 Forwards IE Info Notice 80-45, "Potential Failure of H
 Backup Manual Brm Capability." No written response
 required
 KEPLER, J.O. Region 3, Chicago, Office of the Director 80/12/
 2pp 07420 325

810130246 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Cen
 Rods to Insert During Scram at BWR." No written response
 required.
 KEPLER, J.O. Region 3, Chicago, Office of the Director 80/12/
 2pp 07465 339

8101050232 Forwards IE Bulletin 80-25, "Operating Problems w/Targ
 Rock Safety Relief Valves at 3Mw." No response required
 KEPLER, J.O. Region 3, Chicago, Office of the Director 80/12/
 2pp 07377 349

8101290486 Forwards IE Insp Repts 50-440/80-27 & 50-441/80-28 on
 801101-30 No noncompliance noted
 FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineer
 Support Branch 80/12/22 2pp 07575 158.

--8101290491 IE Insp Rept 50-440/80-27 & 50-441/80-28 on 801101-3
 noncompliance noted Major areas inspected safety-related
 const activities including containment spray sys piping &
 heating, ventilation & air conditioning ducts.
 HUGHES, J., WILLIAMS, C.C. Region 3, Chicago, Office of the
 Director 80/12/17 3pp 07575 160

8101200517 Responds to IE Bulletin 80-21, "Valve Yokes Supplied
 Malcolm Foundry Co. Inc." Castings are not used in active
 safety-related valves at facilities
 DAVIS, D.R. Cleveland Electric Illuminating Co. 80/12/23.
 07487 051

8101290160 Ack receipt of 801015 ltr informing NRC of steps taken
 correct violations noted in IE Insp Rept 50-440/80-18
 FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineer
 Support Branch 81/01/08 1p 07567 354.

--8101290169 Responds to NRC 800912 ltr re violations noted in 1
 Rept 50-440/80-18 Corrective actions formal definition of
 weave per ASME Section IX will be added to each general
 welding std
 DAVIS, D.R. Cleveland Electric Illuminating Co. 80/10/15
 07567 355

8101220116 Ack receipt of 801219 ltr informing NRC of steps taken
 correct violations noted in IE Insp Repts 50-440/80-25 &
 50-441/80-23
 FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineer
 Support Branch 80/01/09 1p. 07502 004

--8101220121 Responds to NRC 801119 ltr re violations noted in 1
 Repts 50-440/80-25 & 50-441/80-23. Corrective actions
 Pullman Power Products Procedure IX-53 incorporating
 procedures of piping stress tests initiated
 DAVIS, D.R. Cleveland Electric Illuminating Co. 80/12/16
 07502 005

B Reportable occurrences, LERs & related correspondence

8101220545 Interim deficiency rept re improper reactor protection sys flexible conduit grounding in power generation control complex. Caused by mounting termination module on painted surface. Final rept will be submitted by 810701
DAVIDSON, D R Cleveland Electric Illuminating Co 81/01/14 2pp
07303 151

8101220420 Interim deficiency rept re lamination identified in A36 gusset plate hanger steel nail. Initially reported on 801219 Insp program & evaluation of results will determine addl corrective actions. Final rept will be submitted by 810302
DAVIDSON, D R Cleveland Electric Illuminating Co 81/01/15 2pp
07502 249

BUCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101130710 Forwards request for addl info re ultimate capacity analysis of ice condenser & Mark III containment
TEEGES, R L Assistant Director for Licensing 80/12/18 3pp
07454 046

8101300458 Responds to NRC 801226 ltr requesting schedule for performing ultimate capacity analysis for Mark III containment design. Static pressure analysis for surfaces within sectional strength may be completed by Nov 1981
DAVIDSON, D R Cleveland Electric Illuminating Co 81/01/22 1p
07582 352

F Security, medical, emergency & fire protection plans

8101070587 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 Ltr by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

D Inspection reports, IE Bulletins & correspondence

8101050244 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30 2pp 07389 116

8101060110 Forwards IE Circular 80-23, "Potential Defects in Belfoit PWR Sys Emergency Generators." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/31 1p 07397 3211

8101090264 Forwards IE Insp Repts 50-440/80-25 & 50-441/80-23 on 801001-31 & notice of violation
FICRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/19 2pp 07421:289

--8101080271 Notice of violation from Insp on 801001-31, "Region 3, Chicago, Office of the Director 80/11/17 1p 07421 291

--8101080284 IE Insp Repts 50-440/80-25 & 50-441/80-23 on 801001-31 Noncompliance noted. Failure to follow engineer drawings & fabricated spool pieces 1-E15-32 & 1-E15-33 being cold-pulled into position
HUGHES, J. WILLIAMS, C C Region 3, Chicago, Office of the Director 80/11/17 11pp 07421 292

8101050526 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05 2pp 07390 297

8101080556 Forwards IE Info Notice 80-45, "Potential failure of BWR Backup Manual Scram Capability." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17 2pp 07420 325

8101050246 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Rods to Insert During Scram at BWR." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05 2pp 07465 359

8101050232 Forwards IE Bulletin 80-25, "Operating Problems With Rock Safety Relief Valves at BWRs." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05 2pp 07377 349

8101290406 Forwards IE Insp Repts 50-440/80-27 & 50-441/80-25 on 801101-30 No noncompliance noted
FICRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/22 2pp 07575 198

--8101250491 IE Insp Rept 50-440/80-27 & 50-441/80-25 on 801101-30 Noncompliance noted. Major areas inspected safety-related const activities including containment spray sys piping & heating, ventilation & air conditioning ducts
HUGHES, J. WILLIAMS, C C Region 3, Chicago, Office of the Director 80/12/17 3pp 07575 160

8101200537 Responds to IE Bulletin 80-21, "Valve Yoke Supplier Malcolm Foundry Co. Inc.' Castings are not used in active safety-related valves at facilities
DAVIDSON, D R Cleveland Electric Illuminating Co 80/12/23 07487 051

8101220116 Ack receipt of 801219 ltr informing NRC of steps to correct violations noted in IE Insp Repts 50-440/80-25 & 50-441/80-23
FICRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/01/09 1p 07502.004

--8101220121 Responds to NRC 801119 ltr re violations noted in Repts 50-440/80-25 & 50-441/80-23 Corrective actions Pullman Power Products Procedure IX-53 incorporating procedures of piping stress tests initiated
DAVIDSON, D R Cleveland Electric Illuminating Co. 80/12/07502 005

B Reportable occurrences, LERs & related correspondence

8101220545 Interim deficiency rept re improper reactor protection flexible conduit grounding in power generation control complex. Caused by mounting termination module on painted surface. Final rept will be submitted by 810701
DAVIDSON, D R Cleveland Electric Illuminating Co 81/01/14 07303 151

8101220420 Interim deficiency rept re lamination identified in gusset plate hanger steel nail. Initially reported on 801219 Insp program & evaluation of results will determine addl corrective actions. Final rept will be submitted by 810302
DAVIDSON, D R Cleveland Electric Illuminating Co 81/01/15 07502 249

BUCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8101220456 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101100228 Informs that 801118 request for partial transfer of CP & CPR-136 only requires Class II fee for Unit 1 & Class I fee for Unit 2. Refund will be processed in 2-wk period
BEGGS, R H License Fee Management Branch 80/12/22 1p 07445:216

8101190625 Approves until 801208 request for authorization to use Code Case N-279 in const of components at facility. When preloading is used as locking device & joint requires removal, bolting shall be replaced if original is strained
VANDERBLOED, G J Licensing Branch 1 80/12/29 2pp 07472

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101070254 Requests that encl emergency planning info be made publicly available H/O encl
SQUJER, J L Division of Rules and Records 80/12/17 1p
07414 298

G Adjudicatory correspondence

8101070513 Interrogatories directed to applicant Requests info re witnesses & util position on Intensity IX earthquake
Certificate of Svc encl
WEISS, E R JORDAN, W B New England Coalition on Nuclear Pollution
WEISS, E R Sheldon, Harmon & Weiss 81/01/02 11pp 07415 100

8101070306 Chinnery answers to applicant Interrogatories re seismic issues Affidavit to be included shortly Certificate of Svc encl
JORDAN, W B New England Coalition on Nuclear Pollution JORDAN, W B
Sheldon, Harmon & Weiss 81/01/06 25pp 07187 001

8101270334 Responds to ltr re NRC discovery Requests New England Coalition on Nuclear Power delete Interrogatories B.9 & 15
Proposes single deposition of NRC witnesses as panel & B10212 as deposition date
LESSBY, R P Antitrust Division 81/01/15 3pp 07546 081.

8101230196 Order granting extension until 810130 for Commission to review ALAB-623 Certificate of Svc encl
CHILK, S J Office of the Secretary of the Commission 81/01/16 4pp 07512 026

8101280591 Answers & objections to New England Coalition on Nuclear Power Interrogatories Certificate of Svc encl
VANDEBURGH, D J BIGNAN, T G Public Service Co. of New Hampshire
BIGNAN, T G Bignan, T O 81/01/21 20pp 07535 140

8101270434 Forwards transcript of MD Trifunac deposition Corrections listed Requests review & addl changes
LESSBY, R P Antitrust Division 81/01/26 2pp 07546 184.

H General correspondence

8101080399 Responds to 801113 ltr expressing concerns re usefulness in siting policy as outlined in WUREO-0625 Financial problems have not excluded facility owners from activities authorized by NRC regulations Ltr dtd 801021 to RA Backus encl
YOUNGBLOOD, B J Licensing Branch 1 80/12/08 2pp 07419 263

8101140208 Responds to 001116 ltr expressing concern re nuclear accident insurance Price-Anderson Act provides sys of private funds & govt indemnity to pay public liability claims for personal injury & property damage
DENTON, H R Office of Nuclear Reactor Regulation, Director.
80/12/24 5pp 07309 001.

--8101140214 Expresses concern re const of facilities & requests info re nuclear accident insurance.
PETIT, R Affiliation Unknown 80/11/16 2pp 07309 001

8101090100 Comments that Seabrook const should be stopped, since nuclear power is unsafe & power plant operation is inefficient
PETIT, R Affiliation Unknown 00/12/30 1p 07442 235

8101090508 Expresses adamant opposition to licensing of facilities
MOYER, H S Affiliation Unknown 81/01/07 5pp 07463 143

8101190114 Responds to encl 801210 ltr to President Carter expressing concern re const of facilities & questioning need for nuclear power Licensing procedure explained.
YOUNGBLOOD, B J Licensing Branch 1 81/01/07 3pp 07475 319.

G Inspection reports, IE Bulletins & correspondence

8101070399 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director.
80/11/26, 1p 07414 086

8101060849 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/16 1p 07397 009

8101170301 Immediate Action ltr 80-55, confirming until 801222 commitments re items of non-compliance re cold repairs in safety-related piping sys licensee will issue stop work order to halt repairs performed by Callinan-Higgins
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/22 2pp 07474 276

S Reportable occurrences, LERs & related correspondence

8101230497 Final deficiency rept originally reported on 801216 re pipe supports not meeting ASME code requirements Caused by design & human error Formal design manual issued, check list initiated to confirm requirements & training session begun
DEVINCENFIS, J Public Service Co. of New Hampshire 81/01/15 07510 022

T Hearings transcripts on non-antitrust matters

810126256 Transcript of 780604 proceedings in Washington, DC re consideration of stay of facilities during review of ALAB-471
Commissioners 70/06/09 46pp 07503 320

DOCKET 80-444 SEABROOK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8101280446 Ltr to all power reactor licensees & applicants forward summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 00/11/26 8pp

8101100228 Informs that 801118 request for partial transfer of CPR & CPRR-126 only requires Class 11 fee for Unit 1 & Class 1 fee for Unit 2 Refund will be processed in 2-wk period
DIQGB, H H License Fee Management Branch 80/12/22 1p 07419 216

8101190625 Approves until 801208 request for authorization to use Code Case H-279 in const of components at facility when preloading is used as locking device & joint requires removal, bolting shall be replaced if original is strained
YOUNGBLOOD, B J Licensing Branch 1 80/12/29 2pp 07472 311

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

8101070254 Requests that encl emergency planning info be made publicly available H/O encl
SQUJER, J L Division of Rules and Records 80/12/17 1p
07414 298

G Adjudicatory correspondence

8101070513 Interrogatories directed to applicant Requests info re witnesses & util position on Intensity IX earthquake
Certificate of Svc encl
WEISS, E R JORDAN, W B New England Coalition on Nuclear Pollution
WEISS, E R Sheldon, Harmon & Weiss 81/01/02 11pp 07415 100

8101070306 Chinnery answers to applicant Interrogatories re seismic issues Affidavit to be forwarded shortly Certificate of Svc encl
JORDAN, W B New England Coalition on Nuclear Pollution JORDAN, W B
Sheldon, Harmon & Weiss 81/01/06, 25pp 07187 001

8101270334 Responds to ltr re NRC discovery Requests New England Coalition on Nuclear Power delete Interrogatories B.9 & 15
Proposes single deposition of NRC witnesses as panel & B10212 as deposition date
LESSBY, R P Antitrust Division 81/01/15 3pp 07546 081

8101230196 Order granting extension until 810130 for Commission review, ALAB-623 Certificate of Svc encl
CHILK, S J Office of the Secretary of the Commission 81/01/16 4pp 07512 026

8101280591 Answers & objections to New England Coalition on Nuclear Power Interrogatories Certificate of Svc encl
VANDEBURGH, D J BIGNAN, T G Public Service Co. of New Hampshire
BIGNAN, T G Bignan, T O 81/01/21 20pp 07535 140

01127000 Forwards transcript of MO Testimony deposition Corrections
Listed Requests review & addl changes
LESTER, R. P. Antitrust Division 81/01/26 2pp 07346 184

H General correspondence

8101140738 Responds to B01116 ltr expressing concern re nuclear
accident insurance. Price-Anterson Act provides sys of
private funds & govt indemnity to pay public liability
claims for personnel injury & property damage
DELLER, H. R. Office of Nuclear Reactor Regulation, Director
80/12/24 3pp 07309 001

--8101140714 Expresses concern re costs of facilities & requests info re
nuclear accident insurance
PETIT, K. Affiliation Unknown 80/11/16 2pp 07309 001

8101090100 Comments that heatseeker tests should be stopped, since
nuclear power is unsafe & power plant operation is
inefficient
PETIT, K. Affiliation Unknown 80/12/30 1p 07442 235

8101090908 Expresses adamant opposition to licensing of facilities
MORFEN, H. S. Affiliation Unknown 81/01/07 3pp 07463 145

8101140116 Responds to encl B01210 ltr to President Carter expressing
concern re costs of facilities & questioning need for
nuclear power. Licensing procedure explained
VORHAGEN, C. J. Licensing Branch 1 81/01/07 3pp 07475 319

I Inspection reports, IE Bulletins & correspondence

8101070395 Forwards Hoppel 1 to IE Info Notice 80-29. Broken Studs on
Terry Turbine Steam Inlet Flange. No written response
required
GRIFER, D. H. Region 1, Philadelphia, Office of the Director
80/11/26 1p 07414 006

8101060849 Forwards IE Info Notice 80-44. 'Activation of ECCS in
Retirculation Mode While in Hot Shutdown'. No written
response required
GRIFER, D. H. Region 1, Philadelphia, Office of the Director
80/12/16 1p 07377 009

G Reportable occurrences, LERs & related correspondence

8101230497 Final deficiency rept. originally reported on 80126, re
pipe supports not meeting ASME code requirements. Caused by
design & human error. Formal design manual issued, check list
initiated to confirm requirements & training session begun.
DEVINCEN, T. S. J. Public Service Co. of New Hampshire, 01/01/13 1p
07510 022

T Hearing transcripts on non-antitrust matters

8101220296 Transcript of 700609 proceedings in Washington, DC re
consideration of stay of facilities during review of
ALAB-471
* Commissioners 78/06/09 46pp 07503 328

DOCKET 80-445 (CMANICHE PEAK STEAM ELECTRIC STA. UNIT 1)

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12. 'Potential for Low Fracture
toughness & Lamellar Tearing on Component Supports'
EISENHART, D. O. Division of Licensing 80/11/26 8pp

8101050318 Submits suppl to util 800808 rept re architectural tapping
placed on floor slabs. Project completion anticipated 810201
GARY, R. J. Texas Utilities Generating Co 80/12/22 1p 07305 271

8101200242 Informs that evaluation of pull-out performance of 1-inch
diameter Hilti Quik-Bolt anchors continues due to change in
published values. Status rept will be provided by 810901
GARY, R. J. Texas Utilities Generating Co 81/01/12 1p 07487 002

8101270110 Forwards request for addl info needed to complete review of
the application. FEAR should be amended to include new info
TEDESCO, R. L. Assistant Director for Licensing 81/01/13 4pp
07547 041

8101290443 Summary of B01015 meeting 3/01/11 in Bethesda, MD re facility
response to proposed design change for improving nuclear
steam sys response to boron dilution transients. List of
attendees & slide presentation encl
BARNWELL, S. P. Licensing Branch 2 81/01/14 4pp 07571 001

8101300521 Requests documentation of maint records re preservice ins
testing of snubbers due to problems w/ inoperable &
incorrectly installed snubbers. Preservice exam should be
made of snubbers listed in STR Tables 3 7-4a & 3 7-4b
TEDESCO, R. L. Assistant Director for Licensing 01/01/14 3pp
07587 074

8101270347 Forwards updated U10115 Well data rept Rept superseded
80922 rept
WEARNER, H. Texas Utilities Services, Inc 81/01/16 1p 07560 001

--8101270753 Well data on all wells within 5-mile radius of
facility, as of 801231
REHNER, L. J. H. J. Gray & Associates, Inc 81/01/15 8pp
07560 001

C Utility Environmental Report (ER), amends & correspondence

8101060462 Forwards affidavit of svr of Amend 2 to environ rept. DL
stage
SCM101, H. C. Texas Utilities Generating Co 80/12/29 9pp
07396 079

8101160590 Forwards Amend 3 to environ rept Affidavit encl
GRAY, J. R. Texas Utilities Co 81/01/00 2pp 07472 130

--8101160507 Amend 3 to environ rept
* Texas Utilities Co 01/01/31 2pp 07472 132

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP hold
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of PSAR
EISENHART, D. O. Division of Licensing 80/11/13 2pp

8101070291 Releasees public version of State of TX, Hood County, City
Granbury, Somervell County & City of Glen Rose emergency
operations plans
FELTON, J. H. Division of Rules and Records 80/12/02 1p
07309 001

--8101070298 Forwards public version of State of TX, Hood County, City
Granbury, Somervell County & City of Glen Rose emergency
operations plans
EDWARDS, J. O. Texas Utilities Co 80/01/29 1p 07309 001

--8101070302 Public version of State of TX, Hood County & City of
Granbury emergency operations plan
* Hood County, TX * Granbury, TX 76/09/20 26pp 07309 001

--8101070307 Public version of State of TX, Somervell County & City
Glen Rose emergency operations plan
* Somervell County, TX * Glen Rose, TX 00/01/29 23pp
07309 001

8101300131 Forwards facility emergency planning info for placement
LFOR w/o 8101070298
SOUDER, J. L. Division of Rules and Records 81/01/16 1p
07583 075

Q Adjudicatory correspondence

8101050478 Response to Citizens Association for Bound Energy second
of interrogatories. Discovery request relevancy determined in
view of Contention 3, worded as accepted by ABLB in 800616
order. Certificate of Svc encl. Related correspondence
REYNOLDS, N. S. MORIN, W. A. Texas Utilities Generating Co
REYNOLDS, N. S. Debevoise & Liberman 80/12/22 11pp 07390 206

8101050523 Response to NRC 801209 response to Citizens Association
Bound Energy motions for separate intervenor status &
appointment as lead party for consolidated contentions.
Clarifies previous pleadings. Certificate of Svc encl.
ELLIS, J. Citizens Association for Bound Energy 00/12/23 9pp
07390 236

0508 Order denying Citizens Association for Sound Energy motion
separate intervenor status Consolidates parties on
Entorons 4, 5, 22, 23 & 24 Appoints lead party intervenor
on other contentions
R.V.B. Atomic Safety and Licensing Board Panel 00/12/31
07415 087

0037 Answers to applicant first set of interrogatories & requests
to produce per ASLB 801219 memorandum & order Most response
is supplemented at later date Certificate of Svc encl
ated correspondence
J.M. Association of Community Organizations for Reform
Texas GAY, G.M. West Texas Legal Services 81/01/05 13pp
B 326

0233 Second set of interrogatories & requests to produce directed
Citizens Association for Sound Energy re Contention 22.
licants' failure to comply w/10CFR50 emergency planning
requirements Certificate of Svc encl
0008.M.S. , HIRIN, W.A. Texas Utilities Generating Co
0008.M.S. Debevoise & Liberman 81/01/12. 17pp 07470 199

0073 First set of interrogatories & request for production of
evidence directed to intervenor Citizens Association for
Sound Energy Includes identification of witnesses &
series of positions Certificate of Svc encl
SCHILD, M.U. Operations & Administrative Division 81/01/19
07502.009

0078 First set of interrogatories & request for production of
evidence directed to Association of Community Organizations
for Reform Now includes identification of witnesses &
series of positions Certificate of Svc encl
SCHILD, M.U. Operations & Administrative Division 81/01/19
07502 036

0082 First set of interrogatories & request for production of
evidence directed to Citizens for Fair Util Regulation
Includes identification of witnesses & summaries of
positions Certificate of Svc encl
SCHILD, M.U. Operations & Administrative Division. 81/01/19
07502:077

Section reports, IE Bulletins & correspondence

0117 Ack receipt of IE Insp Repts 50-445/80-18 & 50-446/80-18 No
proprietary info
R.J. Texas Utilities Generating Co 80/10/18 1p 07547.212

0247 Discusses IE Insp Repts 50-445/80-23 & 50-446/80-23
01009 & forwards notice of violation Repts to be
aid in near future
E.H.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/10/16. 2pp 07445.221

100251 Notice of violation from Insp on 801008 Noncompliance noted
disconnecting stiffener plates to balance of Assembly
07 were not complete penetration welds
Region 4, Dallas, Office of the Director 80/10/16 1p.
07445 223

0814 Ack receipt of IE Insp Repts 50-445/80-20 & 50-446/80-20
proprietary info
R.J. Texas Utilities Generating Co. 80/11/12. 1p 07549 093

0059 Forwards IE Insp Repts 50-445/80-23 & 50-446/80-23 on
01-31.
E.H.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/11/19 2pp 07443 019

100063 IE Insp Repts 50-445/80-23 & 50-446/80-23 on 801001-1031
noncompliance noted: failure to follow procedures for making
all penetration welds
VLDR, R.O., CROSSMAN, W.A. Region 3, Chicago, Office of the
Director. 80/11/19 7pp 07443 021

0171 Forwards IE Insp Repts 50-445/80-28 & 50-446/80-28 on
03-06 No noncompliance noted.
E.H.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch. 80/11/19 2pp. 07443.008

10017B IE Insp Repts 50-445/80-28 & 50-446/80-28 on 801003-06 No
noncompliance noted: Major areas inspected const activities &
records for RCPB piping.
LBERI, L.D., CROSSMAN, W.A. Region 3, Chicago, Office of the
Director. HALL, R.E. Region 3, Chicago, Reactor Construction &
Engineering Support Branch 80/11/18 3pp. 07443 010

801017055a Responds to IE Bulletin 80-20, "Failures of Westinghouse
Type --2 Spring Return to Neutral Control Switches"
Corrective actions scheduled for 811201 completion contact
lights will be repaired & auxiliary relay for alarm added
GRAY, R.J. Texas Utilities Generating Co 80/11/19 2pp
07488 242

80101270152 Ack receipt of IE Insp Repts 50-445/80-24 & 50-446/80-24 No
proprietary info
GARY, R.J. Texas Utilities Generating Co 80/11/19 1p 07547 292

80101270147 Ack receipt of IE Insp Repts 50-445/80-25 & 50-446/80-25 No
proprietary info
GARY, R.J. Texas Utilities Generating Co 80/12/03 1p 07547 298

80101030619 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Steam Discharge Vol at Dresden Unit 2" No
response required
SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/12/08
1p 07391 091

0101080182 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown" No written
response required
SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/12/16
1p 07391 288

8010100716 Ack receipt of 801112 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-445/80-23 &
50-446/80-23
E.H.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/23 1p 07443 225

--8010103726 Responds to NRC 801016 ltr re violations noted in IE Insp
Repts 50-445/80-23 & 50-446/80-23 Corrective actions
assembly repaired & fabrication drawings reviewed
GARY, R.J. Texas Utilities Generating Co 80/11/12. 3pp
07443 226

8010109732 Ack receipt of 801110 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-445/80-20 &
50-446/80-20
E.H.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/23 1p 07443 229

--8010100738 Responds to NRC 801021 ltr re violations noted in IE Insp
Repts 50-445/80-20 & 50-446/80-20 Corrective actions
applicable flow diagrams revised to reflect actual
pressurizer/spray valve arrangement
GARY, R.J. Texas Utilities Generating Co 80/11/18 3pp
07443 239

8010120372 Forwards IE Insp Repts 50-445/80-26 & 50-446/80-26 on
801105-07, 13-14, 18-20 & 24-25 No noncompliance noted
E.H.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch. 80/12/23 2pp 07487 308

--80101210077 IE Insp Repts 50-445/80-26 & 50-446/80-26 on 801105-07,
13-14, 18-20 & 24-25 No noncompliance noted Major areas
inspected const activities including reactor vessel/
internals & instrumentation components & sys
CROSSMAN, W.A., STEWART, R.C. Region 4, Dallas, Office of the
Director. 80/12/23 6pp 07489 310

8010100621 Requests documentation of maint records re pressservice Insp &
testing of snubbers due to problems w/inoperable &
incorrectly installed snubbers Pressservice exam should be
made of snubbers listed in SIS Tables 3 7-4a & 3 7-4b
TEDESCO, R.L. Assistant Director for Licensing 81/01/14 3pp
07587 074

B Reportable occurrences, LERs & related correspondence

80101200246 Interim deficiency rept re mfp deficiency of component
supports associated w/auxiliary piping sys diesel
generators, initially reported 800926 Evaluation will be
completed by 810731.
GARY, R.J. Texas Utilities Generating Co 81/01/12 1p 07487 091.

80101200253 Interim deficiency rept re unauthorized field mods to
Hilti-Kwik concrete anchor bolts, initially reported 801001.
Bolts have not been modified in unauthorized manner
Follow-up rept will be submitted by 810417
GARY, R.J. Texas Utilities Generating Co 81/01/12 2pp
07487 089

A. Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. Potential for Low Fracture Toughness & Laminar tearing on Component Supports
EISENHUT, D. G. Division of Licensing 80/11/26 2pp

B101050316 Submits suppl to util 800808 rept re architecture of topping placed on floor slabs project completion anticipated B10801
GARY, R. J. Texas Utilities Generating Co 80/12/22 1p 07389 271

B101203242 Informs that evaluation of pull-out performance of 1-inch diameter Hilti Walk-Bolt anchors continues due to change in published values Status rept will be provided by B10901
GARY, R. J. Texas Utilities Generating Co 81/01/12 1p 07487 092

B101270110 Forwards request for addl info needed to complete review of Q. application FSAR should be amended to include new info.
TEDESCO, R. L. Assistant Director for Licensing 81/01/13. 9pp
07547 041

B101290463 Summary of B01015 meeting w/util in Bethesda, MD re facility response to proposed design change for improving nuclear steam sys response to boron dilution transients List of attendees & slide presentation encl
BURWELL, S. G. Licensing Branch 2 81/01/14 4pp 07571 001

B101300521 Requests documentation of main records re preservice insp & testing of snubbers due to problems w/Inoperable & incorrectly installed snubbers Preservice exam should be made of snubbers listed in SIS tables 3 7-46 & 3 7-4b
TEDESCO, R. L. Assistant Director for Licensing 81/01/14 3pp
07587 074

B101270347 Forwards updated B10115 well data rept Rept supersedes B00922 rept
WEACER, R. Texas Utilities Services, Inc 81/01/16 1p 03560 001.

--B101270353 Well data on all wells within 5-mile radius of facility, as of B01231.
REHAEEMPER, L. J. H. J. Gray & Associates, Inc 81/01/15. 8pp.
03560 001

C. Utility Environmental Report (ER), agenda & correspondence

B101060462 Forwards affidavit of svc of Amend 2 to environ rept.OL stage.
SCHMIDT, H. C. Texas Utilities Generating Co 80/12/29 9pp
07396 079

B101160560 Forwards Amend 2 to environ rept Affidavit encl
GRAY, J. A. Texas Utilities Co 81/01/08 2pp 07472 130

--B101160507 Amend 3 to environ rept
" Texas Utilities Co 81/01/31 2pp 07472 132

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants. CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D. G. Division of Licensing 80/11/13 2pp.

B101070291 Releases public version of State of TX.Hood County, City of Granbury, Somervell County & City of Glen Rose emergency operations plans
FELTON, J. M. Division of Rules and Records. 80/12/02 1p
07309 001

--B101070298 Forwards public version of State of TX.Hood County, City of Granbury, Somervell County & City of Glen Rose emergency operations plans
EDWARDS, J. D. Texas Utilities Co 80/01/29 1p. 07309 001

--B101070302 Public version of State of TX.Hood County & City of Granbury emergency operations plan
" Hood County, TX " Granbury, TX 76/09/20 26pp. 07309 001.

--B101070307 Public version of State of TX, Somervell County & City of Glen Rose emergency operations plan
" Somervell County, TX " Glen Rose, TX 80/01/29 25pp
07309 001

D. Adjudicatory correspondence

B101050478 Response to Citizens Association for Sound Energy second set of interrogatories Discovery request relevancy determined in view of Contention 3: Jorred as accepted by ASLB in 800616 order Certificate of Svc encl Related correspondence
REYNOLDS, M. S., MORIN, W. A. Texas Utilities Generating Co.
REYNOLDS, M. S., Debevoise & Liberman 80/12/22 11pp 07390 206

B101050523 Response to NRC B01209 response to Citizens Association for Sound Energy motions for separate intervenor status & appointment as lead party for consolidated contentions Clarifies previous pleadings Certificate of Svc encl.
ELLIS, J. Citizens Association for Sound Energy 80/12/23. 9pp
07390 236

B101070508 Order denying Citizens Association for Sound Energy motion for separate intervenor status Consolidates parties on Contentions 4, 5, 22, 23 & 24 Appoints lead party intervenor status on other contentions
DEALE, V. B. Atomic Safety and Licensing Board Panel. 80/12/31 13pp 07415 087

B101130037 Answers to applicant first set of interrogatories & request to produce per ASLB B01219 memorandum & order Most responses to be supplemented at later date Certificate of Svc encl Related correspondence
GAY, R. M. Association of Community Organizations for Reform Now-Texas GAY, O. M. West Texas Legal Services. 81/01/09 13pp.
07448 326

B101160233 Second set of interrogatories & requests to produce directed to Citizens Association for Sound Energy re Contention 22. applicants' failure to comply w/IOCFR50 emergency planning requirements Certificate of Svc encl
REYNOLDS, M. S., MORIN, W. A. Texas Utilities Generating Co.
REYNOLDS, M. S. Debevoise & Liberman. 81/01/12. 17pp 07470: 149.

B101220073 First set of interrogatories & request for production of documents directed to intervenor Citizens Association for Sound Energy includes identification of witnesses & summaries of positions Certificate of Svc encl
ROTHSCHILD, M. U. Operations & Administrative Division 81/01/19 27pp 07502. 609

B101220078 First set of interrogatories & request for production of documents directed to Association of Community Organizations for Reform Now includes identification of witnesses & summaries of positions Certificate of Svc encl.
ROTHSCHILD, M. U. Operations & Administrative Division 81/01/19 41pp. 07502 036

B101220082 First set of interrogatories & request for production of documents directed to Citizens for Fair Util Regulation. includes identification of witnesses & summaries of positions Certificate of Svc encl.
ROTHSCHILD, M. U. Operations & Administrative Division. 81/01/19 38pp 07502 077

O. Inspection reports, IE Bulletins & correspondence

B101270117 Ack receipt of IE Insp Repts 50-445/80-18 & 50-446/80-18 M proprietary info
GARY, R. J. Texas Utilities Generating Co. 80/10/15 1p 07547 21

B101100247 Discusses IE Insp Repts 50-445/80-23 & 50-446/80-23 on B01009 & forwards notice of violation Repts to be issued in near future
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/10/16. 2pp. 07443: 221.

--B101100251 Notice of violation from Insp on B01008 Noncompliance no welds connecting stiffener plates to balance of Assembly M-29 were not complete penetration welds.
" Region 4, Dallas, Office of the Director. 80/10/16. 1p.
07445 223

B101270114 Ack receipt of IE Insp Repts 50-445/80-20 & 50-446/80-20 No proprietary info
GARY, R. J. Texas Utilities Generating Co. 80/11/12 1p. 07549 01

B101100059 Forwards IE Insp Repts 50-445/80-23 & 50-446/80-23 on B01001-31.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/11/19 2pp 07443: 019.

00563 IE Insp Repts 50-445/80-23 & 50-446/80-23 on 801001-103t compliance noted failure to follow procedures for making penetration welds
LOR, R G , CROSSMAN, W A Region 3, Chicago, Office of the Director 80/11/19 7pp 07443 021

171 Forwards IE Insp Repts 50-445/80-20 & 50-446/80-20 on 80/06/06 No noncompliance noted
HALL, R E Region 4, Dallas, Reactor Construction & Engineering Branch 80/11/19 2pp 07443 008

00178 IE Insp Repts 50-445/80-28 & 50-446/80-28 on 801103-06 No compliance noted Major areas inspected const activities & plans for RCPO piping
LOR, R G , CROSSMAN, W A Region 3, Chicago, Office of the Director HALL, R E Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/19 3pp 07443 010

006 Responds to IF Bulletin 80-20, "Failures of Westinghouse 12 Spring Return to Neutral Control Switches" - corrective actions scheduled for 811201 completion contact will be required & auxiliary relay for alarm added
J Texas Utilities Generating Co 80/11/19 2pp 242

52 Ack receipt of IE Insp Repts 50-445/80-24 & 50-446/80-24 No entry info
J Texas Utilities Generating Co 80/11/19 1p 07547 292

47 Ack receipt of IE Insp Repts 50-445/80-25 & 50-446/80-25 No entry info
J Texas Utilities Generating Co 80/12/03 1p 07547 259

82 Forwards IE Info Notice 80-44, "Actuation of ECCB in Isolation Mode While in Hot Shutdown" No written response required
T, K V Region 4, Dallas, Office of the Director 80/12/16 7391 200

16 Ack receipt of 801112 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/80-23 & 50-446/80-23
H C Region 4, Dallas, Reactor Construction & Engineering Branch 80/12/23 1p 07443 229

0726 Responds to NRC 801016 ltr re violations noted in IE Insp Repts 50-445/80-23 & 50-446/80-23 Corrective actions completed & fabrication drawings reviewed
J Texas Utilities Generating Co 80/11/12 3pp 226

32 Ack receipt of 801118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/80-20 & 50-446/80-20
H C Region 4, Dallas, Reactor Construction & Engineering Branch 80/12/23 1p 07443 229

0738 Responds to NRC 801021 ltr re violations noted in IE Insp Repts 50-445/80-20 & 50-446/80-20 Corrective actions completed & flow diagrams revised to reflect actual surtifier/spray valve arrangement
J Texas Utilities Generating Co 80/11/18 3pp 230

72 Forwards IE Insp Repts 50-445/80-26 & 50-446/80-26 on 80/13-14, 18-20 & 24-25 No noncompliance noted
H C Region 4, Dallas, Reactor Construction & Engineering Branch 80/12/23 2pp 07489 308

0077 IE Insp Repts 50-445/80-26 & 50-446/80-26 on 801103-07, 18-20 & 24-25 No noncompliance noted Major areas inspected const activities including reactor vessel/instrumentation components & sys
SMAN, W A , STEWART, R C Region 4, Dallas, Office of the Director 80/12/23 6pp 07489 310

19 Forwards IE Info Notice 80-43, "Failures of Continuous Water Monitor for Baram Discharge Vol at Dresden Unit 2" No response required
T, K V Region 4, Dallas, Office of the Director 80/12/08 7391 031

21 Requests documentation of maint records re pressurization insp & of snubbers due to problems w/inoperable & incorrectly installed snubbers. Preservice exam should be of snubbers listed in STB Tables 3 7-4a & 3 7-4b
R L Assistant Director for Licensing 81/01/14 3pp

S Reportable occurrences, LERS & related correspondence

8101205246 Interim deficiency rept re r/f deficiency of component supports associated w/auxiliary piping sys diesel generators. Initially reported 800926 Evaluation will be completed by 810731
GARY, R J Texas Utilities Generating Co 81/01/12 1p 07487 091

8101206233 Interim deficiency rept re unauthorized field mods to 1111-Mux concrete anchor bolts. Initially reported 801001 Bolts have not been modified in unauthorized manner Follow-up rept will be submitted by 810417
GARY, R J Texas Utilities Generating Co 81/01/12 2pp 07487 089

COCKET 50-447 469549-238, GENERAL, ELECTRIC CO

A Application/construction stage documents & correspondence

8101190589 Grants 6-month extension to preliminary design approval. POA-1 pending development & implementation of new extension guidelines
EISENHUT, O C Division of Licensing 80/12/31 3pp 07475 012

COCKET 50-448 DOUGLAS POINT NUCLEAR STATION, UNIT 1

C Adjudicatory correspondence

8101090379 Response raising no objection to applicant 801224 motion to withdraw CP applications No determination made as to conditions of withdrawal Certificate of Svc encl
BARTH, C A Hearing Branch 3 81/01/07 3pp 07422 240

8101206057 Order granting applicant 801224 motion to withdraw application for CPs w/o qualifying terms or conditions Certificate of Svc encl
BLIERS, E S Atomic Safety and Licensing Board Panel 81/01/14 4pp 07486 322

COCKET 50-449 DOUGLAS POINT NUCLEAR STATION, UNIT 2

C Adjudicatory correspondence

8101090379 Response raising no objection to applicant 801224 motion to withdraw CP applications No determination made as to conditions of withdrawal Certificate of Svc encl
BARTH, C A Hearing Branch 3 81/01/07 3pp 07422 240

8101206057 Order granting applicant 801224 motion to withdraw application for CPs w/o qualifying terms or conditions Certificate of Svc encl
BLIERS, E S Atomic Safety and Licensing Board Panel 81/01/14 4pp 07486 322

COCKET 50-452 GREENWOOD ENERGY CENTER, UNIT 2

A Application/construction stage documents & correspondence

8012100052 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTOW, J H Division of Rules and Records 80/11/21 3pp 07222 211

--8008050201 Amends 800627 memo re manpower costs for CP review Associated contractual costs are \$124,000
BERKOW, K H Management Analysis Branch 80/07/29 1p 03078 180

--8011240002 Submits CP review costs incurred by various program ofcs from filing of application to date of withdrawal
HULLOWAY, C J License Fee Management Branch 80/11/10 1p 03749 245

--8011240224 Requests billing of util for fees for review of CP application withdrawn on 800709 Ofc of Administration should be notified when total amount is collected
MILLER, W D License Fee Management Branch 80/11/10 1p 03749 334

--8012100135 Forwards IE cost data worksheets reflecting prof manhours expended & associated costs in reviewing CP application for facilities info encompasses 750101-800714
DOUGLASS, L J Resource Management Branch 80/08/15 3pp

B01120143 Informs that 145.5 prof manhours were expended on joint CP review of facilities
MCKINNEY, R E ACRS - Advisory Committee on Reactor Safeguards.
80/06/04 1p

--B01200151 Informs that prof manhours expended by ASLB re CP application have not been recorded Proceeding was contested
LAZOR, R M Atomic Safety and Licensing Board Panel. 80/07/29 1p

--B01200165 Informs that no prof manhours were expended in connection w/ sua sponte review of CP application for facilities
ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel
80/07/29 1p

DOCKET 80-453 GREENWUDD ENERGY CENTER, UNIT 3

A Application/construction stage documents & correspondence

B01200002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTCH, J H Division of Rules and Records 80/11/21 3pp
07222 211

--B008050201 Amends 000627 memo reorrower costs for CP review.
Associated contractual costs are \$124,000
BERNARD, H H Management Analysis Branch 80/07/29 1p
03078 180

--B011240002 Submits CP review costs incurred by various program ofcs from filing of application to date of withdrawal.
HOLLANDWAY, S J License Fee Management Branch 80/11/10 1p
03745 245

--B011240024 Requests billing of util for fees for review of CP application withdrawn on 800709 Ofc of Administration should be notified when total amount is collected.
MILLER, M D License Fee Management Branch 80/11/10 1p
03745 334

--B01200135 Forwards IE cost data worksheets reflecting prof manhours expended & associated costs in reviewing CP application for facilities Info encompasses 790101-800714
O'NEILL, L J Resource Management Branch 80/08/15 3pp

--B01200143 Informs that 145.5 prof manhours were expended on joint CP review of facilities
MCKINNEY, R E ACRS - Advisory Committee on Reactor Safeguards
80/08/04 1p

--B01200151 Informs that prof manhours expended by ASLB re CP application have not been recorded Proceeding was contested
LAZOR, R M Atomic Safety and Licensing Board Panel 80/07/29 1p

--B01200165 Informs that no prof manhours were expended in connection w/ sua sponte review of CP application for facilities
ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel
80/07/29 1p

DOCKET 80-454 BAYON STATION, UNIT 1

A Application/construction stage documents & correspondence

B01220466 Ltr to all power reactor licensees & applicants forwarding summary of B01121 meeting re implementation of guidance for unresolved safety issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D G Division of Licensing 80/11/26 8pp

B011000002 Notification of case load forecast panel B0106-08 meetings w/ util at sites to update NRC estimate of const completion date
MORAN, C W Licensing Branch 1 80/12/24 3pp 07443 061.

B01130476 Requests addl info re OL applications for facilities
Specific requests in encl are ninth set of round one questions
TEDESCO, R L Assistant Director for Licensing. 81/01/02 23pp.
07454 070

B01160543 Forwards request for addl info re first set of second round questions on OL application
TEDESCO, R L Assistant Director for Licensing 81/01/02 18pp.
07471 163.

B01220359 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 last 111 A 2
DELGEMORE, L D Commonwealth Edison Co 81/01/19 1p

--B01220371 Offsite Dose Calculation Sys Meteorological Monitoring
Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants, Revision 2
DELGEMORE, J C Commonwealth Edison Co 80/07/31 130pp

--B01220379 "Study of Low Level Dispersion Over Northern IL."
Murray & Trettel, Inc 74/06/30 106pp

F Security, medical, emergency & fire protection plans

B01090397 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B010102 & to applicants as part of FEAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

B01160572 Notifies that guard training & qualification plans are required until B00811 etc. is acceptable
REYNOLDS, D B J Licensing Branch 1 80/12/30 2pp 07471 201

D Adjudicatory correspondence

B01130008 Memorandum & order admitting DeKalb Area Alliance for Responsible Energy & Mississippi Alliance for Environment Contentions 1, 2, 2a, 3, 4, 6, 7, 8 & 9 & denying Contention 5
MILLER, M E Atomic Safety and Licensing Board Panel 80/12/14 3pp 07440 262.

--B01130019 Order admitting Rockford League of Women Voters Contentions 2, 5, 6, 10, 14, 16, 17, 19, 20, 63, 66, 78, 80, 81, 83, 90, 93, 97, 100, 102, 117, 119, 120, 122, 126, 129, 134, 137, 141, 144 & 146 & denying other contentions Certificate of Svc encl
MILLER, M E, COLLIER, F. CALLIHAN, O Atomic Safety and Licensing Board Panel 80/12/19 23pp 07448 265

B01200187 Advises that B01121 petition on behalf of Rockford League of Women Voters will be treated as request under 10CFR2.206. Request (d) for halt of const is denied Public health & safety considerations not jeopardized
EISENHUT, R R Office of Nuclear Reactor Regulation, Director 80/12/22 3pp. 07487 093

--B01200191 Notice of Rockford League of Women Voters request for action under 10CFR2.206 & 10CFR2.202
EISENHUT, R R Office of Nuclear Reactor Regulation, Director 80/12/22 1p. 07487 101

--B01200195 Discusses B01121 petition on behalf of Rockford League of Women Voters requesting proceeding per 10CFR2.202 Offers assistance & suggestions in preparing response. Draft acknowledgment ltr encl
MURRAY, J P. Rulemaking & Enforcement Division. 00/12/02. 4 07487 102

B01030416 Renewal Rockford League of Women Voters B01102 request immediate const shutdown Cites NRC B01222 refusal as illegal & grossly negligent Gives notice that if NRC does not reply by B01116, relief will be sought from courts.
CHERRY, M M Cherry, M. M /Cherry, Flynn & Kanter 80/12/30 07380 189

B01160732 Order granting extension until B01031 for Commission consideration of Director's partial denial of Rockford League of Women Voters petition Certificate of Svc encl
CHILKOT, S J Office of the Secretary of the Commission 81/01/14 2pp 07472 061.

B01260347 Requests that Rockford Register Star newspaper be placed on list for facility proceeding Certificate of Svc encl.
MORRIS, C E Affiliation Unknown. 81/01/14. 3pp. 07955 105.

B01270323 Forwards B01219 memorandum & order re admissibility of revised contentions filed by Intervenor League of Women Voters, Rockford League of Women Voters Contention 19 also encl. 140 encls
CHRISTENBURY, T Office of the Executive Legal Director. 81/01/14 07546 073

DOCKETED ITEMS

P. Operating license stage documents & correspondence

B101090001 Forwards Revision 15 pages to CE-1-A, OA program topical report Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
AUEL, J. S. Commonwealth Edison Co 81/01/02 1p

--B101090005 Revision 15 pages to OA program topical report
* Commonwealth Edison Co CE-1-A R15 81/01/02 57pp.

Q. Inspection Reports, IE Bulletins & correspondence

B101050247 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/50 2pp

B101050462 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/06 2pp.

B101050530 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Valve at Dresden Unit 2." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/05 2pp

B101070105 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/16 1p 07415 024

B101130667 Responds to B01114 ltr re IE Bulletin 80-23 No Valcor solenoid valves V70900-21-1 or V70900-21-3 are in use at LaSalle County Station Rept addressing affected valves at Byron & Braidwood Stations to be submitted by B10212
RAUSCH, T. J. Commonwealth Edison Co 80/12/29 2pp 07454 033

B101190796 Confirms B10109 meeting to review insp findings re electrical const work at site
KEPPLER, J. G. Region 3, Chicago, Office of the Director 81/01/06 1p 07472, 285

B101200528 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." LaSalle County Station contains 139 safety-related valves cast by Malcolm & mfg by Anchor-Darling Valve Co Valves will be replaced
RAUSCH, T. J. Commonwealth Edison Co 81/01/06 2pp 07487 046

B101280613 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount, Inc. pressure transmitters Rosemount Model 1152 transmitters used could not be exposed to input pressures resulting in anomalous output signals
RAUSCH, T. J. Commonwealth Edison Co 81/01/08 2pp 07557 308

B101280636 Submits supplemental response to IE Bulletin 80-20 Add'l info of Westinghouse Type W-2 spring return to neutral control switches identified Initial response to bulletin unchanged. List of add'l switches & applications encl
RAUSCH, T. J. Commonwealth Edison Co 81/01/09 3pp 07557 305.

B101260698 Ack receipt of B01211 ltr informing NRC of stops taken to correct violations noted in IE Insp Repts 80-454/B0-09, 50-455/80-08, 50-456/80-04 & 50-457/80-04
FIORELLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 81/01/12 1p 07531 177

--B101260707 Responds to NRC B00711 ltr re violations noted in IE Insp Repts 50-454/80-09, 50-455/80-08, 50-456/80-04 & 50-457/80-04 Completion of supplier study & util technical assessment expected by B10215
AUEL, J. S. Commonwealth Edison Co 80/12/11 1p 07531 178

B101270097 Immediate action ltr re B01201 & B10109 meetings held to discuss recent insp findings Util will discontinue installation of Class IE cables until listed DA/OC programmatic actions completed
KEPPLER, J. G. Region 3, Chicago, Office of the Director 81/01/13 2pp 07546 179

DOCKET 50-455 BYRON STATION, UNIT 2

A. Application/construction stage documents & correspondence

B101200466 Ltr to all power reactor licensees & applicants Forward survey of B01112 meeting re implementation of guidance for Unresolved Safety Issue A 12, "Potential for Low Fracture Toughness & Low-Cycle Fatigue on Component Supports"
EISENHUT, D. G. Division of Licensing 80/11/26 8pp

B101100007 Notification of baseload forecast panel (B10106-08) next update at sites to update NRC estimate of const completion date
ROSEN, C. H. Licensing Branch 1 80/12/21 3pp 07443 051

B101130426 Requests add'l info re OL applications for facilities Specific requests in encl are ninth set of round and questions
TEDESCO, R. L. Assistant Director for Licensing 81/01/02 13pp 07454 070

B101160543 Forwards request for add'l info re first set of second questions on OL application
TEDESCO, R. L. Assistant Director for Licensing 81/01/02 19pp 07471 163

B101220385 Forwards offsite dose calculation sys description per meteorological data requirements in HLWFO-0737 Test 131 A 2
DELOE, G. E. L. D. Commonwealth Edison Co 81/01/19 1p

--B101220374 "Offsite Dose Calculation Sys Meteorological Monitoring Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants." Revision 2
COLLETT, J. C. Commonwealth Edison Co 80/07/31 130pp

--B101220379 "Study of Low Level Dispersion Over Northern Ill."
* Hurry & Trettel, Inc 74/06/30 106pp

F. Security, medical, emergency & fire protection plans

B101090087 Ltr to all licensees of operating reactor plants, CP Inc & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FEAR
EISENHUT, D. G. Division of Licensing 80/11/13 2pp

B101160977 Notifies that guard training & qualification plan as by util B00811 ltr is acceptable
YOUNGBLOD, B. J. Licensing Branch 1 80/12/30 2pp 07471 21

G. Adjudicatory correspondence

B101130068 Memorandum & order admitting DeKalb Area Alliance for Responsible Energy & Mississippi Alliance for Environment B00509 Contentions 1, 2, 2a, 3, 4, 6, 7, B & 4 & denying Contentions 5.
MILLER, M. E. Atomic Safety and Licensing Board Panel 80/12/13 3pp 07448 262.

--B101130019 Order admitting Rockford League of Women Voters Contn 2, 5, 8-10, 14, 16, 17, 19, 20-63, 66-76, 80, 81, 83-90, 95, 97-100, 102-117, 119, 120, 122-126, 129, 131-137, 141-144 & 146 & denying other contentions Certificate of Disencl.
MILLER, M. E. COLLIER, F. COLLIHAN, D. Atomic Safety and Licensing Board Panel 80/12/19 23pp 07448 263

B101200187 Advises that B01171 petition on behalf of Rockford League of Women Voters will be treated as request under 10CFR2.204 Request (d) for halt of const is denied Public health & safety considerations not jeopardized
DEWICH, W. R. Office of Nuclear Reactor Regulation, Director 80/12/22 3pp 07487 070

--B101200191 Notice of Rockford League of Women Voters request action under 10CFR2.204 & 10CFR2.202
DEWICH, W. R. Office of Nuclear Reactor Regulation, Director 80/12/22 1p 07487 101.

--B101200195 Discusses B01171 petition on behalf of Rockford League of Women Voters requesting proceeding per 10CFR2.202 Offers assistance & suggestions in preparing response Brief

B10150414 Reopens B10101 League of Women Voters B01102 request for immediate const shutdown Cites WEC B01222 refusal as illegal & grossly negligent. Demands ensure that if NRC does not reply by B10116, relief will be sought from courts.
CHERRY, R. M. Cherry, R. M. & Cherry, R. M. & Cherry, R. M. B01/12/30 3pp 07380 168

B10150732 Order granting extension until B10131 for Commission consideration of Director's partial denial of Rockford League of Women Voters petition Certificate of Svc encl
CHILK, S. J. Office of the Secretary of the Commission B1/01/14 2pp 07472 051

B10150947 Requests that Rockford Register Star newspaper be placed on sus. list for facility preceding Certificate of Svc encl
MORRIS, C. E. Affiliation Unknown B1/01/14 3pp 07555 105

B10127023 Forwards B01119 Memorandum & order re admissibility of revised contentions filed by Intervenor League of Women Voters Rockford League of Women Voters Contention 19 also encl W/O encl
CHRISTENSEN, E. Office of the Executive Legal Director B1/01/22 1p 07546 073

F. Operating license stage documents & correspondence

B101090001 Forwards Revision 15 pages to CE-1-A, QA program topical rept Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
APEL, J. S. Commonwealth Edison Co B1/01/02 1p

--B101090005 Revision 15 pages to QA program topical rept
* Commonwealth Edison Co CE-1-A R15 B1/01/02 57pp

G. Inspection reports, IE Bulletins & correspondence

B101050241 Forwards IE Info Notice B0-78, "Cracking on Charging Pump Casing Cladding" No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director B0/10/30 2pp

B101050462 Forwards IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director B0/11/05 2pp

B101050530 Forwards IE Info Notice B0-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vial at Dresden Unit 2" No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director B0/12/05 2pp

B101050105 Forwards IE Info Notice B0-44, "Activation of ECCS in Reirculation Mode While in Hot Shutdown" No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director B0/12/16 1p

B101100627 Responds to B01114 ltr re IE Bulletin B0-23 No Valve orificoid valves V70900-21-1 or V70900-21-3 are in use at LaSalle County Station Repl addressing affected valves at Byron & Braidwood Stations to be submitted by B10212
RAUSCH, T. J. Commonwealth Edison Co B0/12/29 2pp

B101100796 Confirms B10109 meeting to review insp findings re electrical const work at site
KEPPLER, J. G. Region 3, Chicago, Office of the Director B1/01/06 1p 07472 285

B101050528 Responds to IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." LaSalle County Station contains 133 safety-related valves cast by Malcolm & mfg by Anchor-Burling Valve Co. Valves will be replaced
RAUSCH, T. J. Commonwealth Edison Co B1/01/06 2pp

B101280513 Responds to IE Bulletin B0-16 re potential misapplication of Rosemount, Inc. pressure transmitters Rosemount Model 1152 transmitters used could not be exposed to input pressures resulting in anomalous output signals
RAUSCH, T. J. Commonwealth Edison Co B1/01/08 2pp 07557 308

B101280636 Submits supplemental response to IE Bulletin B0-20 Addl use of Westinghouse Type W-2 spring return to neutral control switches identified. Initial response to bulletin unchanged. List of addl switches & applications encl
RAUSCH, T. J. Commonwealth Edison Co B1/01/09 3pp 07557 305

B101280636 Addl receipt of B01211 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts B0-454/B0-09, B0-455/B0-09, B0-456/B0-04 & B0-457/B0-04
FIORILLI, J. Region 3, Chicago, Reactor Construction & Engineering Support Branch B1/01/12 1p 07531 177

--B101280737 Responds to NRC B00711 ltr re violations noted in IE Insp Repts B0-454/B0-09, B0-455/B0-09, B0-456/B0-04 & B0-457/B0-04 Completion of supplier study & util technical assessment expected by B10215
APEL, J. S. Commonwealth Edison Co B0/12/11 1p 07931 170

B101270177 Immediate action ltr re B01231 & B10109 meetings held to discuss recent insp findings Util will discontinue installation of Class IE cables until listed OAO/C programmatic actions completed
KEPPLER, J. G. Region 3, Chicago, Office of the Director B1/01/12 2pp 07546 179

SECRET B0-456 BRAIDWOOD STATION, UNIT 1

A. Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENBUD, D. O. Division of Licensing B0/11/26 8pp

B101100507 Notification of caseload forecast panel B10106-08 meeting w/Util at sites to update NRC estimate of const completion date
ROCK, C. W. Licensing Branch 1 B0/12/24 3pp 07443 061

B101130426 Requests addl info re CL applications for facilities. Specific requests in encl are ninth set of round one questions
TEDESCO, R. L. Assistant Director for Licensing B1/01/02 23pp 07454 070

B101160541 Forwards request for addl info re first set of second round questions on CL applications
TEDESCO, R. L. Assistant Director for Licensing B1/01/02 10pp 07471 163

B101220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task 111 A 2
DELGECROE, L. Q. Commonwealth Edison Co B1/01/19 1p

--B101220374 "Offsite Dose Calculation Sys Meteorological Monitoring Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants." Revision 2
QUIDEN, J. C. Commonwealth Edison Co B0/07/31 130pp

--B101220379 "Study of Low Level Dispersion Over Northern IL."
* Murray & Irattel, Inc 74/05/30 106pp

F. Security, medical, emergency & fire protection plans

B101070387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENBUD, D. O. Division of Licensing B0/11/13 2pp

B101000629 Notifies that guard training & qualification program required by licensee B03811 ltr is acceptable
YOUNGBLOOD, J. J. Licensing Branch 1 B0/12/30 2pp 07486 133

F. Operating license stage documents & correspondence

B101090001 Forwards Revision 15 pages to CE-1-A, QA program topical rept Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
APEL, J. S. Commonwealth Edison Co B1/01/02 1p

--B101090005 Revision 15 pages to QA program topical rept
* Commonwealth Edison Co CE-1-A R15 B1/01/02 57pp

G. Inspection reports, IE Bulletins & correspondence

B101050249 Forwards IE Info Notice B0-78, "Cracking in Charging Pump Casing Cladding" No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director B0/10/30 2pp

Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
J G Region 3, Chicago, Office of the Director 80/11/06

Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Control for Steam Discharge Valve at Dresden Unit 2" No response required
J G Region 3, Chicago, Office of the Director 80/12/09

Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
J G Region 3, Chicago, Office of the Director 80/12/16

Ack receipt of 801204 ltr informing IIRC of steps taken to correct violations noted in IE Insp Repts 80-456/80-12 & 80-457/80-11
J G Region 3, Chicago, Reactor Construction & Engineering Branch 80/12/27 2pp 07443 303

01 Responds to NRC 801029 ltr re violations noted in IE Insp Repts 80-456/80-12 & 80-457/80-11 Corrective actions w/open ends sealed & surveillance performed
S Commonwealth Edison Co 80/12/04 5pp 07443 305

Responds to 801114 ltr re IE Bulletin 80-23 No Valcor valves V70900-21-1 or V70900-21-3 are in use at County Station Rept addressing affected valves at Braided Stations to be submitted by 810212
J Commonwealth Edison Co 80/12/27 2pp

Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." LaSalle County Station contains 138 related valves cast by Malcolm & mfg by Anchor-Valve Co Valves will be replaced
J Commonwealth Edison Co 81/01/06 2pp

Responds to IE Bulletin 80-16 re potential misapplication of Rosemount Model 1152 transmitters used could not be exposed to input pressures resulting in anomalous output signals
J Commonwealth Edison Co 81/01/09 2pp 07557 308

Submits supplemental response to IE Bulletin 80-20 Addl use of phase type H-3 spring return to neutral control identified. Initial response to bulletin unchanged addl switches & applications incl
J Commonwealth Edison Co 81/01/09 3pp 07557 305

Ack receipt of 801211 ltr informing IIRC of steps taken to correct violations noted in IE Insp Repts 80-454/80-04, 80-456/80-04 & 80-457/80-04
J G Region 3, Chicago, Reactor Construction & Engineering Branch 81/01/12 1p 07531 177

07 Responds to NRC 800711 ltr re violations noted in IE Insp Repts 80-454/80-04, 80-455/80-08, 80-456/80-04 & 80-457/80-04
tion of supplier study & util technical assessment led by 810219
S Commonwealth Edison Co 80/12/11 1p 07531 178

457 BRAIDWOOD STATION, UNIT 2

tion/construction stage documents & correspondence

Ltr to all power reactor licensees & applicants forwarding of 801112 meeting re implementation of guidance for Reactor Safety Issue A-12, "Potential for Low Fracture Stress & Lamellar Tearing on Component Supports"
D O Division of Licensing 80/11/26 8pp

Notification of newload forecast panel 810106-CB meeting at sites to update NRC estimate of const completion
Licensing Branch 1 80/12/24 3pp

Requests addl info re CL applications for facilities requests in encl are ninth set of round one
R L Assistant Director for Licensing 81/01/02 27pp

Forwards request for addl info re first set of second round of an CL application
R L Assistant Director for Licensing 81/01/02 18pp

8101200293 Forwards Offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Iss1
III A 2
DELESEECELEL D Commonwealth Edison Co 81/01/19 1p

8101200374 Offsite Dose Calculation Sys Meteorological Monitoring, Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants, Revision 2
COLBEN J C Commonwealth Edison Co 80/07/31 130pp

8101200379 Study of Low Level Dispersion Over Northern IL
* Murray S Tippet, Inc 80/08/30 186pp

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810702 & by applicants as part of FRAI
EISENBUT, D G Division of Licensing 80/11/19 2pp

8101200029 Notifies that joint training & qualification program revised by licensee 800811 ltr is acceptable
YOGI, DELESEECELEL D J Licensing Branch 1 80/12/20 2pp 07486 153

P Operating license stage documents & correspondence

8101070001 Forwards Transmittal 15 pages to CE-1-A-A program topical report Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certification
ASSEL, J S Commonwealth Edison Co 81/01/02 1p

8101090005 Revision 15 pages to QA program topical report
* Commonwealth Edison Co CE-1-A-R19 81/01/02 57pp

Q Inspection reports, IE Bulletins & correspondence

8101050244 Forwards IE Info Notice 80-58, "Clanking in Charging Pump Casing Cladding" No response required
HEPPLER, J G Region 3, Chicago, Office of the Director 80/10/20 2pp

8101050462 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
HEPPLER, J G Region 3, Chicago, Office of the Director 80/11/06 2pp

8101050530 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Control for Steam Discharge Valve at Dresden Unit 2" No response required
HEPPLER, J G Region 3, Chicago, Office of the Director 80/12/05 2pp

8101070105 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
HEPPLER, J G Region 3, Chicago, Office of the Director 80/12/16 1p

810100294 Ack receipt of 810204 ltr informing IIRC of steps taken to correct violations noted in IE Insp Repts 80-456/80-12 & 80-457/80-11
FICRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/27 2pp 07443 303

8101100301 Responds to NRC 801029 ltr re violations noted in IE Insp Repts 80-456/80-12 & 80-457/80-11 Corrective actions w/open ends sealed & surveillance performed
ASSEL, J S Commonwealth Edison Co 80/12/04 3pp 07443 305

8101130667 Responds to 801114 ltr re IE Bulletin 80-23 No Valcor solenoid valves V70900-21-1 or V70900-21-3 are in use at LaSalle County Station Rept addressing affected valves at Braided Stations to be submitted by 810212
RAUSCH, T J Commonwealth Edison Co 80/12/24 2pp

8101200578 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." LaSalle County Station contains 138 safety-related valves cast by Malcolm & mfg by Anchor-Valve Co Valves will be replaced
RAUSCH, T J Commonwealth Edison Co 81/01/06 2pp

8101280613 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount, Inc pressure transmitters Rosemount Model 1152 transmitters used could not be exposed to input pressures resulting in anomalous output signals
RAUSCH, T J Commonwealth Edison Co 81/01/08 2pp

80120657 Submits supplemental response to IE Bulletin 80-20. Use of Westinghouse Type W-2 spring return to neutral control switches identified. Initial response to bulletin unchanged. List of add'l switches & applications encl.
BRAPER, E. L. Gulf States Utilities Co. 80/01/09 3pp.

80120698 Ack receipt of 80/0111 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-454/80-09, 80-455/80-09, 80-456/80-09, 80-457/80-09.
FIGURE, J. L. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/01/10 1p

80120707 Responds to 80/0111 ltr re violations noted in IE Insp Repts 80-454/80-09, 80-455/80-09, 80-456/80-09 & 80-457/80-09. Completion of supplier study & util technical assessment expected by 80/0215.
ADEL, J. S. General Electric Edison Co. 80/12/11 1p

DOCK#1 50-459 RIVER BEND STATION, UNIT 1

A. Application/construction stage documents & correspondence

80120466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports".
EISENHUT, D. G. Division of Licensing 80/11/26 8pp

80121597 Advises that no new items have been discovered which would require IEEE-303 environ qualification testing, per 801205 ltr.
BRAPER, E. L. Gulf States Utilities Co. 80/01/21 1p 07548 092.

F. Security, medical, emergency & fire protection plans

80109038 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 801012 & by applicants as part of FSAR.
EISENHUT, D. G. Division of Licensing 80/11/13 2pp

801214037 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUDER, J. L. Division of Rules and Records 80/12/16 1p 07461 335

G. Financial information

80120640 Forwards loan commitment agreement which includes conditions required for funds loaned by REA, per 801003 ltr.
BRAPER, E. L. Gulf States Utilities Co. 80/01/14 18pp 07183 001

H. Inspection reports, IE Bulletins & correspondence

80121670 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes." Final response scheduled for 801124, pending investigation by vendor.
BRAPER, E. L. Gulf States Utilities Co. 80/11/03 1p, 07488 244

801080401 Forwards IE Investigation Rept 80-458/80-15 on 801029-31.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/11/18, 2pp 07421 313

80108067 IE Investigation Rept 80-458/80-11 on 801029-31. No noncompliances noted. Major areas discussed. 801021 allegation that upper mgmt engineering supervisors lowered quality of work by creating difficult engineering schedules.
HEPR, R. X., SEYFRIT, K. V. Region 4, Dallas, Office of the Director
MAITIN, L. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/17 11pp 07421 315

801210677 Submits supplemental response to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes." GE will perform design review during First Quarter 1981.
BRAPER, E. L. Gulf States Utilities Co. 80/12/02 2pp, 07468 245.

801100122 Ack receipt of 80/0910 & 1103 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 80-454/80-09.
FIGURE, J. L. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/09 1p 07443 002

80111177 Responds to 80/01003 ltr re violations noted in IE Insp Rept 80-458/80-09. Lists not weather requirements to be imposed. Correlation testing will be performed on all Category 1 concrete placements w/ compliance.
BRAPER, E. L. Gulf States Utilities Co. 80/11/03 3pp 07443 003

80108017 Forwards IE Info Notice 80-40, "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2." No response required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/12/08 1p 07591 046

80121045 Forwards IE Insp Rept 80-458/80-12 on 801118-21 & notice of violation.
FIGURE, J. L. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/08 2pp 07419 301

80121058 Notice of violation from Insp on 801118-21.
Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/05 2pp 07489 303

80121075 IE Insp Rept 80-458/80-12 on 801118-21 Noncompliance note: insufficient lighting of concrete placement & water/cement ratio exceeded max allowable.
TAPPA, J. L., MAITIN, L. E. Region 4, Dallas, Reactor Construction & Engineering Support Branch. CRUSSMAN, H. A. Region 4, Dallas, Office of the Director 80/12/09 3pp 07489 305

801190388 Forwards IE Info Notice 80-45, "Potential Failure of BWV Backup Manual Steam Capability." No response required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/12/17 1p 07452 090

801190387 Forwards IE Bulletin 80-29, "Operating Problems W/ Targis Rock Safety-Relief Valves at BWRs." No response required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/12/19 1p 07449 139

I. Reportable occurrences, IERs & related correspondence

801090204 PW-1V-80-41 on 801230, util QA manager notified Region 4 that step work order had been issued on Category 1 work. Order resulted from discovery that incoming drawings had not been processed by document control since 801106.
JEACH, A. B., HALL, R. E. Region 4, Dallas, Office of the Director 80/12/31 1p 07442 072

DOCK#1 50-459 RIVER BEND STATION, UNIT 2

A. Application/construction stage documents & correspondence

80120466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports".
EISENHUT, D. G. Division of Licensing 80/11/26 8pp

801270687 Advises that no new items have been discovered which would require IEEE-303 environ qualification testing, per 801205 ltr.
BRAPER, E. L. Gulf States Utilities Co. 80/01/21 1p, 07548 092

F. Security, medical, emergency & fire protection plans

80109038 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 801012 & by applicants as part of FSAR.
EISENHUT, D. G. Division of Licensing 80/11/13 2pp

801114037 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUDER, J. L. Division of Rules and Records 80/12/16 1p 07461 335

G. Inspection reports, IE Bulletins & correspondence

801210670 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes." Final response scheduled for 801124, pending investigation by vendor.
BRAPER, E. L. Gulf States Utilities Co. 80/11/03 1p 07488 244

801210672 Submits supplemental response to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes." GE will perform design review during First Quarter 1981.
BRAPER, E. L. Gulf States Utilities Co. 80/12/02 2pp 07488 245

B101055617 Forwards IE Info Notice 80-41, "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2 " No response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/08
1p 07391 046

B101130388 Forwards IE Info Notice 80-41, "Potential Failure of BWR Startup Manual Steam Capability " No response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/17
1p 07452 070

B101130087 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rod Safety-Relief Valves at NIMs " No response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/19
1p 07449 139

S Reportable occurrences, LIRs & related correspondence

B101095204 PNO-IV-80-41 on B01170, utfl OK manager notified Region 4 that stop work order had been issued in Category 1 Work Order resulted from discovery that incoming drawings had not been processed by document control since B01106
BEACON, A B, HALL, K E Region 4, Dallas, Office of the Director 80/12/01 1p 07442 272

SECRET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports "
EISENHUT, D G Division of Licensing 00/11/26 8pg

F Security, medical, emergency & fire protection plans

B101096387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pg

Q Inspection reports, IE Bulletins & correspondence

B101060085 Forwards supplemental response to IE Bulletin 79-02, Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "
MAZUR, D W Washington Public Power Supply System 80/11/13 3pg 07399 119

B101050510 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2 " No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/12/05 1p 07390 277

B101150837 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown " No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/12/16 1p 07308 001

B101300583 Ack receipt of B01212 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-460/80-13 & 50-513/80-13
SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 81/01/26 1p 07585 041

--B101300588 Responds to NRC B01121 ltr re violations noted in IE Insp Repts 50-460/80-13 & 50-513/80-13 Corrective actions OK personnel will provide procurement controls for rail substitutions
MAZUR, D W Washington Public Power Supply System 80/12/12 4pg 07586 042

--B101300573 Forwards IE Insp Repts 50-460/80-13 & 50-513/80-13 on B01020-23 & notice of violation
SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/11/21 2pg 07586 046

--B101300598 Notice of violation from Insp on B01020-23
* Region 5, San Francisco, Office of the Director 80/11/21 1p 07585 048

B1011111 IE Insp Repts 50-460/80-13 & 50-513/80-13 on B01020-23 Non-compliance with failure to provide adequate procurement controls for parts to be used within containment
MAZUR, D W, MAZUR, D F KAR3UT, P H Region 5, San Francisco, Office of the Director 80/11/21 10pg 07586 049

S Reportable occurrences, LIRs & related correspondence

B101230230 Part 21 report re failure to provide proper Control Component limit values supporting 21 part flow when in closed position
Caused by valve failure Affected licensees notified & selection of alternative method under way
JAN04, J H "Nuclear Analysis Co 81/01/07 2pg 07308 001

SECRET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports "
EISENHUT, D G Division of Licensing 80/11/26 8pg

B101060059 Forwards preliminary CR review schedule for facility Requests identification of blind reviewers & contact & mailing address of contracted technical assistance
TEDESCO, R L Assistant Director for Licensing 80/12/16 3pg 07399 123

B101100016 Informs of licensing milestones for facility & staffing arrangements for project Preliminary review schedule encl
TEDESCO, R L Assistant Director for Licensing 80/12/16 1pg 07445 155

B101100019 Requests performance of ultimate reactivity analysis of MCR III containment as part of generic review of effects of hydrogen evolving from postulated accident Analysis procedure encl
TEDESCO, R L Assistant Director for Licensing 80/12/19 3pg 07445 196

B101190505 Ltr to all BWR applicants for BWR BWR steam discharge safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for steam discharge vol encl
TEDESCO, R L Assistant Director for Licensing 80/12/22 2pg

--B101190514 Forwards generic safety evaluation re BWR steam discharge sys Review identified 100 add'l requirements to those proposed by owners group re steam discharge vol designs Rept should be transmitted to license applicants
CHECK, P S Assistant Director for Plant Systems 80/12/01 2pg 07183 001

B101090631 Requests acceleration of NRC licensing process re facility Review of R. Tedesco B01216 ltr re preliminary review schedule indicates that many activities are scheduled later than prudent for anticipated fuel loading & startup
JAN04, J H Illinois Power Co 81/01/05 2pg 07442 062

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pg

C Adjudicatory correspondence

B101230172 Forwards Prairie Alliance suppl to petition for leave to intervene & request for hearing
SAPELSD, A Prairie Alliance 81/01/14 1p 07187 001

--B101230178 Suppl to petition for leave to intervene & request for hearing Certificate of Supp encl
SAPELSD, A Prairie Alliance 81/01/14 10pg 07107 001

B101290057 Notice of filing of encl applicant answer to Prairie Alliance suppl to petition for leave to intervene & request for hearing 11/notice of appearance
FAZIO, P V Illinois Power Co FAZIO, P V Schiff, Hardin & Wallis 81/01/26 2pg 07567 202

--B0100000 Answer Lapsing Prairie Alliance suppl to petition for leave
to intervene requested for reacting Suppl fails to present
distinguishable contentions or prove defects in original filing
Certificate of Service Unit of appearance encl
KLEIN, D. Illinois Power Co 8/10/26 2pp 0735/ 204

B0100000 Forwards IE Bulletin 80-23. Potential Defects in Beloit
Press Emergency Generators. No written response
required
KEMPNER, J. C. Region 3, Chicago, Office of the Director 80/10/31
1p 0740/ 081

B0100000 Forwards IE Info Notice 80-59. Malfunction of Solenoid
Valves. Valco Engineering Corp. No written response
required
KEMPNER, J. C. Region 3, Chicago, Office of the Director 80/10/31
1p 0740/ 143

B0100000 Forwards IE Info Notice 80-59. Malfunction of Solenoid
Valves. Valco Engineering Corp. No written response
required
KEMPNER, J. C. Region 3, Chicago, Office of the Director 80/10/31
1p 0740/ 143

B0100000 Forwards IE Bulletin 80-21. Valve Yokes Supplied by
Malcolm Foundry Co. No written response required
KEMPNER, J. C. Region 3, Chicago, Office of the Director 80/11/06
1p 0740/ 115

B0100000 Forwards IE Info Notice 80-40. Excessive Nitrogen Supply
Pressure Actuates Safety-Relief Valve Operation to Cause
Reactor Degradation. No written response required
KEMPNER, J. C. Region 3, Chicago, Office of the Director 80/11/07
2pp 0740/ 148

B0100000 Forwards IE Info Notice 80-41. Failure of Safety Check
Valve in Reactor Heat Removal Sys at Davis Besse Unit 1. No
response required
KEMPNER, J. C. Region 3, Chicago, Office of the Director 80/11/10
2pp 0739/ 073

B0100000 Forwards IE Insp Rept 50-461/80-23 on B01001-1101 & notice
of violation
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/12 2pp 0744/ 153

--B0100000 Notice of violation from Insp of B01001-1101
Region 3, Chicago, Office of the Director 80/11/10 1p
0744/ 155

--B0100000 IF Insp Rept 50-461/80-23 on B01001-1101 Noncompliance
noted Major areas inspected safety-related const activities
reactor degradation & storage areas & fire protection/prevention
LIVERMORE, H. H. KEMPNER, J. C. Region 3, Chicago, Office of the
Director 80/11/10 10pp 0744/ 154

B0100000 Forwards IE Bulletin 80-23. Failures of Solenoid Valves
Mfg by Valco Engineering Corp. No written response required
KEMPNER, J. C. Region 3, Chicago, Office of the Director 80/11/14
2pp 0739/ 247

B0100000 Ack receipt of B01112 ltr informing NRC of steps taken to
correct violation noted in IE Insp Rept 50-461/80-19
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/25 1p 0742/ 345

B0100000 Forwards IE Insp Rept 50-461/80-24 on B01005-07 No
noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/02 2pp 0746/ 343

--B0100000 IE Insp Rept 50-461/80-24 on B01005-07 No noncompliance
noted Major areas inspected electrical conduit support work
activities & electrical conduit work activities
KEMPNER, J. C. Region 3, Chicago, Office of the Director
KEMPNER, J. C. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/28 7pp 0746/ 345

B0100000 Forwards IE Info Notice 80-40. Failures of Continuous Water
Level Monitor for Steam Discharge Val at Dresden Unit 2. No
response required
KEMPNER, J. C. Region 3, Chicago, Office of the Director 80/12/05
2pp 0739/ 297

B0100000 Forwards IE Insp Rept 50-461/80-26 on B01103-26 No
noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/09 2pp 0746/ 003

B0100000 IF Insp Rept 50-461/80-26 on B01103-26 No noncompliance
noted Major areas inspected safety-related const activities
reactor degradation & storage areas & fire protection/prevention
LIVERMORE, H. H. KEMPNER, J. C. Region 3, Chicago, Office of the
Director 80/12/05 8pp 0746/ 005

B0100000 Ack receipt of B01112 ltr informing NRC of steps taken
correct violation noted in IE Insp Rept 50-461/80-21
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/11 1p 0740/ 294

--B0100000 Responds to NRC B01023 ltr re violations noted in IE
Insp Rept 50-461/80-21 Corrective actions ultrasonic instrument
recalibrator & add-on to reactor core isolation recall cycle log
KEMPNER, J. C. Illinois Power Co 80/11/24 2pp 0740/ 249

B0100000 Responds to IE Bulletin 80-21. Failures of Solenoid Valves
Mfg by Valco Engineering Corp. Specified valves will not
be installed at facility
KEMPNER, J. C. Illinois Power Co 80/12/12 1p 0741/ 292

B0100000 Forwards IE Insp Rept 50-461/80-25 on B01119-21 No
noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/12 2pp 0748/ 316

--B0100000 IE Insp Rept 50-461/80-25 on B01119-21 No noncompliance
noted Major areas inspected containment dome lifting &
attaching procedures & observation of fitup for primary
containment inlet piping
KEMPNER, J. C. Region 3, Chicago, Reactor Construction &
Engineering Support Branch 80/12/12 4pp 0749/ 310

B0100000 Forwards IE Info Notice 80-45. "Potential Failure of
Backup Manual System Capability." No written response
required
KEMPNER, J. C. Region 3, Chicago, Office of the Director 80/11/10
2pp 0742/ 021

B0100000 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of Control
Rods to Insert During Scram at BWR." No written response
required
KEMPNER, J. C. Region 3, Chicago, Office of the Director 80/11/10
2pp 0746/ 335

B0100000 Forwards IE Bulletin 80-25. "Operating Problems W/ Reactor
Safety Relief Valves at BWRs." No response required
KEMPNER, J. C. Region 3, Chicago, Office of the Director 80/11/10
2pp 0737/ 317

B0100000 Ack receipt of B01219 ltr informing NRC of steps taken
correct violations noted in IE Insp Rept 50-461/80-23.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/01/07 1p 0746/ 240

--B0100000 Responds to NRC B01112 ltr re violations noted in IE
Insp Rept 50-461/80-23 Corrective actions personnel trained re
restrictions of Baldwin Associates's rigging hoisting &
landing procedure
KEMPNER, J. C. Illinois Power Co 80/12/19 1p 0746/ 241

B0100000 Responds to IE Bulletin 80-21 re Malcolm Foundry Co valve
failures Investigations remain uncompleted Complete
response expected by B01028
KEMPNER, J. C. Illinois Power Co 81/01/08 1p 0755/ 212

& Reportable occurrences, LERs & related correspondence

B0100000 Final deficiency rept originally reported on B00620.0
thin-walled elbow discovered in reactor pressure vessel
drain line Defective elbow replaced Drain line elbows
extensively investigated Manufacturer to inspect elbows
KEMPNER, J. C. Illinois Power Co 80/12/31 3pp 0741/ 203

B0100000 50-462 CLINCH POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

B0100000 Ltr to all power reactor licensees & applicants for
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12. "Potential for Low Fracture
Toughness & Laminar Tearing on Component Supports."
KEMPNER, J. C. Division of Licensing 80/11/26 8pp

Forwards preliminary review schedule for facility identification of branch reviewers & contact & address of contracted technical assistance
R L Assistant Director for Licensing 00/12/16 3pp
27

Infers of licensing milestones for facility & staffing elements for project Preliminary review schedule encl
R L Assistant Director for Licensing 00/12/16 3pp
29

Requests performance of ultimate capacity analysis of Markainment as part of generic review of effects of evolving from postulated accident Analysis
encl
R L Assistant Director for Licensing 00/12/19 3pp
38

Requests acceleration of IIRC licensing process re facility of RL Tedesco H01216 ltr re preliminary review
indicates that many activities are scheduled later
dependent for anticipated fuel loading & startup
J Illinois Power Co 01/01/05 2pp 07442:062

Medical, emergency & fire protection plans

Ltr to all licensees of operating reactor plants. CP holders
licants Revised radiological emergency response
it be submitted by licensees within 60 days of
by applicants as part of FSAH
B.O. Division of Licensing 00/11/13 2pp

atory correspondence

Forwards Prairie Alliance suppl to petition for leave to
& request for hearing
A Prairie Alliance 01/01/14 1p 07187:001

Suppl to petition for leave to intervene & request for
Certificate of Svc encl
A Prairie Alliance 01/01/14 10pp 07187:001

Notice of filing of encl applicant answer to Prairie
suppl to petition for leave to intervene & request
ing II/notices of appearance
V Illinois Power Co A210.P V Schiff, Hardin & Waite
5 2pp 07567:202

Answer opposing Prairie Alliance suppl to petition for leave
intervene & request for hearing Suppl fails to present
fiable contention or cure defects in original filing
icate of Svc & notices of appearance encl.
D Illinois Power Co 01/01/26 25pp 07567:204.

lion reports. IE Bulletins & correspondence

Forwards IE Circular 00-23. "Potential Defects in Detroit
ys Emergency Generators " No written response
J Q Region 3, Chicago, Office of the Director 00/10/31.
378:081

Forwards IE Info Notice 00-39. "Malfunction of Solenoid
f by Valcor Engineering Corp " No written response
red.
J Q Region 3, Chicago, Office of the Director 00/10/31
401:140

Forwards IE Bulletin 00-21. "Valve Yokes Supplied by
Foundry Co, Inc " Written response required.
J Q Region 3, Chicago, Office of the Director 00/11/06
7400:135.

Forwards IE Info Notice 00-40. "Excessive Nitrogen Supply
e Actuators Safety-Relief Valve Operation to Cause
Depressurization " No written response required.
J Q Region 3, Chicago, Office of the Director 00/11/07
7400:148

Forwards IE Info Notice 00-41. "Failure of Swing Check
n Decay Heat Removal Sys at Davis Besse Unit 1 " No
e required
J Q Region 3, Chicago, Office of the Director 00/11/10
7391:073.

610105044 Forwards IE Info Notice 00-43. Failures of Continuous Water
Level Monitor for Steam Discharge Vnl at Dresden Unit 2 " No
response required
MEPLER, J Q Region 3, Chicago, Office of the Director 00/12/05
2pp 07390:257

6101070213 Responds to IE Bulletin 00-21. Failures of Solenoid Valves
f by Valcor Engineering Corp " Specified valves will not
be installed at facility
MULLER, G E Illinois Power Co 00/12/12 1p 07314:297

6101060594 Forwards IE Info Notice 00-45. "Potential Failure of BWR
Backup Manual Steam Capability " No written response
required
MEPLER, J Q Region 3, Chicago, Office of the Director 00/12/17
2pp 07423:321

6101156210 Forwards Suppl 4 to IE Bulletin 00-17. "Failure of Control
Rods to Insert During Scram at BWR " No written response
required
MEPLER, J Q Region 3, Chicago, Office of the Director 00/12/18
2pp 07465:335

6101056156 Forwards IE Bulletin 00-35. "Operating Problems w/Target
Ruck Safety Relief Valves at BWRs " No response required
MEPLER, J Q Region 3, Chicago, Office of the Director 00/12/19
2pp 07277:337

6101200600 Responds to IE Bulletin 00-21 re Malcolm Foundry Co valve
yoke failures Investigations remain uncompleted Complete
response expected by 010208
MULLER, G E Illinois Power Co 01/01/08 1p 07550:212

DOCKET 50-463 FULTON GENERATING STATION, UNIT 1

G Adjudicatory correspondence

6101270315 Reply supporting applicant earlier motion to withdraw CP
application w/o prejudice Opposes intervenor York Committee
for Safe Environ response supporting withdrawal of
application w/prejudice Certificate of Svc encl
IRWIN, D P Philadelphia Electric Co 01/01/23 5pp 07546:066

I Financial information

601260144 Forwards SEC Form 10-Q, Quarterly Financial Rept & supporting
mgt comments, in response to IIRC 790721.1109 & 800B11
requests for info re significant financial developments
affecting utility in restart proceeding
CONDON, V H General Public Utilities 00/11/26 3pp

--601260154 Quarterly Financial Rept Sept 1980 & supporting mgt
comments
• General Public Utilities 00/11/14 44pp

DOCKET 50-464 FULTON GENERATING STATION, UNIT 2

G Adjudicatory correspondence

6101270315 Reply supporting applicant earlier motion to withdraw CP
application w/o prejudice Opposes intervenor York Committee
for Safe Environ response supporting withdrawal of
application w/prejudice Certificate of Svc encl
IRWIN, D P Philadelphia Electric Co 01/01/23 5pp 07546:066.

I Financial information

601260144 Forwards SEC Form 10-Q, Quarterly Financial Rept & supporting
mgt comments, in response to IIRC 790721.1109 & 800B11
requests for info re significant financial developments
affecting utility in restart proceeding
CONDON, V H General Public Utilities 00/11/26 3pp

--601260154 Quarterly Financial Rept Sept 1980 & supporting mgt
comments
• General Public Utilities 00/11/14 44pp

DOCKET 50-465 ALLEN CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

D. NRC Draft/Final Environmental Statements, Suppl & correspondence

B101050280 Forwards draft Suppl 2 to facility FES INUREG-04701 & FR notice of availability Draft not encl
YOUNGLODD, B J Licensing Branch 1 80/12/12 1p 07389 237

B101050282 Notice of availability of draft Suppl 2 to FES
YOUNGLODD, B J Licensing Branch 1 00/12/12 2pp 07389 238

B101050533 Forwards draft Suppl 2 to FES for facility & FR notice of availability w/o draft Suppl 2
YOUNGLODD, B J Licensing Branch 1 80/12/12 3pp 07390 307

B101050106 Forwards draft suppl to FES for review & comment Comments due within 45 days after publication in FR
YOUNGLODD, B J Licensing Branch 1 80/12/12 3pp 07426 298

B101210312 Forwards FR notice & draft Suppl 2 to FES, INUREG-0470
Requests comments w/o Suppl 2
YOUNGLODD, B J Licensing Branch 1 80/12/12 2pp 07488 225

B101050055 Verifies filing of EIS, INUREG-0470, Suppl 2 w/Dfc of Environ Review. EPA scheduled publication of notice of availability in FR on 801224 & public review period is scheduled to terminate on 800211
MILSON, M L Environmental Protection Agency. 80/12/22 1p 07385 267

B101120497 Ack receipt of draft Suppl 2 to FES re proposed const of facility
CORNEP, M L Agriculture, Dept of 81/01/05 1p 07446 277

B101230444 Advises that draft suppl to FES has been reviewed No comments forthcoming
HACKOCK, V J Housing & Urban Development, Dept of 81/01/19 1p 07511 125

F. Security, medical, emergency & fire protection plans

B101050087 Ltr to all licensees of operating reactor plants, LP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
CIEBHUT, D G Division of Licensing 80/11/13 2pp

G. Adjudicatory correspondence

B101090019 Requests info re public hearings in Houston, TX scheduled for B10114 & 19 Expresses wish to make prepared statement
BRUNDAGE, J T Affiliation Unknown 80/12/17 1p 07442 001

B101050014 Appeal to receive transcript of 001202 prehearing conference Intervenor was under impression that recently changed NRC rules would provide gratis copy Certificate of Svc encl
DOHERTY, J F Doherty, J F 00/12/27 2pp 07378 349

B101050065 Expresses concern re amount of time taken to handle & process requests re Reo3 Rept
DOHERTY, J F Doherty, J F 80/12/27 1p 07376 288

B101050608 Response to intervenor B01222 motion for B01231 late filing of direct testimony NRC has no objection Certificate of Svc encl
BLACK, R L Hearing Branch 1 00/12/31 3pp 07390 293

B101050055 Response to TX PIRG B01216 motion & Intervenor Hinderstein B01222 motion for extension to file 11 Session direct testimony Applicant does not oppose motion Certificate of Svc encl
HASKIN, D J COPELAND, J G Houston Lighting & Power Co RASKIN, D Loewenstein, Newman, Reis, Atelrad & Toll 80/12/31 3pp 07427 298

B101080442 Requests permission to present testimony at CP hearing for proposed facility on B10114 at Univ of Houston, TX
WADDT, B Affiliation Unknown 81/01/01 1p 07420 312

B101090400 Requests to make limited appearance statement at B10114 hearing in Houston, TX re proposed facility operation
WODDS, J Affiliation Unknown 81/01/03 1p 07442 105

B101140891 Requests to make limited appearance statement at B10114 hearing in Houston, TX
FRAM, F Affiliation Unknown 81/01/03 1p 07308 081

B101050088 Order granting extension until B10130 for intervenor to respond to applicant B01218 answers in support of NRC 001126 motion for summary disposition Only new facts & arguments should be addressed
WLF, S J Atomic Safety and Licensing Board Panel 81/01/05 07419 341

B101090088 Notice that ASLB & other interested parties will meet w/applicant representative on B10113 in Bealy, TX to visit proposed site
WLF, S J Atomic Safety and Licensing Board Panel 81/01/05 07426 244

B101090107 Order dismissing JF Doherty appeal restating entitlement transcript of B01202 prehearing conference Decision based on ASLB B01209 order rescinding orders or issuances granting assistance to intervenors
TOLPAHUS, S A Atomic Safety and Licensing Appeal Panel 81/01/05 07426 303

B101200030 Requests to make limited appearance statement at license hearing
REARMAN, M Affiliation Unknown 81/01/05 1p 07477 316

B101120538 Order granting extension until 001231 for intervenors TX PIRG & Hinderstein to file 11 Session Wilton direct testimony
WLF, S J Atomic Safety and Licensing Board Panel 81/01/06 07445 189

B101160104 Response to ASLB B01120 order providing nexus between OK jet pumps & earlier ASLBs in support of Intervenor B01015 Contention 53 Certificate of Svc encl
DOHERTY, J F Affiliation Unknown 81/01/06 3pp 07183 001

B101200033 Requests to make limited appearance statement at license hearing
SIRUSE, H P Affiliation Unknown 81/01/00 1p 07477 317

B101190011 Brief in form of pleading opposing Potthoff appeal to ASLB B01113 order which granted applicant motion for summary disposition & dismissing Potthoff as Intervenor Certificate of Svc encl
NEHMAN, J R Houston Lighting & Power Co NEHMAN, J R Loewenstein, Newman, Reis, Atelrad & Toll 01/01/09 12pp 07462 317

B101140853 Requests to make limited appearance statement
WESTBY, J Affiliation Unknown 01/01/12 1p 07300 001

B101200027 Requests to make limited appearance statement at license hearing Certificate of Svc encl
FEINEZ, C A Affiliation Unknown 81/01/14 4pp 07187 001

B101230604 Motions directed to ASLB for interlocutory appeal & certification of questions re NEPA requirements on Class 9 accidents & to ASLB for directed certification of questions per ALAO-271
SCOTT, J H Texas Public Interest Research Group 81/01/15 3pp 07812 239

B101270288 Contention 51 re designation of site L1-3 as superior & Contention 52 re ability of govt to decide issues of wildlife habitat & Contentions 53 & 54 re NUREG-470, Suppl 2, Certificate of Svc encl
DOHERTY, J F Affiliation Unknown 81/01/15 12pp 07309 001

B101260494 Order withholding action on intervenor TX PIRG B10115 motion for direct certification until ASLB decision on reaffirming ruling or certifying questions Certificate of Svc encl
BISHOP, C J Atomic Safety and Licensing Appeal Panel 81/01/19 3pp 07329 221

B101280293 Supplemental response to applicant motion for summary disposition of Intervenor Doherty Contention 5 Portions withheld (ref 10CFR2 790)
DOHERTY, J F Affiliation Unknown 81/01/19 2pp 07308 001

B101280325 Motion requesting that ASLB call B Basdoks as witness Intervenor J Doherty Contentions 8, 12, 24, 28, 41, 42 & 17 Certificate of Svc encl
DOHERTY, J F Affiliation Unknown 81/01/19 3pp 07308 001

B101280168 Response in form of brief opposing Potthoff appeal of ASLB B01130 order Board action dismissing Contention 6 re marine biomass production & Potthoff as party-Intervenor was correct Certificate of Svc encl
BLACK, R L Hearing Branch 1 81/01/26 22pp 07556 120

031 Opposes proposed facility No permit should be granted
M H Affiliation Unknown 80/12/22 1p 07309 001

035 Opposes facility operation No more pollution is needed in

R J Affiliation Unknown 80/12/28 1p 07442 287

037 Opposes facility const
Affiliation Unknown 81/01/08 1p 07187 001

ing transcripts on non-antitrust matters

452 Transcript of 810112 hearing in Wallis, TX Pp 2.005-2.121
omic Safety and Licensing Board Panel 81/01/12 117pp
093

472 Transcript of 810113 hearing in Wallis, TX Pp 2.122-2.282
omic Safety and Licensing Board Panel 81/01/13 22pp
030

424 Transcript of 810114 hearing in Houston, TX Pp 2.203-2.309
omic Safety and Licensing Board Panel 81/01/14 108pp.
148

478 Transcript of 810115 hearing in Houston, TX Pp 2.310-2.495
omic Safety and Licensing Board Panel 81/01/15 187pp
114

460 Transcript of 810116 hearing in Houston, TX Pp 2.496-2.731
omic Safety and Licensing Board Panel 81/01/16 237pp
199

279 Transcript of 810117 hearing in Houston, TX Pp 2.732-2.969
omic Safety and Licensing Board Panel 81/01/19 239pp
096.

283 Transcript of 810120 hearing in Houston, TX Pp 2.970-3.230.
omic Safety and Licensing Board Panel 81/01/20 262pp.
299

098 Transcript of 810121 hearing in Houston, TX Pp 3.231-3.429
omic Safety and Licensing Board Panel 81/01/21 250pp
163

285 Transcript of 810122 hearing in Houston, TX Pp 3.488-3.736
omic Safety and Licensing Board Panel 81/01/22 256pp
196

182 Transcript of 810123 hearing in Houston, TX Pp 3.737-3.878
omic Safety and Licensing Board Panel 81/01/23 143pp
142

Professional/Executive Correspondence

314 Responds to 801009 ltr re NRC progress in review of CPs, use
resources for Section 110 of NRC 1980 Authorization Act.
in adjudicatory proceedings & lack of coherent
regulatory guidance W/o encl documentation
NEARNE, J F. Commissioners 80/12/22 4pp 07422 007

80362 Responds to 801009 ltr re NRC progress in review of CPs, use
resources for Section 110 of NRC 1980 Authorization Act.
in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl.
NEARNE, J F. Commissioners 80/12/22 4pp 07422 023

80-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

Professional/Executive Correspondence

314 Responds to 801009 ltr re NRC progress in review of CPs, use
resources for Section 110 of NRC 1980 Authorization Act.
in adjudicatory proceedings & lack of coherent
regulatory guidance W/o encl documentation.
NEARNE, J F. Commissioners 80/12/22 4pp 07422 007

80362 Responds to 801009 ltr re NRC progress in review of CPs, use
resources for Section 110 of NRC 1980 Authorization Act.
in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl
NEARNE, J F. Commissioners 80/12/22 4pp 07422 023

A Application/construction stage documents & correspondence

810150145 Grants six month extension to preliminary design approval
for CESSAR Sys 80 std plant
EISENHUT, D G Division of Licensing 80/12/31 2pp 07463 217

K Utility Final Safety Analysis Report (FSAR) & amendments

8101070196 Forwards FSAR W/o encl
SCHEPER, A E C-F Power Systems 80/12/18 1p 07414 291

DOCKET 80-471 PITCHER NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12: "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR.
EISENHUT, D G Division of Licensing 80/11/13 2pp

D Adjudicatory correspondence

8101060918 Order granting NRC 800117 motion to receive into record CB
Bauer & CV Hedge suppl testimony re applicant Contention 9
Testimony received as NRC Exhibit 68
GOODWIN, P A C Atomic Safety and Licensing Board Panel 80/12/30
1p 07401 092

D Advisory Committee on Reactor Safeguards reports & correspondence

810130477 Forwards ACRS 810112 ltr to Chairman Ahearns re review of
requirements for near-term CP applications
MIRAGLIA, F J Licensing Branch 3 81/01/21 4pp 07587 058

U Congressional/Executive Correspondence

8101060314 Responds to 801009 ltr re NRC progress in review of CPs, use
of resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance W/o encl documentation
NEARNE, J F Commissioners 80/12/22 4pp

--8101060362 Responds to 801009 ltr re NRC progress in review of CPs, use
of resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl
NEARNE, J F Commissioners 80/12/22 4pp

DOCKET 87N-50-460 RESAR-41

A Application/construction stage documents & correspondence

8101190148 Grants 6-month extension to preliminary design approval of
facility
EISENHUT, D G Division of Licensing 80/12/31 3pp 07475 209

DOCKET 87N-50-462 WOLF CREEK GENERATING STATION, KANSAS GAS & ELECTRIC

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12: "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp.

8101090874 Approves Revision I to QA program Revision contents &
chronology encl
VORAGSLOO, B J Licensing Branch 1 80/12/22 5pp 03893 255.

0101260510 Receipt of B01016 letter corrective actions revision in regard to Work Hold Agreement 13. DDC should be informed of plans to resume work in advance to allow pipe cleanliness evaluation.

SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 01/01/22 2pp 07529 233

0101260511 Comments on B01209-15 hearing with PC & LLC. Recommends measures to be taken in further expedite & facilitate FSAR review. More technical review meetings should be held. Format revision needed.
SEIDLE, W. C. Standardized Nuclear Unit Power Plant System, Bethesda, MD 01/01/15 2pp 07529 311

0101260512 Comments request for April info re FSAR for facility. Applicant must provide provisions for emergency food, water & medical supplies in description of control room habitability. All areas must have emergency ventilation systems.
SEIDLE, W. C. Assistant Director for Licensing 01/01/07 4pp 07422 048

0101260521 Notification of B01013 hearing. 010113 in Bethesda, MD to discuss C. review.
SEIDLE, W. C. Licensing Branch 1 01/01/08 3pp 07463 223

0101260522 Forwards handwritten transcript of B01209-10. NUPPS review meeting on FSAR Chapter B. Transcript available in Central files only.
SEIDLE, W. C. Standardized Nuclear Unit Power Plant System, Bethesda, MD 01/01/20 2pp 07517 135

6 Security, medical, emergency & fire protection plans

0101260527 Ltr to all licensees of operating reactor plants. CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B01016 & C, applicants as part of FSAR.
SEIDLE, W. C. Division of Licensing 00/11/13 2pp

4 Adjunctive correspondence

0101260528 Petition to intervene in proceeding Certificate of Svc encl
SEIDLE, W. C. Affiliation Unknown 01/01/06 2pp 07508 001

0101260529 Petition to intervene in proceeding Certificate of Svc encl
SALAVA, M. E. Affiliation Unknown 01/01/13 2pp 07183 001

0101260529 Forwards petition for leave to intervene on behalf of PSC of MO. Notice of appearance also encl.
SEIDLE, W. C. Missouri, State of 01/01/16 2pp 07523 296

0101260529 Petition for leave to intervene in proceeding Affidavit & Certificate of Svc encl
SEIDLE, W. C. Missouri, State of 00/12/16 5pp 07523 298

0101260530 Petition for leave to intervene in proceeding Certificate of Svc encl
NEBAL, L. American Nuclear Society 01/01/16 2pp 07546 039

0101260531 Petition for leave to intervene
MILLER, C. C. MASCH, J. E., GAVINS, J. J. Consens for Sensible Energy 01/01/19 3pp 07512 283

0101260533 Answer opposing W. Christy B01016 petition to intervene. Applicant does not oppose Christy limited appearance statement Certificate of Svc encl
RIDGEWAY, D. A. Kansas Gas & Electric Co. RIDGEWAY, D. A. Shaw, Pittman, Potts & Troubridge 01/01/21 5pp 07546 112

0101260532 Answer opposing ME Salava B01013 motion to intervene. Applicant does not oppose Salava limited appearance statement Certificate of Svc encl
SILBERG, J. E. Kansas Gas & Electric Co. SILBERG, J. E. Shaw, Pittman, Potts & Troubridge 01/01/21 5pp 07544 037

0101260530 Response to PSC of MO B01016 petition to intervene as representative of State. Applicant does not object to participation if hearing is ordered. Certificate of Svc encl
RIDGEWAY, D. A. Kansas Gas & Electric Co. RIDGEWAY, D. A. Shaw, Pittman, Potts & Troubridge 01/01/21 4pp 07544 091

0101260534 Notice of appearance in proceeding Certificate of Svc encl
RIDGEWAY, D. A. Kansas Gas & Electric Co. RIDGEWAY, D. A. Shaw, Pittman, Potts & Troubridge 01/01/21 3pp 07550 108

0101260535 Answer supporting W. Christy petition for leave to intervene re standing issue. ASLR ruling on petition as whole would be premature because petitioner still has time to file certificate Certificate of Svc encl
KAPPA, M. Hearing Branch 2 01/01/22 3pp 07529 233

0101260532 Notice of appearance in proceeding Certificate of Svc encl
KAPPA, M. Hearing Branch 2 01/01/22 2pp 07529 236

0101260534 Answer to PSC of MO B01016 petition for leave to intervene as representative of State. NRC would support petition if hearings are held in consider DL application Certificate of Svc encl
KAPPA, M. Hearing Branch 2 01/01/26 2pp 07556 091

H General correspondence

0101260534 Opposes licensing of facility
KAPPA, M. Affiliation Unknown 01/01/14 1p 07546 074

Q Inspection reports, IE Bulletins & correspondence

0101260537 Forwards IE Hgt Meeting Rept 50-402/80-22 on B01103
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 00/11/14 1p 07421 503

0101260539 IE Hgt Meeting Rept 50-482/80-22 on B01103 Noncompliance noted failure to approve qualifications of blasting specialist & to establish housekeeping zone designations for cleanliness.
SEIDLE, W. C. CHROSEMAN, W. A. Region 4, Dallas, Office of the Director. SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 00/11/14 9pp 07421 304

0101260540 Ack receipt of B01030 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-402/80-1B.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 00/12/03 1p 07537 339

0101260547 Responds to NRC B01008 ltr re violations noted in IE Insp Rept 50-482/80-1B. Corrective actions: weld portion deposited by shielded manual arc process removed & welders responsible for electrode angle reprimanded & suspended.
KESTER, G. L. Kansas Gas & Electric Co. 00/10/30 2pp 07537 340

0101260550 Discusses IE Insp Rept 50-402/80-1B on B00922-1031 & forwards notice of violation.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 00/10/08 1p 07537 342

0101260550 Notice of violation from Insp on B01001 Noncompliance noted low hydrogen electrodes not maintained in heated containers & welding done using overexposed & cold electrodes.
Region 4, Dallas, Office of the Director. 00/10/08 1p 07537 343

0101260551 Forwards IE Insp Rept 50-482/80-1B on B00922-1031
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 00/12/05 2pp 07537 344

0101260550 IE Insp Rept 50-402/80-1B on B00922-1031. Noncompliance noted failure to follow procedures in welding.
VANCE, T. E., CHROSEMAN, W. A. Region 4, Dallas, Office of the Director 00/12/04 13pp 07537 346

01012605614 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vol. at Dresden Unit 2." No response required.
SEIDLE, W. C. Region 4, Dallas, Office of the Director 00/12/08 1p 07391 042

01012605615 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required.
SEIDLE, W. C. Region 4, Dallas, Office of the Director. 00/12/16 1p 07391 292

0101260561 Approves lifting of B01120 Work Hold Agreement 13 re pipe cleanliness program at facility. Util corrective actions acceptable.
SEIDLE, W. C. Region 4, Dallas, Office of the Director. 00/12/31 1p 07461 349

0101260564 Responds to IE Bulletin 80-21, "Valve Yoke Supplied by Malcom Foundry Co. Inc." Ref parts not found in continuing investigation. Final rept will be filed within 30 days.
PETERICK, A. Standardized Nuclear Unit Power Plant System. 01/01/05 1p 07570 345

B10114044 Motion for extension until B10116 to answer local govt
petitions to participate in hearings Certificate of Svc
encl
BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts &
Troubridge B1/01/0n 4pp 07442 321

B10114026 Response opposing petition to intervene by MO-KA section.
AMS who prejudice to timely renewal. Supports petition for
participation by E BROWN, H Lottman & R Lueky Certificate of
Svc encl
LESSY, R P Antitrust Division B1/01/12 9pp 07450 089

B101190477 Response opposing MO-KS section of AMS B01219 petition to
intervene Applicant would not oppose refiling petition to
intervene to cure deficiencies Certificate of Svc encl
BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts &
Troubridge B1/01/17 7pp 07474 068

B101230615 Response to B01222 requests for participation Applicant does
not object to two petitions but requests that Presiding
Judges Lottman & Lueky & School District Superintendent
Brunn show representative authority Certificate of Svc encl
BERNSTEIN, D L Union Electric Co BERNSTEIN, D L Shaw, Pittman,
Potts & Troubridge B1/01/16 5pp 07512 269.

B101260486 Answer to Judge Wright B10116 request for participation
Applicant has no objection provided that petitioner can
substantiate representative authority during first
prehearing conference Certificate of Svc encl
BERNSTEIN, D L Union Electric Co BERNSTEIN, D L Shaw, Pittman,
Potts & Troubridge B1/01/21 4pp 07529 211

B101260307 Answer opposing J Botwinick B0120B petition for leave to
intervene & request for hearing Petitioner failed to
establish particular interest or standing Certificate of Svc
encl
BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts &
Troubridge B1/01/23 5pp 07537 164.

B101300018 Response supporting Wright B10116 petition for local govt
representative participation when representative capacity is
shown Botwinick B10113 petition for leave to intervene
should be denied w/leave to amend Certificate of Svc encl
LESSY, R P Antitrust Division B1/01/2B 10pp 07582 199.

H General correspondence

B101140031 Responds to B01209 ltr re requirements to limit discharge
into MO River NRC will require that util meet regulations
VOLANS, B L D J Licensing Branch 1 B0/12/29 1p 07308 001

--B101140037 Requests info re requirements for util in limiting discharge
into MO River according to NRC & Federal regulations
HUNPAT, J E Affiliation Unknown B0/12/09 1p 07308 001.

B101290783 Responds to B01219 ltr requesting comment on TB Class B01203
ltr expressing concern re dumping of low level radioactive
water into MO River All operating reactors must stay within
design objective dose limits
DIERCKS, W J Office of the Executive Director for Operations
B1/01/06 2pp 07309 001

--B101290787 Forwards TB Class B01203 ltr expressing concern re dumping
of low level radioactive water from facilities into MO
River Requests response.
BOLLING, R House of Rep B0/12/09 2pp 07309 081.

B101150610 Forwards B01203 ltr to State of MO Clean Water Commission &
MO Dept of Resource B01215 response re issuance of OL
Petition std B01203 protesting licensing of facility
provided
ECHELE, C. Affiliation Unknown B1/01/11 6pp 07309 001

I Inspection reports, IE Bulletins & correspondence

B101050287 Forwards IE Info Notice B0-3B, "Cracking in Charging Pump
Casing Cladding." No response required
KEPPLER, J Q Region 3, Chicago, Office of the Director. B0/10/30.
2pp 07389 294

Power Sys Emergency Generators." No written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07444 097

B101060737 Forwards IE Bulletin B0-21, "Valve Yokes Oppul
Malcolm Foundry Co. Inc." Written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07400 270

B101070421 Forwards IE Info Notice B0-40, "Excessive Nitro
Pressure Actuates Safety-Relief Valve Operation to Cause
Reactor Depressurization." No written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07442-219

B101060385 Forwards IE Info Notice B0-41, "Failure of Bus
Valve in Decay Heat Removal Bus at Davis Besse Unit 1."
response required
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07391 082

B101060510 Forwards IE Bulletin B0-23, "Failures of Boler
Mfg by Valcor Engineering Corp." Written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07391 235

B101050572 Forwards IE Info Notice B0-43, "Failures of Co
Level Monitor for Steam Discharge Vol at Dresden Unit 2
response required
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07386 040

B101220536 Forwards IE Insp Rept B0-4B3/B0-20 on B01117-1
violation
FIORELLI, G Region 3, Chicago, Reactor Construction &
Support Branch. B0/12/12 2pp 07103 001.

--B101220510 Notice of violation from insp on B01117-2B
FIORELLI, G Region 3, Chicago, Reactor Construction
Support Branch B0/12/12 1p 07183 001.

--B101220516 IE Insp Rept B0-4B3/B0-20 on B01117-2B. Noncon
inadequate design control of delineation of acceptance
criteria for Insp
KNOX, R C, NANSSEN, W A Region 3, Chicago, Office of
B0/12/09 7pp 07183 001

B101070092 Forwards IE Info Notice B0-44, "Actuation of 1
Recirculation Mode While in Hot Shutdown." No written
response required.
KEPPLER, J Q Region 3, Chicago, Office of the Director
1p 07419 036

B101290264 Responds to IE Bulletin B0-21, "Valve Yokes B
Malcolm Foundry Co. Inc." Ref parts not found in contin
investigation. Final rept will be filed within 30 days
PETRICK, N A Standardized Nuclear Unit Power Plant By
B1/01/05 1p 07570 345

B101270850 Ack receipt of B10106 ltr informing NRC of at
correct violations noted in IE Insp Rept B0-4B3/B0-2B
FIORELLI, G Region 3, Chicago, Reactor Construction &
Support Branch B1/01/16 1p 07550 129

--B101270853 Responds to NRC B01212 ltr re violations no
Rept B0-4B3/B0-2B Corrective actions approval obtain
allow smaller cable bend radius Bend radii shall be
to inside edge of bend
BRYAN, J K Union Electric Co B1/01/06 2pp 075

J Reportable occurrences, LERs & related correspondence

B101100045 Ack receipt of B01107 ltr forwarding addl in
re defective Corner & Leda pipe support sway braces In
will be reviewed & evaluated
CARLSON, R T Region 1, Philadelphia, Reactor Construct
Engineering Support Branch. B0/11/13 1p 07445 242

B101140589 Interim deficiency rept. originally reported on B01209.re
concrete deficiencies discovered near surface of reactor bldg
cone. Further evaluation will be performed by Bechtel Final
evaluation to be completed by B10401
BRYAN, J. H. Union Electric Co B1/01/02 1p 07461 244

B101140505 Final deficiency rept. originally submitted B00620.re out of
tolerance conditions on major bolt diameters & minor nut
diameters supplied by Industrial Mechanic, Inc. Analysis by
A/E indicates no predicted reduction in design capacity
BRYAN, J. H. Union Electric Co B1/01/07 2pp 07461 160

B101290690 Summarizes B01224 telcon repl re generic deficiency in
analytical techniques used by Bechtel in design of pipe whip
restraints used for std power block Bechtel reviewing design
calculations Final rept not to be issued until B10228
SEIKEN, S. J. Standardized Nuclear Unit Power Plant System B1/01/23
2pp 07566 331

DOCKET STN-50-485 STERLING POWER NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing B0/11/26 8pp

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B01002 & by applicants as part of FSAR.
EISENHUT, D. O. Division of Licensing B0/11/13 2pp

B101290583 Release public version of evacuation time estimates for
Facility
FELTON, J. M. Division of Rules and Records B1/01/27 1p
07373 267

--B101290589 Forwards public version of upgraded evacuation time
estimates for facilities in response to NRC B01209 ltr
MAIER, J. E. Rochester Gas & Electric Corp B1/01/14 23pp
07573 268

3 Inspection reports, IE Bulletin & correspondence

B101070392 Forwards Suppl 1 to IE Info Notice B0-27, "Broken Studs on
Terry Turbine Steam Inlet Flange." No written response
required
GRIER, D. H. Region 1, Philadelphia, Office of the Director
B0/11/26 1p 07414 089

B101060829 Forwards IE Info Notice B0-44, "Activation of ECCB in
Recirculation Mode While in Hot Shutdown." No written
response required
GRIER, D. H. Region 1, Philadelphia, Office of the Director
B0/12/16 1p 07397 033

DOCKET STN-50-486 CALLAWAY PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing B0/11/26 8pp

B101090052 Comments on B01209-10 meeting w/NRC & LLL. Recommends
measures to be taken to further expedite & facilitate FSAR
review. More technical review meetings should be held. Format
revision provided.
PETRICK, N. A. Standardized Nuclear Unit Power Plant System
B0/12/23 1p 07373 311

B101140641 Requests util actions re cultural resources onsite &
transmission corridors at Facility as result of NRC B01216
visit. Actions include physical structure survey & analysis &
maint of fence around site
YOUNGBLOOD, D. J. Licensing Branch 1 B0/12/24 3pp 07308 001

B101210253 Forwards request for addl info re FSAR for Facility
Applicant must provide provisions for emergency food, water &
medical supplies in description of control room habitability
& list areas & paths in emergency ventilation sys zone
TEDESCO, R. L. Assistant Director for Licensing B1/01/07 4pp
07492 048

B101230565 Forwards marked-up transcript of B01209-10 B4LPPB rev
meeting on FSAR Chapter B Transcript available in Central
Files only
PETRICK, N. A. Standardized Nuclear Unit Power Plant System
B1/01/20 1p 07517 035

C Utility, Environmental Report (ER), Amends & correspondence

B101330702 Advises that accepted version of environ rept. Vols 1-3
being forwarded. Previously submitted version should be
discarded
ECHEFF, J. L. Division of Rules and Records B1/01/19 1p
07584 152

B101300708 Advises that accepted version of environ rept. Vols 1-3
being forwarded. Previously submitted version should be
discarded
SUDDER, J. L. Division of Rules and Records B1/01/19 1p
07584 153

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B01002 & by applicants as part of FSAR.
EISENHUT, D. O. Division of Licensing B0/11/13 2pp

D Adjudicatory correspondence

B101320454 Motion for extension until B10116 to answer local govt
petitions to participate in hearings. Certificate of Svc
encl
BAXTER, L. A. Union Electric Co BAXTER, T. A. Shaw, Pittman, Po
Trotteridge B1/01/06 4pp 07442 321

B101140626 Response opposing petition to intervene by MD-KA sects
AFS, w/o prejudice to timely renewal. Supports petition for
participation by E. Brown, H. Cottman & K. Luekey. Certificate of
Svc encl
LESSY, R. P. Antitrust Division B1/01/12 9pp 07450 010

B101300810 Response supporting Wright B10116 petition for local govt
representative participation when representative capacity is
shown. Botwinick B10113 petition for leave to intervene
should be denied w/leave to amend Certificate of Svc encl.
LESSY, R. P. Antitrust Division B1/01/28 10pp 07582 199

H General correspondence

B101140031 Responds to B01209 ltr re requirements to limit discha
into MD River. NRC will require that util meet regulations
YOUNGBLOOD, D. J. Licensing Branch 1 B0/12/29 1p 07308 001

--B101140037 Requests info re requirements for util in limiting d
into MD River according to NRC & Federal regulations
MURRAY, J. E. Affiliation Unknown B0/12/09 1p 07308 001

B101290783 Responds to B01219 ltr requesting concern re dumping of low level radioactive
water into MD River. All operating reactors must stay within
design objective dose limits
BIRCHES, W. J. Office of the Executive Director for Operations
B1/01/04 2pp 07309 001

--B101290789 Forwards TB Class B01203 ltr expressing concern re d
of low level radioactive water from facilities into MD
River. Requests response
BOLLING, R. House of Rep B0/12/07 2pp 07309 001

B101150510 Forwards B01201 ltr to State of MD Clean Water Commis
MD Dept of Resource B01215 response re issuance of OL
Petition dtd B01203 protesting licensing of Facility
provided
ECHEFF, J. L. Affiliation Unknown B1/01/11 6pp 07309 001

U Inspection reports, IE Bulletins & correspondence

B10106037 Forwards IE Info Notice 80-39, "Cracking in Charging Pump
Casing Cladding." No response required
MEPLER, J G Region 3, Chicago, Office of the Director 80/10/30
2pp 07349 254

B10106052 Forwards IE Info Notice 80-39, "Malfunction of Solenoid
Valve by Valcor Engineering Corp." No written response
is required
MEPLER, J G Region 3, Chicago, Office of the Director 80/10/31
2pp 07401 184

B10106074 Forwards IE Circular 80-23, "Potential Defects in Beloit
Power Sys Emergency Generators." No written response
required
MEPLER, J G Region 3, Chicago, Office of the Director 80/10/31
4pp 07444 297

B10106077 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Lindsay Co. Inc." Written response required
MEPLER, J G Region 3, Chicago, Office of the Director 80/11/05
2pp 07463 270

B10106091 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply
Pressure Activates Safety-Relief Valve Operation to Cause
Reactor Depressurization." No written response required.
MEPLER, J G Region 3, Chicago, Office of the Director 80/11/07
2pp 07462 215

B10106095 Forwards IE Info Notice 80-41, "Failure of Spring Check
Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No
response required
MEPLER, J G Region 3, Chicago, Office of the Director 80/11/10
2pp 07371 062

B101060910 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp." Written response required
MEPLER, J G Region 3, Chicago, Office of the Director 80/11/14
2pp 07391 235

B101060972 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Steam Discharge Vnt at Dresden Unit 2." No
response required
MEPLER, J G Region 3, Chicago, Office of the Director 80/12/05
2pp 07386 040

B101070692 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown." No written
response required
MEPLER, J G Region 3, Chicago, Office of the Director 80/12/16
1p 07415 016

B101290264 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Lindsay Co. Inc." Ref parts not found in continuing
investigation. Final rept will be filed within 30 days.
PETRIC, B A Standardized Nuclear Unit Power Plant System
81/01/05 1p 07570 345

S Reportable occurrences, LERs & related correspondence

B101100045 Ack receipt of B01107 ltr forwarding addl info to final rept
re defective Cornish & Lada pipe support stay braces info
will be reviewed & evaluated
CARPENTER, T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/11/13 1p 07445 242

B101100559 Interior deficiency rept. originally reported on B01205, re
concrete deficiencies discovered near surface of reactor bldg
done. Further evaluation will be performed by Bechtel. Final
evaluation to be completed by B10401
BRYAN, L K Union Electric Co 81/01/02 1p 07461 244

B101290690 Summaries B01224 telcon rept re generic deficiency in
analytical techniques used by Bechtel in design of pipe whip
restraints used for std power block. Bechtel reviewing design
calculations. Final rept not to be issued until B10223
BEIKER, S J Standardized Nuclear Unit Power Plant System 81/01/23
2pp 07565 331

DOCKET STN 50-480 PERKINS NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B10120466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."

F Security, medical, emergency & fire protection plans

B101070367 Ltr to all licensees of operating reactor plants, CP
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10162 & by applicants as part of FSAR
EISENHART, D G Division of Licensing 80/11/13 2pp

G Adjudicatory correspondence

B101050516 Brief in opposition to intervenor 000029 exceptions
ASLB B00222 Partial Initial Decision 3 holding no obviously
superior alternative site exists. Decision should be
affirmed. Certificate of Bvc encl
MCOARRY, J H, PCRTER, W L Duke Power Co MCOARRY, J H Deo
Barbar 80/12/31 48pp 07397 029

B101100299 Response opposing intervenors' exceptions an appeal
B00222 partial initial decision re site alternatives.
Decision should be affirmed. Certificate of Bvc encl
BARRELL, C A Hearing Branch 3 81/01/12 42pp 07462 273

B101100715 Order setting B10218 oral argument in Bethesda, MD re
intervenor RA Davis & Yadkin River Committee appeal from
ASLB B00222 partial initial decision. Certificate of Bvc
encl
BISHOP, C J Atomic Safety and Licensing Appeal Panel 81/0
4pp 07472 080

B101260499 Motion for extension to set oral argument on altern
site issue for B10401 Certificate of Bvc encl
MCOARRY, J H Duke Power Co MCOARRY, J H Debevoise & Libe
81/01/21 4pp 07529 226

B101270024 Denies B10117 request for limited appearance statem
Right to make statement is limited to evidentiary hearing &
proceeding is now in appellate stage
BISHOP, C J Atomic Safety and Licensing Appeal Panel 81/0
2pp 07347 032

--B101270070 Requests to make limited appearance statement
SPRINGER, D Affiliation Unknown 81/01/17 1p 07547 0

B101280139 Order granting applicant motion to postpone oral an
appeal from ASLB B00224 partial initial decision until
B10401 Certificate of Bvc encl
BISHOP, C J Atomic Safety and Licensing Appeal Panel 81/0
4pp 07556 099

U Inspection reports, IE Bulletins & correspondence

B101060216 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown." No written
response required
D'REILLY, J P Region 2, Atlanta, Office of the Director 8
1p 07391 321

U Congressional/Executive Correspondence

B1010800314 Responds to B01009 ltr re NRC progress in review of
of resources for Section 110 of NRC 1980 Authorization Act
delay in adjudicatory proceedings & lack of coherent
regulatory guidance. W/o encl documentation
AHEARN, J F Commissioners 80/12/27 4pp

--B101080362 Responds to B01009 ltr re NRC progress in review
of resources for Section 110 of NRC 1980 Authorization Act
delay in adjudicatory proceedings & lack of coherent
regulatory guidance. Related documentation encl
AHEARN, J F Commissioners 80/12/22 4pp

DOCKET STN 50-489 PERKINS NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants for
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHART, D G Division of Licensing 80/11/26 8pp

ity. Medical, emergency & fire protection plans

07 Ltr to all licensees of operating reactor plants. CP holders
applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
1/4 by applicants as part of FSAR
UT-D.C. Division of Licensing 80/11/13 2pp

Adjudicatory correspondence

00222 Brief in opposition to intervenor EC0029 exceptions to
00222 Partial Initial Decision 3 holding no obviously
superior alternative site exists Decision should be
affirmed Certificate of Svc encl
J. M. PERIER, W. L. Duke Power Co MCGARRY, J. M. Douglas &
80/12/31 40pp 07307 025

00222 Response opposing intervenors' exceptions on appeal of ASLB
00222 partial initial decision re site alternatives
Decision should be affirmed Certificate of Svc encl
L. A. Hearing Branch 3 81/01/12 42pp 07462 273

00222 Order setting 810218 oral argument in Bethesda, MD re
intervenor MA Davis & Yachin River Committee appeal from
00222 partial initial decision Certificate of Svc

00222 C. J. Atomic Safety and Licensing Appeal Panel 81/01/13
07472 080

00222 Motion for extension to set oral argument on alternative
site issue for 810401 Certificate of Svc encl
J. M. PERIER, W. L. Duke Power Co MCGARRY, J. M. Debevoise & Liberman
81/01/21 4pp 07529 226

00222 Denies 810117 request for limited appearance statement.
Right to make statement is limited to evidentiary hearing &
proceeding is now in appellate stage
C. J. Atomic Safety and Licensing Appeal Panel 81/01/22
07547 032

00222 Requests to make limited appearance statement
SPRINGFIELD Affiliation Unknown 81/01/17 1p 07547 034

00222 Order granting applicant motion to postpone oral argument on
appeal from ASLB 000222 partial initial decision until
810401 Certificate of Svc encl
C. J. Atomic Safety and Licensing Appeal Panel 81/01/22
07556 099

Inspection reports, IE Bulletins & correspondence

00222 Forwards IE Info Notice 00-44, 'Activation of ECCB in
Recirculation Mode While in Hot Shutdown' No written
response required
LY, J. P. Region 2, Atlanta, Office of the Director 80/12/16

Congressional/Executive Correspondence

00222 Responds to 801009 ltr re NRC progress in review of CPs, use
of resources for Section 110 of NRC 1980 Authorization Act,
delay in adjudicatory proceedings & lack of coherent
regulatory guidance W/o encl documentation
E. J. F. Commissioners 80/12/22 4pp

00222 Responds to 801009 ltr re NRC progress in review of CPs, use
of resources for Section 110 of NRC 1980 Authorization Act,
delay in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl
E. J. F. Commissioners 80/12/22 4pp

DOCKET BTH-90-491 CHEROKEE NUCLEAR STATION, UNIT 3

Application/construction stage documents & correspondence

00222 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12: 'Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports.'
UT-D.C. Division of Licensing 80/11/26 8pp

F. Security, medical, emergency & fire protection plans

810102587 Ltr to all licensees of operating reactor plants. CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 1/4 by applicants as part of FSAR
EISENHUT, D. C. Division of Licensing 80/11/13 2pp

G. Adjudicatory correspondence

8101050616 Brief in opposition to intervenor EC0029 exceptions to
ASLB 800222 Partial Initial Decision 3 holding no obviously
superior alternative site exists Decision should be
affirmed Certificate of Svc encl
J. M. PERIER, W. L. Duke Power Co MCGARRY, J. M. Douglas &
Barbar 80/12/31 48pp 07307 025

8101150279 Response opposing intervenors' exceptions on appeal of ASLB
EC00222 partial initial decision re site alternatives
Decision should be affirmed Certificate of Svc encl
Barbar 81/01/12 42pp 07462 273

8101160715 Order setting 810218 oral argument in Bethesda, MD re
intervenor MA Davis & Yachin River Committee appeal from
ASLB 800222 partial initial decision Certificate of Svc

8101160715 C. J. Atomic Safety and Licensing Appeal Panel 81/01/13
4pp 07472 080

8101260499 Motion for extension to set oral argument on alternative
site issue for 810401 Certificate of Svc encl
MCGARRY, J. M. Duke Power Co MCGARRY, J. M. Debevoise & Liberman
81/01/21 4pp 07529 226

810127064 Denies 810117 request for limited appearance statement
Right to make statement is limited to evidentiary hearing &
proceeding is now in appellate stage
EISENHUT, C. J. Atomic Safety and Licensing Appeal Panel 81/01/22
2pp 07547 032

--8101270070 Requests to make limited appearance statement
SPRINGFIELD Affiliation Unknown 81/01/17 1p 07547 034

8101280119 Order granting applicant motion to postpone oral argument on
appeal from ASLB 000222 partial initial decision until
810401 Certificate of Svc encl
EISENHUT, C. J. Atomic Safety and Licensing Appeal Panel 81/01/22
4pp 07556 099

H. Inspection reports, IE Bulletins & correspondence

8101060216 Forwards IE Info Notice 00-44, 'Activation of ECCB in
Recirculation Mode While in Hot Shutdown' No written
response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/16
1p

I. Congressional/Executive Correspondence

810108031 Responds to 801009 ltr re NRC progress in review of CPs, use
of resources for Section 110 of NRC 1980 Authorization Act,
delay in adjudicatory proceedings & lack of coherent
regulatory guidance W/o encl documentation
EISENHUT, J. F. Commissioners 80/12/22 4pp

--8101080362 Responds to 801009 ltr re NRC progress in review of CPs, use
of resources for Section 110 of NRC 1980 Authorization Act,
delay in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl
EISENHUT, J. F. Commissioners 80/12/22 4pp

DOCKET BTH-90-491 CHEROKEE NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12: 'Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports.'
EISENHUT, D. C. Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

B101070387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp.

G Inspection reports, IE Bulletins & correspondence

B101070320 Forwards supplemental responses to NRC B01016 ltr re violations noted in IE Insp Repts 50-369/80-08, 50-370/80-05, 50-413/80-04, 50-414/80-09, 50-491/80-02, 50-492/80-06 & 50-493/80-06 Final rpt to be submitted by B10131
PARKER, W D Duke Power Co 80/11/11 2pp.

B101060216 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p

H Reportable occurrences, LERs & related correspondence

B101230502 Interim deficiency rept. originally reported on B01217, re breakdowns in mfg. cleaning & insp processes on shutdown heat exchangers. Caused by contamination of tube side matl; surfaces fixchangers returned to supplier for ess & repair
DAIL, L C Duke Power Co 81/01/15 2pp 07510 026

DOCKET STN-90-492 CHEROKEE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp.

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensee within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

B101070320 Forwards supplemental responses to NRC B01016 ltr re violations noted in IE Insp Repts 50-369/80-08, 50-370/80-05, 50-413/80-04, 50-414/80-09, 50-491/80-02, 50-492/80-06 & 50-493/80-06 Final rpt to be submitted by B10131
PARKER, W D Duke Power Co 80/11/11 2pp

B101060216 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07391 321

DOCKET STN-90-493 CHEROKEE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp.

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

D Inspection reports, IE Bulletins & correspondence

B101070320 Forwards supplemental responses to NRC B01016 ltr re violations noted in IE Insp Repts 50-369/80-08, 50-370/80-05, 50-413/80-04, 50-414/80-09, 50-491/80-02, 50-492/80-06 & 50-493/80-06 Final rpt to be submitted by B10131
PARKER, W D Duke Power Co 80/11/11 2pp

B101060216 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07391 321

DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1

J Insurance & indemnity information

B101270725 Forwards Endorsement 4 to NELA Binders EB-15 & EB-16
IFFLAND, R R Northeast Utilities 81/01/22 3pp

B101270744 Forwards Endorsements 65 & 66 to NELA Policy NF-173
IFFLAND, R R Northeast Utilities 81/01/22 4pp

DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

J Insurance & indemnity information

B101270726 Forwards Endorsement 4 to NELA Binders EB-15 & EB-16
IFFLAND, R R Northeast Utilities 81/01/22 3pp.

B101270744 Forwards Endorsements 65 & 66 to NELA Policy NF-173
IFFLAND, R R Northeast Utilities 81/01/22 4pp

DOCKET STN-90-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

B101050281 Informs of review of FSAR describing QA program sub support of facility CL Description of QA program in compliance w/regulations & guidelines.
MORAN, V G Assistant Director for Materials & Qualification Engineering 80/11/18 2pp 07385 047

--B101050288 Safety evaluation supporting operations phase QA g
e Office of Nuclear Reactor Regulation, Director 80/11/18 07385 049.

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp.

B101270257 Ack receipt of B00924 ltr describing analysis & resp Rehtel recommendations requested by NRC during B00819 public meeting
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07546 029.

--B101270257 Forwards util analysis & response to Rehtel recommendations as result of B00819 public meeting
OPREA, G W Houston Lighting & Power Co 80/09/24 8pp. 07546 030

B101270918 Ack receipt of B00922 ltr transmitting addl info req during B00912 meeting
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07550 114

--B101270924 Forwards addl info requested during B00912 meeting re-assembly, repair & restart of safety-related welding, concrete restart plans & schedules & interim controls
OPREA, G W Houston Lighting & Power Co 80/09/22 13pp 07550 115.

B101080131 Ack receipt of util B00904 documentation re complex restart program & STP welding program per NRC B00430 order to show cause
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/23 1p. 07421 061.

8101080140 Submits preliminary schedule for complex concrete restart program & STP welding program for reinsp & repair of existing welds & restart plan re safety-related AWS & ASME welding Requests 000913 meeting in Arlington, TX
OPREA, Q W Houston Lighting & Power Co 80/07/04 1p
07421 062

8101120388 Ack receipt of 800815 ltr forwarding concrete verification program status re: in response to 800430 order to show cause item 3b
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/23 1p 07439 119

--8101120391 Forwards concrete verification program status re: in response to 800720 show cause order item 3b
OPREA, Q W Houston Lighting & Power Co 80/08/15 2pp
07439 120

--8101120393 "Concrete Verification Program" status re: pt
* Houston Lighting & Power Co 80/08/15 41pp 07439 122

8101270261 Notification of cancellation of 810126-28 meeting w/uttl in Houston & Bay City, TX to prepare SER input & hearing on mgt qualification
SELLS, D Licensing Branch 2 80/12/30 1p 07546 038

8101330194 Confirms 810102 discussion & uttl 801217 & 30 ltrs re ASME safety-related welding 10-wk work plan & resumption of safety-related AWS welding work will commence 810105 ASME welding will be expended as set forth in uttl 801217 ltr
SEYFRIT, K V Region 4, Dallas, Office of the Director 81/01/05 2pp 07502 131

8101210628 Confirms 810109 discussion of uttl 810108 ltr re actions taken in initiating complex concrete work activities Utll should inform NRC of plans to extend concrete placement beyond 7-h
SEYFRIT, K V Region 4, Dallas, Office of the Director 81/01/13 2pp 07489 250

E NRC Safety Evaluation Report (SER), supply & correspondence

8101100577 Notification of 810126 & 28 meeting in Houston, TX & 810127 meeting in Bay City, TX w/uttl to prepare SER input & to prepare for hearing on mgt qualification.
SELLS, D Licensing Branch 2 80/12/30 3pp 07444 150

8101270261 Notification of cancellation of 810126-28 meeting w/uttl in Houston & Bay City, TX to prepare SER input & hearing on mgt qualification
SELLS, D Licensing Branch 2 80/12/30 1p 07546 038

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FBAR.
EISENHUT, D O Division of Licensing 80/11/13 2pp.

G Adjudicatory correspondence

8012180257 FOIA request for V Stello closed door statement & items which were not included in show cause order re facility proceeding
EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/10/29 1p 07271-346

8012180252 Responds to FOIA request for V Stello closed door statement & items which were not included in show cause order re facility proceeding Forwards 800415 transcript & NRC addl response to requests for info
FELTON, J H Division of Rules and Records 09/12/11 1p 07271-345

--8012180263 Transcript of 800415 briefing in Bethesda, MO re investigation of OA-QC problems at facilities Pp 1-72
* Commissioners 80/04/15 73pp

--8012180549 Addl response to Citizens Concerned About Nuclear Power 801117 requests for info inspector names withheld per 18CFR2.790. V Stello statement encl Items not encl in show cause order available in LPDR. W/Certificate of Svc
BORDENICK, B H Hearing Branch 4 80/12/08 7pp 03774 351.

8101230192 Third set of interrogatories to Citizens Concerned About Nuclear Power, Inc re intended witnesses & testimony in 810504 licensing hearing Certificate of Svc encl
HUDSON, T B, NEWMAN, J R Houston Lighting & Power Co HUDSON, Baker & Batts 81/01/16 3pp 07512 034

8101230190 Fourth set of interrogatories to Citizens Concerned About Nuclear Power, Inc re intended witnesses & testimony in 810504 licensing hearing Certificate of Svc encl
HUDSON, T B, NEWMAN, J R Houston Lighting & Power Co HUDSON, Baker & Batts 81/01/16 3pp 07512 037

8101280577 Requests extension to file motion to compel answers to interrogatories or to compel production of documents within 10 days after applicant receives responses to interrogatories 1 other Requests Certificate of Svc encl
HUDSON, T B, NEWMAN, J R Houston Lighting & Power Co HUDSON, Baker & Batts 81/01/16 12pp 07557 264

--8101280595 Second set of interrogatories & request to produce documents directed to Citizens for Equitable Utility Concerns SIP const records Certificate of Svc encl
HUDSON, T B Houston Lighting & Power Co HUDSON, T B Baker & Batts 80/12/05 3pp 07557 219

8101290149 Informs that review of applicant managerial capabilities will be performed in 810217-17 & appropriate SER sections will be issued in Apr 1981 Hearings on QC/OA plans will be deferred until June 1981
REIS, E J Hearing Branch 3 81/01/26 2pp 07566 317

--8101290155 Advises of delay in preparation of Licensee Qualification Branch input re mgt qualification to SER
TEDESCO, R Assistant Director for Licensing 81/01/23 2pp 07566 319

8101290142 Forwards NRC transcript from 800819 public meeting in City, TX per AEB request during 801119 prehearing conference 11/2 encl
GUTIERREZ, J H Hearing Branch 3 81/01/27 1p 07567 350

8101360022 Advises that NRC, by Commission directive, cannot provide transcripts during evidentiary hearings Comptroller General opinion encl
GUTIERREZ, J H Hearing Branch 3 81/01/28 5pp 07309.001

I Financial information

8101090233 Forwards annual repts for Houston Lighting & Power, Central Power & Light & financial statements for City of San Antonio, TX & City of Austin, TX
GOLDBERG, J H Houston Lighting & Power Co 80/12/31 1p 07517 045

O Inspection reports, IE Bulletins & correspondence

8101100260 Forwards IE Insp Repts 50-498/80-35 & 50-499/80-35, on 801102-07 re noncompliance noted.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/19 2pp 07443 290

--8101100269 IE Insp Repts 50-498/80-35 & 50-499/80-35 on 801102- noncompliance noted Major areas inspected Followup of const activities & review of responses to Insp Repts 50-498/79-17 & 50-499/79-19
TOMLINSON, D P, CROSSMAN, W A Region 4, Dallas, Office of the Director, HALL, R E Region 4, Dallas, Reactor Construction Engineering Support Branch 80/11/18 3pp 07443 292

8101100722 Advises of review of uttl 000720 response to NRC 800413 order to show cause & responds to uttl 801024 corrective actions re safety-related complex concrete const Restart of work will be authorized by immediate action ltr
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/11/21 3pp 07444 313

8101100739 Forwards IE mgt Meeting Repts 50-498/80-37 & 50-499/80-37 on 801118 re noncompliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/24 1p 07444 058

--8101100766 IE mgt Meeting Repts 50-498/80-37 & 50-499/80-37 on re noncompliance noted Major areas discussed status of show cause order items & limited work restart
SEYFRIT, K V, CROSSMAN, W A Region 4, Dallas, Office of the Director, SEIDLE, W C Region 4, Dallas, Reactor Construction Engineering Support Branch 80/11/24 3pp 07444 059.

8101140548 Forwards IE Insp Repts 50-498/80-30 & 50-499/80-30 on 800201-31 No noncompliance noted
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/72 2pp 07461 132

8101140551 IE Insp Repts 50-498/80-30 & 50-499/80-30 on 801021-31 No noncompliance noted. Major areas inspected const activities. Unresolved items & site cost orders
HUBBARD W C Region 4, Dallas, Office of the Director
TAPLIN J L GILBERT L B Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/82 8pp 07461 134

8101050623 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor For Nuclear Discharge Vot at Dresden Unit 2" No response required
SEATTLE W C Region 4, Dallas, Office of the Director 80/12/08 1p 07391 059

8101060177 Forwards IE Info Notice 80-44, "Activation of ECCS in Anticipation Mode while in Hot Shutdown" No written response required
SEATTLE W C Region 4, Dallas, Office of the Director 80/12/16 1p 07391 204

8101070672 Ack receipt of 800710 ltr transmitting commitments in response to 800728 order to show cause 4, 800819 public meeting re violations in IE Insp Repts 50-498/79-19 & 50-499/79-19
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07350 062

8101270078 Forwards commitments in response to 800728 order to show cause & 800819 public meeting items classified into three categories
DPREA G W Houston Lighting & Power Co 80/09/18 4pp 07552 063

8101270087 Ack receipt of 800929 ltr providing updated response to IE Investigation Repts 50-498/79-19 & 50-499/79-19
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07375 163

8101270174 Update response to IE Investigation Repts 50-498/79-19 & 50-499/79-19 Full compliance w/commitment to add site auditors will not be met until 810101
DPREA G W Houston Lighting & Power Co 80/09/29 5pp 07375 164

8101140479 Ack receipt of 800928 ltr transmitting list of completed commitments in response to NRC 800430 order to show cause
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/23 1p 07458 147

8101140484 Forwards list of completed commitments to NRC 800430 order to show cause per discussions at close of 800819 public meeting
DPREA G W Houston Lighting & Power Co 80/08/23 3pp 07358 143

8101270904 Ack receipt of 800829 ltr transmitting documentation re mod of commitment dates to reflect work load of concrete placements in response to NRC 800430 order to show cause & IE Insp Repts 50-498/79-19 & 50-499/79-19
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/23 1p 07550 108

8101270917 Informs that amount of work required for order to show cause item 33 is greater than earlier anticipated Commitment dates modified.
DPREA G W Houston Lighting & Power Co 80/08/29 3pp 07550 109

8101200151 Ack receipt of 811 800909 ltr re vibratory rollers used for backfill compaction at facilities in response to NRC 800430 order to show cause info & corrective actions will be reviewed during future visits
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 81/01/13 1p 07309 031

8101002188 Forwards Dynapac rept, "Recent Developments in Field of Dynamic Compaction of Soil/Rock Fill & Asphalt," in response to NRC 800819 request for criteria re vibratory rollers used for backfill compaction at facilities
BARBER D G Houston Lighting & Power Co 80/09/09 4pp 07269 001

8101260176 Lectures entitled "Recent Developments in Field of Dynamic Compaction of Soil/Rock Fill & Asphalt," presented in Australia, Feb 1981
* Dynapac, Inc 1107 2 9-1613 76/02/27 27pp 07309 001

8101260177 "Vibratory Compaction in Const of Roads, Airfields & Other Projects"
* Dynapac, Inc 8222 77/02/28 25pp 07309

5 Reportable occurrences LERs & related correspondence

8101160354 Interim Deficiency Rept 2 re environ qualification electrical equipment associated w/auxiliary feedwater pumps. Analytical model for isolation valve cubicle structure has been developed. Next rept to be submitted by 810820
DPREA G W Houston Lighting & Power Co 81/01/09 4pp 0

8101160463 Interim deficiency rept re tensile strengths of 1-1/2 inch bolt expansion anchors. Revised load capacity values are reflected in revised technical ref document. Next rept to be submitted by 810220
DPREA G W Houston Lighting & Power Co 81/01/09 5pp 0

8101270403 PLO-IV-80-340 by 810108 ltr. Util requested Region 4 authority for restart of placement of copier concrete. Limited resumption of copier concrete placement authorized.
HUBBARD W C (CRISMAN) W A Region 4, Dallas, Office of the Director 81/01/13 1p 07557 057

8101270331 Final deficiency rept. Initially reported 800929 re cooling water intake structure gantry crane seismic analysis. SSE response spectra values incorrectly calculated. Crane & diesel generator fuel storage tanks requalified.
DPREA G W Houston Lighting & Power Co 81/01/15 5pp 0

8101270515 Second interim deficiency rept re welding of main & pipe whip restraints. Initially reported on 800926. Visual reinsp will determine if welds meet AWS D 1.1-1977 requirements. Next rept will be forwarded by 810501
DPREA G W Houston Lighting & Power Co 81/01/15 4pp 0

8101270718 Fifth interim deficiency rept re matl control of AS A990 structural steel bolts. Originally reported 800617. Required documentation to qualify bolts for Category 1 has been received. Final rept will be submitted by 810410
DPREA G W Houston Lighting & Power Co 81/01/20 4pp 0

800821 SH-50-499 SOUTH TEXAS PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8101050281 Informs of review of FSAR describing QA program w/ support of facility GL. Description of QA program in compliance w/regulations & guidelines.
HUBBARD W C Assistant Director for Materials & Qualification Engineering 80/11/18 2pp 07385 047

8101050288 Safety evaluation supporting operations phase QA
* Office of Nuclear Reactor Regulation, Director 80/11/07393 049

8101201466 Ltr to all power reactor licensees & applicants for summary of 80112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

8101270257 Ack receipt of 800924 ltr describing analysis & rect Dechtel recommendations requested by NRC during 800819 public meeting.
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07546 029

8101270657 Forwards util analysis & response to Dechtel recommendations made as result of 800819 public meeting.
DPREA G W Houston Lighting & Power Co 80/09/24 8pp 07546 030

8101270918 Ack receipt of 800922 ltr transmitting addl info re during 800912 meeting.
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07550 114

8101270924 Forwards addl info requested during 800912 meeting re examination, repair & restart of safety-related welding, concrete restart plans & schedules & intercom controls.
DPREA G W Houston Lighting & Power Co 80/09/22 13pp 07550 115

DOCKETED ITEMS

B0108013: Ack receipt of util B00904 documentation re complex concrete restart program & STP welding program per NRC B00430 order to show cause
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/23 1p 07421 061

--B01080140 Submits preliminary schedule for complex concrete restart program & STP welding program for reinspect & repair of existing welds & restart plan re safety-related AWS & ASME Welding Requests B00913 meeting in Arlington, TX
CPREA, G W Houston Lighting & Power Co 80/09/04 1p 07421 062

B01120388 Ack receipt of B00815 ltr forwarding concrete verification program status rpt in response to B00430 order to show cause Item 3h
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/23 1p 07439 119

--B01120391 Forwards concrete verification program status rpt in response to B00728 show cause order Item 3j
OPREA, G W Houston Lighting & Power Co 80/08/15 2pp 07439 120

--B01120393 "Concrete Verification Program" status rpt
Houston Lighting & Power Co 80/08/15, 41pp 07439 122.

B01270261 Notification of cancellation of B01026-28 meeting w/util in Houston & Bay City, TX to prepare SER input & hearing on rgt qualification
SELLE, D Licensing Branch 2 80/12/30 1p

B01300194 Confirms B0102 discussion & util B01217 & 30 ltrs re ASME safety-related welding 10-wk work plan & resumption of safety-related AWS welding work will commence B0105 ASME welding will be expanded as set forth in util B01217 ltr
SEYFRIT, K V Region 4, Dallas, Office of the Director 81/01/05 2pp 07582 131

B01210628 Confirms B0107 discussion of util B0108 ltr re actions taken in initiating complex concrete work activities. Util should inform NRC of plans to extend concrete placement beyond 7-h
SEYFRIT, K V Region 4, Dallas, Office of the Director 81/01/13 2pp 07489 250

E. NRC Safety Evaluation Report (SER), supp's & correspondence

B01100577 Notification of B01026 & 28 meeting in Houston, TX & B01027 meeting in Bay City, TX w/util to prepare SER input & to prepare for hearing on rgt qualification
SELLE, D Licensing Branch 2 80/12/30 3pp 07444 150

B01270261 Notification of cancellation of B01026-28 meeting w/util in Houston & Bay City, TX to prepare SER input & hearing on rgt qualification
SELLE, D Licensing Branch 2 80/12/30 1p 07546 038

F. Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP holders & CP Applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G. Adjudicatory correspondence

B012180257 FOIA request for V Stello closed door statement & items which were not included in show cause order re facility proceeding
EASTMAN, K Citizens Concerned About Nuclear Power, Inc. 80/10/29 1p 07271 346

B012180252 Responds to FOIA request for V Stello closed door statement & items which were not included in show cause order re facility proceeding Forwards B00415 transcript & NRC add'l response to requests for info
FELTON, J M Division of Rules and Records 89/12/11 1p 07271 345

--B012180263 Transcript of B00415 briefing in Bethesda, MD re investigation of OA-QC problems at facilities, Pp 1-72
Commissioners 89/04/15 73pp

--B012180549 Add'l response to Citizens Concerned About Nuclear Power, Inc. B01117 requests for info Inspector names withheld per 10CFR 2.70 V Stello statement encl items not encl in show cause order available in ECR w/Certificate of RVC
B04CEMICH, J M Hearing Branch 4 80/12/09 7pp 03774 301

B01230192 Third set of interrogatories to Citizens For Equitable Utils, Inc re intended witnesses & testimony re B010504 licensing hearing Certificate of RVC encl
HODSON, T R, LEWIS, J R Houston Lighting & Power Co HUDGINS, B Baker & Botts 81/01/16 3pp 07512 031

B01230198 Fourth set of interrogatories to Citizens Concerned About Nuclear Power, Inc re intended witnesses & testimony re B010504 licensing hearing Certificate of RVC encl
HODSON, T R, LEWIS, J R Houston Lighting & Power Co HUDGINS, B Baker & Botts 81/01/16 3pp 07512 037

B01280777 Requests external re file motion to compel answers to interrogatories or to compel production of documents within 10 days after appellant receives responses to interrogatories & other requests Certificate of RVC encl
HODSON, T R, LEWIS, J R Houston Lighting & Power Co HUDGINS, B Baker & Botts 81/01/16 12pp 07537 204

--B01290585 Second set of interrogatories & request to produce documents directed to Citizens For Equitable Utils Concerns SIP cost terms Certificate of RVC encl
HODSON, T R Houston Lighting & Power Co HUDGINS, T B Baker & Botts 80/12/05 3pp 07557 219

B01290149 Informs that review of applicant managerial responsibilities will be performed on B01217-19 & appropriate SER sections will be issued in Apr 1981 Hearings on QC/QA plans will be deferred until June 1981
REIBER, J Hearing Branch 3 81/01/26 2pp 07546 117

--B01290155 Advises of delay in preparation of Licensee Qualification Branch input re rgt qualification to SER
TEDESCO, R Assistant Director for Licensing 81/01/23 2pp 07546 319

B01290142 Forwards NRC transcript from B00819 public meeting in City, TX per ASME request during B0111V prehearing conference B/A encl
CUTLER, J M Hearing Branch 3 81/01/27 1p 07567 398

B01290222 Advises that NRC, by Commission directive, cannot provide transcripts during evidentiary hearings Comptroller General opinion encl
CUTLER, J M Hearing Branch 3 81/01/28 5pp 07309 001

I. Financial information

B01090023 Forwards annual repts for Houston Lighting & Power, Central Power & Light & financial statements for City of San Antonio, TX & City of Austin, TX
CULBERG, J M Houston Lighting & Power Co 80/12/31 1p 07517 045

O. Inspection reports, IF Bulletins & correspondence

B01100260 Forwards IE Insp Repts 50-498/80-35 & 50-499/80-35, on B01102-07 Noncompliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/19 2pp 07443 270

--B01160267 IE Insp Repts 50-498/80-35 & 50-499/80-35 on B01103-Noncompliance noted Major areas inspected Followup of most activities & review of responses to Insp Repts 50-498/79-19 & 50-499/79-19
HOLINSON, D P, CRIBBS, W A Region 4, Dallas, Office of the Director HALL, R E Region 4, Dallas, Reactor Construction Engineering Support Branch 80/11/10 3pp 07443 292

B01100072 Advises of review of util B00728 response to NRC B00415 order to show cause & responds to util B01024 corrective actions re safety-related complex concrete and Restart of work will be authorized by immediate action ltr
SELLE, D Office of Inspection & Enforcement, Office of the Director 80/11/21 3pp 07444 312

B01100759 Forwards IF Mgt Meeting Repts 50-498/80-37 & 50-499/80-37 B0111B Noncompliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/24 1p 07444 058

--B101100/56 IE Insp Repts 50-498/80-37 & 50-499/80-37 on 801118
to noncompliance noted Major areas discussed status of show
cause order items & limited work restart
SEIFRIT, K W CROSSMAN, W A Region 4, Dallas, Office of the
Director SEIDLE, W C Region 4, Dallas, Reactor Construction &
Engineering Support Branch 80/11/24 3pp 07444 059

B101140548 Forwards IE Insp Repts 50-498/80-30 & 50-499/80-30 on
801021-J1 No noncompliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/03 3pp 07461 132

--B101140556 IE Insp Repts 50-498/80-30 & 50-499/80-30 on 801021-J1 No
noncompliance noted Major areas inspected const activities,
unresolved items & show cause orders
HUZACHEM, W D Region 4, Dallas, Office of the Director
IAFIA, J J, GILBERT, I D Region 4, Dallas, Reactor Construction &
Engineering Support Branch 80/12/02 8pp 07461 134

B101050623 Forwards IE Info Notice 80-43, 'Failures of Continuous Water
Level Monitor for Steam Discharge Vol at Dresden Unit 2' No
response required
SEIFRIT, K W Region 4, Dallas, Office of the Director 80/12/08
1p 07391 059

B101060177 Forwards IE Info Notice 80-44, 'Actuation of ECCS in
Recirculation Mode While in Hot Shutdown' No written
response required
SEIFRIT, K W Region 4, Dallas, Office of the Director 80/12/16,
1p 07391 284

B101270872 Ack receipt of 800918 ltr transmitting commitments in
response to 800728 order to show cause & 800819 public
meeting re violations in IE Insp Repts 50-498/79-19 &
50-499/79-19
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/16 1p 07550 062

--B101270876 Forwards commitments in response to 800728 order to show
cause & 800819 public meeting items classified into three
categories.
OPREA, G W Houston Lighting & Power Co 80/09/18, 41pp
07550 063

B101290487 Ack receipt of 800929 ltr providing updated response to IE
Investigation Repts 50-498/79-19 & 50-499/79-19
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/16 1p 07575 163

--B101290494 Updates response to IE Investigation Repts 50-498/79-19 &
50-499/79-19 Full compliance w/commitment to add title
auditors will not be met until 810101
OPREA, G W Houston Lighting & Power Co 80/09/29 5pp
07575 164

B101140479 Ack receipt of 800828 ltr transmitting list of completed
commitments in response to NRC 800430 order to show
cause
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/23 1p 07458 147

--B101140484 Forwards list of completed commitments to NRC 800430 order
to show cause, per discussions at close of 800819 public
meeting
OPREA, G W Houston Lighting & Power Co 80/08/28 3pp
07458 148

B101270904 Ack receipt of 800829 ltr transmitting documentation re need
of commitment dates to reflect work load of concrete
placements, in response to NRC 800430 order to show cause
& IE Insp Repts 50-498/79-19 & 50-499/77-14
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/23 1p 07550 108

--B101270909 Informs that amount of work required for order to show cause
item 33 is greater than earlier anticipated Commitment dates
modified
OPREA, G W Houston Lighting & Power Co 80/08/29 3pp
07550 109

B101260161 Ack receipt of util 800909 ltr re vibratory rollers used for
backfill compaction at facilities, in response to NRC 800430
order to show cause Info & corrective actions will be
reviewed during future insps
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 81/01/13 1p 07309 001

--B101330168 Forwards Dynaspec rept, 'Recent Developments in Field
Dynamic Compaction of Soil, Rock Fill & Asphalt.' in response
to NRC 800819 request for criteria re vibratory rollers
used for backfill compaction at facilities
BARBER, D C Houston Lighting & Power Co 80/09/09 4pp
07309 021

--B101330176 Lectures entitled 'Recent Developments in Field of
Compaction of Soil, Rock Fill & Asphalt.' presented in
Australia, Far East & Iran
* Dynaspec, Inc 1113-7 9-1613 76/02/29 27pp 07309 001

--B101330182 'Vibratory Compaction in Const of Roads, Airfields, D
Other Projects'
FORSEBERG, L Dynaspec, Inc 8222 77/02/28 25pp 07309 001

5 Reportable occurrences, LERs & related correspondence

B101160454 Interim deficiency Rept 2 re environ qualification of
electrical equipment associated w/auxiliary feedwater pump.
Analytical model for isolation valve cubic structure has
been developed Next rept to be submitted by 810820
OPREA, G W Houston Lighting & Power Co 81/01/09 4pp 074

B101160460 Interim deficiency rept re tensile strengths of 1-inch
bolt-weld expansion anchors Revised load capacity values
are reflected in revised technical ref document Next rept
to be submitted by 010320
OPREA, G W Houston Lighting & Power Co 81/01/09 5pp 074

B101280403 PKO-IV-00-340 by B10108 ltr, util requested Region 4
authority for limited restart of placement of complex
concrete Limited resumption of complex concrete placement
authorized
HUZACHEM, W D, CROSSMAN, W A Region 4, Dallas, Office of the
Director 81/08/13 1p 07597 057

B101220331 Final deficiency rept, initially reported 800829, re
cooling water intake structure gentry crane seismic
analysis SSE response spectra values incorrectly calculated
Crane & diesel generator fuel storage tanks requalified
OPREA, G W Houston Lighting & Power Co 81/01/15 5pp 075

B101220515 Second interim deficiency rept re welding of main steam
pipe whip restraints, initially reported on 800926 Visual
reinsp will determine if welds meet AWS D 1.1-1977
requirements Next rept will be forwarded by 810901
OPREA, G W Houston Lighting & Power Co 81/01/15 4pp 075

B101270718 Fifth interim deficiency rept re natl control of ASTM
A490 structural steel bolts, originally reported 800617
Required documentation to qualify bolts for Category 1 has
been received Final rept will be submitted by 810410.
OPREA, G W Houston Lighting & Power Co 81/01/20 4pp 075

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220468 Ltr to all power reactor licensees & applicants for
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lameillac Tracing on Component Supports."
EISENHUT, D G Division of Licensing 80/11/26 8pp.

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants at part of FBAR.
EISENHUT, D G Division of Licensing 80/11/13 2pp.

G Adjudicatory correspondence

B101060910 Order compelling NRC & applicant to file detailed br
by 810219 re steps necessary to complete termination of
proceeding & estimated dates of completion.
COTTER, B P Atomic Safety and Licensing Board Panel 80/12/1
07401:089

D-501 DAVIS-3F5SF NUCLEAR POWER STATION, UNIT 3

ation/construction stage documents & correspondence

6 Ltr to all power reactor licensees & applicants forwarding
of B01112 meeting re implementation of guidance for
ved Safety Issue A-12: "Potential for Low Fracture
ss & Lamellar Tearing on Component Supports"
T.D.O. Division of Licensing 80/11/26 0pp

ty, medical, emergency & fire protection plans

7 Ltr to all licensees of operating reactor plants, CP holders
applicants Revised radiological emergency response
must be submitted by licensees within 60 days of
& by applicants as part of FSAR
T.D.O. Division of Licensing 80/11/13 2pp

atory correspondence

O Order compelling NRC & applicant to file detailed briefs
19 re steps necessary to complete termination of
ing & estimated dates of completion
B P Atomic Safety and Licensing Board Panel 80/12/31 1p
089

N-50-500 WPPSS NUCLEAR PROJECT, UNIT 3

ation/construction stage documents & correspondence

6 Ltr to all power reactor licensees & applicants forwarding
of B01112 meeting re implementation of guidance for
ved Safety Issue A-12: "Potential for Low Fracture
ss & Lamellar Tearing on Component Supports"
T.D.O. Division of Licensing 80/11/26 8pp

ty, medical, emergency & fire protection plans

7 Ltr to all licensees of operating reactor plants, CP holders
applicants Revised radiological emergency response
must be submitted by licensees within 60 days of
& by applicants as part of FSAR
T.D.O. Division of Licensing 00/11/13 2pp

tion reports, IE Bulletins & correspondence

O Forwards IE Info Notice 80-43: "Failures of Continuous Water
Monitor for Steam Discharge Vol at Dresden Unit 2"
onse required
N.R.H. Region 5, San Francisco, Office of the Director
9 1p 07390 277

9 Forwards IE Info Notice 80-44: "Actuation of ECCB in
lation Mode While in Hot Shutdown." No response
d.
N.R.H. Region 5, San Francisco, Office of the Director
6 1p 07308 001

O Ack receipt of B01219 ltr informing NRC of steps taken to
violations noted in IE Insp Repts 50-508/80-12
9/80-12 Add'l beam clip will be added to safety-
duct
J.G.B. Region 5, San Francisco, Reactor Construction &
ring Support Branch 81/01/12 1p 07497 298

25 Responds to NRC B01126 ltr re violations noted in IE Insp
50-500/80-12 & 50-509/80-12 Corrective actions
nforming Wallace/Superior Procedure, OCP 12-12, revised
EE.F.O. Washington Public Power Supply System 80/12/19
07497 299

531 Forwards IE Insp Repts 50-508/80-12 & 50-509/80-12 on
1-24 & notice of violation
KEN, R.H. Region 5, San Francisco, Office of the Director
7/26 2pp 07497 303

535 Notice of violation from Insp on B01021-24
gion 5, San Francisco, Office of the Director 80/11/26 1p
7 305

543 IE Insp Repts 50-508/80-12 & 50-509/80-12 on B01021-24
pliance noted nonconforming conditions by heating,
lation & air conditioning contractor not controlled
S.R.C. Region 5, San Francisco, Reactor Construction &
Engineering Support Branch, HAIST, D.P., WADNER, W.J. Region 5, San
isco, Office of the Director 80/11/26 8pp 07497 306

S Reportable occurrences, LERs & related correspondence

B01220730 Part 21 rept re failure to provide proper Control Components
Intl valves supplying 2 gpm flow when in closed position
Caused by valve failure Affected licensees notified &
selection of alternative method underway
TAYLOR, J.H. Babcock & Wilcox Co 81/01/09 2pp

DOCKET 50-509 WPPSS NUCLEAR PROJECT, UNIT 5

A Application/construction stage documents & correspondence

B01220165 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unsolved Safety Issue A-12: "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT D.O. Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

B01079087 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B01012 & 5; applicants as part of FSAR
EISENHUT, D.O. Division of Licensing 80/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

B01056510 Forwards IE Info Notice 80-43: "Failures of Continuous Water
Level Monitor for Steam Discharge Vol at Dresden Unit 2"
No response required
ENGELKEM, R.H. Region 5, San Francisco, Office of the Director
80/12/05 3p

B01150835 Forwards IE Info Notice 80-44: "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No response
required
ENGELKEM, R.H. Region 5, San Francisco, Office of the Director
80/12/16 1p 07308 031

B01220520 Ack receipt of B01219 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-508/80-12
& 50-509/80-12 Add'l beam clip will be added to safety-
related duct
SPENCER, J.S. Region 5, San Francisco, Reactor Construction &
Engineering Support Branch 81/01/12 1p 07497 298

--B01220525 Responds to NRC B01126 ltr re violations noted in IE Insp
Repts 50-508/80-12 & 50-509/80-12 Corrective actions
nonconforming Wallace/Superior Procedure, OCP 12-12, revised
MCLELLAN, F.D. Washington Public Power Supply System 80/12/19
4pp 07497 299

--B01220531 Forwards IE Insp Repts 50-508/80-12 & 50-509/80-12 on
B01021-24 & notice of violation
ENGELKEM, R.H. Region 5, San Francisco, Office of the Director
80/11/26 2pp 07497 303

--B01220535 Notice of violation from Insp on B01021-24
* Region 5, San Francisco, Office of the Director 80/11/26 1p
07497 305

--B01220543 IE Insp Repts 50-508/80-12 & 50-509/80-12 on B01021-24
Noncompliance noted nonconforming conditions by heating,
ventilation & air conditioning contractor not controlled
HAYNES, R.C. Region 5, San Francisco, Reactor Construction &
Engineering Support Branch, HAIST, D.P., WADNER, W.J. Region 5, San
Francisco, Office of the Director 80/11/26 8pp 07497 306

S Reportable occurrences, LERs & related correspondence

B01230730 Part 21 rept re failure to provide proper Control Components
Intl valves supplying 2 gpm flow when in closed position
Caused by valve failure Affected licensees notified &
selection of alternative method underway
TAYLOR, J.H. Babcock & Wilcox Co 01/01/09 2pp

DOCKET 50-510 BLUE HILLS STATION, UNIT 1

G Adjudicatory correspondence

B01280304 Response to ASLO 800909 order requesting briefs & add'l info
re early site review portion of CP application issues
identified in order do not affect issuance of partial
initial decision Certificate of SVC encl
WETTERHAHN, J.J., PLETTMAN, B. Gulf States Utilities Co.
WETTERHAHN, J.J. Conner, Moore & Corbin 81/01/23 7pp 07557 154

BUCKET 50-511 BUREAU HILLS STATION UNIT 2

C Adjudicatory correspondence

BIO1280304 Response to ASLB 800909 order requesting briefs & addl info re early site review portion of CP application issues identified in order to not affect issuance of partial initial decision Certificate of SVC encl
HESTERMAN, J. RICHMAN S Gulf States Utilities Co
HESTERMAN, J. Conner, Moore & Corber 81/01/23 7pp 07557 154

BUCKET 50-512 LAGUNA VERDE STATION

A Inspection reports, IE Bulletins & correspondence

BIO1280419 Updates licensee corrective actions following NRC 800707-11 trip of Unit 2 of Engineering Design Organization construction to provide sufficient organizational freedom, authority & access to NRC
KIPPON, S. H Tennessee Valley Authority 80/10/03 3pp

BUCKET 50-513 SPRING SPRINGS NUCLEAR PROJECT, UNIT 4

A Application/construction stage documents & correspondence

BIO1280466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

BIO1041587 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01022 by applicants as part of FSAR
EISENHUT, D G Division of Licensing 30/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

BIO1041587 Forwards supplemental response to IE Bulletin 79-02: Revision 2 "Triple Support Base Plate Designs Using Concrete Expansion Anchor Bolts"
HARRIS, D W Washington Public Power Supply System 80/11/13 3pp 07397 119

BIO1050510 Forwards IE Info Notice 80-43: "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2"
No response required
EISENHUT, D G Region 5, San Francisco, Office of the Director 80/12/05 1p

BIO1159937 Forwards IE Info Notice 80-44: "Activation of ECCS in Recirculation Mode While in Hot Shutdown." No response required
EISENHUT, D G Region 5, San Francisco, Office of the Director 80/12/16 1p 07308 031

BIO1206534 Ack receipt of B01212 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-460/80-13 & 50-513/80-13
SPENCER, S S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 81/01/26 1p 07386 041

--BIO1300555 Responds to NRC B01121 ltr re violations noted in IE Insp Repts 80-460/80-13 & 50-513/80-13 Corrective actions QA personnel will provide procurement controls for rail substitutions
HARRIS, D W Washington Public Power Supply System 80/12/12 4pp 07586 042

--BIO1300593 Forwards IE Insp Repts 80-460/80-13 & 50-513/80-13 on B01020-23 & notice of violation
SPENCER, S S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/11/21 2pp 07586 046

--BIO1300598 Notice of violation from Insp on B01020-23
Region 5, San Francisco, Office of the Director 80/11/21 1p 07586 048

--BIO1302604 IE Insp Repts 80-460/80-13 & 50-513/80-13 on B01020-23 Noncompliance noted failure to provide adequate procurement controls for paint to be used within containment.
HARRIS, D W KINSEID, D P HARRIS, D P Region 5, San Francisco, Office of the Director 80/11/21 10pp 07586 049

S Requirable occurrences, LEAs & related correspondence

BIO1280430 Part 21 report re failure to provide proper Control Control valves supplying 2 gpm flow when in closed position caused by valve failure Affected licensees notified & selection of alternative method underway
TAYLOR, J H Babcock & Wilcox Co 81/01/09 2pp

BUCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

BIO1280466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

BIO1090287 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01022 by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G Adjudicatory correspondence

BIO1070169 Fourth status report per ASLB 800721 order Applicant proposed findings of fact & conclusions of law on B01022 NRC filed same on B01202 Certificate of SVC encl
SCORDELL, R M Hearing Branch 4 80/12/31 4pp 07415 122

U Congressional/Executive Correspondence

BIO1080314 Responds to B01009 ltr re NRC progress in review of CP of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance W/o encl documentation
AHEARN, J F Commissioners 80/12/22 4pp

--BIO1080362 Responds to B01009 ltr re NRC progress in review of CP of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance Related documentation encl
AHEARN, J F Commissioners 80/12/22 4pp

BUCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

BIO1280466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

BIO1090287 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01022 by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G Adjudicatory correspondence

BIO1070169 Fourth status report per ASLB 800721 order Applicant proposed findings of fact & conclusions of law on B01022 NRC filed same on B01202 Certificate of SVC encl
SCORDELL, R M Hearing Branch 4 80/12/31 4pp 07415 122

U Congressional/Executive Correspondence

BIO1080314 Responds to B01009 ltr re NRC progress in review of CP of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance W/o encl documentation
AHEARN, J F Commissioners 80/12/22 4pp

--BIO1080362 Responds to B01009 ltr re NRC progress in review of CP of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance Related documentation encl
AHEARN, J F Commissioners 80/12/22 4pp

50-516 JAMESPORT NUCLEAR STATION, UNIT 1

 latory correspondence

3 Response supporting applicants B01219 request to end pending
 & CP proceedings Outstanding CPs should be revoked
 date of Svc encl
 CA, B M Hearing Branch 4 B1/01/08 6pp 07445 171

7 Memorandum & order granting applicants' motion to dismiss
 ASLB decision authorizing const is vacated due to
 as CP proceeding terminated Ofc of Nuclear Reactor
 tion will revoke CPs Certificate of Svc encl
 C J Atomic Safety and Licensing Appeal Panel B1/01/15
 7486 334

tion reports, IE Bulletins & correspondence

4 Forwards Suppl 1 to IE Info Notice B0-29, "Broken Studs on
 Turbine Steam Inlet Flange " No written response
 d
 H Region 1, Philadelphia, Office of the Director
 6 1p 07414 071

3 Forwards IE Info Notice B0-44, "Actuation of ECCB in
 lation Mode While in Hot Shutdown " No written
 e required
 H Region 1, Philadelphia, Office of the Director
 6 1p 07397 014

50-517 JAMESPORT NUCLEAR STATION, UNIT 2

 latory correspondence

3 Response supporting applicants B01219 request to end pending
 & CP proceedings Outstanding CPs should be revoked
 date of Svc encl
 CA, B M Hearing Branch 4 B1/01/08 6pp 07445 171

7 Memorandum & order granting applicants' motion to dismiss
 ASLB decision authorizing const is vacated due to
 as CP proceeding terminated Ofc of Nuclear Reactor
 tion will revoke CPs Certificate of Svc encl
 C J Atomic Safety and Licensing Appeal Panel B1/01/15
 7486 334

tion reports, IE Bulletins & correspondence

4 Forwards Suppl 1 to IE Info Notice B0-29, "Broken Studs on
 Turbine Steam Inlet Flange " No written response
 d
 H Region 1, Philadelphia, Office of the Director
 6 1p 07414 071

3 Forwards IE Info Notice B0-44, "Actuation of ECCB in
 lation Mode While in Hot Shutdown " No written
 e required
 H Region 1, Philadelphia, Office of the Director
 6 1p 07397 029

50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

 tion/construction stage documents & correspondence

6 Ltr to all power reactor licensees & applicants forwarding
 of B01112 meeting re implementation of guidance for
 ved Safety Issue A-12, "Potential for Low Fracture
 ss & Lamellar Tearing on Component Supports "
 T.D O Division of Licensing B0/11/26 6pp

7 Forwards Amends 4 to CPR-150, CPR-151, CPR-152 & CPR-153
 UCR.A Licensing Branch 2 B0/12/29 4pp 07477 261

563 Amends 4 to CPR-150, CPR-151, CPR-152 & CPR-153, deleting
 rements for monitoring primary water quality & const
 to determine impact on water quality & aquatic biota
 Cumberland River
 UCR.A Licensing Branch 2 B0/12/29 4pp 07477 265

567 Notice of issuance of Amends 4 to CPR-150, CPR-151 &
 152 & CPR-153
 UCR.A Licensing Branch 2 B0/12/29 2pp 07477 267

B0121042 Advises that AINT issue will be subj of future ruling on
 determine requirements & schedules for plant needs NRC will
 not comment until B00717 etc determining program for
 resolving issue until resolution is finalized
 EISENHUT, D O Division of Licensing B0/12/29 2pp

B0129045 Summary of B01114 meeting w/Hartsville Project Coordination
 Committee & will re data relationship Committee dissatisfied
 w/recent later layoffs technical advice & financial support
 for interconnecting water sys requested
 WCLLSEA, S Licensing Branch 2 B1/01/14 4pp 07575 153

Security, medical, emergency & fire protection plans

B0109039 Ltr to all licensees of operating reactor plants, CP holders
 & CP applicants Revised radiological emergency response
 plans must be submitted by licensees within 60 days of
 B01021 by applicants as part of FSAR
 EISENHUT, D O Division of Licensing B0/11/13 2pp

B0121010 Transcript of B01217 briefing on TVA emergency offsite
 facilities in Washington, DC Pg 1-45
 * Commissioners B0/12/17 49pp

Inspection reports, IE Bulletins & correspondence

B0110064 Forwards IE Insp Repts 50-518/B0-23, 50-519/B0-22,
 50-520/B0-23 & 50-521/B0-21 on B00429-1078 No noncompliance
 noted
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch B0/11/26 2pp 07444 143

--B0110067 IE Insp Repts 50-518/B0-23, 50-519/B0-22, 50-520/B0-23 &
 50-521/B0-21 on B00429-1078 No noncompliance noted Major
 areas inspected A-2 & 3-1 reactor pressure vessel storage
 & open item review
 SMAY, W B Region 2, Atlanta, Office of the Director
 CANIRELL, F B Region 2, Atlanta, Reactor Construction &
 Engineering Support Branch B0/11/26 5pp 07444 145

B01050598 Forwards IE Info Notice B0-43, "Failures of Continuous Water
 Level Monitor for Scram Discharge Vpl at Dresden Unit 2 " No
 response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director B0/12/30
 1p

B01086267 Ack receipt of B00472 & 1027 ltr informing NRC of steps
 taken to correct violation noted in IE Insp Repts
 50-518/B0-17 & 50-520/B0-17 Disagrees w/response refuting
 items of noncompliance
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch B0/12/05 4pp 07421 663

--B01060292 Forwards add response to NRC B00828 ltr re violations noted
 in IE Insp Repts 50-518/B0-17 & 50-520/B0-17 Re-evaluation
 supports previous disagreement w/items of noncompliance
 MILLER, M Tennessee Valley Authority B0/10/27 3pp
 07421 067

--B01080307 Resps to NRC B00828 ltr re violations noted in IE Insp
 Repts 50-518/B0-17 & 50-520/B0-17 Disagrees that magnetic
 particle examination procedure was in violation of ASME
 requirements
 MILLER, M Tennessee Valley Authority B0/09/22 6pp
 07421 070

--B01080318 Forwards IE Insp Repts 50-518/B0-17 & 50-520/B0-17 on
 B00801-08 & notice of violation
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch B0/08/28 2pp 07421 076

--B01060326 Notice of violation from insp on B00304-08
 * Region 2, Atlanta, Office of the Director B0/08/27 1p
 07421 076

--B01060343 IE Insp Repts 50-518/B0-17 & 50-520/B0-17 on B00804-08
 noncompliance noted inadequate magnetic particle examination
 program & qualification requirements for visual examiners
 ZACARI, D Region 2, Atlanta, Office of the Director HERD, A R
 Region 2, Atlanta, Reactor Construction & Engineering Support
 Branch B0/09/27 6pp 07421 079

B01060153 Forwards IE Info Notice B0-45, "Potential Failure of BWR
 Backup Manual Scram Capability " No response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director B0/12/17
 1p

810106024 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/18
1p 07-12 217

8101090217 Forwards IE Bulletin 80-25. "Operating Problems w/Target Rock Safety Relief Valves at BWRs" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/19
1p 07389 055

8101290544 Forwards IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-14 & 50-521/80-17 on 801028-31 No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/19 2pp 07575 257

8101290549 IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-14 & 50-521/80-17 on 801028-31 No noncompliance noted Major areas inspected not controls, CP environment conditions & commitments & status of site spill program
CUMMINGS, G R Region 2, Atlanta, Office of the Director 80/12/19 2pp 07575 259

8101190051 Forwards response to IE Bulletin 80-23 re failure of Valcor Engineering Corp solenoid valves Valcor solenoid valves 070900-71 1 1 070900-21-3 not used Util waiting for vendor response re valves in package components
MILLS, L M Tennessee Valley Authority 80/12/29 2pp 07475 215

8101190135 Responds to IE Bulletin 80-21. Valve Voles Supplied by Malcolm Foundry Co, Inc. Util awaiting vendor response that parts do not contain Malcolm Foundry voles Final rept will be filed by 010517
MILLS, L M Tennessee Valley Authority 81/01/05 1p 07307 001

B. Reportable occurrences, IERs & related correspondence

8101230718 Final Part 21 rept re cracks in reactor pressure vessel shield wall inner shell plates, initially reported on 800314. Cause not determined Shield wall repaired w/GE-approved metal & welding procedures changed
MILLS, L M Tennessee Valley Authority 80/12/31 3pp 07308 001

8101140499 Interim Deficiency Rept 1 re fillet weld misspecification American list of Steel Const stds are being evaluated
Initially reported on 801208
MILLS, L M Tennessee Valley Authority 81/01/07 2pp 07308 001

8101210240 First interim deficiency rept re pressure drop in essential svc water piping, initially reported on 801210 Util is reanalyzing essential svc water piping & high pressure fire protection piping Final rept will be submitted by 810320
MILLS, L M Tennessee Valley Authority 81/01/12 3pp 07489 077

8101220311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to 810104 11p Addl info to be provided by 810211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

8101230426 Second supplemental deficiency rept, originally reported on 800618, re heaters omitted from motor operator GE anticipates shipping deficient motor replacements by 811001
MILLS, L M Tennessee Valley Authority 01/01/15 1p 07308 001

8101290489 Corrects numbers on Util 810107 & 12 interim deficiency repts re pressure drop in essential svc water piping & standby gas treatment design deficiency
MILLS, L M Tennessee Valley Authority 81/01/20 1p 07566 325

DOCKET 81N-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8101290466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHART, D G Division of Licensing 80/11/26 8pp

8101290557 Forwards Amdts 4 to CPR-150, CPR-151, CPR-152 & CPR-153
SCHWENKER, A Licensing Branch 2 80/12/29 4pp 07477 261

8101290563 Amdts 4 to CPR-150, CPR-151, CPR-152 & CPR-153, deleting requirements for monitoring primary water quality & const effects to determine impact on water quality & aquatic biota of Cumberland River

8101290567 Notice of issuance of Amdts 4 to CPR-150, CPR-152 & CPR-153
SCHWENKER, A Licensing Branch 2 80/12/29 2pp

8101290447 Advises that AWC issue will be subj of future determine requirements & schedules for plant mods NRC not comment on Util 800617 ltr describing program for resolving issue until rulemaking is finalized
EISENHART, D G Division of Licensing 80/12/29 2pp

8101290485 Summary of 801114 meeting w/Hartsville Project Committee & Util re work relationship Committee disapproved labor layoffs Technical advice & financial aid for interconnecting water sys requested
EISENHART, D G Licensing Branch 2 81/01/14 4pp 07

F. Security, medical, emergency & fire protection plans

8101090367 Ltr to all licensees of operating reactor plants & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHART, D G Division of Licensing 80/11/13 2pp

8101210407 Transcript of 801217 briefing on TVA emergency facilities in Washington, DC Pp 1-43
Commissioners 80/12/17 49pp

G. Inspection reports, IE Bulletins & correspondence

8101140619 Updates licensee corrective actions following inspg of Util Div of Engineering Design OA organization restructured to provide sufficient organizational freedom & access to mgmt
KIMMICH, S G H Tennessee Valley Authority 80/10/08

8101100664 Forwards IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-23 & 50-521/80-21 on 800929-1028 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 80/11/26 2pp 07444 143

8101100672 IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-21 on 800929-1028 No noncompliance noted areas inspected A-2 & B-1 reactor pressure vessel & open item review
SWAN, W B Region 2, Atlanta, Office of the Director 8101100672 IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-21 on 800929-1028 No noncompliance noted areas inspected A-2 & B-1 reactor pressure vessel & open item review
CARTER, F S Region 2, Atlanta, Reactor Construction Engineering Support Branch 80/11/26 5pp 07444

8101050388 Forwards IE Info Notice 80-43. "Failures of Level Monitor for Scram Discharge Val at Dresden Unit" response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 1p

8101050153 Forwards IE Info Notice 80-45. "Potential Failure Backup Manual Scram Capability" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 1p

8101070023 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of Control Rods to Fully Insert During Scram at BWR" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 1p 07413 317

8101050217 Forwards IE Bulletin 80-25. "Operating Problems Rock Safety Relief Valves at BWRs" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 1p 07389 055

8101290544 Forwards IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-14 & 50-521/80-17 on 801028-31 No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Branch 80/12/19 2pp 07575 257

8101290549 IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-14 & 50-521/80-17 on 801028-31 No noncompliance noted Major areas inspected not controls, CP environment conditions & commitments & status of site spill program
CUMMINGS, G R Region 2, Atlanta, Office of the Director 80/12/19 2pp 07575 259

8101190651 Forwards response to IE Bulletin 80-23 re failure of Valcor Engineering Corp solenoid valves Valcor solenoid valves V70900-21-1 & V70900-21-3 not used Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/29 3pp 07475 215

8101290236 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Util awaiting vendor response that parts do not contain Malcolm Foundry yokes Final rept will be filed by 810527
MILLS, L M Tennessee Valley Authority 81/01/05 1p 07309 001

B Reportable occurrences, LERs & related correspondence

8101140499 Interim Deficiency Rept 1 re fillet weld mis-specification American Inst of Steel Const stds are being evaluated.
Originally reported on 801208
MILLS, L M Tennessee Valley Authority 81/01/07 2pp 07308 001

8101210390 First interim deficiency rept re pressure drop in essential svc water piping, initially reported on 801240 Util is re-analyzing essential svc water piping & high pressure fire protection piping Final rept will be submitted by 810320
MILLS, L M Tennessee Valley Authority 81/01/12 3pp 07489 077

8101220311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to 801104 ltr Addl info to be provided by 810211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

8101290489 Corrects numbers on util 810109 & 12 interim deficiency repts re pressure drop in essential svc water piping & standby gas treatment design deficiency
MILLS, L M Tennessee Valley Authority 81/01/20 1p 07566 325

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8101220166 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101200957 Forwards Amends 4 to CPPR-150, CPPR-151, CPPR-152 & CPPR-153
SCHWENCER, A Licensing Branch 2 80/12/29 4pp 07477 261

--8101200953 Amends 4 to CPPR-150, CPPR-151, CPPR-152 & CPPR-153, deleting requirements for monitoring primary water quality & const effects to determine impact on water quality & aquatic biota of Cumberland River
SCHWENCER, A Licensing Branch 2 80/12/29 4pp 07477 265

--8101200957 Notice of Issuance of Amends 4 to CPPR-150, CPPR-151 & CPPR-152 & CPPR-153
SCHWENCER, A Licensing Branch 2 80/12/29 2pp 07477 269

8101210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mode NRC will not comment on util 800917 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT, D O Division of Licensing 80/12/29 2pp

8101290485 Summary of 801114 meeting w/Hartsville Project Coordination Committee & util re work relationship Committee dissatisfied w/recent labor layoffs Technical advice & financial support for interconnecting water sys requested
KEBLUSEK, S Licensing Branch 2 81/01/14 4pp 07575 153

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101210607 Transcript of 801217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45
* Commissioners 80/12/17 47pp

D Inspector reports, IE Bulletins & correspondence

8101140619 Updates licensee corrective actions following NRC 800701 rept of Util Div of Engineering Design On organization restructured to provide sufficient organizational freedom, authority & access to NRC
KIMMIS, G H Tennessee Valley Authority 80/10/08 3pp

8101106561 Forwards IE Insp Repts 50-510/80-23, 50-519/80-22, 50-520/80-23 & 50-521/80-21 on 800927-1028 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/16 2pp 07444 143

--8101106562 IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-23 & 50-521/80-21 on 800929-1028 No noncompliance noted Major areas inspected A-2 & 3-1 reactor pressure vessel storage & open item review
S/M/M/M Region 2, Atlanta, Office of the Director
CARELL, F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/26 5pp 07444 145

8101650588 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Steam Discharge Val at Dresden Unit 2" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p

8101060667 Ack receipt of 800922 & 1027 ltrs informing NRC of steps taken to correct violation noted in IE Insp Repts 50-516/80-17 & 50-520/80-17 Disagrees w/response refuting items of noncompliance
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/05 4pp 07421 063

--8101060792 Forwards addl response to NRC 800628 ltr re violation in IE Insp Repts 50-518/80-17 & 50-520/80-17 Re-evaluation supports previous disagreement w/items of noncompliance
MILLS, L M Tennessee Valley Authority 80/10/27 3pp 07421 067

--8101060797 Responses to NRC 800628 ltr re violations noted in IE Repts 50-518/80-17 & 50-520/80-17 Disagrees that magnetic particle examination procedure was in violation of ASME requirements
MILLS, L M Tennessee Valley Authority 80/09/22 4pp 07421 070

--8101080318 Forwards IE Insp Repts 50-518/80-17 & 50-520/80-17 on 800804-08 ltr notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/28 2pp 07421 076

--8101080326 Notice of violation from insp on 800804-08
* Region 2, Atlanta, Office of the Director 80/08/27 1p 07421 078

--8101080343 IE Insp Repts 50-518/80-17 & 50-520/80-17 on 800804-08 Noncompliance noted, inadequate magnetic particle examination program & qualification requirements for visual examiners
ZAJAC, L D Region 2, Atlanta, Office of the Director
HERDI, Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/27 4pp 07421 074

8101060153 Forwards IE Info Notice 80-45, "Potential Failure of BW Backup Manual Steam Capability" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p

8101070023 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 Control Rods to Fully Insert During Scram at BWR" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p 07412 317

8101050217 Forwards IE Bulletin 80-25, "Operating Problems w/Targ Rock Safety Relief Valves at BWRs" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p 07389 055

8101290544 Forwards IE Insp Repts 50-510/80-19, 50-519/80-18, 50-520/80-19 & 50-521/80-17 on 801028-31 No noncompliance noted
S/M/R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/19 2pp 07575 297

-B101290519 IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-17 & 50-521/80-17 on B01028-31 No noncompliance noted Major areas inspected mgt controls, CP environ conditions & commitments & status of spill spill program
CUMMINGS, A L Region 2, Atlanta, Office of the Director
JENNINGS, R R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/19 2pp 07575 259

B10190051 Forwards response to IE Bulletin 80-23 re failure of Valcor Engineering Corp solenoid valves Valcor solenoid valves
W2900-21-1 & W2900-21-3 not used Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/29 2pp 07475 215

B101290736 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc. Util awaiting vendor response that parts do not contain Malcolm Foundry yokes Final rept will be filed by B10527
MILLS, L M Tennessee Valley Authority 81/01/05 1p 07309 001

S Reportable occurrences, LERs & related correspondence

B10140499 Interim deficiency Rept 1 re fillet weld misspecification American Inst of Steel Const stds are being evaluated
Originally reported on B01208
MILLS, L M Tennessee Valley Authority 81/01/07 2pp 07308 001

B101210390 First interim deficiency rept re pressure drop in essential svr water piping, initially reported on B01210 Util is reanalyzing essential svr water piping & high pressure fire protection piping Final rept will be submitted by B10320
MILLS, L M Tennessee Valley Authority 81/01/12 3pp 07489 077

B101270311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to B01104 Ltr Addl info to be provided by B10211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

B101290469 Corrects numbers on util B10109 & 12 interim deficiency repts re pressure drop in essential svr water piping & standby gas treatment design deficiency
MILLS, L M Tennessee Valley Authority 81/01/20 1p 07866 325

BUCKET 518-50-571 HARTSVILLE NUCLEAR PLANT, UNIT 4

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-11, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

B101207557 Forwards Amends 4 to CFRP-150, CFRP-151, CFRP-152 & CFRP-153
SCHWENGER, A Licensing Branch 2 80/12/29 4pp

--B101260543 Amends 4 to CFRP-150, CFRP-151, CFRP-152 & CFRP-153, deleting requirements for monitoring primary water quality & const effects to determine impact on water quality & aquatic biota of Cumberland River
SCHWENGER, A Licensing Branch 2 80/12/29 4pp

--B101200567 Notice of issuance of Amends 4 to CFRP-150, CFRP-151 & CFRP-152 & CFRP-153
SCHWENGER, A Licensing Branch 2 80/12/29 2pp

B101210642 Advises that ATUS issue will be subj of future rulemaking to determine requirements & schedules for plant mods NRC will not comment on util B06917 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT, D G Division of Licensing 80/12/29 2pp

B101290485 Summary of B01114 meeting w/Hartsville Project Coordination Committee & util re work relationship Committee dissatisfied w/recent labor layoffs Technical advice & financial support for interconnecting water sys requested
REILUSEN, B Licensing Branch 2 81/01/14 4pp

F Security, medical, emergency & fire protection plans

B101290337 Ltr to all licensees of operating reactor plants, CP holders & CP applicants, Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of FCAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

B101210607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45
* Commissioners 80/12/17 49pp

G Inspector Reports, IE Bulletins & correspondence

B101240619 Updates licensee corrective actions following NRC B03070 insp of util O&E Engineering Design QA organization restructured to provide sufficient organizational freedom, authority, & access to mgt
KIRKOWS, S H Tennessee Valley Authority 80/10/08 3pp

B101100664 Forwards IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-23 & 50-521/80-21 on B03927-1028 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/26 2pp

-B101103672 IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-23 & 50-521/80-21 on B03929-1028 No noncompliance noted Major areas inspected A-N & D-1 reactor pressure vessel storage & open item review
Sullivan, B Region 2, Atlanta, Office of the Director 80/11/26 5pp

B101050588 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Scram Discharge Val at Dresden Unit 2" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p

B101050153 Forwards IE Info Notice 80-45, "Potential Failure of BWB Batrux Manual Scram Capability" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p

B101070023 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 Control Rods to Fully Insert During Scram at BWR" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p

B101050217 Forwards IE Bulletin 80-25, "Operating Problems W/Tang Rock Safety Relief Valves at BWRs" No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p

B101290544 Forwards IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-19 & 50-521/80-17 on B01028-31 No noncompliance noted
STORR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/19 2pp

--B101290519 IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-19 & 50-521/80-17 on B01028-31 No noncompliance noted Major areas inspected mgt controls, CP environ conditions & commitments & status of spill spill program
CUMMINGS, A L Region 2, Atlanta, Office of the Director 80/12/19 5pp

B101190051 Forwards response to IE Bulletin 80-23 re failure of Val Engineering Corp solenoid valves Valcor solenoid valves
W2900-21-1 & W2900-21-3 not used Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/29 2pp

B101290236 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Util awaiting vendor response that parts do not contain Malcolm Foundry yokes Final rept will be filed by B10527
MILLS, L M Tennessee Valley Authority 81/01/05 1p

S Reportable occurrences, LERs & related correspondence

B101140499 Interim deficiency Rept 1 re fillet weld misspecification American Inst of Steel Const stds are being evaluated
Originally reported on B01208
MILLS, L M Tennessee Valley Authority 81/01/07 2pp

B101210390 First interim deficiency rept re pressure drop in essential svr water piping, initially reported on B01210 Util is reanalyzing essential svr water piping & high pressure fire protection piping Final rept will be submitted by B10320
MILLS, L M Tennessee Valley Authority 81/01/12 3pp

B101226711 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to B01104 Ltr Addl info to be provided by B10211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

40387 Corrects numbers in Unit B10169 & 12 interim deficiency
to re procedure drop in essential svr water piping &
w/ dry gas treatment design deficiency
B10169 Tennessee Valley Authority 8/10/20 1p

STN-50-522 SKAGIT NUCLEAR PLANT, UNIT 1

Application/construction stage documents & correspondence

20466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

Security, medical, emergency & fire protection plans

40387 Ltr to all licensees of operating reactor plants, CP holders
CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

Judiciary correspondence

10368 Submits applicant second quarterly status rpt per ASLB
re of B00827 Geological & geophysical program involved
essential field work by consultants, including drilling,
mining & geological mapping Related correspondence
MSEW, F T Puget Sound Power & Light Co 80/12/24 3pp
069 088

50625 Order granting Skagit County, WA B01124 motion to withdraw
in proceeding
ALE, V B Atomic Safety and Licensing Board Panel 80/12/31 2pp
0387 261

Congressional/Executive Correspondence

B01014 Responds to B01009 ltr re NRC progress in review of CPs use
of resources for Section 110 of NRC 1980 Authorization Act,
delay in adjudicatory proceedings & lack of coherent
regulatory guidance N/A encl documentation
MERRINE, J F Commissioners 80/12/22 4pp

B1080362 Responds to B01009 ltr re NRC progress in review of CPs use
of resources for Section 110 of NRC 1980 Authorization Act,
delay in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl
MERRINE, J F Commissioners 80/12/22 4pp

STN-50-523 SKAGIT NUCLEAR PLANT UNIT 2

Application/construction stage documents & correspondence

20466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

10368 Submits applicant second quarterly status rpt per ASLB
re of B00827 Geological & geophysical program involved
essential field work by consultants, including drilling,
mining & geological mapping Related correspondence
MSEW, F T Puget Sound Power & Light Co 80/12/24 3pp
069 088

Security, medical, emergency & fire protection plans

40387 Ltr to all licensees of operating reactor plants, CP holders
CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

Judiciary correspondence

50625 Order granting Skagit County, WA B01124 motion to withdraw
in proceeding
ALE, V B Atomic Safety and Licensing Board Panel 80/12/31 2pp
0387 261

Congressional/Executive Correspondence

B01060314 Responds to B01009 ltr re NRC progress in review of CPs use
of resources for Section 110 of NRC 1980 Authorization Act,
delay in adjudicatory proceedings & lack of coherent
regulatory guidance N/A encl documentation
MERRINE, J F Commissioners 80/12/22 4pp

B01060362 Responds to B01009 ltr re NRC progress in review of CPs use
of resources for Section 110 of NRC 1980 Authorization Act,
delay in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl
MERRINE, J F Commissioners 80/12/22 4pp

DOCKET 50-524 SKAGIT UNIT 1

G Adjudicatory correspondence

B101090310 Forwards NRC response to applicant request for withdrawal
of applications N/A encl
CPAY, J R Hearing Branch 1 81/01/07 1p 07425 267

DOCKET 50-525 SKAGIT UNIT 2

G Adjudicatory correspondence

B101090370 Forwards NRC response to applicant request for withdrawal
of applications N/A encl
CPAY, J R Hearing Branch 1 81/01/07 1p 07425 267

DOCKET 50-526 SKAGIT UNIT 3

G Adjudicatory correspondence

B101090370 Forwards NRC response to applicant request for withdrawal
of applications N/A encl
CPAY, J R Hearing Branch 1 81/01/07 1p 07425 267

DOCKET 50-527 SKAGIT UNIT 4

G Adjudicatory correspondence

B101090370 Forwards NRC response to applicant request for withdrawal
of applications N/A encl
CPAY, J R Hearing Branch 1 81/01/07 1p

DOCKET STN-50-528 FALD VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101120090 Forwards 425 Updated electrical instrumentation & control
drawings & 135 updated P&IDs per FSAR Amend 3 Aperture
Cards only in PDF
VALI, BRUIT, E E Arizona Public Service Co 80/12/18 1p
07493 175

B101060500 Forwards "Summary of Future Qualification Tests" & Vol 1,
"Instruction Manual for Installation, Operation & Maint of
Auxiliary & Isolation Relay Cabinets, Generator Protection
Cabinet, Metering Cabinet & Auto Synchronizer Cabinet"
VALI, BRUIT, E E Arizona Public Service Co 80/12/23 8pp
07309 001

B101060507 Vol 1, Revision 1, "Instruction Manual for Installation,
Operation & Maint of Auxiliary & Isolation Relay Cabinets,
Generator Protection Cabinet, Metering Cabinet & Auto
Synchronizer Cabinet"
VALI, BRUIT, E E Arizona Public Service Co 80/10/03 8pp

B101060478 Requests meeting in Jan to discuss sys review schedule
status & to determine which sys could, in advance, be
prepared for sys reviews
VALI, BRUIT, E E Arizona Public Service Co 80/12/29 1p
07396 315

011069B Requests lists of attendees, contracts and agenda for E10127-29 site visit info re potential contentions encl
MIRAGLIA, F J Licensing Branch 3 81/01/26 2pp 07464 143

01131329 Clarifies technical support and training requirements discussed at 80116 meeting
VAN BRUNT, E E Arizona Public Service Co 81/01/08 2pp
07151 330

01126053 Responds in ltr 801229 ltr requesting meeting to discuss facility revised schedule meeting on 810122 suggested
EISENHUT, D G Division of Licensing 81/01/14 2pp 07534 173

01130344 Notification of 80119 meeting w/utl & ANL in Buckeye, AZ to discuss environ revised site visit
MIRAGLIA, F J Licensing Branch 3 81/01/19 3pp 07576 340.

01270441 forwards response to NRC 801214 request for updated subsistence info Six plots exhibit random scatter within accuracy of survey Settlement results from localized causes induced by man
VAN BRUNT, E E Arizona Public Service Co 81/01/20 4pp
07549 031

Utility Environmental Report (ER), amends & correspondence

01070463 Forwards proof of svc for updated distribution list for suppl & amends to facility general info.FSAR & environ rept per NRC 800625 ltr
VAN BRUNT, E E Arizona Public Service Co 80/12/29 5pp

NRC Draft/Final Environmental Statements, suppl & correspondence

01280474 Requests info re proposed or listed plant &/or animal species which may be present in vicinity of facilities Also extends invitation to participate in 810127-28 site visit
MIRAGLIA, F J Licensing Branch 3 81/01/23 6pp 07187 001

Security, medical, emergency & fire protection plans

01090337 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810202 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

Adjudicatory Correspondence

01120459 Order granting intervenor PL Hourihan until 810120 to respond to contentions objected to by joint applicants or NRC Certificate of Svc encl
LAZD, R H Atomic Safety and Licensing Board Panel 81/01/06 3pp
07447 219

01270272 Informs of representation for PL Hourihan in claim against utl 801211 action re invasion of privacy by wiretapping Certificate of Svc & news articles encl
TODD, J S Tobin, J S 81/01/13 6pp 07309 001

01270175 Ack receipt of 810113 ltr re PL Hourihan claim against utl 810121, C J Atomic Safety and Licensing Appeal Panel 81/01/16
lp 07546 059

0101270706 Informs of representation for PL Hourihan in claim against utl 801211 action re invasion of privacy by wiretapping Certificate of Svc encl
TODD, J S Tobin, J S 81/01/13 3pp 07546 060

Utility Final Safety Analysis Report (FSAR) & amends

01070264 Forwards proof of svc of Amend 3 to FSAR distribution list encl
VAN BRUNT, E E Arizona Public Service Co 80/12/29 3pp.
07414 124

01070463 Forwards proof of svc for updated distribution list for suppl & amends to facility general info.FSAR & environ rept per NRC 800625 ltr
VAN BRUNT, E E Arizona Public Service Co 80/12/29 5pp

0 Inspection reports, IE Bulletins & correspondence

0101050333 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Screen Discharge Val at Dresden Unit 2 " No response required
EISENHUT, R H Region 5, San Francisco, Office of the Director 80/12/25 1p 07387 289

810115638 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown " No response required
EISENHUT, R H Region 5, San Francisco, Office of the Director 80/12/16 1p 07398 031

8101220976 Requests 60-day extension to respond to IE Bulletin 80-23, "Failures of Solenoid Valves Rfg by Valcor Engineering Corp " Info from vendors required
VAN BRUNT, E E Arizona Public Service Co 80/12/18 1p
07495 254

8101220104 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Melcor Foundry, Co. Inc - Vendors have confirmed that specified valves were not supplied Two responses are outstanding
VAN BRUNT, E E Arizona Public Service Co 80/12/30 1p
07495 255

8101270459 Approves utl 801218 request for 30-day extension to respond to IE Bulletin 80-23, "Failures of Solenoid Valves Rfg by Valcor Engineering Corp "
EISENHUT, R H Region 5, San Francisco, Office of the Director 81/01/08 1p 07549 060

S Reportable occurrences, LERs & related correspondence

8101060425 Revised final deficiency rept, originally reported on 800612, re undersized structural steel fillet welds Supple original final rept w/corrections & addl info re "Analysis of Safety Implications" section
VAN BRUNT, E E Arizona Public Service Co 80/12/24 23pp.
07309 001

8101210330 Interim deficiency rept re assumption in containment fuel transfer housing tube design Revised calculation will be completed by 810301 Final rept will be submitted by 810401.
VAN BRUNT, E E Arizona Public Service Co 81/01/12 3pp
07490 128

8101210335 Interim deficiency rept re cable tray supports not meeting drawing requirements Installation drawings & work plan procedures will be reviewed & revised Installation will be corrected or accepted after insp Final rept due by 810401
VAN BRUNT, E E Arizona Public Service Co 81/01/12 4pp
07490 124

8101230492 Final deficiency rept, originally reported on 801211, re Class IE conductors within six inches of non-Class IE conductors on six ITE Gould 480 volt load ctr isolation relay cabinets Corrective action will be completed prior to sys startup
VAN BRUNT, E E Arizona Public Service Co. 81/01/12 4pp
07510 018

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8101220456 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D G Division of Licensing. 80/11/26 8pp

8101220976 Forwards 425 updated electrical, instrumentation & control drawings & 135 updated P&IDs, per FSAR Amend 3, Aperture cuts only in PDR
VAN BRUNT, E E Arizona Public Service Co. 80/12/18 1p.
07453 175

8101060500 Forwards "Summary of Future Qualification Tests" & Vol 1, "Instruction Manual for Installation, Operation & Maint of Auxiliary & Isolation Relay Cabinets, Generator Protection Cabinet, Metering Cabinet & Auto Synchronizer Cabinet."
VAN BRUNT, E E Arizona Public Service Co. 80/12/23 6pp.
07309 031

B101102038 Final deficiency, reprimand originally reported B01211 re pipe
stocks failed to facilitate installation of pipe supports
possibly overstressing welds Bechtel Corp will repair piping
sys Personnel instructed to follow installation spec
VAN BRUNT, E E Arizona Public Service Co 81/01/12 4pp
07490 120

B101230492 Final deficiency, reprimand originally reported on B01211 re Class
IE conductors within six inches of non-Class IE conductors
on six IIE Gould 480 volt load center isolation relay cabinets
Corrective action will be completed prior to sys startup
VAN BRUNT, E E Arizona Public Service Co 81/01/12 4pp
07510 018

B01242 SIN-50-570 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12: "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

B10120018 Forwards 425 updated electrical instrumentation & control
drawings & 135 updated P&IDs per FSAR Amend 3 Aperture
cards only in P&ID
VAN BRUNT, E E Arizona Public Service Co 80/12/18 1p
07493 175

B101060503 Forwards "Summary of Future Qualification Tests" & Vol 1.
"Instruction Manual for Installation, Operation & Maint of
Auxiliary & Isolation Relay Cabinets, Generator Protection
Cabinet, Metering Cabinet & Auto Synchronizer Cabinet"
VAN BRUNT, E E Arizona Public Service Co 80/12/23 6pp
07399 001

--B101260507 Vol 1, Revision 3, "Instruction Manual for Installation,
Operation & Maint of Auxiliary & Isolation Relay Cabinets,
Generator Protection Cabinet, Metering Cabinet & Auto
Synchronizer Cabinet"
* Arizona Public Service Co 80/10/03 39pp

B101060478 Requests meeting in Jan to discuss sys review schedule
status & to determine which sys could, in advance, be
prepared for sys reviews
VAN BRUNT, E E Arizona Public Service Co 80/12/29 1p
07396 315

B101070463 Forwards proof of svc for updated distribution list for
supplies & amends to facility general info, FSAR & environ
rept per HRC 800825 ltr
VAN BRUNT, E E Arizona Public Service Co 80/12/29 5pp
07403 355

B101150928 Requests lists of attendees, contracts and agenda for
B10127-29 site visit info re potential contentions incl
MIRAGLIA, F J Licensing Branch 3 81/01/05 2pp 07464 149

B101130327 Clarifies technical support ctr running requirements
discussed at B01118 meeting.
VAN BRUNT, E E Arizona Public Service Co 81/01/08 2pp
07451 350

B10126853 Responds to util B01229 ltr requesting meeting to discuss
facility review schedule Meeting on B10122 suggested
EISENHUT, D G Division of Licensing 81/01/14 2pp 07534 173

B101306344 Notification of B10119 meeting w/util & AML in Buckeye, AZ to
discuss environ review site visit
KERRIGAN, J D Licensing Branch 3 81/01/19 3pp 07576 360

B101270411 Forwards response to NRC B01219 request for updated
subsistence info Six plots exhibit random scatter within
accuracy of survey Settlement results from localized causes
induced by man
VAN BRUNT, E E Arizona Public Service Co 81/01/20 4pp
07549 051

B101200041 Notification of B10122 meeting w/util in Bethesda, MD to
discuss facilities review schedule
KERRIGAN, J D Licensing Branch 3 81/01/22 3pp 07583 085

C Utility Environmental Report (IER), amends & correspondence

B101070463 Forwards proof of svc for updated distribution list for
supplies & amends to facility general info, FSAR & environ
rept per HRC 800825 ltr
VAN BRUNT, E E Arizona Public Service Co 80/12/29 5pp

D NPC Draft/Final Environmental Statements, supp & correspondence

B101280474 Requests info re proposed or listed plant &/or animal
species which may be present in vicinity of facilities Also
extends invitation to participate in B10127-28 site visit
MIRAGLIA, F J Licensing Branch 3 01/01/23 6pp 07187 031

F Security, medical, emergency & fire protection plans

B101290387 Ltr to all licensees of operating reactor plants, CP hold
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G Adjudicatory correspondence

B101280499 Order granting intervenor PL Hourihan until 01/01/20 to
respond to contentions objected to by joint applicants or
IAC Certificate of Svc encl
LAW, R M Atomic Safety and Licensing Board Panel 81/01/06
07447 210

B101270272 Informs of representation for PL Hourihan in claim appeal
util B01211 action re invasion of privacy by wiretapping.
Certificate of Svc & news articles encl
TODIN, J S Tobin, J S 81/01/13 6pp 07309 001

B101270295 Ack receipt of B10113 ltr re PL Hourihan claim against
BISHOP, C J Atomic Safety and Licensing Appeal Panel 81/01/16
1p 07346 059

--B101270306 Informs of representation for PL Hourihan in claim appeal
util B01211 action re invasion of privacy by wiretapping
Certificate of Svc encl
TODIN, J S Tobin, J S 01/01/13 3pp 07346 060

H Utility Final Safety Analysis Report (FSAR) & amends

B101070364 Forwards proof of svc of Amend 3 to FBAR
Distribution list encl
VAN BRUNT, E E Arizona Public Service Co 00/12/29 3pp
07414 124

B101070463 Forwards proof of svc for updated distribution list for
supplies & amends to facility general info, FSAR & environ
rept per HRC 800825 ltr
VAN BRUNT, E E Arizona Public Service Co 80/12/29 5pp

B101270537 Forwards FBAR Pages 9 3-1/9 3-1A & 9 5-1B/9 5-2 to repl
Pages 9 3-1/9 5-2 erroneously provided as part of FBAR
Amend 3 in Vol B
* Bechtel Power Corp (subs of Bechtel Corp.) 81/01/19 5pp
07518 329

I Inspection reports, IE Bulletins & correspondence

B101050533 Forwards IE Info Notice 80-43, "Failures of Continuous
Level Monitor for Baram Discharge Vol at Oresdan Unit 2"
No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
80/12/03 1p 07387 288

B101150838 Forwards IE Info Notice 80-44, "Actuation of ECCB In
Recirculation Mode While in Hot Shutdown" No response
required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
83/12/16 1p 07308 031

B101220096 Requests 60-day extension to respond to IE Bulletin 80-
"Failures of Solenoid Valves Mfg by Valcor Engineering
Corp" Info from vendors required
VAN BRUNT, E E Arizona Public Service Co 80/12/18 1p
07495 254

B101220104 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co, Inc" Vendors have confirmed that
specified valves were not supplied. Two responses are
outstanding.
VAN BRUNT, E E Arizona Public Service Co 80/12/30 1p
07495 255

B101270459 Approves util B01218 request for 30-day extension to r
to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by
Valcor Engineering Corp"
ENGELKEN, R H Region 5, San Francisco, Office of the Director
81/01/08 1p 07547 060

portable occurrences, LERs & related correspondence

60425 Revised final deficiency rept. originally reported on 800612. undersized structural steel fillet welds Suppl's original al rept w/corrections & addl info re "Analysis of Safety Locations" section
BRUNT, E E Arizona Public Service Co 80/12/24 23pp.
09 001.

60335 Interim deficiency rept re cable tray supports not meeting wiring requirements. Installation drawings & work plan procedures will be reviewed & revised. Installation will be rejected or accepted after insp. Final rept due by 010401.
BRUNT, E E Arizona Public Service Co 81/01/12 4pp.
90 124

60492 Final deficiency rept. originally reported on 801211. re Class conductors within 6 in. inches of non-Class 1E conductors. 1E 17E Could 480 volt load ctr isolation relay cabinets. corrective action will be completed prior to sys startup
BRUNT, E E Arizona Public Service Co 81/01/12 4pp
10: 018

1 50-537 CLINCH RIVER BREEDER REACTOR

Application/construction stage documents & correspondence

70222 "Thermal Hydraulic LMFBR Safety Experiments." monthly flights for June 1980
BERO, T. ABUAF, N Brookhaven National Laboratory FIN A-3024
1270222 80/06/30 4pp 07547-095

80654 "Thermal Hydraulic LMFBR Safety Experiments." monthly flights for Jul 1980.
AF, N. DINBERO, T Brookhaven National Laboratory FIN A-3324
1270654 80/07/31 4pp. 07511-240

70545 "Thermal Hydraulic LMFBR Safety Experiments." monthly flights for Aug 1980
BERO, T. ABUAF, N Brookhaven National Laboratory FIN A-3024
1270545 80/08/31 4pp 07543-333.

70065 "Thermal Hydraulic LMFBR Safety Experiments." monthly flights for Sept 1980.
BERO, T. ABUAF, N Brookhaven National Laboratory FIN A-3024
1270065 80/09/30 4pp 07547-200

70027 AN ADVANCED THERMOHYDRAULIC SIMULATION CODE FOR PODL-TYPE REACTORS (65C-P CODE)
AF, I. K. CAZZO, I. E O Brookhaven National Laboratory. FIN
015 NUREG/CR-1738 00/09/30 105pp Available at NTIS
12: 136

60127 EVALUATION OF TECHNIQUES FOR DYNAMIC MEASUREMENT OF FUEL RODS IN LIQUID-METAL-COOLED FAST-BREEDER REACTOR SAFETY EXPERIMENTS
AB, A. E. ORNDORFF, J. O. Los Alamos Scientific Laboratory. FIN
046 NUREG/CR-1398 00/10/31 67pp. 07523-226

70112 "Thermal Hydraulic LMFBR Safety Experiments." monthly flights for Oct 1980
Brookhaven National Laboratory 8101270112. 80/10/31. 3pp
17: 209.

70337 "Application of Super Svc Code-L to Investigate Natural Convection in Damaged LMFBR Cores." submitted to ANS/ECB/AIE
17-21 International conference.
Y, J. O. Brookhaven National Laboratory CURTIS, R. T. Division of
for Safety Research. 8101210337 80/11/21 6pp 07489-100.

70466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing. 80/11/26. 8pp

70578 "Thermal Hydraulic LMFBR Safety Experiments." monthly flights for Nov 1980.
BERO, T. GREENE, O. A Brookhaven National Laboratory FIN
024. 8101260758 80/11/30. 4pp 07536-018

70544 "Thermal Hydraulic LMFBR Safety Experiments." monthly flights for Jul 1980
AF, N. Brookhaven National Laboratory 8101210544 81/01/15.
07488-334.

Utility Preliminary Safety Analysis Report; amends

8101090492 Forwards Certificate of Svc re distribution of Amend 39 to
P38A
CEPELAND, R. L. Energy Dept. of. Clinch River Breeder Reactor Plant
81/01/05 2pp 07427-331

F Security, medical, emergency & fire protection plans

8101090487 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D. O. Division of Licensing 80/11/13 2pp

DOCKET 57N-59-546 HARBLE HILL NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8101070237 Requests written notification to resume const activities per NRC 800915 order re mechanical & piping const activities by Cherne Contracting Corp & electrical const activities by Commonwealth-Lord JV
EISENHUT, D. O. Public Service Co of Indiana, Inc 80/11/13 1p.
07415-237

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D. O. Division of Licensing 80/11/26 0pp

8101050915 Forwards info re environ qualification tests scheduled for next 2 yrs on safety-related equipment. Info includes equipment description, sys where equipment installed & test location & schedule
EISENHUT, D. O. Public Service Co of Indiana, Inc 80/12/18 4pp
07379-346

8101290504 Requests NRC approval for use of ASME Code Case N-290. Code Case provides use of magnetic particle or liquid penetrant examination in lieu of visual examination
EISENHUT, D. O. Public Service Co of Indiana, Inc. 81/01/23. 1p
07368-334

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D. O. Division of Licensing 80/11/13. 2pp.

H General correspondence

8101130044 Response to 800930 ltr forwarding encl F Hauck, HO Cassidy & R Gray ltrs re nuclear waste disposal bills before Congress & concerns about Facilities Util estimate of facility const costs generally consistent w/NRC estimate
DIRCKS, H. J. Office of the Executive Director for Operations
80/12/30 10pp 07449-310.

Q Inspection reports, IE Bulletin & correspondence

8101050209 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 00/10/30
2pp. 07389-027

8101060540 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valve Mfg by Velcor Engineering Corp." No written response is required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/31
1p 07401-151

8101100790 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 00/10/31
2pp. 07444-086.

8101050475 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/06
2pp 07395-048

Pressure Actuates Safety-Relief Valve Operation to Cause
Reactor Depressurization " No written response required
KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/11/07
2pp 07426 269

B01060379 Forwards IE Info Notice 80-41, "Failure of Swing Check
Valve in Decay Heat Removal Sys at Davis Beesse Unit 1" No
response required
KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/11/10
2pp 07391 076

B01060515 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp " Written response required
KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/11/14
2pp 07391 238

D01060330 Forwards IE Insp Repts 50-546/80-41 & 50-547/80-41 on
B01001-31 No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/26 2pp 07392 037

--B01060306 IE Insp Repts 50-546/80-41 & 50-547/80-41 on B01001-31 No
noncompliance noted. Major areas inspected: auxiliary bldg,
fuel handling bldg & containments to verify compliance w/
790807 stop work order
HARRISON, J. J., WILLIAMS, C. C. Region 3, Chicago, Office of the
Director 80/11/26 4pp 07392 039

B01100369 Forwards IE Insp Repts 50-546/80-42 & 50-547/80-42 on
B01104-06 No noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/26 2pp 07444 001

--B01100378 IE Insp Repts 50-546/80-42 & 50-547/80-42 on B01104-06 No
noncompliance noted. Major areas inspected: OA program of
vendor
HARRISON, J. J., KEY, W., WILLIAMS, C. C. Region 3, Chicago, Office of
the Director 80/11/25 12pp 07444 003

B01050571 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Scram Discharge Vol at Dresden Unit 2 " No
response required
KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/12/03
2pp 07386 035

B01100177 Submits supplemental response to IE Bulletin 79-03A re
longitudinal weld defects in stainless steel piping. Addl
review of welds completed. No welded components designated
for use in any safety-related sys.
SHIELDS, S. W. Public Service Co. of Indiana, Inc 80/12/18 2pp
07443 013

B01070085 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown " No written
response required
KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/12/16
1p 07415 041

B01210097 Forwards IE Insp Repts 50-546/80-39 & 50-547/80-39 on
B01021-24, 1105-07 & 11-14. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/16 2pp 07489 324

--B01210104 IE Insp Repts 50-546/80-39 & 50-547/80-39 on B01021-24,
1105-07 & 11-14. No noncompliance noted. Major areas
inspected: review of BPP-2 const verification program final
rept & insp of civil insp & testing svcs lab.
HAYES, O. W. Region 3, Chicago, Reactor Construction & Engineering
Support Branch HAWKINS, F. C., NEISLER, J. H. Region 3, Chicago,
Office of the Director 80/12/11 11pp 07489 326

G012310165 Notification of B01018 meeting w/util in Bethesda, MD on insp
& testing re cadweld deficiencies at Facilities
MONG, H. J. Assistant Director for Components & Structures
Engineering 80/12/18 3pp 07369 277

B01290152 Forwards IE Insp Repts 50-546/80-43 & 50-547/80-43 on
B01101-30 Noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/18 2pp 07568 289

--B01290166 IE Insp Repts 50-546/80-43 & 50-547/80-43 on B01101-30. No
noncompliance noted. Major areas inspected: auxiliary bldg &
fuel handling bldg & containments to verify compliance
w/790807 stop work order
HARRISON, J. J., WILLIAMS, C. C. Region 3, Chicago, Office of the
Director 80/12/16 8pp 07568 261

ccrort violations noted in IE Insp Repts 50-546/80-28
50-547/80-28
FIORELLI, G. Region 3, Chicago, Reactor Construction &
Support Branch 81/01/14 1p 07583 234

--B010300421 Responds to NRC B01208 ltr re violations no
Repts 50-546/80-28 & 50-547/80-28 Corrective actions
const records investigation to be augmented by onsite
engineering evaluation. Final rept to be filed by B0106
SHIELDS, S. W. Public Service Co. of Indiana, Inc 81/
07563 235

S Reportable occurrences, LERs & related correspondence

B01140645 Interim deficiency rept, first reported on B01
inability to verify certain pipe sleeve installation
const records investigation to be augmented by onsite
engineering evaluation. Final rept to be filed by B0106
SHIELDS, S. W. Public Service Co. of Indiana, Inc 81/
07461 242

B01230487 Interim deficiency rept, originally reported
radiographs of steam generator upper lateral support
embedments not meeting ASME density requirements.
Re-examination results will be available by D0220
SHIELDS, S. W. Public Service Co. of Indiana, Inc 81/
07510 017

DOCKET BSN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B01070239 Requests written notification to resume const
per NRC B00915 order re mechanical & piping const act
by Charns Contracting Corp & electrical const activity
Commonwealth-Lord JV
SHIELDS, S. W. Public Service Co. of Indiana, Inc 80/
07415 237

B01220466 Ltr to all power reactor licensees & applica
summary of B0112 meeting re implementation of guidance
Unresolved Safety Issue A-12, "Potential for Low Fract
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, O. O. Division of Licensing 80/11/26 8pp

B012310165 Notification of B01018 meeting w/util in Beth
& testing re cadweld deficiencies at Facilities.
MONG, H. J. Assistant Director for Components & Structures
Engineering 80/12/18 3pp 07369 277

B01050015 Forwards info re environ qualification tests
next 2 yrs on safety-related equipment. Info includes
equipment description, sys where equipment installed &
location & schedule.
SHIELDS, S. W. Public Service Co. of Indiana, Inc 80/
07379 346

B01290904 Requests NRC approval for use of ASME Code C
Case provides use of magnetic particle or liquid penetr
examination in lieu of visual examination.
SHIELDS, S. W. Public Service Co. of Indiana, Inc 81/
07566 354

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor pla
& CP applicants. Revised radiological emergency respon
plans must be submitted by licensees within 60 days o
B0102 & by applicants as part of F8AR
EISENHUT, O. O. Division of Licensing 80/11/13 2pp

H General correspondence

B01130044 Responds to B00930 ltr forwarding encl F Haur
R Drey ltr re nuclear waste disposal bills before Con
& concerns about facilities. Util estimate of facility
costs generally consistent w/NRC estimate
DICKER, W. J. Office of the Executive Director for Oper
80/12/30 10pp 07449 310

Q Inspection reports, IE Bulletins & correspondence

B01050209 Forwards IE Info Notice 80-38, "Cracking in
Casing Cladding " No response required.
KEPPLER, J. C. Region 3, Chicago, Office of the Director
2pp 07369 027

8101060548 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/31
1p 07401 151

8101100790 Forwards IE Circular 80-23, "Potential Defects in Diesel Power Sys Emergency Generators." No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/31
2pp. 07444 086

8101050475 Forwards IE Bulletin 00-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/06
2pp. 07390 048

8101090090 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization." No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/07
2pp 07426 268

8101060379 Forwards IE Info Notice 80-41, "Failure of Bypass Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/10
2pp 07391 076

8101060515 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/14
2pp 07391 238

8101060300 Forwards IE Insp Repts 80-546/80-41 & 80-547/80-41 on 801001-31 No noncompliance noted.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/11/26 2pp. 07392 037

--8101060306 IE Insp Repts 80-546/80-41 & 80-547/80-41 on 001001-31 No noncompliance noted. Major areas inspected: auxiliary bldg, fuel handling bldg & containments to verify compliance w/ 790807 stop work order.
HARRISON, J. J., WILLIAMS, C. C. Region 3, Chicago, Office of the Director 00/11/26 4pp. 07392 039

8101100369 Forwards IE Insp Repts 80-546/80-42 & 80-547/80-42 on 801104-06 No noncompliance noted.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/26 2pp. 07444 001

--8101100378 IE Insp Repts 80-546/80-42 & 80-547/80-42 on 001104-06 No noncompliance noted. Major areas inspected: OA program of vendor.
HARRISON, J. J., KEYS, W., WILLIAMS, C. C. Region 3, Chicago, Office of the Director 00/11/25 12pp. 07444 003

8101050571 Forwards IE Info Notice 00-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vessel at Dresden Unit 2." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/05
2pp. 07386 035

8101100177 Submit supplemental response to IE Bulletin 79-03A re longitudinal weld defects in stainless steel piping. Add'l review of welds completed. No welded components designated for use in any safety-related sys.
SHIELDS, B. W. Public Service Co. of Indiana, Inc. 80/12/15 2pp. 07443 013

8101070085 Forwards IE Info Notice 80-44, "Activation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/16
1p 07415 041

8101210097 Forwards IE Insp Repts 80-546/80-39 & 80-547/80-39 on 801021-24, 1105-07 & 11-14 No noncompliance noted.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/16 2pp. 07489 324

--8101210104 IE Insp Repts 80-546/80-39 & 80-547/80-39 on 801021-24, 1105-07 & 11-14 No noncompliance noted. Major areas inspected: review of SPP-2 cost verification program final rept & insp of civil insp & testing avcs feb.
HAYES, O. W. Region 3, Chicago, Reactor Construction & Engineering Support Branch, HAWKINS, F. C., NEIBLER, J. H. Region 3, Chicago, Office of the Director 80/12/11 11pp. 07489 326

8101290152 Forwards IE Insp Repts 80-546/80-43 & 80-547/80-43 on 801101-30 Noncompliance noted.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/18 2pp 07568 259

--8101290166 IE Insp Repts 80-546/80-43 & 80-547/80-43 on 801101-30 noncompliance noted. Major areas inspected: auxiliary bldg & fuel handling bldg & containments to verify compliance w/ 790807 stop work order.
HARRISON, J. J., WILLIAMS, C. C. Region 3, Chicago, Office of the Director 80/12/16 8pp 07568 261

8101300413 Ack receipt of 801230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-546/80-28 & 80-547/80-28
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 81/01/14 1p 07503 234

--8101300421 Responds to NRC 801208 ltr re violations noted in IE Insp Repts 80-546/80-28 & 80-547/80-28. Corrective actions: calor gauges installed on equipment & indicator gauges verified against calor gauge.
SHIELDS, B. W. Public Service Co. of Indiana, Inc. 80/12/30 3pp 07583 235

S Reportable occurrences, IERs & related correspondence

8101140645 Interim deficiency rept, first reported on 801208, re inability to verify certain pipe sleeve installation from const records. Investigation to be augmented by onsite insp & engineering evaluation. Final rept to be filed by 810601.
SHIELDS, B. W. Public Service Co. of Indiana, Inc. 01/01/07 2pp 07461 242

8101230487 Interim deficiency rept, originally reported on 000717, re radiographs of steam generator upper lateral support embeddings not meeting ASME density requirements. Re-examination results will be available by 810220.
SHIELDS, B. W. Public Service Co. of Indiana, Inc. 01/01/15 1p 07510 017

DOCKET 80-548 FORT CALHOUN STATION, UNIT 2

A Application/construction stage documents & correspondence

8101210272 Advises of util 801114 request that CP application be withdrawn. Also advises of ASLO proceeding dismissed on 801222 info submitted re manpower hours expended for review.
YOUNGBLOOD, B. J. Licensing Branch 1 81/01/08 1p 07492 059

8101270431 Forwards FR notice re withdrawal of CP application
YOUNGBLOOD, B. J. Licensing Branch 1 01/01/12 1p 07183 001

--8101270436 Notice of withdrawal of CP application
YOUNGBLOOD, B. J. Licensing Branch 1 81/01/12 1p 07103 001

DOCKET 80-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lenticular Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing 00/11/26 8pp

810120269 Requests util perform ultimate capacity analysis of Mark containment for NRC generic review re effects of hydrogen evolving from postulated accident.
TEDESCO, R. L. Assistant Director for Licensing 80/12/19 3pp 07437 316

8101210642 Advises that ATWS issue will be subj of future rulemaking determining requirements & schedules for plant mods. NRC will not comment on util 800917 ltr describing program for resolving issue until rulemaking is finalized.
EISENHUT, D. O. Division of Licensing 80/12/29 2pp

8101220207 Forwards Suppl 1 to Revision 1 of "Geologic Foundation R Fault Descriptions" per NRC 780531 request.
HILLS, L. H. Tennessee Valley Authority 81/01/14 1p 07500 07

--8101220211 "Geologic Foundation Rept Descriptions of Faults 19-25 Suppl 1 to Revision 1.
AVEL, A. P. Tennessee Valley Authority 80/12/31 4pp 07500 07

F. Security, medical, emergency & fire protection plans

B10109038/ Ltr to all licensees of operating reactor plants. CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 00/11/13 2pp

B101210607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington. OC Pp 8-45
* Commissioners 80/12/17 49pp

G. Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC 800707-11 Insp of util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to mgmt.
KIMMONS, G H Tennessee Valley Authority 80/10/08 3pp

B101050588 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Val at Dresden Unit 2." No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/05. 1p

B101050153 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/17 1p

B101070023 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 185 Control Rnds to fully insert During Scram at BWR." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/10 1p

B101050217 Forwards IE Bulletin 80-23, "Operating Problems w/Target Rod Safety Relief Valves at BWRs." No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/19 1p

B101100374 Ack receipt of B01215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-553/80-15 & 50-554/80-16
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/12/24 1p 07444 015

--B101100381 Responds to NRC B01121 ltr re violations noted in IE Insp Repts 50-553/80-15 & 50-554/80-16. Corrective actions all E-308-L stainless steel welding electrodes stored in separate holding ovens
MILLS, L M Tennessee Valley Authority 80/12/19 4pp 07444 016

--B101100394 Forwards IE Insp Repts 50-553/80-15 & 50-554/80-16 on B00927-1002 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/21 2pp. 07444 020

--B101100460 Notice of violation from Insp on B00929-1002
* Region 2, Atlanta, Office of the Director. 00/11/20 1p 07444 022

--B101100410 IE Insp Repts 50-553/80-15 & 50-554/80-16 on B06929-1002. Noncompliance noted 308-L welding electrodes mixed together w/309-L type electrodes
ECCLETON, M Region 2, Atlanta, Office of the Director HEROT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/20 7pp 07444 023.

B101190051 Forwards response to IE Bulletin 80-23 re failure of Valcor Engineering Corp solenoid valves. Valcor solenoid valves V70900-21-1 & V70900-21-3 not used. Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/29. 2pp.

B101290236 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Util awaiting vendor response that parts do not contain Malcolm Foundry yokes. Final rpt will be filed by B10827
MILLS, L M Tennessee Valley Authority 81/01/05 1p.

H. Reportable occurrences, LERs & related correspondence

B101140499 Interim Deficiency Rept 1 re fillet weld misspecification American Inst of Steel Constr stds are being evaluated.
Originally reported on B01208
MILLS, L M Tennessee Valley Authority 81/01/07 2pp.

B101210390 First interim deficiency rpt re pressure drop in essential svc water piping. Initially reported on B01210 Util is reanalyzing essential svc water piping & high pressure fire protection piping. Final rpt will be submitted by B10320
MILLS, L M Tennessee Valley Authority 81/01/12 3pp

B101210348 Final deficiency rpt initially submitted B01014 re welded plates w/c heat treatability. Plates analyzed & found to meet requirements of ASTM A-36
MILLS, L M Tennessee Valley Authority 81/01/13 2pp. 07490 116

B101220311 Forwards First interim rpt re potential flammability of suspended ceiling tiles in control rooms in response to B01104 ltr. Addl info to be provided by B10211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

B101290489 Corrects numbers on util B10109 & 12 interim deficiency repts re pressure drop in essential svc water piping & standby gas treatment design deficiency
MILLS, L M Tennessee Valley Authority 81/01/20 1p

B101270639 First interim deficiency rpt, originally reported on B0122 re failure to radiograph reactor pressure vessel pedestal welds & bypass hold points on concrete pour. Util & GE will evaluate deficiency. Util currently investigating cause.
MILLS, L M Tennessee Valley Authority. 81/01/22 2pp 07309.001

DRCKET 67N-50-554 PHPPS BEND NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

B101220456 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D G Division of Licensing 80/11/26. 8pp.

B101120269 Requests util perform ultimate capacity analysis of Mark I containment for NRC generic review re effects of hydrogen evolving from postulated accident
TEDESCO, R L Assistant Director for Licensing 80/12/19 3pp 07437 316

B101210642 Advises that ATMB Issue will be subj of future rulemaking determine requirements & schedules for plant mods. NRC will not comment on util B00717 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT, D G Division of Licensing 80/12/29 2pp

B101220207 Forwards Suppl 1 to Revision 1 of "Geologic Foundation Rep Fault Descriptions" per NRC 780831 request
MILLS, L M Tennessee Valley Authority 81/01/14. 1p 07500.074

--B101220211 "Geologic Foundation Rept Descriptions of Faults 19-23," Suppl 1 to Revision 1
AVEL, A P Tennessee Valley Authority 80/12/31 4pp 07500 07

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants. CP holder & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing. 80/11/13 2pp.

B101210607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington. OC Pp 1-45.
* Commissioners 80/12/17 49pp

G. Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC 800707-1 Insp of util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to mgmt.
KIMMONS, G H Tennessee Valley Authority 80/10/08. 3pp.

B101050588 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Val at Dresden Unit 2." No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/05 1p

B101050153 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/17 1p.

01070023 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of 76 of 189 Control Rods to Fully Insert During Scram at BWR - No written response required

01REILLY, J.P. Region 2, Atlanta, Office of the Director 80/12/18. 1p

01090217 Forwards IE Bulletin 80-25. "Operating Problems W/Target Rod Safety Relief Valves at BWRs " No response required.

01REILLY, J.P. Region 2, Atlanta, Office of the Director 80/12/19. 1p

01100370 Ack receipt of B01215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-553/80-15 & 80-554/80-16.

MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/24 1p 07444 015.

010100391 Responds to NRC B01121 ltr re violations noted in IE Insp Repts 80-553/80-15 & 80-554/80-16 Corrective actions all E-300-L stainless steel welding electrodes stored in separate holding ovone
MILLS, L.M. Tennessee Valley Authority. 80/12/15 4pp 07444 016

010100394 Forwards IE Insp Repts 80-553/80-15 & 80-554/80-16 on B00929-1002 & notice of violation
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/21 2pp 07444 020

010100400 Notice of violation from Insp on B00929-1002
* Region 2, Atlanta, Office of the Director 80/11/20 1p 07444 022

010100410 IE Insp Repts 80-553/80-15 & 80-554/80-16 on B00929-1002 Noncompliance noted 308-L welding electrodes mixed together w/309-L type electrodes
MILLS, L.M. Region 2, Atlanta, Office of the Director HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/20 7pp 07444 023

01090051 Forwards response to IE Bulletin 80-23 re failure of Valcor Engineering Corp solenoid valve Valcor solenoid valves V70900-21-1 & V70900-21-3 not used. Util awaiting for vendor response on valve in package components
MILLS, L.M. Tennessee Valley Authority 80/12/27 2pp

1290235 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Melcolm Foundry Co. Inc " Util awaiting vendor response that parts do not contain Melcolm Foundry yokes. Final rpt will be filed by B10527
MILLS, L.M. Tennessee Valley Authority 81/01/05 1p

Reportable occurrences, LERs & related correspondence

1140499 Interim Deficiency Rept 1 re Fillet weld mis-specification. American Inst of Steel Const stds are being evaluated. Rightlly reported on B01208
MILLS, L.M. Tennessee Valley Authority. 81/01/07. 2pp

1210370 First interim deficiency rpt re pressure drop in essential svc water piping. Initially reported on B01210. Util is analyzing essential svc water piping & high pressure fire protection piping. Final rpt will be submitted by B10320
MILLS, L.M. Tennessee Valley Authority 81/01/12 3pp

1220311 Forwards first interim rpt re potential flammability of suspended ceiling tile in control rooms in response to B1104 ltr Addl info to be provided by B10211.
MILLS, L.M. Tennessee Valley Authority. B1/01/14 3pp

1290487 Corrects numbers on util B10109 & 12 Interim deficiency re pressure drop in essential svc water piping & standby gas treatment design deficiency
MILLS, L.M. Tennessee Valley Authority 81/01/20 1p

CKET STN-50-556 BLACK FOX STATION, UNIT 1

Application/construction stage documents & correspondence

1220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D.O. Division of Licensing. 80/11/26 8pp

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D.O. Division of Licensing 80/11/13 2pp

B101210607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45
* Commissioners 80/12/17 49pp

G. Adjudicatory correspondence

0101200404 FBIa request for extracts of 27 safety-related issues identified by GE in Reed Rept
DYARS, C. Houston Chronicle 80/12/10 1p 07495 315

B101200401 Responds to FBIa request for extracts of 27 safety-related issues identified by GE in Reed Rept. NRC cannot provide info pending resolution of court claims. Forwards NRC decision & addendum re public availability of Reed Rept w/o encls
CHILK, S.J. Office of the Secretary of the Commission 81/01/06 1p 07485 314

H. Congressional/Executive Correspondence

0101080314 Responds to B01009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance. W/o encl documentation
WEARNE, J.F. Commissioners 80/12/22 4pp

--B101050362 Responds to B01009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance. Related documentation encl
WEARNE, J.F. Commissioners 80/12/22 4pp

CKET STN-50-557 BLACK FOX STATION, UNIT 2

A. Application/construction stage documents & correspondence

B10120466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D.O. Division of Licensing 80/11/26 8pp

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D.O. Division of Licensing 80/11/13 2pp

B101210607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45
* Commissioners 80/12/17 49pp

U. Congressional/Executive Correspondence

B101080314 Responds to B01009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance. W/o encl documentation
WEARNE, J.F. Commissioners 80/12/22 4pp

--B101080262 Responds to B01009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance. Related documentation encl
WEARNE, J.F. Commissioners 80/12/22 4pp

CKET STN-50-366 YELLOW CREEK NUCLEAR PLANT, UNIT 1, TENNESSEE VALLEY

A. Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D.O. Division of Licensing 80/11/26 8pp

B101050610 Forwards geologic rept re suggested graben in Gravelly Springs, AL area Distance to facilities precludes significance of structures Related documentation encl
LEFEVRE, H E Geosciences Branch 80/12/11 15pp

B101210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mods NRC will not comment on until 800917 ltr describing program for resolving issue until rulemaking is finalised
EISENHUT, D O Division of Licensing 80/12/29 2pp

F Security, medical, emergency & fire protection plans

B101070587 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 00/11/13 2pp

Q Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC 800707-11 insp of util Div of Engineering Design, QA organization restructured to provide sufficient organizational freedom, authority & access to mgt
KIMMONS, Q H Tennessee Valley Authority 80/10/08 3pp

B101120240 Forwards response to IE Bulletin 80-20 re Westinghouse Type W-2 control switches w/spring return to neutral position Switches used in all facilities except Yellow Creek Lists sys in which switches are employed
MILLS, L M Tennessee Valley Authority 80/12/12 2pp

B101060203 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p

B101270030 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Valcor solenoid valves V70900-21-1 & V70900-21-3 not used Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/30 1p

B101210239 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc" Util is in process of obtaining assurance from valve suppliers that no Malcolm Foundry yokes are contained in furnished valves
MILLS, L M Tennessee Valley Authority 81/01/06 1p

B101220055 Ack receipt of B01223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-566/80-17 & 80-567/80-17
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/01/07 1p 07501:346

--B101220058 Responds to NRC 801123 ltr re violations noted in IE Insp Repts 80-566/80-17 & 80-567/80-17 Corrective actions Part 11, Section 5.1 of Div of Nuclear Power Operational QA manual rewritten
MILLS, L M Tennessee Valley Authority 80/12/23 2pp 07501:347

--B101220060 Forwards IE Insp Repts 80-566/80-17 & 80-567/80-17 on 801015-17 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/25 2pp 07501:349

--B101220062 Notice of violation from insp on 801015-17
e Region 2, Atlanta, Office of the Director 80/11/24 1p 07501:351

--B101220065 IE Insp Repts 80-566/80-17 & 80-567/80-17 on 801015-17 Noncompliance noted failure to establish responsibilities in pre-service insp of vendor shops
ZAJAC, L D, COLEY, J L Region 2, Atlanta, Office of the Director
HEARDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/24 2pp 07501:352

G Reportable occurrences, LFRs & related correspondence

B101190475 First interim deficiency rept re fillet weld misclassification Initially reported B01210 American Inst of Steel Const stds & affected welds under review Next rept will be submitted by 810408
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07476:007

B1012200311 Forwards first interim rept re potential planeability of suspended ceiling tile in control rooms in response to B01104 ltr Addl info to be provided by B10211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

BUCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2, TENNESSEE VAL

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forward summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101050610 Forwards geologic rept re suggested graben in Gravelly Springs, AL area Distance to facilities precludes significance of structures Related documentation encl
LEFEVRE, H E Geosciences Branch 80/12/11 15pp

B101210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mods NRC will not comment on until 800917 ltr describing program for resolving issue until rulemaking is finalised
EISENHUT, D O Division of Licensing 80/12/29 2pp

F Security, medical, emergency & fire protection plans

B101070587 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

Q Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC 800707-11 insp of util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to mgt
KIMMONS, Q H Tennessee Valley Authority 80/10/08 3pp

B101120240 Forwards response to IE Bulletin 80-20 re Westinghouse W-2 control switches w/spring return to neutral position Switches used in all facilities except Yellow Creek Lists sys in which switches are employed
MILLS, L M Tennessee Valley Authority 80/12/12 2pp

B101060203 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p

B101270030 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Valcor solenoid valves V70900-21-1 & V70900-21-3 not used Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/30 1p

B101210239 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc" Util is in process of obtaining assurance from valve suppliers that no Malcolm Foundry yokes are contained in furnished valves
MILLS, L M Tennessee Valley Authority 81/01/06 1p

B101220055 Ack receipt of B01223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-566/80-17 & 80-567/80-17
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/01/07 1p 07501:346

--B101220058 Responds to NRC 801123 ltr re violations noted in IE Insp Repts 80-566/80-17 & 80-567/80-17 Corrective actions: Part 11, Section 5.1 of Div of Nuclear Power Operational QA manual rewritten
MILLS, L M Tennessee Valley Authority 80/12/23 2pp 07501:347

--B101220060 Forwards IE Insp Repts 80-566/80-17 & 80-567/80-17 on 801015-17 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/25 2pp 07501:349

--B101220062 Notice of violation from insp on 801015-17
e Region 2, Atlanta, Office of the Director 80/11/24 1p 07501:351

--8101220066 IE Insp Repts 90-566/80-17 & 90-567/80-17 on 801015-17 Noncompliance noted failure to establish responsibilities in preservice insp of vendor shops.
ZAJAC, L B. COLEY, J L Region 2, Atlanta, Office of the Director
HEROT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/24 8pp 07501 352

S Reportable occurrences, LERs & related correspondence

8101190475 First interim deficiency rept re fillet weld misspecification initially reported 801210 American Inst of Steel Const stds & affected welds under review Next rept will be submitted by 810408
MILLER, L M Tennessee Valley Authority 81/01/09 2pp 07476 007

8101220311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to 801104 ltr Addl info to be provided by 810211
MILLER, L M Tennessee Valley Authority 81/01/14 3pp

DOCKET 90-50-900 ERIE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--8005220807 Advises of contractual costs associated w/review of CP application Billing may be completed for project
BERKOW, H H Administrative Section Branch (Pre 790604) 80/04/18 1p 02632 208

--8011240009 Submits summary of CP review costs incurred by various program ofcs from filing of application to date of withdrawal
HOLLOWAY, C J License Fee Management Branch 80/11/10 1p 02227 001

--8011250112 Requests billing of util for fees for review of CP application, withdrawn on 800123 Ofc of Administration should be notified when total amount is collected
MILLER, W O License Fee Management Branch 80/11/10 1p 07052 284

--8012100086 Forwards IE cost data worksheets reflecting manpower expended on review of CP application withdrawn on 800128
COBB, L I Executive Officer for Management & Analysis 80/04/22 3pp

--8012100091 Informs that 302 prof manhours were expended in joint CP review of facility, in response to 800320 request
MCKINNEY, R E ACRS - Advisory Committee on Reactor Safeguards 80/04/11 1p

--8012100105 Informs that no manhours were expended in connection w/sponte review of ASLB action in facility proceeding, in response to 800320 request.
ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 80/03/24 1p

--8012100111 Confirms ASLBP 800331 rept All ASLB time was spent on contested case. No record of prof manhours on facility recorded
FITZ, C J Atomic Safety and Licensing Board Panel 80/05/22 1p

--8012100120 Informs that prof manhours expended by ASLBP re CP application have not been recorded Proceeding was contested
LAZD, R M Atomic Safety and Licensing Board Panel 80/03/31 1p

DOCKET 90-50-581 ERIE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--8005220807 Advises of contractual costs associated w/review of CP application Billing may be completed for project
BERKOW, H H Administrative Section Branch (Pre 790604) 80/04/18 1p 02632 208

--8011240009 Submits summary of CP review costs incurred by various program ofcs from filing of application to date of withdrawal
HOLLOWAY, C J License Fee Management Branch 80/11/10 1p 02227 001

--8011250112 Requests billing of util for fees for review of CP application, withdrawn on 800123 Ofc of Administration should be notified when total amount is collected
MILLER, W O License Fee Management Branch 80/11/10 1p 07052 284

--8012100086 Forwards IE cost data worksheets reflecting manpower expended on review of CP application withdrawn on 800128
COBB, L I Executive Officer for Management & Analysis 80/04/22 3pp

--8012100091 Informs that 302 prof manhours were expended in joint CP review of facility, in response to 800320 request
MCKINNEY, R E ACRS - Advisory Committee on Reactor Safeguards 80/04/11 1p

--8012100105 Informs that no manhours were expended in connection w/sponte review of ASLB action in facility proceeding, in response to 800320 request
ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 80/03/24 1p

--8012100111 Confirms ASLBP 800331 rept All ASLB time was spent as contested case. No record of prof manhours on facility recorded
FITZ, C J Atomic Safety and Licensing Board Panel 80/05/22 1p

--8012100120 Informs that prof manhours expended by ASLBP re CP application have not been recorded Proceeding was contested
LAZD, R M Atomic Safety and Licensing Board Panel 80/03/31

DOCKET 90-50-582 SANDSERT, UNIT 1

A Application/construction stage documents & correspondence

8101190738 Forwards FR notice of withdrawal of CP application
YOUNGBLOOD, B J Licensing Branch 1 81/01/09 3pp 07476 116

--8101190741 Notice of CP application withdrawal.
YOUNGBLOOD, B J Licensing Branch 1 81/01/09 1p 07476 119

DOCKET 90-50-583 SANDSERT, UNIT 2

A Application/construction stage documents & correspondence

8101190738 Forwards FR notice of withdrawal of CP application
YOUNGBLOOD, B J Licensing Branch 1 81/01/09 3pp 07476 116

--8101190741 Notice of CP application withdrawal.
YOUNGBLOOD, B J Licensing Branch 1 81/01/09 1p 07476 119

DOCKET 90-50-592 PALO VERDE NUCLEAR STATION, UNIT 4

A Application/construction stage documents & correspondence

8012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--8005220807 Advises of reported review cost for CP application Billing procedure may be completed.
BERKOW, H H Office of Nuclear Reactor Regulation, Director 80/04/23 1p 02593 363

--8011240009 Submits fees incurred for CP review from application to date of withdrawal. Draft memo encl
MILLER, W O License Fee Management Branch 80/11/10 2pp 02747 253

--8012100031 Discusses CP review cost for facilities through 790824 withdrawal of application NRC Ofc of Controller will be notified to bill util for costs incurred for review w/o encl summary of review costs.
HOLLOWAY, C J License Fee Management Branch 80/11/10 1p

- 801210050 Forwards IE cost data worksheets for facilities Review of contract & consultant records did not reveal any cost directly associated w/facilities
COBB, L. I. Executive Officer for Management & Analysis 79/11/20 3pp

--801210059 Informs that 216.2 prof manhours were expended in joint CP review for facility, in response to 791026 request.
FRALTY, R. F. ACRS - Advisory Committee on Reactor Safeguards 79/11/29 1p

--801210071 Informs that prof manhours expended by ASLB re CP applications have not been recorded Proceeding was contested
LAZD, R. M. Atomic Safety and Licensing Board Panel 79/10/30 1p

--801210080 Informs that no prof manhours were expended in review of CP applications for facility
ROSENTHAL, A. B. Atomic Safety and Licensing Appeal Panel 79/10/29 1p

BUCKET 514-50-593 PALO VERDE NUCLEAR STATION, UNIT 3

A Applications/construction stage documents & correspondence

801210002 Addl response to FOIA request for nine categories of records re fees concerning withdrawal, suspended or postponed applications Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 80/11/21 5pp

--800506355 Advises of reported review cost for CP application Billing procedure may be completed
BERKOWITZ, H. M. Office of Nuclear Reactor Regulation, Director 80/04/23 1p 02593 363

--8011260593 Submits fees incurred for CP review from application filing to date of withdrawal Draft memo encl
MILLER, W. D. License Fee Management Branch 80/11/10 2pp 03747 253

--801210031 Discusses CP review cost for facilities through 790824 withdrawal of application NRC Ofc of Controller will be notified to bill bill for costs incurred for review. W/o encl summary of review costs.
HOLCOMB, L. J. License Fee Management Branch 80/11/10 1p

--801210050 Forwards IE cost data worksheets for facilities Review of contract & consultant records did not reveal any cost directly associated w/facilities
COBB, L. I. Executive Officer for Management & Analysis. 79/11/28 3pp

--801210059 Informs that 216.2 prof manhours were expended in joint CP review for facility, in response to 791026 request
FRALTY, R. F. ACRS - Advisory Committee on Reactor Safeguards. 79/11/29 1p

--801210071 Informs that prof manhours expended by ASLB re CP applications have not been recorded Proceeding was contested
LAZD, R. M. Atomic Safety and Licensing Board Panel 79/10/30 1p

--801210080 Informs that no prof manhours were expended in review of CP applications for facility
ROSENTHAL, A. B. Atomic Safety and Licensing Appeal Panel 79/10/29 1p

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

BUCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

801100777 Forwards IE Insp Repts 70-0008/80-02, 30-05728/80-02 & 50-006/80-01 & notice of violation
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/12/08 2pp 07444 062

--801100783 Notice of violation from Insp on 800422-26 & 1112
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/03 1p 07444 064

--801100811 IE Insp Repts 50-006/80-01, 70-0008/80-02 & 30-05728/80-02 on 800922-26 & 1112 Noncompliance noted overexposure of one individual to external radiation & excess radioactivity concentrations in fuel storage pool
PECK, C. C. Region 3, Chicago, Office of the Director. FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/25 10pp 07444 065

BUCKET 70-0025 ROCKWELL INTERNATIONAL CORP

801210002 Addl response to FOIA request for nine categories of records re fees concerning withdrawal, suspended or postponed applications Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 80/11/21 5pp

--8012100199 Requests partial refund of fee due Rockwell Intl in connection w/780823 application for amend to License SNM-21 Lists actual manhours required for review & amount of refund due
MILLER, W. D. License Fee Management Branch 78/12/22 1p

--8012100284 Notifies of partial refund re abandoned application to License SNM-21 Ofc of Controller has been notified
MILLER, W. D. License Fee Management Branch 78/12/22 1p

801070555 Forwards notice of violation from Insp of License SNM-21 on 801120 Areas inspected security procedures of transportation activities Notice withheld (ref 10CFR2 790)
MORSE, HAYES, L. R. Region 5, San Francisco, Safeguards Branch 80/12/02 2pp 07415 274

801160032 Forwards IE Insp Rept 70-0025/80-10 on 801023-24 & 1103-07 No noncompliance noted Encl withheld (ref 10CFR2 790)
MORSE, HAYES, L. R. Region 5, San Francisco, Safeguards Branch 81/01/07 2pp 07470 350

801290545 Forwards IE Insp Rept 70-0025/80-13 conducted on 801208-14 No noncompliance noted Major areas inspected control & accounting program of SNM Encl withheld (ref 10CFR2 790)
MORSE, HAYES, L. R. Region 5, San Francisco, Safeguards Branch 81/01/13 2pp 07575 364

BUCKET 70-0027 BARCOCK & WILCOX CO

801150029 Responds to 800607 request to use DOE printed instructions for completing Matl Status & Matl Transfer Repts Approve request & revies Safeguards Amend MPR-1 accordingly
PARTLO, J. D. Material Control Licensing Branch 80/12/02 1p 07462 165

801050594 Forwards IE Insp Rept 70-0027/80-17 on 801028-31 No noncompliance noted
KEIRNA, W. B. Region 2, Atlanta, Safeguards Branch 80/12/11 1p 07390 247

--801050599 IE Insp Rept 70-0027/80-17 on 801028-31 No noncompliance noted Major areas inspected records, rept storage, internal controls, measurement controls & matl controls mgt Details withheld (ref 10CFR2 790)
FINLEY, A. O. PATTERSON, J. P. BATES, J. W. Region 3, Chicago, Office of the Director. 80/11/17 1p 07390 248

801070566 Informs of cost & manhours incurred for reviewing B&W 800605 application to amend License SNM-42 Application withdrawn 801028
KETZLACH, N., PAGE, R. O. Uranium Fuel Licensing Branch 80/12/11 1p 07415 282

801210267 Safety evaluation supporting license amend authorizing construction of additions to north end of Bays 1A & 2A, mod of process in Bay 3A & utilization of SNM in expanded facility, per vendor 763807 application & 801211 suppl
KETZLACH, N., CROW, W. F. Uranium Fuel Licensing Branch. 80/12/30 2pp 07492 057

801220212 Amend 13 to License SNM-42, authorizing hot isostatic pressing operations re modified process, in response to 780807 application & 801211 suppl
PAGE, R. O. Uranium Fuel Licensing Branch 80/12/30 1p 07495 3

801280418 Notifies that Amend 12 to License SNM-43, issued 801230, was mistakenly identified as Amend 13
PAGE, R. O. Uranium Fuel Licensing Branch 81/01/14 1p 07598 0

BUCKET 70-0033 TEXAS INSTRUMENTS, INC

801210002 Addl response to FOIA request for nine categories of records re fees concerning withdrawal, suspended or postponed applications Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 80/11/21 5pp

--B010150034 Submits costs & manhours for review of 790215 application for renewal of License SHM-23
KETLACH,N Uranium Recovery Licensing Branch 80/09/26 1p
03630 250

B01160116 Forwards 1E Insp Rept 70-0033/80-10 on 801029-31 No noncompliance noted
SMITH,O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/26 2pp 07469 329

--B01160125 1E Insp Rept 70-0033/80-10 on 801029-31 No noncompliance noted Major areas inspected training, terminations, smears, bioassay, procedures & ventilation
CLEHUIS,P Region 1, Philadelphia, Office of the Director
KHAFF,P J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/24 6pp 07469 331

DOCKET 70-0121 INTERIOR, DEPT. CF. GEOLOGICAL SURVEY

B01070563 Forwards 1E Info Notice 80-32, "Classification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials" No written response required
SMIEZEK,J H Division of Fuel Facility & Materials Safety 80/08/29 1p 07415 341

DOCKET 70-0124 TELEDYNE ISOTOPIES

B01190100 Ack receipt of vendor B01110 ltr re possession of radioactive matl in excess of license limits
KIMMERMAN,J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/12/29 1p 07475 317.

--B01190103 Provides written notification of item of noncompliance re possession of U-235 in excess of license limits
DLACK,S A Teledyne Isotopes 80/11/10 1p 07475 310

DOCKET 70-0135 DABCOCK & WILCOX CO

B01300191 Forwards 1E Insp Rept 70-0135/00-29 on 001007-10 & 20-23 No noncompliance noted.
MARTIN,W O Region 1, Philadelphia, Safeguards Branch 80/11/14 2pp 07500 355

--B01300196 1E Insp Rept 70-0135/00-29 on 001007-10 & 20-23 No noncompliance noted Major areas inspected measurements of residual U holdup in high enriched U facility Details withheld (ref 10CFR2.790)
DISBETT,P., COHEN,I., HOLUDY,D Region 1, Philadelphia, Safeguards Branch 80/11/13 1p 07500 357.

B01260772 Ack receipt of B01118 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 70-0135/00-27 Encl to B01118 ltr withheld (ref 10CFR2.790)
MARTIN,W O Region 1, Philadelphia, Safeguards Branch 80/12/10 1p 07536 022

--B01260776 Nonproprietary response to NRC B01028 ltr re violations noted in 1E Insp Rept 70-0135/80-27 Corrective actions withheld (ref 10CFR2.790)
AUSTIN,M A Dabcock & Wilcox Co., Nuclear Material Div. 80/11/18 1p 07536 023

--B01260782 Forwards nonproprietary version of 1E Insp Rept 70-0135/80-27 on B00908-10 & notice of violation Portions of Insp Rept & notice of violation withheld (ref 10CFR2.790)
ORIER,B H Region 1, Philadelphia, Office of the Director. 80/10/20 2pp 07536 024

--B01260787 Nonproprietary version of 1E Insp Rept 70-0135/00-27 on B00908-10 Noncompliance noted Failure to have required number of security force members on duty Details withheld (ref 10CFR2.790)
MCKEON,L M, SMITH,O. Region 1, Philadelphia, Office of the Director
DEVILIN,J W Region 1, Philadelphia, Safeguards Branch. 80/10/20 1p. 07536 026

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC

B01090814 Forwards 1E Insp Rept 70-0143/00-35 on B00909-1104 No noncompliance noted
O'REILLY,J P Region 2, Atlanta, Office of the Director 80/11/25 2pp 07430 259

--B01090821 1E Insp Rept 70-0143/80-35 on B00909-1104 No noncompliance noted Major areas inspected reported inventory difference which exceeded limit of error on inventory difference
Details withheld (ref 10CFR2.790)
KAMLE,J S Region 2, Atlanta, Office of the Director KENNA, Region 2, Atlanta, Safeguards Branch 80/11/24 1p 07430 259

B010606279 Ack receipt of B01112 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 70-0143/80-29
KENNA,W B Region 2, Atlanta, Safeguards Branch 80/12/15 1p 07392 022

--B010606207 Responds to LRC B01024 ltr re violations noted in 1E Insp Rept 70-0143/00-29 Attachment withheld (ref 10CFR2.790)
MAHSEER,W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/11/12 1p 07392 023

--B010606291 Forwards 1E Insp Rept 70-0143/80-29 on B00811-0912 & violation Notice of violation withheld (ref 10CFR2.790)
KENNA,W B Region 2, Atlanta, Safeguards Branch 80/10/24 07392 024

--B010606295 1E Insp Rept 70-0143/80-29 on B00811-0912 Noncompliance noted containers not tamper-safe Details withheld (ref 10CFR2.790)
LEE,T B Region 2, Atlanta, Office of the Director KAMLE,J Region 2, Atlanta, Safeguards Branch 80/10/24 1p. 07392 024

B01080378 Responds to B01120 ltr requesting 6-month time extension recovering certain "old generation" scrap matls Extension granted Encl to B01120 ltr withheld (ref 10CFR2.790)
PARLON,J O Material Control Licensing Branch 80/12/17 1p. 07416 361

B01140818 Responds to B00922 ltr re LRC response to public law re addition of six positions in Div of Safeguards devoted to regulatory improvement & requesting info re facility inventory differences Six person task force formed.
MEARIE,J F Commissioners 80/12/18 2pp. 07461 319.

--B01140832 Responds to B00922 ltr re NRC response to public law re addition of six positions in Div of Safeguards devoted to regulatory improvement & requesting info re facility inventory differences Six person task force initiated
MEARIE,J F Commissioners 80/12/18 2pp 07461 321.

--B01140846 Requests info re NRC response to Public Law 96-295 re addition of six Div of Safeguards positions devoted to regulatory improvements Also requests monthly reports re facility matl losses vs limits prior to D00626 order.
UDALL,M K House of Rep., Interior & Insular Affairs
OJILEM,J H House of Rep 80/09/22 2pp 07461 323

B01120219 Ack receipt of revised Sections 1.0.3.0.4.0 & 0.0 to fundamental nuclear matl control plan Plan revisions acceptable except Section A.2.2
PARLON,J O Material Control Licensing Branch 80/12/22 2pp 07447 034

B01060812 Addl response to F01A request for info re Pu unaccounted at facility Forwards 1E Rept, "Technical Assessment of Inventory Differences at NRS Jan 1978-Mar 1980."
FELTCH,J H Division of Rules and Records 80/12/24 1p. 07460 125

--B01060819 Informs NRC of possible overexposure to highly enriched employee Exposure resulted from leak in U hexafluoride process vent sys. Lists rods to prevent recurrence RD Bailey 790906 ltr encl
MAHSEER,W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 790906 5pp

B01160131 Ack receipt of B01219 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 70-0143/80-24
MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/12/30 1p. 07469 338

--B01160138 Advises that scheduled commitment dates will be delayed to delays in equipment delivery No commitment dates listed All other corrective actions completed as scheduled.
MAHSEER,W C Nuclear Fuel Services, Inc. (subs of Getty Oil Co) 03/12/19 1p 07469 337.

--B01160148 Ack receipt of B01015 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 70-0143/80-24 Supplemental response re review of hexafluoride storage & process sys within Bldgs 302 & 303 to be submitted by B01203
O'REILLY,J P Region 2, Atlanta, Office of the Director 80/11/05 1p 07469 341

810190229 Forwards revised Amend MOP-2 to License SNM-368, amending
fundamental nuclear material control plan, in response to 801202
request New License Condition 2.1 incorporates revisions.
PARKER, J. C. Material Control Licensing Branch 80/12/24. 2pp.
07475 303

8101070598 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials." No written response required
BNIEZEK, J. H. Division of Fuel Facility & Materials Safety
80/08/29 1p 07414-176

DOCKET 70-0607 UNION CARBIDE CORP.

0101100137 Submits info re exemption from compliance w/10CFR70.24 in portions of criticality monitoring program where requirements are inappropriate. Exemption requested for areas where matl is handled in dry oxide form
VOTH, H. H. Union Carbide Corp 80/12/05 8pp 07441-341

8101070226 Recommends that nuclear criticality safety aspects of Union Carbide Corp application to store waste form process containers underwater in transfer canal at facility receive approval
PADE, R. O. Uranium Fuel Licensing Branch 80/12/11 1p 07415-240

8101130232 Requests payment of addl minor safety & environ amend fee for Amend 3 to License BNM-639
WEISB, D. License Fee Management Branch 80/12/19 1p 07309-001

0101130123 Application for amend to License R-B1 & License BNM-639 to change licensee name from Union Carbide Corp to Union Carbide Subsidiary H. Inc (Co B)
HCGOVERH, J. J. Union Carbide Corp 81/01/08 1p 07449-361

DOCKET 70-0720 UTAL, UNIV OF

8101070579 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials." No written response required
BNIEZEK, J. H. Division of Fuel Facility & Materials Safety
80/08/29 1p 07415-325

DOCKET 70-0734 GENERAL ATOMIC CO

0101210002 Addl response to FOIA request for nine categories of records re fees concerning withdrawal, suspended or postponed applications. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 80/11/21 5pp

--8012100268 Requests withdrawal of 700413 proposed amend to License BNM-368. Amend fee should be returned
KIRK, W. F. United Nuclear Corp 70/06/12 1p

--8012100336 Notifies of partial refund of fee re 780629 application for amend to License BNM-696 due to NRC denial. Actual expenditures for prof manpower have been determined & Ofc of Controller notified
MILLER, W. O. License Fee Management Branch 80/02/01 1p

--0012100340 Requests partial refund of fee to GA Co re review of 780629 application for amend to License BNM-696. Lists actual manhours required for review & amount of refund due.
MILLER, W. O. License Fee Management Branch 80/02/01 1p

--8012100344 Submits costs & manhours incurred in review of 780629 application for amend to License BNM-696
MCCORMACK, G. W. Physical Security Licensing Branch. PARTLOW, J. O. Material Control Licensing Branch 79/12/17 1p.

8101290537 Forwards IE Insp Rept 70-0734/80-10 on 800915-19. No noncompliance noted
BOOK, H. E. Region 3, San Francisco, Fuel Facility & Materials Safety Branch 80/12/04 2pp 07309-001.

--801290542 IE Insp Rept 70-0734/80-10 on 800915-19. No noncompliance noted. Major areas inspected: liquid waste evaporation ponds & submerged radioactive liquid waste retention tanks for possible leakage & environ monitoring
COOLEY, W. J., THOMAS, R. O., BOOK, H. E. Region 3, San Francisco, Fuel Facility & Materials Safety Branch 80/12/01 10pp 07309-001.

8012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawal, suspended or postponed applications. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 80/11/21 5pp

--8012100187 Notifies of partial refund due re withdrawal of 780629 application for amend to License BNM-960 Ofc of Controller has been notified
MILLER, W. O. License Fee Management Branch 78/08/23 1p

--8012100192 Requests partial refund of fee due GE re review of application for amend to License BNM-960. Lists actual manhours required for review & amount of refund due
MILLER, W. O. License Fee Management Branch 78/08/23 1p

--8012100277 Denies 780405 application for amend to License BNM-960. Lists actual manhours provided are inadequate to support redesignation of vital areas
MCCORMACK, G. W. Physical Security Licensing Branch 70/07/14

8101050494 Response to ASLB 801210 notice of second prehearing conference. Prehearing process should resume immediately. Evidentiary hearing should begin 60 days after 810106 prehearing conference
EDGAR, G. I. General Electric Co 80/12/29 3pp 07390-221

8101160236 Responds to State of CA Regional Water OC Board 00102 re proposed radiological environ monitoring program. Licensee review of program, reflecting board resolution, will be considered in license renewal evaluation
ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 80/12/29 0746B-355

0101290522 Forwards increment of analysis of effects of natural phenomena re facility. Two reports & LLL draft "Seismic Evaluation of Bldg 102 of GE Valleritos Nuclear Ctr" encl
ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch
NRC-03-78-150 01/01/19 2pp 07573-001

--8101290527 Draft "Seismic Evaluation of Bldg 102 of GE Valleritos Nuclear Ctr"
ENDEBROCK, E. O. Los Alamos Scientific Laboratory 81/01/19 112pp 07573-003

--0101290529 Forwards Hall & Newmark review of LLL draft rept. "Seismic Evaluation of Bldg 102 of GE Valleritos Nuclear Ctr". Recommends that review be adopted as staff position
AYER, J. E., BURKHARDT, W. Advanced Fuel & Spent Fuel Licensing Branch 81/01/19 1p 07573-115

DOCKET 70-0818 EASTERN NAZARENE COLLEGE

8101290508 Discusses IE Insp Rept 70-0818/80-01 conducted on 800915-19. Noncompliance noted. Major areas inspected: examination of procedures, representative records & measurements & observations by inspector.
KINNEHAN, J. O. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/25 1p 07571-316

DOCKET 70-0820 UNITED NUCLEAR CORP

0101290754 Forwards IE Insp Rept 70-0820/80-21 on 801015. No noncompliance noted
MARTIN, W. O. Region 1, Philadelphia, Safeguards Branch 80/12/29 0756D-227

--8101290758 IE Insp Rept 70-0820/80-21 on 801015. No noncompliance noted. Major areas inspected: packaging & sealing matl for export
JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch
MCKEDON, L. M. Region 1, Philadelphia, Office of the Director 80/11/12 1p 0756B-229

8101230218 Forwards IE Insp Rept 70-0820/80-22 on 801104-05. No noncompliance noted. Details of Insp withheld (ref 10CFR2.7901)
MARTIN, W. O. Region 1, Philadelphia, Safeguards Branch 80/12/29 07514-061

--8101230223 IE Insp Rept 70-0820/80-22 on 801104-05. No noncompliance noted. Major areas inspected: verification of imports & exports & review of BNM holdings. Details of Insp withheld (ref 10CFR2.7901)
ZIBULSKY, H. Region 1, Philadelphia, Office of the Director
JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch 80/12/29 07511-063

810121018d Submits agenda of issues to be discussed at next Citizens Advisory Committee state meeting w/related info
GRANL.H Rhode Island, State of 80/12/05 18pp 073CB 001

8101190221 Notifies that shipment of residual waste composed of collected ash, discussed in 801224 telcon will be approved, pending verification of QA program procedures. Approval of lagoon 3, and waste shipments has been deferred.
GRIER, B.H Region 1, Philadelphia, Office of the Director 80/12/11 2pp 07475 307

8101160205 Forwards list of identification numbers re drums & boxes that are acceptable for shipment & burial in Barnueil, SC NRC insp verified that packages contained no liquid waste
GRIER, B.H Region 1, Philadelphia, Office of the Director 80/12/15 2pp 0746B 331

8101160410 Discusses NRC 801210-12 & 15 insp of packaged waste for shipment from facility to SC waste is properly packaged for shipment & burial
GRIER, B.H Region 1, Philadelphia, Office of the Director 80/12/16 2pp 07309 001

--8101160412 Submits list of drums & contents for waste shipment from facility to SC burial site
D'ONNELL, J United Nuclear Corp 80/12/12 2pp 07309 001

--8101160413 Submits list of boxes & contents for waste shipment from facility to SC burial site
D'ONNELL, J United Nuclear Corp. 80/12/12 1p 07309 001

--8101160414 Submits list of boxes & contents for waste shipment from facility to SC burial site
D'ONNELL, J United Nuclear Corp 80/12/12 1p 07309 001

8101190262 Forwards revised Amend MPP-2 to License SNM-777, amending decommissioning fundamental nuclear matl control plan in response to 801203 request New License Condition 2 & incorporates revisions re timing of record adjustments
PARTLOW, J.O Material Control Licensing Branch 80/12/22 2pp 07476 039

8101050551 P18-1-80-179 United Nuclear Corp Recovery Sys granted permission to ship non-lagoon waste to Barnueil, SC, for burial Region 1 inspected packaging consisting of 61 drums & 16 boxes of waste for QA waste shipped on 801217 & 19.
KINNEY, W.W., CROCHER, H.W. Region 1, Philadelphia, Office of the Director 80/12/23 2pp 07375 336

DOCKET 70-0821 WASHINGTON & LEE UNIV

8101090796 Submits estimated resource requirements for completing QESMD proceeding Differences in estimates for original QESMD project & estimates to complete proceeding noted
CUAVINGHAM, R.E Division of Fuel Cycle & Material Safety 80/09/15. 3pp 07309 001

DOCKET 70-0824 BABCOCK & WILCOX CO

8101120548 Discusses info required for development of criteria re decontamination of area adjacent to property. Area must be decontaminated & radionuclides identified
CROCHER, H.W Uranium Fuel Licensing Branch 80/12/30 2pp 07447 187

DOCKET 70-0882 COLUMBIA UNIV.

8101230319 Forwards renewed License SNM-0870, containing conditions discussed & agreed upon on 801113 License valid for 5 yrs. Amends must be requested in form of replacement pages to license application
PAGE, R.O Uranium Fuel Licensing Branch 81/01/14 1p 07512: 075

--8101230323 License SNM-0870 for Columbia Univ in NY City authorizing possession & use of U-235, U-232 & Pu in fission counters & for storage purposes
PAGE, R.O Uranium Fuel Licensing Branch 81/01/14. 17pp 07512 076.

DOCKET 70-0925 CHARRON FACILITY

8012100902 Addl response to FOIA request for nine categories of re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTON, J.H Division of Rules and Records 80/11/21 5pp

--8012100380 Notifies of partial refund due re 790918 application amend to License SNM-928 to use facility for bench-scale coal liquefaction development project No amend to license was necessary
MILLER, W.D License Fee Management Branch 80/03/28 1p

--8012100385 Requests partial refund of fee to Kerr-McOee Nuclear application for amend to License SNM-928 Lists actual manhours required for review & amount of refund due.
MILLER, W.D License Fee Management Branch 80/03/28 1p

--8012100389 Submits costs & manhours incurred in reviewing 790918 application for amend of License SNM-928 Review was completed on 791228
DEANEY, J.C., PAGE, R.O Uranium Fuel Licensing Branch 80/03/28 1p

DOCKET 70-1007 GENERAL ELECTRIC CO

8101090743 Amend 3 of License SNM-54, changing License Condition 2 performance of flow rate checks on process ventilation sys & incorporating Conditions 34 & 35 re exemption from criticality & emergency drill requirements
PAGE, R.O Uranium Fuel Licensing Branch 80/11/10. 2pp 07425 341.

--8101090351 Safety evaluation re application to amend License SNM-54 exempting requirements re annual ventilation flow rate checks & criticality & emergency drill Recommends issuance of amend.
STEVENSON, R.L., CROCHER, H.W Uranium Fuel Licensing Branch 80/11/10 2pp 07425 343

DOCKET 70-1035 BRIGHAM YOUNG UNIV.

8101070598 Forwards 1E Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials - 1p written response required
SMITHEX, J.H Division of Fuel Facility & Materials Safety. 80/08/29 1p 07414 176

DOCKET 70-1100 COMBUSTION ENGINEERING, INC

8101060739 Forwards 1E Insp Rept 70-1100/80-09 on 801006-10 No noncompliance noted
MARTIN, J.Q Region 1, Philadelphia, Safeguards Branch. 80/10/29 2pp 07400 259

--8101060747 1E Insp Rept 70-1100/80-09 on 801006-10 No noncompliance noted Major areas inspected records & repts & license action on immediate action ltr Portions withheld ltr 10CFR2.7901
DELLA RAITA, A., WELTNER, E.F. Region 1, Philadelphia, Office of the Director. JOYNER, J.H Region 1, Philadelphia, Safeguards Branch 80/10/29 1p 07400 301

8101300157 Ack receipt of 801024 ltr informing NRC of steps taken correct violations noted in 1E Insp Rept 70-1100/80-07.
SMITH, G.H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/17 1p 07583: 162

--8101300164 Responds to NRC 801008 ltr re violations noted in 1E Rept 70-1100/80-07. Corrective actions: criticality analyses for not-safe-by-geometry containers will be updated & fuel bundle shipping containers relocated
PIANKI, F.J Combustion Engineering, Inc 80/10/24. 2pp 07583 163

--8101300169 Forwards 1E Insp Rept 70-1100/80-07 on 800826-29 & non violation
SMITH, G.H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/10/08 2pp 07583: 165

--B101300173 Notice of violation from insp on B00026-29
e Region 1, Philadelphia, Office of the Director 80/10/07 1p
075B3 167

--B101300177 IE Insp Rept 70-1103/80-07 on B00026-29 Noncompliance noted
ngt did not assure that use of hot-safe-by-designing
containers had been analyzed to establish safety units &
controls
ROTH, J Region 1, Philadelphia, Office of the Director
CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 00/10/07 17pp 075B3 168

B101190253 Approves vendor B01212 request for 19-day extension to
reconcile physical inventory of low enriched U.
BURNETT, R F Division of Safeguards 80/12/23 1p 07476 072

B101190268 Revises Amend MPP-4 to License SNM-1067, adding License
Condition 2.1.1 re inventory procedures for item
verification of low enriched U fuel rods. in response to
B01218 request
PARTLOW, J O Material Control Licensing Branch 80/12/24 1p
07476.048

DOCKET 70-1110 C-E POWER SYSTEMS

B101130127 Requests payment of minor safety & environ amend fee for
administrative amend to license SNM-10671
WEISS, O License Fee Management Branch 80/12/19 1p 07309 001

DOCKET 70-1111 ELIZABETH TOWN COLLEGE

B101130705 Discusses IE Insp Rept 70-1111/80-01 of License SNM-1063
conducted on B01205 No noncompliance noted. Major areas
inspected: radiation safety & regulations compliance
KINNEHAN, J O Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 80/12/22 1p 07454 039

DOCKET 70-1113 GENERAL ELECTRIC CO

B012100002 Addl response to FOIA request for nine categories of records
re fees concerning withdrawn, suspended or postponed
applications Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--B012100230 Requests partial refund of fee to OE re 790402 application
for amend to License SNM-1097 Lists actual manhours required
for review & amount of refund due.
MILLER, W O License Fee Management Branch 79/07/16 1p

--B012100245 Requests partial refund of fee to OE re 700B03 application
for amend to License SNM-1097 Lists actual manhours required
for review & amount of refund due.
MILLER, W O License Fee Management Branch 79/08/13 1p

--B012100302 Notifies of partial refund due re NRC denial of 790402
application for amend to License SNM-1097 Manhour
expenditures have been reviewed & Ofc of Controller
notified.
MILLER, W O License Fee Management Branch 79/07/16 1p.

--B012100316 Withdraws 700B03 application for amend to License SNM-1097,
to use particular canister w/full face masks. Canisters will
continue to be shipped by current vendor in accordance w/
relevant purchase orders.
KAPLAN, A L General Electric Co 79/04/20 1p

B101290698 Forwards request for addl info re actions to be taken to
correct violations noted in IE Insp Rept 70-1113/80-14.
O'REILLY, J P Region 2, Atlanta, Office of the Director 81/01/12
3pp 07574:299.

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP

B101200134 Ack receipt of IE Insp Rept 70-1151/80-27 on B01104-07. No
proprietary info.
OGDOWIN, M L Westinghouse Electric Corp. 80/12/04 1p 07406 132

--B101200137 Forwards IE Insp Rept 70-1151/80-27 on B01104-07. No
noncompliance noted
KENNA, W B Region 2, Atlanta, Safeguards Branch 00/11/19 1p
07486:133

--B101200144 IE Insp Rept 70-1151/80-27 on B01104-07 No noncompliance
noted Major areas inspected nuclear criticality safety,
operations, procedure control, maint, safety committees & IE
Circulars 00-14 & 00-20
CORYELL, O P Region 2, Atlanta, Office of the Director
KAMLE, J B Region 2, Atlanta, Safeguards Branch 80/11/19
07486 134

B101050573 Forwards IE Insp Rept 70-1151/00-26 on B01020-24 No
noncompliance noted
KENNA, W B Region 2, Atlanta, Safeguards Branch 00/12/16 2p
07390 178

--B101050579 IE Insp Rept 70-1151/80-26 on B01020-24 No noncompliance
noted Major areas inspected shipping & receiving Details
withheld (ref 10CFR2 7901
JOHNS, D H Region 2, Atlanta, Office of the Director KAMLE,
Region 2, Atlanta, Safeguards Branch 80/12/15 1p 07390 1

DOCKET 70-1257 MIXED OXIDE FUEL FABRICATION PLANT, EXXON NUCLEAR CO. 1

B101060377 Forwards IE Insp Rept 70-1257/80-09 on B01117-21 No
noncompliance noted Insp rept withheld (ref 10CFR2 7901
NORDEHANG, L R Region 5, San Francisco, Safeguards Branch
80/12/17 1p 07391 250

B101160347 Forwards IE Insp Rept 70-1257/00-10 on B01200-12 No
noncompliance noted Encl withheld (ref 10CFR2 7901
NORDEHANG, L R Region 5, San Francisco, Safeguards Branch
81/01/06 1p 07470 349

B101210653 Ack receipt of B01208 ltr in response to NRC B01120 not
of violation Corrective actions will be reviewed during next
Insp
NORDEHANG, L R Region 5, San Francisco, Safeguards Branch
81/01/05 1p 07448 360

B101220192 Amend 1 to License SNM-1227, authorizing changes in fill
tests, Condition 9 & company organization
PAGE, R O Uranium Fuel Licensing Branch 81/01/06 1p 07495

--B101220197 Safety evaluation supporting licensee B01121 applicat
amend License SNM-1227 to authorize change in filter tests &
company organization
STEVENSON, R L, CRO, J W T Uranium Fuel Licensing Branch
81/01/06 2pp 07495 347

B101270575 Notifies that administrative amend fee is due re vendor
B01222 request for extension to submit physical protection
plan
WEISS, O License Fee Management Branch 81/01/12 1p 07543:

DOCKET 70-1268 ETHAN UNIV OF

B101070579 Forwards IE Info Notice 00-32, "Clarification of Certain
Requirements for Exclusive Use Shipments of Radioactive
Materials " No written response required
SMITZKE, J H Division of Fuel Facility & Materials Safety
80/08/29 1p 07415 325

DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO

B101230049 Forwards DR Dawson B10105 ltr to RE Cunningham & Revisi
to "Radiological Emergency Plan for Morris Operation."
NEED-21894 Related correspondence
RODNEY, M A Mayer, Drown & Platt 81/01/07 2pp 07511 265

--B101230054 Forwards Revision 3 to "Radiological Emergency Plan f
Morris Operation," NEDO-21894
DANFORD, M General Electric Co 81/01/05 2pp 07511 267

--B101230059 "Radiological Emergency Plan for Morris Operation," R
3
e General Electric Co NEDO-21894-3 80/12/31 64pp
07511 269

B101230032 Forwards amended application for license renewal submit
to NRC on B10112 Related correspondence
RODNEY, M A Mayer, Drown & Platt 81/01/11 1p 07103:001

--B101230038 Forwards amended application for renewal of License
SNM-1265
WOLFE, O General Electric Co 81/01/12 4pp 07103 001

--B01023043 Amended application for renewal of License SM-1265 authorizing receipt, possession, storage & transfer of irradiated fuel from INRS
* General Electric Co 80/12/31 154pp 07183 C01

B010260175 Forwards illustrations omitted from Attachment H on Tech Specs to amended application for renewal of License SM-1265 Related correspondence
RODLEY, M A Mayer, Brown & Plett 81/01/14 3pp 07523 293

DOCKET 70-1327 UT & CONVERSION FACILITY, ALLIED GENERAL NUCLEAR

B01090779 Forwards memos re preliminary estimates of resource needs should "GESMO-type" proceeding be reinstituted info derived from discussion during B01201 meeting
DAVIS J O Office of Nuclear Material Safety & Safeguards, Director 80/12/05 1p

--B01090796 Submits estimated resource requirements for completing GESMO proceeding Differences in estimates for original GESMO project & estimates to complete proceeding noted
CUMMINGHAM, R E Division of Fuel Cycle & Material Safety 80/09/15 3pp

--B010160686 Advises that GESMO 1976 study & rept should be revised pending congressional mandate to reopen hearings
DAVIS J O Office of Nuclear Material Safety & Safeguards, Director 80/08/08 3pp

DOCKET 70-1374 LOUISIANA STATE UNIV

B01070568 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials" No written response required
SMIEZKA, J H Division of Fuel Facility & Materials Safety 80/08/29 1p 07415 333

DOCKET 70-1426 OLAHOMA, UNIV OF

B01070571 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials" No written response required
SMIEZKA, J H Division of Fuel Facility & Materials Safety 80/08/29 1p 07415 339

DOCKET 70-1462 HARPER-GRACE HOSP HARPER HOSP DIV, DETROIT, MI

B01090779 Forwards memos re preliminary estimates of resource needs should "GESMO-type" proceeding be reinstituted info derived from discussion during B01201 meeting
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 80/12/05 1p

--B01090796 Submits estimated resource requirements for completing GESMO proceeding Differences in estimates for original GESMO project & estimates to complete proceeding noted
CUMMINGHAM, R E Division of Fuel Cycle & Material Safety 80/09/15 3pp

--B010160686 Advises that GESMO 1976 study & rept should be revised pending congressional mandate to reopen hearings
DAVID, J O Office of Nuclear Material Safety & Safeguards, Director 80/08/08 3pp

DOCKET 70-1470 VET ADMIN HCSP, LOS ANGELES, CA

B01060687 Forwards IE Info Notice 80-35, "Leaking & Dislodged I-125 Implant Bsees" No written response required w/o encl
ENCKEL, R H Region 5, San Francisco, Office of the Director 80/10/10 1p 07400:182

DOCKET 70-1738 PACIFIC GAS & ELECTRIC CO

B01140780 Amend 9 to License SM-1503, extending expiration date until B01630, in response to B01202 request
PAGE, R G Uranium Fuel Licensing Branch 80/12/31 1p 07451:314

DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO

B010100181 Responds to FOIA request for five categories of documents transportation of Pu Forwards documents listed in Apps A & B info partially withheld safeguards info ref FOIA Exemption 31
FELT, J H Division of Rules and Records 80/12/12 6pp 07437 319

--B010100373 Requests temporary amend to SNM Security Transportation 11 to transport MO-1 containers in conventional 40-ft self-loader van trailer Amend required due to size of containers to be transported
RUTENFRDGER, E Tri-State Motor Transit Co (subs of Georgia Pacific Corp) 80/01/30 3pp

DOCKET 70-1821 PLUT PROD FACIL, ALLIED GENERAL NUCLEAR SERVICES CORP

B01090779 Forwards memos re preliminary estimates of resource needs should "GESMO-type" proceeding be reinstituted info derived from discussion during B01201 meeting
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 80/12/05 1p

--B01090795 Submits estimated resource requirements for completing GESMO proceeding Differences in estimates for original GESMO project & estimates to complete proceeding noted
CUMMINGHAM, R E Division of Fuel Cycle & Material Safety 80/09/15 3pp

--B010160686 Advises that GESMO 1976 study & rept should be revised pending congressional mandate to reopen hearings
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 80/08/08 3pp

B01020094 Advises that add review of Allied-General Nuclear Bycs application file to provide basis for discretionary refund of any part of application fee
BONDHAGE, D J Office of Administration 80/12/22 3pp 07467 10

DOCKET 70-1936 TEXAS A&M UNIV

B01070575 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials" No written response required
SMIEZKA, J H Division of Fuel Facility & Materials Safety 80/08/29 1p 07415 335

DOCKET 70-2249 HUTZEL HOSP DETROIT, MI

B01070292 Ack receipt of B01016 & 1201 ltr informing NRC of steps taken to correct violations noted in IE Insp of License SM-1639 & 21-03001-01
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/22 1p 07415 200

--B01070297 Informs of formation of committee to monitor regulatory compliance
JACOBELL, F Hutzel Hosp Detroit, MI 80/12/01 1p 07415 208

--B01070299 Responds to NRC B00925 ltr re violations noted in IE Insp License 21-03001-01 on B00925, corrective actions: amend to license incorporating appropriate individuals & new possession limit requested
BODTH, E, NOWICKI, K Hutzel Hosp, Detroit, MI 80/10/16 7pp 07415 201

DOCKET 70-2322 EQULOW INTERNATIONAL CO

B010100208 Requests extensions to 791219 route approvals & B00928 Fayetteville bypass Shipment will be four casks containing MTR type fuel elements imported from Sweden
RAVENSCROFT, W Edlow International Co 80/12/03 1p 07309:001

DOCKET 70-2375 PACIFIC GAS & ELECTRIC CO

B01140788 Amend 5 to License SM-1667, extending expiration date until B01630, in response to B01202 request
PAGE, R G Uranium Fuel Licensing Branch 80/12/31 1p 07461 315

DOCKET 70-2434 TRANSNUCLEAR, INC

01290426 Amend 2 to license for Transnuclear, Inc. changing expiration date from 810131 to 820131
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 81/01/23 1p 07570 344

DOCKET 70-2479 TRANSNUCLEAR, INC

01100141 Responds to FOIA request for five categories of documents re transportation of Pu Forward documents listed in Apps A & C. Info partially withheld safeguards info inef FOIA Exemption 3)
FELDM, J. M. Division of Rules and Records 80/12/12 6pp

010100296 Application by Transnuclear, Inc to amend license to import irradiated fuel elements from West Germany, adding addl 8.470 kg U-235 & 0.143 kg Pu
MATBON, V Transnuclear, Inc 78/07/06 3pp

010100394 Application by Transnuclear, Inc for license to import 100.2 kg U-235 & 106 kg Pu in form of irradiated fuel elements from West Germany
MATBON, V Transnuclear, Inc. 77/01/12 3pp

01290417 Amend 5 to license for Transnuclear, Inc. increasing amount of matl imported to 445,277 kg U-235 contained in 935-296 kg U & 966 kg produced Pu
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 81/01/26 1p 07570:343

DOCKET 70-2911 TRANSNUCLEAR, INC.

01300761 Amend 2 to license for Transnuclear, Inc. extending expiration date from 810131 to 020131
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 01/01/23 1pp 07583:345

DOCKET 70-2929 CARDINAL CUSHING GENERAL HOSP BRECKTON, MA

01290623 Ack receipt of 801103 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-01935/80-01 & 70-2929/80-01
KINNEHAN, J. D. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/25 1p 07571 324

0101290626 Responds to NRC 000926 ltr re violations noted in IE Insp Repts 30-01935/80-01 & 70-2929/80-01. Corrective actions: different style syringe shields will be used.
JEPSEN, R. J. Cardinal Cushing General Hosp Brockton, MA 80/11/03 1p. 07571 325

DOCKET 70-2623 MCQUIRE SPENT FUEL POOL, DUKE POWER CO

01120594 Submits Amend 4 to License BNM-1773, permitting movement & insertion of single fuel assembly into various reactor vessel locations for indexing purposes
PAGE, R. G. Uranium Fuel Licensing Branch 80/12/30 1p. 07447:191

01140170 Safety evaluation supporting movement & insertion of single fuel assembly into different locations of core for indexing purposes. License amend recommended.
METZLACH, N. Uranium Fuel Licensing Branch. 80/12/30 2pp 07460:360

01160200 Request for extension until 810209 to file brief in response to NRC & intervenor 801222 briefs on exceptions. Certificate of Bvc encl.
WEISS, E. R., BISHOP, L. L., SCHERR, B. J. Natural Resources Defense Council. 81/01/13 4pp 07470:053

01230404 Response opposing NRDC 810113 motion for extension until 810209 to file brief in opposition to exceptions, because of time constraints. Certificate of Bvc encl.
MCQUARRY, J. M. Duke Power Co MCDARRY, J. M. Debevoise & Liberman. 81/01/16 4pp 07512:120

01220086 Answer to NRDC 010113 motion for extension of time. Clarifies that NRC will not object to motion provided that Council will not object to NRC reply to brief w/notice of appearance & Certificate of Bvc.
BRENNER, L. Hearing Branch 3. 81/01/19 3pp. 07502:115

8101230113 Order granting extension until 810209 for NRDC & other parties to file briefs supporting ASLB decision in spent fuel transportation proceeding. Util brief due 10 days after appellate brief w/ Certificate of Bvc
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 81/01/19 5pp 07512 006

8101230462 Reply supporting NRDC 810113 motion for extension until 810209 to file brief opposing exceptions. Issues are detailed & all counsel are new to case. Certificate of Bvc encl.
WEISS, E. R., BISHOP, L. L. Natural Resources Defense Council WEISS, E. R. Herman & Weiss 81/01/19 App 07512 153

8101270375 Forwards NRC 810114 answer to NRDC motion for extension of time & notice of appearance. W/o encl.
BRENNER, L. Hearing Branch 3 81/01/23 1p 07544 095

8101270049 Notice to ASLB of new info to amicus curiae brief of Electric Util Cos Nuclear Transportation Group re DOT final rules on highway routing of spent fuel shipments FR excerpt encl.
TROSTEN, L. M. Electric Utility Companies Nuclear Transportation Group. TROSTEN, L. M. LeBoeuf, Lomb, Leiby & MacRae 81/01/23 24pp 07309:001

8101230442 Request to file reply to NRDC brief & any other brief filed opposing exceptions to ASLB 801031 decision. Certificate of Bvc encl.
MCQUARRY, J. M. Duke Power Co MCDARRY, J. M. Debevoise & Liberman 81/01/16 4pp. 07512:135

DOCKET 70-2838 CINCINNATI GAS & ELECTRIC CO

810100201 Informs of issuance of Amend 5 to License BNM-102, adding Condition 15 re maintaining & fully implementing all provisions of App F to facility Amend becomes effective 801114
PAGE, R. G. Uranium Fuel Licensing Branch 80/11/05 1p 07444:168

DOCKET 70-2882 SOUTHERN CALIFORNIA Edison CO

8101070232 Requests addl info re util 801027 application for revision of proposed license for new fuel storage. Util should describe controls used to ensure conformance w/ fuel storage pattern & that subcritical conditions will be maintained.
STEVENSON, R. L. Uranium Fuel Licensing Branch 80/12/17 1p 07414 275

DOCKET 70-2901 SOUTHERN CALIFORNIA Edison CO.

8101070232 Requests addl info re util 001027 application for revision of proposed license for new fuel storage. Util should describe controls used to ensure conformance w/ fuel storage pattern & that subcritical conditions will be maintained.
STEVENSON, R. L. Uranium Fuel Licensing Branch 80/12/17 1p

DOCKET 70-2900 VET ADMIN HOSP SAN DIEGO, CA

8101060681 Forwards IE InPo Notice 80-35, "Leaking & Dislodged 1-125 Implant Beads." No written response required w/o encl.
ENGELKEN, R. H. Region 5, San Francisco. Office of the Director 80/12/10 1p 07400:181

DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP. POWER SYSTEMS

8101070371 Expresses opinions on preliminary hearings held by NRC. Westinghouse & Safe Energy Alliance of Central AL re facility license application
WILLIAMS, L. G. Affiliation Unknown 80/12/31 1p 07309 001

0101140931 Response opposing C Oonelson petition to Intervene & motion substituting C Oonelson for DL Allied Certificate of Bvc encl.
COWAN, D. Z., KEURICK, J. R. Westinghouse Electric Corp. COWAN, B. Z. Eckert, Seamans, Cherin & Hellott 81/01/05 7pp. 07458 237

8101290136 Confirms telcon re 801202 ltr Discusses Safe Energy Alliance of Central AL attempt to intervene, receipt of 801124 meetings, whether Alliance contentions will be closed matter after 801219 & limited statement request
TURNER, E. E. Office of the Executive Legal Director 81/01/27 3pp. 07367:290

810100292 Informs that NRC will not file response to C Doneleon 801206
suppl to petition or 801220 second suppl to petition until
30 days after ASLB ruling on 801110 joint motion for
substitution of named intervenor
TJRK, S E Office of the Executive Legal Director 81/01/13 1p
07462 202

DOCKET 70-2936 MISSISSIPPI POWER & LIGHT CO

8101060102 Forwards review of Util 80100t application for authorization
to possess & use in-core detectors & for receipt, possession,
storage, insp & transportation of SM & byproduct matl Addl
info from Util needed by 810109
METZLACK, H Uranium Fuel Licensing Branch 80/12/03 5pp
07399 113

DOCKET 70-2937 PENNSYLVANIA POWER & LIGHT CO

8101060796 Forwards request for addl info needed to complete review of
application to receive & store fuel
METZLACK, H Uranium Fuel Licensing Branch 80/12/02 4pp
03897 261

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND
TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN
CONITIONS

DOCKET 71-0102 SOURCE PROD & EQUIP CO., INC

8101120060 Forwards Revision 1 to QA program for radioactive matl
package
DICHAARY, R F Source Production & Equipment Co., Inc 81/12/05 1p
07439 339

--8101120061 Revision 1 to QA program for radioactive matl package
* Source Production & Equipment Co., Inc 80/12/05 12pp
07439 340

DOCKET 71-0179 NUCLEAR CONTAINERS, INC

8101190748 Advises that unless response is received to NRC 791009
request for addl info, QA program application will be denied.
MACDONALD, C E Transportation Branch 81/01/06 1p 07476 121

DOCKET 71-0358 NAVY, DEPT OF, USS SIERRA

8101120054 Forwards QA program for radioactive matl package
SMITH, R H Navy, Dept of 80/12/03 1p 07445 294

--8101120057 QA program for radioactive matl package
KINSLEY, S B Navy, Dept of 80/08/14 5pp 07445 295

DOCKET 71-0398 TEXAS A&M UNIV

0101140154 Forwards revised QA program in response to NRC 801114 ltr
KANDALL, J D Texas A & M Univ 80/12/09 2pp 07461 197

--8101140163 QA program for shipping packages.
* Texas A & M Univ 80/12/31 6pp 07461 199

8101270934 Forwards QA program approval for radioactive matl package,
Revision 0
MACDONALD, C E Transportation Branch 81/01/09 1p 07549 201

--8101270937 QA program approval for radioactive matl package: 0398,
Revision 0
MACDONALD, C E Transportation Branch 81/01/09 1p 07549 204

DOCKET 71-0400 NAVY, DEPT OF

8101120042 Forwards NRC 800126 ltr w/ written statement confirming that
USS Bryce Canyon possesses NRC-approved QA program
Certificates of Compliance 9005 & 9007 issued to Automation
Industries under License 37-00611-09 retained by ship.
RIEDER, A E Navy, Dept of 80/12/08 2pp 07447 086

DOCKET 71-0401 RELIANCE TESTING LABORATORIES, INC

8101080370 Forwards QA program for NRC approval
FRIEDEL, F C Reliance Testing Laboratories, Inc 80/12/05 1p
07417 338

--8101080376 QA program for radiography Organizational chart incl.
FRIEDEL, F C, BROCKWELL, F Reliance Testing Laboratories, Inc
80/12/05 9pp 07417 339

DOCKET 71-0402 CSR LABORATORIES

8101160606 Lists approved procedures re activities under 10CFR71
utilized at lab Includes location where sealed sources will
be used &/or stored, approved sealed sources to be used in
radiography & approved exposure devices
WATSON, R L C & R Laboratories 80/12/06 4pp 07471 216

--8101160612 Informs that transportation activities may not be cond
in accordance w/10CFR71, lab must register w/NRC prior to
first shipment by certificate number for each package design
intended for use & have acceptable QA plan
MACDONALD, C E Transportation Branch 80/11/26 1p 07471 218

DOCKET 71-0403 SCHLUMBERGER WELL SERVICE

8101270337 Forwards QA program for Type B radioactive matl sealed
source transport packages
RACISER, C E Schlumberger Well Services 80/12/19 1p 07546

--8101270342 QA program for Type G radioactive matl sealed source
transport packages
SHURD, R R Schlumberger Well Services 00/12/19 19pp
07536 150

DOCKET 71-0404 ALASKA WELDING CENTER

8101270124 Forwards QA program for industrial radiography licenses
WATSON, S M Alaska Welding Center 80/12/18 1p 07547 047

--8101270126 QA program for industrial radiography licenses
* Alaska Welding Center 80/12/19 17pp 07547 048

DOCKET 71-0405 ENERGY, INC

8101230275 Forwards QA program for industrial radiography licenses
EMANEL, W H Energy Incorporated 80/12/18 1p 07512 069

--8101230286 QA program for industrial radiography licenses
* Energy Incorporated 80/12/18 5pp 07512 070

DOCKET 71-4986 MODEL RA-2, EXXON NUCLEAR CO., INC

8012100002 Addl response to FOIA request for nine categories of rec
re fees concerning withdrawn, suspended or postponed
applications. Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--8012100396 Notifies of review completion re 800402 application for
revision to Certificate of Compliance 4986
* Transportation Branch 80/07/22 1p

8012290565 Forwards application for renewal of Certificate of
Compliance 4986 for Model RA-2 Info still relevant to Model
RA-2 from all previous amend applications consolidated into
present application
HAPLAN, A L General Electric Co 80/12/10 2pp 07340 189

--8012290571 Application for Amend T-19 to Certificate of Compliance
consolidating all info from previous applications for Model
RA-2
* General Electric Co 80/12/05 98pp 07340 192

8101090907 Forwards Revision 9 to Certificate of Compliance 4986 for
Models RA-1, RA-2, RA-3 & RA-J
MACDONALD, C E Transportation Branch 80/12/19 2pp 03893 228

--8101070917 Certificate of Compliance 4986, Revision 9, for Models RA-1, RA-2, RA-3 & RA-J
MACDONALD, C E Transportation Branch 80/12/19 6pp 03893 283

DOCKET 71-5059 MODEL URAHY WIT-INK, NUCLEAR FUEL SERVICES, INC

8101190356 Requests that expiration date of Certificate of Compliance 5059 be extended until 810331 Consolidated application for certificate renewal will be provided by 810131 in response to WRC 801008 request Renewal Fee encl
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co.)
80/12/08 1p 07476 079

DOCKET 71-5086 MODEL UNC-2600, GENERAL ATOMIC CO

8101290556 Forwards Revision 5 of Drawing D-20354-B, Sheet 7, modifying outer drum lid from 14 gauge min to 16 gauge min Density and change will not effect performance requirements
KIRK, W F United Nuclear Corp, Naval Products Div 80/12/16 2pp 07575-273

DOCKET 71-5364 MODEL NPI-67-0442 NEUTRON PRODUCTS, INC

8101050426 Notifies of registration as user of Model NPI-67-0442.
MACDONALD, C E Transportation Branch 80/12/10 1p 07389 325

DOCKET 71-5760 MODEL BB-250-2, COMBUSTION ENGINEERING CO., INC

8101200003 Advises that drawing revisions to 800926 application for Certificate of Compliance 5768 for Model BB-250-2 shipping package will be submitted before 810131 All revisions will be submitted pending resolution of Item 2
AUSTIN, M A Babcock & Wilcox Co., Nuclear Material Div 80/12/11 1p 07407 022

DOCKET 71-5796 MODEL 181361, PICKER CORPORATION

8101140130 Requests to continue registration as user of Certificate of Compliance 5796
GILIN, B Laurence Livermore Laboratory 80/12/12 1p 07461 193

DOCKET 71-5805 MODEL ATCOR WIND CASK, AICOR, INC

81012290577 Forwards application for renewal of Certificate of Compliance 5805 Encl reflects compilation & consolidation of previously approved QAR & all amends in reg guide approved format.
CORBETT, J S Chem-Nuclear Systems, Inc 00/11/26 1p 07340 047

--81012290501 "BAR for Model CNS-3-55 Shipping Cask."
Chem-Nuclear Systems, Inc 80/11/26 149pp 07340 048

DOCKET 71-5900 MODEL DOT-6M TYPE B, BABCOCK & WILCOX CO

8101100100 Notifies of registration as user of Model DOT-6M Type B
MACDONALD, C E Transportation Branch 80/12/10 1p 07445 008

8101270061 Notifies of expiration of Certificate of Compliance 5908 for Model DOT-6M Type B To continue using package, should request renewal of existing certificate of compliance.
MACDONALD, C E Transportation Branch 01/01/07 1p 07547 031

DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO

81012290549 Forwards simplified drawings of GE Model 100 shipping container as requested Requests replacement of previously submitted detailed engineering drawings & extension of Certificate of Compliance 5926, pending renewal review
CUNNINGHAM, O E General Electric Co. 00/11/14 1p 07340 003

DOCKET 71-5938 MODEL HMPF, GENERAL ATOMIC CO

8101160763 Notifies of expiration of Certificate of Compliance 5938 for Model HMPF To continue using package, should submit consolidated application for renewal.
MACDONALD, C E Transportation Branch 81/01/07 1p 07472 063

DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CO

81012290569 Forwards simplified drawings for GE Model 1500 shipping container Requests replacement of previously submitted detailed engineering drawings
CUNNINGHAM, O E General Electric Co 00/11/14 1p 07340

8101300755 Advises of forthcoming amend fee refund re Revision Certificate of Compliance 5939
MILLER, W D License Fee Management Branch 01/01/19 1p 07505 260

DOCKET 71-5957 MODEL B11-1, ENERGY DEPT OF

81012290618 Submits addl info describing container for 030714 and request to Certificate of Compliance 5957 Contents will not decompose at temps below 000 F Forwards revised drawing of container
VOTH, M H Union Carbide Corp. 80/11/17 4pp 07340 035

DOCKET 71-5971 MODEL GE-200, GENERAL ELECTRIC CO

81012290532 Forwards simplified drawings of GE Model 200 shipping container for review Requests replacement of previously submitted detailed engineering drawings
CUNNINGHAM, O E General Electric Co 80/11/14 1p 07340

DOCKET 71-5980 MODEL GE-600, GENERAL ELECTRIC CO

81012290515 Forwards simplified drawings for GE Model 600 shipping container Requests replacement of previously submitted detailed engineering drawings
CUNNINGHAM, O E General Electric Co. 80/11/14 1p 07340

DOCKET 71-6144 MODEL 32, NUCLEAR ENGINEERING CO

8101190390 Requests registration as user of Certificate of Compliance 6144 for Model 15-1608
BRACKEN, K W Energy, Dept of 00/12/04 1p 07475 174

8101100069 Notifies of registration as user of Model 0-2
MACDONALD, C E Transportation Branch 00/12/10 1p 07444

DOCKET 71-6273 MODEL 48X, F. A. Y. ALLIED-GENERAL NUCLEAR SERVICES

8101190645 Requests renewal of Certificate of Compliance 6273 requests issuance of certificate of compliance for shipment of natural U under License SUB-526
CIPOLLA, A J Allied Chemical Corp 80/10/22 1p 07474 0

--8101190652 Certificate of Compliance 6273, Revision 3 for Model 48X, 48F & 48Y
MACDONALD, C E Transportation Branch 77/01/24 3pp 0

--8101190657 Ack receipt of 801027 ltr for renewal of Certificate of Compliance 6273 Renewal fee should be submitted
WEISS, D License Fee Management Branch 00/11/12 1p 07474 043

8101190744 Informs that application addressing IDCFR71 21 requirement be filed in order to renew Certificate of Compliance 6442
MACDONALD, C E Transportation Branch 81/01/02 1p 0747

DOCKET 71-6375 MODEL PB-1, CHEM-NUCLEAR SYSTEMS, INC

8101130257 Requests payment of fee for 100-day extension of Certificate of Compliance 6375
WEISS, D License Fee Management Branch 80/12/19 1p 07

8101050171 Forwards Revision 10 to Certificate of Compliance 6375
Model CHS 4-45
MACDONALD, C E Transportation Branch 80/12/23 3pp 073

--8101030173 Certificate of Compliance 6375, Revision 10, for Model CHS 4-45
MACDONALD, C E Transportation Branch 80/12/23 2pp 0

DOCKET 71-6460 MODEL SUPER TIGER, WESTINGHOUSE ELECTRIC CORP

801290495 Requests exemption from 10CFR71.42(b)(3) for Model 6400 shipping package. Certificate of Compliance 6400 in accordance with info
DIPAZZA R P. Westinghouse Electric Corp 80/11/20 1p
07340 017

--801290498 "Treatment, Packaging & Safety Assessment for Transporting Large Equipment Waste -
* Westinghouse Electric Corp 80/11/20 14pp 07340 018

--801290532 "Description of HCE/Richland Operations-Super Tiger (Model 6400)
* Westinghouse Electric Corp 80/11/20 3pp 07340 032

810106021 Notifies of authorization to use Model Super Tiger to deliver large equipment waste to carrier for transport in response to 801120 & 1215 requests Waste may not exceed 9 g Pu
MACDONALD, C E Transportation Branch 80/12/10 2pp 07392 399.

DOCKET 71-6458 MODEL BU-5, GENERAL ELECTRIC CO

810127005H Notifies of expiration of Certificate of Compliance 6458 for Model BU-5 To continue using package, should request renewal of existing certificate of compliance
MACDONALD, C E Transportation Branch 81/01/07 1p 07547 035

DOCKET 71-6573 MODEL HIT-506, NUCLEAR BATTERY CORP

801270226 Notifies of expiration of Certificate of Compliance 6573 for Model HIT-506 To continue using package, should request renewal of existing certificate of compliance
MACDONALD, C E Transportation Branch 81/01/07 1p 07546 018.

DOCKET 71-6574 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP

8101050431 Notifies of registration as user of Models HN-100 Series 1, HN-100 Series 2, HN-100S, HN-200, NL1-1/2 & 9080
MACDONALD, C E Transportation Branch 80/12/10 1p 07389 346

DOCKET 71-6601 MODEL LL-50-100, CHEM-NUCLEAR SYSTEMS, INC

8101050464 Notifies of registration as user of Models CNS B-120, GE-1600 & CNS B-175-H
MACDONALD, C E Transportation Branch 80/12/10 1p 07390 030.

8101050039 Requests to register as user of Model CNB1 LL-50-100 radioactive metal shipping cask
MOVEY, G A Metropolitan Edison Co 00/12/18 2pp 07385 273

DOCKET 71-6642 MODEL 4 5 TON CF, ENERGY SEPT OF

8101270084 Notifies of expiration of Certificate of Compliance 6642 for Model 4 5 ton CF To continue using package, should request renewal of existing certificate of compliance.
MACDONALD, C E Transportation Branch 81/01/07 1p 07547 038

DOCKET 71-6690 MODEL NFS-4, NUCLEAR FUEL SERVICES, INC.

8101100168 Requests that Certificate of Compliance 6698, Revision 12, be revised to recognize that inside diameters of end castings & inner cavity pipe were nfg to be slightly different
JOHNSON, C R Nuclear Assurance Corp 80/12/01 2pp 07443 006.

8101050450 Notifies of registration as user of Model NFS-4.
MACDONALD, C E Transportation Branch 80/12/10 1p 07387 023.

DOCKET 71-6717 MODEL 6717 D

8101100108 Notifies of registration as user of Models 6717-B & C-1
MACDONALD, C E Transportation Branch 80/12/10 1p 07445 011.

DOCKET 71-6744 MODEL POLY TIGER, NUCLEAR ENGINEERING CO

801290613 Informs of review of applications for renewal of Certificate of Compliance 6744 Previously submitted Drawing Revision J found not applicable Two cash drawings oncl
GSEYEP, W E Teledyne Energy Systems 80/11/11 4pp 0

DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO

8101140008 Application for revision of Certificate of Compliance Revision 10 Revision J11 clarify requirements for measurement of radiation & permit use of 73J Target Rock valve Fee encl
DAKSON, D M General Electric Co 80/11/26 3pp 07461

DOCKET 71-9097 MODEL 520, AUTOMATION INDUSTRIES, INC

8101050162 Forwards Revision 4 to Certificate of Compliance Model 520
MACDONALD, C E Transportation Branch 00/12/23 2pp 0

--8101050165 Certificate of Compliance 9007, Revision 4, for M
MACDONALD, C E Transportation Branch 80/12/23 2pp

DOCKET 71-9010 MODEL NL1-1/2, NL INDUSTRIES, INC

8101050431 Notifies of registration as user of Models HN-100 Series 1, HN-100 Series 2, HN-100S, HN-200, NL1-1/2 & 9080
MACDONALD, C E Transportation Branch 80/12/10 1p.

8101050456 Notifies of registration as user of Model NL1-1/2
MACDONALD, C E Transportation Branch 80/12/10 1p. 07

8101101122 Notifies of registration as user of Model NL1-1/2
MACDONALD, C E Transportation Branch 80/12/10 1p 07

DOCKET 71-9019 MODEL BU-7, GENERAL ELECTRIC CO

8101300749 Advises that no addl fee is required re Revision Certificate of Compliance 9019
MILLER, W O License Fee Management Branch 01/01/19. 1p 07585 359

DOCKET 71-9023 MODEL NL1-10/24, NL INDUSTRIES, INC

8101270076 Notifies of expiration of Certificate of Compliance for Model NL1-1/2 To continue using package, should request renewal of existing certificate of compliance
MACDONALD, C E Transportation Branch 01/01/07 1p. 07

DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC.

8101140152 Requests registration as user of Tech/Ops Models under Certificates of Compliance 9032 & 9033, respectively
FRIEDEL, F C Reliance Testing Laboratories, Inc 80/12/01 07460 353

DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC.

8101140152 Requests registration as user of Tech/Ops Models under Certificates of Compliance 9032 & 9033, respectively
FRIEDEL, F C Reliance Testing Laboratories, Inc. 80/12/01 07460 353.

DOCKET 71-9035 MODEL 680, TECHNICAL OPERATIONS, INC.

8101190360 Requests that Knolls Atomic Power Lab be registered as user of Certificate of Compliance 9035
SMITH, M E Energy, Dept. of 80/12/06 1p 07476 076

DOCKET 71-9036 MODEL C-1, SOURCE PRODUCTION EQUIPMENT CO.

8101100108 Notifies of registration as user of Models 6717-B & C-1
MACDONALD, C E Transportation Branch 80/12/10 1p. 0

BUCKET 71-9044 MODEL GE-1600. GENERAL ELECTRIC CO

012290590 Forward simplified drawings of GE Model 1600 shipping container Requests replacement of previously submitted detailed engineering drawings & extension of Certificate of Compliance 9044, pending renewal review process
CUNNINGHAM, G E General Electric Co 80/11/14 1p. 07340 011

01190353 Requests that Lynchburg Research Ctr be registered as user of Model CNSI 1-130
OLSEN, A F Babcock & Wilcox Co. 80/12/01 1p. 07475 002

01050464 Notifies of registration as user of Models CNS 8-120, GE-1600 & CNS 14-195-H
MACDONALD, C E Transportation Branch 80/12/10 1p 07390 030

01100104 Notifies of registration as user of Model OE-1600
MACDONALD, C E Transportation Branch 80/12/10 1p 07445 010

01090927 Forwards Revision 7 to Certificate of Compliance 9044 for Model GE-1600
MACDONALD, C E Transportation Branch 80/12/23 3pp 07430 273

0101090830 Certificate of Compliance 9044, Revision 7, for Model GE-1600
MACDONALD, C E Transportation Branch. 80/12/23 4pp 07430 276

BUCKET 71-9065 MODEL BU-4. GENERAL ELECTRIC CO

01270072 Notifies of expiration of Certificate of Compliance 9065 for Model BU-4. To continue using package, should submit consolidated application for renewal.
MACDONALD, C E Transportation Branch 81/01/07 1p 07547 036

BUCKET 71-9070 MODEL N-55. ENERGY DEPT OF

01200007 Requests that Item 5(b)(1)(1)(1) of Revision 3 to Certificate of Compliance 9070 be changed to permit transport of up to 200 g fissile Pu plus U (max) total quantity of Pu not to exceed 200 g Amend fee encl
HANSEN, L E Exxon Nuclear Co., Inc. (subs of Exxon Corp) 80/12/04 1p 07407 018

01100113 Notifies of registration as user of Model N-55
MACDONALD, C E Transportation Branch. 00/12/10 1p 07445 012

BUCKET 71-9072 MODEL OAHG-1. GENERAL ATOMIC CO

01270054 Notifies of expiration of Certificate of Compliance 9072 for Model OAHG-1 To continue using package, should submit consolidated application for renewal
MACDONALD, C E Transportation Branch 01/01/07 1p 07547 025

BUCKET 71-9074 MODEL AP-100. ANECD, INC.

01090446 Notifies of registration as user of Model AP-100
MACDONALD, C E Transportation Branch 00/12/10 1p 07389 340.

BUCKET 71-9079 MODEL HN-100 SERIES 2. HITTMAN NUCLEAR & DEVELOPMENT

01030431 Notifies of registration as user of Models HN-100 Series 1, HN-100 Series 2, HN-100S, HN-200, NL1-1/2 & 9080
MACDONALD, C E Transportation Branch 80/12/10 1p 07389 346.

BUCKET 71-9080 MODEL HN-600. HITTMAN NUCLEAR & DEVELOPMENT CORP

01030431 Notifies of registration as user of Models HN-100 Series 1, HN-100 Series 2, HN-100S, HN-200, NL1-1/2 & 9080
MACDONALD, C E Transportation Branch 80/12/10 1p. 07389 346

BUCKET 71-9086 MODEL HN-100 SERIES 1. HITTMAN NUCLEAR & DEVELOPMENT

01030431 Notifies of registration as user of Models HN-100 Series 1, HN-100 Series 2, HN-100S, HN-200, NL1-1/2 & 9080.
MACDONALD, C E Transportation Branch 80/12/10 1p

0101210132 Advisee of Intent to ship radioactive salt using Model HN-100
HAYEN, L D Northern States Power Co 80/12/10 1p 07491 301

BUCKET 71-9089 MODEL HN-100S

0101050431 Notifies of registration as user of Models HN-100 Series 1, HN-100 Series 2, HN-100S, HN-200, NL1-1/2 & 9080
MACDONALD, C E Transportation Branch 80/12/10 1p

BUCKET 71-9091 MODEL CNSI-14-195-H. CHEM-NUCLEAR SYSTEMS, INC

0101050464 Notifies of registration as user of Models CNS 8-120, GE-1600 & CNS 14-195-H
MACDONALD, C E Transportation Branch 80/12/10 1p 07390 030

BUCKET 71-9111 MODEL CN6-80A. CHEM-NUCLEAR, INC

0101070216 Requests registration as user of Model CN6-80A
HAYNES, J D Southern California Edison Co 80/11/24 1p 07414 243

0101050467 Notifies of registration as user of Model CN6-80A
MACDONALD, C E Transportation Branch 80/12/10 1p 07390 031

0101270143 Application for revision of Certificate of Compliance 9111 to permit use of improved containment strengthened outer shell
HANSEN, L J Nuclear Packaging, Inc 80/12/17 2pp 07546 003

--0101270146 "BAR for Model CN6-80 Shielded Cask to 10CFR71 Type A Packaging Requirements." Revision 3
Nuclear Packaging, Inc 80/12/17 5pp 07546 005

BUCKET 71-9124 MODEL L2-101 & L3-101. NUCLEAR ENGINEERING CO, INC

0012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--0012100212 Requests payment of addl fee for review of 780602 application for approval of Models L2-101 & L3-101, withdrawn on 790115. Addl charge concerns manhours involved in review of application
MILLER, H D License Fee Management Branch 79/03/07 1p

--0012100290 Reiterates 790307 request for addl fee re withdrawal of 780602 application for approval of Models L2-101 & L3-101. Fee should be provided within 30 days
WELLS, B License Fee Management Branch 79/04/24 1p

BUCKET 71-9129 MODEL UH1 LA-90. NORTHEAST UTILITIES

0012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTON, J M Division of Rules and Records 00/11/21 5pp

--0012100357 Notifies that addl fee is required for review costs re 780828 application for IIRC approval of Model UH1 LA-90. Request for approval was denied due to failure to provide addl info to support application
MILLER, H D License Fee Management Branch 80/02/25 1p

--0012100360 Requests that invoice for actual cost of processing 780828 application for shipping package approval be sent to utility
MILLER, H D License Fee Management Branch 80/02/25 1p

--0012100366 Notifies of review completion of 780828 application for shipping package approval. Project was completed in 36-h
Transportation Branch 79/09/17 1p

BUCKET 71-9130 MODEL NP-50-XXL. NUCLEAR PACKAGING, INC

0101050459 Notifies that Certificate of Compliance 9130 expired on 801031. Use of Model NP-50-XXL cannot be authorized.
MACDONALD, C E Transportation Branch 80/12/10 1p. 07390 016

DECREE 71-9102 MODEL T-3 NUCLEAR PACKAGING, INC

B10120002 Responds to 800825 application to amend Model T-3 shipping
case approval license should demonstrate that each of seven
primary contents will remain substantial within 9-inch
diameter capacity or that seven contents remain intact.
MACDONALD, C E Transportation Branch 80/12/19 1p 07487 023

LOCKE 71-9103 MODEL C-10, GAMMA INDUSTRIES

B101190725 Requests addl info in order to complete review of Model
C-10
MACDONALD, C E Transportation Branch 80/12/31 2pp 07476 109

DECREE 71-9141 MODEL 900 TYPE B, TECHNICAL OPERATIONS, INC

B101100075 Notifies of registration as user of Model 900
MACDONALD, C E Transportation Branch 80/12/10 1p 07445 006

DECREE 71-9145 MODEL NUPAC 50, NUCLEAR PACKAGING, INC

B101200316 Forwards info re Model NUPAC 50, in response to
ltr Applicable pages of SAR have been revised to incorporate
data lists summary of response
HANSEN, L J Nuclear Packaging, Inc 80/12/12 12pp

B101270133 Forwards corrected Page 1-13 of B01112 ltr re v
horizontal loads
HANSEN, L J Nuclear Packaging, Inc 80/12/10 1p 07

--B101270137 Corrected Page 1-13 re vertical & horizontal
HANSEN, L J Nuclear Packaging, Inc 80/12/10 1p

NONDOCKETED ITEMS

OCFR COMMISSION MEETING RECORDS

012290476 Transcript of 801211 meeting in Washington, DC re SECY-80-474C Pp 1-32
 * Commissioners 80/12/11 34pp 07335 066

0012290483 SECY-80-474C
 Suppls SECY-80-474 & forwards clarifying changes to 10CFR60 final rule & conforming amends
 DIRCKB, W J Office of the Executive Director for Operations 80/12/09 16pp 07335 104

012290489 Transcript of 801211 Affirmation Session 80-54 in Washington, DC re SECY-80-418, SECY-A-80-168 & SECY-80-482 Pp 1-11
 * Commissioners 80/12/11 13pp 07335 142

0012110612 Draft Commission paper re denial of Public Citizen Litigation Group petition for rulemaking re increase in required levels of financial protection for reactor operators Abstracts of comments & draft FR notice encl DENION, H R Office of Nuclear Reactor Regulation, Director 80/10/23 48pp 03771 145

0010230624 BECY-80-148
 Requests Commission approval of encl revised narrative explanation of Table S-3 specified in Commission order on final fuel cycle rule & draft FR notice
 DAVIS, J O Office of Nuclear Material Safety & Safeguards 80/09/29 100pp 06747 001

01040041 Commission determination releasing portions of transcript of NRC briefing by Dept of State/Arms Control & Disarmament Agency on 780713 in Washington, DC
 CHILK, B J Office of the Secretary of the Commission 80/11/24 2pp 07392 217

0101060044 Portions of transcript of NRC briefing by Dept of State/Arms Control & Disarmament Agency on 780713 in Washington, DC Pp 1-66
 * Commissioners 80/11/24 66pp 07392: 219

01040590 Transcript of 801210 briefing in Washington, DC re BECY-80-551 re storage of low level radioactive et power reactor sites Pp 1-43
 * Commissioners 80/12/10 44pp 07391: 139

0101060596 BECY-80-551
 Requests approval of plan for review of applications proposing addl low level radioactive storage capacity & preparation of programmatic EIS on long-term retrievable radioactive storage IE survey summary & proposed util ltr encl DIRCKB, W J Office of the Executive Director for Operations 80/11/18 21pp 07391: 184

01060699 Transcript of 801211 meeting to discuss SECY 80-491 re proposed rulemaking on reactor operator qualification & operator qualification & licensing requirements
 * Commissioners 80/12/11 49pp 07400: 189

0012080094 BECY-80-491
 Recommends Commission approval of proposed rulemaking "Qualification of Reactor Operators " Draft FR notice, background & discussion, recommendations of BECY-79-330E & draft Congressional ltr & public announcement encl MINIGUE, R D Office of Standards Development, Director 80/11/04 80pp 03768 094

01140111 Staff requirements memo re Affirmation Session 80-54 on 801211 concerning SECY-80-448 Proposed explanatory narrative & proposed rule should be revised as specified Marked-up pages encl CHILK, B J Office of the Secretary of the Commission 80/12/15 13pp 07460 327

--8101140120 Recommends endorsement of interim reliability evaluation program w/o condition of revising Crystal River rept prior to continuing L/program w/o encl recn for signature to accompany endorsement
 FURLEY, T E Division of Reactor Safety Research 80/12/04 2pp 07460 340

--8101140127 Advises of need for interim reliability evaluation program Revision of Crystal River work before undertaking Phase I studies recommended
 YANUVER, S H Division of Human Factors Safety 80/11/25 1p 07460 342

0101190792 Transcript of Commission 801222 meeting in Washington, DC re SECY 80-474 Pp 1-79 W/related info
 * Commissioners 80/12/22 100pp 07472 324

8101200552 Transcript of R & D Association 800425 briefing on containment concept to withstand core melt in Bethesda, MD Pp 1-79 Exempt session
 * Commissioners 80/04/29 81pp 07476 200

0101210246 Staff requirements memo re 801217 briefing on TVA activities in emergency offsite facilities Requests comments on acceptability of util proposal to centralize facilities & applicability of concept to other licensees
 CHILK, B J Office of the Secretary of the Commission 80/12/18 1p 07492 017

8101220239 Transcript of 800415 public Affirmation Session 80-22 in Bethesda, MD re statement of interim policy relative to accident considerations under NEPA Pp 1-5
 * Commissioners 80/04/15 5pp 07503 294

0101220239 Unofficial transcript of 791017 open Affirmation Session 79-32 in Washington, DC re order on Westinghouse export to the Philippines Pp 1-2
 * Commissioners 79/10/17 4pp 07503 289

8101220267 Unofficial transcript of 780906 public session in Washington, DC re BECY-78-308 provision for protection of individuals who provide info to ACR Pp 1-37
 * Commissioners 78/09/06 39pp 07504 044

8101220273 Unofficial transcript of 780906 public session in Washington, DC re presentation to Commissioner Kennedy & presentation of certificates of appointment to HR Danton & WJ Dirck. Pp 1-4
 * Commissioners 78/09/06 5pp 07504 083

8101220270 Unofficial transcript of 780906 public session in Washington, DC re BECY-78-350, role of use of deadly force in safeguarding strategic SNM Pp 1-17
 * Commissioners 78/09/06 30pp 07504 017

8101220504 Unofficial transcript of 790425 public meeting in Washington, DC re interim briefing by study group on const during review Pp 1-34
 * Commissioners 79/04/25 39pp 07501 197

8101220647 Transcript of Commission 810115 meeting in Washington, DC re action plan items due Jan 1901 Pp 1-47
 * Commissioners 81/01/15 49pp 07502 143

8101230658 Transcript of Commission 810115 meeting in Washington, DC re status of SRP Pp 1-28
 * Commissioners 81/01/15 41pp 07512 296

8101260328 Unofficial transcript of 790920 Affirmation Session 79-27 in Washington, DC re ACRS appointments Pp 1-3
 * Commissioners 79/09/20 4pp 07536 057

NONDOCKETED ITEMS

B101276275 Transcript from Affirmation Session 80-35 on B01222 in Washington, DC. Pp 1-7 Includes consideration of SECY-80-325 re open gov. FOIA appeal. SECY-A-146A re Tyrene decision. SECY-80-507 & SECY-80-501
* Commissioners 80/12/22 5pp 07546 117

B101280369 Responds to FOIA request for documents re Task Force on Interim Operation of Indian Point submitted to NRC after B00531 Forwards App A documents App B documents withheld (ref FOIA Exemption 5)
FELTON, J. H. Division of Rules and Records 01/01/21 3pp

--B101280388 Staff requirements memo re OCO626 briefing on recommendations of facilitator, Task Force Commission took no action during meeting Task Force report & other info re facility operation will be reviewed further
CHILKINS, J. Office of the Secretary of the Commission 80/06/30 1p.

B101290392 Unofficial transcript of B00107 Commission meeting in Washington, DC re SECY-80-474. Final rule. 10CFR60. "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures" Pp 1-85
* Commissioners 81/01/07 80pp 07570-001

--B101290399 Submits draft language changes to original text of SECY-80-474 for 10CFR60 Final rulemaking. Ofc of General Counsel concerns re NRC reference to DOE on common defense & security matters addressed.
BICKWITZ, L. Office of the General Counsel 81/01/06 2pp 07573 090

--B101290409 Discusses procedural aspects of final rule deserving further Commission consideration prior to approval of publication as part of 10CFR60. "Disposal of High Level Radwaste in Geologic Repositories" Licensing policy statement encl
HARRAHAN, E. J. Office of Policy Evaluations 81/01/06 5pp 07570 091

--B101290410 Confirms discussion w/w Dirks re dept concerns w/proposed regulations governing disposal of high level radwaste. Commission accommodation of dept views on problems outlined in B00303 ltr requested prior to issuing final rule.
* Energy, Dept of 81/01/06 2pp 07570 096

--B101290415 Staff requirements memo re discussion of SECY-80-474 Final rule. 10CFR60. "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures" Commissioner views on proposed memo to SECY-80-474 encl
CHILKINS, J. Office of the Secretary of the Commission 80-474 81/01/05 4pp 07570 098

--B101290420 Suggests memo to SECY-80-474 final rule. 10CFR60. "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures"
BRADFORD, F. A. Commissioners 80/12/18 4pp 07570 102

B101290479 Staff requirements memo re B10113 discussion of near-term CP requirements Commission deferred decision re hydrogen control question pending further discussion & requested further discussion re need for CP process revision
CHILKINS, J. Office of the Secretary of the Commission 80/11/13 1p 07568 355

B101290509 Staff requirements memo re B10115 briefing on SRP revisions due in Apr 1981 No requests or requirements forwarded
CHILKINS, J. Office of the Secretary of the Commission 80/11/16 1p 07568 353

B101290636 Transcript of Commissioners/ACRS B00808 joint meeting in Washington, DC re nuclear data. Int. Pp 411-446
* ACRS - Advisory Committee on Reactor Safeguards
* Commissioners 80/08/08 37pp 07573:120

B101300409 Unofficial transcript of Commission B10115 meeting in Washington, DC re Affirmation Session 81-2 to discuss waste confidence rulemaking Pp 1-6
* Commissioners 81/01/15 8pp 07583 219

--B101300416 Forwards proposed memorandum & order authorizing use of consultants to assist Commission working group w/waste confidence rulemaking proceeding. Memorandum & order should be adopted & issued
MILLER, H. E. Atomic Safety and Licensing Board Panel 80/12/19 6pp 07583 228

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

B1012020784 Responds to 790727 requests that ACRS address consistency actual component failure experience w/that projected in WASH-1400 & that ACRS determine probabilities of occurrence re Davis-Besse 770724 & Rancho Seco 780320 events
PLESEET, M. B. ACRS - Advisory Committee on Reactor Safeguards 80/02/20 8pp

--B1012020797 Forwards "Analysis of Feedwater Transient Sequences in NBS5." to aid in formulating response to M Udell 790729 ltr. Using WASH-1400 event trees & data directly gives meaningless results
ABBOTT, E. ACRS - Advisory Committee on Reactor Safeguards 80/02/07 1p

--B1012020804 "Analysis of Feedwater Transient Sequences in B&W NBS8." ABBOTT, E. E. ACRS - Advisory Committee on Reactor Safeguards 80/02/07 21pp.

B101090243 Apps to certified summary of 240th ACRS meeting on B00110-12
* ACRS - Advisory Committee on Reactor Safeguards 80/04/10. 400pp 07382 115

B101050637 Comments on repts re waste mgt & waste confidence rulemaking. Biting & design & const of geologic repositories is relatively simple. Demonstration of facts is important work to be performed
PHILBRICK, B. B. Philbrick, B. B. 80/11/06 1p. 07387-019

B101060038 Forwards continuation of B00810 comments on proposed Reg Guide RS 705-6 re lightning protection for nuclear power plants
JHANSCH, J. B. Affiliation Unknown 80/10/08 35pp. 07187 001

B101060223 Summary of ACRS Fluid Dynamics Subcommittee B01119-20 meeting in Los Angeles, CA re recent difficulties w/BWR hydraulic steam sys
* ACRS - Advisory Committee on Reactor Safeguards 80/11/07 9pp 07391 325

B101070347 Comments on waste confidence rulemaking as requested in Waste Mgt Subcommittee B01113-14 meeting. Continued min maint & surveillance will insure safety & practicality of spent fuel storage in reactor water basins
ALSAUGH, F. W. Affiliation Unknown 80/11/19. 3pp 07408 133

B101060317 Forwards review of NRC-sponsored research re nondestructive evaluation research programs. Reliability of insp. code insp & human factors engineering for nondestructive evaluation operators should receive more attention
BERGER, H. Commerce, Dept. of, National Bureau of Standards. 80/11/12 12pp 07417:354

B101090403 Transcript of ACRS Subcommittee on Regulatory Activities B10103 meeting in Washington, DC Pp 1-138.
* ACRS - Advisory Committee on Reactor Safeguards. 81/01/06 141pp 07426 006

B101090406 Transcript of ACRS Subcommittee on Safety Philosophy, Technology & Criteria B10106 meeting in Washington, DC re proposed requirements for plants w/near-term CPs Pp 1-178 Supporting documents encl
* ACRS - Advisory Committee on Reactor Safeguards 11/01/06 276pp 07427 001.

B101090327 Comments on passive containment sys Principle is to channel LOCA steam via closed sys to suppression pool in form of dryout tanks filled w/water, designed to act as passive heat sink.
JUDAH, S. Z. Franklin Institute/Franklin Research Center. 00/11/21. 2pp 07422 251

B101090336 Transcript of ACRS Subcommittee on Metal Components B1010 meeting in Washington, DC re inservice insp requirements. Pp 1-232 Supporting documents encl.
* ACRS - Advisory Committee on Reactor Safeguards 81/01/07. 373pp 07422:253

B101090324 Certified summary of ACRS Safety Philosophy, Technology & Criteria Subcommittee B00903 meeting in Washington, DC re NRC mgt philosophy in developing licensing requirements & cascading failures in nuclear plants.
* ACRS - Advisory Committee on Reactor Safeguards. 80/11/25. 18p 07424 322

8101090544 Certified summary of ACRS Waste Mgt 801003 meeting in Washington, DC re proposed rulemaking on technical criteria for regulating geological disposal of high level radioactive waste
* ACRS - Advisory Committee on Reactor Safeguards 80/11/20 17pp 07462 18B

8101090705 Certified summary of ACRS Subcommittee on Reactor Operations 801007 meeting in Washington, DC re NRC response to Congress on plan for systematic safety evaluation of all currently operating plants
* ACRS - Advisory Committee on Reactor Safeguards 80/10/23 19pp 07430 28B

8101090716 Certified summary of ACRS LER Subcommittee 801020 meeting in Washington, DC re OFC for Analysis & Evaluation of Operational Data evaluation of operating events & collection & sorting of data
* ACRS - Advisory Committee on Reactor Safeguards 80/12/02 4pp 07430 32B

8101090929 Comments on ACRS Subcommittee on ECCS 801021-23 tour Concern for pump reliability in various modes of two-phase flow in full scale reactors lacking ACOSTA, A Union 76 Minerals Exploration Co 80/10/31 2pp 07428 35A

8101120244 Transcript of ACRS 249th general meeting to discuss LOFT Special Review Group report on 810108 in Washington, DC Pp 1-20
* ACRS - Advisory Committee on Reactor Safeguards 81/01/08 22pp 07447 06Z

810113027R Transcript of ACRS 249th general meeting on 810109 in Washington, DC Pp 21-191
* ACRS - Advisory Committee on Reactor Safeguards 81/01/09 174pp 07309 001

8101160358 Summary of 249th ACRS meeting on 810108-10 re requirements for near-term CP applications Agrees w/NRC proposed approach on siting & current position on reliability engineering NRC should defer final action until 250th meeting
HAYLE, J C ACRS - Advisory Committee on Reactor Safeguards 81/01/12 3pp 07471 150

8101160463 Advises of actions taken during 249th ACRS meeting on 810108-10 ACRS concurred w/positions of Reg Guides SC 704-3 & RS 110-5
HAYLE, J C ACRS - Advisory Committee on Reactor Safeguards 81/01/13 1p 07469 75B

8101200010 Comments on proposed rules 10CFR50 & 51. "Proposed Rulemaking on Storage & Disposal of Nuclear Waste" Ability to validate models could become crucial to confidence question
BIEHLER, H Argonne National Laboratory 80/11/18 2pp 07487 015

8101200011 Comments on proposed rules 10CFR50 & 51. "Proposed Rulemaking on Storage & Disposal of Nuclear Waste" Current direction of deep geologic disposal at environmental favorability sites w/high integrity packages is safe
FESTER, R F. Affiliation Unknown 80/11/21 3pp 07487 009

8101220324 Transcript of ACRS Subcommittee on ECCS 810115 meeting in Albuquerque, NM Pp 295-490
* ACRS - Advisory Committee on Reactor Safeguards 81/01/15 197pp 07309 001

8101220327 Transcript of ACRS Subcommittee on ECCS 810114 meeting in Albuquerque, NM Pp 1-294
* ACRS - Advisory Committee on Reactor Safeguards 81/01/14 296pp 07304 229

8101260442 Transcript of ACRS Subcommittee on AC/DC Power Sys Reliability 810122 meeting in Washington, DC Pp 1-242.
* ACRS - Advisory Committee on Reactor Safeguards 81/01/22 244pp 07528 009

8101290413 Transcript of ACRS Subcommittee on Electric Power Sys 810123 meeting in Washington, DC re interaction of control & safety sys Pp 1-152
* ACRS - Advisory Committee on Reactor Safeguards 81/01/23 154pp 07370 10A

8101290656 Transcript of Commissioners/ACRS 800308 joint meeting in Washington, DC re nuclear data link Pp 411-446.
* ACRS - Advisory Committee on Reactor Safeguards & Commissioners 80/08/08 37pp 07373 120

8101300658 Notice of ACRS Subcommittee on Consideration of Class 9 Accidents 801121 meeting in Washington, DC to review NRC safety research budget for FY82 decision on severe accident phenomena Portions of meeting may be closed
HAYLE, J C Office of the Secretary of the Commission 80/10/31 3pp 07587 05Z

8101300760 Certified minutes of ACRS Advanced Reactor Subcommittee 800613 meeting in Washington, DC re NRC sponsored research on advanced reactors FR notice, attendee list & tentative schedule encl
* ACRS - Advisory Committee on Reactor Safeguards 80/09/11 07584 223

8101300767 Notice of ACRS Subcommittee on Procedures & Administration 801203 meeting in Washington, DC re proposed procedures & guidelines for ACRS review of safety-related stds & criteria
HAYLE, J C Office of the Secretary of the Commission 80/11/13 2pp 07304 249

8101300775 Notice of proposed ACRS subcommittees & working groups meetings scheduled from 801203-810204 re procedures & administration, ECCS, reactor radiological effects & site evaluation & combination of dynamic loads
HAYLE, J C Office of the Secretary of the Commission 80/11/20 6pp 07584 253

8101300778 Notice of ACRS Subcommittee on Transportation of Radioactive Materials 801029 meeting in Washington, DC re NRC transportation, certification process for package design
HAYLE, J C Office of the Secretary of the Commission 80/10/14 2pp 07594 259

8101300781 Notice of ACRS Subcommittee on Procedures & Administration 801105 meeting in Washington, DC re proposed changes in ACRS role to strengthen position in regulatory process
HAYLE, J C Office of the Secretary of the Commission 80/10/19 2pp 07584 261

8101300790 Certified summary of ACRS Fluid Dynamics Subcommittee 801113 meeting in Burlington, CA re Nucleonics Engineering Corp passive containment sys
* ACRS - Advisory Committee on Reactor Safeguards 80/12/05 07584 277

8101300794 Certified minutes of ACRS Subcommittee on Waste Mgt 801113-14 meeting in Washington, DC re proposed rulemaking on storage & disposal of nuclear waste FR notice & attendee list encl
* ACRS - Advisory Committee on Reactor Safeguards 80/12/11 07584 280

8101300798 Notice of indefinite postponement of ACRS Subcommittee on B&W Water Reactors 801030 meeting
HAYLE, J C Office of the Secretary of the Commission 80/10/24 1p 07584 294

8101300800 Notice of rescheduled 801112 meeting ACRS Subcommittee on B&W Water Reactors will meet on 801218
HAYLE, J C Office of the Secretary of the Commission 80/11/05 1p 07584 295

8101300804 Notice of rescheduled 801030-31 meeting ACRS Subcommittee on B&W Water Reactors will meet on 801112 in Washington, DC
HAYLE, J C Office of the Secretary of the Commission 80/10/28 1p 07584 296

8101300807 Certified minutes of ACRS Subcommittee on Transportation of Radioactive Materials 801029 meeting in Washington, DC re NRC request to conduct independent review of transportation certification process of NRC.
* ACRS - Advisory Committee on Reactor Safeguards 80/11/07 07584 297

8101300810 Certified summary of ACRS ECCS Subcommittee 801022-23 meeting in ID Falls, ID re review of NRC program to determine need for automatic reactor coolant pump trip following small break LOCA
* ACRS - Advisory Committee on Reactor Safeguards 80/12/05 07584 304

8101300823 Notice of ACRS Subcommittee on ECCS 801209-10 meeting in Los Gatos, CA re NRC reactor safety research program & plans for LOCA & transient research
HAYLE, J C Office of the Secretary of the Commission 80/11/20 2pp 07584 317

8101300618 Notice of ACRS Subcommittee on NRC Reactor Safety Research Program 801203 meeting in Washington, DC re new developments in program since issuance of NUREG-0699 Portions of meeting may be closed
MOYLE, J C Office of the Secretary of the Commission 80/11/14 3pp 07586 200

8101300554 Certified summary of ACRS Subcommittee on Regulatory Activities 801105 meeting in Washington, DC to review Revision 2 to Reg Guides 1.12 & proposed amend to 10CFR90 re domestic licensing of production & utilization facilities
* ACRS - Advisory Committee on Reactor Safeguards 80/12/04 11pp 07586 283

8101300856 Notice of ACRS Subcommittee on Reliability & Probabilistic Assessment 801203 meeting in Washington, DC to review items on use of risk assessment in licensing process Portions of meeting may be closed
CHILKS, J Office of the Secretary of the Commission 80/11/12 3pp 07586 294

COMMISSION NRC COMMISSIONERS

8012110336 Responds to 801003 ltr re NRC review of emergency procedures at operating reactors as part of consideration of ATRS problem IE Bulletin 80-17 required BWR licensees to review emergency procedures re operator shutdown actions
AHEARNE, J F Commissioners 18B-80-17 80/11/24 2pp 03772 020

8012110347 Responds to 800511 request for NRC to consider control sys failures in nuclear power plants Forwards summary of significant corrective measures required as result of control sys malfunction or failure analyses
AHEARNE, J F Commissioners 80/11/17 5pp 03772 023

--8012110652 Requests clarification of NRC 800514 response to 800207 ltr re control sys failures Nature of analysis leading to NRC consensus re safely sys mitigating failures unclear
UDALL, M K House of Rep, Interior & Insular Affairs 80/06/17 2pp 03772 027

8101050428 Forwards list of pending legislation re NRC & programs
FITZGERALD, J A Office of the General Counsel 80/12/02 1p 07385 271

--8101050631 Forwards three active NRC-related legislative items FY81
Authorization Bill, H.R. 8378 costs mgt bill & SECY-80-366.
Fourth item re providing financial assistance to NRC resident inspectors is under development
STOBER, C Office of the General Counsel 80/12/02 70pp 07386 292

--8101050634 SECY-80-366
Informs Commission of NRC legislative program for 97th Congress
STICKHILL, L Office of the General Counsel 80/08/06 11pp 07386 352

8101050636 Forwards memo re status of implementation of Reorganization Plan
FITZGERALD, J A Office of the General Counsel 80/12/02 1p 07387 011

8101060046 Forwards IE notes & plant status rept for 801208
DIRCKS, W J Office of the Executive Director for Operations 80/12/09 3pp 07349 129

8101060052 Discusses possible emergency measures in event of major cutoff of Persian Gulf as result of continued hostilities in Middle East Safety implications should be reviewed in advance to determine safety or emergency production benefit.
GHINISKY, V Commissioners 80/12/05 2pp 07399 127

8101060061 Forwards IE notes & plant status rept for 801209
DIRCKS, W J Office of the Executive Director for Operations 80/12/10 3pp 07187 001

8101060266 Responds to 801010 ltr requesting withdrawal of Pilot Knob mine from list of potential facilities for consideration by Lawrence Berkeley Lab until concerns are resolved
AHEARNE, J F Commissioners 80/11/24 1p 07399 075

8101060432 Responds to 801004, 20 & 28 ltrs re concerns involving transportation & disposal of low level radwastes from United Nuclear Corp NRC investigating ban on United Nuclear shipments in State of NY
AHEARNE, J F Commissioners 80/12/03 5pp 07399 003

--8101060436 Requests NRC inquiry into circumstance surrounding ban against United Nuclear Corp shipping of radwastes from Wood River Junction, RI to Beatty, NV
GARRAHY, J J Rhode Island State of 80/10/29 2pp 07399 001

--8101060440 Expresses gratitude for prompt NRC response to situation in NY re refusal of United Nuclear Corp request to dispose of radwastes NRC should assure that waste is properly packaged
GARRAHY, J J Rhode Island State of 80/10/20 9pp 07399 002

--8101060446 Requests full & public investigation of United Nuclear present waste packaging & of programs to determine if NRC enforcement sanctions are needed
GARRAHY, J J Rhode Island State of 80/10/28 2pp 07399 003

8101060835 Responds to 801110 request for biweekly rept on transit activities at NRC Forwards list of documents provided to NRC transition team, list of personnel associated w/ team & Commission instructions re info to be provided to team
AHEARNE, J F Commissioners 80/12/04 10pp 07400 112

8101060952 Requests that ACRS review NRC rationale re control sys info re ATRS in response to Representative Udall request
AHEARNE, J F Commissioners 80/12/14 1p 07401 110

--8101060953 Requests ACRS review NRC rationale re control sys info re ATRS in response to Representative Udall request
UDALL, M K House of Rep, Interior & Insular Affairs 80/12/14 1p 07401 111

--8101060954 Requests ACRS review of NRC 801023 & 1124 responses to inquiries re ATRS issue
UDALL, M K House of Rep, Interior & Insular Affairs 80/12/14 1p 07401 112

8101070221 Submits daily notes for 801217 Plant status for five 10 regions encl
DIRCKS, W J Office of the Executive Director for Operations 80/12/18 4pp 07197 001

8101070487 Submits daily staff notes for 801216
DIRCKS, W J Office of the Executive Director for Operations 80/12/17 3pp 07309 001

8101070488 Submits daily staff notes for 801215
DIRCKS, W J Office of the Executive Director for Operations 80/12/16 3pp 07404 001

8101070541 Forwards transcript of State Liaison Officers' 801207 meeting in Washington, DC Comments requested by 801233
CORNEI, L E K Office of the Executive Director for Operations 80/12/17 1p 07407 071

--8101070543 Transcript of State Liaison Officers' 801210 meeting Washington, DC Pp 1-121
* Commissioners 80/12/10 129pp 07407 072

--8101070550 Transcript of State Liaison Officers' 801209 meeting Washington, DC Pp 1-239
* Commissioners 80/12/09 260pp 07407 148

8101080072 Advises that no problem expected w/supplying transition team Off of Executive Director staff notes & preliminary notification of events or w/placing both classes of documents in PDR.
FITZGERALD, J A Office of the General Counsel 80/12/04 1p 07419 260

8101080241 Forwards V Riello comments on recommendations in Rep 196-1452 of House Committee on Govt Operations for improvement of NRC IE program Encl lists each recommendation & related comment, Commission agrees in general w/comments
AHEARNE, J F Commissioners 80/12/09 10pp 07422 026

8101080231 Responds to 801007 ltr re NRC progress in review of CF of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance w/o encl documentation
AHEARNE, J F Commissioners 80/12/22 4pp 07422 011

--8101080336 Responds to 801009 ltr re NRC progress in review of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance w/o encl documentation
AHEARNE, J F Commissioners 80/12/22 4pp 07422 015

--B10100360 Responds to B01009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1990 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance w/o encl documentation
AHEARNE, J F Commissioners 80/12/22 4pp 07422 049

--B10100392 Expresses concern re NRC failure to resume caseport reviews of CP applications Expedient processing of applications should be resumed in light of successful identification of lessons learned from TMI-2
BRODWAY, C, LGEFFLER, T, GRAMM, P House of Rep 80/10/09 2pp 07422 024

B10100390 Submits status repts re pending appeal court case challenging NRC export license issuance for nuclear reactor to be constructed in Philippines & implementation of Executive Order 12114
STOIBER, C Office of the General Counsel 80/12/15 13pp 07419 276

B10100390 Forwards list & explanation of pending NRC adjudicatory matters of special public significance
FITZGERALD, J A Office of the General Counsel 80/12/10 4pp 07417 331

B10100246 Informs of B01020 meeting w/DGE to discuss technical aspects of initial DOE plans to implement high level waste solidification project Certain areas require resolution between DOE & NRC Slide presentation encl.
DAVIS, J O Office of Nuclear Material Safety & Safeguards 80/11/13 2pp 07429 321

B10100759 Submits daily staff notes for B01203
DIRCKS, W J Office of the Executive Director for Operations 80/12/08 3pp 07412 043

B10100764 Submits daily staff notes for B01212
DIRCKS, W J Office of the Executive Director for Operations 80/12/15 3pp 07430 070

B101007840 Forwards summary of C Stoiber B01216 memo re status of Philippine lawsuit & Executive Order 12114
FITZGERALD, J A Office of the General Counsel 80/12/18 3pp 07427 356

B10100850 Forwards 790130 list of documents re nuclear siting & licensing reform in response to R Stratford request
FITZGERALD, J A Office of the General Counsel 80/12/19 26pp 07429 290

B101100003 Forwards Kyburz manuscript & translation w/o encl
HENBRIE, J H Commissioners 80/12/15 1p 07445 213

B101100004 Responds to request for review of H R 7865, "Nuclear Safety Research, Development & Demonstration Act of 1980 " NRC takes no position on encl bill.
AHEARNE, J F Commissioners. 80/12/17 6pp 07445 207

B101100007 Responds to B01031 legislative referral memorandum re judicial review of agency actions NRC opposes three versions of Dumpers amendment does not adequately deal w/broad jurisdiction of agency in dealing w/public health & safety
BECKNITZ, L Office of the General Counsel 80/12/10 3pp 07445 191

--B101100010 Legislative referral memorandum requesting judicial review of agency actions Requests review of encl three versions of Dumpers amend.
CARLSTROM, R C Office of Management & Budget 80/10/31 12pp 07445 194

B101100079 Forwards DC Circuit Court decision in S Sholly vs NRC w/o decision
FITZGERALD, J A Office of the General Counsel 80/12/03 1p 07444 319

B101100149 BECY-80-394
Weekly info rept for wk ending B01219.
RENN, L A Office of the Executive Director for Operations 80/12/29 31pp 07443 061

B101100169 Responds to request for info re monitoring of adjudicatory proceedings Each month ASLB submits notice of occurrences, providing list of events in proceedings. Ofc of General Counsel summarizes developments
FITZGERALD, J A Office of the General Counsel 80/12/09 1p 07445 019

B101100239 Advises that final OAD rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly incorporates NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 045

--B101100207 Advises that final OAD rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 046

--B101100212 Advises that final OAD rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 017

--B101100219 Advises that final OAD rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation.
AHEARNE, J F Commissioners 80/12/10 1p 07445 040

--B101100226 Advises that final OAD rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 049

--B101100250 Advises that final OAD rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 050

--B101100298 Advises that final OAD rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners. 80/12/10 1p 07445 051

--B101100345 Advises that final OAD rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners. 80/12/10 1p 07445 052

B101120164 Delegates appropriate authority to Ofc of Nuclear Reg. Regulation Transmittal notice, organization & functions section from NRC manual & FR notice re domestic licensing proceedings encl
MILERS, W A Commissioners 79/01/20 32pp 07436 324

B101130033 Forwards draft "Safety Goal Issue in Historical Perspective," per request.
STOIBER, C R Office of the General Counsel 80/12/22 1p 07448 300

--B101130039 "Safety Goal Issue in Historical Perspective," draft
MAZURAN, G V, WALKER, J S Office of the Secretary of the Commission 80/12/31 29pp 07448 301

B101130620 Responds to OAD B00818 rept, "Analysis of Price-Anders Act," recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents Congress should decide whether to increase liability limit
AHEARNE, J F Commissioners 80/12/31 3pp 07453 184

--B101130622 Responds to OAD B00818 rept, "Analysis of Price-Anders Act," recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents Congress should decide whether to increase liability limit
AHEARNE, J F Commissioners 80/12/31 3pp 07453 187

--B101130632 Responds to OAD B00818 rept, "Analysis of Price-Anders Act," recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents Congress should decide whether to increase liability limit
AHEARNE, J F Commissioners. 80/12/31 3pp 07453 190

--B101130634 Responds to OAD B00818 rept, "Analysis of Price-Anders Act," recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents Congress should decide whether to increase liability limit
AHEARNE, J F Commissioners 80/12/31 3pp 07453 193

--B101130637 Responds to GAO B00B10 rept. "Analysis of Price-Anderson Act." recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents. Congress should decide whether to increase liability limit. AHEARNE, J F Commissioners 80/12/31 3pp 07453 196

--B101130640 Responds to GAO B00B10 rept. "Analysis of Price-Anderson Act." recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents. Congress should decide whether to increase liability limit. AHEARNE, J F Commissioners 80/12/31 3pp 07453 199

--B101130643 Responds to GAO B00B10 rept. "Analysis of Price-Anderson Act." recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents. Congress should decide whether to increase liability limit. AHEARNE, J F Commissioners 80/12/31 3pp 07453 202

--B101130646 Responds to GAO B00B10 rept. "Analysis of Price-Anderson Act." recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents. Congress should decide whether to increase liability limit. AHEARNE, J F Commissioners 80/12/31 3pp 07453 205

B101130715 Forwards BJ Chalk B01113 memo to Commissioners on proposed revisions to internal procedures & Commissioner Action paper on review of delegations of authority in response to request. FITZGERALD, J A Office of the General Counsel 80/12/04 1p 07452 161

--B101130727 Responds to B00929 memo requesting review of internal procedures to identify areas where rods would be appropriate for implementation of reorganization plan. Revisions re format of SECY papers & correspondence are recommended. CHILK, B J Office of the Secretary of the Commission 80/11/13 10pp 07452 162

B101140041 Forwards daily notes for B01218 Plant status for five IE regions encl. DIRCKS, W J Office of the Executive Director for Operations 80/12/19 3pp 07308 C01

B101140666 Responds to B00917 request for NRC views re HR B119 bill requiring Secretary of Commerce to undertake study on effects of past ocean dumping of radwaste. Section re NRC assistance should also include CCE. AHEARNE, J F Commissioners 80/12/12 1p 07462 016

--B101140677 Requests comments on encl B111, HR B119, requiring Secretary of Commerce to undertake study to determine effects of past ocean dumping of radwaste. ASHLEY, T L House of Rep. Merchant Marine & Fisheries 80/09/17 4pp 07462:017

B101140716 Forwards NUREG-0090, Vol 3, Number 2, "Rept to Congress on AOs, Apr-June 1980 " Two AOs at operating nuclear power plants involved loss of decay heat removal & failure of control rods to fully insert during scram W/o encl. AHEARNE, J F Commissioners 80/12/05 1p 07458 313.

--B101140725 Forwards NUREG-0090, Vol 3, Number 2, "Rept to Congress on AOs, Apr-June 1980 " Two AOs at operating nuclear power plants involved loss of decay heat removal & failure of control rods to fully insert during scram. AHEARNE, J F Commissioners 80/12/05 1p 07458 314

--B101140736 NUREG-0090 Vol 3, N02 REPORT TO CONGRESS ON ABNORMAL OCCURRENCES April-June 1980 * Office of Management and Program Analysis 80/11/30. 38pp Available at NTIS 07458 313

B101140774 Forwards proposed rule 10CFR2.50.70 & 73. "Protection of Unclassified Safeguards Info " Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 030.

--B101140779 Forwards proposed rule 10CFR2.50.70 & 73. "Protection of Unclassified Safeguards Info " Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 031

--B101140706 Forwards proposed rule 10CFR2.50.70 & 73. "Protection of Unclassified Safeguards Info " Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 032

--B101140790 Forwards proposed rule 10CFR2.50.70 & 73. "Protection of Unclassified Safeguards Info " Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 033

--B101140799 Forwards proposed rule 10CFR2.50.70 & 73. "Protection of Unclassified Safeguards Info " Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 034

--B101140802 Forwards proposed rule 10CFR2.50.70 & 73. "Protection of Unclassified Safeguards Info " Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 035

--B101140011 "Protection of Unclassified Safeguards Info." 10CFR2.73 proposed rule Regulations identify types of safeguards info to be protected, establish min protection requirements & set conditions for access to safeguards info. CHILK, B J Office of the Secretary of the Commission 80/12/27pp 07457 036

B101140052 Forwards addl info re licenses permitting introduction radioactive matl in sea Review revealed no addl info re sea disposal of radwaste W/o encl. AHEARNE, J F Commissioners 80/12/09 1p 07457 319

--B101140855 Forwards addl info re licenses permitting introduction radioactive matl in sea Review revealed no addl info re sea disposal of radwaste W/o encl. AHEARNE, J F Commissioners 80/12/09 1p 07457 320

--B101140859 Forwards addl info re licenses permitting introduction radioactive matl in sea Review revealed no addl info re sea disposal of radwaste W/o encl. AHEARNE, J F Commissioners 80/12/09 1p 07457 321

--B101140862 Forwards addl info re licenses permitting introduction radioactive matl in sea Review revealed no addl info re sea disposal of radwaste W/o encl. AHEARNE, J F Commissioners 80/12/09 1p 07457 322

--B101140871 Forwards addl info re licenses permitting introduction radioactive matl in sea Review revealed no addl info re sea disposal of radwaste. AHEARNE, J F Commissioners 80/12/09 2pp. 07457 323.

B101140376 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-80-319 outlining new qualification program W/o encl. AHEARNE, J F Commissioners 80/12/15 2pp 07457 331

--B101140881 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-80-319 outlining new qualification program W/o encl. AHEARNE, J F Commissioners 80/12/15 2pp 07457 333

--B101140894 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-80-319 outlining new qualification program W/o encl. AHEARNE, J F Commissioners 80/12/15 2pp 07457 335.

--B101140895 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-80-319 outlining new qualification program W/o encl. AHEARNE, J F Commissioners 80/12/15 2pp. 07457 337

--B101140899 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-80-319 outlining new qualification program W/o encl. AHEARNE, J F Commissioners 80/12/15 2pp 07457 339

--B101140904 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-80-319 outlining new qualification program. AHEARNE, J F Commissioners 80/12/15 2pp. 07457 361

B101140963 Ack receipt of B00822 ltr & manuscript which have been forwarded to nuclear fission staff at DOE. HENDRIE, J H Commissioners 80/12/15 1p. 07461 096.

Observations & Recommendations Re Problem of Steam Generator
Overfill & Combined Primary & Secondary Side Blowdown -
DIRCKS, H J Office of the Executive Director for Operations
80/12/23 1p 07463 026

--8101190366 Ofc of Analysis & Evaluation of Operational Data
Observations & Recommendations Re Problem of Steam Generator
Overfill & Combined Primary & Secondary Side Blowdown -
IMRO, E V, LANNINO, W D Director's Office 80/12/17 28pp
07463 027

8101150425 Forwards proposed revisions to Internal Commission
procedures, in response to Commission 800929 request
Proposed revisions handling of correspondence & format of
SECY papers
CHILK, S J Office of the Secretary of the Commission 80/11/13
10pp 07462 231

8101150055 Forwards requested excerpts from hearings re Nuclear Siting
& Licensing Act of 1970
FITZGERALD, J A Office of the General Counsel 80/12/18 6pp
07309 001

8101150862 Submits daily notes for 801222 Plant status for five IE
regions encl
DIRCKS, H J Office of the Executive Director for Operations
80/12/23 3pp 07309 001

8101150914 Weekly info rept for wk ending 810102
REHM, T A Office of the Executive Director for Operations
81/01/08 29pp 07465 007

8101160124 Forwards requested documents re oil emergencies
HANRAHAN, E J Office of Policy Evaluations 80/12/30 1p
07467 307

--8101160135 Forwards draft response to DOE 801103 ltr requesting contact
for contingency planning in event of oil shortfall emergency
& info re nuclear strategies EJ Hanrahan named as NRC
contact
HANRAHAN, E J Office of Policy Evaluations 80/12/11 13pp
07467 300

--8101160142 Requests NRC contact for contingency planning in event of
oil shortfall emergency & info re nuclear strategies
HCUSE, B R Energy, Dept of Economic Regulatory Administration
80/11/03 3pp 07467 321

--8101160147 Forwards rept of meeting at DOE re development of
initiatives to respond to potential oil shortages
HANRAHAN, E J Office of Policy Evaluations 79/11/19 1p
07467 324

--8101160153 Summary of 001214 meeting in Washington, DC re development of
federal emergency planning for responding to oil shortage
RATHBURN, D Office of Policy Evaluations 79/11/16 15pp
07467 325

--8101160159 Forwards answers in response to 791114 memo re initiatives
to respond to potential oil shortages Areas addressed plant
status & possible startup dates & methods for restricting
new reactors to 50% power
HANRAHAN, E J Office of Policy Evaluations 79/12/19 10pp
07467 340

--8101160164 Forwards draft NRC paper re domestic initiatives to respond
to potential oil shortages
RATHBURN, D Office of Policy Evaluations 79/11/13 23pp
07467 350

--8101160172 Responds to 801208 memo requesting status rept on actions to
be taken during natl energy emergency. In 1979, NRC prepared
analysis of options to increase nuclear productivity in
response to energy emergency
HANRAHAN, E J Office of Policy Evaluations 80/12/18 3pp
07467 011

8101190175 Forwards 810102 memo re NRC actions in event of natl energy
emergency
FITZGERALD, J A Office of the General Counsel 81/01/06 1p
07475 211

--8101190182 Responds to 001205 memo requesting assessment of legislation
required for natl energy emergency. Currently, no statutory
authority exists for licensing temporary operation prior
to completion of hearings
BICKHILL, L B Office of the General Counsel 81/01/02 2pp
07475 212

BICKHILL, L Office of the General Counsel 79/03/14 21p
02450 078

8101270079 Responds to 801129 ltr K McCarthy has been accepted for
course in health physics & radiation protection & W Kern has
been directed to arrange meeting re CT interest in becoming
Agreement State
AHEARNE, J F Commissioners 80/12/11 1p 07590 106

--8101270882 Discusses K McCarthy application to attend course in
physics & radiation protection & requests that favorable
consideration be given
GRASSB, E Connecticut, State of 80/11/25 1p 07590 107

8101280378 Responds to 800912 ltr re util plans to scale down clear
activities due to PA Public Util Commission 800918 order
denying request for rate relief & NRC action schedule Encl
Table 1 lists NRC requirements for safe shutdown
AHEARNE, J F Commissioners 01/01/12 6pp

8101300704 Forwards second monthly Ofc of Nuclear Reactor Regulation
status rept, for 001115-1215, per House Rept 96-1093 Rept
discusses actions taken during month for operating reactors
& licensing reviews of new facilities
AHEARNE, J F Commissioners 80/12/31 14pp 07584 263

CONTRACT NRC CONTRACTS AND MODIFICATIONS

8101090183 Notification of contract execution, Mod 0 to "PDR
Micrographic Storage & Retrieval Sys " Contractor ACCESS
Corp
MEDROW, L A Administrative Contracts Branch NRC-17-79-449
80/12/22 1p 07382 109

--8101050189 Mod 0, clarifying mandatory specs re translator program
"PDR Micrographic Storage & Retrieval Sys "
BAKER, N O Access Corp MATTIA, M J Administrative Contracts
Branch NRC-17-79-449 80/12/22 2pp 07392 110

8101050200 Notification of contract execution, Mod 1 to "Cylogenetic
Studies in Grand Junction, CO " Contractor CO Dept of Health
GUSTAVE, R P Research Contracts Branch FIN 8-7102-0
NRC-01-BU-022 80/12/02 1p 07383 209

--8101050208 Mod 1, adding effective date 800930 in Block 2 of Std F
26, to "Cylogenetic Studies in Grand Junction, CO "
TRAYLOR, F A Colorado, State of MORTON, K V Research Contra
Branch FIN 8-7102-0 NRC-01-BU-022 80/12/02 1p 07303 2

8101060231 Notification of contract execution, Mod 5 to "Licensee
Performance Evaluation " Contractor Teknekon, Inc.
BAIDEN, L Research Contracts Branch FIN 8-122B NRC-05-78-30
80/12/19 1p 07391 330

--8101060237 Mod 5, changing completion schedule & rept requirements
extending period of performance through 801128, to "Licensee
Performance Evaluation "
CHEN, B Teknekon, Inc MORTON, K V Research Contracts Bran
FIN 8-122B NRC-05-78-302 80/12/19 2pp 07391 339

8101060249 Notification of contract execution, Mod 2 to "NRC Monitor
Holsdampfreaktor Seismic Tests " Contractor ANCO
Engineers, Inc
WOLFE, R B Research Contracts Branch FIN 8-675B NRC-04-79-20
80/12/18 1p 07391 357

--8101060258 Mod 2, refining statement of work, test & yearly final r
quirements, to "NRC Monitor Holsdampfreaktor Seismic
Tests "
EHLICH, C B Anco Testing Laboratory, Inc MORTON, K V Research
Contracts Branch FIN 8-675B NRC-04-79-203 00/12/18 8pp
07391 358

8101060275 Notification of contract execution, Mod 4 to "Implementat
of Mods to NRC Contract Info Sys " Contractor Small Business
Administration Subcontractor Social Research Applications
Corp
MEDROW, L A Administrative Contracts Branch NRC-10-79-381
80/11/13 1p 07392 014

--8101060200 Mod 4, decreasing number of progress repts & total amount
of contract, to "Implementation of Mods to NRC Contract Info
Sys "
FURSTALL, J E Small Business Administration MATTIA, M J
Administrative Contracts Branch WOLFE, R B Social Research
Applications Corp NRC-10-79-381 80/11/13 2pp 07392 015

8101060312 Notification of contract execution, Mod 5 to 'Sys Maint Programming' Contractor Small Business Administration
Subcontractor Rehab Group, Inc
MATTIA, M J Administrative Contracts Branch NRC-10-79-375
80/10/15 1p 07392 049

--8101060321 Mod 5, defining Mod 4, incorporating two add later categories
3 rates & increasing funds to 'Sys Maint Programming'
JUILIO, R S Rehab Group, Inc COLLINS, F M Small Business
Administration MATTIA, M J Administrative Contracts Branch
NRC-10-79-375 80/10/15 5pp 07392 050

8101060328 Forwarded executed contract mod forms
LEBO, C D Administrative Contracts Branch NRC-10-60-702
80/12/31 1p 07392 059

--8101060341 Notification of contract execution, Mod 2 to 'Word Processing Svcs' Contractor Automated Correspondence Sys, Inc
CELEMAN, R Administrative Contracts Branch NRC-10-80-702
80/12/31 1p 07392 060

--8101060347 Mod 2, changing contract requirements, to 'Word Processing Svcs'
SPALSMAN, J A Automated Correspondence Systems, Inc LEBO, C D
Administrative Contracts Branch NRC-10-80-702 80/12/31 1p
07392 061

8101060743 Notification of contract execution Human Factors Program
Plan, awarded to Human Factors Soc, Inc
MORTON, K V Research Contracts Branch FIN B-7239 NRC-04-81-186
80/12/14 1p 07400 302

--8101060750 Contract "Human Factors Program Plan," awarded to Human
Factors Soc, Inc
MORTON, K V Human Factors Society, Inc MORTON, K V Research
Contracts Branch FIN B-7239 NRC-04-81-186 80/12/14 4pp
07400 303

8101060783 Notification of contract execution "Political Economy of
Alternative Safety Goals," awarded to L Lave
LAVE, L B Administrative Contracts Branch NRC-19-81-492 80/12/18
1p 07400 309

--8101060790 Contract "Political Economy of Alternative Safety Goals,"
awarded to L Lave
LAVE, L B LAVE, L PERLMAN, J Administrative Contracts Branch
NRC-19-81-492 80/12/18 5pp 07400 310

8101060799 Notification of contract execution, Mod 4 to "Analysis of
Matl Accounting Practices at Specific Nuclear Facility"
Contractor Science Applications, Inc
MILES, E B Administrative Contracts Branch FIN B-6393-B
NRC-02-78-049 80/12/01 1p 07401 101

--8101060942 Mod 4, deobligating funds to "Analysis of Matl Accounting
Practices at Specific Nuclear Facility"
MATH, S O Science Applications, Inc PERLMAN, J Administrative
Contracts Branch FIN B-6393-B NRC-02-78-049 80/12/01 1p
07401 102

8101070321 Notification of contract execution 'Technical Assistance for
EIS on LOGFR61,' awarded to Dames & Moore
HARRISON, C SMITH, P Technical Assistance Contracts Branch FIN
B-7318-1 NRC-02-81-049 80/12/01 2pp 07408 122

8101090392 Notification of contract execution, Mod 7 to 'PDR
Micrographic Storage & Retrieval Sys' Contractor ACCESS
Corp
MEDROW, L A Administrative Contracts Branch NRC-17-79-449
80/12/10 1p 07442 211

--8101090394 Mod 7, extending maint coverage & increasing total amount of
contract, to 'PDR Micrographic Storage & Retrieval Sys.'
* ACCESS Corp MATTIA, M J Administrative Contracts Branch
NRC-17-79-449 80/12/10 7pp 07442 212

8101090395 Notification of contract execution, Mod 3 to "Guidelines on
Use of Geochronological Methods in Nuclear Power Plant
Siting" Contractor OH Curtis
GUSTAVE, R P Research Contracts Branch FIN B-16057
NRC-01-77-070 80/12/16 1p 07442 021

--8101090706 Mod 3, re-establishing final delivery date of 810115, to
'Guidelines on Use of Geochronological Methods in
Nuclear Power Plant Siting'
* Curtis, O H MORTON, K V Research Contracts Branch FIN
B-10357 NRC-01-77-070 80/12/16 1p 07442 022

8101090393 Notification of contract execution, Mod 3 to
Ingers Contractor Data Composition Svcs, Inc
MAGAN, T F Administrative Contracts Branch NRC-10-
80/12/18 1p 03893 231

--8101090398 Mod 3, changing specs re issuances required
cumulative index required for 1975 through 1979, to
Issuance & Indexes
WHITE, R J Data Composition Services, Inc MATTIA,
Administrative Contracts Branch NRC-10-80-661
03893 232

8101090998 Notification of contract execution 'Holding
And Conflict,' awarded to Graduate School, USIA
CELEMAN, R Administrative Contracts Branch NRC-10-
80/12/17 1p 03893 346

--8101091000 Contract "Holding Public Meetings And C
to Graduate School, USIA
SHEA, A C Agriculture, Dept of LEBO, C D Admini
Contracts Branch NRC-10-81-389 80/12/17 6pp

8101100302 Notification of contract execution, Mod 3 to
Assistance for Fire Protection Program Review & Eval
Contractor Gage-Babcock & Associates, Inc
SHEA, D Technical Assistance Contracts Branch FIN
NRC-03-79-127 80/11/20 1p 07443 311

--8101100307 Mod 3, allotting add funds to "Technical
Protection Program Review & Evaluation"
CEHN, B M Gage-Babcock Associates, Inc DOUHERTY
Assistance Contracts Branch FIN B-6588 NRC-03-
80/11/20 1p 07443 312

8101100711 Notification of contract execution, Mod 10 to
Seismology Support Contractor Natl Academy of Sciences
WILLETT, S Research Contracts Branch FIN A-4053
80/12/18 1p 07443 326

--8101100316 Mod 10, extending period of performance to
allocating add funds, to "Committee on Seismology &
SITTON, P L National Academy of Sciences MORTON,
Contracts Branch FIN A-4053 NRC-04-76-104 80/
07443 327

8101100321 Notification of contract execution, Mod 3 to
Gas-Liquid Flow Patterns Contractor Univ of Houston
HAGLEY, H Research Contracts Branch FIN B-6273 N
80/12/15 1p 07443 328

--8101100325 Mod 3, extending period of performance to
of Gas-Liquid Flow Patterns
NORRIS, J J Houston, Univ of MORTON, K V Resea
Branch FIN B-6273 NRC-04-78-213 80/12/15 2p

8101100392 Notification of contract execution, Mod 3 to
Nuclear Facilities in Harst & Other Areas Susceptible
Ground Collapse Contractor Dept of Army
GUSTAVE, R P Research Contracts Branch B-10869
80/12/15 1p 03886 330

--8101100399 Mod 3, extending period of performance to
Increase to "Biting of Nuclear Facilities in Harst
Areas Susceptible to Group Collapse"
GIRARDOT, D C Army, Dept of MORTON, K V Research
Branch FIN B-10869 NRC-01-79-006 80/12/15

8101100947 Notification of contract execution, Mod 15 to
Operate Document Control Sys. Contractor TERA Advan
Svcs Corp
SCHLOSSER, L A Contract Policy Branch NRC-10-78-5
1p 07454 148

--8101100955 Mod 15, increasing funds to "Implement & O
Control Sys"
* TERA Corp LEBO, C D Administrative Contracts
NRC-10-78-580 80/12/31 2pp 07454 149

8101100267 Notification of contract execution, Mod 5 to
Svc Contractor Beltway Limousine Svc, Inc
MARTIN, L C Technical Assistance Contracts Branch
80/12/31 1p 07458 142

--8101100375 Mod 5, deobligating funds & completing clo
Bus Svc.
ROBERTSON, J Q Beltway Limousine Service, Inc L
Administrative Contracts Branch NRC-10-70-415
07458 143

8101140792 Notification of contract execution, Mod 6 to 'FLECHT SEASET " Contractor Westinghouse & EPRI
WILLET, S Research Contracts Branch FIN 0-6204 NRC-04-77-127
80/12/29 1p 07461 113

--8101140776 Mod 6, adding incremental funds, to "FLECHT SEASET " FARRAR, A B Electric Power Research Institute TAYLOR, J J Westinghouse Electric Corp MORTON, K V Research Contracts Branch FIN 0-6204 NRC-04-77-127 80/12/29 2pp 07461 114

8101140805 Notification of contract execution, Mod 6 to 'Consulting on Foreign Countries' Code Development Programs " Contractor PB Anderson
WILLET, S Research Contracts Branch FIN 0-6390 NRC-04-79-177
80/12/18 1p 07461 097

--8101140813 Mod 6, correcting scope of work, to "Consulting on Foreign Countries' Code Development Programs " ANDERSEN, P B P B Anderson, MORTON, K V Research Contracts Branch FIN 0-6390 NRC-04-79-177 80/12/18 2pp 07461 098

8101140835 Notification of contract execution, Mod 1 to 'Behavioral Observation Program to Assure Continued Reliability of Employees' Contractor Personnel Decisions, Inc
GUSTAVE, R P Research Contracts Branch FIN 0-10829 NRC-01-79-003 80/12/12 1p 07461 038

--8101140843 Mod 1, extending period of performance to 801208 w/no increase in cost, to "Behavioral Observation Program to Assure Continued Reliability of Employees " MEYER, P Personnel Decisions, Inc MORTON, K V Research Contracts Branch FIN 0-10829 NRC-01-79-003 80/12/12 1p 07461 031

8101150039 Notification of contract execution, Mod 1 to 'Study of US Nuclear Health & Safety Info Dissemination to Foreign Countries " Contractor Franklin Inst
MEYER, H L Administrative Contracts Branch NRC-08-80-338 80/12/24 1p 07462 179

--8101150045 Mod 1, extending period of performance & time of delivery to "Study of US Nuclear Health & Safety Info Dissemination to Foreign Countries " LOVELAKE, R F Franklin Institute/Franklin Research Center LEBB, C O Administrative Contracts Branch NRC-08-80-338 80/12/24 2pp 07462 180

8101150120 Notification of contract execution, Mod 12 to 'Consulting Svcs (A-E) Re Evaluation of Facilities Concepts, Cost Estimates & Schedules for Experimental Facilities " Contractor Burns & Roe, Inc
BROMBERG, O Research Contracts Branch NRC-04-77-097 80/12/22 1p 07462 188

--8101150129 Mod 12, changing date in work directive 7, scope of work, estimated period of performance, to 801230 to, "Consulting Svcs (A-E) Re Evaluation of Facilities Concepts, Cost Estimates & Schedules for Experimental Facilities " PUCILLI, A C Burns & Roe Co MORTON, K V Research Contracts Branch NRC-04-77-097 80/12/22 1p 87462 189

8101150205 Notification of contract execution, Mod 7 to 'Tornado Parameters for Nuclear Power Plants " Contractor Univ of Chicago
HAGEY, H Research Contracts Branch FIN A-4059 NRC-04-74-239 80/12/31 1p 07462 169

--8101150210 Mod 7, extending period of performance & increasing funds to "Tornado Parameters for Nuclear Power Plants " BIAL, B B Chicago, Univ of MORTON, K V Research Contracts Branch FIN A-4059 NRC-04-74-239 80/12/31 4pp 07462 178

8101150217 Notification of contract execution, Mod 6 to "Extreme Max/Min Temp Analysis " Contractor US Dept of Commerce
GUSTAVE, R P Research Contracts Branch FIN 0-10318 NRC-01-76-340 80/12/24 1p 07465 338

--8101150223 Mod 6, extending completion date to 810331 w/no cost extension to, "Extreme Max/Min Temp Analysis " MITCHELL, B B Commerce, Dept of MORTON, K V Research Contracts Branch FIN 0-10318 NRC-01-76-340 80/12/24 1p 07465 339

8101150229 Notification of contract execution, Mod 3 to "Extreme Snow Loads for the Great Lake States " Contractor US Dept of Commerce
GUSTAVE, R P Research Contracts Branch FIN 0-10807 NRC-01-77-109 80/12/24 1p 07465 343

--8101150237 Mod 3, extending completion date to 810331 w/no cost extension to, "Extreme Snow Loads for Great Lake States " MITCHELL, B B Commerce, Dept of MORTON, K V Research Contracts Branch FIN 0-10807 NRC-01-77-109 80/12/24 1p 87465 344

8101150286 Notification of contract execution, Mod 3 to "Side for Psychological Assessment of Security Personnel " Contractor Assessment Designs, Inc
GUSTAVE, R P Research Contracts Branch FIN 0-10883 NRC-01-79-004 80/12/29 1p 07466 004

--8101150328 Mod 3, extending period of performance to 881231 at no cost to, "Side for Psychological Assessment of Security Personnel " FRANK, F D Assessment Designs, Inc FIN 0-10663 NRC-01-79-004 80/12/29 1p 07466 005

8101160971 Mod 1, extending period of performance to 810930 w/no add'l funding required
* Navy, Dept of, Naval Research Laboratory MATTHEW, M J Administrative Contracts Branch NRC-03-80-123 80/12/38 1p 87469 302

8101160380 Notification of contract execution, Mod 12 to 'Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions " Contractor Franklin Inst
HAIRSTON, C C GLAGOLA, A F Technical Assistance Contracts Branch FIN 3-7539 NRC-03-79-118 80/12/23 1p 07469 303

8101160091 Notification of contract execution, Mod 2 to 'Technical Assistance Assessment of Repository Siting & Design " Contractor US Bureau of Mines
HAIRSTON, C C FIELDS, J Technical Assistance Contracts Branch FIN 0-6934-1 NRC-02-80-875 80/12/24 1p 07469 304

8101160105 Notification of contract execution, Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor Nuclear Svcs Corp
HAIRSTON, C C GILLIN, P Technical Assistance Contracts Branch NRC-82-77-201-1 81/01/08 1p 87469 323

--8101160111 Mod 5, extending period of performance one add'l yr to 810101 to, "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " * Nuclear Services Corp MATTHEW, M J Administrative Contracts Branch NRC-02-77-201-1 81/01/08 5pp 07469 324

8101190154 Response to FOIA request for documents re six categories of written communications between NRC & Human Factors Research, Inc, Lifespring Corp, or Lifespring Foundation forwards documents listed in App A
FELTON, J M, Division of Ruins and Records 81/01/09 2pp 87475 204

--8101190167 Confirms verbal request for ltr of credit financing for Contract NRC-04-81-186 issued to Human Factors Soc Type is cost (no-fee) contract, w/13-month performance period
MORTON, K V Research Contracts Branch FIN 9-7239 NRC-04-81-186 80/12/11 1p

8101200426 Notification of contract execution, "Bioassay Procedures for Promethium-147," awarded to Univ of FL
MOYLE, A E Administrative Contracts Branch FIN 0-7110 NRC-81-81-004 81/01/08 1p 07487 039

--8101200432 Contract "Bioassay Procedures for Promethium-147," awarded to Univ of FL
RANDAZZO, A F Florida, Univ of Gainesville PERLMAN, J Administrative Contracts Branch FIN 0-7110 NRC-01-81-004 81/01/08 6pp 07487 040

8101200455 Notification of contract execution, Mod 1 to "Technical Assistance to NRC in Area of Reactor Vessel Irradiation Damage " Contractor Naval Research Lab
HAIRSTON, C C GLAGOLA, A F Technical Assistance Contracts Branch FIN 3-8897 NRC-83-88-123 80/12/30 1p 07487 117

8101208465 Notification of contract execution, Mod 5 to 'Seismic Zoning Map for Siting Nuclear Electric Power Generating Facilities in Eastern US " Contractor Rondout Associates, Inc
HAIRSTON, C C SHIFF, P A Technical Assistance Contracts Branch NRC-03-78-154 80/12/82 1p 07487 119

--8101200473 Mod 5, increasing funds to "Seismic Zoning Map for Siting Nuclear Electric Power Generating Facilities in Eastern US " POMEROY, P G Rondout Associates DOUGHERTY, O J Technical Assistance Contracts Branch NRC-03-78-154 80/12/82 1p 07487 120

B101200471 Notification of contract execution, Mod 2 to "Table S-3 Rulemaking Expert Testimony - Contractor Science Applications, Inc. PERLMAN, J. Administrative Contracts Branch FIN B-6349 NRC-02-78-026 01/01/02 1p 07487 121

--B101200480 Mod 2, closing out contract & debobligating balance to "Table S-3 Rulemaking Expert Testimony - Contractor Science Applications, Inc. PERLMAN, J. Administrative Contracts Branch FIN B-6349 NRC-02-78-026 01/01/02 1p 07487 127

B101200484 Mod 2, increasing funds, to "Technical Assistance for Assessment of Repository, Siting & Design." Interior, Dept. of, Bureau of Mines. MATTHEW, M. J. Administrative Contracts Branch FIN B-6344-1 NRC-02-80-075 01/12/24 1p 07487 123

B101200487 Notification of contract execution, Mod 10 to "Technical Assistance in Reviewing Original Seismic Design Bases & Design Bases for Operating Plants." Contractor NM Neumark, Consulting Engineering Svcs. GLACIELA, A. J. MAISTON, C. Technical Assistance Contracts Branch FIN B-1168 NRC-03-78-150 01/12/22 1p 07487 124

--B101200498 Mod 10, increasing funds & modifying authorized representative to "Technical Assistance in Reviewing Original Seismic Design Bases & Design Bases for Operating Plants." EMMARK, M. H. M. Neumark Consulting Engineering Services MATTHEW, M. J. Administrative Contracts Branch FIN B-1168 NRC-03-78-150 01/12/22 1p 07487 125

B101200022 Notification of contract execution, Mod 6 to "Mobile Lab." Contractor Mobile Sys. WIGGINS, E. Administrative Contracts Branch FIN B-1014 NRC-05-79-257 01/01/12 1p 07489 278

--B101200027 Mod 6, de-obligating remaining balance to, "Mobile Lab." KIMMEL, J. J. Mobile Systems MATTHEW, M. J. Administrative Contracts Branch FIN B-1014 NRC-05-79-257 01/01/12 1p 07489 279

B101200077 Notification of contract execution, Mod 2 to "Emergency Procedures Criteria for Nuclear Power Plant Operations." Contractor XYZYX Info Corp. MAISTON, C. J. VEYSER, J. Technical Assistance Contracts Branch FIN B-6872 NRC-03-80-118 01/12/31 1p 07489 300

B101200294 Mod 5, extending period of performance for addl yr. to "Basic Ordering Agreement to Develop Regulatory Framework for Nuclear Waste Mgt." STAGGS, D. O. Dames & Moore MATTHEW, M. J. Administrative Contracts Branch NRC-02-77-201-20 01/12/24 3pp 07493 083

B101200374 Notification of contract execution, Mod 10 to "Geophysical Investigation of Anna, Ok Earthquake Region." Contractor Univ. of MI. JACOBS, A. Research Contracts Branch, FIN B-5545 NRC-04-76-192 01/12/30 1p 07493 094

--B101200378 Mod 10, modifying Article 111, Govt Property, to "Geophysical Investigation of Anna, Ok Earthquake Region." MATHEWS, C. W. Michigan, Univ. of MORTON, K. V. Research Contracts Branch FIN B-5545 NRC-04-76-192 01/12/30 3pp 07493 095

B101200381 Notification of contract execution "Foreign Research & Licensing Practice Coordinator for General Reactor Safety Research." awarded to Structural Mechanics Associates. BAISDEN, L. Research Contracts Branch FIN B-6769 NRC-04-81-175 01/12/31 1p 07493 098

--B101200391 Contract "Foreign Research & Licensing Practice Coordinator for General Reactor Safety Research." awarded to Structural Mechanics Associates. STEVENSON, J. D. Structural Mechanics Associates. MORTON, K. V. Research Contracts Branch FIN B-6769 NRC-04-81-175 01/12/31 3pp 07493 099

B101200553 Mod 2, to include Task 2 to "Emergency Procedures Criteria for Nuclear Power Plant Operations." GBLD, R. L. XYZYX Information Corp. OUCHERTY, D. J. Technical Assistance Contracts Branch FIN B-6872 NRC-03-80-118 01/12/31 3pp 07488 030

B101200560 Mod 3, extending & increasing funds, to "Engineering Assistance in Connection w/ Antitrust Hearings." HDZER, M. H. Ch2m Hill, Inc. OUCHERTY, D. J. Technical Assistance Contracts Branch NRC-03-78-127-09 01/01/06 2pp 07488 008

B101200572 Notification of contract execution, Mod 2 to "Licensing Technical Assistance." Contractor Science Applications, Inc. MAISTON, C. EDGEWORTH, P. J. Technical Assistance Contracts Branch NRC-02-80-033-003 01/12/24 1p 07488 010

--B101200578 Mod 2, extending period of performance to B10320 to "Licensing Technical Assistance." Science Applications, Inc. MATTHEW, M. J. Administrative Contracts Branch NRC-02-80-033-0003 01/12/24 1p 07488 011

B101200727 Mod 3, extending contract from B10231 to B10131 & increase funds to, "Vol Reduction Techniques in Low Level Radwaste Mgt." CDHEIL, S. Teknekon Research, Inc. MATTHEW, M. J. Administrative Contracts Branch B-6413-1 NRC-02-79-024 01/12/31 2pp 07549 134

B101200734 Notification of contract execution: "Conduct Hearing Re Employee Grievance Under Agency Grievance Procedure & Provide Recommendation for Action by Reviewing Official in Resolving Grievance." Awarded to AH Mallor. FLYNN, M. J. Administrative Contracts Branch NRC-10-80-392 01/01/12 1p 07549 139

--B101200741 Contract "Conduct Hearing re Employee Grievance Under Agency Grievance Procedure & Provide Recommendation for Action by Reviewing Official in Resolving Grievance." MALLOR, A. J. Affiliation Unknown. PERLMAN, J. Administrative Contracts Branch NRC-10-81-393 01/01/21 7pp 07549 140

B101200766 Notification of contract execution, Mod 1 to "Computer Support of Info Requirements Control Automated Sys." awarded to Dept of Defense. FLYNN, M. J. Administrative Contracts Branch NRC-10-80-392 01/01/13 1p 07549 136

--B101200782 Mod 1, extending period of performance for 1 yr & increasing total funding to, "Computer Svcs in Support of Info Requirements Control Automated Sys." SCOTT, W. S. Defense, Dept. of, Defense Nuclear Agency LEBO, C. D. Administrative Contracts Branch NRC-10-80-392 01/01/13 2pp 07549 137

B101280440 Responds to FOIA request for Task 2 rept & monthly progress reports submitted by NUSAC, Inc. under NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model." Forwards nonproprietary versions of rept. FELTEN, J. H. Division of Rules and Records. 01/01/16 1p 07558 083

--B101280451 Forwards nonproprietary version of Revision 1 to Task 2 draft technical rept. "Mathematical Derivation of Advanced Matl Accounting Sys Simulation (AMASB) Model." prepared under NRC-02-80-024. PEVENSTEIN, J. E. NUSAC, Inc. NRC-5.1 01/10/24 1p.

--B101280455 591 Nonproprietary version of Task 2 draft technical rept. "Mathematical Derivation of Advanced Matl Accounting Sys Simulation (AMASB) Model." NUSAC, Inc. NRC-02-80-024 01/10/24 33pp.

--B101280459 Submits nonproprietary version of monthly progress report for NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model." AMASB mathematical methodology is under development. PEVENSTEIN, J. E. NUSAC, Inc. NRC-02-80-024. 01/08/18 3pp

--B101280464 Submits nonproprietary version of addendum to monthly progress rept for NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model." Addl info concerns 800805 meeting to discuss results of Task 1. PEVENSTEIN, J. E. NUSAC, Inc. NRC-02-80-024. 01/08/21 1p.

--B101280469 Submits nonproprietary version of monthly progress report for NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model." for 800809-0908 includes work performed, personnel time expenditures & costs. PEVENSTEIN, J. E. NUSAC, Inc. NRC-02-80-024. 01/09/19 2pp

--B101280474 Submits nonproprietary version of monthly progress report for NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model." for 800909-1010 includes work performed, personnel time expenditures & costs. PEVENSTEIN, J. E. NUSAC, Inc. NRC-02-80-024. 01/10/15 3pp

--B101280478 Submits nonproprietary version of monthly progress report for NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model." for 801011-1110 includes work performed, administrative matters & costs. PEVENSTEIN, J. E. NUSAC, Inc. NRC-02-80-024 01/11/15 3pp

01280447 FOIA request for Task 2 rept & monthly progress repts submitted by HUSAC, Inc under NRC-02-80-024. "Development of Advanced Moti Accounting Sys Simulation Model" FINOLEY, D E Science Applications, Inc 80/12/16 1p 07558 086

01290096 Notification of contract execution "Evaluation of NRC Executive Development & Mgt Program," awarded to Project Associates, Inc
COLEMAN, R Administrative Contracts Branch NRC-10-01-356 81/01/16 1p 07309 001

0101290105 Contract "Evaluation of NRC Executive Development & Mgt Program," awarded to Project Associates, Inc
QIBSON, R S Project Associates LEBO, C O Administrative Contracts Branch NRC-10-01-356 81/01/16 38pp 07309 001

01290337 Notification of contract execution "Consultant to LCFT Special Review Group," awarded to Aerospace Corp
LITTLE, M Administrative Contracts Branch FIN 8-7490 NRC-04-01-197 80/12/29 1p 07570 264

0101290341 Contract "Consultant to LCFT Special Review Group," awarded to Aerospace Corp
GULVER, C M Aerospace Corp PERLMAN, J Administrative Contracts Branch FIN 8-7490 NRC-04-01-197 80/12/29 5pp 07570 265

01290525 Notification of contract execution, Mod 3 to "Engineering Assistance in Connection w/Antitrust Hearings - Contractor CH2M Hill
GLAQUA, A F, HAIRSTON, C Technical Assistance Contracts Branch NRC-03-78-127-09 81/01/06 1p 07575 292

01290794 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/Commonwealth of VA" Contractor Commonwealth of VA
BAIBOEN, L Research Contracts Branch FIN D-5116 NRC-05-80-277 81/01/26 1p 07568 037

0101290798 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/Commonwealth of VA"
* Virginia, State of MORTON, K V Research Contracts Branch FIN D-5116 NRC-05-80-277 01/01/01 1p 07568 030

01300069 Notification of contract execution, Mod 1 to "Environ Monitoring Program w/State of MN" Contractor State of MN
BAIBOEN, L Research Contracts Branch FIN D-1292 NRC-05-80-288 81/01/26 1p 07583 051

0101300075 Mod 1, providing funding for CYBI effort to "Environ Monitoring Program w/State of MN"
* Minnesota, State of MORTON, K V Research Contracts Branch FIN 3-1292 NRC-05-80-200 81/01/26 1p 07583 052

01300086 Notification of contract execution, Mod 3 to "Environ Monitoring Program w/Commonwealth of PA" Contractor Commonwealth of PA
BAIBOEN, L Research Contracts Branch FIN D-5111 NRC-05-80-272 81/01/26 1p 07583 075

0101300093 Mod 3, providing funding for CYBI effort to "Environ Monitoring Program w/Commonwealth of PA"
* Pennsylvania, State of MORTON, K V Research Contracts Branch FIN B-5111 NRC-05-80-272 81/01/26 1p 07503 076

01300183 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/State of WI" Contractor State of WI
BAIBOEN, L Research Contracts Branch FIN D-5114 NRC-05-80-273 81/01/26 1p 07500 353

0101300107 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/State of WI"
* Wisconsin, State of MORTON, K V Research Contracts Branch FIN B-5114 NRC-05-00-275 01/01/26 1p 07580 394

01300285 Notification of contract execution, Mod 5 to "Sys Analysis of Shallow Land Burial" Contractor Science Applications, Inc
HAIRSTON, C, EDGEWORTH, P Technical Assistance Contracts Branch NRC-02-79-032 80/12/26 1p 07587 006

0101300291 Mod 5, extending period of performance, to "Sys Analysis of Shallow Land Burial"
* Science Applications, Inc MATTIA, M J Technical Assistance Contracts Branch NRC-02-79-032 80/12/26 1p 07587 037

01300300 Notification of contract execution, Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt," Contractor Genes & Moore
HAIRSTON, C, SMITH, P Technical Assistance Contracts Branch NRC-02-77-201-20 80/12/24 1p 07586 227

0101300307 Notification of contract execution, Mod 1 to "Licensing Review of CL Applications" Contractor Naval Surface Weapons Ctr
HAIRSTON, C, EDGEWORTH, P Technical Assistance Contracts Branch FIN B-6978 NRC-03-80-109 03/12/22 1p 07587 003

0101300312 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/State of NY" Contractor State of NY
BAIBOEN, L Research Contracts Branch FIN D-5109 NRC-05-80 271 81/01/26 1p 07587 037

--0101300316 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/State of NY"
* New York, State of MORTON, K V Research Contracts Branch FIN B-5109 NRC-05-80-271 01/01/26 1p 07587 010

0101300320 Notification of contract execution, Mod 1 to "Environ Monitoring Program w/State of MS" Contractor State of MS
BAIBOEN, L Research Contracts Branch FIN D-1297 NRC-05-80-289 81/01/26 1p 07587 025

--0101300325 Mod 1, providing funding for CYBI effort, to "Environ Monitoring Program w/State of MS"
* Michigan, State of MORTON, K V Research Contracts Branch FIN B-1297 NRC-05-80-289 81/01/26 1p 07587 026

0101300332 Notification of contract execution, Mod 3 to "Statistical Analysis Study" Contractor SL Wolfbein
FLYNN, M J Administrative Contracts Branch NRC-10-60-694 81/01/12 1p 07587 023

--0101300337 Mod 3, extending period of performance, to "Statistical Analysis Study"
WOLFBEIN, S L LEBO, C D Administrative Contracts Branch NRC-10-60-694 81/01/12 1p 07567 024

0101300344 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/State of MD" Contractor State of MD
BAIBOEN, L Research Contracts Branch FIN D-5106 NRC-05-80-269 81/01/26 1p 07585 251

--0101300349 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/State of MD"
* Maryland, State of MORTON, K V Research Contracts Branch FIN B-5106 NRC-05-80-269 01/01/26 1p 07503 255

0101300359 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/State of CO" Contractor State of CO
BAIBOEN, L Research Contracts Branch FIN D-5104 NRC-05-80-267 81/01/26 1p 07587 051

--0101300365 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/State of CO"
* Colorado, State of MORTON, K V Research Contracts Branch FIN B-5104 NRC-05-00-267 81/01/26 1p 07587 052

0101300372 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/State of ME" Contractor State of ME
BAIBOEN, L Research Contracts Branch FIN D-5113 NRC-05-80-274 81/01/26 1p 07587 054

--0101300381 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/State of ME"
* Maine, State of MORTON, K V Research Contracts Branch FIN B-5113 NRC-05-80-274 81/01/26 1p 07587 055

0101300370 Notification of contract execution, Mod 1 to "Environ Monitoring Program w/State of DE" Contractor State of DE
BAIBOEN, L Research Contracts Branch FIN B-1260 NRC-05-80-291 81/01/26 1p 07587 056

--0101300406 Mod 1, providing funding for CYBI effort, to "Environ Monitoring Program w/State of DE"
* Delaware, State of MORTON, K V Research Contracts Branch FIN B-1260 NRC-05-80-291 01/01/26 1p 07587 057

DISCLOSURE FINANCIAL DISCLOSURE INFORMATION

0101090700 Informs that exemption is granted from requirements of 10CFR 735-21 Recipient may participate in matters affecting Sandia Recipient possesses vested interest in Sandia pension plan, but cannot influence amount received SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/08 1p 07442 049

9004250139 Submits comments on Ofc of Mgt & Program Analysis review of Commission paper re enforcement program. Proposed policy prevents more aggressive enforcement program but does not address timing, regional delegation or enforceability. STELLD.V. Office of Inspection & Enforcement, Office of the Director 80/03/10 6pp 02554 23R.

-8004250144 Requests review of Ofc of Mgt & Program Analysis comments on Commission paper re enforcement program. 800318 info should include estimates impacts of sanctions, addl resources needed & ability to delegate enforcement to regions. DICKINSON, J. Office of the Executive Director for Operations, 80/03/14 1p 02564 244

8016030653 Forwards comments re 800320 proposed IE Commission paper. Supports objective to publish comprehensive enforcement policy & program defining levels of severity. Paper requires addl work prior to issuance for public comment. MINOZUE, R. B. Office of Standards Development, Director 80/02/27 3pp 02680 017

8007250759 Comments on revised NRC enforcement policy in response to 800630 memo Causes of equipment failure for which citations are not issued does not include maint. BUSH, L. L. Division of Safeguards Inspections 80/07/09 1p 03063 206

-8007250862 Requests comments on revised NRC enforcement policy by 800709. THOMPSON, O. Executive Officer for Operations Support 80/06/30 1p 03063 207

-8007250864 Forwards marked up copy of revised NRC enforcement policy. Comments requested by 800714. STELLD.V. Office of Inspection & Enforcement, Office of the Director 80/06/30 3pp 03063 208

8009120018 Advises that comments re revised NRC enforcement policy were previously in form of marked up copy. No further comments. MORELEV, N. C. Division of Reactor Operations Inspections 80/07/16 1p 03526 030

8009120327 Forwards comments re revised NRC enforcement policy. SMIELEK, J. H. Division of Fuel Facility & Materials Safety 80/07/14 4pp 03526 021

8009120320 Forwards comments on draft Commission paper re NRC enforcement program. No addl comments will be submitted. SMIELEK, J. H. Division of Fuel Facility & Materials Safety 80/06/26 47pp 03525 080

8010100294 Forwards 10CFR2, 'Proposed General Statement of Policy & Procedure for Enforcement Actions,' for transmittal to Ofc of FR for publication w/90-day public comment period. THOMPSON, O. Executive Officer for Operations Support 80/10/01 1p 03629 220

-8010100210 "Proposed General Statement of Policy & Procedure for Enforcement Actions." 10CFR2 informs licensees & public of basis for taking various enforcement actions. Comments due by 801231. Suppls encl. STELLD.V. Office of Inspection & Enforcement, Office of the Director 80/10/01 47p 03629 222.

8011070114 Forwards revised proposed general statement of policy & procedure for enforcement actions. Commission should seek concurrence in first few cases in which application of reduction of civil penalties for "good faith" is used. STELLD.V. Office of Inspection & Enforcement, Office of the Director 80/09/23 50pp 03714 196.

-8011070110 Summarizes 800904 discussion & vote on general statement of enforcement policy & Commission requests. CHILK, S. J. Office of the Secretary of the Commission 80/09/10 2pp 03714 206

8012050060 FOIA request for nine categories of info re fees concerning withdrawn, suspended or postponed applications. SILBERG, J. E. Shaw, Pittman, Potts & Trowbridge 80/10/30 3pp 07204 127

8012100023 'List of Withdrawn & Announced Cancellations, Suspensions or Indefinite Postponements Beginning 780323.' * Commissioners 80/11/21 4pp

--8012100252 Cases in which CP applications have been withdrawn, denied or abandoned by licensee & ltr to Philadelphia Electric Co notifying of fees based on manpower expended. MILLER, W. O. License Fee Management Branch 79/12/04 1p

--8012100400 Forwards FR notice re fees for review of applications. Ltrs to appropriate Congressional committees w/o encl ltr. SHAPAR, H. K. Office of the Executive Legal Director 80/10/14 1p

-8012100402 Notice of proposed rule to clarify fees for review of applications. Related documentation encl. CHILK, S. J. Office of the Secretary of the Commission 80/10/14 9pp.

8012180267 App C to 800530 ltr listing noncompliances to rept del. Includes noncompliance, criterion, rept section ref & rept page number. * Commissioners 80/09/30 1p

8010106072 Responds to FOIA request for listing of people &/or companies licensed by NRC to use radioactive mat'l & state agencies & addresses for Agreement States which issue licenses. Forwards computer printout w/o encl. FELTON, J. M. Division of Rules and Records 80/12/24 1p 07399 360.

8010106076 FOIA request for listing of people &/or companies licensed by NRC to use radioactive mat'l & state agencies & addresses for Agreement States which issue licenses to companies. RUSIECKI, G. Axon Industries Services, Inc 80/12/03 1p 07399 361.

80101060724 Responds to FOIA request for various categories of info re use, mgmt & sales of cobalt between 1946 & 1958. Forwards documents listed in App A Home telephone numbers withheld. ref FOIA Exemption 61. FELTON, J. M. Division of Rules and Records 80/12/22 7pp 07400 098

-80101060736 Notifies that all authorizations for radioisotope procurement will expire in 90 days. Requests submittal of application for all byproduct mat'l or stored waste w/o instructions, application forms & regulations. AEBERLE, D. C. Atomic Energy Commission 1E8.29 57/01/01

-80101060742 Forwards application for mat'l/byproduct license. MARTIN, W. F. Sun Shipbuilding & Dry Dock Co. (subs. Sun Co.) 57/04/16 1p

-80101060752 Application for mat'l/byproduct license authorizing use of &/or supervise use of four sources of 400 mCi Co-60 in metal to be used as source of radiation for radiographic exam. Home telephone numbers withheld (ref FOIA Exemption 61). * Sun Shipbuilding & Dry Dock Co. (subs. Sun Co. , Inc.) 57/04/15 9pp

-80101060759 Mat'l/Byproduct License 37-02900-01 for Sun Shipbuilding & Dry Dock Co. authorizing possession & use of four sources of 400 mCi Co-60 in metal to be used as source of radiation for radiographic exams of weldments, castings & forgings. * Atomic Energy Commission 57/04/29 2pp.

-80101060766 Requests encl of ltr & advisement as to whether new Co sources may be purchased by authority of License 37-02900-01 or whether new authorization is warranted. Inquire whether spent sources should be returned to original vendor. BOETTGER, C. S. Sun Shipbuilding & Dry Dock Co. (subs. Sun Co. , Inc.) 58/08/26 2pp.

-80101060775 Responds to 580826 ltr re replacement of four sources Co-60 under License 37-02900-01. Co-60 sources are no longer available from ORNL. New mat'l/byproduct license application should be submitted. New vendor will dispose spent sources. MILLER, W. O. Atomic Energy Commission 58/09/12 1p.

80101060730 FOIA request for various categories of info re use, mgmt & sales of cobalt between 1946 & 1958. KAHN, J. R. Blank, Rado, Comisky & McCauley 80/11/24 3pp 07400 101.

80101070004 Responds to FOIA request for four categories of documents: cold shutdown w/ regard to fire protection requirements in App A to 10CFR50. Forwards D Davis 790614 memo & P Matthews/ J Knight memo re 790228 review group meeting. FELTON, J. M. Division of Rules and Records 80/12/30 1p 07414 182

--B101070012 Discusses requirements for achieving cold shutdown of SEP plants Lists shutdown & cooldown criteria developed in ongoing fire protection review SEP position for plant cooldown capabilities encl
OAVIS, D K Systematic Evaluation Program Branch (Pre 791030)
79/06/14 4pp

B101070008 FOIA request for four categories of documents re cold shutdown w/regard to fire protection requirements in App R to 10CFR50
SIEHLMEYER, J O Edison Electric Institute 80/12/12 2pp
07414 183

B101070022 FOIA request for seven categories of NRC documents
MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 80/10/16 3pp
07414 187

B101070026 Responds to FOIA request for all documents discussing or identifying alternatives to fire protection requirements of App R to 10CFR50 Documents are available in PCR
FELTON, J M Division of Rules and Records 80/12/31 1p
07414 189

B101070028 FOIA request for all documents discussing or identifying alternatives to fire protection requirements of App R to 10CFR50
WATKINS, M Debovoise & Liberman 80/12/12 2pp 07414 190

B101070034 Responds to FOIA request for winning proposal awarded under RFP RB-NMS-B1-032, "Technical Support for Confidence Rulemaking Proceeding" Contract has not yet been awarded
FELTON, J M Division of Rules and Records 80/12/30 1p
07414 192

B101070040 FOIA request for winning technical proposal awarded under RFP RB-NMS-B1-032, "Technical Support for Confidence Rulemaking Proceeding"
RUETHERFORD, J F BOM Corp BOM/M-JFR-073B 80/12/12 1p
07414 193

B101070046 Responds to FOIA request for addresses of Ohmart Corp. Inc. US Radium Corp. AECL & Central Scientific Labs Forwards list of addresses. Central Scientific Labs is not NRC licensee, therefore, no address is available
FELTON, J M Division of Rules and Records 80/12/31 1p
07414 194

--B101070053 List of addresses for Ohmart Corp. Inc. US Radium Corp. AECL & Central Scientific Labs
* Commissioners 80/12/31 1p 07414 195

B101070049 FOIA request for addresses of Ohmart Corp. Inc. US Radium Corp. AECL & Central Scientific Labs
LAUDIG, B 80/08/25 1p 07414 196

B101070059 Responds to FOIA request for six categories of info re fire protection requirements in App R to 10CFR50 Encl PR Matthew draft memo is responsive to request & will be placed in PCR
FELTON, J M Division of Rules and Records 80/12/30 1p
07414 197

--B101070070 Summary of 790228 fire protection review group meeting to discuss differences in fire protection measures accepted by Div of Sys Safety & Div of Operating Reactors to protect redundant divs of sys necessary for safe hot shutdown
MATTHEWS, P R Auxiliary Systems Branch KNIGHT, J Assistant Director for Engineering 79/03/14 18pp

B101070076 Addl response to FOIA request for info re spent nuclear fuel transportation routes. Forwards final version of NUREG-0725 & list of transfers of spent fuel into, out of, or through State of CA w/o encl NUREG-0725
FELTON, J M Division of Rules and Records 80/12/29 1p
07414 200

--B101070080 Listing of transfers of spent fuel into, out of, or through State of CA during 790101-801031
* Commissioners 80/12/29 2pp 07414 203

B101070086 Responds to FOIA request for documents re BECY-80-409, "Proposed Rulemaking to Amend 10CFR50 Concerning ATWS Events" NRC will provide all AWS documentation & list of any which may be withheld
FELTON, J M Division of Rules and Records 80/12/31 3pp
07414 205

B101070091 FOIA request for documents re BECY-80-409, "Proposed Rulemaking to Amend 10CFR50 Concerning ATWS Events"
EARLEY, A F Hunton & Williams 80/11/25 19pp 07414 208

B101090137 Forwards draft IE bulletin entitled, "Performance of Licensed Operators at Controls of Reactors" & draft ltr in all holders of operator or senior operator licenses re performance while on duty at controls of nuclear reactor
KEPPLER, J G Region 3, Chicago, Office of the Director 80/07/2pp

--B101090150 Discusses IE policies for reporting, evaluating & doing significant safety matters, in light of incident at facility. Consideration of safety significance always precedes noncompliance in evaluating any concern Related info encl
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/10/01 4pp

--B101090163 Forwards Ofc of Nuclear Reactor Regulation & Ofc of Enforcement comments on draft Commission paper, "NRC Enforcement Program" IE draft notification of significant enforcement action encl
BRYAN, S E Division of Reactor Operations Inspections EN-80/02/10 2pp

--B101090166 Notification of 800527 meeting in Bethesda, MD in dis enforcement policy. Limited personnel closely associated w/subj & able to contribute to discussions may attend
DICKS, W J Office of the Executive Director for Operations 80/05/23 1p

--B101090169 Ack receipt of ltr concerning NRC enforcement policy. Proposed changes to enforcement policy are currently undergoing extensive review & will clarify concerns raised
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/06/05 3pp

--B101090172 Discusses NRC proposed enforcement policy. Increasing emphasis on penalties in enforcement actions will be counterproductive to increasing safety. Records greater flexibility in applying penalties
JENSEN, W H Detroit Edison Co 80/05/05 2pp

--B101090179 Requests comments on encl revised NRC enforcement policy
800707
THOMPSON, D Executive Officer for Operations Support 80/06/36pp

--B101090103 Forwards revised NRC enforcement policy Requests review comment
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/06/30 38pp

--B101090188 Forwards draft of revised NRC enforcement policy Requests comments by 800714 w/o encl
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/01 1p

--B101090196 Requests NRC policy statement re resident inspector participation in licensee internal labor relation disputes that result from enforcement action
BRYAN, S E Division of Reactor Operations Inspections 80/06/1p

--B101090202 Notifies that regional public meetings on NRC enforcement policy will be scheduled Requests cooperation
THOMPSON, D Executive Officer for Operations Support 80/07/1p

--B101090213 Discusses use of IE revised enforcement criteria New enforcement criteria should be invoked when insp or investigation programs disclose serious violations occurring between 800630 & 0901
THOMPSON, D Executive Officer for Operations Support 80/07/1p

B101090298 Partial response to FOIA request for documents re nuclear accident in USSR in 1955 Forwards documents listed in Apps A & B, NRC 1979 Annual Rept, "Outline History of Nuclear Regulation & Licensing, 1946-1979" & 801110 transcript
FELTON, J M Division of Rules and Records 80/12/03 3pp
07442 085

--B101090307 Book review of, "Nuclear Disaster in Urals," published by Press Intelligence, Inc. Newspaper clippings re nuclear disaster encl
PATTERSON, W O Affiliation Unknown 79/07/15 4pp

--B101090318 Transcript of 60 Minutes 801110 television program re nuclear disaster. Pg 1-7
* CBS News, CBS, Inc NRC-8343 80/11/10 7pp

150088 FOIA request for nonproprietary version of winning proposal submitted in response to RFP RS-OSD-80-017. "Evaluation of Geotechnical Surveillance Techniques for Monitoring High Level Waste Repository Performance" SHILLER, R.P. Shannon & Wilson, Inc. 80/12/16 1p 07462 207

11150093 Responds to FOIA request for listing of all bidders responding to RFP RS-OSD-01-001. "Evaluation of Util Self-Insurance as Option for Assuring Funds for Decommissioning" FELTON, J.M. Division of Rules and Records 81/01/07 1p 07475 209

11150079 FOIA request for listing of all bidders responding to RFP RS-OSD-01-001. "Evaluation of Util Self-Insurance as Option for Assuring Funds for Decommissioning" FELTON, J.M. Division of Rules and Records 80/12/08 1p 07462 209

11150107 Responds to FOIA request for winning proposals submitted under RFP RS-OSD-80-012 & RFP RS-CDD-80-019 Forwards nonproprietary versions of proposals listed in app FELTON, J.M. Division of Rules and Records 80/12/30 2pp 17462 210

11150127 Nonproprietary response to RFP RS-OSD-80-019. "Evaluation of Geotechnical Surveillance Techniques for Monitoring High Level Waste Repository Performance" Describes technical effort, resources, relevant qualifications & subcontractors HOCKING, O., HARDY, M.P., ADAPITO, J.F., J.F.T. Acapito & Associates, Inc. RS-OSD-00-019 80/07/09 44pp

11150134 Nonproprietary response to RFP RS-OSD-00-019. "Evaluation of Geotechnical Surveillance Techniques for Monitoring High Level Waste Repository Performance" Describes technical effort, available resources & relevant qualifications HOCKING, O., ADAPITO, J.F., HARDY, M.P., J.F.T. Acapito & Associates, Inc. RS-OSD-80-019 80/07/07 131pp

11150142 Submits answers to NRC questions & revised cost estimate concerning response to RFP RS-OSD-00-012. "Info Needs for Site Characterization Plans" Response constitutes best & final offer WERNER, M. FUORO, INC. RS-OSD-80-012 80/07/15 11pp

11150149 Response to RFP RS-OSD-00-012. "Info Needs for Site Characterization Plans." Vol 3 Includes scope of work & technical approach, experience w/regulatory sys. support personnel & facilities & potential problem areas FUORO, INC. RS-OSD-80-012 80/07/31 176pp

11150110 FOIA request for winning proposals re RFP RS-OSD-80-012. "Info Needs for Site Characterization Plans" & RFP RS-OSD-80-019. "Evaluation of Geotechnical Surveillance Techniques for Monitoring High Level Waste" FELTON, J.M. Energy Resources Co., Inc. 00/10/24. 1p 07462 212

11190137 Responds to FOIA request for 11 documents Forwards requested documents w/o encls FELTON, J.M. Division of Rules and Records 81/01/07 1p 17475 325

11190142 FOIA request for 11 specific documents BONES, L. Black Hills Alliance. 80/12/12 2pp 07475 326

11190145 Partial response to FOIA request for all documents re correspondence between NRC & T Madden of Kaye, Scholer, Fierman, Hays & Handler Forwards documents listed in App A w/o encls. FELTON, J.M. Division of Rules and Records 81/01/00 2pp 17475 200

11190148 FOIA request for all documents re correspondence between NRC & T Madden of Kaye, Scholer, Fierman, Hays & Handler FELTON, J.M. Division of Rules and Records 80/12/16 9pp 07475 202

11190154 Responds to FOIA request for documents re six categories of written communications between NRC & Human Factors Research, Inc. Lifespring Corp. or Lifespring Foundation Forwards documents listed in App A FELTON, J.M. Division of Rules and Records 81/01/07 2pp 17475 204

11190167 Confirms verbal request for ltr of credit financing for Contract NRC-04-B1-106 issued to Human Factors Soc Type is cost (no-fee) contract w/13-month performance period MORTON, K.V. Research Contracts Branch FIN B-7239 NRC-04-B1-106. 80/12/11. 1p

--B101190176 Forwards ltr of credit & authorized signature card for payment vouchers on ltr of credit for Human Factors Soc PUGLISE, A.S. Division of Accounting 00/12/31 3pp

B101190139 FOIA request for documents re six categories of written communications between NRC & Human Factors Research, Inc. Lifespring Corp. or Lifespring Foundation FELTON, J.M. Division of Rules and Records 80/12/01 3pp 07475 206

B101190576 Responds to FOIA request for data re individual shipments of U made 1976-1980 Forwards computer printout of data on U shipments from Jan 1976-April 1980 & listing of current repeating identification symbols w/o encls FELTON, J.M. Division of Rules and Records 81/01/08 1p 07475 355

B101190531 FOIA request for data re individual shipments of U made during 1976-1980 CRALFORD, W.I. General Electric Co. 80/11/17 1p 07475 356

B101210538 Responds to FOIA request for listing of all matl concerning areas of nuclear science such as reactor design, const & security, general publications & nuclear weapons program Forwards documents listed in App A w/o encls FELTON, J.M. Division of Rules and Records 81/01/16 2pp 07489 110

B101210549 FOIA request for listing of all matl concerning areas of nuclear science such as reactor design, const & security, general publications & nuclear weapons program SHAFAN, H. Affiliation Unknown 81/01/05 1p 07489 112

B101210554 Partial response to FOIA request for four categories of documents re NRC release of spent fuel routing & other shipment info to public Forwards documents listed in App A Addl documents are undergoing review for release FELTON, J.M. Division of Rules and Records 81/01/15 2pp 07489 113

--B101210563 Responds to Item 7 of 750525 memo re release of info re irradiated fuel shipments Specific details of approved routes, strap maps & shipment notices will be withheld (ref ICCFR 7901 info will be distributed on need-to-know basis GIBBS, W.J. Office of Nuclear Material Safety & Safeguards 79/06/25 2pp

--B101210569 Reviews report re withholding of spent fuel info Disagrees w/recommendation Alternative 3 should be replaced w/method of releasing route info to state authorities w/suggestion that info be retained in official channels MCCORMACK, O.D. Physical Security Licensing Branch. 80/03/26 2pp

--B101210574 Advises of BCO630 meeting w/Off of Executive Legal Director re policy for release of safeguards info per FY80 authorization bill Meeting summary encls BURNETT, R.E. Division of Safeguards 80/07/11 3pp

B101210558 FOIA request for four categories of documents re NRC release of spent fuel routing & other shipment info to public LEE, O.D. Americans for Nuclear Energy 00/12/18 1p 07489 115

B101210580 Responds to FOIA request for documents re Nuclear Equipment Chemical Corp & Fern Labs NRC has no documents subj to request FELTON, J.M. Division of Rules and Records 00/14/2 81/01/16 1p 07489 123

B101210582 FOIA request for documents re Nuclear Equipment Chemical Corp & Fern Labs HATBOW, I.M. FOI Service 00/14/2 80/12/15 1p 07489 124

B101210597 Responds to FOIA request for final version of generic EIS re U milling, NUREG-0706 Forwards documents listed in App A w/o encls FELTON, J.M. Division of Rules and Records 81/01/13 2pp 07489 131

B101210599 FOIA request for final version of generic EIS re U milling PULS, H. Fells United to Inhibit Unsafe Radiation Emission (FUTURE) 80/12/21 2pp. 07489 133

B101210602 Responds to FOIA request for documents re use of burros in radiation research during 1950s No documents are available subj to request. Request has been forwarded to BCE FELTON, J.M. Division of Rules and Records 81/01/15 1p 07489 135

8101260259 FOIA request for documents re use of LWRs in radiation research during 1950s
SCHWARTZ, J. M. Search Associates 80/12/22 1p 07469 135

8101260176 Responds to FOIA request that specified documents be placed in PER items 1-5 GE topological cells are located in PCR on microfiche items 6 & 7 are being replaced in PCR
FELICH, J. M. Division of Rules and Records 81/01/15 1p 07511 031

8101260175 FOIA request re placement of documents listed in encl in PCR
SCHWARTZ, J. M. Search Associates 80/12/17 1p 07511 035

8101260175 Responds to FOIA request for seven categories of LWR documents Forwards computer printout indicating pertinent documents & other documents published 1979-80 & documents in response to request
FELICH, J. M. Division of Rules and Records 80/12/31 2pp 07515 132

--8101260024 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARP, J. C. Division of Rules and Records 80/12/18 3pp 07506 135

--8101260052 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARP, J. C. Division of Rules and Records 80/12/02 3pp 07506 146

--8101260034 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARP, J. C. Division of Rules and Records 80/12/18 3pp 07506 135

--8101260052 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARP, J. C. Division of Rules and Records 80/12/02 3pp 07506 115

--8101260061 Forwards 790524 & 0921 memos re investigation rept. "Michelson Rept - Events & Levels of Review." Memos should be made part of official file
STRICKLER, L. J. Office of Inspector & Auditor 79/10/12 1p 07507 023

--8101260034 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARP, J. C. Division of Rules and Records 80/12/18 3pp 07506 136

--8101260052 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARP, J. C. Division of Rules and Records 80/12/02 3pp 07506 146

--8101260120 Forwards "Michelson Rept - Events & Levels of Review." in response to request
CUMMINGS, J. J. Office of Inspector & Auditor 79/08/01 1p 07507 063

--8101260128 Rept of investigation. "Michelson Rept - Events & Levels of Review."
STRICKLER, L. J. Office of Inspector & Auditor 79/07/25 16pp 07507 065

--8101260161 Discusses 790705 interview w/6 Newberry re events & levels of review concerning analysis of Michelson rept. "Decay Heat Removal During Very Small Break LCCA for BSW 205 Fuel Assembly PWR." Newberry unaware of reft prior to 790701
STRICKLER, L. J. Office of Inspector & Auditor 79/07/10 1p 07507 070

--8101260173 Discusses 790702 interview w/6 Paretti re Michelson reft. "Decay Heat Removal During Very Small Break LCCA for BSW 205 Fuel Assembly PWR." Paretti received reft in 1977 or 1978. but did not review in detail WA Post article encl
GAUBLE, D. H. Office of Inspector & Auditor 79/07/10 3pp 07507 071

--8101260188 Submits reft of interview w/6 Michelson on 790521 re reft. "Decay Heat Removal During Very Small Break LCCA for BSW 205 Fuel Assembly PWR."
WARD, W. J. Office of Inspection & Enforcement, Office of the Director 79/05/21 4pp 07507 093

--8101260201 Lists principal lines of inquiry on which investigation of reft. "Decay Heat Removal During Very Small Break LCCA for BSW 205 Fuel Assembly PWR." will be based
IE & Dir of Inspector & Auditor are responsible
THORNBURG, H. D. Division of Reactor Construction Inspection 79/05/24 1p 07507 098

--8101260208 Confirms 790608 memo characterizing C Michelson as inadequate forum existed within nuclear regulatory sys. re safety-related concern info re decay heat removal problem encl
STRICKLER, L. J. Office of Inspector & Auditor 79/06/11 07507 099

--8101260218 Submits reft of interview w/RC Jones on 790529 re "Decay Heat Removal During Very Small Break LCCA for BSW Fuel Assembly PWR."
WARD, W. J. Office of Inspection & Enforcement, Office of the Director 79/05/29 2pp 07507 243

--8101260222 Forwards reft entitled "NRC Program for Resolution of Generic Issues Related to Nuclear Power Plants." in accordance w/reporting requirements of Energy Reorganization Act of 1974 W/o encl
HELDORIE, J. M. Commissioners 77/12/10 2pp 07507 245

--8101260227 Draft Commission paper informing Commission of investigation results & proposed enforcement actions re BSW PWR response to small break LCCAs Forwards draft civil penalty package & notice of noncompliance
STELL, D. V. Office of Inspection & Enforcement, Office of the Director 80/03/25 13pp 07507 268

--8101260237 Discusses IE May-Nov 1979 investigations into whether had adequately analyzed potential safety problems & whether problems should have been reported per 10CFR21 No evidence constituting criminality found
CUMMINGS, J. J. Office of Inspector & Auditor 80/04/02 07507 288

--8101260247 Submits results of first phase of audit of implementation action plan items relating to Dir of Nuclear Reactor Regulation investigation focused on util personnel licensing & training Provides scope, findings & comments
CUMMINGS, J. J. Office of Inspector & Auditor 80/10/03 07507 290

--8101260255 Comments on draft reft re audit of implementation action plan items relating to Dir of Nuclear Reactor Regulation Reft focused on util personnel licensing & training Related documentation encl
DIRCKS, W. J. Office of the Executive Director for Operations 80/09/29 7pp 07507 299

--8101260260 Discusses audit review of NRC reactor insp program objective was to assess degree to which IE policies & procedures for inspecting nuclear plants were being implemented Forwards info reft on reactor insp program
CUMMINGS, J. J. Office of Inspector & Auditor 80/07/31 07507 297

--8101260267 Informs that IE has no substantive comment on reactor insp program IE will utilize reft & survey responses on ongoing reviews of insp program
DIRCKS, W. J. Office of the Executive Director for Operations 80/07/01 1p 07507 306

--8101260276 Discusses potential problem w/temporary duty transfer authorizations for resident inspectors Practice is contrary to Comptroller General Decisions B-188093, B-182427 & B-193401 W/o encl Decision B-100093
CUMMINGS, J. J. Office of Inspector & Auditor 80/06/20 07507 337

--8101260282 Forwards reft re review of NRC plan for research safety of LWRs Review purpose was to determine whether NRC was responsive to Public Law 95-209 Provides summary of findings, recommendations & agency comments
CUMMINGS, J. J. Office of Inspector & Auditor 80/06/11 07507 360

--8101260288 Comments on recommendations in draft reft on research plan for research to improve safety of LWRs Concurs w/recommendations
BURKHARTZ, R. J. Office of Nuclear Regulatory Research, Director 80/06/09 2pp 07508 021

--8101260298 Discusses NRC required experience for senior resident inspectors. Inspector must possess min of 2 yrs experience in NRC regulatory program before being relocated as senior resident inspector
STELL, D. V. Office of Inspection & Enforcement, Office of the Director 80/03/06 1p 07508 023

--B101260314 Submits rept on undesirable effects of accelerating implementation of NRC resident insp program Includes summary of findings, conclusions, recommendations & agency comments Related documentation encl CUMINGS, J J Office of Inspector & Auditor 79/06/22 15pp 07500 062

--B101260319 Submits no comment on draft rept re undesirable effects of accelerating implementation of NRC resident insp program GOSBICK, L V Office of the Executive Director for Operations 79/06/22 200pp 07508 077

--B101260329 Submits audit rept of ongoing review of Ofc of Nuclear Regulatory Research activities NRC should continue to negotiate w/ERDA to clarify responsibilities of each agency & simplify organization of working relationship HCTIERNAN, T J Office of Inspector & Auditor 76/07/24 31pp 07508 078

--B101260334 Memorandum of understanding between NRC & ERDA re joint research programs BEAMAN, H C Energy Research & Development Admin (Presently DOE) ANDERSON, W A Commissioners 75/00/03 10pp 07500 111

--B101260339 Submits review of rept on NRC/ERDA relations in research activities Joint task force should investigate working relationship Related documentation encl GOSBICK, L V Office of the Executive Director for Operations 76/07/29 350pp 07508 120

B101270171 Responds to FOIA request for documents re disposal of nuclear wastes off NJ coast by Navy in Oct 1947 NRC has no documents subj to request FELTON, J M Division of Rules and Records 81/01/21 1p 07547 066

B101270178 FOIA request for documents re disposal of nuclear wastes off NJ coast by Navy in Oct 1947 MAADDIS, S Courier-News Bridgewater, NJ 81/01/02 2pp 07547 067

B101270197 FOIA request for four categories of documents REID, A B Black Hills Alliance 80/12/14 2pp 07543 023

B101280350 Responds to FOIA request for updated list of threats to licensed nuclear facilities since 790330 Info can be found in NUREG-0525, Revision 2 & 3, which are available at NRC. Div of Technical & Document Control & NTIS FELTON, J M Division of Rules and Records 81/01/21 1p 07550 057

B101280350 FOIA request for updated list of threats made to licensed nuclear facilities since 790330 MAZUR, A Syracuse Univ 01/01/01 1p 07550 058

B101280365 Responds to FOIA request for documents re Task Force on Interim Operation of Indian Point submitted to NRC after 800531 Forwards App A documents App D documents withheld (ref FOIA Exemption 3) FELTON, J M Division of Rules and Records 01/01/21 3pp

--B101280380 Staff requirements memo re 800626 briefing on recommendations of facility Task Force Commission took no action during meeting Task force rept & other info re facility operation will be reviewed further CHILKIS, J Office of the Secretary of the Commission 80/04/30 1p

B101280408 Responds to FOIA request for NRC most recent functional organizational chart Forwards requested info w/o encl FELTON, J M Division of Rules and Records 81/01/23 1p 07550 073

B101280410 FOIA request for NRC most recent functional organizational chart EBERLEIN, F Control Data Corp 81/01/19 1p 07550 074

B101280432 Partial response to FOIA request for documents re Paragraphs 1 & 2 of 701027 FR notice Lists excerpt from NRC 1975 annual rept w/respect to query re vacant commissioner'ship Another document subj to request is undergoing review FELTON, J M Division of Rules and Records 81/01/21 1p 07550 080

--B101280431 Forwards nonproprietary version of Revision 1 to Task 2 draft technical rept "Mathematical Derivation of Advanced Matl Accounting Sys Simulation (AMASS) Model," prepared under NRC-02-80-024 PEVENSTIEIN, J E NUSAC, Inc NRC-02-80-024 80/10/24 1p

--B101280455 591 Nonproprietary version of Task 2 draft technical rept, "Mathematical Derivation of Advanced Matl Accounting Sys Simulation (AMASS) Model" NUSAC, Inc NRC-02-80-024 80/10/30 73pp

--B101280459 Submits nonproprietary version of monthly progress report for NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model" AMASS mathematical methodology is under development PEVENSTIEIN, J E NUSAC, Inc NRC-02-80-024 80/08/15 3pp

--B101280466 Submits nonproprietary version of addendum to monthly progress rept for NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model" Addl info concerns 030005 meeting to discuss results of Task 1 PEVENSTIEIN, J E NUSAC, Inc NRC-02-80-024 80/08/21 1p

--B101280469 Submits nonproprietary version of monthly progress report for NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model" for 000019-0908 Includes work performed, personnel time expenditures & costs PEVENSTIEIN, J E NUSAC, Inc NRC-02-80-024 80/09/15 2pp

--B101280474 Submits nonproprietary version of monthly progress report for NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model" for 000019-1010 Includes work performed, personnel time expenditures & costs PEVENSTIEIN, J E NUSAC, Inc NRC-02-80-024 80/10/15 3pp

--B101280478 Submits nonproprietary version of monthly progress report for NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model" for 001011-1110 Includes work performed, administrative matters & costs PEVENSTIEIN, J E NUSAC, Inc NRC-02-80-024 80/11/15 2pp

B101280447 FOIA request for Task 2 rept & monthly progress rept submitted by NUSAC, Inc under NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model" FINDLEY, D E Science Applications, Inc 00/12/16 1p 07550 040

B101280481 Responds to FOIA request for documents re Paragraphs 1 & 2 of 701027 FR notice Forwards EECY-80-341 w/o encl FELTON, J M Division of Rules and Records 81/01/22 1p 07550 106

B101280608 Responds to FOIA request for info re incidents concerning unaccounted for & other types of safeguards violations Forwards NUREG-0525, Revision 3, "Safeguards Summary Event List (SSEL)" PNDs are located in PUR 110a encl NUREG-0525 FELTON, J M Division of Rules and Records 01/01/22 1p 07550 209

B101280612 FOIA request for info re incidents concerning unaccounted for & other types of safeguards violations, for use in research project EISENHAEUER, M H Affiliation Unknown 81/01/06 1p 07550 210

B101290055 Responds to FOIA request for records re investigation, audits or regulatory proceedings involving Enersch Corp & subsidiaries or affiliates & all correspondence within past 10 yrs Encl App A documents available in PER FELTON, J M Division of Rules and Records 01/01/13 3pp 07573 291

--B101290067 Matl/Oxyproduct license 29-07056-03 for Ebasco Svcs, Amended per 790224 application Amend 5 changes expiration date in item 4 to 806331 & revises Condition 16 BASSIN, N Licensing Management Branch 75/06/10 1p

--B101290322 Matl/Byproduct License 29-07056-03 for Ebasco Svcs, Inc is amended per 721115 application Amend 3 revises Condition 16 & authorizes possession, use, transfer & import of 599 kg U contained as shielding matl in radiography devices
BASSIN, N Atomic Energy Commission, Directorate of Licensing
72/09/10 1p

--B101290347 Matl/Byproduct License 29-07056-03 for Ebasco Svcs, Inc is amended per 720324 application Amend 2 authorizes possession & use of Co-60, no single source to exceed 10 Ci in Technical Operations Model A-424-15 sealed sources
BASSIN, N Atomic Energy Commission, Directorate of Licensing
72/09/19 1p

--B101290790 Matl/Byproduct License 29-07056-03 for Ebasco Svcs, Inc is amended per 710218 application Amend 1 authorizes possession & use of Co-60, no single source to exceed 250 Ci in Technical Operations Model A-424-15 sealed sources
BASSIN, N Atomic Energy Commission, Directorate of Licensing
71/04/30 1p

--B101290104 Matl/Byproduct License 29-07056-03 for Ebasco Svcs, Inc, authorizing possession & use of Ir-192 & Co-60 in forms of Technical Operations sealed sources & exposure devices
BASSIN, N Atomic Energy Commission 71/02/03 1p

--B101290116 Forwards application for renewal of Matl/Byproduct License 29-07056-03
TENZER, H E Ebasco Services, Inc (subs of Enserch Corp) 1
95016 75/02/24 2pp

--B101290124 Application for renewal of Matl/Byproduct License 29-07056-03, authorizing possession & use of Ir-192 & Co-60 in forms of Technical Operations sealed sources & exposure devices including certificate & proof qualifications encl
TENZER, H E Ebasco Services, Inc (subs of Enserch Corp) 1
95016 75/02/24 14pp

--B101290131 Requests renewal of Matl/Byproduct License 29-07056-03
BU, LEN, H C Ebasco Services, Inc (subs of Enserch Corp) 1
94548 75/01/28 1p

--B101290143 Forwards list indicating quantity of depleted U contained as shielding matl in radiography devices & source changers authorized under License 29-07056-03 Add exposure devices have not been purchased
BU, LEN, H C Ebasco Services, Inc (subs of Enserch Corp) 1
74/06/20 2pp

--B101290255 Requests amend to Matl/Byproduct License 29-07056-03, authorizing use, transfer & import of 1,000 kg or more U, contained as shielding matl in radiography devices & source changers Radiographic exposure device inventory steel encl
BU, LEN, H C Ebasco Services, Inc (subs of Enserch Corp) 1
43969 74/01/03 2pp

--B101290261 Requests amend to Matl/Byproduct License 29-07056-03 procedure, "Manual for Operating & Emergency Procedures for Isotope Radiography," Revision & Supplemental data sheet encl
ALLIKBERG, R Ebasco Services, Inc (subs of Enserch Corp) 1
32056 72/11/15 3pp

--B101290151 Responds to AEC 720821 request for clarification re use of source changer for quarterly insp & maint of radiographic equipment Forwards Revision 5 to isotope radiography manual for operating & emergency procedures Cover page only
ALLIKBERG, R Ebasco Services, Inc (subs of Enserch Corp) 1
72/09/01 2pp

--B101290171 Requests clarification of statement contained in 720726 procedure for quarterly insp & maint of radiographic equipment re storage of source in Technical Operations Model 416 source changer Review to continue upon receipt of info
BASSIN, N Atomic Energy Commission 72/03/21 1p

--B101290157 Responds to AEC 720670 request for more complete instructions re quarterly insp & maint procedure W/a encl manual for operating & emergency procedures for isotope radiography
ALLIKBERG, R Ebasco Services, Inc (subs of Enserch Corp) 1
72/07/23 1p

--B101290310 Revision 3 of Manual for operating & emergency procedures for isotope radiography
* Ebasco Services, Inc (subs of Enserch Corp) 1 72/05/31 71pp

--B101290186 Informs that revised operating & emergency procedures, per 720426 application for amend to License 29-07056-03, should include ref or instructions for use of Model 684 exposure device & name of person conducting quarterly insp & maint
BASSIN, N Atomic Energy Commission, Directorate of Licensing
72/05/09 1p

--B101290324 Requests amend to Matl/Byproduct License 29-07056-03, authorizing use of Co-60, no single source to exceed 10 Ci, for use in Model A-424-15 sealed sources & revising Condition 14
BU, LEN, H C Ebasco Services, Inc (subs of Enserch Corp) 1 27/01 72/04/26 2pp

--B101290281 Submits addl info re amend to Matl/Byproduct License 29-07056-03 in response to AEC 710301 request Technical Operations devices Models 680 & 676 will be utilized at Port Kennedy facility only Technical Operations 710401 ltr encl
BU, LEN, H C Ebasco Services, Inc (subs of Enserch Corp) 1
71/04/01 3pp

--B101290203 Requests addl info re 710218 application for license to possess & use 250 Ci Co-60 in Technical Operations Model 676 exposure device, including where source & device will be used & revised operating & emergency procedures
BASSIN, N Atomic Energy Commission 71/03/11 1p

--B101290330 Requests amend to Matl/Byproduct License 29-07056-03, authorizing possession & use of 250 Ci Co-60 in Technical Operations Model 676 exposure device for Industrial radiography
BU, LEN, H C Ebasco Services, Inc (subs of Enserch Corp) 1 2017 71/02/18 1p

--B101290287 Responds to AEC 701221 ltr Picker Corp performs calibr survey meters at Stoughton, MA facility, after instruments are repaired. Clarifies discrepancies re training program & operating & emergency procedures W/Picker Corp 710104 ltr
TENZER, H E Ebasco Services, Inc (subs of Enserch Corp) 1
71/01/20 4pp

--B101290343 Matl/Byproduct License 34-07225-08 for Picker X-Ray Co is amended in its entirety per 681115 application Amend 20 authorizes use & possession of 3,000 Ci Co-60, 100 Ci Ir-192, 200 Ci Tm-170 & 200 Ci Yb-169 in sealed sources
MALARD, J C Atomic Energy Commission 60/12/10 5pp

--B101290349 Matl/Byproduct License 34-07225-13 for Picker Corp authorizing possession & use of 3,000 Ci Co-60, 100 Ci Ir-192, 200 Ci Tm-170 & 200 Ci Yb-169 in sealed sources
MALARD, J C Atomic Energy Commission 69/03/07 5pp

--B101290360 Matl/Byproduct License 34-07225-08 for Picker Corp is amended per 691126 application Amend 24 revises Subitems 9 C, 9 D, 9 E, 9 F & authorizes possession, use, transfer & import of U contained as shielding in exposure devices
MALARD, J C Atomic Energy Commission 69/12/09 7pp

--B101290327 Ack receipt of 701203 addl info submitted in response request Requests license number or authority by which Picker Corp uses byproduct matl for instrument calibr W/a encl AEC licensing guide for radiography
BASSIN, N Atomic Energy Commission 70/12/21 2pp

--B101290290 Responds to AEC 701124 ltr vs application for amend to Byproduct License 31-07056-02 Calibr of survey instruments is performed by Ebasco Matls Engineering Lab, using Technical Operations Model 571 meter calibr kit
TENZER, H E Ebasco Services, Inc (subs of Enserch Corp) 1
70/12/03 10pp

--B101290313 "Procedure for Qualification & Certification of Nondestructive Testing Personnel" Related info encl
* Ebasco Services, Inc (subs of Enserch Corp.) 1 70/06/30 83pp

--B101290246 Requests addl info re 701105 application for amend to License 31-07056-02 Includes info re instrument calibr svcs offered by Picler Industrial & X-Ray Industrial Distributors & revised procedures
BASSIN, N Atomic Energy Commission 70/11/24 3pp.

--B101290298 Confirms 701113 telcon instructing AEC to disregard phrase in manual for operating & emergency procedures for isotope radiography. Phraseology is for internal purposes & does not apply to AEC
TENZER, B E Ebasco Services, Inc (subs of Enserch Corp) 70/11/13 1p

--B101290304 Forwards application for amend to Matl/Byproduct License 31-0056-02 due to transfer of all nondestructive testing equipment to new facility
TENZER, B E Ebasco Services, Inc (subs of Enserch Corp) 70/11/06 1p

--B101290335 Application for amend to Matl/Byproduct License 31-07056-02, authorizing use & possession of 100 Ci Ir-192 & 200 Ci Co-60 in Technical Operations exposure devices for industrial radiography, source changers & storage containers
TENZER, B E Ebasco Services, Inc (subs of Enserch Corp) 70/11/03 10pp

--B101290317 Revision 1 of manual for operating & emergency procedures for isotope radiography Related info encl
* Ebasco Services, Inc (subs of Enserch Corp) 18616 70/11/30 8pp

B101290061 FOIA request for records re investigations, audits or regulatory proceedings involving Enserch Corp & subsidiaries or affiliates & all correspondence within past 10 yrs
SCHIFF, R F Washington Service Bureau, Inc 80/12/30 1p 07573 294

GEN TEC 19 OENERIC TECHNICAL ISSUES

B101050178 Forwards nonproprietary version of Burns & Roe, Inc repl. "Analytical Model for LOCA Water Jet in Mark II Containment (Ring Vortex Model)," provided on behalf of Mark II Owners group as part of Mark II containment program
BUCIMOLZ, R H General Electric Co HFN-108-80 80/12/11 1p 07376 008

--B101050107 Nonproprietary version of rept. "Analytical Model for LOCA Water Jet in Mark II Containments (Ring Vortex Model)"
CHU, C K, LEE, T Burns & Roe Co 80/09/30 116pp 07376:049

B101210322 Forwards Draft 2 of proposed Reg Guide GC 709-A, "Ultrasonic Testing of Reactor Vessel Welds During Preservice & Inservice Insp."
ARLOTTO, O A Division of Engineering Standards 81/01/02 39pp 07308 001

B101290632 "ASYMMETRIC BLOWDOWN LOADS ON PWR PRIMARY SYSTEMS," RESOLUTION OF OENERIC TASK ACTION PLAN A-2
HOBFORD, S O, MATTU, R, MEYER, R O Division of Safety Technology 81/01/31 81pp Available at NTIS \$4.00 07574 001

B101290684 Forwards NURE0-0609, "Asymmetric Blowdown Loads on PWR Primary Sys.," providing NRC resolution of Unresolved Safety Issue Task A-2 Rept covers development of loading transients & structural analysis criteria. W/O encl
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/03 1p 07576 145

B101290694 Forwards NURE0-0609, "Asymmetric Blowdown Loads on PWR Primary Sys.," providing NRC resolution of Unresolved Safety Issue Task A-2 Rept covers development of loading transients & structural analysis criteria. W/O encl
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/03 1p 07574 192

B101290710 Forwards NURE0-0609, "Asymmetric Blowdown Loads on PWR Primary Sys.," providing NRC resolution of Unresolved Safety Issue Task A-2 Rept covers development of loading transients & structural analysis criteria. W/O encl
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/03 1p 07574 244

B101300015 Forwards NURE0-0609, "Asymmetric Blowdown Loads on PWR Primary Sys.," providing NRC resolution of Unresolved Safety Issue Task A-2 Rept covers development of loading transients & structural analysis criteria. W/O encl
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/03 1p 07579 317

13E INSPECTION AND ENFORCEMENT

B002200570 IE Info Notice 80-17, "Potential Hazards Associated With Interchangeable Parts on Radiographic Equipment"
* Office of Inspection & Enforcement, Office of the Director 80/05/03 1p 05118 200

0005050346 IE Info Notice 80-25, "Transportation of Pyrophoric U"
* Office of Inspection & Enforcement, Office of the Director 80/05/30 3pp 03755 240

B006190050 IE Bulletin 80-22, "Automation Industries Model 200-52 Sealed Source Connectors" IE Circular 79-16, "Excessive Radiation Exposures to Members of General Public & Radiographer" & hood & eye drawing encl
* Office of Inspection & Enforcement, Office of the Director 80/09/31 2pp 06810 117

B008220279 IE Info Notice 80-13, "Failures of the Lanthanum Water Level Monitor for the Scram Discharge Valve at Dresden Unit 2"
* Office of Inspection & Enforcement, Office of the Director 80/12/03 2pp 07374 020

B011040252 IE Bulletin 80-17 Supp 1 "Failure of Control Rods to Drop During a Scram at BWR"
* Director's Office, Office of Inspection and Enforcement 80/12/18 4pp

B012160001 IE Info Notice 80-44, "Activation of ECCS in the Recirculation Mode While in Hot Shutdown"
* Office of Inspection & Enforcement, Office of the Director 80/12/16 2pp 07374 280

B012160002 IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Stop Capability"
* Office of Inspection & Enforcement, Office of the Director 80/12/17 2pp 07374 283

B012310266 PND-1-80-177 on B01222, "Crack in Valve of Fire Sprinkler System" that stop work order had been issued on Category 1 Corl
Order resulted from discovery that incoming drawings had not been processed by document control since 001105
OEA, C A B Region 4, Dallas, Office of the Director 80/12/23 2pp

B101050539 PND-1-80-178 on B01222, "Crack in Valve of Fire Sprinkler System" that stop work order had been issued on Category 1 Corl
Order resulted from discovery that incoming drawings had not been processed by document control since 001105
OEA, C A B Region 4, Dallas, Office of the Director 80/12/23 2pp

B101090192 PND-1V-81-01 on B10102, "Crack in Valve of Fire Sprinkler System" that stop work order had been issued on Category 1 Corl
Order resulted from discovery that incoming drawings had not been processed by document control since 001105
OEA, C A B Region 4, Dallas, Office of the Director 81/01/03 1p

B101090204 PND-1V-80-41 on B01230, "Crack in Valve of Fire Sprinkler System" that stop work order had been issued on Category 1 Corl
Order resulted from discovery that incoming drawings had not been processed by document control since 001105
OEA, C A B Region 4, Dallas, Office of the Director 80/12/23 2pp

B101090224 PND-1-80-181 on B01229, "Crack in Valve of Fire Sprinkler System" that stop work order had been issued on Category 1 Corl
Order resulted from discovery that incoming drawings had not been processed by document control since 001105
OEA, C A B Region 4, Dallas, Office of the Director 80/12/23 2pp

B101090241 PND-1-80-180: Unit 1 outage has been extended until 81/01/11 Outage caused by B01224 discovery of failed main turbine thrust bearing during initial Cycle 5 startup
MCCABE, E C Region 1, Philadelphia, Office of the Director 80/12/29 1p

B101190554 PNA-80-029A on B01203, "State of AR notified Nuclear Diagnostic Labs that license had been revoked Caused by failure to respond to state B01024 enforcement ltr Updates & closes-out PNA-80-029 issued on B00022
LUBENAU, J O, BOLLING, A Office of State Programs, Director 80/12/18 1p 07475 338

8101200127 PWD-TM1-B1-01 on 810112, water samples from onsite well 2 contained trace quantities of Cs-137 & Cs-134. Subsequent samples on 810106, 15 & 1903 indicated concentrations at less than lower limit of detection. Item to be reviewed 810115
SHAWBANK, M. TMI Program Office 81/01/13 3pp

8101200374 PWD-B1-01-05 on 810112, roughly sample of auxiliary cooler condensate return identified 10-5 uCi/ml activity, primarily Cs-134 & Cs-137. Monitor should have detected activity but isolation valve found closed in sample line
PULLEN, K. KISTLER, H. H. Region 1, Philadelphia, Office of the Director 81/01/13 2pp

8101200560 PWD-B1-01-06 on 810115, high airborne radioactivity was identified on refueling floor of reactor bldg. Caused by the workers cleaning area around head of reactor while refueling floor whole body counts indicated 20 & 200 MPC-hrs
WHLIZ, R. Region 1, Philadelphia, Office of the Director 81/01/15 2pp

8101200403 PWD-IV-80-340 by 810108 ltr. util requested Region 4 authority for limited restart of placement of complex concrete. Limited resumption of complex concrete placement authorized
JUBACEK, W. D. Region 4, Dallas, Office of the Director 81/01/13 1p

8101200416 PWD-B1-01-04 on 810111, during sampling of vent control tank inadvertent gaseous release occurred resulting in 62.2 Ci noble gas being released over period of 131 minutes. No personnel exposures involved. Media interest expected
WHLIZ, R. Region 1, Philadelphia, Office of the Director 81/01/12 2pp

8101200426 PWD-B1-01-02 on 810107, during startup for restart, event occurred which resulted in introduction of reactor coolant into nitrogen gas supply sys. Caused by two open valves in nitrogen supply line to RCS Valves left open during maint
AELHIO, R. Region 1, Philadelphia, Office of the Director 81/01/09 2pp

8101200507 PWD-TM1-B1-03A on 810118, operational & testing activities temporarily terminated due to small leak in makeup sys piping discovered on 810117 RCS decommissioned to 45 psig & being held in that condition
HAEVERMAN, D. R. TMI Program Office 81/01/19 2pp

8101200513 PWD-B1-01-012 Ion Track Instruments, Inc. License 20-15525-02E, distributes explosive detection devices exempt from NRC licensing which are suspected of leaking Ni-63. Special insp will be conducted to determine cause
JERMAN, P. C. MINNEAPOLIS, J. D. Region 1, Philadelphia, Office of the Director 81/01/22 1p 07557 050

8101200519 PWD-TM1-B1-02 on 810113, estimated 600 gallons of concentrated sulfuric acid siphoned from storage tank, through two valves, & out of 2-inch flange pipe. Valves inadvertently opened or left open by maint
BARLEY, W. L. SHAWBANK, L. TMI Program Office 81/01/14 2pp

8101200524 PWD-TM1-B1-03 on 810116, licensee commenced planned activities to raise reactor coolant pressure & temp from 0 psig, 121 F to approx 340 psig & max 195 F. Activities expected to last approx one wk
REKITU, L. W. BARRETT, L. TMI Program Office 01/01/16 2pp

8101200655 PWD-IV-B1-04 State of OK notified that individual in Okmulgee, OK, hosp suffering from serious radiation injuries to chest & left forearm. Individual had recently worked for Houston Insp in State of NM
BROOK, C. D. Region 4, Dallas, Office of the Director 81/01/23 2pp 07566 347

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

810140056 Delegates D Reiff as acting chief of Mechanical Engineering Research Branch from 801224 - 810102
RICHARDSCH, J. E. Mechanical Engineering Branch 80/12/24 1p 07461 226

810140061 Supports JE Richardson for membership on Affirmative Action Advisory Committee
SERPAN, C. Z. Assistant Director for General Reactor Safety Research 80/12/22 1p 07461 227

810150579 Forwards memorandum of understanding between Ofc of Nuclear Reactor Regulation & IE re regionalization of operator licensing program & final implementation schedule.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/12/23 1p 07464 266

810150583 Memorandum of understanding between Ofc of Nuclear Reactor Regulation & IE re regionalization of operator licensing program
STELLO, V. Office of Inspection & Enforcement, Office of the Director 80/12/11 10pp 07464 267

810150576 Low Level Radwaste Modeling Needs from NRC Perspective
SMITH, R. D. HANNA, S. E. F. Low Level Waste Licensing Branch 80/12/22 3pp 07464 134

8101505725 Nuclear Reactor Regulation Ofc Letter 19, Revision 1, forwarding revised procedures for notifying licensing boards of relevant new info
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/12/09 6pp 07308 001

8101505737 Ack receipt of 801203 ltr requesting meeting w/NRC to re info re isoline platoon Meeting w/RW Houston in second or third wk of Jan 1981 would be appropriate
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/12/24 1p 07463 179

810120267 Summary of 001209 meeting w/Paul-Honroe Hydraulics, Inc. Bethesda, MD re hydraulic snubbers & inservice insp/test in place capability
ENGLE, L. D. Operating Reactors Branch 3, 81/01/06 6pp 07309

8101200074 NRC-AIG-003
"Financial Implications of Retrospective Premium Assessments on Electric Utilities - Related info incl
Commissioners MELCHER, R. W. Colorado, Univ. of Denver 76/09/30 37pp Available at HTIS 94.C0 07556 346

8101200348 Responds to 801201 request for info on nuclear plant locations, waste dumps & safe distances from nuclear plants. Excerpts from 1979 annual rept & from rept of President's Commission on Mill incl in response to inquiries
ZELCH, G. Technical Support Branch 81/01/06 26pp 07571 325

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

8012050440 Comments on 00 Eisenhower ltr to licensees re Section 11.1 "Performance Testing of SWR & PWR Relief & Safety Valves". Present program does not provide for testing of PWR valves under A-TS conditions or include tests of block valves
LEVENSOW, R. Electric Power Research Institute 80/11/26 1p 07171 346

8012310226 Forwards Ofc of Nuclear Regulatory Research 800711.22.20 29 needs referred to in NUREG-0735, "Plan for Developing Safety Goal - Mett should be included in PDR files w/o incl
LARKINS, J. F. Program Coordination Branch 80/12/08 1p 07371 201

8101050052 Forwards Change 1 to "LOFT Sys & Test Description (5 5-Ft Nuclear Core 1 LOCES)", NUREG-CR-0247, TREE-1208 includes addition which contains recently calculated coolant vols of LOFT primary coolant sys
KAWFISH, W. C. EOLG Idaho, Inc. TREE-1208, 80/10/21 2pp 07378 001

--8101050069 NUREG-CR-0247
Change 1 to LOFT SYSTEM & TEST DESCRIPTION (5 5-Ft NUCLEAR CORE 1 LOCES)
* EOLG Idaho, Inc. TREE-1208 80/09/30 250pp 07378 004

8101050111 NUREG-CR-1211
UNCERTAINTY IN CALCULATED SURFACE TEMPERATURE & SURFACE HEAT FLUX OF THERMAL HYDRAULIC TEST FACILITY HEATER REOS
CHLOS, K. W. Union Carbide Corp. FIN 0-0123 00/12/31 60pp 07398 001

8101060449 Forwards comments on NUREG-0731, "Guidelines for Util Mgt & Technical Resources, Sept 1980". Considers that organizational structure should not be prescriptive
WHIELOS, S. H. Public Service Co. of Indiana, Inc. 80/12/23 5pp 07376 204

8101060860 Provides info concerning testing program sponsored by U in BWR owners group to satisfy provisions of NUREG-0578, Section 2.1.2, safety & relief valves test program description & program scope incl
WATERS, D. B. Carolina Power & Light Co. 80/09/17 3pp 07400 1

--8101060860 NUREG-0578 BWR safety relief valve test description
* BWR Owners Group 80/09/17 71pp 07400 318

NONDOCKETED ITEMS

B101080256 NUREG-0384 R1
ASSURING AVAILABILITY OF FUNDS FOR DECOMMISSIONING NUCLEAR
FACILITIES Draft Report Revision 1
KODOR, R S Utility Finance Branch (formerly Antitrust & Indemnity)
7/7/12/31 57pp 07420 027

B101090445 NUREG/CR-1274
FLAW PREPARATIONS FOR HST PROGRAM VESSEL FRACTURE
MECHANICS TESTING MECHANICAL-CYCLOC PUMPING & ELECTROCYCLE
WELD-HYDROGEN CHARGE CRACKING SCHEMES
HCLZ, P P Oak Ridge National Laboratory FIN D-0119
ORNL/NUREG/TH-3 80/05/31 18pp 07424 253

B101090487 Forwards "NRC Owners Group Evaluation of NUREG-0737, Item
11 K 3 138 Reactor Core Isolation Cooling Sys Automatic
Reset"
WATERS, D B BWR Owners Group NUREG-80-12 80/12/29 1p
07440 226

--B101090453 "NRC Owners Group Evaluation of NUREG-0737, Item 11 K 3 138
Reactor Core Isolation Cooling Sys Automatic Reset"
* BWR Owners Group 80/12/29 97pp 07440 227

B101090951 NUREG/CR-1774
HIGH-TEMPERATURE GAS-COOLED REACTOR SAFETY STUDIES FOR THE
DIVISION OF REACTOR SAFETY RESEARCH, QUARTERLY PROGRESS
REPORT, APRIL 1 - JUNE 30, 1980
BALL, S J, CLEVELAND, C J, CHIKKIN, J C Oak Ridge National
Laboratory FIN D-0122 ORNL/NUREG/TH-4 80/12/31 14pp
Available at NTIS 07430 213

B101090962 NUREG/CR-1020
EDDY-CURRENT INSPECTION FOR STEAM GENERATOR TUBING PROGRAM,
QUARTERLY PROGRESS REPORT FOR PERIOD ENDING MARCH 31, 1980
DODD, C V, DEEDS, W E, MCCLUNG, R W Oak Ridge National Laboratory
FIN D-0417 ORNL/NUREG/TH-4 80/12/31 13pp Available at NTIS
07430 146

B101090969 NUREG/CR-1029
EDDY-CURRENT INSPECTION FOR STEAM GENERATOR TUBING PROGRAM,
QUARTERLY PROGRESS REPORT FOR PERIOD ENDING JUNE 30, 1980
DODD, C V, DEEDS, W E, MCCLUNG, R W Oak Ridge National Laboratory
FIN D-0417 ORNL/NUREG/TH-4 80/12/31 10pp Available at NTIS
07430 138

B101100120 NUREG-0525 R3
SAFEGUARDS SUMMARY EVENT LIST (GSEL) REVISION 3
DAVIDSON, J J, MACMURDY, P H Office of Nuclear Material Safety &
Safeguards 80/12/31 166pp Available at NTIS 07434 206

B101100714 Ack receipt of comments re NUREG/CR-1021, "Final Rept -
Phase 1 Sys Interaction Methodology Applications Program"
BCHREDEH, F Assistant Director for Generic Projects 80/12/24
2pp 07445 123

B101100808 NUREG/CR-1017
COMPARISON OF COMPARE MOO-1 SUBCOMPARTMENT CALCULATIONS
W/DADELLE-FRAHAFURT D-SERIES TEST RESULTS
DOLSTAD, J H, O'DO, R O, OREGORY, W R Los Alamos Scientific
Laboratory FIN A-7111 LA-8615-MS 80/12/12 55pp Available at
NTIS 07441 223

B101100857 NUREG/CR-1241
LWR PRESSURE VESSEL IRRADIATION SURVEILLANCE OBSERVATION,
QUARTERLY PROGRESS REPORT, JANUARY-MARCH 1980 Volume 1
OUTINIE, O L, MCCLROY, W H Hanford Engineering Development
Laboratory FIN D-3988-7 HEDL-IPE 00-4 80/12/31 71pp
Available at NTIS 07431 256

B101120049 Comments on NUREG-0735 re NRC plan for developing safety
goal Endorses concept Goal should focus on providing
adequate level of protection to public relative to benefit
derived from plant-electrical power production
SHERWOOD, O O General Electric Co. MFH-204-00 80/11/26 2pp
07307 001

B101120053 Responds to request for comments on list of topics being
considered in development of safety goal for nuclear power
plants Many individuals exhibit fairly extreme risk aversion
to low probability-high consequence events
BUEHRHARD, W A Argonne National Laboratory 80/11/21 2pp
07447 083

B101120359 NUREG/CR-0015
REVIEW GROUP CONFERENCE ON ADVANCED INSTRUMENTATION
RESEARCH FOR REACTOR SAFETY Proceedings of NRC Conference
at ORNL July 29-31, 1980
HARRIS, A L, SANDERSON, D J, HARRIS, V V Division of Reactor Safety Research

B101130074 NUREG-0383 V2 R3
DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE
MATERIALS PACKAGES Certificates of Compliance, Volume 2,
Revision 3
* Division of Fuel Cycle & Material Safety 80/12/31 60p
07450 001

B101130080 NUREG-0383 V3
DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE
MATERIALS PACKAGES Summary Report of NRC Approved Quality
Assurance Programs for Radioactive Material Packages
Volume 3
* Division of Fuel Cycle & Material Safety 80/12/31 11p
07309 001

B101130311 NUREG-0383 V1 R3
DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE
MATERIALS PACKAGES Summary Report of NRC Approved Packages
Volume 1, Revision 3
* Division of Fuel Cycle & Material Safety 80/12/31 25p
07452 102

B101130317 Comments on NUREG-0577, "Potential for Low Fracture
Toughness & Laminar Tearing on PWR Steam Generator &
Reactor Coolant Supports." Used guidance stress corrosion
acceptance criterion should be eliminated
CRIDLEY, R L General Electric Co MFH-219-00 80/12/30
07437 278

B101130402 NUREG-0747
DESCRIPTION OF CURRENT & PLANNED RESEARCH IN STRUCTURAL
ENGINEERING
BAGCHI, O Division of Reactor Safety Research 80/12/31
Available at NRC \$3.75 07451 253

B101130408 NUREG/CR-1024
ASSESSMENT OF FRAGMENTATION OF CALCULATED FISSION GAS
RELEASE IN RISO FUEL RODS
CHAMBERS, R, LAATS, E T EG&G Idaho, Inc FIN A-6167
EGG-CAAP-5219 80/12/31 21pp 07454 243

B101130414 NUREG/CR-1023
DESCRIPTION & CHARACTERIZATION OF EVALUATION MODELS IN
FRACCON-1
LAATS, E T, CHAMBERS, R EG&G Idaho, Inc FIN A-6167
EGG-CAAP-5217 80/12/31 45pp 07454 202

B101130603 Forwards draft guidelines, "Draft Emergency Action
Guidelines for Nuclear Power Plants," for interim use
DELTON, H R Office of Nuclear Reactor Regulation, Director
7/7/09/19 1p 07454 182

--B101130689 NUREG-0610
DRAFT EMERGENCY ACTION LEVEL GUIDELINES FOR NUCLEAR POWER
PLANTS
* Office of Nuclear Reactor Regulation, Director 7/7/09/19
19pp 07454 103

B101140539 NUREG/CR-1171
THE EFFECT OF CRACK LENGTH AND SIDE GROOVES ON THE DUCTILE
FRACTURE TOUGHNESS PROPERTIES OF ASTM A533 STEEL
CARLSON, K W, WILLIAMS, J A Hanford Engineering Development
Laboratory FIN D-0119 HEDL-THE 79-65 80/01/31 71pp
Available at NTIS 07157 252

B101140544 NUREG-0633
FUEL PERFORMANCE ANNUAL REPORT Period Through December 1970
MOURICAN, M O Division of Systems Safety 7/7/12/31 30pp
Available at NTIS 07457 221

B101140550 NUREG-0623
GENERIC ASSESSMENT OF DELAYED REACTOR COOLANT PUMP TRIP
DURING SMALL BREAK LOSS-OF-COOLANT ACCIDENTS IN PRESSURIZED
WATER REACTORS
SHERWOOD, O O Bulletin & Orders 7/7/11/30 79pp Available
at NTIS 07457 145

B101140716 Forwards NUREG-0090, Vol 3, Number 2, "Rept to Congress
ADs, Apr-June 1980" Two ADs at operating nuclear power
plants involved loss of decay heat removal & failure of
control rods to fully insert during scan
AHEARN, J F Commissioners 80/12/05 1p 07458 313

--B101140725 Forwards NUREG-0090, Vol 3, Number 2, "Rept to Congress
ADs, Apr-June 1980" Two ADs at operating nuclear power
plants involved loss of decay heat removal & failure of
control rods to fully insert during scan
AHEARN, J F Commissioners 80/12/05 1p 07458 313

-B:01140735 NUREG-0690 V3 N22

REPORT TO CONGRESS ON ANNUAL OCCURRENCES April-June 1983
• Office of Management and Program Analysis PO/11/30 38pp
Available at NTIS 07458 315

8101140723 NUREG/CR-1169

SAFEGUARD VULNERABILITY ANALYSIS PROGRAM (SVA) Executive
Summary
OTTMAN, F. M., OTTMAN, R. M. H., BRVIL, N. J. Lawrence Livermore
Laboratory FIN A-0115 OURL-52724 00/04/30 34pp Available at
NTIS 07457 113

8101150337 NUREG/CR-1811

NUCLEAR REACTOR SAFETY Quarterly Progress Report for
April-June 1983
STEVENSON, M. G., VIOILL, J. C. Los Alamos Scientific Laboratory FIN
A-7014 LA-8507-PR 00/11/30 72pp Available at NTIS
07463 290

8101150801 NUREG/CR-1174

A STUDY TO DETERMINE THE FEASIBILITY OF CONDUCTING
EPIDEMIOLOGIC INVESTIGATIONS OF THE HEALTH EFFECTS OF
LOW LEVEL IONIZING RADIATION Phase I Report
BREYER, A. A., CLAPP, N. W., COVINO, S. J. Equifax Health Systems Div
FIN B-1090-9 RM-901-9 80/05/31 132pp. Available at NTIS
07464 005

8101190513 Comments on NUREG-0668 re NRC review of Hertzberg rept NRC
assessment on biological absorption of radionuclides is
narrow in scope & does not account for meteorological
conditions suggests use of plant-specific analysis method
ROBERTS, T. H. Affiliation Unknown 80/12/30 7pp 07475 069

8101190520 NUREG/CR-1045

ACUTE EFFECTS OF INHALATION EXPOSURE TO URANIC HEXAFLUORIDE
& PATTERNS OF DEPOSITION Corrected Pages 29 & 31
• Rochester Univ. of 00/12/30 3pp 07473 026

8101210219 Comments on NUREG-0518 re possession, use & transfer of low
enriched U as contaminant in retail Opposes NUREG
SHIVELY, R. P., SHIVELY, V. M. Affiliation Unknown. 45FR70874 1394
80/12/08 1p 07487 252

8101210271 NUREG/CR-1794 V3

SUMMARY OF ACTIVITIES & ACCOMPLISHMENTS AUGUST 1 TO
OCTOBER 31, 1979 A PROPOSAL TO DEVELOP A METHOD FOR THE
DETECTION OF HELIUM EMPLOYING CHEMILUMINESCENCE REACTIONS
Progress Report, Volume 3
NEARY, M. P. Los Alamos Scientific Laboratory FIN A-7210
LA-0599-PR 00/11/30 12pp Available at NTIS 07490 072

8101210278 NUREG/CR-1787

EXPERIMENTAL & STATISTICAL INVESTIGATION OF THERMALLY
INDUCED FAILURE IN REACTOR FUEL PARTICLES
LUNFORD, J. L., IMPRESCHIA, R. J., BOHMAN, A. L. Los Alamos Scientific
Laboratory FIN A-7014 LA-0547-MS 80/10/31 26pp Available at
NTIS 07490 091

8101210285 NUREG-0530 V3 N06

ADVANCED REACTOR SAFETY RESEARCH Status Summary Report Data
as of November 30, 1979 Volume 3 (Buff Book)
• Office of Nuclear Regulatory Research, Director 79/11/30 77pp.
Available at NTIS.

8101210597 Response to FOIA request for final version of generic EIS
re U milling, NUREG-0705 Forwards documents listed in App A
N/O encl
FELTON, J. M. Division of Rules and Records 81/01/13 2pp
07487 131

8101220249 PNL-2950

"Valuing Environ Via Bidding Games Psychological
Perspective." Interim reprint, excerpt from NUREG/CR-0989, Vol 2.
App B
NEDEERT, J. A., SHUKTAR, R., PERRY, R. W. Battelle Memorial Institute,
Pacific Northwest Laboratory PNL-2950 80/08/31 50pp
07503 200

8101220501 NUREG/CR-1240 V4

LIGHT WATER REACTOR PRESSURE VESSEL IRRADIATION SURVEILLANCE
DOSIMETRY Quarterly Progress Report October-December 1979
Volume 4
SUIPRIE, O. L., MCLEROY, W. N. Hanford Engineering Development
Laboratory FIN B-5988-7 MED-TME 80-3 80/12/31 80pp
Available at NTIS 07500 323

8101220603 NUREG/CR-1240 V3

LIGHT WATER REACTOR PRESSURE VESSEL IRRADIATION SURVEILLANCE
DOSIMETRY Quarterly Progress Report, July-September 1979.
Volume 3
SUIPRIE, O. L., MCLEROY, W. N. Hanford Engineering Development
Laboratory FIN B-5988-7 MED-TME 80-2 80/12/31 86pp.
Available at NTIS 07497 316

8101220619 NUREG-0540 V2 N09

TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE
1-30, 1980 Volume 2, Number 9
• Office of Administration 80/12/31 485pp
07309 001

8101220647 Transcript of Commission 810115 meeting

re action plan items due Jan 1981 Pp 1-47
• Commissioners 81/01/15 49pp 07502 143

8101230658 Transcript of Commission 810115 meeting

status of SRP Pp 1-38
• Commissioners 81/01/15 41pp 07512 296

8101260079 NUREG-0669 V3

FIXED SITE PHYSICAL PROTECTION UPON ADOPTION OF THE
COMMISSION Volume 3
EVANS, L. J., ALLEN, T. Regulatory Improvements Branch
450pp Available at NTIS 07519 030

8101260114 NUREG/CR-1614

APPROACHES TO ACCEPTABLE RISK A CRITICAL GUIDE
FISCHOFF, B., LICHTENSTEIN, S., SLOVIC, P. Decision
B-0424 ORNL/SUO-7656/1 00/12/31 736pp 0752

8101260127 NUREG/CR-1398

EVALUATION OF TECHNIQUES FOR DYNAMIC MEASUREMENT
MODTIN IN LIQUID-METAL-COOLED FAST-BREEDER REACTOR
EXPERIMENTS
EVANS, A. F. Los Alamos Scientific Laboratory FIN
80/10/31 67pp

8101260136 NUREG/CR-1070

AN EVALUATION OF THE UNLOADING COMPLIANCE PROCEDURE
INTEGRAL TESTING IN THE HOT CELL Final Report
CLARKE, O. A. Westinghouse Electric Corp FIN 0-01
ORNL/SUO-7594/1 79/10/31 71pp 07523 157

8101260144 NUREG/CR-1717 V4

SOIL-STRUCTURE INTERACTION METHODS SLAM CODE Volume
CONSTANTINO, C., MILLER, C. A. Brookhaven National Lab
A-3216-9 ORNL-NUREG-51263 79/09/30 150pp 07

8101260163 NUREG/CR-1717 V3

SOIL-STRUCTURE INTERACTION METHODS SIM CODE Volume
MILLER, C. A., CONSTANTINO, C. Brookhaven National Lab
A-3216-9 ORNL-NUREG-51263 79/09/30 98pp. 075

8101270301 NUREG-0030 V3 N03

CONSTRUCTION STATUS REPORT, NUCLEAR POWER PLANTS
August 31, 1980 For Period May 1, 1980 - August 31, 1980
(Yellow Book) Volume 3, Number 3
• Commissioners 80/12/31 156pp. Available at

8101270131 NUREG/CR-1645

THE PARADOXES OF COOLANT ACCIDENT ANALYSIS CAPABILITY
WRAP-FM SYSTEM
GREEDRY, M. V., DERANEK, F. Savannah River Ecology Lab
B-4126-8 OPRG-LURED-80-1 80/08/31 47pp. 075

8101270583 Forwards Page 7 for NUREG/CR-0773, "Train

Personnel for Performing Measurements for Control
Accounting of SNM."
• Division of Technical Information & Document Co
1p 07543 359

--8101270589 NUREG/CR-0773 ERR

ERRATA (PAGE 71 for NUREG/CR-0773, "TRAINING AND
PERSONNEL FOR PERFORMING MEASUREMENTS FOR CONTROL
ACCOUNTING OF SPECIAL NUCLEAR MATERIAL."
• Battelle Memorial Institute, Pacific Northwest
80/12/30 1p. 07543 360

8101270602 NUREG/CR-1806

HEAVY-SECTION STEEL TECHNOLOGY PROGRAM QUARTERLY P
REPORT FOR JULY-SEPTEMBER 1980
WHITMAN, O. D., BRYAN, R. H. Oak Ridge National Labor
ORNL/NUREG/TM-4 80/12/31 70pp. Available at

8101270810 NUREG-0540 V2 N10

TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE
October 1-31, 1980 Volume 2, Number 10
• Office of Administration 81/01/31 481pp
07183 001

8101270818 NUREG/BR-0007

INSTRUCTIONS FOR COMPLETING MATERIAL BALANCE REPORT
PHYSICAL INVENTORY LISTING & CONCISE NOTE FORMS (P
NRC-712, 742C & 740M).
• Office of Nuclear Material Safety & Safeguards.
07542 103

8101270027 NUREO/CR-1738
"AN ADVANCED THERMOHYDRAULIC SIMULATION CODE FOR POST-TYPE
LMBRBS ISSC-P CODE"
MAONI, I K. Brookhaven National Laboratory. FIN A-3015
BNL-NUREG-51280. 80/09/30 105pp Available at NTIS

8101270038 NUREO/CR-1510
CONTAMINATION CONTROL IN SANDIA EQUATION-OF-STATE
EXPERIMENTS
BREITUNG, W H. Sandia Laboratories. FIN A-1016 SAN880-1277
80/10/31 112pp Available at NTIS. 07546 105

0101270861 NUREO/CR-1157 V3
THERMAL/HYDRAULIC ANALYSIS RESEARCH PROGRAM QUARTERLY
REPORT, JULY-SEPTEMBER 1980 Volume 3
THOMPSON, B L. Sandia Laboratories. FIN A-1209 SAN880-1091
80/00/31 116pp Available at NTIS. 07541 140

8101270867 NUREO-0380 V4 N03
PROGRAM SUMMARY REPORT Volume 4 Number 3
• Office of Management and Program Analysis. 80/03/21 94pp
Available at NTIS. 07542 281

8101270943 NUREO/CR-1018
FUEL PERFORMANCE ANNUAL REPORT FOR 1979
TOKAR, M. Core Performance Branch. BAILEY, W J., CUNNINGHAM, M E.
Battelle Memorial Institute, Pacific Northwest Laboratory. FIN
B-2320 PNL-3583 01/01/31 45pp Available at NTIS. \$2.90
07542 239

8101280187 Documents 010114 telcon clarifying NUREO-0737 items
11 K 3 24 & 11 K 3 29 Loss of alternating current power is
intended to mean only loss of offsite power for both items
& failure of onsite emergency power need not be assumed
WATERS, B D. BWR Owners Group. BNRO0 8114 81/01/23 1p
07558 051.

8101290008 Discusses review of NUREO-0731 to evaluate regulation bases
for approved IMI action plan items. Categorization to cover
wide variation outlined w/o encl recommended procedure for
addl items & categorization tables.
SCINTO, J V. Hearings Division. 81/01/16 4pp 07567 106

8101290024 Forwards comments on NUREO-0660 re NRC action plan developed
as result of IMI-2 accident. Plan should require inserting of
BWR Mark III & PWR 1cc containment
BATES, A. The Nuclear Regulatory Commission. 45FR50613 C04
00/12/09. 2pp. 07568 337.

8101290062 Forwards addendum to SAN000-0701, "Assessment of Core
Penetration of PWR Reactor Vessel & Particulate Oebriis
Coolability in TMLB", S20 & ABC Accidents."
LIPINSKI, R J. Sandia Laboratories. 80/11/10. 1p 07309 001

--8101290066 NUREO/CR-1510 A00
ASSESSMENT OF CORE PENETRATION OF PWR REACTOR VESSEL &
PARTICULATE OEBRIIS COOLABILITY IN TMLB, S20 & ABC
ACCIDENTS Addendum
• Sandia Laboratories. SAN080-0701 80/11/10 3pp 07309 001

8101290180 NUREO/CR-1132
A SURVEY OF POTENTIAL LIGHT WATER REACTOR FUEL ROD FAILURE
MECHANISMS & OMAOE LIMITS
COURTRIGHT, E L. Battelle Memorial Institute, Pacific Northwest
Laboratory. FIN B-2150 PNL-2787 79/07/31 48pp. Available at
NTIS. 07575 322

8101290465 Informs of three errors in NUREO/CR-1746, "Steam Explosion
Efficiency Studies."
CORRAOINI, M L. Sandia Laboratories. SAN080-1324 81/01/19 3pp
07568 337

8101290509 Staff requirements memo re 810115 briefing on SRP revisions
due in Apr 1981. No requests or requirements forwarded
CHILK, S J. Office of the Secretary of the Commission. M810115B
81/01/16. 1p 07568 353

8101290632 "ASYMMETRIC BLOWDOWN LOADS ON PWR PRIMARY SYSTEMS."
RESOLUTION OF GENERIC TASK ACTION PLAN A-2.
HOBFORD, S B., MATTU, R., MEYER, R D. Division of Safety Technology
81/01/31 81pp. Available at NTIS. \$4.00 07574 001

8101290684 Forwards NUREO-0609, "Asymmetric Blowdown Loads on PWR
Primary Sys.," providing NRC resolution of Unresolved Safety
Issue Task A-2. Rept covers development of loading transients
& structural analysis criteria w/o encl.
BENTON, H R. Office of Nuclear Reactor Regulation, Director
81/01/05. 1p. 07576 145

8101290692 NUREG/CR-1842
REACTIVITY INITIATED ACCIDENT TEST SERIES. TEST R1A 1-2
FUEL BEHAVIOR REPORT
COCH, S A., FUKUDA, S K., MARTINSON, Z R. Idaho National Engineering
Laboratory. FIN A-6041 EG2-2073 81/01/31 56pp Available
NTIS. 07574 302

8101290694 Forwards NUREO-0609, "Asymmetric Blowdown Loads on PWR
Primary Sys.," providing NRC resolution of Unresolved Safety
Issue Task A-2. Rept covers development of loading transients
& structural analysis criteria w/o encl.
BENTON, H R. Office of Nuclear Reactor Regulation, Director
81/01/05. 1p. 07574 192

8101290695 Comments on NUREO-0518 re possession, use & transfer
enriched U as contaminant in metals. Opposes NUREO
JONES, A. Affiliation Unknown. 45FR70074 1947 80/12/08
07183 001

8101290700 NUREO-0403 V3 N01
BWR BODM SYSTEMATIC EVALUATION PROGRAM Status Summary
Report Volume 3, Number 1 Date as of October 1, 1980
RUSSELL, W T. Systematic Evaluation Program Branch. CHUTCHER,
Operating Reactors Branch 5. 80/12/01 66pp Available at
93 75 07567 293.

8101290703 NUREO/CR-1441
EXPERIMENT DATA REPORT FOR SEMISCALE FOD-3 SMALL BREAK TEST
S-07-100 (BABELITE TEST SERIES)
SACKETT, K F., CLEGG, L D. Idaho National Engineering Laboratory
A-6038 EG2-2065 80/12/31 57pp Available at NTIS. 07574 302

8101290706 NUREO/CR-0006
INSTRUCTIONS FOR COMPLETING NUCLEAR MATERIAL TRANSACTION
REPORTS Forms DCE/NRC-741, 741A & 7404
• Office of Nuclear Material Safety & Safeguards. 01/01/01
07574 079

8101290710 Forwards NUREO-0609, "Asymmetric Blowdown Loads on PWR
Primary Sys.," providing NRC resolution of Unresolved Safety
Issue Task A-2. Rept covers development of loading transients
& structural analysis criteria w/o encl.
BENTON, H R. Office of Nuclear Reactor Regulation, Director
01/01/05. 1p. 07574 244

8101290745 NUREO/CR-1907
LMBR ACCIDENT OULINATION STUDY, PHASE I, FINAL REPORT
WILLIAMS, O C., SMELTIS, J A., SCIACCA, F H. Sandia Laboratories
A-1197 SAN280-1267 80/11/30 600pp 07564 076

8101290796 NUREO/CR-1791
LMBR AEROSOL RELEASE & TRANSPORT PROGRAM QUARTERLY
PROGRESS REPORT FOR APRIL-JUNE 1980
KRESS, T D., TODIAS, M L. Oak Ridge National Laboratory. FIN
ORNL/NUREO/TH-4 00/12/31 36pp Available at NTIS. 07560 158

8101290811 NUREO/CR-1790
LMBR AEROSOL RELEASE & TRANSPORT PROGRAM QUARTERLY
PROGRESS REPORT FOR JANUARY-MARCH 1980
KRESS, T D., TODIAS, M L. Oak Ridge National Laboratory. FIN
ORNL/NUREO/TH-4 00/12/31. 37pp Available at NTIS. 07568 158

8101290817 NUREO/CR-1760
ADVANCED TWO-PHASE FLOW INSTRUMENTATION PROGRAM QUARTERLY
PROGRESS REPORT FOR APRIL-JUNE 1980
TURNAGE, X O., DAVIS, C E., ANDERSON, H L. Oak Ridge National
Laboratory. FIN B-0401 ORNL/NUREO/TH-4 80/12/31 27pp
Available at NTIS. 07560 158

8101290819 NUREO/CR-1601
LIGHT-WATER-REACTOR SAFETY RESEARCH PROGRAM Quarterly
Progress Report, April-June 1980
MASSEY, W E., TILL, C E. Argonne National Laboratory. FIN A-2
ANL-80-107 80/10/31 41pp Available at NTIS. 07568 183

0101290825 NUREO/CR-1794 V4
SUMMARY OF ACTIVITIES & ACCOMPLISHMENTS, FINAL REPORT A
PROPOSAL TO DEVELOP A METHOD FOR THE DETECTION OF HELIUM
EMPLYING CHEMILUMINESCENCE REACTIONS. Volume 4
NEARY, M P. Los Alamos Scientific Laboratory. FIN A-7210
LA-8396-PR. 81/01/31 51pp Available at NTIS. 07568 269

8101300009 NUREO-CR-1059
SYSTEMS INTERACTION: STATE-OF-THE-ART REVIEW & METHODS
EVALUATION
LIN, J J., RICE, T R., MCCORD, R K. Lawrence Livermore Laboratory
A-0247 UCRL-53016 81/01/31 134pp Available at NTIS
07579 094

8101300153 NUREG/CR-1071
PARTICLE ANALYSIS OF MIXED-OXIDE NUCLEAR FUEL MATERIALS BY
ENERGY DISPERSIVE X-RAY FLUORESCENCE
EISENHART, R. GUYE, P. B. MACKELL, C. A. Lovelace Biomed & Environmental
Research Institute FIN A-1031 LMF-RC 81/01/31 17pp
Available at NTIS \$1.75 07579 302

8101300209 NUREG/CW-1650
INITIAL QUANTIFICATION OF HUMAN ERRORS ASSOCIATED WITH
REACTOR SAFETY SYSTEM COMPONENTS IN LICENSED NUCLEAR POWER
PLANTS
LUNDAHL, J. E. HALL, K. E. Brookhaven National Laboratory FIN A-7219
BN-4960-01023 81/01/31 42pp Available at NTIS \$2.35
07579 224

8101300217 NUREG/CR-1605
PROGRAM FOR FIELD VALIDATION OF THE SYNTHETIC APERTURE
FOCUSING TECHNIQUE FOR ULTRASONIC TESTING (SAFT UT)
JACKSON, J. I. Southwest Research Institute FIN S-5605 81/01/31
42pp Available at NTIS \$2.35 07579 263

8101300225 NUREG/CR-0912 V1
GEOSCIENTIFIC DATA BASE HANDBOOK FOR RECYCLING A NUCLEAR WASTE
REPROCESSING Volume 1
SHER, GUD, D. Lawrence Livermore Laboratory, FIN A-0277 UCRL-5219
V1 81/01/31 358pp Available at NTIS \$7.50 07581 001

8101300397 NUREG-0400 V4 N01
LICENSEE CONTRACTOR & VENDOR INSPECTION STATUS REPORT
Quarterly Report, March 31, 1980, Volume 4, Number 1
* Office of Inspection & Enforcement Office of the Director
80/03/31 195pp Available at NTIS 07579:244

8101300439 NUREG-0020 V4 N12
OPERATING UNITS STATUS REPORT, LICENSED OPERATING REACTORS
Data as of November 30, 1980 Volume 4, Number 12 (Grey Book)
* Office of Management and Program Analysis 80/12/31 163pp
Available at NTIS \$12.50

8101300768 NUREG/CR-1465
REACTIVITY INITIATED ACCIDENT TEST SERIES TEST RIA 1-1
(RADIAL AVERAGE FUEL ENTHALPY OF 205 CAL/G) FUEL BEHAVIOR
REPORT
SEIFFERT, S. L. MANTINSON, Z. R. FUKUDA, S. K. EG&G Idaho, Inc. FIN
A-6041 EGG-2040 80/09/30 137pp Available at NTIS 07183 001

CRC CORRESPONDENCE WITH OTHER ORGANIZATIONS

8012230207 Summary of 801119 meeting w/Inct of Nuclear Power Operations
in Oathesda, MO info on organizational roles exchanged &
possibility of interface to further efforts in regulation
process discussed
RICHARDSON, S. B. Reactor Systems Branch 80/11/19 4pp 07317 046

8101090516 Informs that IE Bulletin 80-25, "Overcoming Problem w/Target
Rock Safety Relief Valves at OHRs," was sent to listed
licensees on 801219
CARROLL, D. E. Region 3, Chicago, Office of the Director 80/12/19
2pp 07390 261

8101070645 Advises that encl IE Circular 80-25, "Case Histories of
Radiography Events," should be issued on 801205 Draft
transmittal ltr also encl
THORNBURG, H. D. Division of Reactor Construction Inspection
80/11/24 8pp 03897 117

8101090337 Requests analyses of interactions of severe geophysical
events, earthquakes & volcanic eruptions, w/State & local
plans for radiological emergency preparedness around
commercial power plant in region per NRC request
O'CONNELLY, J. H. Federal Emergency Management Agency 80/12/01 1p
07187 001

8101090312 Advises that IE Info Notice 80-17, "Potential Hazards
Associated w/Interchangeable Parts on Radiographic
Equipment," was sent to listed licensees on 800505
PAPPAS, H. Region 3, Chicago, Office of the Director 80/05/06
8pp 07425 254

8101090765 Informs that branch has not commented on NCA-3800 for
several yrs. Changes made to Jul 1980 draft were made w/o NRC
involvement. Suggests discussion of changes w/Reeds, chairman.
Subcommittee III of ASME Boiler & Pressure Vessel Committee
HAASS, W. P. Quality Assurance Branch 80/11/10 1p 07430 354

8012150222 Forwards comments on draft ANSI N45-N551 2. In response to
801114 request Section 11.2 re QA/QC requirements should be
rewritten
HAASS, W. P. Quality Assurance Branch 80/12/01 7pp 03779 329

8101150457 Forwards branch responses to 801028 memo requesting review
of stds re qualification of ASME Code Class 2 & 3 pumps for
safety sys & qualification for turbine drives
MURLEY, T. E. Division of Safety Technology 80/12/17 1p
07462 244

8101150465 Forwards Mechanical Engineering Branch comments on draft
ANSI N45-N551 2 re qualification of ASME Code Class 2 & 3
pumps for safety sys & N551.5 re qualification for turbine
drives. In response to 801114 request
BOSJAR, R. J. Mechanical Engineering Branch 80/12/12 14pp
07462 248

8101160275 Advises that IE Info Notice 80-45, "Potential Failure of
Backup Manual Scram Capability," was sent to listed
licensees on 801217
CARROLL, D. E. Region 3, Chicago, Office of the Director 80/12/18
2pp 07470 275

8101190248 Confirms NRC support for FEMA radiological emergency plan
training program for FY81. In response to 801217 request.
GRIMES, B. H. Emergency Preparedness Program Office (after 801119
18E) 80/12/30 1p 07476 073

8101210634 Forwards Radiological Health Stds Branch Info Rept 9 re
epidemiologic study of civilian employees at Portsmouth
Naval Shipyard for placement in PDR
GELBOM, H. R. Radiological Health Standards Branch 81/01/07 2pp
07488 343

8101210637 Radiological Health Stds Branch Info Rept 9 re epidemiologic
study of civilian employees at Portsmouth Naval Shipyard.
GELBOM, H. R. Radiological Health Standards Branch 81/01/06
2pp 07488 345

8101230472 Forwards permanent measuring point elevation for Well 27
table of water levels reflecting elevation changes since Jul
1980 installation
WATSON, L. R. Interior Dept of Geological Survey 81/01/03 2pp
07510 301

8101270534 Submits list of facilities within US not associated
w/activities w/direct natl security significance to govt of
US
* Commissioners 80/11/26 40pp 07543 308

8101280573 50-80-84
Safety guide, "Site Selection & Evaluation for Nuclear Power
Plants w/Respect to Population Distribution"
* International Atomic Energy Agency (Austria) 80/12/31 32pp
07107 001

PR PROPOSED RULE

8012110279 Comments on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14. Supports rule. Urges NRC to continue to study ways
of reducing low level waste requiring special disposal
AHMAD, H. St. Louis Univ Medical Center St. Louis, MO 45FR67018
17B 80/11/10 1p 07225 302

8012120051 Comments by Intersociety Council for Biology & Medicine on
proposed rule 10CFR20 re disposal of liquid scintillation
media & animal carcasses containing tritium & C-14. Supports
proposal
MCRGAT, T. E. Affiliation Unknown 45FR67018 210 80/11/21 1p
07230 285

8012120057 Comments on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14. Supports proposal. Proposed limits are too low
BUNAKAY, G. A. Southern Illinois Univ., School of Medicine 45FR67
211 80/11/18 1p 07237 259

8012290476 Transcript of 801211 meeting in Washington, DC re UECY-80-
474C Pp 1-32
* Commissioners 80/12/11 34pp 07335 066

--B01229083 SECY-80-474C

Suppl's SECY-80-474 & forwards clarifying changes to 10CFR60
final rule & conforming amendments
01RKS:W J Office of the Executive Director for Operations
80/12/09 16pp 07335 104

B01229089 Transcript of B01211 Affirmation Session 80-54 in
Washington, DC re SECY-80-440, SECY-A-80-169 & SECY-80-482
Pp 1-11
* Commissioners 80/12/11 13pp

B01050637 Comments on repts re waste mgt & waste confidence
rulemaking Biting & design & const of geologic repositories
is relatively simple Demonstration of facts is important
work to be performed
PHILBRICK:G B Philbrick, G B 80/11/06 1p 07387 019

B01070004 Responds to FOIA request for four categories of documents re
cold shutdown w/regard to fire protection requirements in
App R to 10CFR50 Forwards D Davis 790619 memo & P Matthews/
J Knight memo re 790220 review group meeting
FELTON:J M Division of Rules and Records 80/12/30 1p
07414 187

B01070026 Responds to FOIA request for all documents discussing or
identifying alternatives to fire protection requirements of
App R to 10CFR50 Documents are available in FDR
FELTON:J M Division of Rules and Records 80/12/31 1p
07414 189

B01070020 FOIA request for all documents discussing or identifying
alternatives to fire protection requirements of App R to
10CFR50
WATKINS:M Debevoise & Liberman 80/12/12 2pp 07414 190

B01070172 Comments on behalf of Kerr-McGee Nuclear Corp., United Nuclear
Corp., United Nuclear Homestake Partners, Union Carbide Corp.,
Anaconda Copper Co., Gulf Oil Corp. & Western Nuclear, Inc. on
proposed rule 10CFR20 re U mill activities Opposes rule
NICKLES:J J MONTAGNE, C H Covington & Burling 45FR26072 006
80/10/28 1pp 07411 093

--B01070178 Memorandum in support of motion for partial summary
judgment re U milling Summary judgment should be granted
CROUT:O S United Nuclear - Homestake Partners BLACK:J D
Kerr-McGee Nuclear Corp. CROUT:O S Bigbee, Stephenson, Carpenter,
Crout & Binstead CIV 80-0203C 80/07/17 11pp 07411 140

--B01070186 Statement of nat'l facts as to which there is no genuine
issue Exhibits A-1 encl
CROUT:O S United Nuclear - Homestake Partners BLACK:J D
Kerr-McGee Nuclear Corp. CROUT:O S Bigbee, Stephenson, Carpenter,
Crout & Binstead CIV 80-0203C 80/07/17 100pp 07411 181

B01070230 Comments on proposed rule 10CFR2 re proposed NRC
enforcement policy Opposes rule
MILLER:R A Henry County Health Center, Mt Pleasant, IA 45FR66754
047 80/12/01 2pp 07419 241

B01070347 Comments on waste confidence rulemaking as requested in
Waste Mgt Subcommittee B01113-14 meeting Continued min reinit
& surveillance will insure safety & practicality of spent
fuel storage in reactor water basins
ALBAUGH:F H Affiliation Unknown 80/11/19 3pp 07408 133

B01070582 Comments on proposed rules 10CFR30, 40, 70, 150 & 170 re
revision of radiation protection stds codified as 40CFR190
Requests that NRC stay implementation of 40CFR190 pending
resolution of uncertainties & ambiguities re compliance
OVERTON:J A American Mining Congress 44FR50012 80/12/04 4pp

--B01070590 Transcript of B01114 proceedings re 40CFR190 in Silver
Spring, MO Pp 1-99
* Commissioners 44FR50012 00/11/14 60pp

B01070600 Comments on proposed rules 10CFR30, 40, 70, 150 & 170 Renew
B01014 request to NRC to stay enforcement & implementation
of 40CFR190 Requests that encl petition & apps filed w/EPA
be made part of record to incorporate 40CFR190 into 10CFR20
OVERTON:J A American Mining Congress 44FR50012 80/11/07 4pp

--B01070628 Forwards petition filed w/EPA re reconsideration &
revision of radiation protection stds for nuclear power
operation in 40CFR190 Requests that NRC stay enforcement &
implementation pending EPA consideration of petition
OVERTON:J A American Mining Congress 44FR50012 80/10/14
4pp.

--B01070633 Requests for relief from 40CFR190 re environ radiation
protection stds for nuclear power operations Rulemaking
proceeding should be reopened for reconsideration & revision
of 25 mtr Apps A & B encl
MCCABE:E A American Mining Congress THOMSON: A J Hmel, P
McCabe & Saunders 80/10/14 375pp

B01080024 Comments by State Water Resources Control Board on proposed
rule 10CFR20 re disposal of liquid scintillation media &
animal carcasses containing tritium & C-14 Opposes rule
MITHLEV:C California, State of 45FR67018 303 80/11/26 4pp
07417 304

B01080028 Comments on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14 Opposes rule
ROWELL:L A Harrisburg Hosp Harrisburg, PA 45FR67018 307
80/12/08 2pp 07419 302

B01080032 Comments by College of Physicians & Surgeons of Columbia
Univ on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14 Supports rule
COYNE:W D Affiliation Unknown 45FR67018 310 80/11/20 1p
07419 301

B01080033 Comments by Director of Environ Health & Safety at Medic
Ctr on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14 Supports rule
STEPHENS:R D Illinois, Univ of, at Chicago Circle 45FR67018
80/12/11 1p 07419 300

B01080042 Comments on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14 Supports rule but suggests deferring change until
sufficient info available to make risk & cost assessments
NEDEMAN:W H Environmental Protection Agency 45FR67018 312
80/12/11 1pp 07419 292

B01080047 Forwards RJ Blarshay 001205 ltr commenting on proposed
10CFR2 re proposed general statement of policies &
procedures for enforcement action
REUSS:W S Congress, Joint Economic Committee 45FR66754 055
80/12/12 1p 07419 287

--B01080057 Comments by Milwaukee Children's Hosp on proposed rule
10CFR2 re proposed general statement of policy & procedure
for enforcement actions Opposes rule Rule should
exempt health care facilities
STARSHAW:R J Affiliation Unknown 45FR66754 055 80/12/05
2pp 07419 290

B01080063 Comments on proposed rule 10CFR2 re proposed general
statement of policy & procedure for enforcement actions
Civil penalties will not ensure compliance w/LRC
requirements Orders & immediate action ltrs should be used
BURKE:J J Affiliation Unknown 45FR66754 053 80/12/09 2pp
07419 281

B01080127 Forwards comments on proposed rule 10CFR50 re consideration
of degraded or melted cores in safety regulation
LOOMIS:J B Sargent & Lundy, Inc 45FR65474 007 80/12/12 2p
07417 357

B01080132 Comments on proposed rule 10CFR50 re domestic licensing
of production & utilization facilities Rule must not be
used as excuse to delay safety improvements
LEWIS:M I Affiliation Unknown 45FR65474 006 80/12/10 10p
07309: 001

B01090544 Certified summary of ACRB Waste Mgt B01003 meeting in
Washington, DC re proposed rulemaking on technical criteria
for regulating geological disposal of high level radwaste
* ACRB - Advisory Committee on Reactor Safeguards 80/11/20
07442 188.

B01090871 Comments on proposed rule 10CFR170 re fees for review of
applications Rule should not be adopted
AXELRAD:M Lowenstein, Newman, Reis, Axelrad & Toll 45FR74493 001
80/12/03 2pp 07439 041

B01090877 Forwards comments on behalf of AL Power Co on proposed
10CFR170 re fees for review of applications To assess fees
where application for permit or license was denied, withdrawn
or suspended is beyond statutory authority of NRC.
JORDAN:A L Balch, Viningham, Baker, Hawthorne, Williams & Ward
45FR74493 002 80/12/05 11pp 07430: 050

10109C711 Comments on proposed rule 10CFR2 re proposed enforcement policy. Policy should reflect greater need for discretion in determining enforcement actions
JENKINS, H Detroit Edison Co 45FR66754 051 80/12/08 2pp 07443 355

101100141 Informs that Steering Group on Development of Safety Goal will concentrate on three extant approaches to formulating criteria during 80120 meeting. Decision was made in view of fundamental difference in nature of approaches
LIBAKIN, M J AC95 - Advisory Committee on Reactor Safeguards 80/11/28 2pp 07443 331

101130146 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FABRE, V A Affiliation Unknown 45FR70874 0509 80/12/08 1p

101130150 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FABRE, L Affiliation Unknown 45FR70874 0512 80/12/08 1p

101130156 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCKENZIE, M Affiliation Unknown 45FR70874 0513 80/12/08 1p

101130163 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
AUGUSTE, O Affiliation Unknown 45FR70874 0514 80/12/08 1p

101130169 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SMITH, O Affiliation Unknown 45FR70874 0518 80/12/08 1p

101130172 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHEVER, C Affiliation Unknown 45FR70874 0521 80/12/08 1p

101130177 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FOUNTAIN, J Affiliation Unknown 45FR70874 0522 80/12/08 1p

101130185 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
EVANS, H Affiliation Unknown 45FR70874 0526 80/12/08 1p

101130189 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CISTERNINO, M Affiliation Unknown 45FR70874 0529 80/12/08 1p

101130192 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0530 80/12/08 1p

101130197 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GREEN, S Affiliation Unknown 45FR70874 0532 80/12/08 1p

101130202 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCALERA, A Affiliation Unknown 45FR70874 0534 80/12/08 1p

101130207 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HEISLER, M Affiliation Unknown 45FR70874 0535 80/12/08 1p

101130212 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0517 80/12/08 1p

8101130255 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GONZALEZ, C Affiliation Unknown 45FR70874 0469 80/12/08 1p

8101130261 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BALL, J R Affiliation Unknown 45FR70874 0471 80/12/08 1p

8101130263 Forwards "Proposed Changes in NRC Reactor Safety Policy Response to NRC Invitation for Comments on Degraded Cores in Safety Regulation"
HUBBARD, H W R & D Associates 80/12/31 1p 07451 293

--8101130274 "Proposed Changes in NRC Reactor Safety Policy Response to NRC Invitation for Comments on Degraded Cores in Safety Regulation"
HULLIDAY, D L HUBBARD, H W LATTER, A R & O Associates 80/12/29 21pp 07451 254

8101130267 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0472 80/12/08 1p

8101130275 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DEPT-DEB, C Affiliation Unknown 45FR70874 0474 80/12/08 1p

8101130280 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LUCAS, J Affiliation Unknown 45FR70874 0475 80/12/08 1p

8101130286 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KENDALL, O Affiliation Unknown 45FR70874 0476 80/12/08 1p

8101130290 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHIPP, O M Affiliation Unknown 45FR70874 0477 80/12/08 1p

8101130301 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
NORDB, R Affiliation Unknown 45FR70874 0480 80/12/08 1p

8101130306 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ROSB, P Affiliation Unknown 45FR70874 0481 80/12/08 1p

8101130312 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MERCAD, I Affiliation Unknown 45FR70874 0482 80/12/08 1p

8101130316 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MASLAN, A A Affiliation Unknown 45FR70874 0483 80/12/08 1p

8101130319 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MOORE, A M Affiliation Unknown 45FR70874 0484 80/12/08 1p

8101130324 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCKENZIE, L Affiliation Unknown 45FR70874 0489 80/12/08 1p

8101130328 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SMITH, O Affiliation Unknown 45FR70874 0485 80/12/08 1p

NONDOCKETED ITEMS

8101130332 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
OELSEL, C Affiliation Unknown 45FR70874 0487 80/12/05 1p

8101130335 Forwards "Proposed Changes in NRC Reactor Safety Policy. Response to NRC invitation for Comments on Degraded Cores in Safety Regulation"
HUGBARD, H W R & O Associates 81/01/06 1p 07451 331

8101130338 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JOYCE, P Affiliation Unknown 45FR70874 0479 80/12/05 1p

8101130343 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
Affiliation Unknown 45FR70874 0473 80/12/05 1p

8101130347 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JOYCE, M Affiliation Unknown 45FR70874 0470 80/12/05 1p

8101130351 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEE, K Affiliation Unknown 45FR70874 0536 80/12/05 1p

8101130361 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
OORNET, C Affiliation Unknown 45FR70874 0533 80/12/05 1p

8101130367 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PAPEONI, F Affiliation Unknown 45FR70874 0525 80/12/05 1p

8101130383 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RAMS, Y Affiliation Unknown 45FR70874 0537 80/12/03 1p

8101140042 Requests review & comments on encl working paper no later than 801205 Comments will be used in preparation of preliminary policy paper
SEGE, O Office of Policy Evaluations 80/12/01 5pp 07460 255

8101140054 Submits highlights of D Bidebotham & C Iselin 801117 interview Safety-cost tradeoff should be permissible only after prescribed min safety level is met Cost should not bar retrofit.
SEGE, O Office of Policy Evaluations 80/12/08 2pp 07460 260

8101140066 Informs that outline proposed in working paper re safety goal formulation suffers from definitional confusion
Outline should be restricted to safety goals.
LABARKIN, M W. ACRS - Advisory Committee on Reactor Safeguards 80/12/04 3pp 07460 262

8101140074 Informs of NC Rasmussen 801117 interview to gain benefit of views re establishment of safety goals Demand for probable risk assessment exceeds available supply of people.
SEGE, O Office of Policy Evaluations 80/12/10 3pp 07460 292

8101140084 Submits comments on notice of proposed general policy evaluation of Agreement State radiation control programs.
NRC is attempting futile effort in finding clear cut guide w/numerical indicators to judge compatibility
FUNDERBURG, R D Idaho, State of 80/10/30 2pp 07461 231

8101140090 Informs of D Bridenbaugh & R Hubbard 801105 interview re views on safety-goal formulation Safety assurance effectiveness depends on factors that involve direct costs to utility.
SEGE, O Office of Policy Evaluations 80/12/04 2pp 07460 295

8101140092 Submits comments on revised criteria for evaluation of Agreement State programs in response to State of NV 801015 1tr.
WILSON, E F Arkansas, State of 80/10/28 2pp 07461 233

8101140096 Advises that comments on NRC proposed statement of policy on evaluation of Agreement State radiation control programs were received from 13 states. Submits comments from TN.

8101140102 Informs of V Joksimovic, WJ Houghton & CR Fisher 801104 interview re thoughts on safety-goal formulation
Quantitative safety goals should be set before other major rulemakings are completed
SEGE, O Office of Policy Evaluations 80/12/08 2pp 07460

8101140116 Comments on behalf of Kerr-McOee Nuclear Corp on proposed policy re evaluation of Agreement State radiation control programs Statement asserts authority over Agreement States which NRC does not possess.
NICHES, P J, MONTAGNE, C H Covington & Durling 4563726 001 80/11/14 19pp 07450 170

8101140122 Submits comments on proposed statement of policy on guide for evaluation of Agreement State radiation control programs
SPELL, W H Louisiana, State of 80/12/19 2pp 07461 209

8101140127 Comments on proposed rule 10CFR2 re interim enforcement policy Policy statement is uncompromising & inflexible
FAY, C W Wisconsin Electric Power Co 45FR66754 048 80/12/03 3pp 07462 113

8101140134 Submits comments on guide for evaluation of Agreement radiation control programs Rept should remain as uncodified guide
DERUSE, L D Georgia, State of 80/12/16 1p 07461 194

8101140138 Comments on behalf of Milwaukee Children's Hosp on proposed rule 10CFR2 re general statement of policy & procedure for enforcement actions Rule should exempt health care facilities
STARSHAW, R J Affiliation Unknown 45FR66754 053 80/12/05 07462 111

8101140141 Submits comments on NRC proposed statement of policy evaluation of Agreement State radiation control programs No objections to proposal
CLARK, U Florida, State of 80/12/12 1p 07461 196

8101140146 Forwards comments on proposed rule 10CFR2 re general statement of policy & procedure for enforcement actions. Portions of policy need clarifying to eliminate as many questions as possible
SHINDOCK, J D American Electric Power Co, Inc INDIAN, R S Indiana & Michigan Electric Co 45FR66754 052 80/12/08 11p 07462 100

8101140147 Advises of no addl comments on NRC proposed guide for evaluation of state radiation control programs
MOUNT, D K North Dakota, State of 80/12/19 1p 07304 001

8101140159 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Public comment period should be extended by 30 days
REHLEY, M E Rockwell International Corp, Energy Systems Div 45FR66754 071 80/12/23 1p 07462 088

8101140423 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Comment period should be extended by 90 days More time is needed to review vast amount of mail
TODOROVICH, L H Scientists & Engineers for Secure Energy 45FR 070 80/12/18 2pp 07462 077

8101140431 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Univ-owned research & training reactor should be exempt from rule Policy discriminates against nuclear facilities w/o substantial financial resources
CUNNINGHAM, R O Pennsylvania State Univ 45FR66754 069 80/12/22 07462 075

8101140446 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Fines are much too high relative to listed violations, especially in categories other than power reactors.
GEORGE, K D Affiliation Unknown 45FR66754 068 80/12/17 2pp 07462 073

8101140527 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Rule is unreasonable Includes hereh requirement in dealing w/low level radiation Consistent presentation at NRC 801202 public hearing encl
SACKEL, R J Palos Community Hosp, Palos Park, IL 45FR66754 067 80/12/04 5pp 07462 040

8101140532 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Concept of levying fines for accidents should be applied to other industries Addl comments encl.

B101140537 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy is unfair Nuclear reactors & other high-powered industrial applications are considered at same public safety, risk level as health physics
LANZC, W H Lakeland Hosp Elkhorn, NE 45FR66754 057 80/12/10 3pp 07462 031

B101140541 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Supports rule Large fines should be levied for violations
ENHNS, J S Affiliation Unknown 45FR66754 056 80/12/12 2pp 07308 001

B101140552 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Requests reply in encl ltr from Milwaukee Children's Hosp expressing opinion that hosp need no further bureaucratic intervention.
ZAGLICKI, C J House of Rep 45FR66754 054 80/12/12 2pp 07462 027

B101140553 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Community hosp & other radioisotope users practice prudent radiation safety NRC already has authority to mandate corrective action whenever necessary
GRUBBS, J B REED, S A St Elizabeth Hosp Appleton, WI 45FR66754 051 80/12/15 2pp 07461 295

B101140560 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Antideficiency Act prohibits one govt agency from fining another Violations should be reviewed on case by case basis Automatic fines encourage noncompliance
RUS, HIRSH, D H Interior, Dept of, Geological Survey 45FR66754 066 80/12/19 1p 07462 047

B101140565 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Requests extension of comment period to 10/22/79, to allow thorough review of complex issues
FIRESTONE, E A General Electric Co 45FR66754 052 80/12/17 1p 07308 001

B101140573 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Rule is counterproductive. Licensees will not rest problems if penalty will be imposed.
BOESTER, U L Kansas Gas & Electric Co 45FR66754 065 80/12/17 3pp 07462 044

B101140578 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Requests that comment period be extended until 8/10/81, to permit company & clients opportunity to develop detailed comments & suggested alternatives
KUTILL, D F KMC, Inc 45FR66754 059, 80/12/19 1p 07462 043

B101140583 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
AKELIE, D Affiliation Unknown 45FR70874 1477 80/12/10 1p

B101140585 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TREXLER, K Affiliation Unknown 45FR70874 1479 80/12/10 1p

B101140586 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TERRY, J Affiliation Unknown 45FR70874 1478 80/12/10 1p

B101140588 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DEES, M. Affiliation Unknown 45FR70874 1474 80/12/10 1p

B101140590 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRIGGS, K Affiliation Unknown 45FR70874 1467 80/12/10 1p

B101140592 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ANDERSON, F I Affiliation Unknown 45FR70874 1465 80/12/10 1p

B101140593 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DEKER, K. Affiliation Unknown 45FR70874 1466 80/12/10 1p

B101140599 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BERGIN, A Affiliation Unknown 45FR70874 1464 80/12/10 1p

B101140503 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JENKINS, D Affiliation Unknown 45FR70874 1473 80/12/10

B101140604 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MARRAS, E Affiliation Unknown 45FR70874 1472 80/12/10

B101140607 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ADAMS, E A Affiliation Unknown 45FR70874 1471 80/12/10

B101140610 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GITLIN, S, E Affiliation Unknown 45FR70874 1470 80/12/10

B101140614 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
OLMER, A Affiliation Unknown 45FR70874 1469 80/12/10

B101140624 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MITCHELL, M Affiliation Unknown 45FR70874 1476 80/12/10

B101140629 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHEER, E Affiliation Unknown 45FR70874 1475 80/12/10

B101140637 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LITTLEJOHN, J Affiliation Unknown 45FR70874 1390 80/12/10

B101140643 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FERGUSON Affiliation Unknown 45FR70874 1399 80/12/10

B101140651 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COLELLI, E Affiliation Unknown 45FR70874 1398 80/12/10

B101140676 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WILSON, K Affiliation Unknown 45FR70874 1397 80/12/10

B101140683 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CROELL, N Affiliation Unknown 45FR70874 1396 80/12/10

B101140688 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DEWITT, C Affiliation Unknown 45FR70874 1468 80/12/10

B101140774 Forwards proposed rule 10CFR2.50, 70 & 73. "Protect Unclassified Safeguards Info" Required rept to Congress will be submitted concurrent w/issuance of final rule w/encl
AHEARNE, J F Commissioners 80/12/22 1p 07457:030

--B101140779 Forwards proposed rule 10CFR2.50, 70 & 73. "Protect Unclassified Safeguards Info" Required rept to Congress will be submitted concurrent w/issuance of final rule w/encl
AHEARNE, J F Commissioners 80/12/22 1p 07457:031

--B101140786 Forwards proposed rule 10CFR2.50, 70 & 73. "Protect Unclassified Safeguards Info" Required rept to Congress will be submitted concurrent w/issuance of final rule w/encl
AHEARNE, J F Commissioners 80/12/22 1p 07457:032

--B101140790 Forwards proposed rule 10CFR2.50, 70 & 73. "Protect Unclassified Safeguards Info" Required rept to Congress will be submitted concurrent w/issuance of final rule w/encl
AHEARNE, J F Commissioners 80/12/22 1p 07457:033

--B101140799 Forwards proposed rule 10CFR2.50.70 & 73. "Protection of Unclassified Safeguards Info - Required rept to Congress will be submitted concurrent w/issuance of final rule W/O encl
McEARNIE, J F Commissioners 80/12/22 1p 07497 034

--B101140802 Forwards proposed rule 10CFR2.50.70 & 73. "Protection of Unclassified Safeguards Info - Required rept to Congress will be submitted concurrent w/issuance of final rule
McEARNIE, J F Commissioners 80/12/22 1p 07497 035

--B101140811 "Protection of Unclassified Safeguards Info." 10CFR2.50.70 & 73 proposed rule Regulations identify types of safeguards info to be protected, establish min protection requirements & set conditions for access to safeguards info
CHILKIS, J Office of the Secretary of the Commission 80/12/19 2pp 07497 036

B101140962 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DUNNETT, P Affiliation Unknown 45FR70874 1504 80/12/05 1p

B101140964 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAY, T S Affiliation Unknown 45FR70874 1503 80/12/07 1p

B101140971 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RASHTI, A Affiliation Unknown 45FR70874 1501 80/12/08 1p

B101140976 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LYKOS, M Affiliation Unknown 45FR70874 1507 80/12/08 1p

B101140981 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RASHTI, J Affiliation Unknown 45FR70874 1500 80/12/09 1p

B101140986 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
OYER, J F Affiliation Unknown 45FR70874 1505 80/12/10 1p

B101140989 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DONALLEY, R H Affiliation Unknown 45FR70874 1508 80/12/10 1p

B101150095 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHOVER, B J Affiliation Unknown 45FR70874 1510 80/12/10 1p

B101150105 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PELLETIER, B C Affiliation Unknown 45FR70874 1504 80/12/10 1p

B101150109 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ZANE, A J Affiliation Unknown 45FR70874 1509 80/12/10 1p

B101150123 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LYONS, K Affiliation Unknown 45FR70874 1455 80/12/10 1p

B101150132 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BERNERSHEIM, K Affiliation Unknown 45FR70874 1436 80/12/10 1p

B101150143 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FRIEDMAN, P Affiliation Unknown 45FR70874 1457 80/12/10 1p

B101150148 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ADCOCK, A Affiliation Unknown 45FR70874 1498 80/12/10 1p

B101150157 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CANALE, J D Affiliation Unknown 45FR70874 1460 80/12/10

B101150160 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GELM, C Affiliation Unknown 45FR70874 1461 80/12/10 1p

B101150164 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BUTLER, A Affiliation Unknown 45FR70874 1462 80/12/10 1p

B101150173 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MDFIANN, A Affiliation Unknown 45FR70874 1450 80/12/10

B101150179 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GLADSTAR, R Affiliation Unknown 45FR70874 1451 80/12/10

B101150184 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DELEB, J D Affiliation Unknown 45FR70874 1452 80/12/10

B101150191 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WINTERB, C Affiliation Unknown 45FR70874 1453 80/12/10

B101150194 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ROWLAND, A Affiliation Unknown 45FR70874 1454 80/12/10

B101150200 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SZADAT, S Affiliation Unknown 45FR70874 1443 80/12/10

B101150207 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HOWER, J Affiliation Unknown 45FR70874 1444 80/12/10 1p

B101150213 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HUGHES, O Affiliation Unknown 45FR70874 1445 80/12/10

B101150222 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TALBOT, P Affiliation Unknown 45FR70874 1446 80/12/10

B101150226 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FOLDVARY, D Affiliation Unknown 45FR70874 1447 80/12/10

B101150235 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GROSS, C Affiliation Unknown 45FR70874 1448 80/12/10 1p

B101150257 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHRISTENSEN, B Affiliation Unknown 45FR70874 1449 80/12/10

B101150267 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MANGAN, A Affiliation Unknown 45FR70874 1436 80/12/10

B101150272 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCHRA, A Affiliation Unknown 45FR70874 1439 80/12/10 1p

B101150277 Comments by Ecology Action Educational Inst on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
Affiliation Unknown 45FR70874 1438 80/12/10 1p

B101150283 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHMIDT, M Affiliation Unknown 45FR70874 1437 80/12/10 1p

B101150293 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VECKHUNE, P Affiliation Unknown 45FR70874 1442 80/12/10 1p.

B101150298 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FELDER, Y E Affiliation Unknown 45FR70874 1440 80/12/10 1p

B101150475 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHONO, K Affiliation Unknown 45FR70874 0624 80/12/01 1p

B101150486 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LCARDI, C Affiliation Unknown 45FR70874 0571 80/12/02 1p

B101150486 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0627 80/12/02 1p

B101150842 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COMPLIN, M Affiliation Unknown 45FR70874 0541 80/11/29 1p

B101150844 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRENNAN, T Affiliation Unknown 45FR70874 0638 80/11/25 1p

B101150846 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ATKINSON, A Affiliation Unknown 45FR70874 1355 80/12/07 1p

B101150852 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCDOUGALL, J Affiliation Unknown 45FR70874 0612 80/12/04 1p

B101150858 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCCEMA, C Affiliation Unknown 45FR70874 0593 80/12/04 4pp

B101160003 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHARP, R H Affiliation Unknown 45FR70874 1393 80/12/09 1p.

B101160006 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 1480 80/12/09 1p

B101160008 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HARLAN, M F Affiliation Unknown 45FR70874 1469 80/12/09 1p

B101160010 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COPE, C Affiliation Unknown 45FR70874 1481 80/12/09 1p

B101160011 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CODY, S Affiliation Unknown 45FR70874 1488 80/12/09 1p

B101160013 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 1372 80/12/09 1p

B101160015 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHILLING, R K Affiliation Unknown 45FR70874 1383 80/12/09 1p

B101160018 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MARKER, R A Affiliation Unknown 45FR70874 1437 80/12/10 1p

B101160023 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 1442 80/12/10 1p.

B101160027 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHURT, M Affiliation Unknown 45FR70874 1440 80/12/10 1p

B101160032 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCLEVAY, F Affiliation Unknown 45FR70874 0624 80/12/01 1p

B101160041 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BARRONS, O C Affiliation Unknown 45FR70874 0571 80/12/02 1p

B101160048 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LASTY, S Affiliation Unknown 45FR70874 0627 80/12/02 1p

B101160052 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RASHTI, J Affiliation Unknown 45FR70874 0541 80/11/29 1p

B101160060 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEE, O C Affiliation Unknown 45FR70874 0638 80/11/25 1p

B101160066 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PETRIE, E R Affiliation Unknown 45FR70874 1355 80/12/07 1p

B101160075 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GAFFNEY, E Affiliation Unknown 45FR70874 0612 80/12/04 1p

B101160093 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LIEBHART, P C Affiliation Unknown 45FR70874 0593 80/12/04 4pp

B101160103 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DEWITT, O Affiliation Unknown 45FR70874 1393 80/12/09 1p.

B101160112 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
REINSON, S Affiliation Unknown 45FR70874 1480 80/12/09 1p

B101160121 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MATTHEW, O Affiliation Unknown 45FR70874 1469 80/12/09 1p

B101160130 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FRASER, B Affiliation Unknown 45FR70874 1481 80/12/09 1p

B101160139 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BILLIG, B Affiliation Unknown 45FR70874 1488 80/12/09 1p

B101160149 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRIGHTMAN, W Affiliation Unknown 45FR70874 1372 80/12/09 1p

B101160160 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PITTS, M Affiliation Unknown 45FR70874 1383 80/12/09 1p

810160340 Comments on proposed rules 10CFR30.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in retail Spocess rules
BURNS, I Affiliation Unknown 45FR70974 1567 00/12/06 1p

8101160337 Comments on proposed rule 10CFR33.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules.
SUTHERLAND, E Affiliation Unknown 49FR70874 1568 80/12/06

8101160372	Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules	NAFLAN, N	Affiliation Unknown	45FR70874	1970	00/12/06	1
------------	--	-----------	---------------------	-----------	------	----------	---

B101160390 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MINTZ, M Affiliation Unknown 49FR70874 1973 00/12/06 1p

2101160480 Comments on proposed rules 10CFR70.32, 70 & 150 re
possession, use & transfer of low enriched U as contentment
in metals Opposes rules
LEVINE, A Affiliation Unknown 45FR70874 1574 80/12/06 1

SI01160495 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules	KCMAL, A	Affiliation Unknown	45F87C074 197B	89/12/06	1p
--	----------	---------------------	----------------	----------	----

810160499 Comments on proposed rules 10CFR30.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
FISHER, N. J. Affiliation Unknown 49FR70974 0935 00/12/12

810160505 Comments on proposed rules 10CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposee rules
KANDAKFAR, R Affiliation Unknown 45FR70874 0934 00/12/18

8101150515 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.

8101160531	Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in details Opposes rules				
EDLER, A	Affiliation Unknown	45FR70874	0932	80/12/18	1

possession, use & transfer of low enriched U as contaminant
in metals Opposes rule
01RDN, H P Affiliation Unknown 45FR70874 0931 00/12/10.

PEREZ, J Affiliation Unknown 45FR70074 0930 80/12/10 1p

8101160546 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MIXED, T. Affiliation Unknown 45FR70874 0929, 80/12/18. 1p

B10160551 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAR01D, L 1 Affiliation Unknown 45FR70874 0927 80/12/18

8101160554 Comments on proposed rules 10CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
THOMPSON, R Affiliation Unknown 45FR70874 0926 00/12/10

8101160559 Comments on proposed rules 10CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
JONES, A. Affiliation Unknown 45FR70074 0696 00/12/18 ip

B10110553 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
DAIDORE,C Affiliation Unknown 45FR70874 0090, 80/12/18

8101160568 Comments on proposed rules 10CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Oppose rules
KAUFMAN, M Affiliation Unknown. 45R70874 0899. 80/12/18

8101160571 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHUMLAHYER, W Affiliation Unknown 45FR70874 C678 60/12/18 1p

8101160576 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JOHNS, J Affiliation Unknown 45FR70874 C691 60/12/18 1p

8101160578 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WIEHER, J Affiliation Unknown 45FR70874 C692 60/12/18 1p

8101160583 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCLEATO, J Affiliation Unknown 45FR70874 C693 60/12/18 1p

8101160584 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCQUIRE, D Affiliation Unknown 45FR70874 C694 60/12/18 1p

8101160592 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BUIENSKY, M D Affiliation Unknown 45FR70874 C698 60/12/18 1p

8101160590 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FESTER, R Affiliation Unknown 45FR70874 0910 60/12/18 1p

8101160603 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SAVAGE, G Affiliation Unknown 45FR70874 0911 60/12/18 1p

8101160609 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRUNDELD, C Affiliation Unknown 45FR70874 0912 60/12/18 1p

8101160614 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JEANVITON, L Affiliation Unknown 45FR70874 0913 60/12/18 1p

8101160618 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RIVERA, A Affiliation Unknown 45FR70874 0914 60/12/18 1p

8101160625 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GREEN, M Affiliation Unknown 45FR70874 0915 60/12/18 1p

8101160632 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TRYLIE, M Affiliation Unknown 45FR70874 0916 60/12/18 1p

8101160638 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
REYES, E Affiliation Unknown 45FR70874 0906 60/12/18 1p

8101160643 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MURKELLY, M Affiliation Unknown 45FR70874 0917 60/12/18 1p

8101160647 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SINOW, R L Affiliation Unknown 45FR70874 1588 60/12/06 1p

8101160652 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules

8101160656 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VILLAR, N S Affiliation Unknown 45FR70074 0902

8101160658 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SEIMCH, A E Affiliation Unknown 45FR70874 1987

8101160687 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VIESTI, G Affiliation Unknown 45FR70074 1607

8101160692 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
REISERT, I Affiliation Unknown 45FR70074 1608

8101160695 Comments on proposed rule 10CFR50 re degraded or melted cores in safety regulation Int approach to rulemaking should be taken Priority given to safety goal & methodology development
LEE, B Atomic Industrial Forum 45FR69474 021 07469 083

--8101160697 Forwards comments on proposed rule 10CFR50 re degraded or melted cores in safety regulation emergency planning rule should be re-examined.
QIBBS, D C Atomic Industrial Forum 45FR69474 34pp 07469 085

8101160698 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BUDOFF, D S Affiliation Unknown 45FR70874 0635

8101160701 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SMILL, H Affiliation Unknown 45FR70874 1612

8101160702 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MERKEN, B J Affiliation Unknown 45FR70074 1074

8101160705 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BUDRETZKY, F Affiliation Unknown 45FR70874 1075

8101160707 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CONN, I Affiliation Unknown 45FR70874 1046

8101160710 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRADY, R Affiliation Unknown 45FR70074 1552

8101160712 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TOSK, S Affiliation Unknown 45FR70874 1613

8101190001 Comments by Nuclear Util Group on Enforcement rule 10CFR2 re policy & procedure for enforcement. Sanctions should be designed & imposed to encourage licensees to initiate programs for solving problems
DUNBIL, W O, REYNOLDS, N S Affiliation Unknown 60/12/31 103pp 07474 082

8101190002 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SMITH, J Affiliation Unknown 45FR70074 0904

8101190003 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BARNARD, M Affiliation Unknown 45FR70874 0903

NONDOCKETED ITEMS

B101190026 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MURTHA, M Affiliation Unknown 45FR70874 0907 80/12/01 1p

B101190038 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
WHEELER, J Affiliation Unknown, 45FR70874 0897 00/12/01 1p

B101190011 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MONTPEQUE, J E Affiliation Unknown 45FR70874 0095 80/12/01 1p

B101190014 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
RODRIGUEZ, D Affiliation Unknown 45FR70874 0720 80/12/01 1p

B101190016 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHIMI, E Affiliation Unknown 45FR70074 0901 80/12/01 1p

B101190018 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CAMPOELL, H. Affiliation Unknown 45FR70874 0926 80/12/01 1p

B101190020 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MORGAN, J F Affiliation Unknown 45FR70874 0925 80/12/01 1p

B101190022 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KENISTON, J. Affiliation Unknown 45FR70874 0940 80/12/01 1p

B101190024 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LABOW, A Affiliation Unknown 45FR70874 0939 00/12/01 1p

B101190027 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHUMA, M Affiliation Unknown 45FR70074 0950 80/12/01 1p

B101190029 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
OURNS, J Affiliation Unknown 45FR70874 0941 80/12/01 1p

B101190033 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MULLEN, J Affiliation Unknown 45FR70874 1365 80/12/10 1p

B101190039 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
FORBESON, L Affiliation Unknown 45FR70074 1359 80/12/10 1p

B101190047 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
Affiliation Unknown 45FR70874 1360 80/12/10 1p

B101190055 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
Affiliation Unknown 45FR70874 1363 80/12/10 1p

B101190057 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GRBSE, L Affiliation Unknown 45FR70874 1398 80/12/10 1p

B101190062 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LAUGHLING, D L F Affiliation Unknown 45FR70574 1329 80/12/10 1p.

B101190065 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CORRYAN, L Affiliation Unknown 45FR70874 1324 00/12/10

B101190067 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FEBL, M Affiliation Unknown 45FR70874 1325 80/12/10 1p

B101190070 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SIEFF, A Affiliation Unknown 45FR70874 1326 80/12/10 1p

B101190073 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VALERIG, M P Affiliation Unknown 45FR70874 1327 80/12/10

B101190075 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WASSERMAN, J H Affiliation Unknown 45FR70874 1335 80/12/10

B101190079 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAUNILL, O Affiliation Unknown 45FR70874 1333 80/12/10

B101190081 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SYMONIX, O Affiliation Unknown 45FR70874 1332 80/12/10

B101190084 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KINKEAD, O Affiliation Unknown 45FR70874 1331 80/12/10

B101190086 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WITKOWSKI, R C Affiliation Unknown 45FR70874 1330 80/12/10

B101190091 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CRESBMAN, D Affiliation Unknown 45FR70874 1338 80/12/10

B101190093 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COLMAN, L Affiliation Unknown 45FR70874 1339 80/12/10 1p

B101190111 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MIRO, L Affiliation Unknown 45FR70874 1533 80/12/10 1p

B101190117 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LADDY, B Affiliation Unknown 45FR70874 1532 80/12/10 1p

B101190121 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HIDALL, N Affiliation Unknown 45FR70874 1530 80/12/10 1p

B101190126 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BLAKELY, H S Affiliation Unknown, 45FR70874 1529 80/12/10.

8101190593 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GCRBCLB Affiliation Unknown 45FR70874 0592 80/12/03 1p

8101190597 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GUTIESFELD P Affiliation Unknown 45FR70874 0575 80/12/03 1p

8101190590 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0561 80/12/03 1p

8101190594 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ARNDIC D L Affiliation Unknown 45FR70874 0576 80/12/03 1p

8101190624 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PLEVER, S Affiliation Unknown 45FR70874 0574 80/12/03 1p

8101190651 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ARNDT, E C Affiliation Unknown 45FR70874 0644 80/12/03 1p

8101190658 Comments on general policy statement on evaluation of Agreement State radiation control plan Revision period of 4 or 5 yrs may allow for more efficient use of staff LR Bolton
801114 memo to J South end
DANALCBF96ER, J New York, State of 80/12/22 2pp 074/6 093

8101190659 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BODDM, R Affiliation Unknown 45FR70874 0641 80/12/03 1p

8101190665 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ROTH, E Affiliation Unknown 45FR70874 1060 80/12/03 1p

8101190666 Comments on general policy statement on evaluation of Agreement State radiation control plans Agreement State reviews should be conducted by third party
YOUNG, R E Affiliation Unknown 80/12/22 2pp 07193 001

8101190670 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TAMUNHO, M Affiliation Unknown 45FR70874 1033 80/12/03 1p

8101190673 Comments on general policy statement on evaluation of Agreement State radiation control plans. More emphasis should be placed on technical advisory committees & consultants & on competence of senior staff
O'DRIEAM, J Affiliation Unknown 80/12/19 2pp 07123 001

8101190681 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEVINE, S Affiliation Unknown 45FR70874 1037 80/12/03 1p

8101190687 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SALZHAUER, S Affiliation Unknown 45FR70874 1039 80/12/03 1p

8101190693 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SACHS, C Affiliation Unknown 45FR70874 1049 80/12/03 1p

8101190697 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BLAUDEL, C Affiliation Unknown 45FR70874 1572 80/12/03 1p

8101190712 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ACKSON, R Affiliation Unknown 45FR70874 1579 80/12/03 1p

8101190719 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
YEDAM, L Affiliation Unknown 45FR70874 1604 80/12/03 1p

8101190723 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHAPIRO, J Affiliation Unknown 45FR70874 1617 80/12/03 1p

8101190731 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHANGELMAN, R Affiliation Unknown 45FR70874 1618 80/12/03 1p

8101190736 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCMEWELL, E R Affiliation Unknown 45FR70874 1621 80/12/03 1p

8101190752 Transcript of Commission 801222 meeting in Washington, D.C. re SECY 80-474 Pp 1-79 Material info
* Commissioners 80/12/22 103pp 07472 324

8101200010 Comments on proposed rules 10CFR50 & 51. "Proposed Rulemaking on Storage & Disposal of Nuclear Waste." Ability to validate models could become crucial to confidence
Question
STEINBLER, R Argonne National Laboratory 80/11/18 2pp 07487 015

8101200011 Comments on proposed rules 10CFR50 & 51. "Proposed Rulemaking on Storage & Disposal of Nuclear Waste." Current direction of deep geologic disposal at environmentally favorable sites with high integrity packages is safe
FOSTER, R F Affiliation Unknown 80/11/21 5pp 07487 009

8101200127 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
YORR, J Affiliation Unknown 45FR70874 1493 80/12/03 1p

8101200130 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SABRACCI, Y Affiliation Unknown 45FR70874 1495 80/12/03 1p

8101200133 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
AYTELL, J Affiliation Unknown 45FR70874 1067 80/12/03 1p

8101200138 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LAWRENCE, M Affiliation Unknown 45FR70874 1065 80/12/03 1p

8101200143 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MATHIAS, D Affiliation Unknown 45FR70874 1066 80/12/03 1p

8101200149 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RAFUANO, K O Affiliation Unknown 45FR70874 1064 80/12/03 1p

8101200153 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BABS, A Affiliation Unknown 45FR70874 1068 80/12/03 1p

8101200156 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MUELLER, M Affiliation Unknown 45FR70874 1069 80/12/03 1p

8101200160 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
IMBODEN, E Affiliation Unknown 45FR70874 1070 80/12/03 1p

8101200163 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JENKINS, M Affiliation Unknown 45FR70874 1071 80/12/03 1p

8101200166 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules NEEQLEMAN, L Affiliation Unknown 45FR70874 1073 80/12/07 1p	8101200318 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ROBEY, L Affiliation Unknown 45FR70874 1008 80/12/04 1p
8101200173 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules AURA, D Affiliation Unknown 45FR70874 1052 80/12/09 1p	8101200720 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules WASSERBACH, A E Affiliation Unknown 45FR70874 1066 80/12/04 1p
8101200177 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SCHABNACK, P Affiliation Unknown 45FR70874 1053 80/12/09 1p	8101200321 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HART, R Affiliation Unknown 45FR70874 1027 80/12/04 1p
8101200203 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules OOL, J Affiliation Unknown 45FR70874 1072 80/12/10 1p	8101200377 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ZETCO, EY, K Affiliation Unknown 45FR70874 1060 80/12/04
8101200212 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules LITVCK, D Affiliation Unknown 45FR70874 1051 80/12/10 1p	8101200407 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 1059 80/12/04 1p
8101200215 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DIAMOND, R Affiliation Unknown 45FR70874 1459 80/12/10 1p	8101200410 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules CASTAFIAN, L Affiliation Unknown 45FR70874 1050 80/12/04
8101200224 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HOPKINS, T R Affiliation Unknown 45FR70874 1463 80/12/10 1p	8101200421 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules AGATA, C Affiliation Unknown 45FR70874 1056 80/12/04 1p
8101200224 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules GARRETT, P Affiliation Unknown 45FR70874 1493 80/12/10 1p	8101200425 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules REGAN, A Affiliation Unknown 45FR70874 1561 80/12/04 1p
8101200226 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules VLNER, A Affiliation Unknown 45FR70874 1496 80/12/10 1p	8101200429 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ESPPOSITO, M L Affiliation Unknown 45FR70874 1562 80/12/04
8101200230 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules VLNER, J W Affiliation Unknown 45FR70874 1494 80/12/10 1p	8101200434 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules COHEN, A Affiliation Unknown 45FR70874 1565 80/12/04 1p
8101200262 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SHERI, Z Affiliation Unknown 45FR70874 0033 80/12/03 1p	8101200439 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules FIER, A Affiliation Unknown 45FR70874 1566 80/12/04 1p
8101200265 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HENDON, Z Affiliation Unknown 45FR70874 0054 80/12/03 1p	8101200443 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MACDONALD, S Affiliation Unknown 45FR70874 1569 80/12/04
8101200267 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules FOSTER, L A Affiliation Unknown 45FR70874 0056 80/12/03 1p	8101200447 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SULLIVAN, M Affiliation Unknown 45FR70874 1571 80/12/04
8101200270 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules CASADO, N Affiliation Unknown 45FR70874 0057 80/12/03 1p	8101200451 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules PARA, A Affiliation Unknown 45FR70874 1575 80/12/04 1p
8101200272 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules RABELAIR, P Affiliation Unknown 45FR70874 0058 80/12/03 1p	8101200456 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules OZEROTT, D Affiliation Unknown 45FR70874 1576 80/12/04 1p
8101200276 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DUNFORD, J Affiliation Unknown 45FR70874 0059 80/12/03 1p	8101200461 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SHILLIE Affiliation Unknown 45FR70874 1580 80/12/04 1p
8101200283 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules NEGRI, P Affiliation Unknown 45FR70874 0052 80/12/03 1p	8101200464 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules OASTON, W Affiliation Unknown 45FR70874 1583 80/12/04 1p
8101200308 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 1097 80/12/04 2pp	

9101200532 Comments on proposed rules 10CFR30.12.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
PICCOLI, A M Affiliation Unknown 45FR70074 1594 80/12/05 10

8101210013 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEWIS, R. 884111, 11-11-88, Unknown, 455870974, 1418, 80/12/09, 10

8101210199 Comments on proposed titles 10CFR30.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
HA0DIX.K F Affiliation Unknown 45FR70874 1378 00/12/08 1p

8101210263 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LTKOS:K Affiliation Unknown J9F87UG74 1517 80/12/08 1p

B101210447 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals. Opposes rules
LUNNEY, M. Affiliation: Unknown. USER70874 0577 B0/12/08

8101210450 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ORSIHIL, J Affiliation Unknown 45FR70874 0580 80/12/08 1p

8101210456 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ZAHADJAI, D Affiliation Unknown 45FR70874 0584 80/12/08 1p

8101210540 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BLURENHAL, J Affiliation Unknown 45FR70874 0592 80/12/08 2pp

8101210946 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KAOAN, M Affiliation Unknown 45FR70874 0595 80/12/08 2pp

8101210951 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BEWDE, W. J Affiliation Unknown 45FR70074 0637 80/12/08 2pp

8101210952 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BORT, S. Affiliation Unknown 45FR70874 0601 80/12/08 2pp

8101210956 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CUTJTB, G Affiliation Unknown 45FR70874 0589 00/12/05 1p

8101210959 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCRTICK, S Affiliation Unknown 45FR70874 1308 80/12/08 1p

8101210962 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRAZ, Z. Affiliation Unknown 45FR70874 1306 80/12/08 1p

8101210964 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JAMISON, L Affiliation Unknown 45FR70874 1307 00/12/08 1p

8101210967 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SELIO, A Affiliation Unknown 45FR70874 1311 80/12/08 1p

8101210970 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
FAULKNER, M. L Affiliation Unknown 45FR70874 1319 80/12/08 1p

8101210973 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SEROUTON, N Affiliation Unknown 45FR70874 1318 80/12/08 1p

8101210979 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RIBORDAN, B Affiliation Unknown 45FR70874 1317 80/12/08 1p

8101220003 Memorandum & order directing Commission working group to file by 810129 rept summarizing record & identifying key issues Participants may submit comments on rept within 35 days of filing Certificate of Svc encl
CHILK, B. J Office of the Secretary of the Commission 81/05/16 11pp, 07501 310

8101220064 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
AUTREY, S. F. Affiliation Unknown 45FR70874 1523 80/12/07 1p

8101220068 Comments on behalf of WA Energy Facility Site Evaluation Council on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy appears rational & reasonable Supports rule
FITCH, W. L Washington, State of 45FR66754 058 80/12/10 2pp 07500 066

8101220072 Comments on behalf of State Board of Health on proposed rule 10CFR2 re policy & procedure for enforcement actions Large fines on nuclear power plants will not achieve improvement in safety records of involved utilities
PICKARD, R. C Indiana, State of 45FR66754 073 80/12/22 1 07500 063

8101220074 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Except for serious & willful violations or gross negligence, civil penalties should be last step prior in order to shut down, suspend or revoke license
THOMAS, J. W Pennsylvania, Univ of 45FR66754 093 80/12/23 07500 063

8101220083 Forwards comments on proposed rule 10CFR2 re policy & procedure for enforcement actions NRC should re-examine need for very aggressive enforcement policy & suspend interim use until findings established
MINER, L. E Marquette Univ 45FR66754 096 80/12/31 11pp 07500 097

8101220089 Comments by American Hosp Association on proposed rule 10CFR2 re policy & procedure for enforcement actions Communications & educational programs should precede enforcement of fines & other penalties
FLAVADAN, R. J Affiliation Unknown 45FR66754 083 80/12/29 07500 046

8101220094 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Generally approves rule, but could like mechanism for appeal established, since different inspectors would have different interpretations of rule
HEHOEE, W. R Society of Nuclear Medicine 45FR66754 082 80/12/29 2pp 07500 094

8101220099 Comments by Baptist Memorial Hosp Sys on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy will probably increase medical costs w/no added benefit to public health
GCFE, D. L Affiliation Unknown 45FR66754 072 80/12/29 2pp 07500 092

8101220103 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Basis for civil penalty assessment should be damage to public health & safety resulting from specific violation
MIFTE, R. L Public Service Electric & Gas Co of New Jersey 45FR66754 099 80/12/31 3pp 07500 037

8101220111 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CURTIS, M. C Affiliation Unknown 45FR70074 1316 80/12/08

8101220118 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PRIED, J. Affiliation Unknown 45FR70874 1315 00/12/08 1

8101220120 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ROEMHILD, F Affiliation Unknown 45FR70874 1314 80/12/08

8101220125 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LENS, S Affiliation Unknown 45FR70074 1320 80/12/08 1p

8101220129 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GUTHALL, R Affiliation Unknown 45FR70874 1313 80/12/08 1

8101220134 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BOTTER, M Affiliation Unknown 45FR70074 1090 00/12/08 1

8101220136 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HARITZER, E Affiliation Unknown 45FR70874 1086 80/12/08

8101220142 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LYNCH, R Affiliation Unknown 45FR70074 1085 80/12/08 1p

E 8101220145 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
L10FR1.L Affiliation Unknown 45FR70874 1004 80/12/00 1p

E 8101220148 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ATKINSON.M Affiliation Unknown 45FR70874 1023 80/12/09 1p

E 8101220154 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FARBFR.R Affiliation Unknown 45FR70874 1082 80/12/08 1p

E 8101220159 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MERN.R Affiliation Unknown 45FR70874 1078 80/12/08 1p

E 8101220160 Comments by American Council on Education on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy may have potentially deleterious effect on scholarly research at colleges & univs
STERNBACH.S E Affiliation Unknown 45FR66754 080 80/12/22 4pp
07500 020

E 8101220165 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WEINSTEIN.A Affiliation Unknown 45FR70874 1076 80/12/08 1p

E 8101220169 Comments by WI Hosp Association on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy lacks clarity, incentives for encouraging licensees to report are not sufficient
VEN EIREN.H R Affiliation Unknown 45FR66754 081 80/12/22 2pp
07500 121

E 8101220170 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ZALAS.F D Affiliation Unknown 45FR70874 1075 80/12/00 1p

E 8101220173 Comments by Troutman, Sanders, Lockerman & Ashmore for OA Power Co on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy fails to provide positive incentives for self-policing by licensees
EDWARDS R F , ROSENBERG.S C Affiliation Unknown 45FR66754 085 80/12/20 4pp 07500 115

E 8101220178 Comments on behalf of BMW on proposed rule 10CFR2 re policy & procedure for enforcement actions Rule lacks clarity & objectivity Penalizing equipment failure as inconsistent w/ existing policy
EDGAR.G L Morgan, Lewis & Bockius 45FR66754 086 80/12/31 17pp 07500 096

E 8101220184 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CURRAN.B Affiliation Unknown 45FR70874 0937 80/12/01 1p

E 8101220227 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GISCARD.E.K. Affiliation Unknown 45FR70874 0586 80/12/08 1p

E 8101220263 Comments by Gray Panthers of Santa Barbara on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 1391 80/12/10 1p

E 8101220283 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ANDERSON.T H Westinghouse Electric Corp NS-TMA-2352 80/12/09 1p

E 8101220371 Forwards comments by Henry County Health Ctr on proposed rule 10CFR2 re policy & procedure for enforcement actions. Requests return of NRC views of encl ltr
JEPSELL.R Senate 45FR66754 107 80/12/06 3pp 07183 001

E 8101220482 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KEMPENICH.R Affiliation Unknown 45FR70874 1063 80/12/08 1p

E 8101220487 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
TATELMAN.J Affiliation Unknown 45FR70874 1064 80/12/08 1p

E 8101220509 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
JACOBOWITZ.E Affiliation Unknown 45FR70874 1065 80/12/08 1p

E 8101220514 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
SABOURIN.D A Affiliation Unknown 45FR70874 1066 80/12/08 1p

E 8101220519 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
* Affiliation Unknown 45FR70874 0631 80/12/08 1p

E 8101220524 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
GOETZ.M W Affiliation Unknown 45FR70874 0632 80/12/08 1p

E 8101220530 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
AFRAN.B Affiliation Unknown 45FR70874 0620 80/12/08 1p

E 8101220536 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
ROTH.L Affiliation Unknown 45FR70874 0622 80/12/08 1p

E 8101220544 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
DEPADLA.R N Affiliation Unknown 45FR70874 0623 80/12/08 1p

E 8101220547 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
HEAVER.J Affiliation Unknown 45FR70874 0624 80/12/08 1p

E 8101220554 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
BERTANI.E D Affiliation Unknown 45FR70874 0625 80/12/08 1p

E 8101220558 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
* Affiliation Unknown 45FR70874 0572 80/12/08 1p

E 8101220561 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
WALKER.M Affiliation Unknown 45FR70874 0543 80/12/08 1p

E 8101220564 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
O'DONNELL.C Affiliation Unknown 45FR70874 0585 80/12/08 1p

E 8101220568 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
TURBES.P Affiliation Unknown 45FR70874 1355 80/12/10 1p

E 8101220570 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
BRIDGEMAN.P Affiliation Unknown 45FR70874 1356 80/12/10 1p

E 8101220572 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
ALCURI.E C Affiliation Unknown 45FR70874 0500 80/12/08 1p

E 8101220576 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
DEGUZHAN.M D Affiliation Unknown 45FR70874 1357 80/12/10 1p

E 8101220579 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
DEGUZHAN.M D Affiliation Unknown 45FR70874 1358 80/12/10 1p

8101220580 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules CAKROCK, I Affiliation Unknown 45FR70874 1098 80/12/02 1p	8101220592 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules FUSCHNER, G Affiliation Unknown 45FR70874 0547 80/12/08
8101220583 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules Affiliation Unknown 45FR70874 0609 80/12/08 1p	8101220595 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules EIZENBERG, G Affiliation Unknown 45FR70874 0603 80/12/08
8101220585 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules LIGHTSTONE, A Affiliation Unknown 45FR70874 0611 80/12/08 1p	8101220597 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MENDELSCHEIN, D Affiliation Unknown 45FR70074 0602 80/12/08
8101220599 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ZELVIN, L Affiliation Unknown 45FR70874 1045 80/12/02 1p	8101220598 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules Affiliation Unknown 45FR70874 0607 80/12/08 1p
8101220594 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HINNANT, B L Affiliation Unknown 45FR70874 0579 80/12/02 1p	8101220500 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MOY, D Affiliation Unknown 45FR70374 0554 80/12/08 1p
8101220608 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SILVERMAN, A J Affiliation Unknown 45FR70874 1491 80/12/04 1p	8101220601 Comments on proposed App C to 10CFR2 re policy & procedure for enforcement actions Regulation goes beyond historical intent of Atomic Energy Act to promote peaceful use of atomic energy w/o jeopardizing common defense & security HOOVER, J J Union Carbide Corp 45FR66794 109 00/12/30 07309 001
8101220589 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ZELVIN, L Affiliation Unknown 45FR70874 1045 80/12/02 1p 07309 001	8101220602 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules PERTES, L Affiliation Unknown 45FR70874 0544 80/12/08 1p
8101220594 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HINNANT, B L Affiliation Unknown 45FR70874 0579 80/12/02 1p 07309 001	8101220604 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SALTZMAN, A Affiliation Unknown 45FR70874 0545 80/12/08
8101220608 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SILVERMAN, A J Affiliation Unknown 45FR70874 1491 80/12/04 1p 07500 168	8101220606 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SWARTZ, W M Affiliation Unknown 45FR70874 0546 80/12/08
8101220589 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ZELVIN, L Affiliation Unknown 45FR70874 1045 80/12/02 1p 07309 001	8101220609 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules KEPP, H L Affiliation Unknown 45FR70874 0498 80/12/08 1p
8101220594 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HINNANT, B L Affiliation Unknown 45FR70874 0579 80/12/02 1p 07309 001	8101220610 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SANCHEZ, R Affiliation Unknown 45FR70874 0496 80/12/08 1p
8101220608 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SILVERMAN, A J Affiliation Unknown 45FR70874 1491 80/12/04 1p 07500 168	8101220612 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules LEVELLE, W J Affiliation Unknown 45FR70874 0495 80/12/08
8101220589 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ZELVIN, L Affiliation Unknown 45FR70874 1045 80/12/02 1p 07309 001	8101220614 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Health & safety of site personnel & public should remain paramount, if not ultimate, concern for all parties FERGUSON, J H Virginia Electric & Power Co 45FR66794 100 80/12/31 4pp 07500 164
8101220594 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HINNANT, B L Affiliation Unknown 45FR70874 0579 80/12/02 1p 07309 001	8101220615 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DUBARRY, R Affiliation Unknown 45FR70874 0493 80/12/08
8101220608 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SILVERMAN, A J Affiliation Unknown 45FR70874 1491 80/12/04 1p 07500 168	8101220621 Comments on behalf of Houston Lighting & Power on proposed rule 10CFR2 re policy & procedure for enforcement actions Regulation places excessive emphasis on fines & penalties POWELL, D O Lowenstein, Neuman, Reiss, Axelrad & Toll 45FR66794 80/12/31 4pp 07500 160
8101220590 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules Affiliation Unknown 45FR70874 0549, 80/12/08 1p	8101220639 Forwards comments by H. Power Co to JA McClure on proposed rule 10CFR2 re policy & procedure for enforcement actions Particular attention should be given to citation for violations resulting from safety-related equipment failure HENDRIE, J H Commissioners 45FR66794 094 80/12/18 10pp 07309 001

B101230654 Comments on proposed rule 10CFR2.22 re priority & procedure for enforcement actions heavy fines & severe penalties for initial violators unfair
 FULCRA, R J Affiliation Unknown 45FR66754 105 80/12/08 1p
 07500 159

B101230001 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 GOMILAS, E Affiliation Unknown 45FR70874 0492 80/12/08 1p

B101230002 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 GELMAN, B Affiliation Unknown 45FR70874 0491 81/12/08 1p

B101230003 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 FEDERMAN, J Affiliation Unknown 45FR70874 0569 80/12/08 1p

B101230004 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 ORFELMAN, S Affiliation Unknown 45FR70874 0568 80/12/08 1p

B101230005 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 PUTMAN, A J Affiliation Unknown 45FR70874 0565 80/12/08 1p

B101230006 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 JANCFF, D Affiliation Unknown 45FR70874 0561 80/12/08 1p

B101230007 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 SICILIANO, A Affiliation Unknown 45FR70874 0560 80/12/08 1p

B101230008 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 ZADIFF, M Affiliation Unknown 45FR70874 0558 80/12/08 1p

B101230009 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 CESSIFF, S Affiliation Unknown 45FR70874 1009 80/12/08 2pp

B101230010 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 HEPLEY, J Affiliation Unknown 45FR70874 1007 83/12/08 2pp

B101230012 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 SHAH, S Affiliation Unknown 45FR70874 1041 80/12/08 2pp

B101230013 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 LEWIS, M I Affiliation Unknown 45FR70874 1050 80/12/08 2pp

B101230101 BECV-80-131A
 Summarizes comments on Commission action on BECV-80-131, "Nuclear Power Plant Accident Considerations under NEPA."
 Statement of interim policy should not be changed as result of comments FR notice on 1
 DIRKS, W J. Office of the Executive Director for Operations
 80/12/08 8pp 07511 064

B101230247 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 HASTINGS, E Affiliation Unknown 45FR70874 0454 80/12/08 1p

B101230253 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 HUME, K Affiliation Unknown 45FR70874 1427 80/12/10 1p

B101230264 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 GALLARDI, E Affiliation Unknown 45FR70074 1428

B101230269 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 GARRETT, P Affiliation Unknown 45FR70074 1428

B101230274 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 LITVACK, O Affiliation Unknown 45FR70874 1428

B101230278 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 KUNEZ, O Affiliation Unknown 45FR70874 1421

B101230284 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 WILLS, S Affiliation Unknown 45FR70874 1428

B101230291 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 WATERS, J. J Affiliation Unknown 45FR70874 1421

B101230294 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 BRINDEL, P Affiliation Unknown 45FR70874 1428

B101230300 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 SCHUMACHER, M Affiliation Unknown 45FR70874 1428

B101230304 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 SADLER, D Affiliation Unknown 45FR70074 1430

B101230310 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 CHRISTENSEN, U Affiliation Unknown 45FR70874 1428

B101230316 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 FLEBA, A Affiliation Unknown 45FR70074 1434

B101230321 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 COOPER, C Affiliation Unknown 45FR70074 1430

B101230325 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 MCLAUGHLIN, K Affiliation Unknown 45FR70874 1428

B101230329 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 PARK, M A Affiliation Unknown 45FR70874 1400

B101230331 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 ALLEN, S Affiliation Unknown 45FR70874 1405

B101230336 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 BERNI, A Affiliation Unknown 45FR70874 1404

B101230340 Comments on proposed rules 10CFR30.32, possession, use & transfer of low enriched U as in metals Opposes rules
 ORUFF, J Affiliation Unknown 45FR70874 1400

8101230342 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHWARTZ, J. L. Affiliation Unknown 45FR70874 1402 80/12/11. 1p

8101230346 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DILLINGHAM, M. Affiliation Unknown 45FR70874 1401 80/12/11 1p

8101230387 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JACOBS, A. M. Affiliation Unknown 45FR70874 0447 80/12/02 1p

8101230390 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BUNCE, D. J. Affiliation Unknown 45FR70874 0453 80/12/03. 1p

8101230578 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHNUR, M. Affiliation Unknown 45FR70874 0442 80/12/04 1p.

8101230584 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCKE, V. Affiliation Unknown 45FR70074 0444. 08/12/04 1p

8101230587 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RUSSELL, H. L. Affiliation Unknown 45FR70874 0448 80/12/04 1p

8101230591 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ADDON, J. L. Affiliation Unknown 45FR70874 0449 80/12/04 1p

8101230596 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LYNN, L. Affiliation Unknown 45FR70074 0443 80/12/05 1p

8101230617 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PEBTQUE, B. Affiliation Unknown 45FR70874 0445 80/12/05. 1p

8101230621 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KOROWITZ, J. Affiliation Unknown 45FR70874 0450 80/12/05 1p

8101230624 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ENIKIN, D. Affiliation Unknown 45FR70874 0431 80/12/05. 1p

8101230630 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FLANAGAN, E. Affiliation Unknown 45FR70874 0452 80/12/05 1p

8101230634 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TITUS, V. Affiliation Unknown 45FR70874 1424. 00/12/05 1p

8101230640 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCREE, V. Affiliation Unknown 45FR70074 0438 80/12/06 1p

8101230645 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KLEDANOW, A. Affiliation Unknown. 45FR70874 1426 80/12/07 1p

8101230655 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BROWN, P. Affiliation Unknown 45FR70874 1410. 80/12/09 1p

8101230664 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
NOWLIN, D. Affiliation Unknown 45FR70874 1411 80/12/09 1p

8101230670 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VIRAMONTES, S. Affiliation Unknown 45FR70874 1425 80/12/09

8101260302 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PATTEN, L. Affiliation Unknown 45FR70874 0467 80/12/00 1p

8101260005 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WASHINGTON, R. Affiliation Unknown 45FR70874 0466 80/12/08

8101260007 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PALLER, L. C. Affiliation Unknown 45FR70074 0465 00/12/09

8101260308 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MILLS, S. Affiliation Unknown 45FR70874 0464 80/12/08 1p

8101260011 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JCSO, J. M. Affiliation Unknown 45FR70874 0453 80/12/08 1p

8101260014 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SIEMRA, J. Affiliation Unknown 45FR70074 0462 80/12/08 1p

8101260023 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HEBEZ, A. Affiliation Unknown. 45FR70874 0461 80/12/08 1p

8101260327 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHEAR, M. Affiliation Unknown 45FR70074 0460 80/12/00 1p

8101260032 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RINIRA, M. Affiliation Unknown. 45FR70874 0459 80/12/00 1p

8101260036 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCINTYRE, T. Affiliation Unknown 45FR70874 0439 80/12/08

8101260048 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAYTAN, D. W. Affiliation Unknown 45FR70074 0437 00/12/08

8101260051 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TIMOTHY, H. Affiliation Unknown 45FR70874 0458 80/12/08

8101260055 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCANLON, A. Affiliation Unknown 45FR70074 0457 80/12/08 1p

8101260059 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PEARLMAN, C. Affiliation Unknown 45FR70874 0456. 80/12/08

8101260062 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BERO, R. A. Affiliation Unknown. 45FR70874 0440. 80/12/08 1p

8101260066 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WEBB, A. Affiliation Unknown 45FR70874 0446 80/12/00 1p

8101260069 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ANN, S. Affiliation Unknown 45FR70074 0455 80/12/08 1p

B101260074 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TUTTLE, B P Affiliation Unknown 45FR70874 2434 80/12/16 1p

B101260090 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DAY, G Affiliation Unknown 45FR70874 2435 80/12/16 1p

B101260104 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAGAK, J Affiliation Unknown 45FR70874 2433 80/12/16 1p

B101260111 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CRONE, I Affiliation Unknown 45FR70874 2432 80/12/16 1p

B101260121 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHARTAUD, D J Affiliation Unknown 45FR70874 2431 80/12/16 1p

B101260130 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LUNNINGHAM, R S Affiliation Unknown 45FR70874 2430 80/12/16 1p

B101260149 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHENSTEIN, J Affiliation Unknown 45FR70874 2426 80/12/16 1p

B101260157 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DIALOND, M D Affiliation Unknown 45FR70874 2427 80/12/16 1p

B101260167 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WATTERS, R Affiliation Unknown 45FR70874 2428 80/12/16 1p

B101260172 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MERK, D Affiliation Unknown 45FR70874 2422 80/12/16 1p

B101260179 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CELLENG, S Affiliation Unknown 45FR70874 2418 80/12/16 1p

B101260183 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2417 80/12/16 1p

B101260191 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
O'CONNELL, P Affiliation Unknown 45FR70874 2414 80/12/16 1p

B101260194 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCCLENNOCK, S Affiliation Unknown 45FR70874 2410 80/12/16 1p

B101260203 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MURDOCH, J Affiliation Unknown 45FR70874 2412 80/12/16 1p

B101260210 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHWILDER, R W Affiliation Unknown 45FR70874 2411 80/12/16 1p

B101260217 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HENDRICKS, J C Affiliation Unknown 45FR70874 2410 80/12/16 1p

B101260229 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LAURENCE, C L Affiliation Unknown 45FR70874 2409 80/12/16 1p

B101260233 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2408 80/12/16 1p

B101260239 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
EENNETT, C Affiliation Unknown 45FR70874 2407 80/12/16 1p

B101260263 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2406 80/12/16 1p

B101260275 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SPITZ, M Affiliation Unknown 45FR70874 2405 80/12/16 1p

B101260287 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DCHALSON, B J Affiliation Unknown 45FR70874 2404 80/12/16 1p

B101260293 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCREECHFIELD, J Affiliation Unknown 45FR70874 2403 80/12/16 1p

B101260299 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
QAGNON, R Affiliation Unknown 45FR70874 2402 80/12/16 1p

B101260305 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
NIEVEROM, L P Affiliation Unknown 45FR70874 2401 80/12/16 1p

B101260309 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2366 80/12/16 1p

B101260322 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2365 80/12/16 1p

B101260330 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DAVIDSON-ROLLIN Affiliation Unknown 45FR70874 2364 80/12/16 1p

B101260336 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MARTIN, A Affiliation Unknown 45FR70874 2363 80/12/16 1p

B101260343 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VAUPEL, J K Affiliation Unknown 45FR70874 2362 80/12/16 1p

B101260350 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCORE, C Affiliation Unknown 45FR70874 2361 80/12/16 1p

B101260354 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HANLEY, K Affiliation Unknown 45FR70874 2360 80/12/16 1p

B101260356 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2359 80/12/16 1p

610126C647 Comments on proposed rules 16CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Dposes rules
MUELLER, A Affiliation Unknown 45FR70874 2444 60/12/16 1p

0101260655 Comments on proposed rules 10CFR30 32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CRAVER, E Affiliation Unknown 45FR00074 2443 60/12/16 lp

8101260660 Comments on proposed rules 16CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opponees rules
KEVIN MILLER, A Affiliation Unknown 45FR70374 2442 80/12/15

0101200565 Comments on proposed rules 10CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Duplicates rules
BALLARD, B Affiliation Unclear 45FR70874 2441 80/12/16 1p

01012606B2 Comments on proposed rules 10CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in reals Opposes rules
BUCHHINO, C Affiliation: Unknown 45FR70874 2440 03/12/16 tp

0101260606 Comments on proposed rules 10CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
MAY, M Affiliation Unknown 45FR79874 2434 80/12/16 16

0181240691 Comments on proposed rules 10CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
SCHEMATA, M. Affiliation Unknown 45FR70074 2433 00/12/16 1p

0101260695 Comments on proposed rules 10CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
WEATHERBY, J R Affiliation Unknown 15FR70274 2437. 80/12/16.

B101260702 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals processes rules
LAFFRENIERE, J AFFILIATION Unknown 45FR70874 2436 00/12/16

101260703 Comments on proposed rules 18CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals opposes rules.
 GR4:1 Affiliation Unknown 19F870874 2355 EO/12/16 1p

6181260709 Comments on proposed rules 10CFR39, 32.70 & 190 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
ALEXCF.F J T Affiliation Unknown 45FR70874 2338 00/12/16

80126071: Comments on proposed rules 10CFR30, 32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MILBURN, D A Affiliation Unknown. 451R70874 2277 80/12/16

B0126D717 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JOHNSTON, A Affiliation Unknown 45FR70874 2276 88/12/16 1

810126072] Comments on proposed rules 10CFR30.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
KATZ, K Affiliation Unknown 45FR78074 2275 80/12/16 1p

B101260727 Comments on proposed rules 10CFR20.32.70 & 190 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAXWILL, R D Affiliation Unknown 45FR70874 2274 B3/12/16 1

B10126073 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HAYWARD, C A Affiliation Unknown. 45FR70874 2273 80/12/16

810126074B Comments on proposed rules 10CFR30.32, 7B & 150 re
possession, use & transfer of low enriched U as contaminant
in metals. Opposes rules
BUSH, L Affiliation Unknown 45FR70874 2272 80/12/16 1p

8101260746 Comments on proposed rules 10CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
TRANSESTER, V Affiliation Unknown 45FR70874 2271 80/12/16

B01260762 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VINCIGLI, M Affiliation Unknown 45FR70874 2269 80/12/16 1p

B01260766 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TELFORD, J Affiliation Unknown 45FR70874 2270 80/12/16 1p

B01270007 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2268 80/12/16 1p

B01270033 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2267 80/12/16 1p

B01270036 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2266 80/12/16 1p

B01270012 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PHILLIPS, L Affiliation Unknown 45FR70874 2265 80/12/16 1p

B01270014 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
THOMSON, W G Affiliation Unknown 45FR70874 2264 80/12/16 1p

B01270017 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WEAVER, M Affiliation Unknown 45FR70874 2266 80/12/16 1p

B01270018 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2262 80/12/16 1p

B01270020 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SENNER, S L Affiliation Unknown 45FR70874 2261 80/12/16 1p

B01270022 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2260 80/12/16 1p

B01270028 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PEEFER, S C Affiliation Unknown 45FR70874 2258 80/12/16 1p

B01270033 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ROSE, G A Affiliation Unknown 45FR70874 2303 80/12/16 1p

B01270039 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MORSEBON, J Affiliation Unknown 45FR70874 2302 80/12/16 1p

B01270050 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BENEL, P A Affiliation Unknown 45FR70874 2301 80/12/16 1p

B01270275 Transcript from Affirmation Session 80-56 on B01222 in Washington, DC Pp 1-7 Includes consideration of SECY-80-925 re open govt FOIA appeal, SECY-A-146A re Tyrone decision, SECY-80-507 & SECY-80-401
* Commissioners 80/12/22 9pp 07546 117

B01270293 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules

B01270320 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ALTMAN, L Affiliation Unknown 45FR70874 2269 80/12/16 1p

B01270335 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BACKEB, C Affiliation Unknown 45FR70874 2268 80/12/16 1p

B01270310 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TODT, R Affiliation Unknown 45FR70874 2267 80/12/16 1p

B01270316 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FIELDS, J Affiliation Unknown 45FR70874 2266 80/12/16 1p

B01270320 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RICHING, D Affiliation Unknown 45FR70874 2265 80/12/16 1p

B01270325 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
REITSTADLER, J Affiliation Unknown 45FR70874 2264 80/12/16 1p

B01270331 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
STUDER, M Affiliation Unknown 45FR70874 2263 80/12/16 1p

B01270335 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KILLGARD, K Affiliation Unknown 45FR70874 2262 80/12/16 1p

B01270340 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PERRY, L Affiliation Unknown 45FR70874 2261 80/12/16 1p

B01270365 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KRINGHAUS, G C Affiliation Unknown 45FR70874 2260 80/12/16 1p

B01270371 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WARNER, R B Affiliation Unknown 45FR70874 2259 80/12/16 1p

B01270374 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DUNHAU, A K Affiliation Unknown 45FR70874 2258 80/12/16 1p

B01270381 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEVY, P Affiliation Unknown 45FR70874 2322 80/12/16 1p

B01270384 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RYAN, A B Affiliation Unknown 45FR70874 2321 80/12/16 1p

B01270393 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ALLSUP, M M Affiliation Unknown 45FR70874 2320 80/12/16 1p

B01270399 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SOLDESTIN, J Affiliation Unknown 45FR70874 2319 80/12/16 1p

B01270407 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2318 80/12/16 1p

B101270415 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MARTINEZ, A Affiliation Unknown 45FR70874 2283 80/12/16 1p	B101270824 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ESTES, O Affiliation Unknown 45FR70874 1054 80/11/27 1p
B101270421 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules WILTMAN, R R Affiliation Unknown 45FR70874 2282 80/12/16 1p	B101270830 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DETILLE, R E Affiliation Unknown 45FR70874 0597 80/11/22
B101270426 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules WOOD, X Affiliation Unknown 45FR70874 2281 80/12/16 1p	B101270835 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 1061 80/11/20 1p
B101270432 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules RAMEY, J A Affiliation Unknown 45FR70874 2280 80/12/16 1p	B101270839 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules OLIVIA, A Affiliation Unknown 45FR70874 1312 80/11/28
B101270437 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules THOMPSON, R Affiliation Unknown 45FR70874 2279 80/12/16 1p	B101270844 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules OLIVER, L Affiliation Unknown 45FR70874 1103 80/11/29
B101270445 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules PORTER, D Affiliation Unknown 45FR70874 2300 80/12/16 1p	B101270856 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules GARCEA, D Affiliation Unknown 45FR70874 1502 80/11/30
B101270449 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HATO, C Affiliation Unknown 45FR70874 2299 80/12/16 1p	B101270858 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules WARTER, D Affiliation Unknown 45FR70874 0543 80/11/30
B101270534 Submit a list of facilities within US not associated w/activities w/direct natl security significance to govt of US * Commissioners 80/11/26 40pp 07543 308	B101280308 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HATZEL, H Affiliation Unknown 45FR70874 2740 80/12/04 1p
B101270757 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HADLEY, K Affiliation Unknown 45FR70874 1377 80/12/10 1p	B101280315 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 2742 80/12/04 1p
B101270761 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules LANTZ, D E Affiliation Unknown 45FR70874 1334 80/12/11 1p	B101280319 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HABEL, C Affiliation Unknown 45FR70874 2741 80/12/04 1p
B101270773 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DECK, K Affiliation Unknown 45FR70874 1342 80/12/11 1p	B101280322 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 2731 80/12/04 1p
B101270778 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MUEGE, J Affiliation Unknown 45FR70874 1595 80/12/07 1p	B101280326 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 2750 80/12/04 1p
B101270781 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MUREAU, D Affiliation Unknown 45FR70874 1074 80/12/07 1p	B101280329 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 1936 80/12/03 1p
B101270793 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules BRAYSON, Y Affiliation Unknown 45FR70874 0583 80/11/03 1p	B101280338 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules EASTMAN, J Affiliation Unknown 45FR70874 2743 80/12/03
B101270801 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules PRECESTIN, O Affiliation Unknown 45FR70874 0055 80/11/26 1p	B101280341 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules PARKER, D Affiliation Unknown 45FR70874 2746 80/12/03
B101270804 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MAYO, I Affiliation Unknown 45FR70874 0069 80/11/25 1p	B101280344 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 0060 80/12/03 1p
B101270811 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules POSE, K Affiliation Unknown 45FR70874 0640 80/11/25 1p	B101280345 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules LERNER, D Affiliation Unknown 45FR70874 0068 80/12/03
B101270817 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SINER, T Affiliation Unknown 45FR70874 1553 80/11/29 1p	B101280349 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MERONE, P Affiliation Unknown 45FR70874 0062 80/12/03

B101280446 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SUTTER, E Affiliation Unknown 45FR70874 0651 80/12/03 1p

B101280458 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BELLON, B Affiliation Unknown 45FR70874 0653 80/12/03 1p

B101280463 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SIGNESS, G Affiliation Unknown 45FR70874 0654 80/12/03 1p

B101280466 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCCRE, M R Affiliation Unknown 45FR70874 0655 80/12/03 1p

B101280474 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KELLER, J J Affiliation Unknown 45FR70874 0667 80/12/03 1p

B101280475 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BELFRY, D Affiliation Unknown 45FR70874 3226 80/12/13 1p

B101280485 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
Affiliation Unknown 45FR70874 2521 80/12/13 1p

B101280493 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GRIEN, S S Affiliation Unknown 45FR70874 2516 80/12/13 1p

B101280500 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PASE, P Affiliation Unknown 45FR70874 2629 80/12/13 1p

B101280503 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HAYVIC, E L Affiliation Unknown 45FR70874 2629 80/12/13 1p

B101280537 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LINDHOLD, M J Affiliation Unknown 45FR70874 2633 80/12/13 1p

B101280570 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MEBB, C Affiliation Unknown 45FR70874 2827 80/12/11 1p

B101280597 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHANSON, M Affiliation Unknown 45FR70874 2829 80/12/11 1p

B101280604 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ALEXANDER, P Affiliation Unknown 45FR70874 2821 80/12/11 1p

B101280607 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HARRO, L C Affiliation Unknown 45FR70874 3261 80/12/11 1p

B101280715 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FEILER, I Affiliation Unknown 45FR70874 2757 80/12/11 1p

B101280737 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
Affiliation Unknown 45FR70874 2756 80/12/11 1p

B101280742 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SARGENT, S Affiliation Unknown 45FR70874 1970 80/12/11 1p

B101280446 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SUTTER, E Affiliation Unknown 45FR70874 0651 80/12/03 1p

B101280458 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BELLON, B Affiliation Unknown 45FR70874 0653 80/12/03 1p

B101280463 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SIGNESS, G Affiliation Unknown 45FR70874 0654 80/12/03 1p

B101280466 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCCRE, M R Affiliation Unknown 45FR70874 0655 80/12/03 1p

B101280470 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KELLER, J J Affiliation Unknown 45FR70874 0667 80/12/03 1p

B101280475 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BELFRY, D Affiliation Unknown 45FR70874 3226 80/12/13 1p

B101280485 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCCRE, J J Affiliation Unknown 45FR70874 2521 80/12/13 1p

B101280544 Comments on proposed rule 10CFR2 re policy & procedures for enforcement actions Power reactor licensees Board of review should be established to ensure severity level consistent with 10CFR2.103pp 07997 326

B101280555 Comments on proposed rule 10CFR2 re policy & procedures for enforcement actions Power reactor licensees Board of review should be established to ensure severity level consistent with 10CFR2.103pp 07997 314

B101290038 Advises recipients of comments on proposed rules 10CFR30.32.70 & 150 that comments numbered 380 through 402 are mislabeled Comment Numbers 360 through 402 will be re-used
* Docketing & Services Branch, 45FR70874 0651 80/12/03 1p

B101290063 Forwards comments on behalf of utility 10CFR170 re fees for review of applications for siting criteria Rules should prevent future siting criteria changes
CHARNOFF, D Shaw, Pittman, Potts & Trowbridge 80/12/08 29pp 07968 230

B101290088 Comments on proposed rules 10CFR50.51 siting criteria Rules should prevent future siting criteria changes
PAYNE, J B Affiliation Unknown 45FR50350 07957 360

B101290112 Comments on proposed rule 10CFR50 re hydrogen control & certain degraded core conditions Negative safety impacts not adequately considered against benefits to be gained
NOVARRO, J P Long Island Lighting Co 45FR6103pp 07967 357

B101290137 Comments on proposed rule 10CFR50 re hydrogen control & certain degraded core conditions considerations implementation on interim basis waste of resources
TRIMBLE, D C Arkansas Power & Light Co 45FR6104pp 07975 036

B101290156 Comments on proposed rule 10CFR50 re design changes Rule would take design changes out of process Eventually litigants would be contending approved designs that have no basis
LEWIS, M I Affiliation Unknown 45FR61602 07975 034

8101290168 Comments on proposed rule 10CFR73 re requiring thorough search of individuals before entering sensitive areas of nuclear power plants Supports rule Rule should be put into effect as soon as possible
WUDSON, W K Affiliation Unknown 45FR79492 033 80/12/22 1p 07575 033

8101290184 Comments on proposed rule 10CFR73 re requiring thorough search of individuals before entering sensitive areas of nuclear power plants Submits recommended definition of visitor to be used in rule
UTLEY, E E Carolina Power & Light Co 45FR79492 004 80/12/24 2pp 07575 032

8101290392 Unofficial transcript of 800107 Commission meeting in Washington, DC re BECY-80-474, final rule, 10CFR60. "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures " Pp 1-86
* Commissioners 81/01/07 88pp 07570 091

--8101290399 Submits draft language changes to original text of BECY-80-474 for 10CFR60 Final rulemaking Ofc of General Council concerns re NRC deference to DOE on common defense & security matters addressed
BICKWIT, L Office of the General Counsel 81/01/06 2pp 07570 090

---8101290405 Discusses procedural aspects of final rule deserving further Commission consideration prior to approval of publication as part of 10CFR60. "Disposal of High Level Radwaste in Geologic Repositories " Licensing policy statement encl
HARRAHAN, E J Office of Policy Evaluations. 81/01/06 5pp. 07570 091

--8101290410 Confirms discussion w/ W Dircks re dept concerns w/ proposed regulations governing disposal of high level radwaste. Commission accommodation of dept views on problems outlined in 800303 ltr requested prior to issuing final rule.
* Energy, Dept of. 81/01/06 2pp 07570 096

--8101290415 Staff requirements memo re discussion of BECY-80-474 final rule, 10CFR60. "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures " Commissioner views on proposed memo to BECY-80-474 encl
CHILK, B J Office of the Secretary of the Commission 80-474 81/01/05 4pp. 07570 098.

--8101290420 Suggests memo to BECY-80-474 final rule, 10CFR60. "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures."
BRAOFOFO, P A Commissioners 80/12/18 4pp 07570 102

8101290560 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KELLER, A C Affiliation Unknown 45FR 70874 1992 80/12/11 1p

8101290566 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
YOUNG, F. Affiliation Unknown 45FR70874 2499. 80/12/11 1p

8101290570 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CORNWALL, H Affiliation Unknown 45FR70874 2524 80/12/11 1p

8101290572 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
PORTER, A Affiliation Unknown 45FR70874 2500. 80/12/11 2pp

8101290582 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 3220 81/01/05 1p

8101290585 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
IRWIN, S Affiliation Unknown 45FR70874 3221 81/01/05 1p

8101290639 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHNEIDER, S Affiliation Unknown 45FR70874 1502 80/12/08 2pp

8101290644 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHERRY, R H Affiliation Unknown. 45FR70874 2509 80/12/08 1p

8101290647 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
LAUSHER, L Affiliation Unknown 45FR70874 2502 80/12/08

8101290660 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RYAN, G E H Affiliation Unknown 45FR70874 1968 80/12/08

8101290663 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COHEN, S Affiliation Unknown 45FR70874 1913 80/12/08 1p

8101290665 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HASTINGS, E H Affiliation Unknown 45FR70874 1906 80/12/08

8101290670 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CEENA, B W Affiliation Unknown 45FR70874 2749 80/12/08

8101290677 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WDA, E Affiliation Unknown 45FR70874 2573 80/12/08 2pp

8101290681 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LUCAS, R O Affiliation Unknown 45FR70874 2596 80/12/08 1p

8101290693 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
SUND, D Affiliation Unknown 45FR70874 2611 80/12/08 1p

8101290698 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
GRAVELLE, D. Affiliation Unknown 45FR70874 1961 80/12/08

8101290699 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
AMBER, W Affiliation Unknown. 45FR70874 1946 80/12/08 1p

8101290704 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCDONNELL, S A Affiliation Unknown 45FR70874 1944 80/12/08

8101290709 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
NICHOLS, C E A Affiliation Unknown 45FR70874 1941. 80/12/08

8101290714 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HENZLERING, L E Affiliation Unknown 45FR70874 1923 80/12/08 1p

8101290716 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 1896 80/12/08 1p

8101290719 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CARP, P Affiliation Unknown 45FR70874 2324 80/12/08 1p

8101290721 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
STEIN, L L Affiliation Unknown 45FR70874 2314. 80/12/08 1

8101290725 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PHOULT, N Affiliation Unknown 45FR70874 2310 80/12/08 1p

B101299727 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 EATON, T. M. Affiliation Unknown 45FR70874 2307 80/12/08 1p

B10129730 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 FEINER, D. A. Affiliation Unknown 45FR70874 2318 80/12/08 1p

B10129732 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 GILQUZ, M. A. Affiliation Unknown 45FR70874 1940 80/12/08 2pp

B10129735 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 HADDICK, R. Affiliation Unknown 45FR70874 1930 80/12/08 2pp

B101297001 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 KERRS, R. Affiliation Unknown 45FR70874 2972 80/12/05 1p

B101296002 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 * Affiliation Unknown 45FR70874 2747 80/12/05 1p

B101296003 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 MINER, U. Affiliation Unknown 45FR70874 2745 80/12/05 1p

B101296004 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 NICHOLSON, C. Affiliation Unknown 45FR70874 2567 80/12/05 1p

B101300105 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 KOLMER, M. Affiliation Unknown 45FR70874 1993 80/12/05 1p

B101300006 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 REEDS, S. Affiliation Unknown 45FR70874 1921 80/12/05 1p

B101300007 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 LASCOLO, J. Affiliation Unknown 45FR70874 1920 80/12/05 1p

B101300010 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 THOMAS, B. Affiliation Unknown 45FR70874 2015 80/12/10 1p

B101200016 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 MORRIS, O. Affiliation Unknown 45FR70874 3118 80/12/10 1p

B101300023 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 WALSH, J. Affiliation Unknown 45FR70874 2845 80/12/10 1p

B101300039 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 EDWARDS, L. D. Affiliation Unknown 45FR70874 2967 80/12/06 1p

B101300047 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 BLACKETT, S. F. Affiliation Unknown 45FR70874 2703 80/12/05 1p

B101300053 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 MASOGLU, Affiliation Unknown 45FR70874 1956 80/12/06 1p

B101300058 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 NABRACCI, T. Affiliation Unknown 45FR70874 3034 80/12/10 1p

B101300061 Responds to B101210 letter expressing comments on proposed rules 10CFR30.32.70 & 150, prompting comments on residual radioactive contamination from licensing requirements. Comments will be addressed in final OIRCP5. H. J. Office of the Executive Director for RI/01/09 2pp

B101300063 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 STERN, H. Affiliation Unknown 45FR70874 2733

B101300064 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 ROGERMAN, E. Affiliation Unknown 45FR70874 130

B101300071 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 * Affiliation Unknown 45FR70874 2784 80/12/05

B101300076 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 LESTER, D. Affiliation Unknown 45FR70874 3297

B101300079 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 SPIEGEL, J. Affiliation Unknown 45FR70874 2511

B101300081 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 DELMAN, J. B. Affiliation Unknown 45FR70874 240

B101300084 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 * Affiliation Unknown 45FR70874 1369 80/12/05

B101300086 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 * Affiliation Unknown 45FR70874 2744 80/12/05

B101200090 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 MCARDY, C. S. Affiliation Unknown 45FR70874 2133

B101300094 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 PINSKY, R. Affiliation Unknown 45FR70874 2739

B101300095 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 KULFE, P. Affiliation Unknown 45FR70874 2730

B101300100 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 RIBBLI, M. Affiliation Unknown 45FR70874 2326

B101300101 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 MISHA, A. Affiliation Unknown 45FR70874 2748

B101300102 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 GILBERT, G. D. Affiliation Unknown 45FR70874 2

B101300105 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 LUSKE, L. Affiliation Unknown 45FR70874 2328

B101300110 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
 GUSTAFSON, J. Affiliation Unknown 45FR70874 2

NONDOCKETED ITEMS

8101300111 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BOJRLAND, U J Affiliation Unknown 45FR70874 2333 80/12/10 2pp

8101300112 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEGNARO, D B Affiliation Unknown 45FR70874 2332 80/12/10 2pp

8101300110 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ZAVLBERGEN, H Affiliation Unknown 45FR70874 2335 80/12/10 2ip

8101300124 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MUELLER, P E Affiliation Unknown 45FR70874 1791 80/12/10 2pp

8101300130 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2291 80/12/07 1p

8101300132 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
O'NEIL, M Affiliation Unknown 45FR70874 2335 80/12/10 2pp

8101300135 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ROSEMAN, M L Affiliation Unknown 45FR70874 2334 80/12/10 2pp

8101300137 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VANKILIK, B Affiliation Unknown 45FR70874 2337 80/12/10 2pp

8101300140 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WEAVER, D A Affiliation Unknown 45FR70874 1492 80/12/07 2pp

8101300142 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MITCHELL, M E Affiliation Unknown 45FR70874 2270 80/12/10 2pp

8101300146 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CLEGG, M Affiliation Unknown 45FR70874 2405 80/12/10 2pp

8101300149 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
OCKERY, N M Affiliation Unknown 45FR70074 2579 80/12/07 1p.

8101300150 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WILITE, K Affiliation Unknown 45FR70874 2403 80/12/10 2pp

8101300159 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JULIAN, D Affiliation Unknown 45FR70074 2582 80/12/07 1p.

8101300166 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
YOUNGBLOOD, E M Affiliation Unknown 45FR70874 2584 80/12/07 1p

8101300174 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KUETT, K. Affiliation Unknown 45FR70874 2656 80/12/07 1p

8101300179 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules

8101300104 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JONES, J Affiliation Unknown 45FR70874 2774 80/12/07

8101300192 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CEGENFELDER, E Affiliation Unknown 45FR70874 2715 80/12/07

8101300200 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HILLAND, D Affiliation Unknown 45FR70874 2760 80/12/07

8101300207 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SMALLWOOD, J C Affiliation Unknown 45FR70874 2784 80/12/07

8101300215 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KALGANI, J Affiliation Unknown 45FR70874 1923 80/12/07

8101300232 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2292 80/12/07 1p

8101300236 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WILCOX, W Affiliation Unknown 45FR70874 2397 80/12/10

8101300241 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LOSTYR, R S Affiliation Unknown 45FR70874 2398 80/12/10

8101300247 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHITH, K Affiliation Unknown 45FR70874 2295 80/12/07 1p

8101300255 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WILLIS, C Affiliation Unknown 45FR70874 2399 80/12/10

8101300257 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SIETRAN, A Affiliation Unknown 45FR70874 2290 80/12/07

8101300263 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HALL, L F T Affiliation Unknown 45FR70874 1715 80/12/10

8101300268 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEWIS, S Affiliation Unknown 45FR70074 2269 80/12/07 1p

8101300269 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FERNANDEZ, Z Affiliation Unknown 45FR70874 1795 80/12/10

8101300275 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PERRER, T R Affiliation Unknown 45FR70874 1716 80/12/10

8101300277 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
STEADMAN, F H Affiliation Unknown 45FR70074 2288 80/12/07

8101300280 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MORRIS, R L Affiliation Unknown 45FR70874 1812 80/12/10

8101300362 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHICARAY, C Affiliation Unknown 45FR70874 3213 80/12/10 1p

8101300331 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCHARRAY, A Affiliation Unknown 45FR70874 2295 82/12/07 1p

8101300334 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KREIS, J Affiliation Unknown 45FR70874 1821 80/12/10 1p

8101300339 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KORN, L Affiliation Unknown 45FR70874 1822 80/12/10 1p

8101300343 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CERRATO, M Affiliation Unknown 45FR70874 2577 80/12/10 1p

8101300353 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VILALE, R Affiliation Unknown 45FR70874 2578 80/12/10 1p

8101300362 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KINO, D Affiliation Unknown 45FR70874 2708 80/12/10 1p

8101300369 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GRANIERI, M Affiliation Unknown 45FR70874 2586 80/12/10 1p

8101300375 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TOTH, P Affiliation Unknown 45FR70874 2597 80/12/10 1p

8101300388 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2571 80/12/10 1p

8101300391 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PATTEN, G Affiliation Unknown 45FR70874 2558 80/12/10 1p

8101300403 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VANDER BELT, R Affiliation Unknown 45FR70874 2562 80/12/10 1p

8101300405 Unofficial transcript of Commission 810115 meeting in Washington, DC re Affiliation Session 81-2 to discuss Waste Confidence rulemaking Pp 1-5
* Commissioners 81/01/15 App 07283 219

--8101300416 Forwards proposed memorandum & order authorizing use of consultants to assist Commission working group w/waste confidence rulemaking proceeding Memorandum & order should be adopted & issued
MILLER, M E Atomic Safety and Licensing Board Panel 80/12/19 App 07563 220

8101300419 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAGY, E R Affiliation Unknown 45FR70874 2568 80/12/10 1p

8101300422 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PISFLO, D M Affiliation Unknown 45FR70874 2551 80/12/10 1p

8101300449 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MURPHY, B L Affiliation Unknown 45FR70874 3212 80/12/15 1p

8101300462 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BIAZ, C Affiliation Unknown 45FR70874 3213

8101300472 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JONES, T Affiliation Unknown 45FR70874 3216

8101300480 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RAMS, W D L Affiliation Unknown 45FR70874

8101300482 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
IAC, M Affiliation Unknown 45FR70874 3223

8101300485 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BAKKIS, P Affiliation Unknown 45FR70874 3221

8101300489 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HANNAN, S Affiliation Unknown 45FR70874 3221

8101300497 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GALLICHO, J Affiliation Unknown 45FR70874

8101300505 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JAWLEY, L Affiliation Unknown 45FR70874 3221

8101300516 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
THURTELL Affiliation Unknown 45FR70874 3221

8101300521 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCCAULEY, S Affiliation Unknown 45FR70874

8101300526 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COSNER, D P Affiliation Unknown 45FR70874

8101300531 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BINSFELD, J Affiliation Unknown 45FR70874 3197

8101300536 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HAYES, L Affiliation Unknown 45FR70874 3197

8101300540 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CAURACHO, R Affiliation Unknown 45FR70874

8101300544 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VANUERSK, M Affiliation Unknown 45FR70874

8101300545 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SEDT, L Affiliation Unknown 45FR70874 3209

8101300547 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 3211 80/12/10

8101300550 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 3240 80/12/10

01300552 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HARVEY, N Affiliation Unknown 45FR70874 2815 80/12/15 1p

01300556 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HDLT, J Affiliation Unknown 45FR70874 2812 80/12/15 1p

01300606 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
REEVES, F P Affiliation Unknown 45FR70874 2640 00/12/15 1p

01300669 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PERKINS, J Affiliation Unknown 45FR70874 2708 80/12/15 1p

01300679 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRIEN, K A Affiliation Unknown 45FR70874 3067 00/12/15 1p

01300794 Certified minutes of ACRS Subcommittee on Waste Mgt 201113-14 meeting in Washington, DC re proposed rulemaking on storage & disposal of nuclear waste FR notice & attendee list encl
ACRS - Advisory Committee on Reactor Safeguards 80/12/11 14pp
07584 200

01300821 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MARTUOLTA, B Affiliation Unknown 45FR70874 1794 00/12/16 1p

01300828 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KINCHLOE, J Affiliation Unknown 45FR70874 1793 80/12/16 1p

01300834 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HUNDGH, C Affiliation Unknown 45FR70874 1718 80/12/16 1p

01300840 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FRANCIS, D. Affiliation Unknown 45FR70874 1749 80/12/16 1p

01300850 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ALVERIO, A Affiliation Unknown 45FR70874 1748 80/12/16 1p

01140992 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ANDERSON, E I. Affiliation Unknown 45FR70874 1465 80/12/10 1p
07308 001.

1 PETITION FOR RULEMAKING

02080008 BECY-00-901
Forwards proposed FR notice on disposition of Critical Mass Energy Project, et al petition for rulemaking re emergency response, draft ltr to petitioners & proposed Congressional ltr to Representative FM Udall
HINOUE, R D Office of Standards Development, Director. 80/11/07 1pp. 03767.181

2290489 Transcript of 801211 Affirmation Session 80-54 in Washington, DC re BECY-80-14B, SECY-A-80-168 & SECY-80-482
1-11
Commissioners 80/12/11. 13pp 07435.142

01160212 Forwards FR notice of petition for rulemaking 30-57 re amend of exemption for ionizing radiation measuring instruments No ltrs have been received in response to notice.
HENRY, J. J. Transportation & Product Standards Branch. 336-2003 80/12/19 3pp. 07469.251

01270275 Transcript from Affirmation Session 80-56 on 801222 in Washington, DC, Pp 1-7 Includes consideration of BECY-80-925 re open govt FOIA appeal, SECY-A-146A re Tyrone decision, BECY-80-507 & BECY-80-501
Commissioners 80/12/22 9pp 07546.117.

801290384 Comments on petition for rulemaking 30-57 re AWE Overall cost estimates too low Proposed fines will have negative effect on reactor safety & unit availability,
Arizona Public Service Co 45FR73080 011 80/12/30 1p
07969 362

PROJ PROJECTS - PRECROCKET LICENSING

801060143 Summary of 801203 meeting w/DCE in Germantown, MD re DOE/NRC interagency agreement required by West Valley Demonstration Project Act Definition section should be included to define explicitly important items
TIND, H W Advanced Fuel & Spent Fuel Licensing Branch 80/12/08 3pp 07399 088

801200034 Comments on behalf of SD State Historical Society on final CEIS re W milling App F-6 clearly demonstrates that NH is aware of body of law & regulation re cultural resource protection
SPERRY, J E Affiliation Unknown 18088 80/12/03 44pp
07487 021

801200008 Ack SD State Planning Bureau receipt of final CEIS w/ milling No comment
RICHARDSON, J H South Dakota, State of 18005 80/11/21 1p
07487 017

801270286 Notice of JB Rupp, CJ Corica & H Monsef depositions on 801201 in Alameda, CA & H Hyland, JH Shepard & RE Cecchetti depositions on 801204 in Alameda, CA Certificate of Svc encl Related correspondence
HEISS, R L, DOYLE, H M Pacific Gas & Electric Co HEISS, R I McCutchen, Doyle, Brown & Emerson 81/01/20 6pp 07546 09J

801290276 Forwards SH Lewis notice of appearance in proceeding Participation in proceeding poses no conflict of interest, in spite of relationship w/member of participating law firm
QULBERG, J R Office of the General Counsel 1584955 A 81/01/27 2pp 07576 149

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

8012100406 Part 21 rept re N521-S4 actuators, reported on 801113 Parts sawing problem have been changed by 801118 engineering change notice
LOCASCIO, A T Oil Shettle Corp 80/11/17 4pp 07218 001

06999 QUALITY ASSURANCE INSPECTIONS

801080399 Forwards QA Program Insp Rept 99700003/80-08 on 801031-1114 No noncompliance noted Closeout survey for formerly licensed site scheduled for 1st quarter of 1981 to determine if any residual contamination is onsite
DAVIS, A S Region 3, Chicago, Fuel Facility & Materials E Branch. 80/12/13 1p 03775 001

801080420 QA Program Insp Rept 995 noncompliance noted Major areas 1 determine status of expired licenses
MICHAELSON, H A, PAPERIELLO, C J Director 80/12/02 11pp 037;

801150374 Forwards QA Program Insp 1 No noncompliance noted
POTAPOV, U Region 4, Dallas, Venc 2pp 07463:231

801150381 QA Program Insp Rept 995 noncompliance noted Major areas 1 deficiency rept, implementation of qualifications
BROWN, R L, WHITEGELL, D E Region Branch 80/11/14 7pp 07443 2

801150389 Forwards QA Program Insp R No noncompliance noted
POTAPOV, U Region 4, Dallas, Venc 1p. 07309 001

801150395 QA Program Insp Rept 995 noncompliance noted Major areas 1 10CFR50, App B & followup on 10CFR discrepancies in valves for Bequo
GILLER, R E, BARNES, J Region 1. 80/11/21 6pp 07307 001

PIC1150305 Ack receipt of 801218 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900252/80-03
 POTAPQVS.U Region 4, Dallas Vendor Inspection Branch 8/10/04
 1p 07463 246

- 8101150410 Responds to NRC 801170 ltr re deviation noted in QA Program Insp Rept 99900522/80-03 Corrective actions FSAR App 3.64 will be revised Any reanalysis required will be performed per Bechtel Engineering Best Procedure 4.27
 ALLEN, R O Bechtel Power Corp (subs of Bechtel Corp)
 80/12/18 3pp 07463 247

--8101150418 Forwards QA Program Insp Rept 99900522/80-03 on 801020-23
 1 notice of deviation
 POTAPQVS.U Region 4, Dallas, Office of the Director 80/11/20
 3pp 07463 250

--8101150422 Notice of deviation from insp on 801020-23
 * Region 4, Dallas, Office of the Director 80/11/19 1p
 07463 252

--8101150429 QA Program Insp Rept 99900522/80-03 on 801020-23
 Noncompliance noted failure to perform adequate review of design calculations of high energy line break analysis as required by internal procedures
 BRICKLEY, R H, ANDERSON, D G, HALE, C J Region 4, Dallas, Vendor Inspection Branch 80/11/19 14pp 07463 253

8101150441 Ack receipt of 801204 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900501/80-01
 POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/12/16
 1p 07463 267

- 8101150446 Responds to NRC 801105 ltr re deviation noted in QA Program Insp Rept 99900501/80-01 Corrective actions memo issued re-emphasizing procedures re microfilm quality & control of design interface control log
 HALL, M W Bechtel Power Corp (subs of Bechtel Corp)
 80/12/09 2pp 07463 268

--8101150450 Forwards QA Program Insp Rept 99900501/80-01 on 801007-10
 1 notice of deviation
 POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/11/05
 2pp 07463 270

--8101150454 Notice of deviation from insp on 801007-10
 * Region 4, Dallas, Office of the Director 80/11/03 2pp
 07463 272

--8101150460 QA Program Insp Rept 99900501/80-01 on 801007-10
 Noncompliance noted design insp microfilm (QA record) of two calculations were not legible Design interface control log not maintained in control sys design group
 BRICKLEY, R H, ANDERSON, D O, ACEF, J H Region 4, Dallas, Vendor Inspection Branch 80/11/03 16pp 07463 274

8101150826 Ack receipt of 801230 ltr clarifying questions raised in QA Program Insp Rept 99900503/80-01
 POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 81/01/08
 1p 07464 299

--8101150840 Clarifies questions raised in QA Program Insp Rept 99900503/80-03 re design verification procedures
 TENZER, B F Ebasco Services, Inc (subs of Entserch Corp)
 80/12/30 2pp 07464 300

--8101150845 Forwards QA Program Insp Rept 99900505/80-03 on 801020-24
 No noncompliance noted
 POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/11/19
 2pp 07464 302

--8101150851 QA Program Insp Rept 99900505/80-03 on 801020-24 No noncompliance noted Major areas inspected Implementation of Typical Rept ETR-1001 & followup on regional requests
 CCRTELLO, J R, JOHNSON, J M, HALE, C J Region 4, Dallas, Vendor Inspection Branch 80/11/19 11pp 07464 304

8101150882 Ack receipt of 801212 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900028/80-01
 POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/12/24
 1p 07466 010

--8101150893 Responds to NRC 800926 ltr re deviation noted in QA Program Insp Rept 99900028/80-01 Corrective Actions supplier notified & QA manual revised
 SEAY, J I Chemtron Corp : Tube Turns Div 80/12/08 2pp
 07466 011

--8101150898 Forwards QA Program Insp Rept 99900028/80-01 on 801020-23
 Notice of deviation
 POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/09/25 12pp 07466 016

8101170780 Forwards QA Program Insp Rept 99900028/80-01 on 801020-23
 No noncompliance noted
 POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/09/25 12pp 07466 016

--8101190702 QA Program Insp Rept 99900028/80-01 on 801020-23
 Noncompliance noted Major areas inspected QA prior to vendor activities & exit interview
 KELLY, W D, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 80/10/22 4pp 07476 120

8101200106 Ack receipt of 801027 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900025/80-04
 POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/10/27 4pp 07485 115

--8101200112 Responds to NRC 800925 ltr re deviation noted in QA Program Insp Rept 99900025/80-04 Corrective actions utilized to reveal any rejectable defects in piping subassemblies
 MDERKE, M H Southwest Fabricating & Welding Co International Corp : 80/10/27 4pp 07486 116

--8101200117 Forwards QA Program Insp Rept 99900025/80-04 on 801007-10
 1 notice of deviation
 POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/11/05
 2pp 07486 120

--8101200118 Notice of deviation from insp on 800902-10
 * Region 4, Dallas, Office of the Director 80/11/03 2pp
 07486 122

--8101200121 QA Program Insp Rept 99900025/80-04 on 801007-10
 Noncompliance noted failure to perform required ultrasonic examination of pipe
 BARNES, J Region 4, Dallas, Vendor Inspection Branch 80/11/03 4pp 07486 123

8101200125 Forwards QA Program Insp Rept 99900361/80-01 on 801007-10
 No noncompliance noted
 POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/11/03 4pp 07486 127

--8101200131 QA Program Insp Rept 99900361/80-02 on 801007-10
 Noncompliance noted Major areas inspected Implementation of 10CFR90, App B criteria, applicable codes & stds & previous insp findings
 ELLERBHAHL, E, BARNES, J Region 4, Dallas, Vendor Inspection Branch 80/11/25 3pp 07486 129

8101200538 Ack receipt of 801204 ltr resolving questions raised in QA Program Insp 99900504/80-04
 SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/08 1p 07477 251

--8101200640 Responds to NRC 800821 ltr re questions raised in QA Program Insp 99900504/80-04 Background check of contractor design employee qualifications performed Evaluation completed
 HASLAM, E F Stone & Webster Engineering Corp 80/12/08 2pp 07477 252

8101210255 Forwards QA Program Insp Rept 99900721/80-01 on 801020-23
 No noncompliance noted
 POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/12/08 2pp 07490 058

--8101210262 QA Program Insp Rept 99900721/80-01 on 801020-23
 Noncompliance noted Major areas inspected, Implementation of 10CFR90, App B, applicable codes & stds including QA review
 KELLY, W D, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 80/10/28 9pp 07490 060

B01230506 Ack receipt of B01219 ltr informing NRC of steps taken to correct violation noted in QA Program Insp Rept
99900524/B0-02
POTAPOV, S. U Region 4, Dallas, Vendor Inspection Branch B1/01/05
1p 07512 190

--B01230507 Responds to NRC B01124 ltr re violation noted in QA Program Insp Rept 99900524/B0-02 Corrective actions documents posted where needed in safety-related areas & documents placed in storage
DERENZO, P P 0166 & Hill, Inc (subs of Drive Corp) B0/12/19 14pp 07512 191

--B01230508 Forwards QA Program Insp Rept 99900524/B0-02 on B01020-23 & notice of violation
POTAPOV, S. U Region 4, Dallas, Vendor Inspection Branch B0/11/24
2pp 07512 192

--B01230509 Notice of violation from Insp on B01020 23
* Region 4, Dallas, Office of the Director B0/11/21 1p
07512 194

--B01230510 QA Program Insp Rept 99900524/B0-02 on B01020-23
Noncompliance noted Failure to post copy of Section 206 & regulations
FOX, D F, JUMYSCH, J N, HALE, C J Region 4, Dallas, Vendor Inspection Branch B0/11/21 11pp 07512 195

B01260161 Discusses 790706 interview w/B Newberry re events & scope of review concerning analysis of Michelson rept, "Decay Heat Removal During Very Small Break LOCA for B&W 205 Fuel Assembly PWR " Newberry unaware of rept prior to 790701.
STRICKLER, L J Office of Inspector & Auditor 79/07/10 1p
07507 090

--B01260173 Discusses 790702 interview w/G Matetis re Michelson rept, "Decay Heat Removal During Very Small Break LOCA for B&W 205 Fuel Assembly PWR " G Matetis received rept in 1977 or 1978, but did not review in detail NA Post article encl
GAHLE, D H Office of Inspector & Auditor 79/07/10 3pp
07507 091

--B01260201 Lists principal lines of inquiry on which investigation into handling of rept, "Decay Heat Removal During Very Small Break LOCA for B&W 205 Fuel Assembly PWR," will be based
IE & Ofc of Inspector & Auditor are responsible
THORNBURG, H D Division of Reactor Construction Inspection 79/05/24 1p 07507 098

--B01260208 Confirms 790608 memo characterizing C Michelson opinion that no adequate forum existed within nuclear regulatory sys for safety-related concerns info re decay heat removal problem encl
STRICKLER, L J Office of Inspector & Auditor 79/06/11 113pp
07507 099

--B01260218 Submits rept of interview w/RC Jones on 790327 re rept, "Decay Heat Removal During Very Small Break LOCA for B&W 205 Fuel Assembly PWR "
WARD, W J Office of Inspection & Enforcement, Office of the Director 79/03/29 2pp 07507 243

--B01260227 Draft Commission paper informing Commission of IE investigation results & proposed enforcement actions re B&W PWR response to small break LOCA Forwards draft civil penalty package & notice of noncompliance
BTELLO, V Office of Inspection & Enforcement, Office of the Director B0/03/25 13pp 07507 268

--B01260237 Discusses IE May-Nov 1979 investigations into whether B&W had adequately analyzed potential safety problems & whether problems should have been reported per 10CFR21 No evidence constituting criminality found
CUMMINGS, J J Office of Inspector & Auditor B0/04/02 2pp
07507 288

B01260056 Forwards QA Program Insp Rept 99900048/B0-02 on B01006-09 No noncompliance noted
POTAPOV, S. U Region 4, Dallas, Office of the Director B0/11/05
2pp 07520 214

--B01260064 QA Program Insp Rept 99900048/B0-02 on B01006-09 No noncompliance noted. Major areas inspected: implementation of 10CFR50, App B, criteria & applicable codes & stds including action on previous findings
HUNTER, V H, WHITEBELL, D E Region 4, Dallas, Vendor Inspection Branch B0/10/30 5pp 07520 216

B01260310 Ack receipt of B01121 & 1268 ltrs informing NRC of action to correct deviation noted in QA Program Insp Rept 99900047/B0-02
POTAPOV, S. U Region 4, Dallas, Vendor Inspection Branch B0/11/05
1p 07526 031

--B01260317 Responds to NRC B01310 & 1203 ltrs re deviation noted in QA Program Insp Rept 99900047/B0-02 Corrective actions complete OCR file reviewed, specific licensing session held, PQ2-001 revised & computer files reviewed & updated
MILLER, F D Westinghouse Electric Corp B0M-P0-102 B0/12/19 2pp 07536 032

B01270751 Ack receipt of B01219 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900033/B0-02
POTAPOV, S. U Region 4, Dallas, Vendor Inspection Branch B0/11/05
1p 07549 155

--B01270755 Responds to NRC B01112 ltr re deviation noted in Insp Rept 99900033/B0-02 Corrective actions 10CFR21 requirements incorporated in purchase orders for pressure boundary parts
BAKUS, F R Westinghouse Electric Corp B0/12/19 2pp
07549 156

--B01270758 Forwards QA Program Insp Rept 99900033/B0-02 on B01110-20 & notice of deviation
POTAPOV, S. U Region 4, Dallas, Vendor Inspection Branch B0/11/05
2pp 07549 158

--B01270763 Notice of deviation from Insp on B01110-20
* Region 4, Dallas, Office of the Director B0/12/08 1p
07549 160

--B01270765 QA Program Insp Rept 99900033/B0-02 on B01110-20 Noncompliance noted Part 21 not identified for purchase orders for safety-related items
MCNEILL, W H, WHITEBELL, D E Region 4, Dallas, Vendor Inspection Branch B0/12/08 4pp 07549 161

B01270770 Forwards QA Program Insp Rept 99900044/B0-03 on B01110-20 No noncompliance noted
POTAPOV, S. U Region 4, Dallas, Vendor Inspection Branch B0/11/05
2pp 07549 163

--B01270775 QA Program Insp Rept 99900044/B0-03 on B01027-30 Noncompliance noted Major areas inspected: fuel rod wfg particle fabrication & cleaning & previous insp action
MCNEILL, W H, WHITEBELL, D E Region 4, Dallas, Vendor Inspection Branch B0/11/15 6pp 07549 165

REG00 REGULATORY GUIDES

790917051 Comments on proposed Reg Guide 1.1 XXA data base should be formulated based on current techniques & proposed improvements judged against current techniques
RENGERGER, D L Washington Public Power Supply System 79/09/14
4pp

7912310182 Comments on proposed reg guide, "Ultrasonic Testing of Reactor Vessel Welds During Inservice Examination"
Discussion should state that reg guide is intended to supplement ASME Section XI
BUCHECH, Z R General Electric Co MFI-2H2-79 79/11/26
01661 398

B01060030 Forwards continuation of B00810 comments on proposed Reg Guide 705-4 re lightning protection for nuclear power plants
JCMNSQ, L B Affiliation Unknown B0/10/08 35pp 07107 217

B01070245 Comments on second proposed Revision 2 to Reg Guide "Personnel Qualification & Training" NRC should not finalize reg guide until ref documents are finalized
HARDICK, J A Florida Power & Light Co 3-120-19 B0/12/04
07415 234

B01070251 Forwards comments on second proposed Revision 2 to Reg Guide 1.8 "Personnel Qualification & Training"
ABEL, J B Commonwealth Edison Co B0/12/04 4pp 07415 235

B01070255 Comments on proposed Revision 2 to Reg Guide 1.8 "Personnel Qualification & Training" Guidelines still have detrimental impact on safe operation of plants
PARKER, W O Duke Power Co B0/12/05 7pp 07415 237

B101070471 Forwards RI 3600, Plans & AP Master Comments on proposed Revision 1 to Reg Guide 1.23. "Meteorological Programs in Support of Nuclear Power Plants".
MURPHY, T. E. Division of Systems Integration 80/12/05 1p 07403 337

--B10107048 Comments on proposed Revision 1 to Reg Guide 1.23. "Meteorological Programs in Support of Nuclear Power Plants". New paragraph should be inserted between second & third paragraphs of implementation section of guide.
SALAS, R. L. Safety Program Evaluation Branch 80/11/06 2pp 07403 338

--B101070482 Trip report of B101007 to US visit to Philadelphia, PA to discuss dynamic performance of wind wave & aus of propeller anemometer methods for determining accuracy & precision of de-gaging measurements.
REINIS, J. Accident Evaluation Branch 80/12/16 1p 07403 340

--B101070485 Comments on proposed Revision 1 to Reg Guide 1.23. "Meteorological Programs in Support of Nuclear Power Plants". Draft: "Std Method for Determining Dynamic Performance of Wind Vane." encl.
HOSKIN, R. P. Commerce, Dept. of, National Oceanographic & Atmospheric Administration 80/12/05 14pp 07403 341

B101070495 Comments on proposed Revision 1 to Reg Guide 1.21. "Meteorological Programs in Support of Nuclear Power Plants". Document is excellent in all respects.
COPELAND, R. L. Energy, Dept. of, Clinch River Breeder Reactor Plant 80/12/05 1p 07404 350

B101070497 Forwards comments on second proposed Revision 2 to Reg Guide 1.8. "Personnel Qualification & Training".
MILLER, D. W. Ohio State Univ 80/12/05 6pp 07404 344

B101080070 Comments on Revision 1 to draft Reg Guide 1.23. "Meteorological Programs in Support of Nuclear Power Plants". Guide fails to set forth guidance for "an acceptable program". Instrument requirements unjustified.
SULLIVAN, J. J. Consumers Power Co 10273 80/12/02 7pp 07419 308

B101080105 Comments on proposed Revision 2 to Reg Guide 1.8 re personnel qualification & training. Training program fulfills objectives, however effectiveness is not determined by differences from civilian training programs.
KAPRALES, J. Affiliation Unknown 80/12/03 4pp 07419 256

B101080111 Comments on proposed revision to Reg Guide 1.80 the Reg Guide 1.6B.31 re preoperational testing of instrument & control air sys. Rewording would improve guide w/o removing necessary requirements.
STANLEY, L. Quadrex Corp LS-80-185 80/12/03 2pp 07419 254

B101080115 Forwards comments on second Revision 2 to Reg Guide 1.8 re personnel qualification & training.
BUCHHEIM, G. D. Washington Public Power Supply System ELF-AAR-80-028 80/12/05 3pp 07419 249

B101080121 Comments on second proposed revision to Reg Guide 1.8 re personnel qualification & training. Recommendations should be adopted.
PUZM, L. C. General Electric Co. N/C 214 80/12/01 2pp 07417 360

B101090718 Comments on proposed Revision 2 to Reg Guide 1.8. "Personnel Qualification & Training". Intent should be to provide necessary knowledge & skills to assist operators in performing tasks more completely & aid supervisor decisions.
ARCONI, G. C. Arizona Public Service Co 80/12/15 3pp 07442 046

B101090724 Comments on draft Reg Guide FP 716-4. "Std Forest & Content for Health & Safety Sections of Renewal Applications for U Fuel Fabrication Plants".
GETTIER, F. H. Oilco & Mill, Inc (subs of Bravo Corp.) 80/12/11 1p 07429 361

B101090892 Comments on proposed Revision 1 to Reg Guide 1.23. "Meteorological Programs in Support of Nuclear Power Plants".
BRADBURY, R. B. Stone & Webster Engineering Corp 80/12/09 1p 07443 356

B101090899 Comments on proposed Revision 1 to Reg Guide 1.144. "Auditing of QA Programs for Nuclear Power Plants". Audit checklists are not always in form consistent w/ official QA records & should not be retained as official QA records.
MILLS, L. M. Tennessee Valley Authority 80/12/06 2pp 07428 354

B101120001 Comments on proposed Revision 1 to Reg Guide 1.8. "Personnel Qualification & Training". Factor of 27.
MILLER, W. E. General Atomic Co 80/12/05 1p 07447 109

B101120042 Comments on proposed Revision 2 to Reg Guide 1.8. "Personnel Qualification & Training".
MANN, W. E. General Atomic Co 80/12/05 1p 07446 222

B101120048 Submits classification to B101205 concerning Reg Guide 1.8. "Personnel Qualification & Training".
PARKER, W. E. Duke Power Co 80/12/10 2pp

B101120048 Reg Guide 1.05, Revision 1/4. Design & Acceptability, ABCE Section 111.01.1.1.
Office of Standards Development, Director 07454 171

B101140155 Comments on Reg Guide 1.144. "Auditing of Nuclear Power Plants". Retaining audit records valid safety-related purpose. Transes unjustified.
BUCHEIM, G. D. General Electric Co 80/12/05 07308 001

B101140376 Forwards Region 2 comments on draft Reg Guide 1.8. "Personnel Qualification & Training".
SIQUEIRA, C. Reactor Programs Section 80/12/10

--B101140409 Comments on draft Reg Guide 1.6B.31. "Personnel Qualification & Training".
MURPHY, C. E. Region 2, Atlantic Reactor Committee Support Branch 80/12/05 5pp 07462 083

B101140416 Forwards comments on proposed Revision 1.23. "Meteorological Programs in Support of Nuclear Power Plants".
BUCHHEIM, G. D. Washington Public Power Supply System 80/12/16 3pp 07462 079

B101210322 Forwards Draft 2 of proposed Reg Guide 1.8. "Personnel Qualification & Training".
Testing of Reactor Vessel Heads During Pressure Service Insp.
ARLINGTON, G. A. Division of Engineering Standards 07308 001

B101220194 Comments on second proposed Revision 1.8. "Personnel Qualification & Training". Guidelines permit consideration of equivalent experience beyond any stated percentage.
BUCHHEIM, G. D. Carolina Power & Light Co 80-80 07500 093

B101220198 Forwards comments on second proposed Revision 1.8. "Personnel Qualification & Training".
HOWELL, R. W. Atomic Industrial Forum 80/12/10

B101220205 Comments on second proposed Revision 1.8. "Personnel Qualification & Training". One yr training in health physics should be required for protection technicians.
LECNARD, B. E. Institute for Resource Management 07500 085

B101220404 Comments on second proposed Revision 1.8. "Personnel Qualification & Training". Rule making. Final versions of NUREG/CR-1280 & NUREG/CR-16 available prior to drafting of proposed rule.
CONNELL, W. D. Connecticut Yankee Atomic Power Plant Northeast Nuclear Energy Co (subs of Northern 80/12/03 3pp 07500 238

B101220552 Comments on second proposed Revision 1.8. "Personnel Qualification & Training". Require program for operators should be clearly defined.
LARSEN, K. R. Westinghouse Electric Corp 80/12/10

B101220560 Comments on second proposed Revision 1.8. "Personnel Qualification & Training". Degree inappropriate. Selected technical training & a think in diagnostic manner are also needed.
SHIELDS, S. J. Public Service Co of Indiana 07500 169

B101260838 "For Comment" issue of proposed Reg Guide 1.8. "Personnel Qualification & Training".
WORTHINGTON, P. Office of Standards Development 07500 153

OP 034-4 Reg guide should be prepared.
 * Office of Standards Development, Director 80/12/31 6pp
 07534 137

0130C894 Certified summary of ACRS Subcommittee on Regulatory Activities B01105 meeting in Washington, DC to review Revision 2 to Reg Guides 1.12 & proposed amend to 10CFR50 re domestic licensing of production & utilization facilities
 * ACRS - Advisory Committee on Reactor Safeguards 80/12/04 11pp
 07506 283

RESEARCH AND TECHNICAL ASSISTANCE REPORTS

01060097 "Experimental Facility & Preliminary Results for Flashing Transients at 1/15 Scale." technical memo
 CRD/LEVY, C., SAM, R Creara, Inc NRC-04-75-162 TM-708 80/8/31 68pp 07397 111

01060104 "LOFT Steam Generator Simulator & Pump Simulator Performance During LOFT Isothermal Test Series L1"
 JACOBY, M.B., PHABING, P.C Idaho National Engineering Laboratory LTR 20-101, 79/09/03 60pp 07397 177

01060107 "Freezing of Multiphase Mixtures Flowing Downward in Circular Tubes." informal rept.
 GREENE, O.A., BARRY, J.J. Brookhaven National Laboratory BNL-LUREO-28302 80/00/31 04pp 07397 237

01060636 "Analysis of Hypothetical Accidents Resulting in Core Meltdown." monthly progress rept, Nov 1980
 PENNINO, R.B., CYRULSKI, P., OAYBUTT, P. Battelle Memorial Institute, Columbus Laboratories FIN A-4067 80/12/12 7pp 07392 173

01060832 "FLECHT SEASET." monthly status rept, Oct 1980
 MASSIE, H.W. Westinghouse Electric Corp NRC-04-77-127 8P-80-863 80/12/01 9pp 07401 041

01060923 "Shipping Cask Sabotage Source Term Investigation." monthly progress rept, Nov 1980
 TROUT, R.D. Battelle Memorial Institute, Columbus Laboratories FIN B-6012 NRC-04-80-180 80/12/15 3pp 07401 098

01070036 "FLECHT SEASET." monthly status rept, Sept 1980
 MASSIE, H.W. Westinghouse Electric Corp NRC-04-77-127 8P-80-862 80/12/01 9pp 07413 339

01070043 "Steam Generator Tube Rupture Iodine Transport Mechanism." monthly progress rept, Nov 1980
 PENNINO, R.B. Battelle Memorial Institute, Columbus Laboratories NRC-04-76-293 80/12/15 4pp 07414 001

01070534 "CREARE Refill Effects Program." technical memorandum
 BAH, R., SHIFF, W. Creara, Inc NRC-04-75-162 TM-705 80/06/30 65pp 07407 001

01100601 "Best Estimate Prediction for LOFT Nuclear Experiment L3-6." experiment prediction analysis rept
 CHEN, T., MODRO, S.M., CONOIE, K.O. Idaho National Engineering Laboratory, FIN A-6048 00/12/31 140pp 07431 122

01100861 "3WR Refill-Reflood Program." sixtieth monthly progress rept for Oct 1980
 BURNETTE, O.W., DIX, O.E. General Electric Co FIN B-5877 NRC-04-79-184 80/10/31 44pp 07439 088

01102090 "Environ Statements Project." monthly progress rept for Oct 1980
 ZITTEL, H.E. Oak Ridge National Laboratory FIN B-0001 ORNL/E0/E1B-141 00/10/31 9pp 07442 327

01102091 "Iodine Pathway Study." interim contractor repts for Jan-Mar & Apr-June 1980
 KELLER, J.H. Idaho National Engineering Laboratory FIN A-6288 80/06/30 5pp 07442 331

01102092 "Advanced Instrumentation for Reflood Studies Program." Foreign trip rept
 BRITTON, C.L., BUCHANAN, M.E., HESS, R.A. Oak Ridge National Laboratory FIN B-0413 ORNL/FTR-998 80/12/01 62pp 07442 334

01102095 "Mathematical Simulation of Sediment & Contaminant Transport in Surface Waters." quarterly rept, Apr-June 1980
 * Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2271, 80/06/30 8pp 07442 355

801130693 "Experimental Criticality Data for Code Validation." informal quarterly progress rept for Jul-Sept 1980
 BIERMAN, S.R. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2287 80/12/15 4pp 07447 192

801130697 "Revision of Reactor Safety Research (RNL) Program." monthly highlights for Nov 1980
 MYNATT, F.R. Oak Ridge National Laboratory 80/12/10 38pp 07453 345

801150598 "Definition of Parameters for Major Accidents at Waste Solidification & Spent Fuel Storage Facilities." informal monthly progress rept for Nov 1980
 FROENKEL, E.J. Oak Ridge National Laboratory FIN B-0425 80/12/17 3pp 07463 202

801150600 "L&R In-Plant Measurement Program." informal monthly progress rept for Nov 1980
 HANDLER, J.H. EG&G Idaho, Inc FIN A-6075 80/12/19 3pp 07308 001

801150605 "Source Term Characterization Resulting From Explosively Caused Secondary Violations of Spent Fuel Shipping Casks." informal monthly progress rept for Nov 1980
 TROUT, R.D. Battelle Memorial Institute, Columbus Laboratories FIN B-6710 80/12/15 3pp 07465 212

801150610 "Physical Protection of Nuclear Facilities." informal monthly progress rept for Nov 1980
 CHAPMAN, L.O. Sandia Laboratories FIN A-1060 80/12/11 5pp 07465 245

801150617 "Shipping Cask Eventage Source Term Investigation." informal monthly progress rept for Nov 1980
 SCHMIDT, E.W. Battelle Memorial Institute, Columbus Laboratories FIN B-6012 80/12/16 3pp 07465 250

801150633 "Safeguards for Proliferation Resistant Fuels." informal monthly progress rept for Nov 1980
 CAWELL, J.J. Brookhaven National Laboratory FIN A-3221 80/12/11 3pp 07465 266

801150641 "Safeguards for Proliferation Resistant Fuel Cycles." informal monthly progress rept for Oct 1980, 1tr rept
 CAWELL, J.J. Brookhaven National Laboratory FIN A-3221 80/12/11 3pp 07465 269

801210325 Submits status repts on core melt programs for Nov 1980
 BERMAN, M. Sandia Laboratories 01/01/08 7pp 07488 233

801210542 "3WR Blowdown/ECC Program." informal monthly progress rept for Jul 1980
 BURNETTE, O.W. General Electric Co NRC-04-76-215 80/00/07 4pp 07489 106

801210576 "Human Error Rates - Quantification Method from Nuclear Experience & Data."
 LUCKAS, W.J., HALL, R.E. Brookhaven National Laboratory BNL-NUREO-28061 81/01/15 5pp 07489 118

801210589 "Analysis of Natural Circulation Events in B&W Plants Using Super Sys Code - 3L." submitted to ANS/FHS/AIE B01117-21 international conference
 GURRY, J.O., MORAK, M.C., VAN TUYLE, O.J. Brookhaven National Laboratory BNL-NUREO-28049 80/11/21 6pp 07489 125

801210610 "TRAC-PIA Predictions of Battelle-Frankfurt Top Blowdown Test"
 MEYDTON, L. Brookhaven National Laboratory BNL-NUREO-28127 81/01/15 8pp 07489 223

801210615 "Independent Assessment of TRAC-PIA W/Harvlien Critical Flow Tests"
 RGHATGI, U.S., SANKORIN, Y. Brookhaven National Laboratory BNL-NUREO-28126 81/01/15 7pp 07489 231

801210622 "Independent Assessment of TRAC-PIA W/Super-Canon Blowdown Tests"
 SAHA, P., SANKORIN, Y. Brookhaven National Laboratory BNL-NUREO-28125, 01/01/15 6pp 07489 243

U.S. GOVERNMENT PRINTING OFFICE: 1967 O 344087

1974-75 LHR Case Assessment - Application - monthly highlights report for 1974-75
1974-75 Congressional National Laboratory File #3215 80/11750
1974-75 07449-755

104721044 - 124 Safety Program Monthly highlights ltr for Aug 1980
 104721045 - Occupational National Laboratory File A-2016 80/09/C8
 Sig 07415 120

1044-1051 121 Code Development, Verification & Application. Cont'd
 Highlights report for 1965
 1044-1051 121 Distribution National Laboratory. File A-3915 00/12/67
 1044-1051 121

4. "Development Verification & Application" monthly highlights report for Feb 1980
4. CP, 111, Craterview National Laboratory FIN A-3915 80/10/10
100 Q7445 237

DISPATCH: Sci Code Development & Verification: monthly highlights
 report for Aug 1980
 OFFICE: Smithsonian National Laboratory, FILE A-3019 80/09/09
 pp. 07495,243

61027016 LAR Thermal Hydraulic Development Program, monthly
highlights, rept for Aug 1983
A210AF H Biochemical National Laboratory, File A-2045 83/08/31
4pp 07495 250

BIOLOGICAL: Report of Foreign Travel of AP Mallonouras to Germany &
 France
 MALLONOURAS, A P Oak Ridge National Laboratory FIN B-0127
 (Rpt.)/File 1035 20/12/04 14pp 07495 261

0151220183 "Steam Generator Tube Rupture Iodine Transport Mechanisms,"
monthly progress rept for Aug 1983
DEHNARD, R S Battelle Memorial Institute, Columbus Laboratories
EO/G7/15 4pp 07495 342

210120188 Presentation entitled 'Structured Assessment Approach
 Procedure for Assessment of Fuel Cycle Safeguard Sys' for
 801926-18 Second Garada Symposium
 PAULIA, L. A. A. PALENAVIC, E. C. J. RENARD, P. A. Lawrence Livermore
 Laboratory UCR-82722 80/03/06 Spp 07494 003

610120703 "Environ Statements Project." monthly progress rpt for Sept
 1983
 2111EL H E Oak Ridge National Laboratory File 8-C001
 CRN/ED/ELIS-139 80709730 460 07455 349

810127G216 "Analysis of Fi-Vessel Debris/Water Interaction & Potential Overpressurization of Containment"
VASS, J. Brookhaven National Laboratory BNL-NJREQ-28/39 81/01/15
12pp 07495 354

9101260224 "EPA Refill-Reflow Program," monthly progress rept for Jul
1983
BUREAU OF General Electric Co File B-5877 NRC-04-79-183
80/09/68 20pp 07309 001

11012202ZB "Decontamination as Precursor to Decommissioning." monthly
progress report for Mo. L Dec 1980
PERRIGO, L D Battelle Memorial Institute, Pacific Northwest
Laboratory, Pll 5-2335 B1/01/05 3pp 07496 004

101220272 "Ew Refill-Reflood Program" monthly progress rpt for Sept
1980
BURNETT, C II General Electric Co FIN 0-5877 NRC-04-79-184
80/10/13 bfp 0749b 02?

101220237 "Environ Statements Project." monthly progress rept for Jul
1980
2111EL.H.E Oak Ridge National Laboratory FIN 0-0001
09ML/ED/E15-133 B2/07/31 5pp 07496 013

0120249 PHL-2950
Valuing Environ Via Bidding Games Psychological
Perspective, " interim replacement from NUREG/CR-0989, Vol 2.
App D
HEBERL, J A, SHIXIAR, R, PERRY, R W Battelle Memorial Institute,
Pacific Northwest Laboratory PHL-2950 80/08/31 5022
07507 280

8101200250 Presentation entitled 'Real Time Loss Detection
Process' for 800326 second annual symposium on safeguard
nuclear mail rgt
LAWRY, J V. DUNN, D R. GRAVEL, D T Lawrence Livermore L
OACR-82225 80/03/20 9pp 07309 001

910122026D - Evaluation of Backet Files of Terminated Licen
progress report for Nt: 1760
HOLCOMBY, C F. INTRINSIC POLY. J Day Ridge National Laboratory
A-9095-7 ERIC/LIANSRB-101 00/10/31 16pp 07302 204

BI0120266 "Analysis of Hypothetical Accidents Resulting in
Meltdown," monthly progress report for Aug 1980
DENNIS, R S. CYBULSKI, P. BAYHILL, P. Battelle Memorial
Laboratories PIN A-4067 RO/09/15 9pp 07

B101220271 "Environ Assessments of Fuel Cycle Facilities."
progress rept for Oct 1980
21TEL.H.E Oak Ridge National Laboratory FIN B-0279
CR/L/EO/EIS-140 80/10/31 5pp 07502 239

8101220277 "Safeguards Analysis for Byproduct Matls & Sols
of SRI." monthly progress rept for Nov 1980
CHESTER, R. D. RAIDOPHILL L Oak Ridge National Laboratory
8-6108 ORNL/HASBP-105 60/12/05 Bpp 07502 234

#101220295 "Environ Statements Project." monthly progress
 1980
 ZITTEL, H F Oak Ridge National Laboratory FIN 8-0601
 GRNL/ED/EIS-143 8/3/11/70 App 07502 242

8101220620 P/L-2991
"Visual Aesthetic Prediction Method for Use in Benefit-C
Analysis," interim rept. excerpt from NUREG/CR-0789, Vol 2
ADAMS, R. C., CURRIE, J. W. Battelle Memorial Institute, Pa
Northwest Laboratory P/L-2991 80/08/31 30pp 0744

8101220572 Mr. MUREQ-27961
NRC Nuclear Waste Mgt Technical Support in Development
Nuclear Waste Form Criteria Task 1 Waste Package Overview
Interim rept
DAYAL, R. SWYLER, K. J. EOP Brookhaven National Labor
A-3158 Mr. MUREQ-27961 80/06/30 220pp 07448 062

BI0120623 BNL-NUREG-28115
"Quantitative Nuclear Power Plant Siting Methods: Review
Current Practice." Informal rept
PIERCE, D L. NUREG-28115 Brookhaven National Laboratory
BNL-NUREG-28115 77/08/31 61pp 07498 200

8101220625 DIL-NUREG-28343
"Liquid Entrainment By Expanding Gas Or Vapor Bubble Rev
of Experiments & Models," Informal rept
KOSZYNSKI, J R. OLIVERO, T Brookhaven National Laborat
A-3024 DIL-NUREG-28343 80/09/30 62pp 07499 065

610120626 BNL-NUREO-27834
 "Nonlinear Dynamic Analysis of Piping Sys Using Pseudo F
 Method," Informal rept
 BEZLER, P. PHACHUTAM, S Brookhaven National Laboratory
 HARTZMAN, M Mechanical Engineering Branch BNL-NUREO-2
 80/01/31 35pp 07499 125

8101220628 BNL-NUREG-28625
 "Preliminary Determination of Power Shapes, Doppler
 Coefficients & Sodium Void Worths for CDB Phase-II Guide
 Core." informal rept
 LUDEWIG, H., MALLIN, A. N. Brookhaven National Laboratory
 BNL-NUREG-28625 80/11/30 32pp 07499 216

2101220642 DRL-NUREG-28109
Thermal-Hydraulic Effects on Ctr Rod Drop Accidents in
DRL - Informal rept.
CHEVIG, H S. DIAMOND, B J Brookhaven National Laboratory
A-3323 DRL-NUREG-28109 00/07/31 74pp 07494 304

B101220643 "Technology & Cost Termination Surveys Associated with Decommissioning of Nuclear Facilities," monthly progress report for Nov 1980
WITHERSPOON, J., HOLLOWAY, C F Oak Ridge National Laboratory
A-9042 ORNL/HASRD-106 80/11/30 4pp 07903 191

B101220646 "Dosimetry & Biotransport Models to Implement A
Uncertainties in Assessment of Long-term Collective Dose
Health Effects,' rept on foreign travel
KOCHER, D C Oak Ridge National Laboratory FIN A-9041
ORNL/FTR-983 80/11/17 6pp 07503-195

8101220649 "BUR Glowdown/ECC," monthly progress rept for D
DURNETTE, G M General Electric Co FIN B-3014 NRC-04
80/11/20 21pp Q7503 201

B101220650 "SWR Refill/Reflood Program." monthly progress rept for Nov 1980
BURNETTE, G. H. General Electric Co FIN B-5877 NRC-04-79-184
80/12/16 12pp 07503 222

B101220655 "SWR Blowdown/ECC Program." monthly progress rept for Nov 1980
BURNETTE, G. H. General Electric Co FIN B-3014 NRC-04-76-215
80/12/15 6pp 07503 234

B101230039 "Environ Assessments of Fuel Cycle Facilities." monthly progress rept for Nov 1980
ZITTEL, H. F. Oak Ridge National Laboratory FIN B-0279
CRNL/ED/EIS-142 80/11/30 5pp 07510 338

B101230047 "Review of LWR Safety."
CHEN, H. Brookhaven National Laboratory BNL-MUREQ-28722.
80/12/31 45pp 07510 343

B101230189 "LWR Thermal Hydraulic Development Program." monthly highlight ltr for June 1980
ABUAF, N. Brookhaven National Laboratory FIN A-3043 80/06/20
6pp 07300 001

B101230200 "Advanced Reactor Safety Analysis." monthly highlights for June 1980
BARI, R. A. Brookhaven National Laboratory FIN A-3000 80/07/00
4pp 07511 037

B101230202 "Advanced Reactor Safety Analysis." monthly highlights for July 1980
BARI, R. A. Brookhaven National Laboratory FIN A-3000 80/08/07
4pp 07511 041

B101230206 "Thermal Reactor Safety Code Development." monthly highlights for Jul 1980
LEVINE, M. H. Brookhaven National Laboratory 80/07/31 4pp
07511 045

B101230209 "SBC Code Development & Verification." monthly highlights for July 1980
GUPPY, J. G. Brookhaven National Laboratory FIN A-3015 80/08/05
6pp 07511 049

B101230213 "Evaluation of LWR RHR under Accident Conditions." monthly highlights for June 1980
BARI, R. A. Brookhaven National Laboratory FIN A-3315 80/07/08
6pp 07511 055

B101230236 "LWR Thermal Hydraulic Development Program." monthly highlight ltr for Jul 1980
ABUAF, N. Brookhaven National Laboratory FIN A-3043 80/07/31
4pp 07511 225

B101230243 "Stress Corrosion Cracking of PWR Steam Generator Tubing." monthly highlights for Jul 1980
JULISCHECK, T. VAN ROYEN, D. Brookhaven National Laboratory FIN A-3208 80/07/31 5pp 07511 227

B101230248 "MGR Safety Program." monthly highlights ltr for Jul 1980
BASTRE, C. Brookhaven National Laboratory FIN A-3016 80/08/08
6pp 07511 234

B101230262 "Evaluation of LWR RHR under Accident Conditions." monthly highlights for Jul 1980
BARI, R. A. Brookhaven National Laboratory FIN A-3315 80/08/07
7pp 07511 244

B101230743 "Advanced Reactor Safety Analysis." monthly highlights for Aug 1980
BARI, R. A. Brookhaven National Laboratory FIN A-3000 80/09/08
4pp 07511 251

B101230751 "Evaluation of LWR RHR under Accident Conditions." monthly highlights for Aug 1980
BARI, R. A. Brookhaven National Laboratory FIN A-3315 80/09/08
6pp 07511 255

B101230757 "RAMONA-7B Code Mod & Evaluation." monthly highlight ltr for Nov 1980
DIAMOND, D. J. Brookhaven National Laboratory FIN A-3014 80/11/30
4pp 07511 261

B101260752 "Simulator Improvement Program." monthly highlights for Nov 1980
WULF, W. Brookhaven National Laboratory FIN A-3014 80/11/30
4pp 07536 014

B101260758 "Stress Corrosion Cracking of PWR Steam Generator Tubing." monthly highlights for Oct-Nov 1980
JULISCHECK, T. VAN ROYEN, D. Brookhaven National Laboratory FIN A-3208 80/12/05 9pp 07534 138

B101260877 "MGR Safety Program." monthly highlights for Nov 1980
BASTRE, C. Brookhaven National Laboratory FIN A-3016 80/12/05
6pp 07534 147

B101260846 "TRAC Assessment & Model Development." monthly highlights for Aug 1980
SAHA, P. Brookhaven National Laboratory FIN A-3215 80/08/11
6pp 07534 161

B101260849 "Advanced Reactor Safety Analysis Technical Assistance. Reactor Projects." monthly highlights for Sept 1980
BARI, R. A. Brookhaven National Laboratory FIN A-3000 80/10/1
4pp 07536 027

B101260850 "TRAC Assessment & Model Development." monthly highlights for Jul 1980
SAHA, P. Brookhaven National Laboratory FIN A-3215 80/07/31
6pp 07534 167

B101260856 "Evaluation of LWR Residual Heat Removal Under Accident Conditions." monthly highlights for Sept 1980
BARI, R. A. Brookhaven National Laboratory FIN A-3315 80/10/12
5pp 07534 175

B101270071 "LWR Thermal Hydraulic Development Program." monthly highlights ltr for Sept 1980
ABUAF, N. Brookhaven National Laboratory FIN A-3043 80/09/30
4pp 07547 204

B101270161 "Submits progress rept for Dec 1980 for Contract NRC-04-7-162
CRNL/LEY, C. J. ROYCE, P. H. Creare, Inc NRC-04-75-162 345-12
81/01/09 3pp 07545 357

B101270201 "Distribution Coefficients for Radionuclides in Aquatic Environments." quarterly rept for Dec 1977-Feb 1980.
Washington Univ of FIN B-5749 80/07/31 10pp 07547 061

B101270213 "Coastal Zone Predictive Modeling at Power Plant Sites." quarterly progress rept for Oct-Dec 1979 & Jan-Mar 1980
OLTMARS, J. Argonne National Laboratory FIN A-2055 80/06/30
16pp 07547 077

B101270229 "Power Plant Condenser Tube Simulator Research Project." progress rept for 800315-0615
O'CONNOR, J. H. New York Univ Medical Center New York, NY FIN B-6298 80/07/31 15pp 07547 099

B101270391 "Thermal Reactor Safety Code Development." highlights for Aug 1980
LEVINE, M. H. Brookhaven National Laboratory FIN A-3014 80/08/05
5pp 07549 030

B101270974 "Submits status rept for Jul 1980 re qualification of safety related equipment. Supporting tables incl
ROMIZO, L. L. Sandia Laboratories SCL/IEHQ T-MSLR 80/08/06
07549 191

B101270972 "Two-Phase Flow Phenomena in Nuclear Reactor Technology." highlights for Jan-Mar 1980
LMEY, R. T. Rensselaer Polytechnic Inst NRC-04-76-301 80/03/1
34pp 07544 001

B101280548 "Shipping Case Sabotege Source Term Investigation." info monthly progress rept for Dec 1980
SCHMIDT, E. H. Battelle Memorial Institute, Columbus Laboratories FIN B-6012 81/01/15 9pp 07187 001

B101280551 "Experimental Criticality Data for Code Validation." informal quarterly progress rept Oct-Dec 1980
BIERMAN, S. R. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2091 81/01/05 3pp 07550 226

B101290073 "Forwards status rept of ref repository & technology transfer program for Jul 1980.
ORITZ, M. R. Sandia Laboratories FIN A-1158-9 80/08/25 5pp
07567 229

B101290090 BNL-MUREQ-28602
"Review of Recent Studies of Radiation Induced Behavior of Ion Exchange Media." Informal rept.
SWYLER, W. BARLETTA, R. E. OAVIS, R. E. Brookhaven National Laboratory FIN A-3162 BNL-MUREQ-28602 80/11/30 34pp 07567 240

B101290135 "Investigation of Accident Induced Flow & Matl Transport in Nuclear Facilities." Informal progress rept for Nov 1990
MARTIN, R. A., GREGORY, W. S. Los Alamos Scientific Laboratory FIN
A-7629 81/01/06 7pp 07567 283

B101290181 Forwards rept of ref repository, & technology transfer
program for Oct 1980
CHLEY, N. C. Sandia Laboratories FIN A-1158-9 80/11/20 3pp
07569 338

B101290182 "Steam Generator Tube Rupture Iodine Transport Mechanisms."
monthly progress rept for June 1990
CEMINO, R. S. Battelle Memorial Institute, Columbus Laboratories
NRC-04-76-293 80/07/14 4pp 07575 205

B101290186 Submits status rept of core damage accident flow path &
regulation study for Oct 1980
HICKMAN, J. W. Sandia Laboratories 80/11/12 2pp 07566 353

B101290193 Speech entitled "Safeguards Research at LLL," presented at
BOSJ20-28 Second Annual Symposium of Safeguards & Nuclear
Matl Mgt
DUNN, D. R., HJEBEL, J. O., PEGGIO, A. J. Lawrence Livermore Laboratory
UCRL-82324 80/03/20 5pp 07575 209

B101290213 Forwards status repts for work performed for Probabilistic
Analysis Staff for Aug 1980
MCCLOSKEY, D. J. Sandia Laboratories FIN A-1192 80/09/24 31pp
07570 271

B101290245 Forwards status rept of work done for Probabilistic Analysis
Staff for Jul 1980
MCCLOSKEY, D. J. Sandia Laboratories FIN A-1192 80/08/29 30pp
07570 289

B101290219 Submits monthly status rept of environ qualification of
safety related equipment for Aug 1980
BCHAM, L. L. Sandia Laboratories FIN B-3101 SML/LENG, T-MLSR
80/09/09 3pp 07570 261.

B101290239 B101290243
Submits status rept of environ qualification of safety-
related equipment for Oct 1980
BCHAM, L. L. Sandia Laboratories FIN B-3101 SML/LENG, J-MLSR
80/11/11 2pp 07570 332

B101290668 Water Reactor Research Directorate monthly rept, Apr 1980,
for semiscale, thermal fuels behavior program, 20/30 program,
code development & analysis program, code assessment &
applications program, GPP & line items
BOSTWICK, W. E., YBARRO, L. J. Idaho National Engineering Laboratory
80/05/31 197pp 07566 143

B101290674 "Matl Control & Accounting Effectiveness Evaluation
Development." Informal progress rept, Aug 1980
FOSGIO, A. J. Lawrence Livermore Laboratory FIN A-0115 81/01/07
9pp 07568 340

B101290677 "Definition of Parameters for Major Accidents at Waste
Solidification & Spent Fuel Storage Facilities." progress
rept, Dec 1980
FREDERICK, E. J. Oak Ridge National Laboratory FIN B-0425
81/01/21 4pp 07568 349

B101290682 "Evaluation of Docket Files of Terminated Licenses."
progress rept, Nov 1980.
HOLWAY, C. F., WITHERSPON, J. Oak Ridge National Laboratory FIN
A-9085-7 ORNL/HASRO-104 80/11/30 28pp. 07574 259

B101290687 "Nondestructive Examination Evaluation Support." progress
rept, Dec 1980
SMITH, J. H. Oak Ridge National Laboratory FIN B-0233
ORNL/HCD/NEES-B 81/01/09 3pp 07574 287

B101290691 "Analysis of Hypothetical Accidents Resulting in Core
Meltdown." progress rept, Dec 1980
OENNING, R. S., CYBULSKI, P., PAYBUTT, P. Battelle Memorial Institute,
Columbus Laboratories FIN A-4067 81/01/15 9pp 07574 290

B101290741 "Advanced Two-Phase Flow Instrumentation Program."
preliminary rept on tested thermocouple response during
thermal hydraulic test facility Test 3.07 9 quasi-steady-
state film boiling, 800712, 18, 23 & 1001
TURNAGE, A. O., DAVIS, C. E., GLOVER, W. H. Oak Ridge National Laboratory
FIN B-0401 80/12/31 33pp 07568 001

B101290761 "Steam Generator Tube Rupture Iodine Transport Mechanisms."
progress rept, Dec 1980
OENNING, R. S. Battelle Memorial Institute, Columbus Laboratories
81/01/15 5pp 07568 325

B101290763 "Accident Aerosol Characterization." d
rept, Dec 1980
CHARSWILL, P. C. Battelle Memorial Institute, Pac
Laboratory FIN B-2287 81/01/16 5pp 0730

B101300328 "DWR Blowdown/Emergency Core Cooling F
monthly progress rept for June 1980
JURNETTE, O. W. General Electric Co FIN B-3014
80/07/09 61pp 07582 229

B101300145 LO-14-80-071
"Effects of Fuel Centerline Thermocouples on Fu
Steady State Temp & Stored Energy."
CARBONEAU, H. L. EG&G Idaho, Inc LO-14-80-071
07583 127

B101300199 EG0-WRR-5311
"Monthly Rept for Benchmark, 20/30, Code Developm
Assessment & Application Divs. & Thermal Fuels B
Program"
LEACH, L. P. EG&G Idaho, Inc EG0-WRR-5311 80/
07500 171

B101300543 BNL-NURE0-28796
"AUTOMATIC GENERATION OF CROSS SECTION INPUT FO
DYNAMICS CALCULATIONS." INFORMAL REPT
EISENHART, L. O., DIAMOND, O. J. Brookhaven Nation
A-3212 BNL-NURE0-28796 80/11/30 19pp 07

B101300674 BNL-NURE0-28797
"Axial Power Distribution Control Strategies fo
Informal Rept
TODDS, M. A., ARONSON, A. L., DIAMOND, O. J. Brookha
Laboratory FIN A-3212 BNL-NURE0-28797 80/
07585 059

B101300682 BNL-NURE0-28787
"Thermal-Hydraulic Model of BNL-TWIGL." Informal
CHEW, H. Brookhaven National Laboratory FIN
BNL-NURE0-28787 80/12/31 113pp 07585 119

B101300822 "Quick-Look Rept on LOFT Nuclear Exper
preliminary data analysis rept.
MCREEERY, O. E. EG&G Idaho, Inc FIN A-6048. E
80/12/31 98pp 07584 024

B101300624 "SWRI Activities in Support of NRC for
Synthetic Aperture Focusing Technique for Ultra
Testing." monthly progress rept for Dec 1980
HAMLIN, D. R. Southwest Research Institute NRC
7pp. 07586 014

B101300843 "LOFT Monthly Progress Rept for Nov 19
KAUFMAN, N. C. EG&G Idaho, Inc FIN A-6048. EG
80/12/31 94pp. 07585 256

REVIEW ORP NRC RESEARCH REVIEW GROUPS

B101310226 Forwards Ofc of Nuclear Regulatory Res
29 memos referred to in NURE0-0735, "Plan for D
Safety Goal." Matl should be included in PDR fi
encs
LARKINS, J. T. Program Coordination Branch 80/
07371. 201

B101030299 Comments on working paper, "Criteria f
Formulation." Question of verifiability must no
in subordinate role M Spangler comments on draft
ERNST, M. L. Assistant Director for Technology R
6pp 07309 001.

B101070004 Responds to FOIA request for four cate
cold shutdown w/ regard to fire protection requi
App R to 10CFR50 Forwards D Davis 790614 memo &
J Knight memo re 790228 review group meeting.
FELTON, J. M. Division of Rules and Records 80/
07414 182

B101070059 Responds to FOIA request for six cate
protection requirements in App R to 10CFR50 Enc
draft memo is responsive to request & will be p
FELTON, J. M. Division of Rules and Records 80/
07414: 197

--B101070070 Summary of 790228 fire protection re
discuss differences in fire protection measur
Div of Sys Safety & Div of Operating Reactors
redundant divs of sys necessary for safe hot
MATTHEWS, P. R. Auxiliary Systems Branch, KNI
Director for Engineering 79/03/14. 18pp.

B011100341 Informs that Steering Group on Development of Safety Goal will concentrate on three variant approaches to formulating criteria during B01120 meeting Decision was mistake in view of fundamental difference in nature of approaches
LIBARKIN, M W ACRS - Advisory Committee on Reactor Safeguards
B0/11/28 2pp 07443 331

B01120049 Comments on NUREG-0735 re NRC plan for developing safety goal Endorses concept Goal should focus on providing adequate level of protection to public relative to benefit derived from plant-electrical power production
SHERWOOD, G O General Electric Co MF11-204-BB B0/11/26 2pp 07309 001

B01120053 Responds to request for comments on list of topics being considered in development of safety goal for nuclear power plants Many individuals exhibit fairly extreme risk aversion to low probability-high consequence events
BUENRINO, W A Argonne National Laboratory B0/11/21 3pp 07447 003

B01130033 Forwards draft "Safety Goal Issue in Historical Perspective," per request
STOIER, C R Office of the General Counsel B0/12/22 1p 07448 300

--B01130039 "Safety Goal Issue in Historical Perspective," draft
MAZUZAN, Q T, WALKER, J S Office of the Secretary of the Commission B0/12/31 25pp 07440 301

B01130284 Responds to B01200 request for comments re LOFT special review group studies Option A based on selection of most meaningful & expedient tests
SCHIERER, A E C-E Power Systems LD-81-COJ B1/01/09 2pp 07447 223

B01140042 Requests review & comments on encl waiting paper no later than B01205 Comments will be used in preparation of preliminary policy paper
EEGE, O Office of Policy Evaluations B0/12/01 3pp 07460 235

B01140054 Submits highlights of D Sidebotham & C Ivelin B01117 interviews Safety-cost tradeoff should be permissible only after prescribed min safety level is met Cost should not be too high
EEGE, O Office of Policy Evaluations B0/12/08 2pp 07460 260

B01140066 Informs that outline proposed in working paper re safety goal formulation suffers from definitional confusion
Outline should be restricted to safety goals
LIBARKIN, M W ACRS - Advisory Committee on Reactor Safeguards
B0/12/04 3pp 07460 262

B01140074 Informs of NC Rasmussen B01117 interview to gain benefit of views re establishment of safety goals Demand for probable risk assessment exceeds available supply of people
EEGE, O Office of Policy Evaluations B0/12/10 3pp 07460 292

B01140090 Informs of D Bridenbaugh & R Hubbard B01105 interviews re views on safety-goal formulation Safety assurance effectiveness depends on factors that involve direct costs to utility
EEGE, O Office of Policy Evaluations B0/12/04 2pp 07460 295

B01140102 Informs of V Joksimovic, W Houghton & CR Fisher B01104 interviews re thoughts on safety-goal formulation
Quantitative safety goals should be set before other major rulemakings are completed
EEGE, O Office of Policy Evaluations B0/12/08 2pp 07460 313

B01210483 Forwards comments re future LOFT test plans for special review group No tests necessary on safety basis Submit table summarizing tests useful for code assessment
LOFT not representative of expected PWR behavior
ANDERSON, T H Westinghouse Electric Corp MS-TMA-2367 B1/01/16 7pp 07409 271

B01220480 Responds to B01208 request for comments on LOFT special review group studies Option A program recommended Tests L2-6, L7-3 & L8-4 should be carefully evaluated from cost-benefit standpoint
TAYLOR, J H Babcock & Wilcox Co B1/01/20 2pp 07502 259

B01220497 Responds to B01208 request for comments on LOFT special review group studies Proposed testing in areas of man-machine interface & degraded cooling are premature Code verification & sealing will address PWR technology
SHERWOOD, G O General Electric Co MF10-10-B1 B1/01/15 2pp 07502 264

B01290337 Notification of contract execution "Consultant to Special Review Group," awarded to Aerospace Corp
LITTLE, M Administrative Contracts Branch FIN B-7450
NRC-04-01-197 B0/12/29 1p 07570 264

--B01290341 Contract "Consultant to LOFT Special Review Group," awarded to Aerospace Corp
LITTLE, M Aerospace Corp FERLMAN, J Administrative Contracts Branch FIN B-7450 NRC-04-01-197 B0/12/29 5pp 07570 264

SECY POSITION PAPERS BEFORE THE COMMISSION

B01190612 SECY-B0-497

Recommendations that Commissioners conclude that no revisions to delegations of authority are required by Reorganization Plan 1 of 1980 Relevant excerpts from NRC manual & list of delegations in code to Commission level of boards & boards encl
SICKMILL, L Office of the General Counsel B0/11/10 2pp 06916 001

--B01190620 Advises that position is delegated authority for classification of info as top secret Authority may not be redelegated Authority to classify info at secret & confidential levels may be delegated as noted
HEWORTH, J M Commissioners 77/01/02 1p 06916 001

--B01190627 Advises that position is delegated authority for classification of info as top secret Authority may not be redelegated Authority to classify info at secret & confidential levels may be delegated as noted
HEWORTH, J M Commissioners 77/01/02 1p 06916 001

--B01190641 Advises that position is delegated authority for classification of info as top secret Authority may not be redelegated Authority to classify info at secret & confidential levels may be delegated as noted
HEWORTH, J M Commissioners 77/01/02 1p 06916 001

--B01190657 Delegates authority to administer oaths & affirmations enable conduct of investigations on matters within delegated authority Authority may be redelegated to Assistant Director for Investigations of Office of Inspector & Auditor
HEWORTH, J M Commissioners 77/10/26 1p 06916 001

--B01190663 Delegates responsibilities for authorizing affidavits for Commissioners & staff to each Commissioner & Secretary of Commission Responsibilities may be redelegated within each of proper notification
RODGEN, H A Commissioners 77/01/21 1p 06916 001

--B01190673 Designates line of succession for delegation of direct Commission operations & emergency functions pursuant to noted conditions.
CHILKOT, S J Office of the Secretary of the Commission 2pp 06916 001

--B01190681 Delegates authority to carry out NRC national emergency functions to three executive teams designated Alpha, Bravo & Charlie Each team shall be activated by Commission or highest official in line of succession
CHILKOT, S J Office of the Secretary of the Commission 2pp 06916 001

B01200008 SECY-B0-501

Forwards proposed FR notice on disposition of Critical Mass Energy Project, et al petition for rulemaking re emergency response draft ltr to petitioners & proposed Congressional ltr to Representative M. Udall
HARRISON, R W Office of Standards Development, Director 19pp 03767 181

B01220487 Transcript of B01211 Affirmation Session B0-54 in Washington, DC re SECY-B0-448, SECY-A-B0-168 & SECY-B0-482.
Pp 1-11
* Commissioners B0/12/11 13pp 07335 142

--B012110612 Draft Commission paper re denial of Public Citizen Litigation Group petition for rulemaking re increase in required levels of financial protection for reactor operators Abstracts of comments & draft FR notice encl
DENTON, H R Office of Nuclear Reactor Regulation, Director B0/10/23 48pp 03771 145

--B01220624 SECY-B0-448

Requests Commission approval of encl revised narrative explanation of Table S-3 specified in Commission order on final fuel cycle rule & draft FR notice.
DAVIS, J O Office of Nuclear Material Safety & Safeguards B0/09/27 100pp 06747 001

801240399 Informa of review of proposed general evaluation of Agreement State radiation control programs
RATH, EBERGER Interior Dept of FR 80/11/19 07324 091

801406062 Responds to FOIA request for listing of companies licensed by NRC to use radioactive materials & addresses for Agreement States which issue licenses
FELICH, J. H. Division of Rules and Records 07399 360

801060525 FOIA request for listing of people 3/2 by NRC to use radioactive material & state agencies for Agreement States which issue licenses to use
RUSSELL, G. A. Division of Rules and Records 07399 361

801070532 Forwards M. O'Brien & C. Oyster of Connecticut 80117 ltr to Horestate Mining Corp. till apply: Ofc. of State Programs should respond, as matter Agreement State
SCARANO, R. A. Uranium Recovery Licensing Branch 07415 288

801070541 Forwards transcript of State Liaison Meeting in Washington, DC Comments requested by CORNELL, E. K. Office of the Executive Director 80/12/17 1p 07407 071

801070545 Transcript of State Liaison Officers Washington, DC Pg 1-124
* Commissioners 80/12/10 129pp 07407 0

801070590 Transcript of State Liaison Officers Washington, DC Pg 1-259
* Commissioners 80/12/09 260pp 07407 1

801070942 Forwards J.D. Nelson report in response to assessment of adequacy of NM followup to NRC 19 by Church Rock can failure w/o report
SCARANO, R. A. Uranium Recovery Licensing Branch 07415 287

801090328 Confirms NRC 801024 recommendations for of state radiation control program. Addl staff recruited for present radioactive waste program regulatory program for U mills is currently under
KERR, O. W. Office of State Programs, Director 07442 089

801090335 Forwards comments from NRC 801020-24 radiation control program Review of state reg is forthcoming
LUBENAU, J. O. Assistant Director for State Ag 80/11/17 5pp 07442 092

801100213 Informa of review of ltr no 800923 re: comments & recommendations in 800730 ltr for in agreement states program Recommendations result: X Schneider site visits will be incorporated in 00101444 N.Y. New York, State of 80/10/21 1

801100221 Expresses appreciation for visit to AL difficulties state has encountered in obtaining funding to carry out responsibilities under existing agreements
AXELRODD, D. New York, State of 80/10/17 1p

801120010 Comments on evaluation of OA programs NRC should standardize program w/ Agreement State paid to Agreement State or NRC for any licensee duplicate fee should be levied by another licensee
CASH, A. Non-Destructive Testing Management Assoc 012 80/11/12 1p 07447 094

801140084 Submits comments on notice of proposed evaluation of Agreement State radiation control NRC is attempting full effort in finding clear numerical indicators to judge compatibility
FUNDERBURG, R. O. Idaho, State of 80/10/30 2

801140092 Submits comments on revised criteria for Agreement State programs, in response to State of ltr
WILSON, E. F. Arkansas, State of 80/10/28 2p

801240399 Informa of review of proposed general evaluation of Agreement State radiation control programs
RATH, EBERGER Interior Dept of FR 80/11/19 07324 091

801406062 Responds to FOIA request for listing of companies licensed by NRC to use radioactive materials & addresses for Agreement States which issue licenses
FELICH, J. H. Division of Rules and Records 07399 360

801060525 FOIA request for listing of people 3/2 by NRC to use radioactive material & state agencies for Agreement States which issue licenses to use
RUSSELL, G. A. Division of Rules and Records 07399 361

801070532 Forwards M. O'Brien & C. Oyster of Connecticut 80117 ltr to Horestate Mining Corp. till apply: Ofc. of State Programs should respond, as matter Agreement State
SCARANO, R. A. Uranium Recovery Licensing Branch 07415 288

801070541 Forwards transcript of State Liaison Meeting in Washington, DC Comments requested by CORNELL, E. K. Office of the Executive Director 80/12/17 1p 07407 071

801070545 Transcript of State Liaison Officers Washington, DC Pg 1-124
* Commissioners 80/12/10 129pp 07407 0

801070590 Transcript of State Liaison Officers Washington, DC Pg 1-259
* Commissioners 80/12/09 260pp 07407 1

801070942 Forwards J.D. Nelson report in response to assessment of adequacy of NM followup to NRC 19 by Church Rock can failure w/o report
SCARANO, R. A. Uranium Recovery Licensing Branch 07415 287

801090328 Confirms NRC 801024 recommendations for of state radiation control program. Addl staff recruited for present radioactive waste program regulatory program for U mills is currently under
KERR, O. W. Office of State Programs, Director 07442 089

801090335 Forwards comments from NRC 801020-24 radiation control program Review of state reg is forthcoming
LUBENAU, J. O. Assistant Director for State Ag 80/11/17 5pp 07442 092

801100213 Informa of review of ltr no 800923 re: comments & recommendations in 800730 ltr for in agreement states program Recommendations result: X Schneider site visits will be incorporated in 00101444 N.Y. New York, State of 80/10/21 1

801100221 Expresses appreciation for visit to AL difficulties state has encountered in obtaining funding to carry out responsibilities under existing agreements
AXELRODD, D. New York, State of 80/10/17 1p

801120010 Comments on evaluation of OA programs NRC should standardize program w/ Agreement State paid to Agreement State or NRC for any licensee duplicate fee should be levied by another licensee
CASH, A. Non-Destructive Testing Management Assoc 012 80/11/12 1p 07447 094

801140084 Submits comments on notice of proposed evaluation of Agreement State radiation control NRC is attempting full effort in finding clear numerical indicators to judge compatibility
FUNDERBURG, R. O. Idaho, State of 80/10/30 2

801140092 Submits comments on revised criteria for Agreement State programs, in response to State of ltr
WILSON, E. F. Arkansas, State of 80/10/28 2p

0101140096 Advises that comments on NRC proposed statement of policy on evaluation of Agreement State radiation control programs were received from 13 states. Submits comments from NV. WADSWORTH, Nevada, State of 00/12/15 2pp 07308 001

0101140116 Comments on behalf of Kerr-McGow Nuclear Corp. on proposed policy re evaluation of Agreement State radiation control programs. Statement asserts authority over Agreement States which NRC does not possess. NICHLES, P. J., MCWILLIAMS, C. H. Covington & Burling 4569726 001 00/11/14 19pp 07458 170

0101140122 Submits comments on proposed statement of policy on guide for evaluation of Agreement State radiation control programs. SPELLMAN, H. M. Louisiana, State of 00/12/19 2pp 07461 209

0101140134 Submits comments on guide for evaluation of Agreement States radiation control programs. Rept. should remain as uncodified guide. CERROSE, L. B. Georgia, State of 00/12/16 1p 07461 194

0101140141 Submits comments on NRC proposed statement of policy evaluation of Agreement State radiation control programs. No objections to proposal. CLARK, U. Florida, State of 00/12/12 1p 07461 194

0101140147 Advises of no add'l comments on NRC proposed guide for evaluation of state radiation control programs. MOUNT, B. K. North Dakota, State of 00/12/19 1p 07309 001

0101160396 Confirms results of NRC review re State of ID radiation control program. Program is adequate to protect public health & safety. KERR, G. W. Office of State Programs, Director 00/12/22 2pp 07339 001

0101160400 Confirms results of State of ID radiation program review. Program is adequate to protect public health & safety. Telcons substantive in nature should be documented in license files. Specific comments & recommendations encl. LUGENAU, J. O. Assistant Director for State Agreements Programs 00/12/22 3pp 07471 092

0101190564 PNA-80-027A on 001203, State of AR notifies Nuclear Diagnostic Labs that license had been revoked. Caused by failure to respond to state 001024 enforcement ltr. Updates & close-out PNA-80-029 issued on 000822. LUGENAU, J. O., BOLLING, L. A. Office of State Programs, Director 00/12/18 1p 07475 338

0101190658 Comments on general policy statement on evaluation of Agreement State radiation control plan. Revision period of 4 or 5 yrs may allow for more efficient use of staff. LR Solon 001114 memo to J. Spoth encl. DUNKLEBERGER, J. New York, State of 00/12/23 2pp 07476 093

0101190666 Comments on general policy statement on evaluation of Agreement State radiation control plans. Agreement State reviews should be conducted by third party. YOUNG, R. E. Affiliation Unknown 00/12/22 2pp 07183 601

0101190673 Comments on general policy statement on evaluation of Agreement State radiation control plans. More emphasis should be placed on technical advisory committees & consultants & on competence of senior staff. D'ARIELLO, M. J. Affiliation Unknown 00/12/18 2pp 07183 001

0101190679 Ack receipt of 001120 ltr. concerning radiation protection program. Is adequate to protect public health & safety. Unannounced insps will be conducted. GOLDBERG, L. R. New York, State of 00/12/18 1p 07476 093

0101190721 Confirms 001204 discussion of state U. mill regulatory program. More details of state engineer assistance needed. Upon resolution of NRC comments, recommendation re plan adequacy will be made. KERR, G. W. Office of State Programs, Director 01/01/07 4pp 07183 001

0101190730 Confirms 001121 discussion of state radiation control plan. Salaries need to be upgraded in order to be competitive. NRC prepared to recommend finding that state program adequate to protect public health & safety. Salary comparison table encl. KERR, G. W. Office of State Programs, Director 00/12/22 4pp 07476 111

0101200322 Comments on NRC proposed statement of policy re evaluation of Agreement State radiation control programs. Statement suggests that NRC is attempting to increase control over Agreement States. CORDEGRAU, R. L. Nevada, State of 00/12/01 3pp 07187 001

0101270356 Forwards State of SC fourth quarterly progress rpt. (third qtr) on transportation surveillance program, from Jul-Sept 1980. WATKINS, M. Office of State Programs, Director NRC-05-78 357 01/01/07 2pp 07547 196

0101270362 Submits fourth quarterly progress rpt. (third qtr) on transportation surveillance program from Jul-Sept 1980. WILLIAMS, E. F. South Carolina, State of NRC-06-78-357 00/12/01 2pp 07547 193

0101270379 Responds to 001125 ltr. W. McCarthy was been accepted for course in health physics & radiation protection & W. Kerr has been directed to arrange meeting re Cf interest in becoming Agreement State. WATKINS, M. J. Commissioners 00/12/11 1p 07350 106

0101270382 Discusses W. McCarthy application to attend course in health physics & radiation protection & requests that favorable consideration be given. GRASSO, E. Connecticut, State of 00/11/25 1p 07550 107

0101290794 Notification of contract execution. Mod 2 to "Environment Monitoring Program W/ Commonwealth of VA" Contractor BAISDEN, L. Research Contracts Branch FIN B-5116 NRC-05-80-277 01/01/26 1p 07568 037

0101290798 Mod 2, providing funding for CY81 effort to "Environment Monitoring Program W/ Commonwealth of VA" * Virginia, State of BAISDEN, L. Research Contracts Branch FIN B-5116 NRC-05-80-277 01/01/01 1p 07568 038

0101300069 Notification of contract execution. Mod 1 to "Environment Monitoring Program W/ State of MN" Contractor State of MN BAISDEN, L. Research Contracts Branch FIN B-1292 NRC-05-80-208 01/01/26 1p 07583 051

0101300075 Mod 1, providing funding for CY81 effort to "Environment Monitoring Program W/ State of MN" * Minnesota, State of BAISDEN, L. Research Contracts Branch FIN B-1292 NRC-05-80-208 01/01/26 1p 07583 052

0101300086 Notification of contract execution. Mod 3 to "Environment Monitoring Program W/ Commonwealth of PA" Contractor Commonwealth of PA BAISDEN, L. Research Contracts Branch FIN B-5111 NRC-05-80-272 01/01/26 1p 07583 075

0101300093 Mod 3, providing funding for CY81 effort to "Environment Monitoring Program W/ State of PA" * Pennsylvania, State of BAISDEN, L. Research Contracts Branch FIN B-5111 NRC-05-80-272 01/01/26 1p 07583 076

0101300183 Notification of contract execution. Mod 2 to "Environment Monitoring Program W/ State of HI" Contractor State of HI BAISDEN, L. Research Contracts Branch FIN B-5114 NRC-05-80-275 01/01/26 1p 07580 353

0101300187 Mod 2, providing funding for CY81 effort to "Environment Monitoring Program W/ State of WI" * Wisconsin, State of BAISDEN, L. Research Contracts Branch FIN B-5114 NRC-05-80-275 01/01/26 1p 07580 354

0101300312 Notification of contract execution. Mod 2 to "Environment Monitoring Program W/ State of NY" Contractor State of NY BAISDEN, L. Research Contracts Branch FIN B-5109 NRC-05-80-271 01/01/26 1p 07587 009

0101300316 Mod 2, providing funding for CY81 effort to "Environment Monitoring Program W/ State of NY" * New York, State of BAISDEN, L. Research Contracts Branch FIN B-5109 NRC-05-80-271 01/01/26 1p 07587 010

0101300320 Notification of contract execution. Mod 1 to "Environment Monitoring Program W/ State of MS" Contractor State of MS BAISDEN, L. Research Contracts Branch FIN B-1257 NRC-05-80-209 01/01/26 1p 07587 025

0101300325 Mod 1, providing funding for CY81 effort to "Environment Monitoring Program W/ State of MS" * Michigan, State of BAISDEN, L. Research Contracts Branch FIN B-1257 NRC-05-80-209 01/01/26 1p 07587 026

Monitoring Program W/State of MD - Contractor State of MD
BAISEN, L Research Contracts Branch FIN B-3106 NRC-05-80-267
81/01/26 1p 07585 254

--8101300249 Mod 2, providing funding for CVBI effort, to "Environ
Monitoring Program W/State of MD - Contractor State of MD
* Maryland, State of MORTON, K V Research Contracts Branch
FIN B-3106 NRC-05-80-267 81/01/26 1p 07585 259

8101300359 Notification of contract execution, Mod 2 to "Environ
Monitoring Program W/State of CO - Contractor State of CO
BAISEN, L Research Contracts Branch FIN B-3104 NRC-05-80-267
81/01/26 1p 07587 051

--8101300359 Mod 2, providing funding for CVBI effort, to "Environ
Monitoring Program W/State of CO - Contractor State of CO
* Colorado, State of MORTON, K V Research Contracts Branch
FIN B-3104 NRC-05-80-267 81/01/26 1p 07587 052

8101300372 Notification of contract execution, Mod 2 to "Environ
Monitoring Program W/State of PE - Contractor State of PE
BAISEN, L Research Contracts Branch FIN B-3113 NRC-05-80-274
81/01/26 1p 07587 054

--8101300381 Mod 2, providing funding for CVBI effort, to "Environ
Monitoring Program W/State of PE - Contractor State of PE
* Maine, State of MORTON, K V Research Contracts Branch FIN
B-3113 NRC-05-80-274 81/01/26 1p 07587 055

8101300378 Notification of contract execution, Mod 1 to "Environ
Monitoring Program W/State of DE - Contractor State of DE
BAISEN, L Research Contracts Branch FIN B-1260 NRC-05-80-291
81/01/26 1p 07587 056

--8101300406 Mod 1, providing funding for CVBI effort, to "Environ
Monitoring Program W/State of DE - Contractor State of DE
* Delaware, State of MORTON, K V Research Contracts Branch
FIN B-1260 NRC-05-80-291 81/01/26 1p 07587 057

8101300432 Responds to 801231 ltr taking exception to provisions of
Commonwealth of VA radiological emergency response plan Plan
does provide for spokesperson who relates to media at county
level VA Dept of Health 810112 ltr encl
JONES, O L Virginia, State of 81/01/16 5pp 07586 297

TOPREF VENDOR REPORTS AND RELATED CORRESPONDENCE

8011060525 Forwards list of addl info needed to complete review of
800321 Topical Rept 80-67457, "Performance of York Model 299
Type 30 Demister/Moisture Separator in Removing Droplets in
Air-Stream Dispersion"
TEDESCO, R L Assistant Director for Licensing 80/10/22 3pp
02319 196

8101050056 Forwards corrected input listing for LOFT Small Break test
L3-6 W/o encl
JENSEN, S & Exxon Nuclear Co., Inc. (subs of Exxon Corp.)
SEJ 061 80 80/12/12 1p 07375 316

8101050178 Forwards nonproprietary version of Burns & Roe, Inc. rept,
"Analytical Model for LOCA Water Jet in Mark II Containment
(Ring Vortex Model)," provided on behalf of Mark II owners
group as part of Mark II containment program.
BUCHOLD, Z R II General Electric Co RHB-074-82 80/12/11 1p

--8101050187 Nonproprietary version of rept, "Analytical Model for LOCA
Water Jet in Mark II Containment (Ring Vortex Model)"
CHJ, C A LEE, T Burns & Roe Co 80/09/30 116pp 07376 069

8101050561 Discusses 801203 meeting w/review plane in area of core
reloading licensing for coming yr Two licensing topical
repts germane to plans identified, Viewgraphs encl
BERGREN, J S Standardization & Special Projects Branch 80/12/12
23pp 07393 156

8101070296 Submits monthly progress rept for Sept 1980. Efforts were
concerned w/subaccounts for cost control, reviewing project
plans & establishing internal reporting procedures Estimated
& actual cumulative costs through FY81 encl.
OISEKE, J A Battelle Memorial Institute, Columbus Laboratories
80/12/05 3pp 07415 209

8101090047 Forwards Suppl 1 to 3N-GF-79-71 (WP), "Exxon Nuclear Co
Plant Transient Simulator Code for Evaluation of Abnormal
Transients for Jet-Pump BWRs"
DUSLEY, C F Exxon Nuclear Co., Inc (subs. of Exxon Corp.)
GPD 003 81 81/01/03 1p 07441 119

Suppl 1 to "Exxon Nuclear Co Plant Transient Simulator
Code for Evaluation of Abnormal Transients"
81/01/26 1p 07441 119
KELLEY, R H. PRUITT, D W. EXXON
(subs of Exxon Corp.) 80/12/22 43pp

8101090116 Summary of 801203 meeting w/Util re
reloading licensing for coming yr Meeting identified
topical repts germane to plans submitted to NRC
NRC appeared oblivious Viewgraphs encl
BERGREN, J S Standardization & Special Projects Branch
22pp 07427 305

8101090198 Forwards MEDU-24057A, "Assessment of
Vibration in BWR/4 & BWR/5 Plants" & MEDU-24057B
"Assessment of Reactor Internals Vibration in
Plants" MEDU-24057-P-A withheld w/af 10CFR2.7
QUIRK, J F General Electric Co MFN-02-81
07430 073

--8101090209 MEDU-24057A
Nonproprietary version of "Assessment of Reactor
Vibration in BWR/4 & BWR/5 Plants"
GILMAN, J D. DUCKHALD, C S. UMBLE, D G General
80/12/31 61pp 07430 079

8101090487 Forwards "BWR Owners Group Evaluation of
11 K 3 138 Reactor Core Isolation Cooling Sys
Reset"
WATERS, D B BWR Owners Group BWR00-RC-12
07440 226

--8101090493 "BWR Owners Group Evaluation of BWR
Reactor Core Isolation Cooling Sys Automatic"
* BWR Owners Group 80/12/29 97pp 07440

8101090830 Responds to 801202 ltr re organization of
Power Corp affecting nuclear QA program Change
reduce program effectiveness Change acceptable
HAASS, W P Quality Assurance Branch 80/12/1

8101130253 Forwards SCP-01, "Radcal Gamma Thermometer
Measuring Devices for Use in Cores of all PHRs"
3
MORRIS, P A Grandpower, Inc 81/01/09 1p

--8101130265 SCP-01 R3
"Radcal Gamma Thermometers as Local Power Measuring
Devices for Use in Cores of all PHRs," Revision 3
* Grandpower, Inc 80/12/31 300pp 07449

8101130984 Requests that NRC withdraw proprietary
info was submitted by owners of Westinghouse NS
response to IE Bulletin 79-01B re equipment qual
List of owners of Westinghouse NSS encl
ANDERSON, T M Westinghouse Electric Corp NS-
2pp 07452 145

8101150311 Requests addl info re ALARA design for
completion of Radiological Assessment Branch
RECC-2-P, "Radwaste Vol Reduction Sys."
TEDESCO, R L Assistant Director for Licensing
07462 118

8101160020 Notification of 810113 meeting w/Exxon
Bethesda, MD to discuss planned response to first
questions on BWR nuclear methodology w/emphasis on
verification & data bases
LOISL, Core Performance Branch 81/01/05 2pp

8101160342 Forwards revised Tables 1-2 & 1-4 from
revised Table 1-4 from ODVH 801003 submittal
& 1-4 from ODVH 800905 submittal withheld ltr
BUCHOLD, Z R II General Electric Co MFN-03-81
07468 158

--8101160361 Revised Table 1-4 from ODVH 801003 w/o
* General Electric Co 81/01/12 2pp 07468

8101160405 Approves 801110 application & affidavit
40AP-9693 (ref 10CFR2.790).
JORDAN, E L Office of Inspection & Enforcement
Director 80/12/10 2pp 07471 050

8101190225 Approves proposed Revision 9 to ETR-10
annual Revision should be referenced in Section
Programmatic changes to QA program must be subm
review prior to implementation
HAASS, W P Quality Assurance Branch 81/01/03

8101190330 Forwards nonproprietary & proprietary responses to NRC 800815 request for addl info re plant design conditions & fuel damage Application for withholding & affidavit encl Proprietary info withheld (ref 10CFR2 790) ANDERSON, T M Westinghouse Electric Corp NS-TMA-2366 81/01/12 10pp 07474 282

0101200420 Forwards nonproprietary version of WCAP-9812, "Investigation of Feedwater Line Cracking in PWR Plants," Vols 1 & 2 ANDERSON, J M Westinghouse Electric Corp NS-TMA-2356 80/12/10 1p 07400 104

--8101200423 WCAP-9812 Nonproprietary version of "Investigation of Feedwater Line Cracking in PWR Plants," Vols 1 & 2 WHITE, O H, CAMPBELL, T E Westinghouse Electric Corp 81/12/31 700pp 07480 105

8101210246 Staff requirements memo re 801217 briefing on TVA activities in emergency offsite facilities Requests comments on acceptability of util proposal to control facilities & applicability of concept to other licensees CHILK, S J Office of the Secretary of the Commission 8012178 80/12/10 1p 07492 047

8101210359 Forwards Revision 3 to proprietary rept BAW-10804P-A, "Program to Determine In-Reactor Performance of BWR Fuels - Cladding Creep Collapse," Rept withheld (ref 10CFR2 790) TAYLOR, J M Babcock & Wilcox Co 81/01/13 2pp 07407 269

8101210371 Forwards Revision 1 of "Assumptions for Use in Analyzing Mark II BWR Suppression Pool Temp Response to Plant Transients Involving Safety/Relief Valve Discharge," provided on behalf of Mark II owners group DUCHIOLZ, R H General Electric Co MFN-014-B1 81/01/09 2pp 07489 039

--8101210373 Revision 1 of "Assumptions for Use in Analyzing Mark II BWR Suppression Pool Temp Response to Plant Transients Involving Safety/Relief Valve Discharge," * Mark II Owners Group 80/12/31 24pp 07489 037

8101210372 Forwards Duppl 2 to proprietary repts WCAP-8607, E16A & WCAP-8607, E16B, Suppl 2 to nonproprietary WCAP-0907, E16A & WCAP-8587, E16D & Revision 2 to EODP-EGE-16 of Duppl 1 to WCAP-8507 Proprietary repts withheld (ref 10CFR2 790) ANDERSON, T M Westinghouse Electric Corp NS-TMA-2360 81/01/16 10pp 07407 291

--8101210375 WCAP-0907 82-E16B Nonproprietary version of Duppl 2-E 16B to "Equipment Qualification by Combined Analysis & Test Approach for Four-Day Cabinet of Two-Train Solid State Protection Sys 185PB1, 185PB2 Design Verification Analysis & Design," TAND, B, CHANG, B M, VOOEJOIND, E L Westinghouse Electric Corp 80/12/31 20pp 07407 301

--8101210377 EODP-EGE-16 R2 "Solid State Protection Sys (66PB) Two-Train & Safeguard Test Cabinet Three & Four-Day," equipment data qualification package included in Duppl 1 to WCAP-8507 (nonproprietary) ANDERSON, T M Westinghouse Electric Corp Nuclear Energy Systems 5206A 81/01/31 27pp 07407 321

--8101210401 WCAP-8587 82-E16A Nonproprietary version of Duppl 2-E16A to "Equipment Qualification Test Rept Two-Train Solid State Protection Sys (Normal & Abnormal Temp & Humidity Testing)," POTOCINIK, L M, ANDERSON, T M, RAMCIANDRAM, B Westinghouse Electric Corp 81/01/16 22pp 07487 348

8101210382 Discusses draft BER approach to nuclear facility licensing review Direct discussions between NRC & applicant proved more efficient than written question & answer cycle Approach provided early resolution of issues CHAN, A L Bechtel Power Corp Subs of Bechtel Corp 81/01/14 2pp 07489 072

8101210483 Forwards comments re future LOFT test plans for special review group. No tests necessary on safety basis Submits table summarizing tests useful for code assessment LOFT not representative of expected PWR behavior ANDERSON, T M Westinghouse Electric Corp NS-TMA-2369 81/01/16 7pp 07409 271

8101210515 Forwards proprietary version of NEDE-24284-P, "Assessment of Fuel Rod Bowing in GE BWRs," Aug 1980 Withholding requested (ref 10CFR2 790) Rept available in Central Files only SUCHMOLZ, R H General Electric Co MFN-221-80 80/12/23 4pp 07490 112

8101210523 Discusses status of NRC review of Addenda 1 to NED "Power Generation Control Complex Design Criteria & Safety Evaluation," Summary of factory cable cabling process controls provided in 791213 1p 7410, 11 G General Electric Co MFN-004-B1 81/01/12 2p 07490 104

--8101210529 Forwards Friata 1 to NEDU-10466-A, "Power Generation Control Complex Design Criteria & Safety Evaluation," clarifying cable connector requirements STADUM, E P General Electric Co MFN-011-80 80/01/10 07490 106

--8101210531 NEDU-10466-A FR1 1 Friata 1 to Power Generation Control Complex Design Criteria & Safety Evaluation * General Electric Co 79/12/31 5pp 07490 107

8101220426 Confirms 801201 telcon & requests approval of changes approved ECCS evaluation models resulting in higher calculated fuel cladding temps Change does not affect acceptability of previous calculation results ANDERSON, T M Westinghouse Electric Corp NS-TMA-2354 81/01/12 2pp 07502 291

8101220528 Forwards XN-MF-80-5611P4, "Generic Mechanical, Thermal, Hydraulic & Neutronic Design for Exon Nuclear ICPRU0 Reins Fuel Assemblies for PWRs," DUSLEY, D F Exon Nuclear Co, Inc Subs of Exon Corp 1 GFO:008 B1 01/01/20 1p 07502 269

--8101220534 XN-MF-80-5611P4 "Generic Mechanical, Thermal, Hydraulic & Neutronic Design for Exon Nuclear ICPRU0 Reins Fuel Assemblies for PWRs," BROWN, D A, MACDOUFF, K B, HILLY, P O Exon Nuclear Co, Inc Subs of Exon Corp 1 80/12/18 12pp 07502 290

8101230021 Forwards proprietary & nonproprietary versions of "Analysis & Test Verification Data for Four Loop Rod Exchange Technique for Rod Worth Measurement," Proprietary version withheld (ref 10CFR2 790) Affidavits encl ANDERSON, T M Westinghouse Electric Corp, PWR Systems Div NS-TMA-2367 81/01/20 11pp 07513 293

--8101230232 Nonproprietary version of "Analytical & Test Verification Data for Four Loop Rod Exchange Technique for Rod Worth Measurement," * Westinghouse Electric Corp 81/01/20 21pp 07513 294

8101230300 Requests final concurrence L/OE approach to fatigue required by ASME codes as presented in sample evaluations at 801007 meeting in San Jose, CA GAWO, W O General Electric Co MFN 011-B1 81/01/15 2pp 07513 042

8101260516 Forwards nonproprietary versions of "Summary Rept, Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (7300 Sys) (Microprocessor Sys) & UMI Plant," Extra copy of Page 4-32 encl ANDERSON, T M Westinghouse Electric Corp NS-TMA-2371 01/01/20 2pp 07532 089

--8101260647 Nonproprietary version of "Summary Rept, Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (Microprocessor Sys)," * Westinghouse Electric Corp 80/12/30 75pp 07532 07

--8101260652 Nonproprietary version of "Summary Rept, Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (7300 Sys)," * Westinghouse Electric Corp 80/12/31 75pp 07532 11

--8101260657 Nonproprietary version of "Summary Rept, Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (UMI Plant)," * Westinghouse Electric Corp 80/12/31 75pp 07532 25

8101270427 Advises that QA review & concurrence of procedures containing QA requirements will be completed by 810420 Manpower efforts were redirected to priority tasks. KILLS, L M Tennessee Valley Authority 81/01/23 1p 07532 042

8101270598 Forwards ATR-1320, "Analysis of Maldon Irradiation Assembly IFA-223 by GEAP-3 Code," included in NEDE-23705-P Rept withheld (ref 10CFR2 790) Affidavits encl DUCHIOLZ, R H General Electric Co MFN-014-B1 81/01/21 07546 144

8101270709 Forwards Supp 1: "Sys-80 Reactor Coolant Pump Loss of Component Cooling Water Test Rept." to CENPD-201-A. "Performance of C-E Sys-80 Reactor Coolant Pump W/Loss of Component Cooling Water." SCHEERER, A. E. C-E Power Systems. LD-81-006. 81/01/22. 1p. 07545:249.

--8101270714 CENPD-201-A S1 "Sys-80 Reactor Coolant Pump Loss of Component Cooling Water Test Rept." * C-E Power Systems. 81/01/22. 19pp. 07545:250.

WASTE MGT NUCLEAR WASTE MANAGEMENT

8101060114 Responds to 001119 telcon re revision to criteria re cleanup of contamination from Church Rock U mill tailings dam break Revised criteria acceptable. MARTIN, J.B. Division of Waste Management. 80/12/08. 3pp. 07399:091.

--8101060119 Informs that reply to NM should include acknowledgment of receipt of revised criteria info that mods best carried out by NM & offer of continuing contract support, if possible. DAVIS, J.O. Office of Nuclear Material Safety & Safeguards. 80/11/17. 1p. 07399:094.

--8101060122 Requests that NRC offer svcs of consultant to State of NM. DAVIS, J.O. Office of Nuclear Material Safety & Safeguards. 80/10/31. 3pp. 07399:095.

--8101060127 Requests comments on plan to clean up land contaminated by 790716 tailings dam spill. Ltr to United Nuclear Corp from state & amend to state order encl. BACA, T.E. New Mexico. State of. 80/10/14. 8pp. 07399:098.

--8101060130 Informs that JF Ahearn wishes chronology & status rept re decontamination of 790716 tailings dam spill. * Commissioners. 80/10/22. 1p. 07399:106.

8101070523 Comments on "Environ Cleanup Stds (8-2214-0)" for Aug-Oct 1980. Relevant literature searches "w/particular investigators known to have participated in related environ surveillance programs" found not vigorously pursued. EDDIE, G.G. Uranium Recovery Licensing Branch. 80/12/12. 2pp. 07415:293.

8101070528 Confirms 801126 discussions re organization & conduct of workshop concerning radiological surveys in support of Edgemont Cleanup Action Program. Lab is authorized to organize, conduct & participate in workshop. EDDIE, G.G. Uranium Recovery Licensing Branch. 80/12/12. 2pp. 07415:291.

8101070532 Forwards M O'Brien & C Oyster of Gunnison Valley Alliance 801117 ltr re Homestake Mining Corp mill application in CO. Ofc of State Programs should respond as matter involves Agreement State. SCARAND, R.A. Uranium Recovery Licensing Branch. 80/12/11. 1p. 07415:288.

--8101070537 Urges NRC to investigate concentrated mineral development planned for Gunnison County, CO Granting license to Homestake Mining Corp for mill & tailing pond would endanger entire surface & subsurface water sys. O'BRIEN, M.T., OYSTER, C.L. Affiliation Unknown. 80/11/17. 2pp.

8101070542 Forwards JO Nelson rept in response to request for technical assessment of adequacy of NM Followup to NRC issues raised by Church Rock dam failure. W/o rept. SCARAND, R.A. Uranium Recovery Licensing Branch. 80/12/09. 1p. 07415:287.

8101070547 Discusses 801121 state hearing on Dawn Mining Co proposed below-grade tailings impoundment. NRC requirement for rock cover post reclamation unwarranted. LINEHAN, J.J. Uranium Recovery Licensing Branch. 80/12/10. 1p. 07415:286.

8101090722 Forwards RE Williams rept re groundwater contamination problem in vicinity of Cotter Mill in Canon City, CO. Technical assistance will be provided for expeditious resolution of shallow aquifer contamination problems. SCARAND, R.A. Uranium Recovery Licensing Branch. 80/12/09. 1p. 07430:329.

--8101090729 "Status of Cotter Corp Mill Tailings Pond Seepage Project as of 801106." WILLIAMS, R.E. Affiliation Unknown. 80/11/06. 8pp. 07430:330.

8101190089 Requests that G Castro of Geotechnical site on 810106 to determine whether safety evaluation recommendations have been adequately realized in stabilization program. Decision anticipated in Feb. HAZLE, A.J. Colorado. State of. 18082. 80/12/0.

8101270155 Ack receipt of 801015 ltr re license for ore buying station. State license issued to facil 800915. Copies of all U licenses issued by NRC since requested. HAZLE, A.J. Colorado. State of. 80/12/05. 24pp.

8101270260 Trip rept of 800609-23 visit to ANL, ORNL investigations on geotechnical retardation. ROBBINS, G. Office of Nuclear Material Safety & Safeguards. BIRCHARD, G. Division of Safeguards, Fuel Cycle & Research. O'DONNELL, E. Office of Standards Development. 80/09/30. 47pp. 07547:117.

8101270354 Requests NRC attendance at 810107 & 08 mgt present & future Uravan waste mgt sys. HAZLE, A.J. Colorado. State of. 18081. 80/12/05.

8101270467 Expresses concern w/acquisition of financial arrangements provided for proper decommissioning, decontamination & reclamation of U mill site & tailings. Related info encl. HAZLE, A.J. Colorado. State of. 18083. 80/12/08.

--8101270470 Deposition re operation of Uravan mill site encl. HIETT, C.M. Union Carbide Corp. 18083. 80/09/11. 07543:230.

--8101270475 Supplemental deposition re operation of 1942-1976. Exhibits encl. HIETT, C.M. Union Carbide Corp. 18083. 80/09/11. 07543:241.

8101270528 Trip rept of 800908-19 technical survey of TX & MS under preliminary investigation as possible level nuclear waste storage sites. HART, P., JOHNSON, R.L. High Level Waste Technical Division. MICHAELSON, T.J. Geosciences Stds. Div. (formerly SI Br.). 81/01/31. 57pp. 07543:251.

8101270941 FES for proposed Dawn Mining Co mill tailings project. * Washington, State of. 81/01/05. 221pp. 07549:20.

8101270961 Forwards Water Quality Monitoring Rept 7-80, of water sample analyses made during Sept 1980. CAHN, J. Cotter Corp. 18174. 80/12/18. 5pp. 07549:20.

8101270968 Comments on NRC negative declaration re Anac project. NRC grant of waiver to manufacturer may have of removing project from state jurisdiction. BAILEY, E.D. Texas. State of. 18173. 80/12/16. 4pp.

8101280033 Trip rept of 800707-18 visit to Columbia Plant & hydrology & Hanford Reservation re field studies. HARTUNG, L. SIEFEN, D. High Level Waste Technical Division. LEHMAN, L. High Level Waste Licensing Management. 80/09/30. 46pp. 07556:300.

8101290010 Forwards response to comments on NRC input for revisions to draft EIS. SCARAND, R.A. Uranium Recovery Licensing Branch. 80/12/09. 07575:300.

8101290649 Forwards "Union Carbide Corp, Uravan Co, SUA-0673 Disposal Rept, Nov. 1980." JONES, R.R. Union Carbide Corp. 18175. 80/12/16. 1p.

--8101290654 "Union Carbide Corp, Uravan, CO, SUA-0673 Solid Rept, Nov 1980." * Union Carbide Corp. 80/12/16. 46pp. 07309:001.

EXPORT LIC EXPORT AND IMPORT LICENSES

7909210430 Discusses findings re license request by NL Ind to import 47 kg of U, containing 17 kg U-235 enriched to 10% from Canada to Savannah River Project, Aiken, SC. Import will not be unreasonable risk to public. MOORE, R.N. Office of International Programs, Director. 2pp. 00752:303.

8101050424 Reiterates concerns in 800620 petition to intervene re export of two reactors to questionable site in Taiwan. Evidence of significant seismic dangers posed by Yen Liao site encl
MATTISON, L Center for Development Policy 80/12/11 9pp

8101050487 Response to Ctr for Development Policy 801209 petition to intervene DCS position identical to that taken in 800721 response to CDP petition re GE & Westinghouse applications for exports to Taiwan Certificate of Noe encl
BETTAUER, P J State Dept of 80/12/27 4pp 07390 317

8101050584 License for Sigma Chemical Co to export 10 kg deuterium oxide to India
DEVINE, J B Assistant Director for Export/Import & International Safeguards D-61 80/12/26 2pp 07390 245

8101060210 Application by Sigma Chemical Co for license to export 10 kg deuterium oxide over 2-yr period to Italy
STERN, M C Sigma Chemical Co (subs of Sigma-Aldrich Corp) 80/11/24 1pp 07391 316

8101060264 Forwards IE insp rept on 801201 of activities under License XSNM-1656 No noncompliance noted insp rept withheld
ref 10CFR2 7901
MORDEHAU, L R Region 5, San Francisco, Safeguards Branch 80/12/17 2pp 07342 008

8101060889 License for Seanoval Transport Corp to export 2.7 kg natural U & 230 g U as NBS stds. to Belgium
DEVINE, J B Assistant Director for Export/Import & International Safeguards A0/1542 80/12/19 2pp 07401 053

8101060892 Forwards duplicate export license applications previously sent 801129
WILSON, B H General Electric Co MW 80137 80/12/10 1p 07401 035

8101060874 License for Aldrich Chemical Co, Inc to export 5 kg deuterium oxide to India
DEVINE, J B Assistant Director for Export/Import & International Safeguards 21/80 80/12/19 2pp 07401 057

8101060956 License for Mitsubishi Intl Corp to export 399 kg U-235, contained in 14,613 kg U to Japan
DEVINE, J B Assistant Director for Export/Import & International Safeguards H8A-9480-09 80/12/19 2pp 07187 001

8101060978 License for Exxon Nuclear Co, Inc to export 76 kg U-235, contained in 2,670 kg U as U dioxide fuel pellets or fabricated fuel elements, to West Germany
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/19 2pp 07401 059

8101070225 Application by QA Co for Amend 2 to license to export miscellaneous specially designed parts & components to Canada, extending license for 3 yrs
MOWRY, W R General Atomic Co (subs of Gulf Oil Co) 1E1-2030 80/12/09 1p 07410 294

8101070305 Informs that since no well changed circumstances exist since issuance of License XSNM-166B, License XSNM-1730 may be issued
MOORE, R N Assistant Director for Export/Import & International Safeguards 80/12/13 1p 07187 001

8101070310 License for Mitsui & Co (USA), Inc to export 426 kg U-235, contained in 22,475 kg U as U dioxide, to Japan
DEVINE, J B Assistant Director for Export/Import & International Safeguards MBK-HI-R7 80/12/19 2pp 07187 001

8101070652 Informs that since no well changed circumstances exist since issuance of License XSNM-166B, License XSNM-1734 may be issued
MOORE, R N Assistant Director for Export/Import & International Safeguards 80/12/13 1p 07187 001

8101070655 License for Mitsubishi Intl Corp to export 337 kg U-235, contained in 11,823 kg U to Japan
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/19 2pp 07187 001

8101080332 Informs that Teledyne Wah Chang Albany has requested expeditious processing of request to export components to West Germany. License issued w/o normal 15 day waiting period
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/12 1p 07421 326

8101080340 License for Teledyne Wah Chang Albany to export 2 Zircaloy-2 tube shells to West Germany
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/12 1p 07421 327

8101080350 Submits status rept re pending appeals court case challenging IIRC export license issuance for nuclear reactor to be constructed in Philippines & implementation of Executive Order 12114
STOBER, C Office of the General Counsel 80/12/16 13pp 07419 276

8101090256 Executive Branch position re C E application for license to export 8,782 kg U enriched to max of 11.5% for initial cores & one full core reload to Taiwan. License should be issued
MOSEKOW, L V State Dept of, Bureau of Oceans & International Scientific Affairs 80/12/12 13pp 07424 018

8101090429 Application by Intl Business Development to amend license extending expiration date to 811231
MORROW, M International Business Development 80/12/31 07442 014

8101090531 Discusses PML 801125 application for license to import 607 g U enriched U from United Kingdom, West Germany & Belgium re high burnup investigations of LWR sintered U. License subject fuel import not critical to defense
MOORE, R N Office of International Programs, Director 80/12/11 1p 07442 186

8101090538 License for PML to import 607 g U containing 39 g U from United Kingdom, West Germany & Belgium
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/11 1p 07442 187

8101090522 Executive Branch position re Harburt America Corp application for license to export 3,486 kg U-235, contained in 156,333 kg U dioxide, to Japan Ltr of assurance encl
MOSEKOW, L V State Dept of, Bureau of Oceans & International Scientific Affairs 80/12/01 2pp 07187 001

8101090532 Forwards notice of receipt for licenses to export/import nuclear facilities or materials Requests FR publication
MOORE, R N Office of International Programs, Director 80/12/24 2pp 07427 354

8101090912 Ltr of assurance re Transnuclear, Inc application for license to export 1,197 kg U-235, contained in 34,900 kg U to West Germany
MORROW, J European Communities, Commission of 80/12/04 02543 207

8101090919 Ltr of assurance re Transnuclear, Inc application for license to export 847,705 kg U-235, contained in 25,931 kg U to West Germany
MORROW, J European Communities, Commission of 80/12/01 03873 270

8101090524 Ltr of assurance re Edlow Intl Co application for license to export 19,865 kg U, containing 675 kg U-235, to Sweden
MORROW, C Sweden 80/12/11 1p 03873 291

8101090774 License for Sigma Chemical Corp to export 10 kg deuterium oxide to India
DEVINE, J B Assistant Director for Export/Import & International Safeguards D-59 80/12/26 2pp 03775 001

8101090778 License for Exxon Nuclear Co, Inc to export miscellaneous specially designed nuclear fuel element hardware to West Germany. Export of assembled pressure vessels & primary coolant pumps not authorized
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/22 1p 03775 001

8101090981 License for Exxon Nuclear Co, Inc to export specially designed nuclear fuel element hardware to West Germany. Export of assembled pressure vessels, primary coolant pumps, fuel charging & discharging machines not authorized
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/22 1p 03775 001

8101090987 Amend 2 to license for Edlow Intl Co, allowing construction of re-export from United Kingdom 3.7 mg Cf-252 as cermet wire to India
DEVINE, J B Assistant Director for Export/Import & International Safeguards TRC-4 80/12/26 1p 03775 001

- 810100570 License for Carpenter Technology Corp to export 24 2mm diameter-3 fuel channels & 24 2 5mm diameter-4 fuel channels to Japan
LEVINE, J B Assistant Director for Export/Import & International Safeguards CAP TECH-570 01 80/12/30 1p 03775 001
- 810100572 Executive Branch position re Westinghouse application for license to export two light water moderated steam supply sys to Taiwan Ltr of assurance encl license should be issued subject to Section 4 of analysis
NOSEN20, L V State Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/12/12 13pp 03893 333
- U01100089 Ltr of assurance re export of 395 kg U-235, contained in 14 417 kg U, to Japan Kansai Electric Power Co. Inc is designated as authorized person
MIYABAYASHI, H Japan 80/12/04 1p 07445 003
- 810110092 Ltr of assurance re export of 493 kg U-235, contained in 19 141 kg U, to Japan Kansai Electric Power Co. Inc is designated as authorized person
MIYABAYASHI, H Japan 80/12/04 1p 07445 605
- 810110099 Ltr of assurance re export of 337 kg U-235, contained in 17 823 kg U, to Japan Kansai Electric Power Co. Inc is designated as authorized person
MIYABAYASHI, H Japan 80/12/04 1tp 07445 007
- 8101100102 Ltr of assurance re export of 626 kg U-235, contained in 22 475 kg U, to Japan Chubu Electric Power Co. Inc is designated as authorized person
MIYABAYASHI, H Japan 80/12/04 1p 07445 009
- 8101100161 Responds to FOIA request for five categories of documents re transportation of Pu Forwards documents listed in Apps A & B info partially withheld safeguards info (ref FOIA Exemption 3)
FELTON, J M Division of Rules and Records 80/12/12 6pp
- 8101100198 Discusses findings re proposed import of Pu-242 & 244 by Univ of CA Mbl is of US origin import meets statutory requirements, will not be inimical to common defense & security & will have no significant environ impact
MCORE, R H Office of International Programs, Director 79/10/10 1p
- 8101100203 License for Ramsey Engineering Co to import 35 2 mg Pu-238, 80-70% concentration, contained in 20 Pu-238 sources, from any country
SHEA, J R Office of International Programs, Director 78/06/21 2pp
- 8101100210 Discusses findings re proposed import of Pu-238 sources by Ramsey Engineering Co Air transport is prohibited import meets statutory requirements, will not be inimical to common defense & security & will not pose undue risk to public
MCORE, R H Office of International Programs, Director 78/06/21 1p
- 8101100222 Discusses BOGDIY request for increase in quantity & extension of expiration date for license issued to NL Industries to import 47 1 kg U from Canada Requested amends will not constitute unreasonable risk
MCORE, R H Office of International Programs, Director 80/03/28 1p
- 8101100230 License for NL Industries, Inc to import 47.1 kg U, containing up to 27 0 kg U-235 as spent NMX & TRU reactor fuel, from Canada
PETERSON, R Assistant Director for Export/Import & International Safeguards 79/08/20 2pp
- 8101100239 Amend 1 to license for CE to import 8 403 kg U, containing 0 442 kg U-235, enriched to 13.3 w/o max & 54 1 g Pu as metal clad fuel rods, from Norway, extending expiration date to 811001 All other conditions remain unchanged.
LEVINE, J B Office of International Programs, Director 80/08/19 1p
- 8101100261 Discusses findings re DOE proposed report of high enriched U from Germany, Netherlands & France Import will not be inimical to common defense & security or constitute undue risk to public health, safety or environ.
MCORE, R H Assistant Director for Export/Import & International Safeguards 79/12/28 2pp
- 8101100272 Discusses findings re DOE proposed report of low enriched U
- 8101100281 Discusses findings re proposed amend to authorize import of 243 31 kg U, containing U-235 & 345 3 g of produced Pu Proposed amend inimical to common defense & security
MCORE, R H Office of International Programs, 1p
- 8101100288 SECY-70-433
Discusses Transnuclear, Inc proposed amend to import highly enriched U, to authorize addl B containing 6 27 kg U-235 & 0143 kg produced & Austria Proposed amend should be issued
SHEA, J R Office of International Programs, 2pp
- 8101100306 Concurs in issuance of proposed Amend
ISM, M-01699
SMITH, C V Office of Nuclear Material Safety 78/08/02 1p
- 8101100310 Advises that Commission has accepted License ISMM-01699 to authorize addl import of Germany Any re-export will be subj to terms of Non-Proliferation Act
CHILK, S J Office of the Secretary of the Com 1p
- 8101100322 Application by Transnuclear, Inc to a irradiated fuel elements from West Germany, to 1156d quantities of elements
MATSON, V Transnuclear, Inc 78/01/13 3pp
- 8101100327 Concurs in issuance of proposed amend to import high-enriched U
SMITH, C V Office of Nuclear Material Safety 78/03/01 1p
- 8101100338 Advises that Commission approves proposed Transnuclear, Inc to import 159 B kg U, enriched U-235 & 186 g produced Pu in form of irradiated elements, from West Germany
CHILK, S J Office of the Secretary of the Com 1p
- 8101100345 SECY-77-465
Recommends approval of Transnuclear, Inc proposed import 159 B kg high-enriched U in spent MTR from Germany
SHEA, J Office of International Programs, Director 78/06/21 3pp
- 8101100362 Application by Transnuclear, Inc to a license to import U & U-235, from West Germany, quantity of U to 159 B kg & U-235 to 121 5 kg.
MATSON, V Transnuclear, Inc 77/04/07 1p
- 8101100368 Responds to NRC 770224 request. Advise from requirements in 10CFR73 in accordance w/ 73 61b1.
MATSON, V Transnuclear, Inc 77/02/25 1p
- 8101100386 Discusses findings re proposed license to import 159 B kg U in form of irradiated fuel from West Germany Importation will not be inimical to common defense & security Draft license encl
MCORE, R H Office of International Programs, 4pp
- 8101100298 Application by Westinghouse for license compensated ionization chambers, Model WL6777, to SCHNAUTZ, C E Westinghouse Electric Corp ZE-2 07443 310
- 8101100300 Application by Nuklearna Elektrarna Krska to import 280,000 lbs natural U, from Yugoslavia
DULAR, J Affiliation Unknown 80/12/11 2pp
- 8101100435 Executive Branch position re Transnuclear for license to export 2,065.5 kg U-235 enriched & 136 kg U-235 enriched to 3.4% to West Germany should be issued Ltr of assurance encl
NOSEN20, L V State Dept of Bureau of Oceans & Scientific Affairs 80/12/27 3pp 07444-19B
- 8101100442 Executive Branch position re Teledyne for license to export 2 9 to depleted U to China

B101100493 Executive Branch position re Transnuclear, Inc. application for license to export 7,965 kg U-235 enriched to max 3.35% & 1675 kg U-235 enriched to 3.35% to West Germany. License should be issued Ltr of assurance encl.
NOSENZO, L V State, Dept. of, Bureau of Oceans & International Environ & Scientific Affairs 80/12/29 3pp 07444 238

B101100461 Executive Branch position re Westinghouse application for license to export six radiation surveillance capsules containing total of 90 mg HP-237 to Republic of Korea. License should be issued.
NOSENZO, L V State, Dept. of, Bureau of Oceans & International Environ & Scientific Affairs 80/12/29 1p 07444 241

B101100470 Requests Executive Branch position re Pacific Pumps, Inc. application for license to export miscellaneous specially designed components for coolant pumps to India. Views re applicability to Atomic Energy Act criteria requested.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/31 1p 07444 242

B101100474 Executive Branch position re Edlow Intl Co application for license to export 50,000 Ci tritium in bulk gaseous form to United Kingdom. License should be deferred.
NOSENZO, L V State, Dept. of, Bureau of Oceans & International Environ & Scientific Affairs 80/12/22 2pp 07444 243

B101100480 Executive Branch position re Westinghouse application for license to export one compensated ion chamber to Indonesia. License should be issued.
NOSENZO, L V State, Dept. of, Bureau of Oceans & International Environ & Scientific Affairs 80/12/22 2pp 07444 245

B101100485 Executive Branch position re Embassy of Austria application for license to export enriched U fuel Encl ltr of assurance meets requirements of Section 127 (3) of Atomic Energy Act.
NOSENZO, L V State, Dept. of, Bureau of Oceans & International Environ & Scientific Affairs 80/12/12 2pp 07444 247

B101100488 License for Teledyne Isotopes to export 2.9 kg depleted U in form of calibr plates contained in TLO sys to China.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/31 2pp 07444 249

B101100494 License for Westinghouse to export one compensated ionization chamber, Model HL 0105, to West Germany.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 2E-10227 81/01/07 1p 07309 001

B101100499 Application by Reuter-Stokes, Inc. for license to export 20 regenerative incore neutron detectors, Model RS-C6-1100-242, to Sweden.
EECHMOUT, A Reuter-Stokes, Inc W-0824 80/12/22 1p 07444 262

B101100509 Application by Isotope Products Labs for license to export 10 uCi neutron source Cf to Austria.
HELM, K Isotope Products Laboratories W/O 8339 80/12/19 2pp 07444 271

B101100515 Application by Matheson Gas Products for license to export five Btse 4 cylinders, containing total of 503 liters chemically pure deuterium to Australia.
W300, L O Matheson Gas Products 80/12/22 1p 07444 278

B101100521 License for Westinghouse to export one compensated ionization chamber, Model HL23743, to France.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 81/01/02 1p 07309 001

B101100525 Application by Westinghouse for license to export 12 BF3 proportional counters to West Germany.
PDCAL, W F Westinghouse Electric Corp 2E-10349 80/12/17 1p 07444 279

B101100548 License for Westinghouse to export three compensated ionization chambers, Model HL 6377, to France.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 2E-20359 80/12/31 1p 07444 288

B101100555 License for Reuter-Stokes, Inc. to export one incore fission chamber, Model RS-06-0201-231, to West Germany.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 81/01/02 1p 07309 001

B101100558 License for Edlow Intl Co to export 100,000 Ci tritium in bulk gaseous form to United Kingdom.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/29 2pp 07309 001

B101120023 Submits addl info re RC0721 amend request for post-enrichment storage of 248,000 kg U as natural U hexafluoride. Although consignor reactor will not go on line until late 1980s, contractual obligations must be met.
HAYMON, D W Edlow International Co 80/12/03 2pp 07447 029

B101120027 Executive Branch position re Exxon Nuclear Co, Inc. application for license to export 76 kg U-235, contained in 2,670 kg U, to West Germany. License should be issued. Encl statement encl.
NOSENZO, L V State, Dept. of, Bureau of Oceans & International Environ & Scientific Affairs 80/12/05 3pp 07447 009

B101120031 Recommends issuance of license to Syd Kraft Aktiebolag to import 138,791 kg natural U from Canada, although customary period of 15 days from posting in PDR has not yet elapsed.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/09 1p 07445 316

--B101120069 License for Syd Kraft Aktiebolag to import 138,791 kg natural U from Canada.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/09 1p 07445 317

B101120037 Amend D to license for Boeing Co to export max of 250,000 lbs depleted U in form of aircraft counterweights to 54 listed airlines. Amend adds New Zealand, Trinidad & Ivory Coast.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80C 40-7703 80/12/16 3pp 07309 001

B101120039 License for Mitsubishi Intl Corp to export 120 mg HP-237 six reactor vessel irradiation surveillance test capsules & 84 kg natural U to Japan.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 61-7239-80 80/12/16 2pp 07309 001

B101120064 Confirms that Austria will maintain physical security measures re matl exported from US to Austria under License XSM-1725 & any ENM produced by such use.
LEHMANN, R Austria 8176-A/80 80/12/09 1p 07437 360

B101120073 Confirms that Austria will maintain physical security measures re matl exported from US to Austria under License XSM-1727 & any ENM produced by such use.
LEHMANN, R Austria 8176-A/80 80/12/09 1p 07445 314

B101120080 Provides ltr of assurance that Austria will maintain physical security measures re matl exported from US to Austria under License XSM-1726 & any ENM produced by such use.
LEHMANN, R Austria 8176-A/80 80/12/09 1p 07445 315

B101120184 Executive Branch position re GE application for license to export 11,400 kg U-235, contained in 478,800 kg U, to Taiwan. License should be issued.
NOSENZO, L V State, Dept. of, Bureau of Oceans & International Environ & Scientific Affairs 80/12/12 13pp 07447 007

B101120188 Executive Branch position re Westinghouse application for license to export 12,480 kg U-235, contained in 312,000 kg U, to Taiwan. License should be issued.
NOSENZO, L V State, Dept. of, Bureau of Oceans & International Environ & Scientific Affairs 80/12/12 13pp 07447 020

B101120192 License for Nuclear Transport & Storage, Inc. to import 250,000 kg depleted U as aircraft counterweights from Canada.
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/22 1p 07447 033

B101120198 Executive Branch position re Edlow Intl Co application for license to export 100,000 Ci tritium in bulk gaseous form to United Kingdom. License should be issued.
NOSENZO, L V State, Dept. of, Bureau of Oceans & International Environ & Scientific Affairs 80/12/19 1p 07447 034

B101130115 Forwards application to export nuclear matl & equipment soon as application is accepted, all future shipments, for approx next 5 yrs, will be against new license.
MADDEN, T G New York International Customs Service, Inc 80/11/11 1p 07457 023

--B101130119 Application by NY Intl Customs Svcs, Inc. for license to export 907,185 kg depleted U in form of solid metal plates to Switzerland.
MADDEN, T G New York International Customs Service, Inc 80/11/11 1p 07457 024

--B101130122 Informs that European Organization for Nuclear Research has instructed NY Intl Customs Svc. Inc to apply for export license for shipments of depleted U plates.
DORAN, M. A. European Organization for Nuclear Research.
F1/HAO/MAD/5843 80/12/02. 1p. 07457:025.

B101130411 License for Exxon Nuclear Co. Inc to import 530 kg U-235, contained in 21,600 kg U from West Germany.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/31. 1p. 07454:051.

B101130419 Amend 1 to Transnuclear, Inc export license, extending expiration date to 820301.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. RBU 310 79-2587. 80/12/31. 1p. 07454:056.

B101130423 Amend 2 to Transnuclear, Inc export license, indicating exported matl will be in form of U-hexafluoride or U metal.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. MISC 321 80-073. 81/01/05. 1p. 07454:057.

B101130433 Amend 3 to Edlow Intl Co export license, allowing re-export from United Kingdom to West Germany of 3.5 mg Cf-252 as kernet wire.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 7AC-4. 81/01/05. 1p. 07309:001.

B101130695 License for Sigma Chemical Co to export 10 kg deuterium oxide to India.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/26. 2pp. 07309:001.

B101140139 Requests that NUKEM GmbH be designated as intermediate consignee for B01002 application to export U-308 contained in 9,000 kg U to West Germany.
HANSEN, L. E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp. 1. 80/12/11. 1p. 07460:352.

B101140258 Answer opposing Ctr for Development Policy B01209 petition to intervene & request for hearing. Petitioner fails to establish standing. Notice of appearance & Certificate of Svc encl.
SHEA, K. H. Combustion Engineering, Inc. 81/01/08. 16pp. 07458:108.

B101140266 License for Australia to export 660 kg heavy water to Australia.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. AEC RE 20/80. 80/12/16. 2pp. 07308:001.

B101140271 Informs that Teledyne Wah Chang Albany request for license to export 4,409 lb Zircaloy-2 trex tubes to West Germany resulted in issuance of license w/o normal 15-day waiting period.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/16. 1p. 07462:094.

--B101140275 License for Teledyne Wah Chang Albany to export 4,409 lb Zircaloy-2 trex tubes to West Germany.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 3685 (JFM). 80/12/16. 1p. 07462:095.

B101140281 License for Nissho-Iwai American Corp to export 1.82 Ci Cf-252, contained in sealed neutron radiation source, to Japan.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. OBM-1262. 80/12/16. 2pp. 07308:001.

B101140319 Application by Carpenter Technology Corp for license to export 48 BWR Zircaloy-4 fuel channels to Japan.
WOZNIAK, D. R. Carpenter Technology Corp. 80/12/05. 5pp. 07462:089.

B101140350 Informs that license may be issued since there are no matl changed circumstances associated w/ License XSNM-1744 since previous issuance.
MOORE, R. N. Office of International Programs, Director. 80/12/19. 1p. 07458:139.

T. Inc to export 847.705 kg U-235 in 3 U-235 in 1 kg
or Export/Import & International
12/31. 2pp. 07458:140.

c export license, reflecting that
ride or U-metal.
port/Import & International
/02. 1p. 07461:100.

B101140825 License for Westinghouse to export 90 uCi neptunium-237 contained in six radiation surveillance capsules to Korea.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/21. 2pp. 07308:001.

B101140879 Submits application to amend license to import additional quantities of irradiated fuel elements packaged in modified Gaslar container.
MATSON, V. Transnuclear, Inc. 80/12/23. 2pp. 07461:288.

B101140885 Application by Reuter-Stokes, Inc for license to export Reuter-Stokes Model RS-C3-2510-114 ion chamber to Great Britain.
ECKHOUT, A. Reuter-Stokes, Inc. W-8857. 80/12/30. 1p. 07461:288.

B101140890 Requests name of intermediate consignee be changed to subsidiary.
HARMON, D. W. Edlow International Co. 80/12/15. 1p. 07458:351.

B101140892 Amend 3 to Edlow Intl Co export license, extending expiration date to 810101.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. UEB/SW-1. 80/12/31. 1p. 07461:291.

B101140896 Informs that license may be issued since there are no matl circumstances since XSNM-1572 issued.
MOORE, R. N. Office of International Programs, Director. 80/12/19. 1p. 07461:292.

--B101140905 License for Exxon Nuclear Co. Inc to export 240 kg U-235, 10,000 kg U-hexafluoride, to West Germany.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/31. 2pp. 07461:293.

B101140903 Requests amend of B00115 ltr re Transnuclear, Inc application for license to export Amount of total U should be 905,849 kg.
MARCHAL, J. European Communities, Commission of. TNP-288. 80/12/19. 1p. 07458:354.

B101140914 Notifies that NRC has not completed licensing action on application to export Zirconium extruded tubes to Romania.
SHEA, J. R. Office of International Programs, Director. 81/01/02. 1p. 07458:355.

B101140922 Notifies that NRC has not completed licensing action on application to export specially designed & prepared equipment to Switzerland.
SHEA, J. R. Office of International Programs, Director. 81/01/02. 1p. 07458:356.

B101140930 Requests Commission expedite export request after receipt of necessary info from Executive Branch. Delay causes inability to meet customer obligations.
TAYLOR, R. R. Monsanto Research Corp. 80/12/24. 1p. 07458:357.

B101140934 Application for license to import Pye Dynalene PD2F Otto Fuel Detector.
HAAS, D. J. Philips Electronic Instruments, Inc. DJH-B0-110. 80/12/12. 1p. 07458:358.

B101140945 Submits application to amend license to change name & address of intermediate consignee in item 14 to Japan.
Nuclear Fuel Conversion Co. Ltd. 2600 Ishigami Tojoku, Tokamura Naka-Gun Ibaragi Pref. Japan.
SHIMA, S. Mitsubishi International Corp. (subs. of Mitsubishi Corp. 1. HSA-5480-10. 80/12/19. 2pp. 07461:056.

B101140950 Submits application to amend license to change name & address of supplier in item 4 to Goodyear Atomic Corp. P.O. Box 628, Picketon, OH 45601.
SHIMA, S. Mitsubishi International Corp. (subs. of Mitsubishi Corp. 1. HSA-5480-11. 80/12/19. 2pp. 07461:058.

B101140954 Forwards application for license to export deuterium oxide to Great Britain.
EDELSTEIN, B. Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich Corp. 1. 80/12/29. 1p. 07457:109.

--B101140959 Application by Aldrich Chemical Co. Inc for license to export 10 kg deuterium in 40 kg deuterium oxide to Great Britain.
EDELSTEIN, B. Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich Corp. 1. 80/12/29. 1p. 07457:110.

B101150020 Forwards application for license to export U in form of U-hexafluoride to Switzerland.
MATSON, V.

--B10115026 Application by Transnuclear, Inc. for license to export 4,254.769 kg U-235, contained in 127,008 kg U-hexafluoride & 0.179 kg U-233, contained in 5 kg U-hexafluoride, to Switzerland
MATSON, V. Transnuclear, Inc. RDU 359 80-258/ 80/12/30 3pp 07462 162

B101190031 Forwards application for license to export SHM to Japan
SAIKI, T. Mitsui & Co. (U.S.A.), Inc. (Subs. of Mitsui & Co., Ltd.) 80/12/23 1p 07462 166

--B101190034 Application by Mitsui & Co. (USA), Inc. for license to export 6 kg U-233, contained in 137 kg enriched U-hexafluoride, to Japan
MAYDEN, T. Mitsui & Co. (U.S.A.), Inc. (Subs. of Mitsui & Co., Ltd.) MBX-NALQ 00/12/23 2pp 07462 167

B101190049 Requests that DOE advise govt. of Japan of Edlow Intl requested change of intermediate consignee on Export License Application XBNM-1760 so ltr of assurance will contain correct intermediate consignee
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 80/12/31 1p 07462:182

B101190256 Requests Executive Branch position re Edlow Intl 801218 request for Amend 4 to License X3-1091 for removal of condition of prior approval for re-export of 3.5 mg Cf-252 from United Kingdom to West Germany
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 81/01/05 1p 07465 354

B101190265 Forwards Elion Nuclear Co. Inc. ltr advising that intermediate consignee on export license application will be NUXEM GmbH W/O encl
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 80/12/31 1p 07465 359

B101190467 Informs license may be issued since no matl changed circumstances since XBNM-1744 issued
MOORE, R.N. Office of International Programs, Director 80/12/19 1p 073011 001

--B101190472 License for Transnuclear, Inc. to export 1,159 kg U-235, in 34,900 kg U-hexafluoride, & 0.0332 kg U-233, in 1 kg U-hexafluoride, to West Germany
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards RDU 359 80-230/ 80/12/31 2pp 07308 031

B101190477 Informs license may be issued since no matl changed circumstances since XBNM-1572 issued
MOORE, R.N. Office of International Programs, Director 80/12/08 1p 07309 001

--B101190481 License for Edlow Intl Co. to export 699 kg U-235, contained in 19,065 kg U-hexafluoride, to Sweden
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 80/12/31 2pp 07309 001

B101190620 Discusses findings re proposed import of depleted U metal castings by Nuclear Transport & Storage, Inc. from Canada
License should be issued
MOORE, R.N. Office of International Programs, Director 80/12/22 1p 07465 253

B101190218 Requests withdrawal of condition to obtain prior approval for re-export, excluding specific countries if timely exemption cannot be granted; requests approval to re-export 3.5 mg Cf-252 source to West Germany
HARMON, D. Edlow International Co 80/12/10 1p 07183 001

B101190224 Notifies that NRC has not completed licensing action on Westinghouse application for license to export two incore-neutron detectors to Switzerland
SHEA, J.R. Office of International Programs, Director 81/01/02 1p 07468 354

B101190227 Approves Elion Nuclear Co. Inc. application for license to import 21,600 Kg low enriched U-enriched to 2.95% from West Germany
MOORE, R.N. Assistant Director for Export/Import & International Safeguards 00/12/31 1p 07468 353

B101190550 Informs that NRC has not completed licensing action on export license application XBNM-1105 for export of 904 micrograms Cf-252 & 250 mg U-237 to Taiwan
SHEA, J.R. Office of International Programs, Director 81/01/02 1p 07471 295

B101190365 Application by Transnuclear, Inc. for Amend 2 to export license. Cerin Lab notified that Intl Customs Svcs Inc. should be listed as licensee. Original export license & Amend 1 will be returned for NRC handling
MATSON, V. Transnuclear, Inc. 73-067/5/01 NW 80/12/15 07474 279

B101190382 Advises that Transnuclear, Inc. has been requested to export license. Intl Customs Svcs is new licensee. Requests that licensing procedure be expedited
BOYAN, H.A. CERIN, Trepp, Div., Switzerland 80/12/16 1p 07183 001

B101190557 Requests ack of receipt of B01218 table & Transnuclear export license & whether new license has been issued to Intl Customs Svcs
BOYAN, H.A. CERIN, Trepp, Div., Switzerland 80/12/17 1p 07183 001

B101190751 Forwards Mitsubishi Intl Co B01219 request for amend export license application changing intermediate consignee. Govt. of Japan must be notified so that ltr of assurance reflects change W/O encl
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 81/01/07 1p 07476 122

B101190755 Ltr of assurance re Transnuclear, Inc. B01201 Application 64 034 14 U-235, contained in 1,911 kg U, to the Netherlands
PARCHEL, J. European Communities, Commission of 80/12/23 07476 123

B101190756 Requests amend to license, changing intermediate consignee to HEIMANN, O. Reactor Experiments, Inc 81/01/06 1p 07183 001

B101200005 Provides info re status of reactor components for Malaysia pending approval of license application. Reactor plant & mechanical & electronic components fabricated & in storage at OA Co
MCWHY, W.B. General Atomic Co (subs. of Gulf Oil Co.) 80/12/10 1p 07487 020

B101200006 Provides status of reactor components awaiting export Morocco under pending license. All mechanical & electronic components purchased & prepared for shipping
MCWHY, W.B. General Atomic Co (subs. of Gulf Oil Co.) 80/12/10 1p 07487 014

B101200096 Forwards application for export license
GUMPER, D.A. Nuclear Metals, Inc 81/01/02 1p 07477 358

--B101200435 Application by Nuclear Metals, Inc. for license to deplete U-rare shield component to Canada
Nuclear Metals, Inc 1-201-7 80/12/24 1p 07477 001

B101200436 Executive Branch position re Monsanto Research Corp application for license to export 1 mg Cf-252 contained in neutron source to Bhabha Atomic Research Ctr, India
NOBENZO, L.V. State Dept. of, Bureau of Oceans & International Scientific Affairs 81/01/05 1p 07487 112

B101200453 License for Reuter-Stokes Inc. to export 29 incore detectors for flux mapping to Sweden
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards U-8524 81/01/09 1p 07487 116

B101200460 Mod 1 to add Daint Seivoshia Company, Ltd. as an intermediate consignee to License XBNM-1715
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 81/01/07 1p 07487 118

B101200540 Requests Executive Branch position re Transnuclear application for license to export SHM to Switzerland for use in Gosseligen-Deoniken Reactor as multiple reloads
W/O encl
DEVINE, J.B. Office of International Programs, Director 81/01/02 1p 07487 126

B101210105 Executive Branch position re C-E application for 1 export ton light water moderated & cooled pressurized water NSS w/design power level of 900 Mw to Taiwan. License should be issued
NOBENZO, L.V. State Dept. of, Bureau of Oceans & International Scientific Affairs 00/12/12 13pp 07487 337

B101210583 License for Isotope Products Labs to export 10 uCi of ²²⁶Ra to Austria
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards W/O 0369 81/01/12 2pp 07488 012

Assistant Director for Export/Import & International
 12-17-79 10: 07485 112

* The following transcript of 771019 open Affirmation Session
was sent by teletype to the Order on Westinghouse export to
the East Coast of U.S.
* Transmitters: 771019 4x; 07503 259.

The following is the basic information re GE application for license to use the GE light water moderated & cooled BWR steam turbine used to power the reactor. The license should be issued only to the owner of the reactor.

NOTE: Note Dept. of Bureau of Oceans & Internatl. Environ.
Telephone: 212-12 81pp 07309.001

Enclosed are two copies of B01106 memo requesting NRC comments on concise
summary of status issues re nuclear power plant export to
India. Re final comments at this time.
Director of International Programs, Director. 80/11/23.

... of Assessment of findings re proposed report of source mat) by
the Director, Office of International Programs, Director. B1/01/06.

14-00000 License for Ljubljana Elektrarna Krsko to import 126,000
kg normal U from Canada
14-00000 Assistant Director for Export/Import & International
14-00000 R1 01000 Ip 0700B 001

10/14/78 License for Westinghouse to export one compensated
 information re: General Electric WL-8105 to Indonesia.
 Classification Assistant Director for Export/Import & International
 Ref: 105 GPO/CS 1p 07547.039.

15-1210187 Informing that there are no materially changed circumstances
 exhibited in application since issuance of License
 1509-1710
 MOORE is in Office of International Programs, Director. 80/12/31
 1p 0134 010

0011-10705 License for Transnuclear, Inc. to export 2.065.5 kg U-235,
 contained in 70.000 kg U. to West Germany
 REVISED Assistant Director for Export/Import & International
 Safeguards 81/01/07 App 07546:011

44-38861-10000 I found that there are no met changed circumstances
associated with application since issuance of License
AD-10-1719
WIRE R. Office of International Programs, Director. 60/12/31
16 0744 213

BIOHAZARD License for Transnuclear, Inc to export 2.965 kg U-235,
 contained in 50.500 kg U to West Germany
 CSJ/HF U B Assistant Director for Export/Import & International
 Safeguards BIO/107 2pp 07546-014.

10127241 License for Edw Int'l Co to export 595 kg U-235, contained
in 10 B25 kg U-235, to Sweden.
C.E. H. J. Assistant Director for Export/Import & International
Sales, 85/12/31 App 07309.001.

44-38861-104 Executive Branch position re Exxon Nuclear Co. inc
application for license to export 225 lg U-235 contained in
9 CPG lg U to West Germany Ltr of assurance encl. License
should be granted
NORWOOD L A
E: Ltr to: Affairs 81/01/09 3pp 07555:160.
Bureau of Oceans & Internatl. Environ. &

8101615 Requests that export licenses & applications be amended to name Japen Nuclear Fuel Conversion Co as intermediate consignee & intermediate end user Japen Nuclear Fuel Conversion Co 80123 for and
SAINT Mitsui & Co (U S A), Inc. (Subs. of Mitsui & Co., Ltd. I.
8101615 2pp C-959 259

#1 01060307 Contains B10004 telcon re status of pending exports of fuel bundles to Spain. Nucenor has 18 spare bundles in storage. GE has 95 bundles in storage. Nucenor plans to change to 18-month refueling cycle. B10004 B B General Electric Co B04 B1000. B1/01/13. 1p.

U.S. 01290102 Requester wants to license, increasing matl to be exported to
20 552 of U-235
MATERNAL Transuclear, Inc 80-173/01. 81/01/14. ip. 07575:189.

8101290457 Executive Branch position re Univ of CA application
license to export over 10 yrs, no more than 100 mCi tritium
per yr to all countries combined. License should be granted.
NOSENZ, L. V. State, Dept. of Bureau of Oceanic & Internatl. Envi
Scientific Affairs. 81/01/14. 1p. 07570:342.

8101290460 Requests Executive Branch position re Aldrich Chemical
Inc application for license to export 10 kg heavy water to
United Kingdom.
DEVINE, J. B. Assistant Director for Export/Import & International
Safeguards. 81/01/16. 1p. 07575:127.

8101290470 Executive Branch position re Transnuclear, Inc applicant
for license to export 94.24 kg U-235, contained in 101 kg U,
to Canada. Ltr of assurance encl. License should be granted.
NOSSENZO, L. V. State, Dept. of, Bureau of Oceans & Internat. Envir
Scientific Affairs. 81/01/14. 14pp. 07571:023.

8101290477 Executive Branch position re Transnuclear, Inc. application for license to export 4,473.0 kg U-235, contained in 131,600 kg U to West Germany. Ltr of assurance encl. License should be granted.

NOSENZO, L. V. State, Dept. of, Bureau of Oceanic & Internatl. Enviro Scientific Affairs. 81/01/09. 3pp. 07575: 144.

8101270650 License for Westinghouse to Export 12 proportional coun
Model BF3 to West Germany.
DEVINE, J. D. Assistant Director for Export/Import & International
Safeguards. ZE-10349. 81/01/16 Ip. 07566; 130.

8101290653 Executive Branch position re Westinghouse application to
license to export two primary neutron sources containing
470 micrograms Cf-252 to South Korea. License should be
granted.
NOSENZ, L. V. State, Dept. of, Bureau of Oceans & Internatl. Environ.
Scientific Affairs. 81/01/09. 1p. 07971:328.

8101290801 Forwards application for export license for minor nuclear
export. Ltr of assurance required, W/o encl.
DEVINE, J. B. Assistant Director for Export/Import & International
Safeguards. 81/01/23. Ip. 07868:119.

8101290806 Application by Nissho-Iwai American Corp for amend to ext
validity of License XGNM-1331 for 18 months.
YAMANA, K. Nissho-Iwai American Corp. MACPJ 2469KY. 81/01/06. 1p
07568: 120.

810129GB09 Application by United Kingdom Treasury & Supply Delegation
for license to export 15 mg U-233, in three 233 spike assay &
isotopic solution std ampoules, to United Kingdom.
THOMPSON, S.L. United Kingdom. QT 7774. 81/01/05. 1p. 07548:182

8101290812 Application by Westinghouse for license to export three
proportional counters, Model NL23095, to Italy.
FOCHAL, W. F., BCNNAUTZ, C. Westinghouse Electric Corp. ZE40066.
81/01/08, 1p. D7568; 23.

9101270814 License for United Kingdom Treasury & Supply Delegation to
export 15 mg U-233 in 30 g nitric acid solution to United
Kingdom.
DEVINE, J. B. Assistant Director for Export/Import & International
B safeguards. 81/01/27. 1pp. 07568:226.

8101270818 Amend 1 to license for Nuclear Metals, Inc., extending
expiration date from 810301 to 830301.
DEVINER, J. B. Assistant Director for Export/Import & International
Safeguards, 81/01/26. 07568; 225.

8101290821 Amend 1 to license for Westinghouse, extending expiration
date from 801231 to 811231.
DEVINE, J. B. Assistant Director for Export/Import & International
Safeguards. 81/01/23. 1p. 07968:224.

8101300120 Forwards IE Insp Rept 110-0325/80-01 on 801019-20. No
noncompliance noted.
MARTIN, W. Q. Region I, Philadelphia, Safeguards Branch. 80/11/14.
lp. 07583:092.

--B301300126 IE Insp Rept #10-0325/80-01 on 801019-20. No noncompliance noted. Major areas inspected: in-transit surveillance of BSNM shipment by road. Details withheld (ref 10CFR2.740).
DEVLIN, J. Region 1, Philadelphia, Safeguards Branch. SMITH, G., CHRISTOFFER, G. Region 1, Philadelphia, Office of the Director.
89/11/14. Ip. 07583:093.

8101308447 Requests Exxon Nuclear Co, Inc export license application be
withdrawn from records per encl 810113 ltr. w/o encl.
DEVINE, J. B. Assistant Director for Export/Import & International
Safeguards. 81/01/23. Ir. 07987:049.

0101300457 Requests Executive Branch position to 1x instruments. inc
application for license amend to export addl 100.000 Ci
tridium as gas contained in glass-sealed light sources
DEVINE, J B Assistant Director for Export/Import & International
Safeguards 01/01/23 1p 07587 050

0101300464 Amend 1 to license for Westinghouse, extending expiration
date from 010310 to 010715
DEVINE, J B Assistant Director for Export/Import & International
Safeguards 01/01/23 1pp 07583 300

0101300469 License for Reuter-Stokes, Inc to export one ion chamber.
Reuter-Stokes Model RS-C3-2510-114, to United Kingdom
DEVINE, J B Assistant Director for Export/Import & International
Safeguards 01/01/19 1pp 07587 053

0101300490 Application by Westinghouse for license to export one
WL23914 compensated ion chamber at no charge to France
SCHNAUF, C E. Westinghouse Electric Corp IE-20293-3A 01/01/16
1pp 07583 317

0101300496 License for Monsanto Research Corp to export 1 mg Cf-252 as
neutron source (Model 2765), to India
DEVINE, J B Assistant Director for Export/Import & International
Safeguards 191-9AD (1) 01/01/21 2pp

0101300527 License for Eberline Instrument Corp to export 0.22
micrograms Pu-237 to United Kingdom
DEVINE, J B Assistant Director for Export/Import & International
Safeguards SO 7687 01/01/21 2pp 07183 001

0101300532 License for Westinghouse to export 470 micrograms Cf-252 to
South Korea
DEVINE, J B Assistant Director for Export/Import & International
Safeguards ILS-011 01/01/23 1pp 07583 320

0101300534 Amend 2 to license for Hissco (was American Corp.) extending
expiration date from 010201 to 020901
DEVINE, J B Assistant Director for Export/Import & International
Safeguards NIAC-7B-C01 01/01/19 1p 07583 321

0101300539 License for Nuclear Metals, Inc to export 908 kg depleted U
to Canada
DEVINE, J B Assistant Director for Export/Import & International
Safeguards I-201-7 01/01/23 2pp 07587 046

0101300616 Amend 1 to for Mitsui & Co. Inc license increasing quantity
of export rail from 101.853 lb to 127.316 lb, increasing
value of export items & adding Kyushu Electric Power Co. Inc
as ultimate consignee
DEVINE, J B Assistant Director for Export/Import & International
Safeguards 01/01/23 1p 07587 048

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket/subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. Those categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ABBOTT, E	0101202779*	ACRS	HEARNE, J F	0101140871*	COMMISSION	ALKEP, F. J. T	0101260709	PR
ABBOTT, C. E.	01012020801*	ACRS	HEARNE, J F	0101140880	COMMISSION	ALLEN, T	0101260077	PR
ABEL, J. S.	0101094810*	50-254 G	HEARNE, J F	0101140897*	COMMISSION	ALLEN, S	0101230331	PR
ABEL, J. S.	0101090244*	50-254 G	HEARNE, J F	0101140912*	COMMISSION	ALLEN, R. B.	0101150410*	QA999
ABEL, J. S.	0101070251	RF600	HEARNE, J F	0101140929*	COMMISSION	ALLKBERG, R	0101290159*	FOIA
ABEL, J. S.	0101100301*	50-456 G	HEARNE, J F	0101140928*	COMMISSION	ALLKBERG, R	0101290131*	FOIA
ABEL, J. S.	0101260707*	50-454 G	HEARNE, J F	0101140933*	COMMISSION	ALLKBERG, R.	0101290261*	FOIA
ABEL, J. S.	0101260689*	50-299 G	HEARNE, J F	0101140935*	COMMISSION	ALLKBERG, R. M.	0101270393	PR
ABEL, J. S.	0101090360	50-10 P	HEARNE, J F	0101140945*	COMMISSION	ALLKBERG, A. G.	0101220243	50-28
ABEL, J. S.	0101090301	50-10 P	HEARNE, J F	0101140927*	50-220 P	ALLKBERG, O.	0101140583	PR
ABEL, J. S.	0101230117	50-373 S	HEARNE, J F	0101270877	COMMISSION	ALPERT, S.	0101210034	PR
ADKINSON, H.	0101170587	50-299 H	HEARNE, J F	0101060952	COMMISSION	ALPERT, R.	0101300830	PR
ADKINSON, H.	0101130595	50-299 H	HEARNE, J F	0101060953	50-320 P	ALPERT, R. M.	0101290499	PR
ADKINSON, S.	0101230193	PR	HEARNE, J F	0101080277	50-320 U	ALPERT, S. B.	0101130233*	50-13
ADKINSON, S.	0101230189	REG	HEARNE, J F	0101140666	COMMISSION	AND, E.	0101290677	PR
ADKINSON, S.	0101270222	50-537 A	HEARNE, J F	0101140876	COMMISSION	ANDERSON, W. A.	0101120164*	COMMISSION
ADKINSON, S.	0101230676	REG	HEARNE, J F	0101140881*	COMMISSION	ANDERSON, W. A.	0101290234*	FOIA
ADKINSON, S.	0101230559	50-537 A	HEARNE, J F	0101140894*	COMMISSION	ANDERSON, P. A.	0101100163*	50-28
ADKINSON, S.	0101220076	REG	HEARNE, J F	0101140895*	COMMISSION	ANDERSON, J. J.	0101200291*	50-20
ADKINSON, S.	0101270545	50-537 A	HEARNE, J F	0101140899*	COMMISSION	ANDERSON, S. L.	0101270526*	50-34
ADKINSON, S.	0101270069	50-537 A	HEARNE, J F	0101140904*	COMMISSION	ANDERSON, O. O.	0101150460*	QA999
ADKINSON, S.	0101270071	REG	HEARNE, J F	0101140904*	COMMISSION	ANDERSON, O. O.	0101150429*	QA999
ADKINSON, S.	0101210544	50-537 A	HEARNE, J F	0101140818	70-143	ANDERSON, T. M.	0101220283	PR
ADKINSON, S.	0101090929	ACRS	HEARNE, J F	0101140832	70-143	ANDERSON, E. I.	0101140592	PR
ADKINSON, S.	0101100129	40-8584	HEARNE, J F	0101140831*	50-466 U	ANDERSON, J. M.	0101260420	TOPRE
ADKINSON, S.	0101220620	REG	HEARNE, J F	0101080331*	COMMISSION	ANDERSON, P. B.	0101140813*	COMMISSION
ADKINSON, S.	0101140607	PR	HEARNE, J F	0101080336*	COMMISSION	ANDERSON, T. M.	0101140569*	50-28
ADKINSON, S.	0101150140	PR	HEARNE, J F	0101080360*	COMMISSION	ANDERSON, T. M.	0101220426	TOPRE
ADKINSON, S.	0101070102	50-387 G	HEARNE, J F	0101080362*	50-466 U	ANDERSON, C. J.	0101200197	50-32
ADKINSON, S.	0101130031	50-289 G	HEARNE, J F	0101140774	COMMISSION	ANDERSON, R. L.	0101290817	TOPRE
ADKINSON, S.	0101130031	50-289 G	HEARNE, J F	0101140779*	COMMISSION	ANDERSON, T. M.	0101130584	TOPRE
ADKINSON, S.	0101120506	50-289 G	HEARNE, J F	0101140786*	COMMISSION	ANDERSON, T. M.	0101190730	TOPRE
ADKINSON, S.	0101270691	PR	HEARNE, J F	0101140790*	COMMISSION	ANDERSON, T. M.	0101210372	TOPRE
ADKINSON, S.	0101060736*	FOIA	HEARNE, J F	0101140799*	COMMISSION	ANDERSON, T. M.	0101210401*	TOPRE
ADKINSON, S.	0101120444	50-329 G	HEARNE, J F	0101140802*	COMMISSION	ANDERSON, T. M.	0101210483	REVIEW
ADKINSON, S.	0101220530	PR	HEARNE, J F	0101140705	50-289 H	ANDERSON, T. M.	0101260516	TOPRE
ADKINSON, S.	0101150134*	FOIA	HEARNE, J F	0101130620	COMMISSION	ANDERSON, T. M.	0101230211	TOPRE
ADKINSON, S.	0101150127*	FOIA	HEARNE, J F	0101120622*	COMMISSION	ANDERSON, T. M.	0101210377*	TOPRE
ADKINSON, S.	0101200421	PR	HEARNE, J F	0101130632*	COMMISSION	ANDERSON, T. M.	0101090718	RECORD
ADKINSON, S.	0101150400*	QA999	HEARNE, J F	0101130634*	COMMISSION	ANDERSON, N. J.	0101070311	40-44
ADKINSON, S.	0101060270	50-320 P	HEARNE, J F	0101130637*	COMMISSION	ANDERSON, O.	0101140614	PR
ADKINSON, S.	0101080304*	50-320 U	HEARNE, J F	0101130640*	COMMISSION	ANDERSON, A. F.	0101080403*	50-27
ADKINSON, S.	01012110047	COMMISSION	HEARNE, J F	0101130643*	COMMISSION	ANDERSON, R. L.	0101050059	50-33
ADKINSON, S.	01012110036	COMMISSION	HEARNE, J F	0101130646*	COMMISSION	ARATA, N.	0101260649	PR
ADKINSON, S.	0101060266	COMMISSION	HEARNE, J F	0101300784	COMMISSION	ARAT, N. J.	0101150573*	50-31
ADKINSON, S.	0101060432	COMMISSION	HEARNE, J F	0101280398	50-320 P	ARCIERI, W. C.	0101060457*	50-26
ADKINSON, S.	0101060805	COMMISSION	HEARNE, J F	01012110279	PR	ARCIERI, W. C.	0101060498*	50-32
ADKINSON, S.	0101070017*	50-395 G	HEARNE, J F	0101130516*	50-295 S	ARCIERI, W. C.	0101219019*	50-32
ADKINSON, S.	0101140716	COMMISSION	HEARNE, J F	0101190339	PR	AREAL, A.	0101300759*	50-36
ADKINSON, S.	0101140729*	COMMISSION	HEARNE, J F	0101070362	50-206 P	AREAL, T. D. O. A.	0101210322	RECORD
ADKINSON, S.	0101000241	COMMISSION	HEARNE, J F	0101280405	50-247 H	ARNOLD, D. L.	0101190394	PR
ADKINSON, S.	0101140852	COMMISSION	HEARNE, J F	0101070347	ACRS	ARNOLD, R. C.	0101050111*	50-28
ADKINSON, S.	0101140855*	COMMISSION	HEARNE, J F	0101220572	PR	ARNOLD, R. C.	0101290593	50-28
ADKINSON, S.	0101140859*	COMMISSION	HEARNE, J F	0101210520*	50-277 R	ARNOLD, A. L.	0101300674	RES
ADKINSON, S.	0101140862*	COMMISSION	HEARNE, J F	0101280404	PR	ARNOLD, N.	0101210427	PR

[illegible]

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BIEHALD, B	0101270683	50-322 0	BORGENICK, B M	0101280522	50-516 0	BRIGHTMAN, N	0101166149	PR
BINGESS, O	0101280467	PR	BORGENICK, B M	0101280522	50-322 0	BRIGHT, R H	0101050260	50-3
BILL TO, B	0101160139	PR	BORER, P J	0101070357	50-290 0	BRIGHT, R H	0101070422	50-3
BILLYPS, B	0101200651	PR	BORER, P J	0101270653	50-290 0	BRIINCEL, P	0101230294	PR
BINSFELD, I	0101300051	PR	BORRES, R J	0101300151	50-3 0	BRIINAK, T	0101270230	50-3
BIRCHARD, O	0101270260	NASTE MGT	BORRES, R J	0101300740	50-286 0	BRIITON, C L	0101260292	RES
BIRK, R J	0101090622	50-483 0	BORRES, R J	0101230515	50-320 0	BROADHURST, R H	0101060490	50-3
BIRAEU, R A	0101150911	50-369 A	BERGMAN, E A	0101060281	50-358 0	BROADHURST, R H	0101170417	50-3
BISHOP, C J	0101120502	50-344 0	BORGHAAN, E A	0101210638	50-358 0	BROBBST, G E	0101130507	50-3
BISHOP, C J	0101090260	50-369 0	BORGHAAN, E A	0101150691	50-353 0	BROCATO, V J	0101270650	50-3
BISHOP, L L	0101160200	70-2623	BORGHAAN, E A	0101150500	50-358 0	BROCATO, V J	0101270651	50-3
BISHOP, L L	0101160200	70-2623	BORGHAAN, E A	0101120197	50-358 A	BROCK, C H	0101070402	50-3
BISHOP, C J	0101160745	50-488 0	BORGHAAN, E A	0101140272	50-358 A	BROCKEIT, T	0101090185	50-3
BISHOP, C J	0101200657	50-516 0	BORGHAAN, E A	0101230476	50-358 0	BROCKEIT, T H	0101200141	40
BISHOP, C J	0101270295	50-528 0	BORGHAAN, E A	0101270642	50-358 A	BRODIERICK, M E	0101300242	50-2
BISHOP, L L	0101230462	70-2623	BORGHAAN, E A	0101270272	50-358 1	BRODERICK, H E	0101120353	50-2
BISHOP, L L	0101230462	70-2623	BORGHAAN, E A	0101190304	PR	BRODSKY, R L	0101120004	50-3
BISHOP, C J	0101230113	70-2623	BORIS, W R	0101150506	50-255 1	BRODY, R	0101160710	PR
BISHOP, C J	0101230647	50-272 0	BORT, S	0101210552	PR	BROGAN, R O	0101290771	50-2
BISHOP, C J	0101260494	50-466 0	BOSNAK, R J	0101150463	ORG	BROGAN, R O	0101290771	50-2
BISHOP, C J	0101270064	50-480 0	BOSTWICK, H E	0101290648	RES	BROHBERG, D	0101150120	CONTR
BISHOP, C J	0101280139	50-480 0	BOTLEY, J J	0101060551	50-209 H	BROENDEL, C	0101160509	PR
BISSETT, P	0101300146	70-135	BOUTER, H	0101220134	PR	BROCKES, E H	0101100026	50-2
BLACK, B O	0101070170	PR	BOTHWICK, J	0101160231	50-483 0	BROCKWELL, R	0101200214	50-2
BLACK, B O	0101070186	PR	BOTHWICK, J L	0101190437	PR	BROCKWELL, R	0101100361	50-2
BLACK, B O	0101070178	PR	BOUCHEY, O D	0101080115	HE003	BROCKWELL, R	0101080392	CCMI
BLACK, B O	0101070186	PR	BOUCHEY, O D	0101140126	HE008	BROCKWELL, R	0101070084	50-3
BLACK, E A	0101190103	70-124	BOUCHEY, O D	0101070020	50-397 0	BROCKWELL, R	0101150231	0A999
BLACKETT, B F	0101300047	PR	BOUCHEY, O D	0101190347	50-397 A	BROCKWELL, R	0101140510	50-2
BLACK, R L	0101090600	50-466 0	BOUCHEY, O D	0101190376	50-397 A	BROCKWELL, R	0101080376	71-400
BLACK, R L	0101280160	50-466 0	BOUCHEY, O D	0101210561	50-397 A	BROCKWELL, R	0101230655	PR
BLADEL, C	0101190697	PR	BOUCHEY, O D	0101270743	50-395 0	BROCKWELL, R	0101230655	TCPRE
BLAKE, J	0101090735	50-438 0	BOUCHEY, O D	0101270669	50-397 A	BROCKWELL, R	0101050311	50-10
BLAKELY, H S	0101170126	PR	BOUCHEY, O D	0101280599	50-399 H	BROCKWELL, R	0101230238	50-13
BLAKE, E L	0101170042	50-289 0	BOURNIGHT, J A	0101280599	50-399 H	BROCKWELL, R	0101290655	14E
BLAKE, E L	0101130042	50-289 0	BOURLAND, H J	0101300111	FR	BROCKWELL, R	0101090079	50-16
BLAKE, E L	0101270550	50-289 T	BOURNIA, A	0101100063	50-373 A	BROCKWELL, R	0101090082	50-3
BLISS, O	0101260565	PR	BOWERS, E B	0101140077	50-275 0	BROCKWELL, R	0101150542	50-24
BLONDELL, A B	0101280214	50-289 H	BOWERS, E B	0101160294	50-142 0	BROCKWELL, R	0101160591	50-21
BOOSEOM, J H	0101001144	40-8452	BOWERS, E B	0101230622	50-250 0	BROCKWELL, R	0101070890	50-27
BLOUGH, A R	0101100244	50-277 0	BOWERS, E B	0101260367	50-440 0	BROCKWELL, R	0101150553	50-31
BLOUGH, A R	0101220169	50-277 0	BOWERS, E B	0101200059	50-322 0	BROCKWELL, R	0101160123	50-30
BLOUGH, A R	0101150671	50-277 0	BOWERS, E B	0101200062	50-322 0	BROCKWELL, R	0101220442	50-22
BLUM, B	0101090405	50-369 0	BOWERS, E B	0101280131	50-275 0	BROCKWELL, R	0101100183	50-27
BLUMBERG, H	0101190558	50-317 0	BOWERS, E B	0101200235	50-280 P	BROCKWELL, R	0101100216	50-27
BLUMBERG, H	0101160115	50-309 0	BOWMAN, A L	0101210278	NUREQ	BROCKWELL, R	0101150580	50-24
BLUMBERG, H J	0101160187	50-271 0	BOYD, D C	0101070181	50-255 0	BROCKWELL, R	0101160072	50-27
BLYENTHAL, J	0101210530	PR	BOYD, D C	0101160382	50-151 0	BROCKWELL, R	0101220153	50-27
BOCKEL, R I	0101140527	PR	BOYD, D C	0101210643	50-209 0	BROCKWELL, R	0101150680	50-27
BOOTKE, P J	0101130249	50-255 R	BOYO, O C	0101270432	50-295 0	BROCKWELL, R	0101150559	50-36
BOETIGER, C O	0101060766	FOIA	BOYER, V S	0101280544	PR	BROCKWELL, R	0101300057	50-33
BOODEN, O	0101100015	40-1162	BRACH, A	0101210164	PR	BROCKWELL, R	0101100066	50-28
BOODEN, O	0101100021	40-1162	BRACKEN, K W	0101190398	71-6144	BROCKWELL, R	0101200720	50-24
BOODEN, O	0101270316	40-1162	BRADBURY, R B	0101090692	RE000	BROCKWELL, R	0101090347	50-27
BOODEN, O	0101270957	40-1162	BRADFGRO, P A	0101090157	50-237 0	BROCKWELL, R	0101150566	50-31
BOGGM, R	0101190659	PR	BRADFORD, P A	0101120135	50-142 P	BROCKWELL, R	0101300026	50-30
BOHIA, R J	0101050395	50-367 R	BRADGRO, M H	0101220427	50-349 0	BROCKWELL, R	0101090853	50-38
BOHIA, R J	0101090036	50-367 R	BRADFORD, P A	0101230420	10CFR	BROCKWELL, R	0101100704	50-27
BOHIA, R J	0101130459	50-367 R	BRADFORD, L P	0101160251	50-265 0	BROCKWELL, R	0101300014	50-22
BOHIA, R J	0101210320	50-367 R	BRADLEY, J P	0101220374	50-10 P	BROCKWELL, R	0101060030	50-27
BOHIA, R J	0101230652	50-367 R	BRADLEY, E J	0101120299	50-277 P	BROCKWELL, R	0101100534	50-32
BOHIA, R J	0101220964	PR	BRADLEY, E J	0101120304	50-277 P	BROCKWELL, R	0101220540	50-27
BOHIA, R J	0101200020	PR	BRAMLETT, L S	0101050537	50-313 S	BROCKWELL, R	0101150549	50-31
BOHIA, R J	0101290789	50-483 H	BRAMLETT, L S	0101120389	50-368 S	BROCKWELL, R	0101150641	50-30
BOHIA, R J	0101190554	14E	BRAMLETT, L S	0101130484	50-368 S	BROCKWELL, R	0101220433	50-22
BOHIA, R J	0101100608	NUREQ	BRAMLETT, L S	0101130546	50-313 S	BROCKWELL, R	0101160575	50-21
BOHIA, R J	0101270974	RES	BRAMLETT, L S	0101130452	50-368 S	BROCKWELL, R	0101150562	50-31
BOHIA, R J	0101290279	RES	BRAMLETT, L S	0101210494	50-313 R	BROCKWELL, R	0101150536	50-24
BOHIA, R J	0101290439	RES	BRANCH, M H	0101210643	50-409 0	BROCKWELL, R	0101220141	50-27
BOHIA, R J	0101290542	70-734	BRANDSTEN, L	0101280364	PR	BROCKWELL, R	0101150575	50-24
BOHIA, R J	0101070301	50-187 0	BRAND, W E	0101270349	50-395 H	BROCKWELL, R	0101220126	50-27
BOHIA, R J	0101290537	70-734	BRAND, W E	0101270349	50-395 H	BROCKWELL, R	0101160051	50-27
BOHIA, R J	0101210626	50-361 0	BRANDSON, Y	0101270793	PR	BROCKWELL, R	0101150867	50-27
BOHIA, R J	0101210629	50-361 0	BRAYES, R H	0101090626	50-213 0	BROCKWELL, R	0101090241	50-27
BOHIA, R J	0101290569	50-142 0	BRAZEAU, W	0101210447	PR	BROCKWELL, R	0101090224	50-31
BOHIA, R J	0101290574	50-142 0	BRECHER, H	0101140221	50-208 J	BROCKWELL, R	0101270907	50-33
BOHIA, R J	0101290561	50-224 0	BREITUNG, W M	0101270838	NUREQ	BROCKWELL, R	0101280426	50-33
BOHIA, R J	0101290565	50-224 0	BRENNAN, T	0101150844	PR	BRYAN, S E	0101090163	FOIA
BOHIA, R J	0101160382	50-131 0	BRENNER, L	0101280086	70-2623	BRYAN, S E	0101090176	FOIA
BOHIA, R J	0101070279	70-2249	BRENNER, L	0101270375	70-2623	BRYAN, J C	0101160734	50-36
BORDENICK, B M	0101070468	50-322 0	BRECKLEY, R H	0101150460	0A999	BRYAN, J C	0101290369	50-38
BORDENICK, B M	01012100519	50-490 0	BRECKLEY, R H	0101150429	0A999	BRYAN, L L	0101270555	50-43
BORDENICK, B M	0101060002	50-322 0	BRIEDWATER, P	0101220570	PR	BRYAN, R H	0101270802	NUREQ
BORDENICK, B M	0101060001	50-322 0	BRIGHT, R M	0101150024	50-302 0	BRYAN, J K	0101140549	50-48
BORDENICK, B M	0101070169	50-314 0	BRIGHT, K	0101140590	PR	BRYAN, J K	0101270853	50-48

AUTHOR				ACCESSION NUMBER				SUBJECT CATEGORY				AUTHOR				ACCESSION NUMBER				SUBJECT CATEGORY			
BRYAN, J. A.				8101140335				50-483				CANTIER, H.				8101260887				50-212			
BRYAN, J. Q.				8101190542				PR				CANTRELL, F. S.				8101100672				50-516			
BUCHHEIT, C.				8101260682				PR				CAPITON, D. L.				8101167604				50-213			
BUCHANAN, M. E.				8101120292				RES				CAPITON, D. L.				8101360927				50-245			
BUCHHEIT, Z. R. H.				7912310182				REFUG				CAPITON, D.				8101280454				50-225			
BUCHHEIT, Z. R. H.				8101140155				REFUG				CARBROUGH, E. H.				8101260451				50-255			
BUCHHEIT, Z. R. H.				8101050170				TOPREP				CARSON, E. H. L.				8101300145				RES			
BUCHHEIT, Z. R. H.				8101210515				TOPREP				CARLEY, M. H.				8101260236				50-271			
BUCHHEIT, Z. R. H.				8101210371				TOPREP				CARLSON, A. M.				8101140537				REFUG			
BUCHHEIT, Z. R. H.				8101160342				TOPREP				CARLSON, R. T.				8101300050				50-333			
BUCHHEIT, Z. R. H.				8101270598				TOPREP				LARI, STREIN, R. E.				8101100510				COMMUNIS			
BUCHHEIT, Z. R. H.				8101300841				50-413				CARLSON, R. T.				8101300134				50-317			
BUCHHEIT, Z. R. H.				8101160020				50-361				CARLSON, R. T.				8101057491				50-354			
BUCHHEIT, Z. R. H.				8101270593				FOIA				CARLSON, R. T.				8101160045				50-482			
BUCHHEIT, Z. R. H.				8101160490				PR				CARLSON, R. T.				8101100701				50-387			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8101270598				REFUG				CARLSON, R. T.				8101300060				50-333			
BUCHHEIT, Z. R. H.				8																			

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHILK, S J	B011260571	50-309 G	CLARK, R A	B011230114*	50-309 C	COLMBO, R N	B011200288*	50-
CHILK, S J	B011260571	50-367 O	CLARK, R A	B011300529	50-285 P	COLMBO, R W	B011200302*	50-
CHILENO, V T	B011210418*	50-250 R	CLARK, R A	B011300614*	50-285 P	COLMBO, R W	B011200302*	50-
CHILSON, V T.	B011210418*	50-250 H	CLARK, R A	B011300624*	50-285 P	CONLEY, K O	B011100631	HEC
CHIN, S	B011140130	71-5796	CLAYTON, F L	B011290686	50-348 O	CONROY, V H	B011210144	50-
CHIRAMAL, M	B011100184	50-346 P	CLAYTON, F L	B011100319*	50-348 O	CORRALIN, J C	B011000951	LUR
CHRISTOS, J N	B011160476*	50-206 P	CLAYTON, C	B011163262	PR	COVINO, T E	B011100343*	50-
CHRISTOS, J N	B011160473*	50-206 P	CLAYTON, F L	B011050321	50-348 P	COLOTTI, E	B011100334*	50-
CHODRON, L	B011160327	PR	CLAYTON, F L	B011146507	50-348 P	COLON, T E	B011120070*	50-
CIDWIN, N	B011260754	50-250 G	CLAYTON, F L	B011190101	50-364 P	COLON, T E	B01106089*	50-
CIOULES, H C	B011160156*	50-304 O	CLAYTON, F L	B011210402	50-348 P	CORLON, T E	B011160684*	50-
CIOULES, H C	B011290573*	50-282 Q	CLAYTON, F L	B011290363	50-348 Q	CORNER, L	B011130029	F01
CIOULES, H C	B011210654*	50-346 Q	CLAYTON, F L	B011070370	50-364 A	CONNELL, C	B011200290*	50-
CHRISTA-MARIA	B003270417*	50-155 O	CLAYTON, F L	B011130602	50-360 S	CONNOR, E L	B011190573	53-
CHRISTA-MARIA	B011090942*	50-155 O	CLAYTON, F L	B011220159	50-348 P	CONNER, C I	B011290778	50-
CHRISTENSEN, J	B011050197*	50-287 T	CLAYTON, F L	B011140554	50-348 Q	CONNER, T B	B011280362	50-
CHRISTOFFER, O	B011300126*	XPORTLIC	CLAYTON, F L	B011210411	50-364 P	CONRAD, U	B011230175	F01
CHRISTOFFER, O	B011080392*	50-234 Q	CLAYTON, F L	B011300980	50-248 S	CONROY, D U	B011270944	40-
CHRISTENSEN, J	B011150237	PR	CLAYTON, F L	B011210426	50-348 S	CONSTABLE, C L	B011070252*	50-
CHRISTENSEN, U	B011230310	PR	CLAYTON, F L	B011210518	50-348 R	CONWAY, W F	B011160640*	50-
CHRISTIAN, W	B011290449*	50-331 O	CLAYTON, F L	B011210491	50-364 H	CONWAY, W F	B011160627*	50-
CHRISTENSEN, J	B011090001	50-289 T	CLAYTON, F L	B011260360	50-340 P	CONWAY, W F	B011160665*	50-
CHRISTOFFER, O	B011060270*	50-293 O	CLAYTON, F L	B011290534	50-248 O	CONWAY, W F	B011140913	50-
CHRISTOFFER, O	B011130206*	50-254 Q	CLAYTON, F L	B011270728	50-348 O	CONWAY, W F	B011140707	50-
CHRISTA-MARIA	B011070376	50-155 H	CLAYTON, F L	B011220344	50-364 P	CONWAY, W F	B011060789	50-
CHRISTY, N	B011110066	50-182 O	CLAYTON, F L	B011230425	50-140 P	CONWAY, W F	B011060416	50-
CHRISTMAN, J M	B011130284	50-280 O	CLAYTON, F L	B011260350	50-348 A	CONWAY, W F	B011210530	50-
CHRISTIAN, R W	B0112001169	50-289 H	CLAYTON, F L	B011260365	50-264 V	COLE, J W	B011050600*	50-
CHRISTENSEN, E	B011270323	50-154 Q	CLAYTON, F L	B011270676	50-340 P	COOK, R J	B011070236*	50-
CHJ, C K	B011050187*	TDPREP	CLAYTON, F L	B011270750	50-348 P	COOK, J W	B011120250*	50-
CHLMA, M	B011190927	PR	CLAYTON, F L	B011200164	50-364 P	COCA, R J	B011210533*	50-
CHUNO, J W	B011150550	50-317 Q	CLAYTON, F L	B011270914	50-340 P	COCK, J W	B011050132	50-
CHUNO, J W	B011150550*	50-247 O	CLAYTON, F L	B011280080	50-340 S	COCK, J W	B0110907407	50-
CHUNO, J W	B011300019*	50-720 Q	CLEGG, H	B011300146	PR	COCA, J W	B011060272*	50-
CHILLIS, N	B011210629*	50-361 Q	CLEGG, L B	B011290703	NAMED	COCK, J W	B0112310225	50-
CHILLIS, M	B011290565*	50-224 H	CLEMENTS, P	B011220638*	70-371	COJA, J W	B011050365	50-
CINDIE, M A	B011290732	PR	CLEMENTS, P	B011160125*	70-33	COOK, J W	B011090513	50-
CIPOLLA, A J	B011170615	71-6273	CLEVELAND, C J	B011503817	50-255 P	COJA, J W	B011090594	50-
CIPICOLA, A J	B011100256	40-3392	CLEVELAND, C J	B011100590	50-344 P	COJA, J W	B011280591	50-
CISERNINO, H.	B011130189	PR	CLEVELAND, C J	B011090791	NAMED	COJK, J W	B011140637	50-
CLAPP, D W	B011150601	NUREG	COBB, L I	B012100090*	50-392 A	COJK, J W	B011190604	50-
CLARKE, L S	B011290449*	50-331 O	COBB, L I	B012100096*	50-360 A	COJK, J W	B011230981	50-
CLARKE, O A	B011260136	NUREG	CORREIA, S	B011290663	PR	COJA, J W	B011290500	50-
CLARK, D R	B003102920	50-320 C	CORREIA, S	B011160011	PR	COCK, H A	B011290692	NARE
CLARK, R A	B011070129	50-338 P	CORREIA, C L	B011090660*	50-366 S	COLLEY, K J	B011290542*	70-
CLARK, R A	B011070134*	50-330 P	CORREIA, C L	B013060666*	50-366 S	COONEY, M J	B011050265	50-
CLARK, R A	B011070113*	50-333 P	CORREIA, C L	B013060677*	50-366 S	COONEY, M J	B011090412	50-
CLARK, R A	B011090745	50-344 P	CORREIA, C L	B013060693*	50-321 S	COONEY, M J	B011070496	50-
CLARK, R A	B011090753*	50-344 P	CORREIA, C L	B013060693*	50-321 S	COONEY, M J	B011140519	50-
CLARK, R A	B011090760*	50-344 P	CORREIA, C L	B013060693*	50-366 S	COONEY, M J	B011210522	50-
CLARK, R A	B011090935	50-344 P	COHEN, I	B011300196*	70-135	COONEY, M J	B011220480	50-
CLARK, R A	B011090930*	50-344 P	COHEN, B R	B011170922	PR	COONEY, M J	B011260496*	50-
CLARK, R A	B011070939*	50-344 P	COHEN, A	B011200494	PR	COONEY, M J	B011260266	50-
CLARK, U	B011140141	State Prog	COHEN, S	B011060277*	CONTRACT	COONEY, M J	B011220488	50-
CLARK, T A	B011090941	50-317 P	COHEN, S	B011270727	CONTRACT	COONEY, M J	B011220477	50-
CLARK, R A	B011090943*	50-317 P	COHEN, D	B011160211	50-352 G	COONEY, M J	B011220483	50-
CLARK, R A	B011090947*	50-317 P	COHEN, B H	B011100307*	CONTRACT	COONEY, M J	B011230321	PR
CLARK, R A	B011100139	50-309 P	COHEN, H I	B011160707	PR	COONEY, M J	B011260544	50-
CLARK, R A	B011190377	50-250 F	COHEN, O B	B011140988	50-369 G	COONEY, M J	B011230174	50-
CLARK, R A	B011100490	50-335 P	COHEN, O B	B011140988	50-369 U	COONEY, M J	B011270550	50-
CLARK, R A	B011100510	50-266 P	COHEN, D B	B011260311	50-369 O	COONEY, M J	B011270597*	50-
CLARK, R A	B011100527*	50-266 P	COHEN, G O	B011300102	PR	COOPER, C	B011230321	PR
CLARK, R A	B011100543*	50-266 P	COCKROFT, A H	B011200095	50-259 O	COPELAND, R L	B011070495	REC2
CLARK, R A	B011120051	50-282 P	COLE, R F	B011130017*	50-454 G	COPELAND, J O	B011090355	50-
CLARK, R A	B011120056*	50-282 P	COLELLO, E	B011140651	PR	COPELAND, J O	B011090955	50-
CLARK, R A	B011120062*	50-282 P	COLEMAN, R	B011090998	CONTRACT	COPELAND, R L	B011070492	50-
CLARK, R A	B011140454	50-344 F	COLEMAN, R	B011060341*	CONTRACT	COPELAND, M	B011150842	PR
CLARK, R A	B011160610	50-309 F	COLEMAN, A C	B011280299	50-272 O	COPELAND, J S.	B011230577	71-
CLARK, R A	B011100484	50-335 F	COLEMAN, R	B011290096	CONTRACT	COPELAND, R L	B011090002	Stat
CLARK, R A	B011140458	50-309 P	COLEY, J L	B011220366*	50-366 O	COPELAND, J O	B011090955	50-
CLARK, R A	B011190277	50-266 F	COLLINS, J J	B011050137*	50-289 T	CONNELL, E K	B011070541	CGRM
CLARK, P R	B011050090*	50-289 T	COLL, N A	B011110686	50-250 O	CORRIMAN, L	B011190065	PR
CLARK, R A	B011140476	50-283 F	COLL, N A	B011140886	50-250 O	CORRIMAN, H	B011290570	PR
CLARK, D	B011060482*	50-265 S	COLL, N A	B011160261	50-387 C	CORRADI, H I.	B011290465	NURE
CLARK, R A	B011220176	50-262 F	COLL, N A	B011160261	50-387 O	CORREA, M A	B011210586	90-
CLARK, R A	B011190416	50-317 P	COLL, N A	B011260503	50-250 O	CORREA, C	B011220351	50-
CLARK, R A	B011190500	50-330 P	COLLINS, S J	B011108194*	50-271 O	CORREIA, D	B011270047	50-
CLARK, R A	B011190617*	50-338 P	COLLINS, R E	B011070233*	50-267 O	CORREA, M A	B011270735	50-
CLARK, R A	B011190621*	50-338 P	COLLINS, S	B011160097*	50-271 O	CORREA, M A	B011270728	90-
CLARK, R A	B011190623	50-335 P	COLLINS, F H	B011060321*	CONTRACT	CORREIA, O P	B011090902*	50-
CLARK, R A	B011190626*	50-335 P	COLLINS, J T	B011060105	50-320 R	CORREIA, O P	B011203144*	70-
CLARK, S	B011120349*	50-293 S	COLLINS, J T	B011090771	50-320 R	COSOROVE, J E	B011120505	50-
CLARK, R A	B011190579	50-338 P	COLMAN, L	B011190093	PR	COSTANTINO, C	B011260146	NURE
CLARK, R A	B011290802*	50-336 P	COLMBO, R W	B011130517*	50-312 S	COSTANTINO, C	B011260163	1URE
CLARK, R A	B011290807*	50-336 P	COLMBO, R W	B011150531*	50-312 R	COSTELLO, J R	B011190551*	0A92

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER
CRUTCHFIELD, D. J.	8101200397	50-220 R	CREWS, J. L.	8101600581	50-312 0	CRUTCHFIELD, D.	810120115
CRUTCHFIELD, D. P.	8101200525	PR	CREWS, J. L.	8101210595	50-312 0	CRUTCHFIELD, D.	8101070126
CRUTCHFIELD, M. I.	8101120007	50-466 0	CREWS, J. L.	8101210133	50-39 0	CRUTCHFIELD, D.	8101070152
CRUTCHFIELD, M. L.	8101120011	50-250 P	CREWS, J. L.	8101210110	50-397 0	CRUTCHFIELD, D.	8101070183
CRUTCHFIELD, B. P.	8101060910	50-530 Q	CRUTCHFIELD, E.	8101190016	PR	CRUTCHFIELD, D.	8101070577
CRUTCHFIELD, B. P.	8101160169	50-413 M	CRUTCHFIELD, D.	8101150355	50-287 M	CRUTCHFIELD, D.	8101100048
CRUTCHFIELD, B. P.	8101160141	50-413 M	CRUTCHFIELD, H. H.	8101300177	70-1100	CRUTCHFIELD, D.	8101150323
CRUTCHFIELD, B. P.	8101280041	27-39	CRUTCHFIELD, H. H.	8101090561	70-820	CRUTCHFIELD, D.	8101070174
CRUTCHFIELD, W. T.	8101250057	50-327 S	CRUTCHFIELD, L.	8101130067	50-219 P	CRUTCHFIELD, D.	8101070475
CRUTCHFIELD, W. T.	8101060477	50-327 S	CRUTCHFIELD, H. H.	8101280374	50-247 S	CRUTCHFIELD, D.	8101120323
CRUTCHFIELD, W. T.	8101070777	50-327 S	CRUTCHFIELD, E.	8101260111	PR	CRUTCHFIELD, D.	8101120402
CRUTCHFIELD, W. T.	8101130112	50-327 S	CROSSBY, P. J.	8101050219	50-219 S	CRUTCHFIELD, D.	8101120462
CRUTCHFIELD, W. T.	8101130463	50-327 S	CROSSBY, P. J.	8101050259	50-219 S	CRUTCHFIELD, D.	8101280441
CRUTCHFIELD, J. H.	8101220377	50-438 A	CROSSBY, P. J.	8101050511	50-219 S	CRUTCHFIELD, D.	8101260472
CRUTCHFIELD, H. H.	8101100050	50-423 S	CROSSBY, P. J.	8101150695	50-219 S	CRUTCHFIELD, D.	8101300240
CRUTCHFIELD, H. H.	8101120413	50-245 F	CROSSBY, P. J.	8101230556	50-219 S	CRUTCHFIELD, D.	8101070594
CRUTCHFIELD, H. H.	8101160587	50-213 Q	CROSSBY, P. J.	8101230564	50-219 S	CRUTCHFIELD, D.	8101070610
CRUTCHFIELD, H. H.	8101150540	50-245 Q	CROSSBY, H. A.	8101070261	50-382 Q	CRUTCHFIELD, D.	8101070630
CRUTCHFIELD, H. H.	8101160506	50-217 Q	CROSSBY, H. A.	8101000296	50-482 Q	CRUTCHFIELD, D.	8101120142
CRUTCHFIELD, H. H.	8101140718	50-326 Q	CROSSBY, H. A.	8101160178	50-445 Q	CRUTCHFIELD, D.	8101140047
CRUTCHFIELD, H. H.	8101150028	50-213 Q	CROSSBY, H. A.	8101100269	50-498 Q	CRUTCHFIELD, D.	8101140050
CRUTCHFIELD, H. H.	8101150028	50-213 Q	CROSSBY, H. A.	8101100363	50-445 Q	CRUTCHFIELD, D.	8101140055
CRUTCHFIELD, H. H.	8101100787	50-213 0	CROSSBY, H. A.	8101120096	50-382 Q	CRUTCHFIELD, D.	8101140059
CRUTCHFIELD, H. H.	8101220401	50-213 Q	CROSSBY, H. A.	8101100766	50-498 Q	CRUTCHFIELD, D.	8101140068
CRUTCHFIELD, H. H.	8101100787	50-213 Q	CROSSBY, H. A.	8101140556	50-498 Q	CRUTCHFIELD, D.	8101140070
CRUTCHFIELD, H. H.	8101220404	50-213 P	CROSSBY, H. A.	8101280530	50-482 Q	CRUTCHFIELD, D.	8101140072
CRUTCHFIELD, H. H.	8101050447	50-376 P	CROSSBY, H. A.	8101140500	50-382 Q	CRUTCHFIELD, D.	8101140077
CRUTCHFIELD, H. H.	8101050468	50-213 P	CROSSBY, H. A.	8101210075	50-458 Q	CRUTCHFIELD, D.	8101200637
CRUTCHFIELD, H. H.	8101090002	50-213 P	CROSSBY, H. A.	8101200508	50-302 D	CRUTCHFIELD, D.	8101210173
CRUTCHFIELD, H. H.	8101060310	50-213 P	CROSSBY, H. A.	8101210577	50-445 B	CRUTCHFIELD, D.	8101210174
CRUTCHFIELD, H. H.	8101050076	50-336 P	CROSSBY, J. L.	8101120331	50-327 P	CRUTCHFIELD, D.	8101210186
CRUTCHFIELD, H. H.	8101160363	50-245 F	CROSSBY, J. L.	8101220383	50-327 Q	CRUTCHFIELD, D.	8101210222
CRUTCHFIELD, H. H.	8101070012	50-213 P	CROSSBY, H. A.	8101260403	50-498 Q	CRUTCHFIELD, D.	8101210130
CRUTCHFIELD, H. H.	8101070012	50-213 P	CROSSBY, J. L.	8101270702	50-327 P	CRUTCHFIELD, D.	8101270150
CRUTCHFIELD, H. H.	8101130138	50-213 P	CROSSBY, J. L.	8101260416	50-327 P	CRUTCHFIELD, D.	8101300598
CRUTCHFIELD, H. H.	8101190031	PR	CROSSBY, J. L.	8101270647	50-327 P	CRUTCHFIELD, D.	8101200200
CRUTCHFIELD, H. H.	8101090004	50-213 F	CROSSBY, R. P.	8101300571	50-346 Q	CRUTCHFIELD, D.	8101210210
CRUTCHFIELD, H. H.	8101120037	50-213 V	CROSSBY, R. P.	8101080170	50-346 Q	CRUTCHFIELD, D.	8101210229
CRUTCHFIELD, H. H.	8101120025	50-213 P	CROSSBY, R. P.	8101050626	50-346 Q	CRUTCHFIELD, D.	8101070179
CRUTCHFIELD, H. H.	8101160348	50-213 P	CROSSBY, R. P.	8101070200	50-346 Q	CRUTCHFIELD, D.	8101270720
CRUTCHFIELD, H. H.	8101090004	50-213 F	CROSSBY, R. P.	8101060456	50-346 Q	CRUTCHFIELD, D.	8101230332
CRUTCHFIELD, H. H.	8101160248	50-213 P	CROSSBY, R. P.	8101050531	50-346 P	CRUTCHFIELD, D.	8101230337
CRUTCHFIELD, H. H.	8101120037	50-213 P	CROSSBY, R. P.	8101060589	50-346 P	CRUTCHFIELD, D.	8101230339
CRUTCHFIELD, H. H.	8101120037	50-213 P	CROSSBY, R. P.	8101060473	50-346 P	CRUTCHFIELD, D.	8101230341
CRUTCHFIELD, H. H.	8101200707	50-245 P	CROSSBY, R. P.	8101090023	50-346 P	CRUTCHFIELD, D.	8101230343
CRUTCHFIELD, H. H.	8101150624	50-336 P	CROSSBY, R. P.	8101200185	50-346 Q	CRUTCHFIELD, D.	8101190626
CRUTCHFIELD, H. H.	8101270712	50-213 F	CROSSBY, R. P.	8101220242	50-346 P	CRUTCHFIELD, D.	8101190644
CRUTCHFIELD, H. H.	8101270712	50-213 F	CROSSBY, R. P.	8101160461	50-346 P	CRUTCHFIELD, D.	8101190689
CRUTCHFIELD, H. H.	8101200293	50-336 P	CROSSBY, R. P.	8101260348	50-346 Q	CRUTCHFIELD, D.	8101190704
CRUTCHFIELD, H. H.	8101270670	50-245 P	CROSSBY, R. P.	8101280348	50-346 Q	CRUTCHFIELD, D.	8101190710
CRUTCHFIELD, H. H.	8101290553	50-213 S	CROSSBY, R. P.	8101300554	50-346 Q	CRUTCHFIELD, D.	8101190715
CRUTCHFIELD, H. H.	8101290265	50-245 P	CROSSBY, R. P.	8101190889	50-346 P	CRUTCHFIELD, D.	8101210149
CRUTCHFIELD, H. H.	8101290219	50-245 P	CROSSBY, R. P.	8101220575	50-346 P	CRUTCHFIELD, D.	8101210165
CRUTCHFIELD, H. H.	8101290180	50-245 P	CROSSBY, R. P.	8101220582	50-346 P	CRUTCHFIELD, D.	8101270134
CRUTCHFIELD, H. H.	8101150601	50-245 P	CROSSBY, R. P.	8101260497	50-346 P	CRUTCHFIELD, D.	8101270142
CRUTCHFIELD, H. H.	8101140931	70-2909	CROSSBY, R. P.	8101230405	50-346 P	CRUTCHFIELD, D.	8101270158
CRUTCHFIELD, H. H.	8101140931	70-2909	CROSSBY, R. P.	8101270676	50-346 P	CRUTCHFIELD, D.	8101230444
CRUTCHFIELD, H. H.	8101140244	50-277 Q	CROSSBY, R. P.	8101300603	50-346 P	CRUTCHFIELD, D.	8101230451
CRUTCHFIELD, H. H.	8101220167	50-277 Q	CROSSBY, R. P.	8101300481	50-346 P	CRUTCHFIELD, D.	8101230458
CRUTCHFIELD, H. H.	8101150691	50-277 Q	CROSSBY, R. P.	8101070178	PR	CRUTCHFIELD, D.	8101280477
CRUTCHFIELD, H. H.	8101190292	PR	CROSSBY, O. S.	8101070186	PR	CRUTCHFIELD, D.	8101230501
CRUTCHFIELD, H. H.	8101070306	50-187 Q	CROSSBY, O. S.	8101070178	PR	CRUTCHFIELD, D.	8101230503
CRUTCHFIELD, H. H.	8101290008	50-275 Q	CROSSBY, O. S.	8101070186	PR	CRUTCHFIELD, D.	8101230505
CRUTCHFIELD, H. H.	8101060014	50-275 Q	CROSSBY, W. T.	8101090311	70-1007	CRUTCHFIELD, D.	8101290595
CRUTCHFIELD, H. H.	8101120252	50-133 Q	CROSSBY, W. T.	8101120548	70-824	CRUTCHFIELD, D.	8101290329
CRUTCHFIELD, H. H.	8101130566	50-275 Q	CROSSBY, W. T.	8101210267	70-27	CRUTCHFIELD, D.	8101060035
CRUTCHFIELD, H. H.	8101070206	50-133 Q	CROSSBY, W. T.	8101140948	40-8027	CRUTCHFIELD, D.	8101280460
CRUTCHFIELD, H. H.	8101120547	50-133 Q	CROSSBY, W. T.	8101220197	70-1257	CRUTCHFIELD, D.	8101300508
CRUTCHFIELD, H. H.	8101050382	50-275 Q	CROSSBY, W. T.	8101290145	40-2061	CRUTCHFIELD, D.	8101300608
CRUTCHFIELD, H. H.	8101060018	50-275 Q	CROSSBY, L. A.	8101080028	PR	CRUTCHFIELD, D.	8101280414
CRUTCHFIELD, H. H.	8101030406	50-133 S	CRUTCHFIELD, H.	8101140683	PR	CRUTCHFIELD, D.	8101300077
CRUTCHFIELD, H. H.	8101300728	50-275 F	CRUTCHFIELD, C.	8101060097	RES	CRUTCHFIELD, D.	8101300082
CRUTCHFIELD, H. H.	8101220307	50-133 P	CRUTCHFIELD, D. R.	8101140113	50-250 Q	CRUTCHFIELD, D.	8101300089
CRUTCHFIELD, H. H.	8101210335	50-275 A	CRUTCHFIELD, S. A.	8101210069	PR	CRUTCHFIELD, D.	8101210237
CRUTCHFIELD, H. H.	8101270492	50-133 P	CRUTCHFIELD, C. J.	8101270161	RES	CRUTCHFIELD, D.	8101210246
CRUTCHFIELD, H. H.	8101270672	50-275 A	CRUTCHFIELD, D.	810140126	50-10 P	CRUTCHFIELD, D.	8101210347
CRUTCHFIELD, H. H.	8101200321	50-275 A	CRUTCHFIELD, D.	8101180019	50-155 P	CRUTCHFIELD, D.	8101210349
CRUTCHFIELD, H. H.	8101260655	PR	CRUTCHFIELD, D.	8101190024	50-245 P	CRUTCHFIELD, D.	8101220472
CRUTCHFIELD, H. H.	8101190541	FOIA	CRUTCHFIELD, D.	8101190112	50-409 P	CRUTCHFIELD, D.	8101280098
CRUTCHFIELD, H. H.	8101190091	PR	CRUTCHFIELD, D.	8101300167	50-255 P	CRUTCHFIELD, D.	8101280097
CRUTCHFIELD, H. H.	8101100094	50-312 0	CRUTCHFIELD, D.	8101300377	50-255 P	CRUTCHFIELD, D.	8101280072
CRUTCHFIELD, H. H.	8101100066	50-312 0	CRUTCHFIELD, D.	8101300390	50-255 P	CRUTCHFIELD, D.	8101300403
CRUTCHFIELD, H. H.	8101210104	50-206 Q	CRUTCHFIELD, D.	8101160415	50-206 P	CRUTCHFIELD, D.	8101160266
CRUTCHFIELD, H. H.	8101100078	50-312 0	CRUTCHFIELD, D.	8101290700	NURE0	CRUTCHFIELD, D.	8101300748
CRUTCHFIELD, H. H.	8101210612	50-275 Q	CRUTCHFIELD, D.	8101060320	50-29 P	CRUTCHFIELD, D.	8101300743

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER
CULVER, C. H.	8101290341*	CONTRACT	DALROFF, S. L.	8101130314	50-277 P	DULP, O. A.	8101130112*
CULVER, M. W.	8101200294*	50-302 R	DANCE, H. C.	8101090847*	50-327 0	DULSEL, C.	8101120332
CUMMINGS, J. J.	8101260314*	FOIA	DANCE, H. C.	8101100264*	50-327 0	DUKEVECHIO, A.	8101140915
CUMMINGS, J. J.	8101260120*	FOIA	DANCE, H. C.	8101290370*	50-370 0	DUMPREY, P. A.	8101260030*
CUMMINGS, J. J.	8101260105*	50-320 P	DANIELS, F. T.	8101126070*	50-359 0	DUMPREY, P. A.	8101260222*
CUMMINGS, J. J.	8101260300*	FOIA	DANIELS, M. A.	8101090111	50-289 H	DENNING, R. S.	8101270102
CUMMINGS, J. J.	8101260237*	FOIA	DANIELSEN, D. H.	8101100133*	50-294 0	DENNING, R. S.	8101260103
CUMMINGS, J. J.	8101260262*	FOIA	DANIELSEN, D. M.	8101150599*	50-155 0	DENNING, R. S.	8101260165
CUMMINGS, J. J.	8101260276*	FOIA	DANIELSEN, F. T.	8101290506*	50-346 0	DENNING, R. S.	8101060236
CUMMINGS, J. J.	8101260260*	FOIA	DANIELSEN, F. T.	8101290543*	50-358 0	DENNING, R. S.	8101070043
CUMMINGS, J. J.	8101260247*	FOIA	DANIELSEN, J. D. H.	8101230672*	50-409 0	DENNING, R. S.	8101270591
CUMMINGS, J. J.	8101140173*	50-220 P	DANIELSON, D. H.	8101230687*	50-374 0	DENNING, R. S.	8101290781
CUMMINGS, D.	8101190439	PR	DANIELSON, D. H.	8101290122*	50-329 0	DENNING, R. S.	8101230115
CUMMINGHAM, R. E.	8101090796*	70-821	DANIELSON, D. H.	8101210086*	50-461 0	DENNING, R. S.	8101130269
CUMMINGHAM, R. E.	8012290515	71-5980	DANIELSON, D. H.	8101290438*	50-254 0	DENNING, R. S.	8101100130
CUMMINGHAM, R. E.	8012290532	71-5971	DANIELSON, D. H.	8101160259*	50-227 0	DENNING, R. S.	8011100476*
CUMMINGHAM, R. E.	8012290549	71-5926	DANIELSON, D. H.	8101270856	PR	DENNING, R. S.	8012110612*
CUMMINGHAM, R. E.	8012290569	71-5939	DANIELSON, J. A.	8101270554*	50-348 P	DENNING, R. S.	8101150925
CUMMINGHAM, R. E.	8012290590	71-9044	DANIELSON, D. R.	8101290169*	50-440 0	DENNING, R. S.	8012240475
CUMMINGHAM, R. E.	8101260130	PR	DAVIDSON, R. L. H.	8101260330	PR	DENNING, R. S.	8101060274
CUMMINGHAM, R. G.	8101140431	PR	DAVIDSON, D. R.	8101220121*	50-440 0	DENNING, R. S.	8101150589*
CUMMINGHAM, A. L.	8101290549*	50-518 0	DAVIDSON, J. H.	8101200517	50-440 0	DENNING, R. S.	8101120033
CUMMINGHAM, O. E.	8101280176	50-70 F	DAVIDSON, J. H.	81011100120	WUREO	DENNING, R. S.	8101090932
CUMMINGHAM, M. E.	8101270943	WUREO	DAVIDSON, D. R.	8101220565	50-440 5	DENNING, R. S.	8101090937*
CURBIT, D. R.	8101200070	50-259 0	DAVIDSON, D. R.	8101220420	50-440 5	DENNING, R. S.	8101090936
CURRAN, D.	8101220184	PR	DAVIDSON, O. R.	8101300450	50-440 A	DENNING, R. S.	8101150779
CURRAN, J. H.	8101160513*	50-206 S	DAVIS, D. K.	8101070012*	FOIA	DENNING, R. S.	8101150930*
CURRAN, J. H.	8101210404	50-206 R	DAVIS, J. O.	8101060585*	50-201 0	DENNING, R. S.	8101150777*
CURRIE, J. H.	8101220660	RES	DAVIS, J. O.	8101230624*	100FR	DENNING, R. S.	8101200167
CURTIS, N. H.	8101090857*	50-387 0	DAVIS, J. O.	8101060122*	WASIE 1001	DENNING, R. S.	8101200191*
CURTIS, N. H.	8101100076*	50-387 8	DAVIS, J. O.	8101090646*	COMMISSION	DENNING, R. S.	8101150579
CURTIS, N. H.	8101090071*	50-387 F	DAVIS, A. B.	8101200122*	46-8724	DENNING, R. S.	8101190630
CURTIS, N. H.	8101090375*	50-387 F	DAVIS, I. O.	8101060119*	WASIE 1001	DENNING, R. S.	8101140208
CURTIS, N. H.	8012310343	50-387 0	DAVIS, A. B.	8101090074	50-255 0	DENNING, R. S.	8101150937
CURTIS, R. T.	8101210537	50-517 A	DAVIS, A. B.	8101070113	50-10 0	DENNING, R. S.	8101140237*
CURTIS, N. H.	8101150046*	50-387 0	DAVIS, R. E.	8101290070	RES	DENNING, R. S.	8101230290
CURTIS, M. C.	8101220111	PR	DAVIS, A. B.	8101220116	50-155 0	DENNING, R. S.	8101140181
CURTIS, N. H.	8101170783*	50-387 5	DAVIS, A. B.	8101220131	50-155 0	DENNING, R. S.	8101290684
CURTIS, J. R.	8101290544*	50-142 0	DAVIS, A. B.	8101140847	50-373 0	DENNING, R. S.	8101290694
CURTIS, N. H.	8101090332	50-387 5	DAVIS, J. O.	8101090820*	50-201 P	DENNING, R. S.	8101270710
CURTIS, N. H.	8101090703	50-387 H	DAVIS, J. O.	8101090779	50-201 0	DENNING, R. S.	8101200315
CURTIS, N. H.	8101130166	50-387 A	DAVIS, A. B.	8101150628	50-295 0	DENNING, R. S.	8101210079
CURTIS, N. H.	8101130320	50-387 A	DAVIS, A. B.	8101150634*	50-295 0	DENNING, R. S.	8101210087
CURTIS, N. H.	8101270482	50-387 A	DAVIS, A. B.	8101130779	50-373 0	DENNING, R. S.	8101210695
CURTIS, N. H.	8101120109	50-387 R	DAVIS, A. O.	8101260720	50-346 0	DENNING, R. S.	8101210106
CURTIS, N. H.	8101190207	50-387 A	DAVIS, A. B.	8101150310	50-341 0	DENNING, R. S.	8101210253
CURTIS, N. H.	8101210162	50-387 5	DAVIS, A. B.	8101080379	0A974	DENNING, R. S.	8101210208
CURTIS, J. R.	8101200385	50-349 0	DAVIS, C. E.	8101070319*	50-247 A	DENNING, R. S.	8101210307
CURTIS, M. W.	8101260370	50-387 A	DAVIS, C. E.	8101270741	RES	DENNING, R. S.	8101210310
CURTIS, H. H.	8101270425	50-387 5	DAVIS, C. E.	8101290817	WUREO	DENNING, R. S.	8101290011
CURTIS, N. H.	8101280150*	50-387 A	DAVIS, A. B.	8101150076	50-255 0	DENNING, R. S.	8101290017*
CURTIS, N. H.	8101200500	50-387 A	DAVIS, A. O.	8101270920	50-155 0	DENNING, R. S.	8101280621
CUTCHIN, J. H.	8101160167	50-289 0	DAVIS, A. B.	8101220110	50-303 0	DENNING, R. S.	8101290212
CUTCHIN, J. H.	8101210221	50-289 T	DAVIS, L. J.	8101230638	50-482 0	DENNING, R. S.	8101130054
CUTUJO, B.	8101210556	PR	DAVIS, S. H.	8101230540*	50-317 5	DEPAOLA, R. N.	8101230944
CWALINA, O.	8010070600*	50-10 P	DAVIS, S. H.	8101300533*	50-318 5	PERO-PERO, C.	8101130275
CYBULSKI, P.	8101240265	RES	DAWSON, P.	8101300485	PR	PERO-PERO, C.	8101230507*
CYBULSKI, P.	8101060636	RES	DAWSON, O. H.	8101140009	71-9001	PERO-PERO, C.	8101140134
CYBULSKI, P.	8101290691	RES	DAWSON, D. H.	8101230054*	70-1309	PERO-PERO, C.	8101230607
CZAJAKOWSKI, C. J.	8101220637	50-298 P	DAY, D.	8101260398	PR	PERO-PERO, C.	8101270630
D'ABRAZZI, T.	8101300058	PR	DAY, R.	8101220622	RES	DETULLIO, H.	8101260109
D'ANGELO, A. J.	8101220543*	50-508 0	DEALE, V. B.	8101050625	50-522 0	DEVER, P. J.	8101300153
D'ABRACCI, T.	8101200130	PR	DEALE, V. B.	8101070308	50-445 0	DEVINE, J. B.	8101100239*
D'AMLOUST, J. H.	8101270611	50-317 F	DECECCO, J. H.	8101230973	50-287 H	DEVINE, J. B.	8101120387*
D'AMLOUST, J. H.	8101160563	PR	DECK, M.	8101270773	PR	DEVINE, J. B.	8101090538*
DAHL, L. C.	8101230502	50-491 5	DEEDS, H. E.	8101090962	WUREO	DEVINE, J. B.	8101090532
DALE, L. F.	8101120009	50-416 0	DEEDS, H. E.	8101090965	WUREO	DEVINE, J. B.	8101083340*
DALE, L. F.	8101120123	50-416 0	DEES, K.	8101140588	PR	DEVINE, J. B.	8101100607
DALE, L. F.	8101090100	50-416 A	DEGENFELDER, E.	8101300192	PR	DEVINE, J. B.	8101120037
DALE, L. F.	8101060435	50-416 A	DEGUZIAN, H. D.	8101220376	PR	DEVINE, J. B.	8101140266
DALE, L. F.	8101290367	50-416 0	DEGUZMAN, H. D.	8101220379	PR	DEVINE, J. B.	8101140271
DALE, L. F.	8101130226	50-416 A	DELANEY, J. C.	8012100389*	70-925	DEVINE, J. B.	8101140375*
DALE, L. F.	8101150637	50-416 K	DELFLO, A. H.	8101270319	50-247 0	DEVINE, J. B.	8101140381
DALE, L. F.	8101220474	50-416 A	DELEON, J. D.	8101150184	PR	DEVINE, J. B.	8101060587
DALE, L. F.	8101220294	50-416 A	DELEON, L. O.	8101090415	50-373 5	DEVINE, J. B.	8101060694
DALE, L. F.	8101220337	50-416 A	DELEON, L. O.	8101190352	50-373 K	DEVINE, J. B.	8101060696
DALE, L. F.	8101220490	50-416 A	DELEON, L. O.	8101140512	50-373 A	DEVINE, J. B.	8101060698
DALROFF, S. L.	8101100211*	90-277 0	DELEON, L. O.	8101200245	50-373 A	DEVINE, J. B.	8101070310
DALROFF, S. L.	8101150073*	90-277 0	DELEON, L. O.	8101220360	50-10 P	DEVINE, J. B.	8101070655*
DALROFF, S. L.	8101220135*	90-277 0	DELEON, L. O.	8101230433	50-373 5	DEVINE, J. B.	8101140625
DALROFF, S. L.	8101220149*	90-277 0	DELINGARD, H. H.	8101200623	50-269 H	DEVINE, J. B.	8101090778
DALROFF, S. L.	8101100775	90-277 0	DELLA RATTIA, A.	8101060747*	70-1109	DEVINE, J. B.	8101070981
DALROFF, S. L.	8101140744	90-278 0	DELMAN, J. R.	8101300081	PR	DEVINE, J. B.	8101120192
DALROFF, S. L.	8101230330*	90-277 F	DELING, S.	8101200371*	50-315 5	DEVINE, J. B.	8101090584
DALROFF, S. L.	8101090003	90-277 P	DELING, S.	8101290521*	50-315 5	DEVINE, J. B.	8101090774

0101070553	50-298	P	DOHERTY, J. F.	8101070553
0101080114	50-272	P	DOHERTY, J. F.	8101080114
0101070553	50-280	P	DOHERTY, J. F.	8101070553
0101140101	50-313	P	DOHERTY, J. F.	8101140101
0101080104	50-272	P	DOHERTY, J. F.	8101080104
0101050441	50-344	P	DOHERTY, J. F.	8101050441
0101190779	50-322	A	DOHERTY, J. F.	8101190779
0101100226	50-443	A	DOHERTY, J. F.	8101100226
0101100234	50-268	F	DOHERTY, J. F.	8101100234
0101100240	50-70	F	DOHERTY, J. F.	8101100240
0101200690	50-87	F	DOHERTY, J. F.	8101200690
0101162355	50-324	P	DOHERTY, J. F.	8101162355
0101070355	50-29	P	DOHERTY, J. F.	8101070355
0101210140	50-335	P	DOHERTY, J. F.	8101210140
0101190480	50-280	P	DOHERTY, J. F.	8101190480
0101260473	50-322	A	DOHERTY, J. F.	8101260473
0101280582	50-335	P	DOHERTY, J. F.	8101280582
0101240171	50-70	F	DOHERTY, J. F.	8101240171
0101260591	50-443	Q	DOHERTY, J. F.	8101260591
0101280591	50-443	Q	DOHERTY, J. F.	8101280591
0101120259	50-346	P	DOHERTY, J. F.	8101120259
0101230346	50-193	P	DOHERTY, J. F.	8101230346
0101070598	50-193	P	DOHERTY, J. F.	8101070598
0101210016	71-6400		DOHERTY, J. F.	8101210016
01012290195	71-6400		DOHERTY, J. F.	81012290195
0101210563	FOIA		DOHERTY, J. F.	8101210563
0101250144	FOIA		DOHERTY, J. F.	8101250144
0101090166	FOIA		DOHERTY, J. F.	8101090166
0101260267	FOIA		DOHERTY, J. F.	8101260267
0101260255	FOIA		DOHERTY, J. F.	8101260255
0101060596	10CFR		DOHERTY, J. F.	8101060596
0101140762	50-344	H	DOHERTY, J. F.	8101140762
0101090759	COMMISSION		DOHERTY, J. F.	8101090759
0101230101	SECY		DOHERTY, J. F.	8101230101
01012290483	10CFR		DOHERTY, J. F.	81012290483
0101060046	COMMISSION		DOHERTY, J. F.	8101060046
0101060046	COMMISSION		DOHERTY, J. F.	8101060046
0101050167	50-302	I	DOHERTY, J. F.	8101050167
0101140036	50-250	O	DOHERTY, J. F.	8101140036
0101100049	50-367	O	DOHERTY, J. F.	8101100049
0101120133	50-142	I	DOHERTY, J. F.	8101120133
0101080087	50-247	O	DOHERTY, J. F.	8101080087
0101090764	COMMISSION		DOHERTY, J. F.	8101090764
0101070408	COMMISSION		DOHERTY, J. F.	8101070408
0101070467	COMMISSION		DOHERTY, J. F.	8101070467
0101140166	50-220	P	DOHERTY, J. F.	8101140166
0101070241	COMMISSION		DOHERTY, J. F.	8101070241
0101140041	COMMISSION		DOHERTY, J. F.	8101140041
0101090715	50-295	P	DOHERTY, J. F.	8101090715
0101140162	50-220	P	DOHERTY, J. F.	8101140162
0101150057	COMMISSION		DOHERTY, J. F.	8101150057
0101150862	COMMISSION		DOHERTY, J. F.	8101150862
0101060946	50-312	I	DOHERTY, J. F.	8101060946
0101120044	50-946	H	DOHERTY, J. F.	8101120044
0101290659	50-263	H	DOHERTY, J. F.	8101290659
0101290783	50-483	H	DOHERTY, J. F.	8101290783
0101300021	50-352	H	DOHERTY, J. F.	8101300021
0101270506	50-247	H	DOHERTY, J. F.	8101270506
0101300061	PR		DOHERTY, J. F.	8101300061
0101303198	50-309	H	DOHERTY, J. F.	8101303198
0101300256	50-206	H	DOHERTY, J. F.	8101300256
0101060540	50-220	S	DOHERTY, J. F.	8101060540
0101050087	50-220	I	DOHERTY, J. F.	8101050087
0101070500	50-230	G	DOHERTY, J. F.	8101070500
0101060400	50-220	P	DOHERTY, J. F.	8101060400
0101070381				

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
EARLEY, A. F.	0101280222*	50-322 O	EISENHUT, D. O	0101140848	50-247 F	ERICKSON, P. B.	0101050055*	50-322 O
EARLEY, A. F.	0101280212	50-322 O	EISENHUT, D. O	0101050124	50-244 O	ERICKSON, P. B.	0101050077*	50-322 O
EASEN, S.	0101200205	50-209 H	EISENHUT, D. O	0101060420	50-3 P	ERINSTE, M. L.	0101020275	REV
EASTMAN, K.	0101280237	50-450 O	EISENHUT, D. O	0101120542*	50-255 F	ERL, FLAM, D.	0101060092*	50-322 O
EASTMAN, J.	0101280338	PR	EISENHUT, D. O	0101103046	50-220 F	ERL, FLAM, D.	0101280477	PR
EBERLEIN, F.	0101280310	FOIA	EISENHUT, D. O	0101270466	50-3 P	ESTES, G.	0101270824	PR
EBERT, M.	0101210280	PR	EISENHUT, D. O	0101270466	50-3 P	EVANS, L. J.	0101280077*	50-322 O
EBERTER, S. D.	0101300107*	50-373 O	EISENHUT, D. O	0101280466	50-3 P	EVANS, A. F.	0101280127	50-322 O
EBERTER, B. D.	0101100521*	50-278 O	EISENHUT, L. O	0101300543	RES	EVANS, C. A.	0101100008*	50-322 O
EBERTER, S. D.	0101140120*	50-272 O	EISENHUT, D. O	0101100155	50-269 H	EVANS, N.	0101130089	PR
EDRIGHT, D. J.	0101350179	PR	EISENHUT, D. O	0101190113	50-10 P	EWING, J. E.	0101140541	PR
EDY, U.	0101060530*	50-209 H	EISENHUT, D. O	0101050502	50-307 E	FABRE, V. K.	0101130046	PR
ECHLE, C.	0101150510	50-403 H	EISENHUT, D. O	0101210445	50-3 P	FABRE, L.	0101130150	PR
ECHHART, J. H.	0101300771*	50-361 O	EISENHUT, D. O	0101070521	50-352 H	FABRE, T. C.	0101140038*	50-322 O
ECHHOUT, A.	0101140085	XPORTRLIC	EISENHUT, D. O	0101150163	50-413 A	FABRE, T. C.	0101200046	50-322 O
ECCONCHOS, H.	0101100040*	50-553 O	EISENHUT, D. O	0101150171*	50-413 A	FABRE, R.	0101220154	PR
ECCONCHOS, H.	0101150773*	50-369 O	EISENHUT, D. O	0101160421*	50-337 P	FABRE, L. A. S.	0101280038	50-322 O
EDDIE, D. O.	0101070523	WASTE POT	EISENHUT, D. O	0101210642	50-259 P	FABRE, L. A. S.	0101070004	50-322 O
EDDIE, E. H. W.	0101190455	PR	EISENHUT, D. O	0101170170	50-247 H	FABRE, L. A. S.	0101070029	50-322 O
EDELSTEIN, B.	0101140954	XPORTRLIC	EISENHUT, D. O	0101150145	50-470 A	FABRE, L. A. S.	0101090078	50-322 O
EDELSTEIN, B.	0101140959*	XPORTRLIC	EISENHUT, D. O	0101150152	50-262 F	FABRE, L. A. S.	0101090078	50-322 O
EDGAR, G. L.	0101050506*	50-70 O	EISENHUT, D. O	0101170160	50-460 A	FABRE, L. A. S.	0101280038	50-322 O
EDGAR, G. L.	0101030515*	50-70 O	EISENHUT, D. O	0101190509	50-447 A	FABRE, L. A. S.	0101280038	50-322 O
EDGAR, G. L.	0101050494	50-70 O	EISENHUT, D. O	0101290355	50-247 E	FABRE, L. A. S.	0101280038	50-322 O
EDGAR, G. L.	0101220170	PR	EISENHUT, D. O	0101160000	50-295 H	FABRE, L. A. S.	0101280038	50-322 O
EDGAR, E. C.	0101120317*	50-244 B	EISENHUT, D. O	0101230012	FOIA	FABRE, L. A. S.	0101280038	50-322 O
EDGAR, E. C.	0101160177	50-70 O	EISENHUT, D. O	0101230024	50-330 P	FABRE, L. A. S.	0101280038	50-322 O
EDGEMORTH, P. J.	0101300307	CONTRACT	EISENHUT, D. O	0101300251*	50-237 P	FABRE, L. A. S.	0101280038	50-322 O
EDGEMORTH, P. J.	0101210572	CONTRACT	EISENHUT, D. O	0101300373*	50-220 P	FABRE, L. A. S.	0101280038	50-322 O
EDGEMORTH, P. J.	0101300208	CONTRACT	EISENHUT, D. O	0101300307*	50-293 P	FABRE, L. A. S.	0101280038	50-322 O
EDWARDS, J. B.	0101070598*	50-443 F	EISENHUT, D. O	0101300375*	50-263 P	FABRE, L. A. S.	0101280038	50-322 O
EDWARDS, L. D.	0101300035	PR	EISENHUT, D. O	0101300409*	50-258 H	FABRE, L. A. S.	0101280038	50-322 O
EDWARDS, R. P.	0101220173	PR	EISENHUT, D. O	0101300411*	50-271 P	FABRE, L. A. S.	0101280038	50-322 O
ECKHOUT, A.	0101100499	XPORTRLIC	EISENHUT, D. O	0101300430*	50-331 P	FABRE, L. A. S.	0101280038	50-322 O
ECHENSPERGER, W.	0101260396	50-424 A	EISENHUT, D. O	0101300460*	50-259 P	FABRE, L. A. S.	0101280038	50-322 O
EICHENBINDER, C.	0101290676*	50-247 P	EISENHUT, D. O	0101300467*	50-259 P	FABRE, L. A. S.	0101280038	50-322 O
EICHENBINDER, C.	0101300153	NUREO	EISENHUT, D. O	0101300373*	50-333 P	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101290115	40-8502	EISENHUT, D. O	0101260653	50-528 A	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100504	50-250 P	EISENHUT, D. O	0101220595	PR	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100519*	50-250 P	EL-ASHRY, H. I.	0101220411	50-259 P	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100532	50-315 P	EL-ASHRY, H. I.	0101220020	50-327 E	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100549*	50-315 P	EL-ASHRY, H. I.	0101220020	50-327 E	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100563	50-200 P	EL-ASHRY, H. I.	0101220020	50-327 E	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100574*	50-200 P	EL-ASHRY, H. I.	0101220020	50-327 E	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100587	50-348 P	ELLERSHAW, L. E.	0101200131*	0A999	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100595*	50-348 P	ELLER, V.	0101210182	PR	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100617	50-334 P	ELLIS, B.	0101050370	50-369 H	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100622*	50-334 P	ELLIS, J.	0101050523	50-445 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100629*	50-247 P	ELLIS, J.	0101290631*	50-335 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100636*	50-247 P	EMERY, O. F.	0101270590*	50-247 H	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100646	50-261 P	ENGBERG, E. O.	0101290527*	70-754	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100654*	50-261 P	ENGELKEN, R. H.	0101130675	50-312 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100660	50-206 P	ENGELKEN, R. H.	0101060687	70-1470	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100666*	50-206 P	ENGELKEN, R. H.	0101280531*	50-508 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100674	50-295 P	ENGELKEN, R. H.	0101050489	50-206 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100680*	50-295 P	ENGELKEN, R. H.	0101050496	50-312 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100690	50-272 P	ENGELKEN, R. H.	0101050498	50-344 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100693*	50-272 P	ENGELKEN, R. H.	0101050503	50-528 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100700	50-305 P	ENGELKEN, R. H.	0101050504	50-133 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100706*	50-305 P	ENGELKEN, R. H.	0101050510	50-397 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100737	50-3 P	ENGELKEN, R. H.	0101060601	70-2908	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101090387	50-3 F	ENGELKEN, R. H.	0101150622	50-273 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101090449	50-277 F	ENGELKEN, R. H.	0101150625	50-344 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101090453	50-302 F	ENGELKEN, R. H.	0101150627	50-312 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100254	50-3 P	ENGELKEN, R. H.	0101150632	50-206 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101050485	50-298 F	ENGELKEN, R. H.	0101150635	50-508 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100043	50-263 F	ENGELKEN, R. H.	0101150037	50-360 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100058	50-271 F	ENGELKEN, R. H.	0101150538	50-520 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101100061	50-344 F	ENGELKEN, R. H.	0101130168	50-133 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101120535	50-295 F	ENGELKEN, R. H.	0101130110	50-397 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101130124	50-282 F	ENGELKEN, R. H.	0101090775	50-133 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101130132	50-309 F	ENGELKEN, R. H.	0101070784	50-397 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101130134	50-335 F	ENGELKEN, R. H.	0101050164	50-397 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101130136	50-317 F	ENGELKEN, R. H.	0101050166	50-133 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101130139	50-293 F	ENGELKEN, R. H.	0101100635	50-312 F	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101130142	50-368 F	ENGELKEN, R. H.	0101100838	50-206 F	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101130165	50-272 F	ENGELKEN, R. H.	0101100930	50-344 F	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101130170	50-315 F	ENGELKEN, R. H.	0101100949	50-273 F	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101130184	50-250 F	ENGELKEN, R. H.	0101270459	50-528 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101130717	50-260 F	ENGLE, L. B.	0101270267	MISC	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101140822	50-349 F	ENTWISLE, E. B.	0101270282	50-170 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101140827	50-286 F	ENTWISLE, E. B.	0101270282	50-170 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101140830	50-261 F	EPSTEIN, R.	0101140595	PR	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101140836	50-334 F	ERB, C. M.	0101210058*	50-461 O	FABRE, L. A. S.	0101280038	50-322 O
EISENHUT, D. O.	0101140841	50-303 F	ERB, C. M.	0101160259*	50-229 O	FABRE, L. A. S.	0101280038	50-322 O

[illegible]

EASLEY, A. F.	0101280512	50-322	G	EISENHUT, D. G	0101050124	50-244	G	ERICKSON, P. B	0101100419	50-3
EASEN, S	0101200209	50-289	H	EISENHUT, D. G	0101060470	50-3	P	ERIST, M. L	0101050295	REV
EASIMAN, K	01012100297	50-498	G	EISENHUT, D. G	0101120542	50-295	F	ESHELBAH, D	0101050628	50-3
EAS7MAN, J	0101280338	PR		EISENHUT, D. G	0101100046	50-220	F	ESPOSITO, H. L	0101200479	PR
EEDALEIN, F	0101280410	FOIA		EISENHUT, D. G	0101200466	50-3	P	ESTES, D.	0101270824	PR
EERT, M	0101210280	PR		EISENHUT, D. G	0101200466	50-3	P	EVANS, L. J	0101260379	1048
EDMEIER, S. D	0101300107	50-333	O	EISENHUT, D. G	0101200466	50-3	P	EVANS, A. B	0101280127	50-3
EDNETER, S. D	0101100524	50-278	O	EISENHART, L. D	0101300543	4ES		EVANS, C. A	0101100606	50-3
EDNETER, S. D	0101110120	50-272	D	EISENHUT, D. G	0101100150	50-269	H	EVANS, H	0101130185	PR
EDRIGHT, D. J	0101300179	PR		EISENHUT, D. G	0101190113	50-10	P	EWING, J. E	0101140541	PR
EBY, U	0101060530	50-289	H	EISENHUT, D. G	0101050592	50-387	E	FAURE, Y. H	0101130146	PR
ECHELE, C	0101150510	50-183	G	EISENHUT, D. G	0101210045	50-3	P	FAURE, L	0101130150	PR
ECKHARDT, J. H	0101200771	50-361	G	EISENHUT, D. G	0101070621	50-352	H	FAY, C. T. C.	0101110232	50-3
ECKHARDT, A	0101140835	XPORLIC		EISENHUT, D. G	0101190163	50-473	A	FANNER, T. C.	0101260048	50-3
EDWARDS, H	0101100410	50-353	G	EISENHUT, D. G	0101190171	50-413	A	FARNER, R	0101220154	PR
EDWARDS, H	0101150773	50-369	G	EISENHUT, D. G	0101160421	50-339	P	FARNELL, A. S	0101070284	50-3
EDWIE, Q. O	0101070523	WASTE MOT		EISENHUT, D. G	0101210042	50-259	P	FARNELL, A. S	0101070284	50-3
EDLEMAN, H	0101190435	PR		EISENHUT, D. G	0101190190	50-247	H	FARNELL, A. S	0101070474	50-3
EDLSTEIN, D	0101140954	XPORLIC		EISENHUT, D. G	0101150145	50-470	A	FARNELL, A. S	0101070378	50-3
EDELSTEIN, D	0101140959	XPORLIC		EISENHUT, D. G	0101150152	50-302	P	FARNELL, A. S	0101070078	50-3
EDGAR, O. L	0101050506	50-70	O	EISENHUT, D. G	0101190168	50-483	A	FARNELL, A. S	0101220154	50-3
EDGAR, O. L	0101050515	50-70	O	EISENHUT, D. G	0101190209	50-447	A	FARNELL, A. S	0101200154	50-3
EDGAR, O. L	0101050494	50-70	O	EISENHUT, D. G	0101170035	50-247	S	FARNELL, A. S	0101260279	50-3
EDGAR, G. L	0101220178	PR		EISENHUT, D. G	0101160260	50-295	H	FARNELL, A. S	0101200479	50-3
EDGAR, E. C	0101120317	50-244	G	EISENHUT, D. G	0101230612	FOIA		FARRAR, A. D	0101140796	CONF
EDGAR, O. L.	0101160197	50-70	G	EISENHUT, D. G	0101300324	50-338	P	FARRAR, J. D	0101290320	50-3
EDGEWORTH, P.	0101300307	CONTRACT		EISENHUT, D. G	0101300394	50-237	P	FASANO, A. H	0101150169	50-3
EDGEWORTH, P. J	0101210572	CONTRACT		ETSEHUT, D. O	0101300373	50-200	P	FASANO, A.	0101200129	50-3
EDGEWORTH, P.	0101300205	CONTRACT		EISENHUT, D. G	0101300389	50-293	P	FASANO, A.	0101180515	50-3
EDWARDS, J. D	0101070298	50-445	F	EISENHUT, D. G	0101300395	50-263	P	FASANO, A.	0101280524	50-3
EDWARDS, L. D	0101300203	PR		EISENHUT, D. G	0101300409	50-298	P	FASANO, A. H	0101280507	50-3
EDWARDS, R. P	0101220173	PR		EISENHUT, D. G	0101300411	50-271	P	FAULKENBERRY, B	0101100103	50-3
EEDKHOUT, A	0101100497	XPORLIC		EISENHUT, D. G	0101300430	50-331	F	FAULKENBERRY, G	0101210608	50-3
EERENBERGER, H	0101260396	50-424	A	EISENHUT, D. G	0101300430	50-259	P	FAULKNER, H. I.	0101210570	PR
EICHELDAUER, C	0101290676	50-247	P	EISENHUT, D. G	0101300467	50-259	P	FAULKENBERRY, B	0101060087	50-3
EICSEN, A. F.	0101300153	NOREG		EISENHUT, D. G	0101300757	50-333	F	FAULKENBERRY, B	0101210501	50-3
EISENHART, H. A	0101290115	40-8502		EISENHUT, D. G	0101260853	50-528	A	FAULKENBERRY, B	0101210130	50-3
EISENHUT, D. D	0101100504	50-250	P	EISENHUT, D. G	0101220575	PR		FAULKNER, R	0101280625	50-3
EISENHUT, D. G	0101100519	50-250	P	EL-ASHRY, M. T	0101220411	50-257	P	FAY, R. E	0101270527	50-3
EISENHUT, D. D	0101100532	50-315	P	EL-ASHRY, H. T	0101220202	50-327	S	FAY, C. W	0101090113	50-3
EISENHUT, D. D	0101100549	50-315	P	EL-ASHRY, H. T	0101220318	50-327	O	FAY, C. W	0101090113	50-3
EISENHUT, D. G	0101100563	50-280	P	EL-ASHRY, M. T	0101230436	50-327	S	FAY, C. W	0101140127	PR
EISENHUT, D. G	0101100574	50-280	P	EL-ASHRY, M. T	0101230384	50-438	A	FAY, C. W	0101270575	50-3
EISENHUT, D. G	0101100587	50-348	P	ELLERSON, L. E	0101200131	0A999		FAY, C. W	0101270615	50-3
EISENHUT, D. G	0101100595	50-340	P	ELLER, V	0101210182	PR		FAY, C. W	0101070570	50-3
EISENHUT, D. G	0101100617	50-334	P	ELLIS, B	0101030370	50-369	H	FAY, C. W	0101050429	50-3
EISENHUT, D. G	0101100622	50-334	P	ELLIS, J	0101050573	50-445	O	FAY, C. W	0101050446	50-3
EISENHUT, D. G	0101100629	50-247	P	ELROD, B. A	0101290361	50-335	G	FAY, C. W	0101120393	50-3
EISENHUT, D. G	0101100636	50-247	P	EMERY, O. F	0101270590	50-247	H	FAY, C. W	0101120367	50-3
EISENHUT, D. G	0101100646	50-261	P	ENEDROCK, E. G	0101290527	70-754		FAY, C. W	0101126201	50-3
EISENHUT, D. G	0101100694	50-261	P	ENGELKEN, R. H.	0101130675	50-312	G	FAY, C. W	0101200150	50-3
EISENHUT, D. G	0101100660	50-286	P	ENGELKEN, R. H.	0101060687	70-1470		FAY, C. W	0101150519	50-3
EISENHUT, D. G	0101100666	50-286	P	ENGELKEN, R. H.	0101226931	50-308	G	FAY, C. W	0101210389	50-3
EISENHUT, D. G	0101100674	50-295	P	ENGELKEN, R. H.	0101050489	50-206	D	FAY, C. W	0101270549	50-3
EISENHUT, D. G	0101100680	50-295	P	ENGELKEN, R. H.	0101050496	50-312	G	FAY, C. W	0101270710	50-3
EISENHUT, D. D	0101100690	50-272	P	ENGELKEN, R. H.	0101050490	50-344	D	FAY, C. W	0101150517	50-3
EISENHUT, D. G	0101100693	50-272	P	ENGELKEN, R. H.	0101050503	50-520	D	FAY, C. W	0101270571	50-3
EISENHUT, D. D	0101100700	50-305	P	ENGELKEN, R. H.	0101050504	50-133	G	FAY, C. W	0101270580	50-3
EISENHUT, D. D	0101100706	50-305	P	ENGELKEN, R. H.	0101050510	50-397	O	FAY, C. W	0101270584	50-3
EISENHUT, D. D	0101100737	50-3	P	ENGELKEN, R. H.	0101060681	70-2908		FAY, C. W	0101260410	50-3
EISENHUT, D. G	0101090307	50-3	F	ENGELKEN, R. H.	0101150822	50-275	O	FAY, C. W	0101260340	50-3
EISENHUT, D. G	0101090449	50-277	F	ENGELKEN, R. H.	0101150825	50-344	O	FAY, C. W	0101270666	50-3
EISENHUT, D. G	0101090453	50-302	F	ENGELKEN, R. H.	0101150827	50-312	O	FAZIO, P. V	0101290057	50-4
EISENHUT, D. G	0101100254	50-3	P	ENGELKEN, R. H.	0101150832	50-206	D	FAZIO, P. V	0101290057	50-4
EISENHUT, D. G	0101050405	50-298	F	ENGELKEN, R. H.	0101150835	50-508	D	FEDERMAN, J	0101230703	PR
EISENHUT, D. G	0101100043	50-263	F	ENGELKEN, R. H.	0101150537	50-440	O	FEEL, W. F	0101120413	50-3
EISENHUT, D. G	0101100050	50-271	F	ENGELKEN, R. H.	0101150538	50-528	O	FEEL, W. F	0101150540	50-3
EISENHUT, D. D	0101100061	50-344	F	ENGELKEN, R. H.	0101130100	50-133	O	FEEL, W. F	0101290219	50-3
EISENHUT, D. D	0101120535	50-295	F	ENGELKEN, R. H.	0101130110	50-397	O	FELHARDER, J. M	0101300049	50-3
EISENHUT, D. G	0101130124	50-282	F	ENGELKEN, R. H.	0101070775	50-123	G	FELERABENO, C	0101300205	50-3
EISENHUT, D. G	0101130132	50-309	F	ENGELKEN, R. H.	0101090784	50-397	G	FEILER, T	0101280415	PR
EISENHUT, D. D	0101130134	50-335	F	ENGELKEN, R. H.	0101050164	50-397	O	FEINER, B. A	0101290730	PR
EISENHUT, D. G	0101130136	50-317	F	ENGELKEN, R. H.	0101050166	50-133	O	FEIT, R	0101300626	50-3
EISENHUT, D. G	0101130139	50-293	F	ENGELKEN, R. H.	0101100835	50-312	F	FELDER, Y. E	0101150298	PR
EISENHUT, D. G	0101130142	50-368	F	ENGELKEN, R. H.	0101100838	50-206	F	FELDMAN, F	0101160270	PR
EISENHUT, D. G	0101130165	50-272	F	ENGELKEN, R. H.	0101100840	50-344	F	FELDMAN, J. H	0101290726	50-3
EISENHUT, D. G	0101130170	50-315	F	ENGELKEN, R. H.	0101100839	50-275	F	FELTON, J. H	0101280252	50-3
EISENHUT, D. G	0101130184	50-290	F	ENGELKEN, R. H.	0101270429	50-520	O	FELTON, J. H	0101070529	50-3
EISENHUT, D. G	0101130717	50-200	F	ENGEL, L. J	0101270267	4150		FELTON, J. H	0101070057	50-3
EISENHUT, D. G	0101140822	50-349	F	ENTWISLE, E. B	0101270282	50-170	G	FELTON, J. M	0101070551	50-3
EISENHUT, D. D	0101140827	50-286	F	ENTWISLE, E. B	0101270282	50-170	G	FELTON, J. M	0101060244	50-3
EISENHUT, D. G	0101140830	50-261	F	ERSTEIN, R	0101150595	PR		FELTON, J. M	0101120405	50-3
EISENHUT, D. G	0101140836	50-334	F	ERB, C. M.	0101210688	50-461	G	FELTON, J. M	0101290002	50-3
EISENHUT, D. D	0101140941	50-305	F	ERB, C. M.	0101160259	50-329	D	FELTON, J. M	0101220437	50-3

[illegible]

PERSONAL ACTION INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FCSTER, J E	8101276906*	30-346 O	GARRETT, P	0101230269	PR	GLOVEN, F A	8101230187	30-2
FCSTER, R	8101160598	PR	GARRITY, J H	8101220340	30-359 P	GLOVEN, W H	8101770771	RES
FCULSHAM, P A	8101060565	30-293 J	GARRITY, J H	8101270368	30-309 P	GOLLY, A T	8101156195*	30-2
FOX, C O	8101270069*	30-461 O	GARRITY, J H	8101290402	30-309 R	GOLLY, A T	8101156195*	30-2
FOX, O F	0101230510	0A999	GARRITY, J H	8101300532	30-309 F	GOLLY, M U.	8101230524	PR
FOX, G O.	0101050072	30-369 O	GARVEY, J J	8101300506	30-233 R	GOFF, D L	8101220099	PR
FRALEY, R F	8012100059*	30-592 A	GARY, R J	9101270117	30-445 J	GOLD, R L	8101210553	CONF
FRAY, F	8101140391	30-466 O	GARY, R J	8101100726*	30-445 J	GOLDBERG, S C	8101050031	30-2
FRANZIS, D	8101300810	PR	GARY, R J	0101270814	30-445 J	GOLDBERG, S C	8101050034	30-2
FRANK, F B.	8101150320*	CONTRACT	GARY, R J	8101100730*	30-445 J	GOLDBERG, J H	8101090023	30-4
FRANZ, W	8101200291*	30-206 P	GARY, R J	0101270152	30-445 J	GOLDBERG, S C	8101050587	30-3
FRASER, D	0101160130	PR	GARY, R J	8101270137	30-445 J	GOLDBERG, S C	8101140230	30-3
FRASER, D A	8101210166	30-327 E	GARY, R J	0101050318	30-445 A	GOLDBERG, S C	8101210203	30-3
FREDERICK, E J	0101150598	RES	GARY, R J	0101200042	30-445 A	GOLDBERG, S C	8101270422	30-1
FREDERICK, E J	0101290679	RES	GARY, R J	8101200246	30-445 S	GOLDBERG, S C	0101270370	30-3
FREEMAN, F	8101210203	PR	GARY, R J	8101200253	30-445 S	GOLDBERG, J H	8101290276	PROJ
FREEMAN, R L	8101200095	30-299 J	GAY, R W	0101130135*	30-29 P	GOLDEN, J C	8101220374*	30-1
FRENCH, L O	8101300726*	30-27 S	GAY, O M	0101130037	30-445 G	GOLDEN, J C	8101290791*	30-1
FREUD, C	8101210107	PR	GAY, O M	0101130037	30-445 G	GOLDMAN, H L	8101100711	State
FRIEDLANDER, J	8012240365	State Prog	GEARS, G	0101110028*	30-387 G	GOLDMAN, A	8101230276	PR
FRIEDLAND, D A	8101170526	PR	GEHR, A E	8101050562	30-275 O	GOLDSTEIN, R	8012230439	30-1
FRIEDEL, F C	0101080370	71-401	GEHR, A E	8101050010	30-275 O	GOLDSTEIN, J	8101193574	PR
FRIEDEL, F C	0101000376*	71-401	GEHR, A E	8101050382	30-275 G	GOLDSTEIN, J	8101270599	PR
FRIEDMAN, F C	8101140152	71-9032	GEHR, A E	8101060010	30-275 G	GOLDSTEIN, J	8101210637*	093
FRIEDMAN, P C	8101150113	PR	GEHR, A E	8101260301	30-275 G	GOLDSTEIN, H	0101210534	096
FRIED, D	8101170059	PR	GEHR, A E	8101280620	30-275 G	GOLLO, J	8101060621	30-1
FRIEDMAN, S	8101260605	PR	GEHR, A E	8101280620	30-275 G	GOMER, D A	81012200396	PR
FRONE, R	8101220429*	30-346 B	GELM, S	8101150160	PR	GOMILAS, E	8101230031	PR
FRIST, S R	8101220186*	30-235 O	GELMAN, S	8101230032	PR	GONZALEZ, G	8101130255	PR
FRIST, S R	8101060630	30-135 S	GEORGE, K B.	8101140446	PR	GONZALEZ, A C	8101050918	30-4
FROST, S R	0101060668	30-135 S	GERETY, H F	8101270753	30-219 J	GONULINO, B	8101060508*	30-2
FUKUDA, S K	0101100768	NUREO	GERSTNER, M C	8101060731*	30-461 J	GODMAN, L B	0101050380*	30-4
FUKUDA, S K	0101270692	NUREO	GETTLER, F M	8101090724	NF600	GODMAN, L B	0101050371*	30-4
FULLER, J K	0101070602	30-267 F	GETTY, B C	8101092410*	30-133 S	GODMAN, L B	8101060581*	30-4
FUNDERBURG, R O.	0101140004	State Prog	GIBBONS, Y	8101100609*	30-321 O	GODMAN, L B	8101110494*	30-4
FUNK, K	8101210435	PR	GIBBON, T R	8101050086	30-329 O	GOLDMAN, H L	8101260134	70-1
FURBUSH, M H	8101260301	30-275 O	GIBBS, D C	8101160677*	PR	GORDAN, W D	8101060032	PR
FURBUSH, H H	0101280620	30-275 O	GIBSON, A F	8101120853*	30-302 O	GORDON, B	8101170507	PR
FURR, B J	8101050181	30-261 O	GIBSON, G T	8101050210*	30-250 O	GOREM, B	8101210170	PR
FURR, B J	0101050630	30-324 O	GIBSON, A F	8101150017*	30-389 O	GORLEY, J E	8101200264	30-2
FURR, B J	8101070620	30-324 O	GIBSON, R B	8101290105*	CONTRACT	GROSS, C	8101150025	PR
FURR, B J	8101110209	30-261 O	GIDLO, R O	8101100003	NUREO	GROSSICK, L V	8101260339*	EDIA
FURR, B J	8101160005	30-324 O	GIESEKE, J A	8101070276	TOPREP	GROSSICK, L V	8101260319*	EDIA
FURR, B J	8101220412	30-261 O	GILBERT, L D	8101100170*	30-445 A	GOTCHY, R L	8101230341*	30-3
FUSCHEN, O	8101220392	PR	GILBERT, L O	8101140596*	30-450 A	GOTTESFELD, P	8101190587	PR
GASTON, W	8101200646	PR	GILBERT, D E	8101160772*	30-202 O	GOWER, J	8101260574	PR
GAFFNEY, E	0101160075	PR	GILBERTS, D E	8101070217	30-202 O	GRAEBER, K L	8101110471	30-2
GAOYUN, R	8101260239	PR	GILBERTS, D E	8101130118	30-263 O	GRAEBER, K L	8101050340	30-3
GAHM, J H	8101140489*	30-267 R	GILBERTS, D E	8101190271	30-263 O	GRAEBER, K L	8101230338	30-2
GAHM, J H	0101140630*	30-267 S	GILBERTS, D E	8101140156	30-263 O	GRAEBER, K L	8101120346	30-2
GAHM, J H	8101140616*	30-267 S	GILBERTS, D E	8101200145	30-262 O	GRAEBER, K L	8101130461	30-2
GAHM, J H	8101210410	30-267 S	GILBERTS, D E	8101200170	30-263 O	GRAEBER, K L	8101130541	30-2
GAHM, J H	0101210400	30-267 S	GILBERTS, D E	8101250390	30-262 O	GRAEBER, K L	8101170550	30-3
GAHM, J H	8101270421*	30-267 S	GILBEN, M L	8101080375*	30-303 O	GRAEBER, K L	8101130562	30-3
GALLARDI, E	8101230264	PR	GILINSKY, V	8101260113*	30-320 P	GRAEBER, K L	8101130458	30-2
GALLAGHER, J H	8101270728	30-277 P	GILINSKY, V	8101060052	COMMISSION	GRAEBER, K L	8101270730	30-2
GALLAN, K P	0101090506*	30-70 O	GILLELAND, J E	8101270231*	40-1341	GRANT, P	8101080392*	COM
GALLEN, K P	8101090506*	30-70 O	GILLELAND, J E	8101270251*	40-1341	GRANTER, J A	8101300258	PR
GALLEN, K P	8101050515*	30-70 O	GILLELAND, J E	0101270234*	40-1341	GRANT, W B	8101300361*	30-2
GALLEN, K P	8101090515*	30-70 O	GILMAN, F H	8101140923	NUREO	GRANT, M	8101210188	70-8
GALLO, R M	8101090669*	30-387 O	GILMAN, J D	8101090609*	TOPREP	GRASSO, E	8101270892*	CEM
GALLO, R	8101130616*	30-307 O	GILMORE, L W	8101280450*	30-244 P	GRAVEL, D T	8101220255	RES
GALLO, J	8101090804	PR	GILMORE, L W	8101120332*	30-244 P	GRAVELLE, O	8101290688	PR
GALLO, J	0101160209	30-135 O	GILMORE, L W	8101120332*	30-244 P	GRAVES, R U	8101200408	30-2
GALLUCCIO, J	8101300497	PR	GILMORE, J	8101270733*	30-255 S	GRAVES, R U	8101210376	30-2
GAMBLE, O H	8101260173*	FOIA	GINSBERG, T	8101270222	30-537 A	GRAY, R J	8101210666	30-4
GAMMILL, W P	8101080007	30-209 P	GINSBERG, T	8101270254	30-537 A	GRAY, J R	8101150103*	30-2
GANO, W G	8101210523	TOPREP	GINSBERG, T	8101270545	30-537 A	GRAY, J R	8101190788*	30-2
GANO, W G	0101230380	TOPREP	GINSBERG, T	8101220625	RES	GRAY, J R	0101090370	30-5
GANLEY, D E.	8101220629*	30-371	GINSBERG, T	8101270065	30-537 A	GRAY, J R	8101160550	30-4
GANLEY, D E	8101220504*	70-371	GINSBERG, T.	8101260758	30-537 A	GRAY, J R	8101110215	30-2
GANLEY, B F.	8101220577*	70-371	GINSBERG, T.	8101100399*	CONTRACT	GRAY, J R	8101210204	30-2
GANNIS, S	8101120196*	30-275 H	GIRON, H P	8101160535	PR	GRAY, J R	8101210192	30-2
GANNIS, S	8101280435	FOIA	GISCOMBE, K	8101220227	PR	GRAYBILL, D	8101150222	PR
GARCIA, P J.	8101120154*	40-1162	GITTINGS, E.	8101140610	PR	GREENE, O A	8101060107	RES
GAREIA, P J	8101120151	40-1162	GLADSTAR, R	8101150179	PR	GREENMAN, E G	0101090688*	30-2
GARCIA, P J	8101290043	40-3453	GLAGOLA, A F	8101060764	30-320 P	GREENMAN, E G	8101300558*	30-3
GARCIA, P J	8101270034	40-1162	GLAGOLA, A F	8101200487	CONTRACT	GREENMAN, E G	0101160145*	30-3
GARDNER, E F.	0101050157*	30-289 T	GLAGOLA, A F	8101160080	CONTRACT	GREENMAN, E G	8101160007*	30-2
GARDNER, R N.	8101140151*	30-461 G	GLAGOLA, A F	8101200455	CONTRACT	GREENMAN, E G	8101150585*	30-2
GARDNER, E F	8101050098*	30-289 T	GLAGOLA, A F	8101290525	CONTRACT	GREENMAN, E G	8101220169*	30-2
GARRAHY, J J	COMMISSION		GLASSBERG, B	8101190468	PR	GREENMAN, E G	8101300019*	30-2
GARRAHY, J J	8101060436*	COMMISSION	GLASSER, L	8101270844	PR	GREENMAN, E G	8101220546*	30-2
GARRAHY, J J	8101060436*	COMMISSION	GLEISEHAKER, B	8101140949	30-275 G	GREEN, H J	0011290376	30-3
GARRATT, P	8101200224	PR	GLIVIER, F A	8101130400*	30-267 P	GREENE, O A	8101260756	30-5

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
GREENE, S	8101130197	PS	GRIER, B H	8101050138	50-219	G	GUMBLE, F W	8101070621*	50-28
GREENMAN, S	8101237004	PR	GRIER, B H	8101050140	50-293	G	GUMBLE, F W	8101270722*	50-28
GREEN, H	8101150425	PR	GRIER, B H	8101050142	50-293	G	GUPPY, J O	8101230209	RES
GREEN, H J	8101050426	50-247	GRIER, B H	8101050144	50-220	G	GUPPY, J O	8101220061	RES
GREEN, H J	8101050715	50-259	GRIER, B H	8101050145	50-245	G	GUPPY, J O	8101220157	RES
GREEN, H J	8101070374	50-327	GRIER, B H	8101050149	50-277	G	GUPPY, J O	8101210537	50-53
GREENMAN, E	8101040024	50-271	GRIER, B H	8101160546	50-334	F	GUPPY, J O	8101210585	RES
GREEN, H J	8101090677	50-259	GRIER, B H	8101190221	70-820	G	GUPPY, J O	8101220053	RES
GREEN, D	8101130401*	50-259	GRIER, B H	8101210215	50-220	G	GUTHRIE, W H	8101220216	50-36
GREEN, H J	8101150400	50-327	GRIER, B H	8101060811	50-266	G	GUSTAVE, R P	8101050200	CONTR
GREEN, H J	8101130429	50-240	GRIER, B H	8101060516	50-272	G	GUSTAFSON, B	8101200110	PR
GREEN, H J	8101130437	50-247	GRIER, B H	8101060821	50-289	G	GUSTAVE, R P	8101140835	CONTR
GREEN, H J	8101130469	50-296	GRIER, B H	8101060824	50-412	G	GUSTAVE, R P	8101100392	CONTR
GREEN, H J	8101150490	50-240	GRIER, B H	8101060827	50-485	G	GUSTAVE, R P	8101090695	CONTR
GREEN, H J	8101160477	50-327	GRIER, B H	8101060533	50-316	G	GUSTAVE, R P	8101150217	CONTR
GREEN, H J	8101190593	50-259	GRIER, B H	8101060836	50-336	G	GUSTAVE, R P	8101150229	CONTR
GREEN, H J	8101190636	50-296	GRIER, B H	8101060830	50-263	G	GUSTAVE, R P	8101150286	CONTR
GREEN, H J	8101130409	50-249	GRIER, B H	8101060833	50-244	G	GUTHRIE, O L	8101100557	HAUSE
GREEN, H J	8101210066	50-327	GRIER, B H	8101060847	50-29	G	GUTHRIE, O L	8101220501	K. REO
GREEN, H J	8101170490	50-260	GRIER, B H	8101050649	50-443	G	GUTHRIE, O L	8101220623	NURSE
GREEN, H J	8101210449	50-327	GRIER, B H	8101060851	50-3	G	GUTIERREZ, J M	8101050532	50-57
GREEN, H J	8101220466	50-327	GRIER, B H	8101060855	50-213	G	GUTIERREZ, J M	8101290142	50-49
GREEN, H J	8101230511	50-327	GRIER, B H	8101060860	50-309	G	GUTIERREZ, J M	8101300022	50-49
GREEN, H J	8101160516	50-259	GRIER, B H	8101060870	50-317	G	GUTHRIE, R	8101220129	PR
GREEN, H J	8101220444	50-260	GRIER, B H	8101060879	50-334	G	GUTHRIE, R	8101070281	50-29
GREEN, H J	8101220525	50-327	GRIER, B H	8101160206	70-820	G	GUY, C A	8101210240	PR
GREEN, H J	8101270572	50-296	GRIER, B H	8101160410	70-820	G	GWYN, T P	8101210070*	50-35
GREEN, H J	8101270668	50-296	GRIER, B H	8101050116	50-333	G	GWYN, T P	8101290563*	50-35
GREEN, H J	8101270713	50-296	GRIER, B H	8101060123	50-352	G	HAAS, D J	8101140934	APGRTI
GREEN, H J	8101270725	50-296	GRIER, B H	8101060129	50-322	G	HAASS, W P	8101090765	DRG
GREEN, H J	8101300507	50-327	GRIER, B H	8101060131	50-273	G	HAASS, W P	8012150262*	CRG
GREEN, H J	8101300503	50-260	GRIER, B H	8101060134	50-219	G	HAASS, W P	8101090830	TOPREF
GREEN, H J	8101300511	50-276	GRIER, B H	8101060136	50-177	G	HAASS, W P	8101100020	50-41
GREEN, H J	8101300670	50-259	GRIER, B H	8101060138	50-367	G	HAASS, W P	8101190235	TEMPREP
GREEN, H J	8101300682	50-296	GRIER, B H	8101060139	50-245	G	HAASS, W P	8101280322	PR
GREEN, H J	8101300504	50-296	GRIER, B H	8101050142	50-410	G	HADDER, R		
GREEN, H J	8101300611	50-296	GRIER, B H	8101060144	50-271	G	HADDIX, K F	8101210199	PR
GREGG, I R	8101300381*	50-255	GRIER, B H	8101060145	50-354	G	HADDIX, D	8101290735	PR
GREGORY, P V	8101270131	NAREG	GRIER, B H	8101060148	50-220	G	HADLEY, K	8101270757	PR
GREGORY, W S	8101160808	LOREG	GRIER, B H	8101160101	50-309	G	HAGAN, T F	8101060313	CONTRAC
GREGORY, H E	8101290135	RES	GRIER, B H	8101070942	50-219	G	HAGAN, T F	8101090893	CONTRAC
GRIENER, F C	8101140259	PH	GRIER, B H	8101070044	50-322	G	HAGEY, H	8101100321	CONTRAC
GRIDLEY, R L	810130037	NAREG	GRIER, B H	8101070047	50-410	G	HAGEY, H	8101150205	CONTRAC
GRIER, O H	8101150155*	50-219	GRIER, B H	8101070050	50-394	G	HAGUE, R L	8101190651*	50-266
GRIER, O H	8101160846*	50-271	GRIER, B H	8101070052	50-293	G	HAIG, C	8101270449	PR
GRIER, B H	8101260782*	70-135	GRIER, B H	8101070055	50-352	G	HAIRNES, H	8101290419	50-269
GRIER, B H	8101050345	50-320	GRIER, B H	8101070358	50-387	G	HAIRFIELD, K J	8101130357	50-230
GRIER, B H	8101050397	50-206	GRIER, B H	8101070806	50-271	G	HAIRSTON, C A	8101050220	40-134
GRIER, B H	8101100335	50-293	GRIER, B H	8101070822	50-333	G	HAIRSTON, C A	8101060764	50-380
GRIER, B H	8101100340	50-317	GRIER, B H	8101070824	50-220	G	HAIRSTON, C A	8101070321	CONTRAC
GRIER, B H	8101100081	50-333	GRIER, B H	8101070866	50-245	G	HAIRSTON, C A	8101200465	CONTRAC
GRIER, B H	8101060887	50-219	GRIER, B H	8101070869	50-277	G	HAIRSTON, W O	8101090856	50-264
GRIER, B H	8101060889	50-309	GRIER, B H	8101130090	50-333	G	HAIRSTON, C	8101200348	CONTRAC
GRIER, B H	8101060890	50-334	GRIER, B H	8101130091	50-271	G	HAIRSTON, C	8101300307	CONTRAC
GRIER, B H	8101060890	50-3	GRIER, B H	8101130095	50-277	G	HAIRSTON, C	8101160080	CONTRAC
GRIER, B H	8101070740	50-213	GRIER, B H	8101130097	50-277	G	HAIRSTON, C	8101160091	CONTRAC
GRIER, B H	8101070740	50-293	GRIER, B H	8101130099	50-293	G	HAIRSTON, C	8101210572	CONTRAC
GRIER, B H	8101070771	50-317	GRIER, B H	8101130101	50-245	G	HAIRSTON, C	8101300300	CONTRAC
GRIER, B H	8101070797	50-465	GRIER, B H	8101120103	50-219	G	HAIRSTON, C	8101300285	CONTRAC
GRIER, B H	8101070795	50-443	GRIER, B H	8101120103	50-220	G	HAIRSTON, C	8101200455	CONTRAC
GRIER, O H	8101070396	50-354	GRIER, B H	8101150795	50-354	G	HAIRSTON, C	8101210037	CONTRAC
GRIER, B H	8101070398	50-352	GRIER, B H	8101150830	50-352	G	HAIRSTON, W O	8101210485*	50-354
GRIER, B H	8101070400	50-207	GRIER, B H	8101150805	50-307	G	HAIRSTON, W O	8101210521*	50-349
GRIER, B H	8101070403	50-410	GRIER, B H	8101150806	50-410	G	HAIRSTON, W O	8101200060	27-39
GRIER, B H	8101070404	50-516	GRIER, B H	8101150812	50-322	G	HAIRSTON, W O	8101130608*	50-346
GRIER, B H	8101070404	50-516	GRIER, B H	8101190358	50-244	F	HAIRSTON, W O	8101290525	CONTRAC
GRIER, B H	8101070407	50-322	GRIER, B H	8101190381	50-443	G	HAIRSTON, C	8101160105	CONTRAC
GRIER, B H	8101070409	50-363	GRIER, B H	8101210131	50-213	F	HAIRSTON, W O	8101210430*	50-348
GRIER, B H	8104070431	50-417	GRIER, B H	8101210178	PR		HAIRSTON, W O	8101200291*	50-348
GRIER, B H	8101070431	50-29	GRIER, B H	8101070782*	50-10	P	HAIRSTON, W O	8101280295*	50-348
GRIER, B H	8101070414	50-271	GRIER, B H	8101090388*	50-275	G	HAIRSTON, W O	8101220513*	50-308
GRIER, B H	8101070415	50-244	GRIER, B H	8101190248	CRG		HAIST, O P		
GRIER, B H	8101070418	50-272	GRIER, B H	8101070584*	50-209	F	HALE, C J	8101150460*	0A599
GRIER, B H	8101070419	50-333	GRIER, B H	8101200249	50-271	P	HALE, C J	8101150429*	0A599
GRIER, B H	8101070421	50-286	GRIER, B H	8101270667	50-309	P	HALE, C J	8101150851*	0A599
GRIER, B H	8101070423	50-277	GRIER, B H	8101190657	PR		HALE, C J	8101230510*	0A599
GRIER, B H	8101070425	50-245	GRIER, B H	8101070010	50-395	G	HALL, R E	8101100178*	50-442
GRIER, B H	8101070427	50-220	GRIER, B H	8101150608	50-367	G	HALL, R E	8101100269*	50-495
GRIER, B H	8101070428	50-289	GRIER, B H	8101160726	50-367	G	HALL, R E	8101120076*	50-382
GRIER, B H	8101150140	50-219	GRIER, B H	8101230091	50-155	G	HALL, R E	8101100766*	50-498
GRIER, B H	8101050118	50-352	GRIER, B H	8101260724*	50-367	G	HALL, R E	8101140556*	50-498
GRIER, B H	8101050121	50-354	GRIER, B H	8101230358	50-290	P	HALL, R E	8101210075*	50-458
GRIER, B H	8101050125	50-322	GRIER, B H	8101140555	PR		HALL, R E	8101150222	PR
GRIER, B H	8101050128	50-410	GRIER, B H	8101060534*	50-289	H	HALL, L F T	8101190247	PR
GRIER, B H	8101050130	50-387	GRIER, B H	8101230340	PR		HALL, L F T	8101300263	PR
GRIER, B H	8101050134	50-271	GRIER, B H	8101150651*	50-266	G	HALL, R E	8101090204	50-458
GRIER, B H	8101050134	50-271	GRIER, B H	8101050134	50-271	G	GRIER, B H	8101050134	50-271

HALPERMAN, H L	B101270057	50-70	C	HAYNES, R C	B101220543	50-595	O	HENDERIE, J H	B101190644	50-595	O
HALL, K	B101090865	40-6743		HAYNES, R C	B101330771	50-361	O	HENDRIE, J H	B101190657	50-595	O
HALL, D R	B101305624	RES		HAYNES, J G	B101130650	50-206	O	HENDRIE, J H	B101300376	50-595	O
HAMMETT, P	B101210234	PH		HAYNES, R C	B101270244	50-397	O	HENDRIX, B	B101150354	50-595	O
HAMMER, S H	B101140129	10CFR		HAYNES, J O	B101160564	50-206	F	HENDRICKSEN, A	B101210371	50-595	O
HANCHETT, J O	B101190120	50-275	H	HAYNES, J G	B101210372	50-206	O	HENDRIE, J H	B101100050	50-595	O
HANCHETT, J O	B101190186	50-275	H	HAYNES, J G	B101050776	50-206	V	HENDRIE, J H	B101140763	50-595	O
HANCHETT, J O	B101200209	50-275	H	HAYNES, J G	B101060750	50-206	V	HENDRICK, J F	B101260317	50-595	O
HANCOCK, J A	B101070245	RECSD		HAYNES, J	B101270511	50-206	O	HENDRIE, J H	B101200339	50-595	O
HANCOCK, J A	B101090603	50-302	B	HAYNES, J O	B101060224	50-206	O	HENRY, J J	B101160312	50-595	O
HANCOCK, J A	B101090614	50-302	S	HAYN, H	B101190161	50-275	H	HENRY, L O	B101260173	50-595	O
HANCOCK, J A	B101090590	50-302	S	HAYLE, A J	B101150099	WASTE HOT		HENRIKSEN, L E	B101140714	50-595	O
HANCOCK, J A	B1011160430	50-302	S	HAYLE, A J	B101270155	WASTE HOT		HESLER, J	B101230313	50-595	O
HANCOCK, J A	B1011160555	50-302	S	HAYLE, A J	B101270394	WASTE HOT		HETRERIAN, S	B101260153	50-595	O
HANCOCK, J A	B101190454	50-302	S	HAYLE, A J	B101270467	WASTE HOT		HERT, A R	B101080343	50-595	O
HANCOCK, J A	B101210512	50-302	B	HEAD, W J	B101230501	50-206	F	HERDT, A R	B101160410	50-595	O
HANCOCK, V J	B101230444	50-466	D	HEAD, G F	B101300398	50-424	A	HERDT, A R	B1011500773	50-595	O
HANCOCK, J A	B101230417	50-302	B	HEARNE, T J	B101270192	50-402	A	HERDT, A R	B101230368	50-595	O
HANES, D	B101270472	PR		HEARLE, T J	B101260182	50-482	C	HERDT, A R	B101140113	50-595	O
HANLEY, K	B101260594	PH		HEBERT, J A	B101220249	RES		HERIG, H	B101200501	50-595	O
HANLIER, R H	B101210590	50-395	D	HEEPAN, W H	B101120173	50-320	F	HERKENS, P H	B1011200394	50-595	O
HANNA, B	B101300467	PH		HEEPAN, W H	B101030042	PR		HERL, H, D H	B101210345	50-595	O
HANNA, B	B101090070	50-294	S	HEEDE, H	B101210094	PR		HERMAN, A	B101230165	50-595	O
HANNAH, E J	B1011160147	COMMISSION		HEELEN, S A	B101210391	PR		HERMAN, A	B101280326	50-595	O
HANNAH, E J	B1011160159	COMMISSION		HEIDER, L H	B101300652	50-271	D	HERNANDEZ, C	B101200771	50-595	O
HANNAH, E J	B1011160135	COMMISSION		HEIDER, L H	B101093089	50-271	X	HERNANDEZ, V A	B101070607	50-595	O
HANNAH, E J	B1011160172	COMMISSION		HEIDER, L H	B101090573	50-271	P	HERNANDEZ, V A	B101090682	50-595	O
HANNAH, E J	B1011160124	COMMISSION		HEIDER, L H	B101160447	50-271	F	HERNANDEZ, V A	B101070597	50-595	O
HANNAH, E J	B101290405	10CFR		HEIDER, L H	B101300315	50-271	P	HERNANDEZ, V A	B101160636	50-595	O
HANNAH, E J	B101290675	50-311	T	HEIDER, L H	B101300487	50-271	P	HERNANDEZ, V A	B101190454	50-595	O
HANSEN, L E	B101200007	71-9070		HEIKAN, W J	B101150130	50-271	H	HERNANDEZ, V A	B101230455	50-595	O
HANSEN, W A	B101220516	50-400	O	HEIMAN, D	B101190756	XPORTRIC		HEIR, R K	B101080509	50-595	O
HANSEN, L E	B1011140139	XPORTRIC		HEINERMAN, J M	B101270452	50-250	P	HEIRICK, R H	B101200537	50-595	O
HANSEN, L J	B101200016	71-9145		HEINERMAN, J M	B101300408	50-261	O	HEISCH, H H	B101090429	50-595	O
HANSEN, L J	B101270143	71-9111		HEISERMAN, R F	B101160340	50-235	O	HEISS, P W	B101070029	50-595	O
HANSEN, L J	B101270133	71-9145		HEISHMAN, R F	B101100202	50-205	O	HEISS, H A	B101120292	50-595	O
HANSEN, L J	B101270137	71-9145		HEISHMAN, R F	B101130574	50-273	O	HEYER, R S	B101060146	50-595	O
HANSEN, C M	B101060909	50-352	H	HEISHMAN, R F	B101120066	50-258	O	HEYER, P S	B101200597	50-595	O
HARDT, D	B101080442	50-466	O	HEISHMAN, R F	B101160152	50-304	O	HICKER, C R	B101140574	50-595	O
HARDY, M P	B101190134	FOIA		HEISHMAN, R F	B101070170	50-255	O	HICKMAN, J W	B101270126	50-595	O
HARDY, H P	B101150127	FOIA		HEISHMAN, R F	B101120019	50-315	O	HICKMAN, J W	B101270126	50-595	O
HARLAN, H F	B101160008	PR		HEISHMAN, R F	B101140524	50-305	O	HICKMAN, J W	B101270126	50-595	O
HARMON, H W	B101120020	XPORTRIC		HEISHMAN, R F	B101300740	50-266	S	HICKMAN, J W	B101270126	50-595	O
HARMON, D W	B101140010	XPORTRIC		HEISHMAN, R F	B101080079	50-254	O	HICKMAN, J W	B101270126	50-595	O
HARMON, D	B101160210	XPORTRIC		HEISHMAN, R F	B101140072	50-275	O	HICKMAN, J W	B101270126	50-595	O
HARRAH, G	B101200277	50-245	R	HEISHMAN, R F	B101090770	50-10	O	HICKMAN, J W	B101270126	50-595	O
HARRISON, J	B101190197	50-247	H	HEISHMAN, R F	B101140504	50-263	O	HICKMAN, J W	B101270126	50-595	O
HARRISON, J	B101190202	50-247	H	HEISHMAN, R F	B101090160	50-235	O	HICKMAN, J W	B101270126	50-595	O
HARRISON, J	B101190207	50-247	H	HEISHMAN, R F	B101090234	50-234	O	HICKMAN, J W	B101270126	50-595	O
HARRISON, J	B101190214	50-247	H	HEISHMAN, R F	B101160181	50-266	O	HICKMAN, J W	B101270126	50-595	O
HARRISON, J J	B101100378	50-546	O	HEISHMAN, R F	B101100153	50-205	O	HICKMAN, J W	B101270126	50-595	O
HARRISON, J J	B101060306	50-546	O	HEISHMAN, R F	B101150646	50-266	O	HICKMAN, J W	B101270126	50-595	O
HARRIS, J R	B101160064	50-413	O	HEISHMAN, R F	B101160774	50-151	O	HICKMAN, J W	B101270126	50-595	O
HARRISON, J J	B101290166	50-546	O	HEISHMAN, R F	B101160368	50-151	O	HICKMAN, J W	B101270126	50-595	O
HARRISON, P	B101060546	50-220	S	HEISHMAN, R F	B101150658	50-373	O	HICKMAN, J W	B101270126	50-595	O
HARRISON, P	B101070504	50-220	S	HEISHMAN, R F	B101150654	50-373	O	HICKMAN, J W	B101270126	50-595	O
HARRINGTON, W F	B101070522	50-266	F	HEISHMAN, R F	B101210641	50-409	O	HICKMAN, J W	B101270126	50-595	O
HARRISON, P	B101120069	50-220	S	HEISHMAN, R F	B101290444	50-331	O	HICKMAN, J W	B101270126	50-595	O
HARRISON, P	B101130694	50-220	S	HEISHMAN, R F	B101210640	50-409	O	HICKMAN, J W	B101270126	50-595	O
HARRINGTON, W F	B101300466	50-266	F	HEISHMAN, R F	B101290558	50-358	O	HICKMAN, J W	B101270126	50-595	O
HART, R	B101200321	PR		HEISHMAN, R F	B101300780	50-155	O	HICKMAN, J W	B101270126	50-595	O
HART, P	B101270528	WASTE HOT		HEISHMAN, R F	B101300791	50-155	O	HICKMAN, J W	B101270126	50-595	O
HARTMAN, A	B101260336	PR		HEISHMAN, R F	B101210651	50-346	O	HICKMAN, J W	B101270126	50-595	O
HARTMAN, C J	B101130229	50-159	R	HEISHMAN, R F	B101290458	50-255	O	HICKMAN, J W	B101270126	50-595	O
HARTUNO, L	B101280033	WASTE HOT		HEISHMAN, R F	B101290567	50-202	O	HICKMAN, J W	B101270126	50-595	O
HARTZMAN, H	B101220626	RES		HEISHMAN, R F	B101210650	50-346	O	HICKMAN, J W	B101270126	50-595	O
HARTZLER, E	B101220136	PR		HEISHMAN, R F	B101390275	50-262	O	HICKMAN, J W	B101270126	50-595	O
HARVEY, N	B101300552	PR		HEISHMAN, R F	B101210645	50-246	O	HICKMAN, J W	B101270126	50-595	O
HARWOOD, R	B101050345	50-304	S	HEISHMAN, R F	B101300743	50-266	S	HICKMAN, J W	B101270126	50-595	O
HASLAM, E F	B101200640	QA999		HEISHMAN, R F	B101210242	50-315	P	HICKMAN, J W	B101270126	50-595	O
HASSELL, D F	B101280402	50-247	P	HEISHMAN, R F	B101210625	50-358	A	HICKMAN, J W	B101270126	50-595	O
HASTINOS, E	B101230247	PR		HEISHMAN, R F	B101220190	50-255	O	HICKMAN, J W	B101270126	50-595	O
HASTINOS, E H	B101290645	PR		HEISHMAN, R F	B101300551	50-246	O	HICKMAN, J W	B101270126	50-595	O
HAWLAND, P E	B101050267	50-202	P	HEISHMAN, R F	B101300556	50-246	O	HICKMAN, J W	B101270126	50-595	O
HAWKAMP, D	B101280524	50-289	S	HEISHMAN, R F	B101300556	50-246	O	HICKMAN, J W	B101270126	50-595	O
HAWKAMP, D R	B101280507	50-289	S	HEISLER, H	B101130207	PR		HICKMAN, J W	B101270126	50-595	O
HAWLAND, H	B101260348	PR		HEISLER, J K	B101070181	50-255	O	HICKMAN, J W	B101270126	50-595	O
HAWKINS, F C	B101210104	50-546	O	HELLER, J K	B101290432	50-255	O	HICKMAN, J W	B101270126	50-595	O
HAWKINS, E F	B101150876	MISC		HELM, K	B101100509	XPORTRIC		HICKMAN, J W	B101270126	50-595	O
HAYES, D W	B101140151	50-461	O	HENDERSON, T K	B101120296	50-29	P	HICKMAN, J W	B101270126	50-595	O

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER
HOFFMAN, D P	0101080114	50-155 Q	HOVEY, G K	0101216340	50-320 P	HUNTER, R S	0101190512
HOFFMAN, D P	0101090134	50-155 J	HOVEY, G K	0101230534	50-320 P	HUNTER, R S	0101280510
HOFFMAN, D P	0101100253	50-255 Q	HOVEY, G K	0101230613	50-320 P	HUNTER, R S	0101230529
HOFFMAN, D P	0101110007	50-255 Q	HOVEY, G K	0101230597	50-320 S	HUNTER, R S	0101260579
HOFFMAN, D P	0101200209	50-255 Q	HOVEY, G K	0101270637	50-320 S	HUNTER, R S	0101270579
HOFFMAN, D P	0101290083	50-155 Q	HOVEY, G K	0101290492	50-320 P	HUNTER, R S	0101300494
HOFFMAN, D P	0101050576	50-155 F	HOWE, J	0101190317	PR	HURBT, J	0101260613
HOFFMAN, D P	0101210209	50-155 Q	HOWELL, S H	0101220198	REGED	HUSEBY, D	0101130615
HOFFMAN, D P	0101270654	50-155 Q	HOWELL, R H	0101090631	50-307 Q	HUSEBY, D F	0101230540
HOFFMAN, D P	0101200574	50-155 Q	HUBER, J	0101150207	PR	IACODELL, F	0101070297
HOFFMAN, D P	0101260730	50-255 F	HOWETT, O H	0101273941	50-326 R	IAHURNO, H	0101190670
HOFFMAN, D P	0101140316	50-255 P	HOYLE, J C	0101300770	50-302 Q	IOEKER, K	0101140595
HOFFMAN, D P	0101260339	50-155 S	HOYLE, J C	0101300770	ACRS	IFFLAND, R R	0101260296
HOFFMAN, D P	0101130416	50-255 P	HOYLE, J C	0101300781	ACRS	IFFLAND, R R	0101260303
HOFFMAN, D P	0101130518	50-155 S	HOYLE, J C	0101300793	ACRS	IFFLAND, R P	0101270736
HOFFMAN, D P	0101120310	50-255 P	HOYLE, J C	0101300804	ACRS	IFFLAND, R R	0101270744
HOFFMAN, D P	0101220395	50-255 Q	HOYLE, J C	0101300858	ACRS	IMBODEN, E	0101200160
HOFFMAN, D P	0101120284	50-155 P	HOYLE, J C	0101300808	ACRS	IMRO, E V	0101150366
HOFFMAN, D P	0101110136	50-155 P	HOYLE, J C	0101300860	50-209 Q	IMRO, E V	0101160175
HOFFMAN, D P	0101210415	50-155 S	HOYLE, J C	0101300767	ACRS	IMPRESCIA, R J	0101210278
HOFFMAN, D P	0101200104	50-255 R	HOYLE, J C	0101300840	ACRS	INGRAM, F L	0101120191
HOFFMAN, D P	0101220234	50-155 P	HOYLE, J C	0101300765	50-209 Q	INNERE, A H	0101190502
HOFFMAN, D P	0101230530	50-255 S	HOYLE, J C	0101300775	ACRS	IPPOLITO, T A	0101100336
HOFFMAN, D P	0101230477	50-255 S	HOYLE, J C	0101300633	ACRS	IPPOLITO, T A	0101050474
HOFFMAN, D P	0101230533	50-155 S	HOYLE, A	0101060787	CONTRACT	IPPOLITO, T A	0101100630
HOFFMAN, D P	0101270273	50-155 P	HOYLE, A E	0101200426	CONTRACT	IPPOLITO, T A	0101120273
HOFFMAN, D P	0101280073	50-155 P	HOYLE, J C	0101200382	50-395 M	IPPOLITO, T A	0101100022
HOFFMAN, D P	0101270231	50-155 Q	HOU, Y Y	0101120359	NUREO	IPPOLITO, T A	0101070166
HOFFMAN, D P	0101290358	50-155 P	HUBBARD, H W	0101140556	50-498 Q	IPPOLITO, T A	0101070162
HOFFMAN, D P	0101270523	50-155 S	HUBBARD, H W	0101280403	50-498 S	IPPOLITO, T A	0101120278
HOFFMAN, A	0101150173	PR	HUBBARD, H W	0101130274	PR	IPPOLITO, T A	0101120279
HOLAN, K	0101230253	PR	HUBBARD, H W	0101130267	PR	IPPOLITO, T A	0101120283
HOLEMAN, R D	0101080189	50-332 Q	HUBBARD, H W	0101130335	PR	IPPOLITO, T A	0101090096
HOLEWAY, F	0101140332	PR	HUBSON, S	0101100154	50-271 Q	IPPOLITO, T A	0101100712
HOLLAND, D	0101300200	PR	HUBSON, S	0101220450	50-220 Q	IPPOLITO, T A	0101100717
HOLLAND, D	0101060617	50-237 S	HUBSON, O D	0101160334	50-263 F	IPPOLITO, T A	0101100731
HOLLIDAY, D	0101130274	PR	HUBSON, T B	0101280585	50-498 Q	IPPOLITO, T A	0101210532
HOLLWAY, C J	0101240002	50-452 A	HUBSON, T B	0101280585	50-498 Q	IPPOLITO, T A	0101210539
HOLLWAY, C J	0101240009	50-580 A	HUBSON, T B	0101230192	50-498 Q	IPPOLITO, T A	0101210550
HOLLWAY, C J	0101210031	50-592 A	HUBSON, T B	0101230198	50-498 Q	IPPOLITO, T A	0101210236
HOLLWAY, D	0101120301	REGED	HUBSON, T B	0101280577	50-498 Q	IPPOLITO, T A	0101210543
HOLLIES, E	0101200173	PR	HUBSON, T B	0101230158	50-498 Q	IPPOLITO, T A	0101210571
HOLMES, J L	0101270572	PR	HUBSON, T B	0101280577	50-498 Q	IPPOLITO, T A	0101230451
HOLMES, M S	0101140457	50-280 F	HUBTEL, J G	0101290193	RES	IPPOLITO, T A	0101290033
HOLDRY, D	0101300196	70-135	HUTER, L J	0101230010	50-155 Q	IPPOLITO, T A	0101290400
HOLWAY, C F	0101220280	RES	HUTER, L J	0101150019	50-341 Q	IPPOLITO, T A	0101290525
HOLWAY, C F	0101220643	RES	HUGHES, J	0101080284	50-440 Q	IPPOLITO, T A	0101230603
HOLWAY, C F	0101290182	RES	HUGHES, J	0101150213	PR	IPPOLITO, T A	0101190393
HOLT, R R	0101280376	50-247 P	HUGHES, J	0101270471	50-440 Q	IPPOLITO, T A	0101300691
HOLT, J	0101300556	PR	HUKILL, H D	0101060632	50-289 Q	IPPOLITO, T A	0101300233
HOLT, J	0101270047	50-247 Q	HUKILL, H D	0101080103	50-289 Q	IPPOLITO, T A	0101300358
HOLT, P P	0101090445	NUREO	HUKILL, H D	0101140581	50-289 Q	IPPOLITO, T A	0101300379
HORN, A L	0101120349	NUREO	HUKILL, H D	0101140580	50-289 Q	IPPOLITO, T A	0101300386
HOCO, D	0101120243	50-329 A	HUKILL, H D	0101090133	50-289 T	IPPOLITO, T A	0101300396
HOCO, D	0101100740	50-329 A	HUKILL, H D	0101050238	50-289 S	IPPOLITO, T A	0101300402
HOCO, D	0101100722	50-329 A	HUKILL, H D	0101290652	50-289 F	IPPOLITO, T A	0101300417
HOCO, D	0101140815	50-329 A	HUKILL, H D	0101060405	50-289 F	IPPOLITO, T A	0101300753
HOPKINS, B	0101120034	50-315 Q	HUKILL, H D	0101230312	50-289 P	IPPOLITO, T A	0101300646
HOPKINS, B J	0101150271	PR	HUKILL, H D	0101210379	50-289 P	IPPOLITO, T A	0101200271
HOPKINS, T R	0101200222	PR	HUKILL, H D	0101210374	50-289 Q	IRELAND, J H	0101220250
HORAK, W C	0101216505	RES	HUKILL, H D	0101210587	50-209 P	IRELAND, J H	0101220332
HORIN, W A	0101050470	50-445 Q	HUKILL, H D	0101210677	50-289 R	IRWIN, M	0101260462
HORIN, W A	0101050478	50-445 Q	HUKILL, H D	0101260507	50-289 P	IRWIN, M	0101260583
HORIN, W A	0101160233	50-445 Q	HUKILL, H D	0101270592	50-289 P	IRWIN, O	0101230284
HORIN, W A	0101160233	50-445 Q	HUKILL, H D	0101270605	50-289 Q	IRWIN, O P	0101270305
HORN, R	0101220157	PR	HUKILL, H D	0101270648	50-289 P	IRWIN, B	0101290505
HORNWITZ, J	0101230621	PR	HUKILL, H D	0101270674	50-289 P	IRWIN, D F	0101270315
HOSFORD, S B	0101290632	NUREO	HUKILL, H D	0101270721	50-289 S	ISHERWOOD, D	0101300229
HOSMER, R P	0101070485	REGED	HUKILL, H D	0101290657	50-289 P	ISLEY, T	0101060705
HOSSLER, D	0101190136	PR	HUKILL, H D	0101290652	50-289 P	ISLEY, T	0101060745
HOUSE, B R	0101160142	COMMISSION	HUKILL, H D	0101290755	50-289 P	ISLEY, T	0101060757
HOUSTON, H O	0101140944	NUREO	HUKILL, H D	0101070244	50-285 Q	ISOLA, S C	0101200161
HOVEY, O K	0101050071	50-320 H	HUNNICUTT, D M	0101100236	50-313 Q	ISRAEL, B	0101200389
HOVEY, O K	0101140760	50-320 Q	HUNNICUTT, D M	0101120277	50-282 R	JABLON, R A	0101090340
HOVEY, O K	0101140662	50-320 S	HUNSTAD, A A	0101270658	50-282 S	JABLON, R A	0101090360
HOVEY, O K	0101140730	50-320 Q	HUNSTAD, A A	0101260561	PR	JABLON, R A	0101090360
HOVEY, O K	0101050079	50-289 P	HUNTER, D R	0101150195	50-219 Q	JACKMAN, T J	0101260375
HOVEY, O K	0101050084	50-320 H	HUNTER, V H	0101260054	0A999	JACKMAN, T J	0101300151
HOVEY, O K	0101050174	50-320 S	HUNTER, R S	0101140146	PR	JACKSON, T J	0101300740
HOVEY, G K	0101050419	50-320 S	HUNTER, R S	0101120263	50-315 Q	JACKSON, R	0101190712
HOVEY, G K	0101140650	50-320 S	HUNTER, R S	0101120315	50-315 Q	JACKSON, J L	0101300217
HOVEY, O K	0101190344	50-320 V	HUNTER, R S	0101090461	50-315 F	JACOBY, M S	0101060104
HOVEY, G K	0101230573	50-320 P	HUNTER, R S	0101130217	50-315 P	JACOBS, A H	0101230387
HOVEY, O K	0101190482	50-320 S					
HOVEY, G K	0101210541	50-320 P					

PERSONAL ACTION INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JACOBS, A	8101210374	CONTRACT	JACOB, W. C.	8101140512	50-285 P	KERLUSEK, S	8101160025	50-
JAHNSEN, L.	8101210564	PR	JACOB, W. C.	8101150616*	50-285 P	KERLUSEK, S	8101290485	50-
JANECEK, R. F.	8101300577*	50-254 Q	JONES, J. L.	8101216516*	50-287 S	KERNERT, D.	8101390034*	50-
JANECEK, R. F.	8101080093	50-237 D	JONES, J. L.	8101216507*	50-269 S	KERINIO, R. R.	8101150546*	50-
JANECEK, R. F.	8101060376	50-237 P	JONES, J. L.	8101300432	State Pres	KERINIO, R.	8101280124	50-
JANECEK, R. F.	8101050566	50-265 P	JONES, J. L.	8101230491*	50-269 S	KERINIO, R.	8101280093	50-
JANECEK, R. F.	8101080144	50-10 P	JONES, J. L.	8101230164	50-329 G	KERINIO, R. S.	8101050546*	50-
JANECEK, R. F.	8101120155	50-254 R	JONES, J. L.	8101270630*	50-270 S	KERINIO, R. S.	8101060795*	50-
JANECEK, R. F.	8101200135	50-237 D	JONES, J. L.	8101270650*	50-287 S	KERINIO, R. S.	8101210451*	50-
JANECEK, R. F.	8101200196	50-237 P	JONES, W. L.	8101300513	50-285 S	KELLEY, C.	8101260141*	50-
JANECEK, H. E.	8101260482	50-237 P	JORDAN, B. W.	8101280693	50-329 G	KELLER, J. H.	8101120791	RES
JANECEK, R. F.	8101260597	50-10 P	JORDAN, A. L.	8101070577	PR	KELLER, B. E.	8101070151	50-
JANECEK, R. F.	8101270661	50-10 P	JORDAN, M. J.	8101070785*	50-10 Q	KELLEY, D. L.	8101070744*	50-
JANECEK, R. F.	8101270481	50-237 P	JORDAN, E. L.	8101160403	TOPREP	KELLER, J. J.	8101230170	PR
JANINEK, M.	8101270056	State Pres	JORDAN, W. S.	8101070513	50-443 U	KELLER, A. C.	8101290550	PR
JANIS, M.	8101090155	50-289 U	JORDAN, W. S.	8101070513	50-443 Q	KELLEY, R. H.	8101090650*	10-
JANOFF, D.	8101230006	PR	JORDAN, W. S.	8101090636	50-443 G	KELLOGG, P. J.	8101080648*	50-
JAKULESKI, H.	8101300544	PR	JORDAN, W. S.	8101090636	50-443 G	KELLOGG, P. J.	8101060706*	50-
JAKUSKA, A. O.	8101090114*	50-255 Q	JORDAN, E. L.	810127072*	50-262 S	KELLOGG, P. J.	8101160666*	50-
JAKUSKA, A. O.	8101070125*	50-10 Q	JORGENSEN, B. L.	8101070181*	50-255 Q	KELLY, W. D.	8101190782*	049
JAKE, F.	8101150195*	50-219 D	JORGENSEN, B. L.	8101290432*	50-255 Q	KELLY, W. D.	8101210262*	049
JAKE, F.	8101080177*	50-269 D	JOST, J. H.	8101260011	PR	KELLY, J. A.	8101100600*	50-
JARNEY, L.	8101300505	PR	JOV, J. H.	8101210489*	50-206 R	KELLY, J. A.	8101070214	50-
JEAN-PIERRE, L.	8101160414	PR	JAYCE, P.	8101130338	PR	KELLY, J. A.	8101100374*	50-
JENKINS, G. R.	8101080210*	50-250 Q	JAYCE, M.	8101130347	PR	KELLY, J. A.	8101100305	50-
JENKINS, H.	8101200163	PR	JBYNER, J. H.	8101060747*	70-1100	KELLY, F. L.	8101030123*	50-
JENKINS, D.	8101140603	PR	JBYNER, J. H.	8101290758*	70-620	KEMP, R. L.	8101220439	PR
JENKINS, G. R.	8101290549*	50-518 D	JBYNER, J. H.	8101300196*	70-135	KEPPER, J. S.	8101210210	50-
JENS, W. H.	8101090172*	FOIA	JBYNER, J. H.	8101230523*	70-820	KEPPER, J. S.	8101230434	50-
JENS, W. H.	8101070791*	PR	JBYNER, J. H.	8101220357*	50-280 P	KEPPER, T. B.	8101260590	50-
JENSEN, S. E.	8101050096	TOPREP	JULIAN, C.	8101090049*	50-327 G	KEMFENICH, R.	8101220482*	PR
JEROLD, H. D.	8101220269*	50-393 A	JULIAN, D.	8101300159	PR	KEMFENICH, J. E.	8101070369	50-
JERGEN, R. J.	8101290626*	70-2529	JURUSKA, A. G.	8101150640*	50-295 D	KENALL, G.	8101130286	PR
JERGEN, R. J.	8101220371	PR	KADAM, H.	8101210646	PR	KENISTON, J.	8101190022	PR
JERMAN, P. C.	8101280513	ISE	KAHLE, J. B.	8101060695*	70-143	KENNA, W. B.	8101060691*	70-
JETT, O. H.	8101140449*	50-284 Q	KAHLE, J. B.	8101070802*	50-332 Q	KENNA, W. B.	8101090740	50-
JOE, R. W.	8101160226	50-259 C	KAHLE, J. B.	8101200144*	70-1191	KENNA, W. B.	8101100707*	50-
JOHN, J. R.	8101130400	50-267 P	KAHLE, J. B.	8101090621*	70-143	KENNA, W. B.	8101260137*	70-
JOHN, J. R.	8101230187	50-267 R	KAHLE, J. B.	8101100820*	50-261 D	KENNA, W. B.	8101090821*	50-
JOHNSEN, I. O.	8101060038	ACRB	KAHLE, J. B.	8101050575*	70-1151	KELNA, W. B.	8101100618	70-
JOHNSON, W. D.	8101100276*	50-313 D	KAMI, J. R.	8101060730	FOIA	KENNA, W. B.	8101050594	70-
JOHNSON, J. M.	8101130851*	04999	KAM, S.	8101260059	PR	KENNA, W. B.	8101290381	50-
JOHNSON, A. R.	8101120609*	50-382 Q	KAIN, A.	8101200593	PR	KENNA, W. B.	8101060279	70-
JOHNSON, J. M.	8101230910*	04999	KATSER, W. T.	8101270526*	50-348 P	KENNA, W. B.	8101050231	70-
JOHNSON, C. R.	8101100160	71-6698	KATSER, W. T.	8101160476*	50-206 P	KENNA, W. B.	8101100645	50-
JOHNSON, G. F. J.	8101190459	PR	KATSER, B.	8101190446	PR	KENNA, W. B.	8101220671	50-
JOHNSON, A. J.	8101260717	PR	KALDANI, J.	8101300216	PR	KENNEDY, D. H.	8101130243	50-
JOHNSON, A. J.	8101060087*	50-312 Q	KALIVIANAKIS, N.	8101250754	50-234 S	KENYON, T. J.	8101090568	50-
JOHNSON, A. D.	8101210130*	50-89 Q	KALIVIANAKIS, N.	8101090654	50-234 S	KENYON, T. J.	8101290197	50-
JOHNSON, J. H.	8101090321	50-289 Q	KALIVIANAKIS, N.	8101030390	50-234 S	KENYON, T. J.	8101070408	50-
JOHNSON, J. H.	8101090330*	50-289 Q	KALIVIANAKIS, N.	8101060472	50-263 S	KEOSTER, O. L.	8101070431	50-
JOHNSON, T. C.	8101270580	50-289 P	KALIVIANAKIS, N.	8101060466	50-263 S	KEPPLER, J. O.	8101090137*	FOIA
JOHNSON, V. V.	8101270444	50-287 P	KALIVIANAKIS, N.	8101130558	50-263 S	KEPPLER, J. O.	8101050161*	50-
JOHNSON, J. H.	8101230635	50-209 Q	KALIVIANAKIS, N.	8101200302	50-294 R	KEPPLER, J. O.	8101050206	50-
JOHNSON, J. H.	8101270290	50-387 Q	KALIVIANAKIS, N.	8101210463	50-294 R	KEPPLER, J. O.	8101050207	50-
JOHNSTON, N. V.	8101200385	50-369 Q	KALIVIANAKIS, N.	8101270763	50-254 S	KEPPLER, J. O.	8101050214	50-
JOHNSON, J.	8101270436*	50-346 S	KALIVIANAKIS, N.	8101270740	50-263 S	KEPPLER, J. O.	8101030210	50-
JOHNSON, R. L.	8101270920	WASTE MOT	KALISHILAK, J. H.	8101260468*	50-321 R	KEPPLER, J. O.	8101050575	50-
JOHNSON, W. C.	8101140182	50-285 Q	KALISHILAK, J. H.	8101260527*	50-366 R	KEPPLER, J. O.	8101050232	50-
JOHNSON, W. C.	8101120161	50-203 Q	KALISHILAK, J. H.	8101280197*	50-321 R	KEPPLER, J. O.	8101030239	50-
JOHNSON, W. C.	8101160403	50-285 Q	KAMMERER, C.	8101090019	50-289 U	KEPPLER, J. O.	8101050244	50-
JOHNSON, W. C.	8101120072	50-285 Q	KANDAKAR, R.	8101160505	PR	KEPPLER, J. O.	8101050439	50-
JOHNSON, W. C.	8101120131	50-203 Q	KANE, H.	8101100034	50-382 F	KEPPLER, J. O.	8101050266	50-
JOHNSON, W. C.	8101160542	50-285 Q	KANE, W.	8101140473	50-382 F	KEPPLER, J. O.	8101050270	50-
JOHNSON, W. C.	8101120048	50-203 D	KANE, W.	8101270219	50-395 A	KEPPLER, J. O.	8101050274	50-
JOHNSON, J.	8101300184	PR	KAPLAN, A. L.	81012100316*	70-1113	KEPPLER, J. O.	8101050279	50-
JOHNSON, A.	8101290695	PR	KAPLAN, M.	8101160372	PR	KEPPLER, J. O.	8101050283	50-
JOHNSON, K. H.	8101290709	PR	KAPLAN, A. L.	8101220936	71-4906	KEPPLER, J. O.	8101050287	50-
JOHNSON, L.	8101190142	FOIA	KAPSALES, J.	8101060105	REGD	KEPPLER, J. O.	8101050289	50-
JOHNSON, T.	8101300472	PR	KARLAN, H.	8101260510	50-482 G	KEPPLER, J. O.	8101060109	50-
JOHNSON, D. H.	8101050579*	70-1151	KARMAN, M.	8101260512	50-482 Q	KEPPLER, J. O.	8101060110	50-
JOHNSON, R. K.	8101290649	WASTE MOT	KARMAN, M.	8101280124	50-482 Q	KEPPLER, J. O.	8101060110	50-
JOHNSON, W. C.	8101060761	50-285 S	KATZ, K.	8101260721	PR	KEPPLER, J. O.	8101060129	50-
JOHNSON, A.	8101160559	PR	KAUFMAN, H. C.	8101090062	LUREO	KEPPLER, J. O.	8101060527	50-
JOHNSON, J.	8101160376	PR	KAUFMAN, M.	8101160558	PR	KEPPLER, J. O.	8101060527	50-
JOHNSON, W. C.	8101120300	50-285 S	KAUFMAN, H. C.	8101300845	RES	KEPPLER, J. O.	8101060534	50-
JOHNSON, W. C.	8101130358	50-203 S	KAY, J. A.	8101070383	50-29 P	KEPPLER, J. O.	8101060537	50-
JOHNSON, J. L.	8101080335*	50-287 S	KAY, J. A.	8101140361	50-29 P	KEPPLER, J. O.	8101060547	50-
JOHNSON, J. A.	8101090323	50-400 A	KAY, J. A.	81011120293	50-29 P	KEPPLER, J. O.	8101060548	50-
JOHNSON, H. A.	8101070349	50-285 P	KAY, J. A.	8101130130	50-29 P	KEPPLER, J. O.	8101060552	50-
JOHNSON, J. L.	8101090666*	50-287 S	KAY, J. A.	8101140664	50-29 P	KEPPLER, J. O.	8101060640	50-
JOHNSON, W. C.	8101130373	50-285 P	KAY, J. A.	8101270362	50-29 P	KEPPLER, J. O.	8101060650	50-
JOHNSON, W. C.	8101160485	50-203 R	KAY, J. A.	8101270652	50-29 P	KEPPLER, J. O.	8101060654	50-
JOHNSON, B. W.	8101120515	50-329 Q	KAY, J. A.	8101300681	50-29 P	KEPPLER, J. O.	8101060658	50-
JOHNSON, J. L.	8101300578*	50-270 S	KEATON, R. W.	8101270361*	50-289 T	KEPPLER, J. O.	8101060662*	50-

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER
KEPPLER, J G	810105045	50-367	KEPPLER, J G	810105041	50-341	KINNEY, W H	81010504
KEPPLER, J G	810105046	50-345	KEPPLER, J G	810105046	50-331	KINNEHAN, J D	81011300
KEPPLER, J G	810105047	50-453	KEPPLER, J G	810105048	50-367	KINNEHAN, J D	81011900
KEPPLER, J G	810105049	50-135	KEPPLER, J G	810105049	50-461	KINNEHAN, J D	81012800
KEPPLER, J G	810105049	50-262	KEPPLER, J G	810105049	50-440	KINTNER, L L	81011400
KEPPLER, J G	810105045	50-315	KEPPLER, J G	810105050	50-10	KINTNER, L L	81011600
KEPPLER, J G	810105047	50-155	KEPPLER, J G	810105050	50-155	KINTNER, L L	81012700
KEPPLER, J G	810105048	50-10	KEPPLER, J G	810105050	50-150	KINTNER, L L	81012100
KEPPLER, J G	810105047	50-437	KEPPLER, J G	810105051	50-155	KINTNER, L L	81012700
KEPPLER, J G	810105049	50-545	KEPPLER, J G	810105051	50-231	KINTNER, L L	81012900
KEPPLER, J G	810105047	50-367	KEPPLER, J G	810105051	50-461	KINTNER, L L	81013000
KEPPLER, J G	810105048	50-345	KEPPLER, J G	810105052	50-341	KINTNER, L L	81013000
KEPPLER, J G	810105048	50-365	KEPPLER, J G	810105053	50-267	KIRK, W F	81012100
KEPPLER, J G	810105049	50-463	KEPPLER, J G	810105053	50-373	KIRK, O B	80112500
KEPPLER, J G	810105049	50-461	KEPPLER, J G	810105053	50-10	KIRK, N F	01012900
KEPPLER, J G	810105049	50-324	KEPPLER, J G	810105054	50-440	KIRK, O B	81012200
KEPPLER, J G	810105049	50-263	KEPPLER, J G	810105054	50-263	KIRK, O B	01012200
KEPPLER, J G	810105049	50-461	KEPPLER, J G	810105054	50-350	KIRK, O B	81012500
KEPPLER, J G	810105049	50-367	KEPPLER, J G	810105054	50-329	KIRKPATRICK, R	01013000
KEPPLER, J G	810105049	50-155	KEPPLER, J G	810105054	50-10	KIRSCH, O F	81013000
KEPPLER, J G	810105049	50-469	KEPPLER, J G	810105054	50-155	KIRSCH, D F	01012100
KEPPLER, J G	810105049	50-545	KEPPLER, J G	810105054	50-409	KISTER, H D	81012200
KEPPLER, J G	810105049	50-463	KEPPLER, J G	810105054	50-773	KISTER, H D	81011900
KEPPLER, J G	810105049	50-305	KEPPLER, J G	810105054	50-263	KISTER, H D	81012000
KEPPLER, J G	810105049	50-155	KEPPLER, J G	810105054	50-241	KISTER, H D	81012600
KEPPLER, J G	810105050	50-515	KEPPLER, J G	810105054	50-351	KLEBANOW, A	81012300
KEPPLER, J G	810105050	50-353	KEPPLER, J G	810105054	50-373	KLEEN, N	81012100
KEPPLER, J G	810105050	50-367	KEPPLER, J G	810105054	50-440	KLEIN, GORGE, W	01010900
KEPPLER, J G	810105050	50-263	KEPPLER, J G	810105054	50-358	KLEIN, SMITH, R	81012900
KEPPLER, J G	810105050	50-329	KEPPLER, J G	810105054	50-367	KLOPE, A	81012100
KEPPLER, J G	810105050	50-461	KEPPLER, J G	810105054	50-346	KLUWER, M	81012000
KEPPLER, J G	810105050	50-545	KEPPLER, J G	810105054	70-2249	KNAPP, P J	01012200
KEPPLER, J G	810105050	50-305	KEPPLER, J G	810105054	50-249	KNAPP, P J	81013000
KEPPLER, J G	810105050	50-463	KEPPLER, J G	810105054	50-350	KNAPP, P J	01011600
KEPPLER, J G	810105050	50-409	KEPPLER, J G	810105054	50-746	KNICELY, J	81013000
KEPPLER, J G	810105050	50-305	KEPPLER, J G	810105054	50-315	KNICELEY, J R	81011300
KEPPLER, J G	810105050	50-409	KEPPLER, J G	810105054	50-454	KNIEP, R A	81010500
KEPPLER, J G	810105050	50-358	KEPPLER, J G	810105054	50-249	KNIGHTON, O W	79040400
KEPPLER, J G	810105050	50-155	KEPPLER, J G	810105054	50-263	KNIGHT, J	01010700
KEPPLER, J G	810105050	50-305	KEPPLER, J G	810105054	50-358	KNIGHTON, O W	80050600
KEPPLER, J G	810105050	50-462	KEPPLER, J G	810105054	50-255	KNOP, R C	81011000
KEPPLER, J G	810105050	50-545	KEPPLER, J G	810105054	50-255	KNOP, R C	81010700
KEPPLER, J G	810105050	50-315	KEPPLER, J G	810105054	50-373	KNOP, R C	01011000
KEPPLER, J G	810105050	50-267	KEPPLER, J G	810105054	50-241	KNOP, R C	01011000
KEPPLER, J G	810105050	50-461	KEPPLER, J G	810105054	50-454	KNOP, R C	81012200
KEPPLER, J G	810105050	50-305	KERR, O W	810105054	State Prog	KNOP, R C	01012100
KEPPLER, J G	810105050	50-266	KERR, O W	810105054	State Prog	KNOP, R C	81012000
KEPPLER, J G	810105050	50-255	KERR, O W	810105054	State Prog	KNOP, R C	81012000
KEPPLER, J G	810105050	50-254	KERR, O W	810105054	State Prog	KNOP, R C	81012000
KEPPLER, J G	810105050	50-6	KERR, J E	810105054	50-133	KNOP, R C	01012200
KEPPLER, J G	810105050	50-409	KERRIGAN, J	810105054	50-311	KNOP, R C	81012900
KEPPLER, J G	810105050	50-329	KERRIGAN, J D	810105054	50-320	KNOP, R C	01011400
KEPPLER, J G	810105050	50-440	KERRIGAN, J D	810105054	50-529	KNOP, R C	81011400
KEPPLER, J G	810105050	50-10	KETCHUM, E G	810105054	50-369	KNOP, R C	81011500
KEPPLER, J G	810105054	50-461	KETCHUM, E G	810105054	50-369	KNOP, R C	81011500
KEPPLER, J G	810105054	50-331	KETCHUM, E G	810105054	50-275	KNOP, R C	81010900
KEPPLER, J G	810105054	50-241	KETCHUM, E G	810105054	50-275	KNOP, R C	81012200
KEPPLER, J G	810105054	50-315	KETCHUM, E G	810105054	50-369	KNOP, R C	01010700
KEPPLER, J G	810105054	50-250	KETCHUM, E G	810105054	70-33	KNOP, R C	01010700
KEPPLER, J G	810105054	50-155	KETCHUM, E G	810105054	70-2937	KNOP, R C	81010700
KEPPLER, J G	810105054	50-262	KETZLACH, H	810105054	70-2936	KNOP, R C	01012800
KEPPLER, J G	810105054	50-367	KETZLACH, H	810105054	70-27	KNOP, R C	01010700
KEPPLER, J G	810105054	50-545	KETZLACH, H	810105054	70-2623	KNOP, R C	01010700
KEPPLER, J G	810105054	50-463	KETZLACH, H	810105054	70-27	KNOP, R C	01010700
KEPPLER, J G	810105054	50-305	KETZLACH, H	810105054	70-27	KNOP, R C	01010700
KEPPLER, J G	810105054	50-266	KETZLACH, H	810105054	70-2909	KNOP, R C	81010700
KEPPLER, J G	810105054	50-345	KEURICK, J R	810105054	70-2909	KEHLER, J E	81011400
KEPPLER, J G	810105054	50-345	KEY, W	810105054	50-546	KOLKEY, M	81013000
KEPPLER, J G	810105054	50-3	KEY, W	810105054	50-374	KOLTA, P B	01013000
KEPPLER, J G	810105054	50-358	KEYSER, J	810105054	CONTRACT	KONIGABERO, A	81012000
KEPPLER, J G	810105054	50-266	KIENHOLZ, J	810105054	50-271	KOPACI, J J	80112300
KEPPLER, J G	810105054	50-305	KILLGARD, R	810105054	PR	KOPACI, J J	81010600
KEPPLER, J G	810105054	50-329	KIMEL, H R	810105054	50-289	KOPLEY, K	01012100
KEPPLER, J G	810105054	50-345	KIMMEL, J J	810105054	CONTRACT	KORN, L	81013000
KEPPLER, J G	810105054	50-315	KIMMEL, J J	810105054	50-327	KOSCH, J L	01012900
KEPPLER, J G	810105054	50-329	KIMMEL, J J	810105054	PR	KOVAR, K W	81011300
KEPPLER, J G	810105054	50-282	KING, D	810105054	PR	KOVAL, K	81011600
KEPPLER, J G	810105054	50-545	KINGSLEY, S G	810105054	71-358	KOWATZ, M	81012600
KEPPLER, J G	810105054	50-483	KINGMAO, O	810105054	PR	KRAFT, O C	81012100
KEPPLER, J G	810105054	50-265	KINMAN, L	810105054	PR	KRASNOFF, J	81012100
KEPPLER, J G	810105054	50-305	KINNEHAN, J O	810105054	70-818	KRAMACK, A T	81011300
KEPPLER, J G	810105054	50-255	KINNEHAN, J D	810105054	70-2323	KREGER, W E	78092100
KEPPLER, J G	810105054	50-275	KINNEHAN, J D	810105054	40-8649	KREGER, W E	81011200
KEPPLER, J G	810105054	50-315	KINNEHAN, J D	810105054	40-2003	KREIS, J	81013000
KEPPLER, J G	810105054	50-409	KINNEHAN, J D	810105054	70-1111	KRESS, T S	81012900
KEPPLER, J G	810105054	50-263	KINNEHAN, J	810105054	50-245	KRESS, T S	81012900

LAFFAY, O. C.	0101270365	PR		LAURENCE, L. I.	0101070492*	50-298	S	LESTER, D.	0101260376	PR
LAFFAY, S.	0101190520	PR		LAURENCE, W.	0101230173	PR		LEWIS, E. H. J.	0101260112	PR
LAFFAY, E. C.	0101190651	PR		LAURENCE, J. L.	0101260327	PR		LEWIS, E. W. J.	0101230146*	S-
LAFFAY, H. E.	0101210277	50-387	A	LAZARUS, H.	0101300330*	50-309	D	LEWIS, D. M.	0101205046	PR
LAFFAY, J. L.	0101140528	50-255	P	LAZOR, R. H.	0101210271*	50-592	A	LEWIS, M. H.	0101230205	REG
LAFFAY, K.	0101500174	PR		LAZOR, R. H.	0101210120*	50-583	A	LEWIS, M. H.	0101272571	REG
LAFFAY, B. A.	0101090160	50-289	H	LAZOR, R. H.	01012100151*	50-452	A	LEWIS, S.	0101190581	PR
LAFFAY, T. J.	0101220470*	50-339	P	LAZOR, R. H.	0101090951	50-309	G	LEWIS, A.	0101120480	PR
LAFFAY, B. R.	0101260523	PR		LAZOR, R. H.	0101120497	50-526	G	LEWIS, B. H.	0101260419	50-
LAFFAY, E. T.	0101130108	NUREG		LAZOR, R. H.	0101140915	50-239	M	LEWIS, B. H.	0101270241	PR
LAFFAY, E. T.	0101130141	NUREG		LAZOR, R. H.	0101160741	50-413	M	LEWIS, S.	0101260055	50-
LAFFAY, K. W.	0101140066	REVIEW CRP		LAZOR, R. H.	0101300199	REIS		LEWIS, R. C.	0101230231*	50-
LAFFAY, A.	0101190024	PR		LAZOR, R. H.	0101160741	PR		LEWIS, J.	0101072487*	REG
LAFFAY, H.	0101300412	PR		LAZOR, R. H.	0101170174	PR		LEWIS, R. C.	0101090641*	50-
LAFFAY, W. S.	0101070531*	50-334	S	LAZOR, R. H.	0101091650*	CONTRACT		LEWIS, R. C.	0101080155*	50-
LAFFAY, W. S.	0101130425*	50-334	S	LAZOR, C. D.	0101120164*	50-289	D	LEWIS, R. C.	0101070152*	50-
LAFFAY, W. S.	0101130420*	50-334	S	LAZOR, C. D.	0101150045*	CONTRACT		LEWIS, R. C.	0101230231*	50-
LAFFAY, W. S.	0101130432*	50-334	S	LAZOR, C. D.	0101060320	CONTRACT		LEWIS, R. C.	0101100351	50-
LAFFAY, W. S.	0101130436*	50-334	S	LAZOR, C. D.	0101060347*	CONTRACT		LEWIS, R. C.	0101100623	50-
LAFFAY, W. S.	0101130443*	50-334	S	LAZOR, C. D.	0101130555*	CONTRACT		LEWIS, R. C.	0101220419	50-
LAFFAY, W. S.	0101130515*	50-334	S	LAZOR, C. D.	0101140375*	CONTRACT		LEWIS, R. C.	010116026*	50-
LAFFAY, W. S.	0101190470*	50-334	S	LAZOR, C. D.	0101300327*	CONTRACT		LEWIS, S.	0101230266	PR
LAFFAY, W. S.	0101190477*	50-334	S	LAZOR, C. D.	0101270732*	CONTRACT		LEWIS, M. J.	0101230213	PR
LAFFAY, W. S.	0101220387*	50-334	S	LAZOR, C. D.	0101290105*	CONTRACT		LEWIS, M. J.	0101290373	50-
LAFFAY, W. S.	0101220397*	50-334	S	LAZOR, C. D.	0101150631	50-285	P	LEWIS, M. J.	0101060112	PR
LAFFAY, W. S.	0101220381*	50-334	S	LAZOR, C. D.	0101160695	PR		LEWIS, R. C.	0101090245	50-
LAFFAY, W. S.	0101230471*	50-334	S	LAZOR, C. D.	0101160620	PR		LEWIS, R. C.	0101080121	50-
LAFFAY, W. S.	0101230473*	50-334	S	LAZOR, C. D.	0101210559	FDJA		LEWIS, R. C.	0101080217	50-
LAFFAY, W. S.	0101230478*	50-334	S	LAZOR, C. D.	0101170351	PR		LEWIS, R. C.	0101270357	50-
LAFFAY, W. S.	0101260634*	50-334	S	LAZOR, C. D.	0101072205*	50-267	D	LEWIS, M. J.	0101290156	PR
LAFFAY, W. S.	0101270593*	50-334	S	LAZOR, C. D.	0101120134	50-267	D	LEWIS, M. J.	0101090671	50-
LAFFAY, W. S.	0101190117	PR		LAZOR, C. D.	0101120425	50-267	P	LEWIS, R. C.	0101160694	50-
LAFFAY, R. H.	0101150249*	50-213	D	LAZOR, C. D.	0101170769	50-267	P	LEWIS, M. J.	0101200375	50-
LAFFAY, R. H.	0101260702	PR		LAZOR, C. D.	0101130793	50-267	P	LEWIS, S. H.	0101270106	50-
LAFFAY, R. H.	0101200172	50-289	H	LAZOR, C. D.	0101130394*	50-267	P	LEWIS, M. J.	0101150672	50-
LAFFAY, R. H.	0101150374	50-289	H	LAZOR, C. D.	0101140515*	50-461	D	LEWIS, M. J.	0101100341	REG
LAFFAY, R. H.	0101050113*	50-317	S	LAZOR, C. D.	0101140510*	10PHCP		LEWIS, M. J.	0101220145	PR
LAFFAY, R. H.	0101130623*	50-317	S	LAZOR, C. D.	0101060755*	70-143		LEWIS, M. J.	0101070557*	50-
LAFFAY, R. H.	0101150543*	50-317	S	LAZOR, C. D.	0101290366*	50-260	O	LEWIS, M. J.	0101080297*	50-
LAFFAY, R. H.	0101230526*	50-317	S	LAZOR, C. D.	0101270347*	50-289	T	LEWIS, M. J.	0101070540*	50-
LAFFAY, R. H.	0101270664*	50-318	S	LAZOR, C. D.	0101090610	50-259	P	LEWIS, R. A.	0101210315	50-
LAFFAY, R. H.	0101300530*	50-317	S	LAZOR, C. D.	0101230258	PR		LEWIS, R. A.	0101270747	50-
LAFFAY, R. H.	0101270792	REG		LAZOR, C. D.	0101210267	PR		LEWIS, R. A.	0101260114	REG
LAFFAY, R. H.	0101220374*	50-10	P	LAZOR, C. D.	0101220133	INSTE. NOT		LEWIS, R. A.	0101190471	PR
LAFFAY, R. H.	0101290475	50-29	P	LAZOR, C. D.	0101140017*	50-307	D	LEWIS, R. A.	0101210282	PR
LAFFAY, R. H.	0101210070	PR		LAZOR, C. D.	0101150631	50-283	P	LEWIS, R. A.	0101160393	PR
LAFFAY, R. H.	0101150631	50-289	P	LAZOR, C. D.	0101090016	50-155	G	LEWIS, R. A.	0101220595	PR
LAFFAY, R. H.	0101190323	PR		LAZOR, C. D.	0101090022*	50-155	G	LEWIS, R. A.	0101300039	URE
LAFFAY, R. H.	0101200525	PR		LAZOR, C. D.	0101130148	50-155	O	LEWIS, R. A.	0101090079	50-
LAFFAY, R. H.	0101210227	PR		LAZOR, C. D.	0101130154*	50-155	G	LEWIS, R. A.	0101090107	50-
LAFFAY, R. H.	0101270502	40-8452		LAZOR, C. D.	0101130156*	50-155	G	LEWIS, R. A.	0101050374	50-
LAFFAY, R. H.	0101140537	PR		LAZOR, C. D.	0101220436*	50-220	G	LEWIS, R. A.	0101050353	50-
LAFFAY, R. H.	0101150366*	COMMISION		LAZOR, C. D.	0101140696	50-220	G	LEWIS, R. A.	0101050326	50-
LAFFAY, R. H.	0101290647	PR		LAZOR, C. D.	0101300055	50-220	G	LEWIS, R. A.	0101060561	50-
LAFFAY, R. H.	0101270761	PR		LAZOR, C. D.	0101120335	50-220	S	LEWIS, R. A.	0101090342	50-
LAFFAY, R. H.	0101190533	PR		LAZOR, C. D.	0101150677	50-220	S	LEWIS, R. A.	0101300636	50-
LAFFAY, R. H.	0101210207	NUREG		LAZOR, C. D.	0101150601	50-220	R	LEWIS, R. A.	0101160433	50-
LAFFAY, R. H.	0101210226	REG		LAZOR, C. D.	0101210595	50-220	P	LEWIS, R. A.	0101200178	50-
LAFFAY, R. H.	0101220552	REG		LAZOR, C. D.	0101230580	50-220	R	LEWIS, R. A.	0101140491	50-
LAFFAY, R. H.	0101300507	PR		LAZOR, C. D.	0101100634*	50-250	G	LEWIS, R. A.	0101260515	50-
LAFFAY, R. H.	0101200239	50-289	H	LAZOR, C. D.	0101120364	XPBRTLIC		LEWIS, R. A.	0101220025	50-
LAFFAY, R. H.	0101200497	PR		LAZOR, C. D.	0101120373	XPBRTLIC		LEWIS, R. A.	0101300181	50-
LAFFAY, R. H.	0101160048	PR		LAZOR, C. D.	0101120000	XPBRTLIC		LEWIS, R. A.	0101270345	50-
LAFFAY, R. H.	0101070412	50-322	G	LAZOR, C. D.	0101220125	PR		LEWIS, R. A.	0101070547	50-
LAFFAY, R. H.	0101070459	50-322	G	LAZOR, C. D.	0101280336	PR		LEWIS, R. A.	0101280635	40-
LAFFAY, R. H.	0101220011*	50-312	F	LAZOR, C. D.	0101220205	REG		LEWIS, R. A.	0101290087	40-
LAFFAY, R. H.	0101270675	50-322	G	LAZOR, C. D.	0101210013	PR		LEWIS, R. A.	0101290031	40-
LAFFAY, R. H.	0101270678*	50-322	G	LAZOR, C. D.	0101300112	PR		LEWIS, R. A.	0101290062	40-
LAFFAY, R. H.	0101150496*	50-247	P	LAZOR, C. D.	0101230345	PR		LEWIS, R. A.	0101100361*	50-
LAFFAY, R. H.	0101160690*	50-280	P	LAZOR, C. D.	0101070514	50-298	S	LEWIS, R. A.	0101140510	50-
LAFFAY, R. H.	0101130274*	PR		LAZOR, C. D.	0101070507	50-298	S	LEWIS, R. A.	0101140637	PR
LAFFAY, R. H.	0101210156	PR		LAZOR, C. D.	0101070760	50-298	R	LEWIS, R. A.	0101290494*	50-
LAFFAY, R. H.	0101280450*	50-244	P	LAZOR, C. D.	0101070391	50-298	S	LEWIS, R. A.	0101300308*	50-
LAFFAY, R. H.	0101120332*	50-244	P	LAZOR, C. D.	0101070355	50-298	S	LEWIS, R. A.	0101290337	CON
LAFFAY, R. H.	0101120342*	50-244	P	LAZOR, C. D.	0101070489	50-298	S	LEWIS, R. A.	0101270706	50-
LAFFAY, R. H.	0101300562*	50-244	P	LAZOR, C. D.	0101070477	50-298	S	LEWIS, R. A.	0101200212	PR
LAFFAY, R. H.	0101120353*	50-244	P	LAZOR, C. D.	0101270647	50-298	S	LEWIS, R. A.	0101230274	PR
LAFFAY, R. H.	0101070047	FDJA		LAZOR, C. D.	0101270641	50-298	R	LEWIS, R. A.	0101060197*	50-
LAFFAY, R. H.	0101190062	PR		LAZOR, C. D.	0101130987	50-298	R	LEWIS, R. A.	0101140722*	50-
LAFFAY, R. H.	0101060790*	CONTRACT		LAZOR, C. D.	0101270715	50-298	S	LEWIS, R. A.	0101210016*	PR
LAFFAY, R. H.	0101140011	50-387	G	LAZOR, C. D.	0101270775	50-298	S	LEWIS, R. A.	0101070135	50-
LAFFAY, R. H.	0101200023	50-307	G	LAZOR, C. D.	0101140726	50-483	G	LEWIS, R. A.	0101030372*	CON
LAFFAY, R. H.	0101280628	50-387	G	LAZOR, C. D.	0101270334	50-443	G	LEWIS, R. A.	0101160020	TOP
LAFFAY, R. H.	0101300012	50-259	G	LAZOR, C. D.	0101270434	50-443	G	LEWIS, R. A.	0101150480	PR
LAFFAY, R. H.	0101070511*	50-298	S	LAZOR, C. D.	0101300618	50-483	G	LEWIS, R. A.	0101050150*	50-

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LOCH, R. L.	0101270361	50-239	MACDONALD, C. E.	0101270351	71-9072	MAGILY, H.	0101260543	50-321
LOCH, J. S.	0101270362	PR	MACDONALD, C. E.	0101270361	71-5903	MAGILY, H.	0101260592	50-321
LOCH, R. S.	0101300241	PR	MACDONALD, C. E.	0101270368	71-6450	MAGILY, H.	0101260601	50-321
LOCH, M. H.	0101300305	50-493	MACDONALD, C. E.	0101270372	71-9065	MAGILY, H. C.	0101050819	70-143
LOCH, E. B. C. T. E.	0101270370	40-6200	MACDONALD, C. E.	0101270376	71-9023	MAGILY, H. C.	0101060297	70-143
LOCH, E. B. C. T. E.	0101270377	40-6200	MACDONALD, C. E.	0101270384	71-6652	MAGILY, H. C.	0101160138	70-143
LOCH, E. B. C. T. E.	0101150345	CONTRACT	MACDONALD, C. E.	0101270386	71-6573	MAGILY, D. A.	0101210021	PR
LOCH, E. B. C. T. E.	0101120318	50-155	MACDONALD, C. E.	0101270394	71-390	MAGILY, J. C.	0101160358	ACRS
LOCH, E. B. C. T. E.	0101150379	50-373	MACDONALD, C. E.	0101270397	71-398	MAGILY, J. C.	0101090919	XPORTRIC
LOCH, M.	0101160350	PR	MACDONALD, C. E.	0101270398	XPREP	MAGILY, J. C.	0101090912	XPORTRIC
LOCH, E. B. C. T. E.	0101260147	PR	MAGILY, R. O.	0101080355	50-293	MAGILY, J. C.	0101140703	XPORTRIC
LOCH, E. B. C. T. E.	0101260370	50-357	MAGILY, R. O.	0101140706	50-293	MAGILY, J. C.	0101190755	XPORTRIC
LOCH, E. B. C. T. E.	0101270335	State Prog	MAGILY, R. O.	0101190762	50-293	MAGILY, J. C.	0101140931	70-290
LOCH, E. B. C. T. E.	0101150344	11E	MAGILY, R. O.	0101160516	50-293	MAGILY, J. C.	0101140951	PR
LOCH, E. B. C. T. E.	0101160400	State Prog	MAGILY, R. O.	0101260544	50-293	MAGILY, J. C.	0101210019	PR
LOCH, E. B. C. T. E.	0101130320	PR	MAGILY, R. O.	0101260544	50-293	MAGILY, J. C.	0101210019	PR
LOCH, E. B. C. T. E.	0101270381	PR	MAGILY, R. O.	0101270534	PR	MAGILY, J. C.	0101200539	PR
LOCH, E. B. C. T. E.	0101210376	RES	MAGILY, R. O.	0101300153	RES	MAGILY, J. C.	0101160446	50-327
LOCH, E. B. C. T. E.	0101260328	RES	MAGILY, R. O.	0101160126	RES	MAGILY, J. C.	0101160463	ACRS
LOCH, E. B. C. T. E.	0101050302	50-463	MAGILY, R. O.	0101070522	FOIA	MAGILY, J. C.	0101300814	50-327
LOCH, E. B. C. T. E.	0101300309	NUREG	MAGILY, R. O.	0101130115	XPORTRIC	MAGILY, R. A.	0101160318	PR
LOCH, E. B. C. T. E.	0101070377	50-317	MAGILY, R. O.	0101130119	XPORTRIC	MAGILY, R. A.	0101050350	50-329
LOCH, E. B. C. T. E.	0101150351	50-317	MAGILY, R. O.	0101270178	FOIA	MAGILY, R. A.	0101060742	FOIA
LOCH, E. B. C. T. E.	0101150365	50-317	MAGILY, R. O.	0101210154	50-327	MAGILY, R. A.	0101300760	NUREG
LOCH, E. B. C. T. E.	0101140744	50-317	MAGILY, R. O.	0101160351	50-263	MAGILY, R. A.	0101100194	50-271
LOCH, E. B. C. T. E.	0101050437	50-317	MAGILY, R. O.	0101140510	50-263	MAGILY, R. A.	0101270781	50-334
LOCH, E. B. C. T. E.	0101150373	50-317	MAGILY, R. O.	0101270827	50-337	MAGILY, R. A.	0101000300	50-309
LOCH, E. B. C. T. E.	0101120357	50-317	MAGILY, R. O.	0101070215	50-267	MAGILY, R. A.	0101050497	50-354
LOCH, E. B. C. T. E.	0101260477	50-318	MAGILY, R. O.	0101100029	50-290	MAGILY, R. A.	0101160633	50-271
LOCH, E. B. C. T. E.	0101300322	50-317	MAGILY, R. O.	0101070240	50-205	MAGILY, R. A.	0101090678	50-333
LOCH, E. B. C. T. E.	0101210347	PR	MAGILY, R. O.	0101100625	50-313	MAGILY, R. A.	0101060739	70-1160
LOCH, E. B. C. T. E.	0101210275	NUREG	MAGILY, R. O.	0101070247	50-302	MAGILY, R. A.	0101000177	50-269
LOCH, E. B. C. T. E.	0101300105	PR	MAGILY, R. O.	0101100317	50-313	MAGILY, R. A.	0101290754	70-820
LOCH, E. B. C. T. E.	0101140076	PR	MAGILY, R. O.	0101060894	50-313	MAGILY, R. A.	0101300120	XPORTRIC
LOCH, E. B. C. T. E.	0101210263	PR	MAGILY, R. O.	0101070158	50-213	MAGILY, R. A.	0101300126	XPORTRIC
LOCH, E. B. C. T. E.	0101190167	PR	MAGILY, R. O.	0101070146	50-290	MAGILY, R. A.	0101300191	70-135
LOCH, E. B. C. T. E.	0101150097	FOIA	MAGILY, R. O.	0101200202	50-289	MAGILY, R. A.	0101000359	50-458
LOCH, E. B. C. T. E.	0101220142	PR	MAGILY, R. O.	0101080112	50-244	MAGILY, R. A.	0101070159	50-369
LOCH, E. B. C. T. E.	0101280387	PR	MAGILY, R. O.	0101210639	50-244	MAGILY, R. A.	0101200966	50-382
LOCH, E. B. C. T. E.	0101230511	50-397	MAGILY, R. O.	0101100794	50-244	MAGILY, R. A.	0101150242	50-213
LOCH, E. B. C. T. E.	0101230512	50-397	MAGILY, R. O.	0101060664	50-244	MAGILY, R. A.	0101230218	70-620
LOCH, E. B. C. T. E.	0101050531	50-289	MAGILY, R. O.	0101193440	50-244	MAGILY, R. A.	0101060480	50-354
LOCH, E. B. C. T. E.	0101230576	PR	MAGILY, R. O.	0101150520	50-244	MAGILY, R. A.	0101220427	50-348
LOCH, E. B. C. T. E.	0101150123	PR	MAGILY, R. O.	0101120314	50-244	MAGILY, R. A.	0101140500	50-382
LOCH, E. B. C. T. E.	0101190340	PR	MAGILY, R. O.	0101210297	50-244	MAGILY, R. A.	0101060114	WASTE M31
LOCH, E. B. C. T. E.	0101150441	PR	MAGILY, R. O.	0101290589	50-244	MAGILY, R. A.	0101260772	70-135
LOCH, E. B. C. T. E.	0101190460	PR	MAGILY, R. O.	0101230410	50-244	MAGILY, R. A.	0101060194	50-282
LOCH, E. B. C. T. E.	0101070342	50-321	MAGILY, R. O.	0101230422	50-244	MAGILY, R. A.	0101270415	PR
LOCH, E. B. C. T. E.	0101270122	27-47	MAGILY, R. O.	0101270655	50-244	MAGILY, R. A.	0101160621	50-271
LOCH, E. B. C. T. E.	0101220445	50-10	MAGILY, R. O.	0101260099	50-320	MAGILY, R. A.	0101270361	50-335
MACDONALD, C. E.	0101190552	71-6273	MACKEPPE, J. M.	0101050353	50-247	MAGILY, R. A.	0101140367	CONTRACT
MACDONALD, C. E.	0101070586	50-213	MACKEPPE, J. M.	0101210440	50-247	MAGILY, R. A.	0101290135	RES
MACDONALD, C. E.	0101070608	50-10	MACKEPPE, J. M.	0101270685	50-247	MAGILY, R. A.	0101200629	40-8302
MACDONALD, C. E.	0101270156	50-244	MACKEPPE, J. M.	0101270729	50-247	MAGILY, R. A.	0101200091	50-259
MACDONALD, C. E.	0101160612	71-402	MALAB, J. C.	0101290313	FOIA	MAGILY, R. A.	0101200214	50-259
MACDONALD, C. E.	0101200443	PR	MALAB, J. C.	0101290349	FOIA	MAGILY, R. A.	0101290692	70-135
MACDONALD, C. E.	0101050426	71-5364	MALAB, J. C.	0101290360	FOIA	MAGILY, R. A.	0101060907	50-416
MACDONALD, C. E.	0101050431	71-6974	MALAB, J. C.	0101290431	RES	MAGILY, R. A.	0101100020	50-416
MACDONALD, C. E.	0101050416	71-9074	MALAB, J. C.	0101220628	RES	MAGILY, R. A.	0101130316	PR
MACDONALD, C. E.	0101050450	71-6658	MALAB, J. C.	0101270731	CONTRACT	MAGILY, R. A.	0101140623	50-250
MACDONALD, C. E.	0101050456	71-9010	MALLOV, R. J.	0101070270	50-320	MAGILY, R. A.	0101300053	PR
MACDONALD, C. E.	0101050459	71-9135	MALLOV, R. J.	0101060097	50-312	MAGILY, R. A.	0101230638	50-462
MACDONALD, C. E.	0101050464	71-6601	MALLOV, R. J.	0101200405	PR	MAGILY, R. A.	0101290819	NUREG
MACDONALD, C. E.	0101050467	71-9111	MALLOV, R. J.	0101150600	RES	MAGILY, R. A.	0101060832	RES
MACDONALD, C. E.	0101160369	71-6144	MALLOV, R. J.	0101150267	PR	MAGILY, R. A.	0101070336	RES
MACDONALD, C. E.	0101100065	71-9141	MALLOV, R. J.	0101200177	PR	MAGILY, R. A.	0101210588	50-341
MACDONALD, C. E.	0101100100	71-9908	MALLOV, R. J.	0101090924	XPORTRIC	MAGILY, R. A.	0101270400	50-16
MACDONALD, C. E.	0101100104	71-9044	MALLOV, R. J.	0101050942	CONTRACT	MAGILY, R. A.	0101220114	50-305
MACDONALD, C. E.	0101100108	71-6717	MALLOV, R. J.	0101050235	50-321	MAGILY, R. A.	0101090700	50-305
MACDONALD, C. E.	0101100113	71-9070	MALLOV, R. J.	0101050427	50-321	MAGILY, R. A.	0101070650	50-305
MACDONALD, C. E.	0101100122	71-9010	MALLOV, R. J.	0101050455	50-366	MAGILY, R. A.	0101210378	CONTRACT
MACDONALD, C. E.	0101050321	71-6400	MALLOV, R. J.	0101060559	50-366	MAGILY, R. A.	0101060555	50-305
MACDONALD, C. E.	0101070507	71-4986	MALLOV, R. J.	0101060572	50-366	MAGILY, R. A.	0101210316	50-305
MACDONALD, C. E.	0101070917	71-4986	MALLOV, R. J.	0101060582	50-321	MAGILY, R. A.	0101090529	50-305
MACDONALD, C. E.	0101200002	71-9132	MALLOV, R. J.	0101060640	50-321	MAGILY, R. A.	0101300563	50-305
MACDONALD, C. E.	0101050162	71-9007	MALLOV, R. J.	0101060648	50-366	MAGILY, R. A.	0101130586	50-305
MACDONALD, C. E.	0101050165	71-9007	MALLOV, R. J.	0101060514	50-321	MAGILY, R. A.	0101220387	50-305
MACDONALD, C. E.	0101050171	71-6375	MALLOV, R. J.	0101120298	50-321	MAGILY, R. A.	0101130435	50-305
MACDONALD, C. E.	0101050173	71-6375	MALLOV, R. J.	0101120207	50-321	MAGILY, R. A.	0101210231	50-305
MACDONALD, C. E.	0101070627	71-9044	MALLOV, R. J.	0101120312	50-366	MAGILY, R. A.	0101220355	50-305
MACDONALD, C. E.	0101090938	71-9044	MALLOV, R. J.	0101260463	50-321	MAGILY, R. A.	0101220034	50-305
MACDONALD, C. E.	0101190725	71-9133	MALLOV, R. J.	0101260529	50-366	MAGILY, R. A.	0101260379	50-305
MACDONALD, C. E.	0101190744	71-6273	MALLOV, R. J.	0101280187	50-321	MAGILY, R. A.	0101270625	50-305
MACDONALD, C. E.	0101190748	71-179	MALLOV, R. J.	0101230454	50-321	MAGILY, R. A.	0101280318	50-305
MACDONALD, C. E.	0101160763	71-9938	MALLOV, R. J.	0101230466	50-366	MAGILY, R. A.	0101290543	40-8728

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MATLOCK, R G	B101140510	50-397 S	MAZUR, D H	B101270449	50-397 Q	MCGOVERN, S A	B101296704	PR
MATLOCK, R G	B101095013	50-397 S	MAZUR, S T	B101135639	CONFESSION	MCGOVERN, J J	B101282601	PR
MATLOCK, R G	B101050039	50-397 S	MCCALPINE, E J	B101293356	50-280 Q	MCGOVERN, J J	B101135123	50-
MATLOCK, R G	B101270471	50-397 Q	MCANALLY, M	B101270635	50-232 Q	MCGRIFF, J H	B101160483	50-
MATLOCK, R G	B101270555	50-397 Q	MCCOBEARTY, R A	B101100553	50-271 Q	MCGRIFF, J H	B101210454	50-
MATLOCK, R G	B101140457	50-397 S	MCCABE, E C	B101095259	50-387 Q	MCGRIFF, J H	B101270505	50-
MAISON, V	B101100354	70-2479	MCCABE, E C	B101105244	50-277 Q	MCGRIFF, J H	B101285130	50-
MATSON, V	B101100360	FOIA	MCCABE, E A	B101070638	PR	MCGRIFF, J H	B101225326	50-
MATSON, V	B101100362	FOIA	MCCABE, E C	B101280165	50-277 Q	MCGRIFF, J H	B101205521	50-
MATSON, V	B101100322	FOIA	MCCABE, E C	B101150891	50-277 Q	MCGUIRE, J	B101050210	40-
MATSON, V	B101100296	70-2479	MCCABE, E C	B101155681	50-397 Q	MCGUIRE, D H	B101100731	50-
MATSON, V	B101140319	XPORTLIC	MCCABE, E C	B101150973	50-317 Q	MCGUIRE, D	B101100556	PR
MATSON, V	B101190366	XPORTLIC	MCCABE, E C	B101090211	50-317 S	MCGUIRE, D R	B101220305	50-
MATSON, V	B101140079	XPORTLIC	MCCALLISTER, F	B101200122	50-329 A	MCGURRY, H J	B101280105	50-
MATSON, V	B101200409	40-000	MCCANN, J	B101155580	50-247 Q	MCINTYRE, T	B101260136	PR
MATSON, V	B101156320	XPORTLIC	MCCANN, J	B101270907	50-336 S	MCKINIE, L	B101130324	PR
MATSON, V	B101150026	XPORTLIC	MCCAGLEY, S T	B101130951	PR	MCKINIE, L I	B101260787	70-
MATSON, V	B101270102	XPORTLIC	MCCENA, C	B101150550	PR	MCKINIE, L I	B101297506	70-
MATTHEWS, P R	B101070070	FOIA	MCCENASIN, M J	B101260194	PR	MCKINNEY, R E	B101160094	50-
MATTHEWS, P R	B101200143	PR	MCCLOSKEY, D J	B101270245	RES	MCKINNEY, R E	B101200143	50-
MATTIA, H J	B101060321	CONTRACT	MCCLOSKEY, D J	B101293213	RES	MCLAUGHLIN, K	B101236725	PR
MATTIA, H J	B101100070	50-312 Q	MCCLOSKEY, R U	B101056962	NUREG	MCLAUGHLIN, G O	B101010530	50-
MATTIA, J C	B101300138	50-317 Q	MCCLOSKEY, R H	B101070963	NUREG	MCLAUGHLIN, M T	B101080168	50-
MATTIA, H J	B101060780	50-312 Q	MCCLOSKEY, M J	B101275655	50-350 A	MCLAUGHLIN, M T	B101170485	50-
MATTIA, H J	B101070696	50-312 Q	MCCLOSKEY, J M	B101073037	ORR	MCLAUGHLIN, M T	B101160573	50-
MATTIA, H J	B101120561	50-312 Q	MCCLOSKEY, H J	B101270614	50-358 A	MCLAUGHLIN, P	B101260547	PR
MATTIA, H J	B101120551	50-312 Q	MCCLOSKEY, G W	B1012106277	70-724	MCMANUS, E P	B101170736	50-
MATTIA, H J	B101090399	CONTRACT	MCCLOSKEY, O W	B1012106344	70-724	MCHILLAN, M	B101210170	PR
MATTIA, H J	B101050424	XPORTLIC	MCCLOSKEY, O W	B1012106327	70-354	MCHURRAY, A A	B1011300301	PR
MATTIA, H J	B101070697	CONTRACT	MCCLOSKEY, O W	B101210636	FOIA	MCHAMARA, D H	B101157277	PR
MATTIA, H J	B101050189	CONTRACT	MCCORALE, O W	B101040821	50-210 P	MCHAMARA, A E	B101213476	50-
MATTIA, H J	B101200498	CONTRACT	MCCORALE, O W	B101060373	50-210 P	MCHER, C S	B101220115	50-
MATTIA, H J	B101200481	CONTRACT	MCCORALE, B J	B101190332	PR	MCHER, C S	B101270475	40-
MATTIA, H J	B101210297	CONTRACT	MCCORD, R A	B101300039	NUREG	MCHILLAN, M	B101270666	0A9
MATTIA, H J	B101210578	CONTRACT	MCCOFEY, O F	B101303622	RES	MCHILLAN, M	B101230254	PR
MATTIA, H J	B101300271	CONTRACT	MCCONALD, J R	B101170139	50-206 P	MCHIRNALL, J	B101260324	FOIA
MATTIA, H J	B101060773	50-312 S	MCCONALD, J R	B101205206	50-29 P	MCHIRNALL, L A	B101205275	CON
MATTIA, H J	B101160071	CONTRACT	MCCONALD, J R	B101210101	50-245 P	MCHIRNALL, L A	B101207322	CON
MATTIA, H J	B101270727	CONTRACT	MCCONALD, J R	B101210222	50-219 P	MCHIRNALL, L A	B101123011	50-
MATTIA, H J	B101280075	27-39	MCCONALD, J R	B101210253	50-153 P	MCHIRNALL, L A	B101050185	CON
MATTIA, H J	B101130593	50-312 P	MCCONALD, J R	B101270111	50-409 F	MCHIRNALL, L A	B101350229	CON
MATTIA, H J	B101130472	50-312 S	MCCONALD, J A	B101270378	50-370 Q	MCHIRNALL, R F	B101303917	50-
MATTIA, H J	B101270523	50-312 Q	MCCONALD, R	B101260632	PR	MCHIRNALL, R	B101270286	PRO
MATTIA, H J	B101160111	CONTRACT	MCCONALD, R J	B101200480	CONTRACT	MCHIRNALL, R	B101270286	PRO
MATTIA, H J	B101210527	CONTRACT	MCCONALD, J	B1011130852	PR	MCHIRNALL, C	B101130417	50-
MATTIA, H J	B101200401	50-312 S	MCCUFFIE, H A	B101110200	50-409 Q	MCHIRNALL, C	B101280341	PR
MATTIA, H J	B101220303	50-312 Q	MCCUFFIE, H A	B101210217	50-400 Q	MCHIRNALL, C	B101130156	PR
MATTIA, H J	B101230590	50-312 S	MCCLOY, H II	B101100257	NUREG	MCHIRNALL, C	B101200265	PR
MATTIA, H J	B101270472	50-312 P	MCCLOY, H II	B101220301	NUREG	MCHIRNALL, C	B101220597	PR
MATTIA, H J	B101200297	50-312 Q	MCCLOY, H II	B101270633	NUREG	MCHIRNALL, C	B101260323	PR
MATSON, D	B101160171	PR	MCCLELLAN, F D	B101220325	50-508 Q	MCHIRNALL, C	B101130605	50-
MATSON, D	B101270632	NUREG	MCCLELLAN, C R	B101160714	50-269 Q	MCHIRNALL, C	B101220403	50-
MATSON, D	B101260727	PR	MCCLELLAN, C R	B101270369	50-209 II	MCHIRNALL, C	B101130312	PR
MATSON, D	B101190079	PR	MCCLELLAN, J H	B101050616	50-408 Q	MCHIRNALL, C	B101190450	PR
MATSON, D	B101070389	50-382 A	MCCLELLAN, J H	B101050616	50-408 Q	MCHIRNALL, C	B101160172	PR
MAXWELL, O C	B101270520	50-10 R	MCCLELLAN, J H	B101166220	50-410 M	MCHIRNALL, C	B101280341	PR
MAY, E L	B101140692	50-29 P	MCCLELLAN, J H	B101230404	70-2623	MCHIRNALL, C	B101150235	PR
MAY, H	B101260686	PR	MCCLELLAN, J H	B101230442	70-2623	MCHIRNALL, C	B101260320	50-
MAY, T S	B101140964	PR	MCCLELLAN, J H	B101230404	70-2623	MCHIRNALL, C	B101260320	50-
MAY, T S	B101260251	50-209 II	MCCLELLAN, J H	B101230442	70-2623	MCHIRNALL, C	B101160391	50-
MAYER, L O	B101080298	50-202 F	MCCLELLAN, J H	B101260209	50-369 Q	MCHIRNALL, C	B101190510	PR
MAYER, L O	B101210132	71-9085	MCCLELLAN, J H	B101260399	50-400 Q	MCHIRNALL, C	B101130140	50-
MAYER, L O	B101050262	50-202 P	MCCLELLAN, J H	B101260399	50-400 Q	MCHIRNALL, C	B101210167	PR
MAYER, L O	B101050256	50-282 P	MCCLELLAN, J H	B101126037	50-416 Q	MCHIRNALL, C	B101210167	PR
MAYER, L O	B101050278	50-263 P	MCCLELLAN, J H	B101260765	50-416 S	MCHIRNALL, C	B101140843	CON
MAYER, L O	B101120210	50-263 P	MCCLELLAN, J H	B101056339	50-416 S	MCHIRNALL, C	B101270674	NUREG
MAYER, L O	B101120294	50-282 R	MCCLELLAN, J H	B101050335	50-416 S	MCHIRNALL, C	B101160017	50-
MAYER, L O	B101130575	50-263 R	MCCLELLAN, J H	B101050327	50-416 K	MCHIRNALL, C	B101060268	50-
MAYER, L O	B101160445	50-282 P	MCCLELLAN, J H	B101050325	50-416 K	MCHIRNALL, C	B101270528	NUREG
MAYER, L O	B101200241	50-202 P	MCCLELLAN, J H	B101070415	50-416 A	MCHIRNALL, C	B101190356	71-
MAYER, L O	B101230490	50-263 Q	MCCLELLAN, J H	B101260519	50-416 S	MCHIRNALL, C	B101280341	50-
MAYER, L O	B101260498	50-263 Q	MCCLELLAN, J H	B101270088	50-416 S	MCHIRNALL, C	B101280499	50-
MAYER, L O	B101270635	50-202 S	MCCLELLAN, J H	B101190147	50-416 S	MCHIRNALL, C	B101210455	50-
MAYER, L O	B101270693	50-282 P	MCCLELLAN, J H	B101250241	50-416 S	MCHIRNALL, C	B101210455	50-
MAYER, L O	B101070092	50-289 H	MCCLELLAN, J H	B101270104	50-416 S	MCHIRNALL, C	B101270491	50-
MAYN, B G	B101120337	50-244 P	MCCLELLAN, J H	B101230500	50-416 S	MCHIRNALL, C	B101050317	50-
MAYN, B G	B101120342	50-244 P	MCCLELLAN, J H	B101230599	50-416 S	MCHIRNALL, C	B101280711	CON
MAYNARD, H J	B101190453	PR	MCCLELLAN, J H	B101230607	50-416 S	MCHIRNALL, C	B101060739	CON
MAYNARD, C A	B101260734	PR	MCCLELLAN, J H	B101230482	50-416 S	MCHIRNALL, C	B101090500	FOIA
MAYNARD, T	B101270804	PR	MCCLELLAN, J H	B101270843	50-416 A	MCHIRNALL, C	B101260775	FOIA
MAYS, B E	B101300175	50-266 P	MCCLELLAN, J H	B101300328	50-416 S	MCHIRNALL, C	B1012103175	70-
MAZUR, D H	B101060005	50-460 Q	MCCLELLAN, J H	B101300424	50-416 S	MCHIRNALL, C	B1012103175	70-
MAZUR, D H	B101300988	50-450 Q	MCCLELLAN, J H	B101300455	50-416 S	MCHIRNALL, C	B1012103175	70-
MAZUR, D H	B101270464	50-397 Q	MCCLELLAN, J H	B101300475	50-416 S	MCHIRNALL, C	B1012103175	70-
MAZUR, A	B101280398	FOIA	MCCLELLAN, J H	B101280695	50-247 II	MCHIRNALL, C	B1012103175	70-

0101070474	50-428	S	MINECK, D L	810122035	
0101070475	50-328	S	MINECK, D L	810122036	
0101070432	50-390	S	MINECK, D L	810122037	
0101200411	50-327	P	MINECK, D L	810122038	
0101140635	50-328	S	MINECK, D L	810130033	
0101210157	50-299	Q	MINECK, L E	810122039	
0101220302	50-759	Q	MINECK, J E	810115038	
0101280505	50-299	Q	MINECK, R B	810106039	
0101290235	50-510	Q	MINECK, R B	802033053	
0101140485	50-324	S	MINECK, R B	801202039	
0101140593	50-390	S	MINECK, P	801208038	
0101210239	50-320	Q	MINECK, M	810128023	
0101280427	50-328	H	MINECK, M	810130035	
0101150207	50-328	A	MINECK, M	810118038	
0101140477	50-510	S	MINECK, V	810123054	
0101140611	50-438	B	MINECK, F	810109037	
0101140474	50-328	S	MINECK, F J	810106033	
0101140610	50-390	B	MINECK, F J	810109037	
0101140627	50-438	S	MINECK, F J	810112032	
0101160427	50-327	P	MINECK, F J	810107045	
0101270245	50-390	S	MINECK, F J	810115038	
0101290672	50-391	S	MINECK, F J	810115038	
0101140616	50-320	B	MINECK, F J	810115038	
0101160462	50-390	S	MINECK, F J	810114022	
0101170382	50-438	S	MINECK, F J	810114022	
0101190400	50-320	S	MINECK, F J	810114022	
0101190405	50-390	S	MINECK, F J	810114022	
0101190475	50-566	S	MINECK, F J	810114022	
0101190480	50-328	S	MINECK, F J	810114022	
0101190485	50-320	S	MINECK, F J	810114022	
0101190491	50-390	S	MINECK, F J	810114022	
0101190494	50-320	S	MINECK, F J	810114022	
0101190495	50-296	S	MINECK, F J	810114022	
0101210370	50-510	S	MINECK, F J	810114022	
0101230276	50-391	S	MINECK, F J	810114022	
0101230311	50-439	S	MINECK, F J	810114022	
0101160410	50-390	A	MINECK, J	810114022	
0101160494	50-327	P	MINECK, J	810114022	
0101170360	50-328	S	MINECK, J	810114022	
0101210372	50-438	S	MINECK, J	810114022	
0101210340	50-593	S	MINECK, J	810114022	
0101210121	50-390	S	MINECK, J	810114022	
0101260409	50-390	S	MINECK, J	810114022	
0101220207	50-593	A	MINECK, J	810114022	
0101220311	50-259	S	MINECK, R L	810102030	
0101230468	50-390	Q	MINECK, R L	801219032	
0101230480	50-438	B	MINECK, R L	810110032	
0101280527	50-259	Q	MINECK, R L	810116031	
0101220155	50-327	H	MINECK, R L	8101220103	
0101230271	50-327	P	MINECK, R L	810115035	
0101230372	50-438	A	MINECK, R L	810115035	
0101230426	50-510	S	MINECK, R L	810122044	
0101230542	50-390	S	MINECK, R L	810116035	
0101230553	50-390	S	MINECK, R L	810110038	
0101230562	50-320	B	MINECK, R L	810110039	
0101230600	50-390	S	MINECK, R L	810110039	
0101260428	50-390	S	MINECK, R L	810110039	
0101260446	50-438	S	MINECK, R L	810110039	
0101260430	50-299	Q	MINECK, R L	810110039	
0101260433	50-438	K	MINECK, T	810113060	
0101270562	50-320	A	MINECK, T	810120064	
0101230638	50-402	Q	MINECK, E	810130066	
0101260593	50-295	D	MINECK, E	810115072	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MCCRE, R. W.	8101100081	FOIA	MCCRE, R. W.	8101100081	FOIA	MURRAY, M. J.	8101200046	50-1
MCCRE, R. W.	8101100072	FOIA	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101210432	PR	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101150477	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101120031	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101280466	PR	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101280466	PR	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101090531	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101070305	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101070652	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101260550	PR	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101140350	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101140076	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101150467	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101150620	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101070436	50-334 R	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101270187	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101270210	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101160229	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, R. W.	8101260095	XPORTELIC	MCCRE, R. W.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101080000	50-155 G	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101160104	50-142 A	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101220001	50-193 D	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101220017	50-155 G	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101220020	50-155 G	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101200026	50-155 G	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101270781	PR	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101270037	PR	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8012120051	PR	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101190020	PR	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101090050	ICPREP	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101210559	PR	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101130060	50-322 K	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101110727	50-293 G	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101270445	PR	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.	8101070307	50-293 P	MCCRE, J. E.	8101200046	50-1	MURRAY, T. D.	8101200046	50-1
MCCRE, J. E.								

[illegible]

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PAPERIELLO, C. J.	8101090114	50-255 Q	PASTERNAK, R. J.	8101210499	50-333 S	PETRICK, H. A.	8101090757	50-333 S
PAPERIELLO, C. J.	8101070125	50-10 U	PASTERNAK, R. J.	8101200126	50-333 S	PETRICK, H. A.	8101290264	50-333 S
PAPERIELLO, C. J.	8101080420	0A999	PASTVA, H. J.	8101220528	50-324 S	PETRICK, H. A.	8101230550	50-333 S
PAPERIELLO, C. J.	8101132640	50-295 Q	PASTVA, H. J.	8101140514	50-324 S	PETROME, C.	8101300727	50-333 S
PAPERIELLO, C. J.	8101140098	50-373 Q	PASTVA, H. J.	8101200620	50-324 S	PETTINGILL, H.	8101120154	40-333 S
PAPERIELLO, C. J.	8101260729	50-346 Q	PASTVA, H. J.	8101200629	50-325 S	PETTINGILL, H. J.	8101290230	40-333 S
PASAS, H.	8101090312	0A0	PASTVA, H. J.	8101130540	50-324 S	PEVENSTEIN, J. E.	8101260459	50-333 S
PASA, A.	8101200451	PR	PASTVA, H. J.	8101220596	50-325 S	PEVENSTEIN, J. E.	8101200464	50-333 S
PASK, M. A.	8101230329	PR	PASTVA, H. J.	8101270631	50-325 S	PEVENSTEIN, J. E.	8101260469	50-333 S
PARKER, W. B.	8101070316	50-413 Q	PASTVA, H. J.	8101270708	50-324 S	PEVENSTEIN, J. E.	8101290474	50-333 S
PARKER, W. B.	8101070520	50-369 Q	PASTVA, H. J.	8101280282	50-324 S	PEVENSTEIN, J. E.	8101280451	50-333 S
PARKER, W. B.	8101080140	50-269 Q	PASTVA, H. J.	8101270595	50-329 G	PEVENSTEIN, J. E.	8101290470	50-333 S
PARKER, B.	8101280341	PR	PASTVA, H. J.	8101270695	50-324 S	PHILLIPS, S. S.	8101290517	ACN
PARKER, W. B.	8101070113	50-413 Q	PASTVA, H. J.	8101270794	50-324 S	PHILLIPS, J. H.	8101270519	50-333 S
PARKER, R.	8101210095	PH	PASTVA, H. J.	8101270605	50-324 S	PHILLIPS, G. A.	8101090142	50-333 S
PARKER, W. B.	8101070295	RE00D	PASTVA, H. J.	8101270597	50-324 S	PHILLIPS, H. P.	8101090114	50-333 S
PARKER, W. B.	8101120318	RE00D	PASUPATHI, V.	8101270560	50-213 S	PHILLIPS, H. P.	8101070175	50-333 S
PARKER, W. B.	8101070145	50-369 Q	PATENAUGE, C. J.	8101220188	RES	PHILLIPS, H. P.	8101150640	50-333 S
PARKER, W. B.	8101150136	50-269 Q	PATON, W. D.	8101050003	50-329 T	PHILLIPS, L.	8101270012	HW
PARKER, W. B.	8101150907	50-369 Q	PATON, W. D.	8101050421	50-329 G	PHILLIPS, L. E.	8101210225	50-333 S
PARKER, W. B.	8101150168	50-369 F	PATON, W. D.	8101050073	50-329 G	PHILPOTT, F. T.	8101220380	50-333 S
PARKER, W. B.	8101200227	50-269 P	PATON, W. D.	8101140072	50-329 G	PHUNH, M.	8101240725	70-333 S
PARKER, W. B.	8101160668	50-413 Q	PATON, W. D.	8101270329	50-329 G	PIANKI, F. J.	8101300164	70-333 S
PARKER, W. B.	8101050107	50-287 P	PATON, W. D.	8101270594	50-329 G	PICKARD, A. H.	8101200532	PR
PARKER, W. B.	8101190765	50-369 Q	PATTERSON, W. D.	8101090507	FOIA	PICKARD, R. C.	8101220377	PR
PARKER, W. B.	8101050949	50-269 P	PATTERSON, J. P.	8101050590	70-27	PIERCE, B. L.	8101230523	RES
PARKER, W. B.	8101050351	50-287 S	PATTERSON, J. L.	8101210269	FR	PIERCE, C.	8101160316	PR
PARKER, W. B.	8101060403	50-269 P	PAITEN, L.	8101260032	PR	PIERSON, M. D.	8101200214	50-333 S
PARKER, W. B.	8101160298	50-269 Q	PATTEN, L. C.	8101260307	PR	PICOTT, D. R.	8101230128	50-333 S
PARKER, W. B.	8101160724	50-369 Q	PATTERSON, T. L.	8101160488	50-288 H	PICOTT, D. R.	8101230137	50-333 S
PARKER, W. B.	8101070269	50-269 P	PATTON, G. A.	8101300391	FR	PICOTT, D. R.	8101230137	50-333 S
PARKER, W. B.	8101090657	50-287 S	PAUL, T. W.	8101160526	50-259 G	PICOTT, D. R.	8101230137	50-333 S
PARKER, W. B.	8101190462	50-369 F	PAULK, J. I.	8101130371	50-241 H	PIELANT, J. H.	8101070542	50-333 S
PARKER, W. B.	8101201333	50-369 A	PAULSON, H. A.	8101230347	50-155 P	PIELANT, J. H.	8101080074	50-333 S
PARKER, W. B.	8101270404	50-369 Q	PAULY, S. A.	8101140223	50-109 J	PIELANT, J. H.	8101070155	50-333 S
PARKER, W. B.	8101290408	50-413 Q	PAYNE, J. D.	8101270508	PR	PIELANT, J. H.	8101120050	50-333 S
PARKER, W. B.	8101200575	50-269 Q	PEARLMAN, C.	8101260059	PR	PIELANT, J. H.	8101120138	50-333 S
PARKER, W. B.	8101130401	50-269 P	PEABE, E. A.	8101190179	PR	PIELANT, J. H.	8101050465	50-333 S
PARKER, W. B.	8101140600	50-413 S	PECK, C. C.	8101100511	50-6 Q	PIELANT, J. H.	8101120162	50-333 S
PARKER, W. B.	8101210213	50-269 Q	PETERS, S. C.	8101270520	1-R	PIELANT, J. H.	8101160440	50-333 S
PARKER, W. B.	8101290597	50-269 F	PELLETIER, B. C.	8101150103	PR	PILAT, E. G.	8101080443	50-333 S
PARKER, W. B.	8101290192	50-369 Q	PENCE, W. B.	8101220398	50-318 G	PILKERTON, T.	8101190230	PR
PARKER, W. B.	8101160443	50-369 F	PENCE, W. B.	8101130623	50-317 S	PIMMER, H.	8101200259	PR
PARKER, W. B.	8101260513	50-369 B	PENCE, W. B.	8101230461	50-318 S	PINSKY, R.	8101300074	PR
PARKER, W. B.	8101300576	50-270 S	PENCE, W. B.	8101330538	50-317 S	PIRTLE, G. L.	8101060390	50-333 S
PARKER, W. B.	8101160366	50-269 P	PENDERGRAFT, R.	8101050367	50-368 S	PISCELO, D. H.	8101300422	PR
PARKER, W. B.	8101230493	50-369 A	PENDERGRAFT, R.	8101210514	50-268 R	PITCHER, D.	8101070446	PR
PARKER, W. B.	8101190385	50-269 Q	PEOPLE, B. L.	7711270339	50-10 P	PITTS, M.	8101160160	PR
PARKER, W. B.	8101210511	50-207 B	PEOPLE, B. L.	0003240464	50-237 P	PLESSET, H. S.	8101202078	ACR
PARKER, W. B.	8101210462	50-269 R	PEPPER, A. H.	8101300287	PR	PLESSET, H. S.	8101070545	50-333 S
PARKER, W. B.	8101210493	50-269 P	PERCY, O. W.	8101210345	50-250 P	PLETTHAN, S.	8101230304	50-333 S
PARKER, W. B.	8101210502	50-269 S	PEREZ, M.	8101160540	PR	PLEVER, B.	8101170624	PR
PARKER, W. B.	8101220420	50-269 P	PEREZ, C. A.	8101200027	50-465 G	PLUMLEE, K. E.	8101300040	50-333 S
PARKER, W. B.	8101220370	50-269 S	PERKINS, J.	8101300669	PR	PLUMLEE, K.	8101280374	50-333 S
PARKER, W. B.	8101230440	50-269 F	PERLMAN, J.	8101060942	CONTRACT	POANNI, J.	8101130112	50-333 S
PARKER, W. B.	8101230409	50-269 S	PERLMAN, J.	8101070319	50-367 A	POCAL, W. F.	8101100525	XPC
PARKER, W. B.	8101270640	50-270 S	PERLMAN, J.	8101060770	CONTRACT	POCAL, W. F.	8101070446	PR
PARKER, W. B.	8101300160	50-369 A	PERLMAN, J.	8101290341	CONTRACT	POCAL, W. F.	8101290193	RES
PARKER, W. B.	8101300436	50-369 F	PERLMAN, J.	8101270723	50-320 P	POCAL, W. F.	8101290674	RES
PARKER, W. B.	8101190229	70-371	PERLMAN, J.	8101200471	CONTRACT	POINDEXTER, C. H.	8101060333	50-333 S
PARR, D. D.	8101060353	50-369 A	PERLMAN, J.	8101200480	CONTRACT	POLLARD, R. O.	8101130547	50-333 S
PARTLOW, J. O.	81012100344	70-734	PERLMAN, J.	8101290530	50-70 P	POLLARD, R. O.	8101070446	50-333 S
PARTLOW, J. O.	81012100327	70-364	PERLMAN, J.	8101290541	50-70 P	POPEROV, P. W.	8101200473	CCN
PARTLOW, J. O.	8101060851	50-409 P	PERLMAN, J.	8101200432	CONTRACT	POPEROV, P. W.	8101200473	PR
PARTLOW, J. O.	8101060873	50-213 P	PERLMAN, J.	8101270741	CONTRACT	POSPIAN, R. K.	8101210301	PR
PARTLOW, J. O.	8101150029	70-27	PERLMAN, J.	8101300104	50-390 A	POOLE, D.	8101160438	50-333 S
PARTLOW, J. O.	8101060921	70-820	PERLMAN, J.	8101200469	PR	POOLE, D.	8101210512	50-333 S
PARTLOW, J. O.	8101080398	70-143	PERNEY, C. B.	8101220095	50-395 Q	PORTER, W. E.	8101200252	50-333 S
PARTLOW, J. O.	8101120214	70-371	PEARLCO, L. O.	8101220228	RES	PORTER, I. B.	8101700275	PR
PARTLOW, J. O.	8101120219	70-143	PERRY, R. W.	8101220219	RES	PORTER, A.	8101290512	PR
PARTLOW, J. O.	8101190262	70-020	PERRY, L.	8101270740	PR	PORTER, W. L.	8101050416	50-333 S
PARTLOW, J. O.	8101190260	70-1100	PERRY, R.	8101070272	40-299	PORTER, W. L.	8101070062	50-333 S
PARTLOW, J. O.	8101190244	70-143	PERTEB, L.	8101220602	PR	PORTER, W. L.	8101160620	50-333 S
PARTNER, A. S.	8101270723	50-320 P	PESCHAU, D. F.	8101050309	50-409 H	PORTER, W. L.	8101260209	50-333 S
PARTZALE, A. A.	8101220180	RES	PESL, M.	8101190607	PR	POSE, K.	8101270811	PR
PASI, U.	8101210143	PR	PESTQUE, S.	8101230617	PR	POTAPOV, U.	8101203117	0A9
PASTERNAK, R. J.	8101300074	50-333 Q	PETERSON, R. R.	8101100230	50-320 H	POTAPOV, U.	8101150458	0A9
PASTERNAK, R. J.	8101080129	50-333 Q	PETERSON, A. S.	8101080335	PR	POTAPOV, U.	8101150458	0A9
PASTERNAK, R. J.	8101140766	50-333 Q	PETERS, T. J.	8101200544	PR	POTAPOV, U.	8101210255	0A9
PASTERNAK, R. J.	8101140975	50-333 Q	PETERSON, R. W.	8101260245	50-320 G	POTAPOV, U.	8101190780	0A9
PASTERNAK, R. J.	8101130552	50-333 R	PETERSON, D. W.	8101210380	50-250 P	POTAPOV, U.	8101210512	0A9
PASTERNAK, R. J.	8101120302	50-333 S	PETERSON, H. E.	8101270731	50-205 J	POTAPOV, U.	8101210512	0A9
PASTERNAK, R. J.	8101120306	50-333 B	PETIT, R.	8101140214	50-443 H	POTAPOV, U.	8101150374	0A9
PASTERNAK, R. J.	8101160508	50-333 B	PETIT, R.	8101090160	50-443 H	POTAPOV, U.	8101270970	0A9
PASTERNAK, R. J.	8101210492	50-333 S	PETRIE, E. R.	8101160066	PR	POTAPOV, U.	8101150345	0A9

[illegible]

[illegible]

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SMETEV, J. H.	0101070574	70-728	SOUDER, J. L.	0101303111	50-445 F	STENHART, W.	0101210118	50-744
SMETEV, J. H.	0101070581	70-734	SOUDER, J. L.	0101303079	50-435 F	STELL, V.	0101120177	50-142
SMETEV, J. H.	0101070585	50-100 Q	SOUDER, J. L.	0101300117	50-320 F	STELL, V.	0101260158	FOIA
SMETEV, J. H.	0101070589	50-131 Q	SOUDER, J. L.	0101300122	50-282 F	STELL, V.	0101260177	FOIA
SMETEV, J. H.	0101070592	40-6479	SOUDER, J. L.	0101303702	50-483 L	STELL, V.	0101260177	FOIA
SMETEV, J. H.	0101070591	70-568	SOUDER, J. L.	0101300705	50-483 C	STELL, V.	0101260189	FOIA
SMETEV, J. H.	0101270190	50-247 Q	SOUDER, J. L.	0101290148	50-266 F	STELL, V.	0101260148	FOIA
SMITH, D.	0101230624	PR	SOUDER, J. L.	0101290154	50-287 F	STELL, V.	0101090193	FOIA
SNOW, B. A.	0101210639	50-244 S	SOUDER, J. L.	0101290158	50-369 F	STELL, V.	0101090189	FOIA
SNOW, N.	0101260705	PR	SOUDER, J. L.	0101290162	50-245 F	STELL, V.	0101260144	FOIA
SNOW, B. A.	0101210174	50-244 P	SOUDER, J. L.	0101290165	50-280 F	STELL, V.	0101090189	FOIA
SNYDER, B. J.	0101270200	50-320 P	SOUDER, J. L.	0101290167	50-709 F	STELL, V.	0101260158	50-237
SNYDER, B. J.	0101290203	50-320 P	SOUDER, J. L.	0101290173	50-361 F	STELL, V.	0101090189	50-498
SNYDER, B. J.	01012120019	50-320 P	SOUDER, J. L.	0101290174	50-155 F	STELL, V.	0101150591	50-247
SNYDER, B. J.	0101140743	50-320 S	SOUDER, J. L.	0101290175	50-213 F	STELL, V.	0101260182	50-247
SNYDER, D. J.	0101000330	50-320 H	SOUDER, J. L.	0101300857	50-395 F	STELL, V.	0101260189	50-329
SNYDER, B. J.	0101060636	50-209 H	SOUDER, J. L.	0101210584	50-289 H	STELL, V.	0101260189	50-247
SNYDER, H. L.	0101060790	CONFRACT	SPANGLER, B. A.	0101060347	CONFRACT	STELL, V.	0101260189	50-271
SNYDER, B. J.	0101070323	50-320 P	SPANGLER, R. O.	0101100331	50-298 Q	STELL, V.	0101260189	50-271
SNYDER, B. J.	0101140237	50-320 H	SPILL, W. H.	0101140122	State Prop	STELL, V.	0101260189	50-271
SNYDER, D. J.	0101190640	50-320 P	SPENCER, O. S.	0101300393	50-440 Q	STELL, V.	0101260189	50-271
SNYDER, B. J.	0101140571	50-320 P	SPENCER, O. S.	0101271052	50-344 Q	STELL, V.	0101260189	50-247
SNYDER, H. L.	0101290440	40-8984	SPENCER, O. S.	0101300763	50-361 Q	STELL, V.	0101150591	40-8654
SNYDER, H. L.	0101090161	40-8584	SPENCER, O. S.	0101300765	50-361 Q	STELL, V.	0101150591	40-8654
SNYDER, H. L.	0101210329	40-8584	SPENCER, O. S.	0101290643	50-397 Q	STEPHENS, R. S.	0101260189	FR
SNYDER, B. J.	0101210237	50-320 P	SPENCER, O. S.	0101210145	50-275 Q	STERTON, P.	0101210473	50-10
SNYDER, B. J.	0101271024	50-320 P	SPENCER, O. S.	0101220520	50-508 Q	STERN, W. C.	0101060710	ADPOTIC
SNYDER, D. J.	0101210637	50-320 P	SPENCER, O. S.	0101200756	50-361 Q	STERN, M.	0101260189	PR
SNYDER, B. J.	0101260234	50-320 Q	SPENCER, O. S.	0101270707	50-404 S	STERLING, D. M.	0101210517	50-275
SNYDER, D. J.	0101270244	50-320 P	SPENCER, O. S.	0101300583	50-460 Q	STERLING, D. M.	0101210517	50-397
SNYDER, D. J.	0101270227	50-320 H	SPERDUFF, R.	0101060484	50-237 S	STEVENS, R. L.	0101090189	70-1607
SNYDER, H. L.	0101270610	40-8984	SPERDUFF, R.	0101140620	50-249 S	STEVENS, R. L.	0101150591	40-8654
SPIDER, A.	0101270710	50-294 S	SPERDUFF, R.	0101260671	50-237 S	STEVENS, R. L.	0101070561	70-371
SOLERO, R.	0101160511	PR	SPERRY, J. E.	0101200364	PRD J	STEVENS, R. L.	0101070561	70-371
SOLLEATO, J.	0101160583	PR	SPESBARD, R. L.	0101090142	50-237 Q	STEVENS, R. L.	0101260189	CONFRACT
SOLLO, L. R.	0101190674	Blade Prog	SPESBARD, R. L.	0101130592	50-373 Q	STEVENS, R. L.	0101260189	70-1257
SMELA, V.	0101160277	PR	SPESBARD, R. L.	0101080392	50-254 Q	STEWART, R. C.	0101260243	50-282
SOO, P.	0101220622	HEB	SPESBARD, R. L.	0101140697	50-295 Q	STEWART, R. C.	0101120696	50-382
SODAO, A. L.	0101270320	70-8112	SPESBARD, R. L.	0101090785	50-10 Q	STEWART, R. C.	0101140550	50-382
SOUDER, J. L.	0101090716	50-266 F	SPESBARD, R. L.	0101150663	50-273 Q	STEWART, R. C.	0101260189	50-382
SOUDER, J. L.	0101140137	50-498 F	SPESBARD, R. L.	0101300796	50-155 Q	STEWART, R. C.	0101260508	50-382
SOUDER, J. L.	0101140445	50-213 F	SPIEGEL, J.	0101303079	PR	STEWART, R. C.	0101193140	FOIA
SOUDER, J. L.	0101060615	50-738 F	SPIFLES, P. R.	0101280061	40-8677	STEWART, R. C.	0101210377	50-445
SOUDER, J. L.	0101070200	50-27 F	SPIFLES, P. R.	0101280366	40-8380	STIFFER, H.	0101050395	50-483
SOUDER, J. L.	0101070230	50-7 F	SPITZ, H.	0101260275	PR	STILL, J. H.	0101060498	50-395
SOUDER, J. L.	0101070294	50-443 F	SPRINGER, O.	0101270070	50-488 G	STILLMAN, J. L.	0101060535	50-272
SOUDER, J. L.	0101070297	50-327 F	SPRING, O.	0101200122	40-872 F	STILLMAN, J. L.	0101260243	50-286
SOUDER, J. L.	0101000146	50-738 F	STAKE, T.	0101100375	FOIA	STON, J. P.	0101070535	50-321
SOUDER, J. L.	0101090709	50-263 F	STAFF, M. H.	0101090331	50-465 H	STON, J. P.	0101080726	50-250
SOUDER, J. L.	0101090722	50-327 F	STAGGS, D. O.	0101210394	CONFRACT	STON, J. P.	0101270118	27-47
SOUDER, J. L.	0101140429	50-250 F	STAMIRIS, B.	0101050314	50-329 H	STON, J. P.	0101150015	50-269
SOUDER, J. L.	0101100719	50-334 F	STANLEY, M. A.	0101090145	50-289 H	STON, J. P.	0101070331	50-371
SOUDER, J. L.	0101100724	50-327 F	STANLEY, L.	0101080111	REGD	STON, J. P.	0101050454	50-516
SOUDER, J. L.	0101100729	50-200 F	STARKEY, R. B.	0101190426	50-261 V	STON, J. P.	0101190320	50-369
SOUDER, J. L.	0101100731	50-245 F	STARKE, R. H.	0101220069	50-307 A	STON, J. P.	0101190228	50-390
SOUDER, J. L.	0101100741	50-275 F	STARKE, R. H.	0101080196	50-387 A	STON, J. P.	0101190234	50-395
SOUDER, J. L.	0101100745	50-263 F	STARKEY, R. B.	0101080578	50-261 S	STON, J. P.	0101190442	50-280
SOUDER, J. L.	0101100749	50-199 F	STARKEY, R. B.	0101080589	50-261 S	STON, J. P.	0101190339	50-250
SOUDER, J. L.	0101100753	50-369 F	STARKE, R. H.	0101290146	50-387 F	STON, J. P.	0101190351	50-321
SOUDER, J. L.	0101140039	50-317 F	STARKEY, R. B.	0101170823	50-261 R	STON, J. P.	0101190359	50-261
SOUDER, J. L.	0101140285	50-317 F	STARKEY, R. B.	0101210460	50-261 S	STON, J. P.	0101210565	50-269
SOUDER, J. L.	0101140294	50-269 F	STARKEY, R. B.	0101300569	50-261 S	STON, J. P.	0101050531	CONFRACT
SOUDER, J. L.	0101140301	50-348 F	STARKEY, R. B.	0101280563	50-261 S	STON, J. P.	0101080330	CONFRACT
SOUDER, J. L.	0101140310	50-255 F	STARKEY, R. B.	0101280571	50-261 S	STON, J. P.	0101130033	CONFRACT
SOUDER, J. L.	0101140315	50-309 F	STARSHAW, R. J.	0101080557	PR	STON, J. P.	0101260252	FR
SOUDER, J. L.	0101140325	50-324 F	STARSHAW, R. J.	0101140133	PR	STON, J. C.	0101140396	REGD
SOUDER, J. L.	0101140332	50-399 F	STATION, T. H.	0101290727	PR	STOUT, J.	0101060542	50-746
SOUDER, J. L.	0101150442	50-289 F	STEADMAN, F. H.	0101200277	PR	STRASSBURG, R.	0101270293	PP
SOUDER, J. L.	0101150447	50-289 F	STEELE, W. J.	0101090631	50-272 S	STREETER, J. F.	0101160156	50-304
SOUDER, J. L.	0101190705	50-320 F	STEELE, W. J.	0101090707	50-272 S	STREETER, J. F.	0101160344	50-315
SOUDER, J. L.	0101280092	50-289 F	STEELE, W. J.	0101120324	50-272 S	STREETER, J. F.	0101270573	50-282
SOUDER, J. L.	0101160616	50-346 F	STEELE, W. J.	0101120376	50-272 S	STREETER, J. F.	0101210654	50-346
SOUDER, J. L.	0101190123	50-302 F	STEELE, W. J.	0101200359	50-272 S	STRICKLER, L. J.	0101260200	FOIA
SOUDER, J. L.	0101190688	50-369 F	STEELE, W. J.	0101200371	50-272 S	STRICKLER, L. J.	0101260189	FOIA
SOUDER, J. L.	0101190692	50-286 F	STEELE, W. J.	0101260642	50-272 S	STRICKLER, L. J.	0101260151	50-320
SOUDER, J. L.	0101190696	50-313 F	STEELE, W. J.	0101270569	50-272 S	STRICKLER, L. J.	0101260128	FOIA
SOUDER, J. L.	0101190700	50-273 F	STEELE, E. H.	0101220225	50-395 A	STRICKLER, L. J.	0101260391	50-320
SOUDER, J. L.	0101190709	50-286 F	STEEFENS, N. I.	0101060277	50-170 H	STRICKLER, L. J.	0101260687	FOIA
SOUDER, J. L.	0101200394	50-313 F	STEFEN, H.	0101160240	50-463 C	STROUPE, E. P.	0101210597	TEPPEP
SOUDER, J. L.	0101270988	50-320 F	STEINACH, T.	0101210649	PR	STRUBE, W. P.	0101200033	50-466
SOUDER, J. L.	0101270995	50-155 F	STEIFF, A.	0101190070	PR	STROVE, L.	0101190357	PR
SOUDER, J. L.	0101270998	50-329 F	STEINDLER, H.	0101200510	ACRS	STUDER, M.	0101270331	PR
SOUDER, J. L.	0101300103	50-312 F	STEIN, L. L.	0101290721	PR	SU, T. H.	0101140955	50-322
SOUDER, J. L.	0101300108	50-219 F	STEINMETZ, J. D.	0101070808	FOIA	SULLIVAN, T. J.	0101080778	REGD
SOUDER, J. L.	0101300115	50-327 F	STEINBACH, S. E.	0101220160	PR	SULLIVAN, M. H.	0101200447	PR

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	ELCUG CATEGORY
SULLIVAN, C J	B101090527	50-185 P	TEDESCO, R L	B101090527	50-437 A	THOMPSON, A J	B101070633	PR
SUMMERLEE, V L	B101120527	50-2661 PR	TEDESCO, R L	B101106075	50-286 F	THOMPSON, H L	B101060906	50-3
SUND O	B101290527	PR	TEDESCO, R L	B101106075	50-440 A	THOMPSON, H G	B101270014	PR
SUTHERLAND, E	B101160757	PR	TEDESCO, R L	B101140810	50-390 A	THOMPSON, R	B101270437	PR
SUTHERLIN, R H	B1011000136	50-329 1	TEDESCO, R L	B101070616	50-358 1	THOMPSON, D	B101130140	50-10
SUTHER, E	B101280446	PR	TEDESCO, R L	B1010706254	50-369 A	THOMPSON, D	B101130159	50-247
SWAMY, S A	B101150476*	50-295 P	TEDESCO, R L	B101100318	50-461 A	THOMPSON, R	B101060906	50-329
SWAMY, S A	B101160473*	50-286 P	TEDESCO, R L	B101100257	50-416 A	THOMPSON, D	B101090185	50-329
SWAMY, W D	B101100627*	50-518 G	TEDESCO, R L	B101120645	50-413 A	THOMPSON, S L	B101290809	50-286
SWAMY, G T	B101100025	40-3453	TEDESCO, R L	B101120649	50-553 A	THOMPSON, D	B101290275	50-286
SWANBY, C T	B101060693	40-3453	TEDESCO, R L	B101110752	50-424 G	THOMPSON, D	B101200141	40-6354
SWANBY, G T	B1011210197	40-3453	TEDESCO, R L	B101200091	50-395 F	THOMPSON, F T	B1012310308	50-52
SWANBY, C T	B101280605	40-3453	TEDESCO, R L	B101080554	50-395 A	THOMPSON, H D	B101260201*	50-52
SWANBERG, H	B10123144	50-329 G	TEDESCO, R L	B101090702	50-307 A	THOMPSON, H D	B101270649	50-286
SWANSON, J	B101280377	PR	TEDESCO, R L	B101100505	50-323 A	THOMPSON, R E	B101090056	50-286
SWAYNE, L O T	B101120536	50-259 G	TEDESCO, R L	B101150176*	50-413 A	TILL, C E	B101290819	ALREO
SWANSON, O I	B101141442	50-289 G	TEDESCO, R L	B101120176	50-327 E	TILL, E T T L	B101330516	PR
SWART, F E	B101130400*	50-267 P	TEDESCO, R L	B101150596	50-483 A	TILLMAN, A	B101100711*	50-335
SWART, F E	B101080605	50-267 G	TEDESCO, R L	B101119040	50-327 P	TIMKO, D R	B101160467*	50-334
SWART, F E	B101140191	50-267 G	TEDESCO, R L	B101190423	50-397 A	TIMKO, D R	B101160468*	50-334
SWART, F E	B101120143	50-267 G	TEDESCO, R L	B101190734	50-361 G	TINKER, D R	B101160470*	50-334
SWARTZ, W H	B101200466	PR	TEDESCO, R L	B101210136	50-275 G	TINNEY, H	B101260051	PR
SWARTZ, L L	B101050044	50-285 T	TEDESCO, R L	B101139426	50-454 A	TINK, W H	B101050143	PR
SWARTZ, L L	B101090116	50-285 G	TEDESCO, R L	B101160543	50-454 A	TINDALE, H	B101270824	PR
SWARTZ, L L	B101140575	50-275 G	TEDESCO, R L	B101160966	50-483 C	TITUS, V	B101230634	PR
SWARTZ, L L	B101270729	50-275 G	TEDESCO, R L	B101160590	50-410 A	TOBIAS, M L	B101290796	PR
SWART, F E	B101270629	50-267 P	TEDESCO, R L	B101160537	50-352 A	TOBIAS, M L	B101290811	PR
SWEET, K	B101100055	PR	TEDESCO, R L	B101200583	50-430 F	TODIN, J H	B101270272	50-528
SWEETMAN, A	B101300057	PR	TEDESCO, R L	B101200582	50-395 A	TODIN, J S	B101270106*	50-528
SWEETMAN, P	B101300050*	50-309 G	TEDESCO, R L	B101210250	50-482 A	TODOROVICH, M M	B101140423	PR
SWIFT, W	B101070534	RES	TEDESCO, R L	B101200514	50-361 E	TOUBROW, H	B101300674	RES
SWYLER, K J	B101220622	RES	TEDESCO, R L	B101120015	50-438 F	TODT, M	B101270310	PR
SWYLER, K	B101290050	RES	TEDESCO, R L	B101150506	50-311 F	TOUKAR, A	B101270943	PR
SYLVIA, B R	B101070630*	50-338 G	TEDESCO, R L	B101220109	50-329 A	TOLL, I B N	B101270073	50-324
SYLVIA, B R	B101070637*	50-330 G	TEDESCO, R L	B101210549	50-307 F	TOLL, I B N	B101300502	50-325
SYLVIA, B R	B101070294	50-338 G	TEDESCO, R L	B101270070	50-327 E	TOLL, I B N	B101300507*	50-325
SYLVIA, B R	B101150114	50-335 G	TEDESCO, R L	B101270110	50-445 A	TOLL, I B N	B101300568	50-325
SYLVIA, B R	B101160696*	50-260 G	TEDESCO, R L	B101210621	50-361 A	TOLL, I B N	B101300572*	50-325
SYLVIA, B R	B101120120	50-280 G	TEDESCO, R L	B101270621	50-350 A	TOLL, I B N	B101230491*	50-324
SYLVIA, B R	B1012300480	50-339 P	TEDESCO, R L	B101270986	50-395 F	TOLL, I B N	B101050033	50-324
SYLVIA, B R	B101120151	50-280 G	TEDESCO, R L	B101300219	50-341 A	TOLL, I B N	B101300565	50-324
SYLVIA, B R	B101060345	50-330 P	TEDESCO, R L	B101300629	50-350 A	TOLL, I B N	B101090029	50-324
SYLVIA, B R	B101050352	50-338 P	TEDESCO, R L	B101300621	50-445 A	TOLL, I B N	B101050401	50-324
SYLVIA, B R	B101060308	50-330 P	TEDESCO, R L	B101300751	50-350 A	TOLL, I B N	B101070370	50-324
SYLVIA, B R	B101190357	50-281 G	TEDESCO, R L	B101290775	50-395 A	TOLL, I B N	B101070373*	50-324
SYLVIA, B R	B101090588	50-337 P	TEDESCO, R L	B101300230	50-390 F	TOLL, I B N	B101070498	50-324
SYLVIA, B R	B101090474	50-281 S	TEDESCO, R L	B101300810	50-373 A	TOLL, I B N	B101070365	50-324
SYLVIA, B R	B101290396	50-280 G	TEDESCO, R L	B101300625	50-307 A	TOLL, I B N	B101070360	50-324
SYLVIA, B R	B101130628	50-337 V	TEDESCO, R L	B101290339	50-373 G	TOLL, I B N	B101070491	50-324
SYLVIA, B R	B101190483	50-280 P	TEDESCO, R L	B101290155*	50-490 G	TOLL, I B N	B101070493*	50-324
SYLVIA, B R	B101200695	50-280 R	TEDESCO, R L	B101260766	PR	TOLL, I B N	B101070502*	50-324
SYLVIA, B R	B101200718	50-338 P	TEDESCO, R L	B101270572	50-259 H	TOLL, I B N	B101290228	50-324
SYLVIA, B R	B101200278	50-338 P	TENZER, B E	B101290335*	FOIA	TOLL, I B N	B101090511	50-324
SYLVIA, B R	B101200326	50-338 P	TENZER, B E	B101290303*	FOIA	TOLL, I B N	B101090667	50-325
SYLVIA, B R	B101200354	50-280 P	TENZER, B E	B101290278*	FOIA	TOLL, I B N	B101090676*	50-325
SYLVIA, B R	B101230460	50-339 P	TENZER, B E	B101290290*	FOIA	TOLL, I B N	B101170548	50-324
SYLVIA, B R	B101290757	50-338 P	TENZER, B E	B101290116*	FOIA	TOLL, I B N	B101170561	50-324
SYNTHETIC, D	B101190021	PR	TENZER, B E	B101290124*	FOIA	TOLL, I B N	B101170500	50-324
SZABAT, S	B101150200	PR	TENZER, B E	B101290124*	FOIA	TOLL, I B N	B101200624	50-324
T'NIEMI, H D	B101130551*	50-295 S	TENZER, B E	B101190840*	GA997	TOLL, I B N	B101200624	50-325
TAKAR, M	B101060928	50-382 A	TERRY, J	B101140986	PR	TOLL, I B N	B101130535	50-324
TALBOT, P	B101150222	PR	TERRY, J L	B101190463	PR	TOLL, I B N	B101150532	50-324
TALBOT, P	B101210375*	TOPREP	TESAROW, J J	B101060769*	50-285 B	TOLL, I B N	B101160926	50-324
TAPIA, J I	B101140556*	50-490 G	TESAROW, J J	B101130387*	50-285 B	TOLL, I B N	B101160981*	50-324
TAPIA, J I	B101210075*	50-458 G	TEST, R Z	B101090632*	50-213 G	TOLL, I B N	B101210409	50-324
TATE, KAY, J	B101220487	PR	THIES, A C	B101270643	50-287 B	TOLL, I B N	B101220399	50-325
TATE, R O	B101100063*	50-445 G	THOM, T	B101130588*	50-259 R	TOLL, I B N	B101220393	50-325
TAYLOR, D	B101210397	PR	THOM, T	B101130601*	50-259 R	TOLL, I B N	B101220405	50-324
TAYLOR, R	B1011140930	PORTALIC	THOMAS, W O	B101130112*	50-395 A	TOLL, I B N	B101290886	50-324
TAYLOR, J J	B1011140796*	CONTRACT	THOMAS, R O	B101290542*	70-734	TOLL, I B N	B101270627	50-325
TAYLOR, J H	B101230720	50-344 S	THOMAS, W S	B101190320	PR	TOLL, I B N	B101270703	50-324
TAYLOR, J H	B101210359	TOPREP	THOMAS, W S	B101300810	PR	TOLL, I B N	B101280278	50-324
TAYLOR, J H	B101220490	REVIEW GRP	THOMAS, J W	B101220074	PR	TOLL, I B N	B101270587	50-325
TEDESCO, R L	B101060529	TOPREP	THOMAS, E B	B101050377	50-341 K	TOLL, I B N	B101270688	50-324
TEDESCO, R L	B101150311	TOPREP	THOMAS, W M	B101200629	50-280 P	TOLL, I B N	B101270768	50-324
TEDESCO, R L	B101060011	50-311 F	THOMAS, W H	B101220639	50-339 P	TOLL, I B N	B101270600	50-324
TEDESCO, R L	B101050552	50-390 A	THOMAS, W H	B101300193	50-280 P	TOLL, I B N	B101270600	50-324
TEDESCO, R L	B101060119	50-395 A	THOMAS, W H	B101300188	50-378 P	TOLL, I B N	B101100269*	50-488
TEDESCO, R L	B101060296	50-327 P	THOMPSON, D	B101290362*	FOIA	TOLL, I B N	B101200508*	50-382
TEDESCO, R L	B101080036	50-416 G	THOMPSON, D	B101090179*	FOIA	TOLL, I B N	B101050613	50-155
TEDESCO, R L	B101060012	50-275 F	THOMPSON, S L	B101270861	NUREO	TOMPKINS, B A	B101090107	50-456
TEDESCO, R L	B101060059	50-461 A	THOMPSON, D	B101090202*	FOIA	TOMPKINS, B A	B101090341	50-369
TEDESCO, R L	B101100016	50-461 A	THOMPSON, D	B101090213*	FOIA	TOMPKINS, B A	B101260598	PR
TEDESCO, R L	B101100099	50-27 F	THOMPSON, D	B1010100204	FOIA	TOMPKINS, B A	B101090785*	50-10
TEDESCO, R L	B101090682	50-311 E	THOMPSON, A J	B101070638*	PR	TOOLE, Y	B101290737*	50-289

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DOLE, R. J.	0101050133*	50-209 I	UCALL, M. K.	0101066554*	50-272 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNSON, L.	0101140039	PR	UCERITZ, R. A.	0101050623	50-272 F	VAN BRUNT, E. E.	0101010340	50-264 A
ISIA, S.	0101160712	PR	UCERITZ, R. A.	0101200644*	50-272 F	VAN BRUNT, E. E.	0101010340	50-264 A
ISIA, A. D.	0101290646*	50-247 I	UCERITZ, R. A.	0101090643	50-272 F	VAN BRUNT, E. E.	0101010340	50-264 A
ISIA, K. J.	0101220357*	50-200 P	UCERITZ, R. A.	0101120620	50-272 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, P.	01011000175	PR	UCERITZ, R. A.	0101120637	50-272 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101090030	50-295 P	UCERITZ, R. A.	0101150032	50-272 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101290773	50-344 P	UCERITZ, R. A.	0101200055	50-272 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101270584	50-295 P	UCERITZ, R. A.	0101200126	50-272 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101270617	50-295 P	UCERITZ, R. A.	0101260552	50-272 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101220440	50-344 S	UCERITZ, R. A.	0101260557	50-272 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101090730	50-320 P	UCERITZ, R. A.	0101270511	50-272 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101050008	CONTRACT	UCERITZ, R. A.	0101270616	50-272 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101260746	PR	UCERITZ, R. A.	0101300154	50-254 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101140585	PR	UCERITZ, R. A.	0101300186	50-237 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101090229*	50-313 O	UCERITZ, R. A.	0101300229	50-334 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101120166	50-313 O	UCERITZ, R. A.	0101300337	50-305 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101070164*	50-313 O	UCERITZ, R. A.	0101300642	50-10 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101201055	50-313 O	UCERITZ, R. A.	0101300555	50-295 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101120044	50-313 O	UCERITZ, R. A.	0101102004	50-409 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101120174	50-313 O	UCERITZ, R. A.	0101140673	50-304 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101270137	PR	UCERITZ, R. E.	0101120476*	50-250 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101090267	50-313 O	UCERITZ, R. E.	0101080137*	50-335 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101050020	50-313 O	UCERITZ, R. E.	0101140609	50-250 O	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101090331	50-313 O	UCERITZ, R. E.	0101100702*	50-335 O	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101050361	50-368 S	UCERITZ, R. E.	0101150595*	50-339 O	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101050373	50-368 S	UCERITZ, R. E.	0101150125	50-250 O	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101050381	50-368 S	UCERITZ, R. E.	0101050339	50-250 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101050432	50-368 S	UCERITZ, R. E.	0101270638	50-339 D	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101050440	50-368 S	UCERITZ, R. E.	0101050392	50-250 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101050452	50-368 S	UCERITZ, R. E.	0101050402	50-335 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101050463	50-313 O	UCERITZ, R. E.	0101050453	50-250 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101050411	50-313 O	UCERITZ, R. E.	0101060288	50-335 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101050344	50-313 O	UCERITZ, R. E.	0101060297	50-250 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101060355	50-313 O	UCERITZ, R. E.	0101190350	50-250 D	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101090595	50-313 O	UCERITZ, R. E.	0101270643	50-389 O	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101080414	50-313 O	UCERITZ, R. E.	0101060309	50-250 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101260678*	50-313 O	UCERITZ, R. E.	0101060226	50-250 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101120144	50-368 S	UCERITZ, R. E.	0101060374	50-335 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101130474	50-368 S	UCERITZ, R. E.	0101210592*	50-335 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101130543	50-313 O	UCERITZ, R. E.	0101130373	50-339 V	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101150177	50-313 O	UCERITZ, R. E.	0101210162	50-335 D	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101160406	50-313 O	UCERITZ, R. E.	0101210208	50-250 D	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101130439	50-368 S	UCERITZ, R. E.	0101270694	50-335 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101220414	50-368 S	UCERITZ, R. E.	0101120207	50-335 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101190148	50-368 S	UCERITZ, R. E.	0101220150	50-250 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101200247	50-313 O	UCERITZ, R. E.	0101220172	50-250 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101200290	50-368 S	UCERITZ, R. E.	0101230426	50-335 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101230536	50-313 O	UCERITZ, R. E.	0101230078	50-335 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101200411	50-368 S	UCERITZ, R. E.	0101260306	50-278 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101200256	50-368 P	ULLRICH, W. T.	0101070348	50-277 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101200199	50-368 S	ULLRICH, W. T.	0101120429	50-277 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101210440	50-313 O	ULLRICH, W. T.	0101230352	50-278 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101210509	50-368 R	ULLRICH, W. T.	0101220748	50-277 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101220136	50-313 O	ULLRICH, W. T.	0101203226	PR	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101260384	50-313 O	ULMER, J. H.	0101205230	PR	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101270356	50-313 O	ULMER, J. H.	0101090209*	50-317 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101270372	50-368 S	ULMER, J. H.	0101050413*	50-317 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101270742	50-313 O	ULMER, J. H.	0101090688	50-369 H	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101290936	50-313 O	ULMER, J. H.	0101090688	50-272 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101100503*	50-271 O	UNDERWOOD, H. A.	0101090514	50-369 H	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101290047	70-2623	UTLEY, E. E.	0101220194	REC'D	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101290047	70-2623	UTLEY, E. E.	0101290184	PR	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101060923	REB	UTLEY, E. E.	0101230366*	50-261 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101190603	REB	UTLEY, E. E.	0101060494	50-374 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101190603	REB	UTLEY, E. E.	0101210137*	50-261 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101230225	50-209 O	UTLEY, E. E.	0101260637*	50-374 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101230225	50-289 O	UTLEY, E. E.	0101060453	50-261 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101160632	PR	UTLEY, E. E.	0101050165	50-261 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101090688*	50-254 S	UTLEY, E. E.	0101060587	50-324 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101210465*	50-254 R	UTLEY, E. E.	0101280555	PR	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101060200*	CONTRACT	UTLEY, E. E.	0101160442	50-324 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101220568	70-2909	UTLEY, E. E.	0101150618	50-261 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101150292	70-2909	UTLEY, E. E.	0101190414	50-324 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101290136	70-2909	UTLEY, E. E.	0101190609	50-324 P	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101090609*	50-271 P	UTLEY, E. E.	0101230600	50-261 F	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101080403*	50-271 P	UTLEY, E. E.	0101140096	State Prog	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101080443*	50-271 P	UTLEY, E. E.	0101190373	PR	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101290741	RES	UTLEY, E. E.	0101120078	50-528 A	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101290611	NUREG	UTLEY, E. E.	0101220036	50-528 O	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101210636*	50-271 P	UTLEY, E. E.	0101060500	50-528 A	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101260074	PR	UTLEY, E. E.	0101060425	50-528 S	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101210052*	COMMISSION	UTLEY, E. E.	0101060594	50-528 A	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101140846*	70-143	UTLEY, E. E.	0101060478	50-528 H	VAN BRUNT, E. E.	0101010340	50-264 A
JOHNS, T. R.	0101060953*	COMMISSION	UTLEY, E. E.	0101070354	50-528 H	VAN BRUNT, E. E.	0101010340	50-264 A

[illegible]

WITHERS, B D	8101060000	50-344	Q	YECMAI, B	0101190719	PR	ZAJAC, L D	8101060000	50-518	
WITHERS, B D	0101120567	50-344	Q	YIN, I T	0101290438	50-254	ZAJAC, L D	8101060000	50-408	Q
WITHERS, B D	0101070146	50-344	P	YINCE, H O	0101060438	50-395	ZAJAS, T D	0101260000	50-552	Q
WITHERS, B D	0101130271	50-344	P	YORK, J	0101200127	50	ZAMARIN, R G	0101260110	50-554	Q
WITHERS, B D	0101270453	50-344	Q	YOUNGBLOD, B	0010260823	50-10	ZAMARIN, R G	0101140000	50-554	Q
WITHERS, B D	0101210273	50-344	P	YOUNGBLOD, E H	0101300156	PR	ZAMARIN, R G	0101140000	50-554	Q
WITHERS, B D	0101220070	50-344	Q	YOUNG, T	0101210617	50-273	ZAMARIN, R G	0101260000	50-554	Q
WITHERS, B D	0101270503	50-344	P	YOUNGBLOD, B J	0101080039	50-443	ZAMARIN, R G	0101140000	50-554	Q
WITHERS, B D	0101270657	50-344	Q	YOUNGBLOD, S J	0101050102	50-269	ZAMARIN, R G	0101140000	50-554	Q
WITHERS, B D	0101190086	PR		YOUNG, F	0101290566	PR	ZAMARIN, R G	0101140000	50-554	Q
WITT, F J	7909270626	50-10	P	YOUNGBLOD, D J	0101050280	50-465	ZARAKAS, P	0101140000	50-554	Q
WOESSNER, J O	0101150195	50-219	Q	YOUNGBLOD, B J	0101050280	50-465	ZARAKAS, P	0101140000	50-554	Q
WOLFE, S L	0101300337	CONTRACT		YOUNGBLOD, B J	0101050280	50-465	ZARAKAS, P	0101140000	50-554	Q
WOLFE, R H	0101060080	CONTRACT		YOUNGBLOD, B J	0101050280	50-465	ZARAKAS, P	0101140000	50-554	Q
WOLFE, B	0101300095	PR		YOUNGBLOD, B J	0101210112	50-466	ZARAKAS, P	0101140000	50-554	Q
WOLFE, S J	0101080008	50-466	Q	YOUNG, T	0101060089	50-312	ZARAKAS, P	0101140000	50-554	Q
WOLFE, S J	0101090068	50-466	Q	YOUNG, R E	0101190666	State Prog	ZARAKAS, P	0101140000	50-554	Q
WOLFE, S J	0101120530	50-466	Q	YOUNGBLOD, B J	0101090894	50-482	ZARAKAS, P	0101140000	50-554	Q
WOLFE, B	0101230070	70-1300		YOUNGBLOD, B J	0101140641	50-483	ZARAKAS, P	0101140000	50-554	Q
WOLFEN, I H	0101270124	50-482	H	YOUNGBLOD, B J	0101120271	50-269	ZARAKAS, P	0101140000	50-554	Q
WOLLETT, S	0101060047	CONTRACT		YOUNGBLOD, B J	0101130621	50-483	ZARAKAS, P	0101140000	50-554	Q
WOLLETT, S	0101100111	CONTRACT		YOUNGBLOD, B J	0101130626	50-483	ZARAKAS, P	0101140000	50-554	Q
WOLLETT, S	0101140809	CONTRACT		YOUNGBLOD, B J	0101140631	50-482	ZARAKAS, P	0101140000	50-554	Q
WOLLETT, S	0101140792	CONTRACT		YOUNGBLOD, B J	0101160417	50-339	ZARAKAS, P	0101140000	50-554	Q
WOLLETT, E F	0101060747	70-1100		YOUNGBLOD, B J	0101160423	50-339	ZARAKAS, P	0101140000	50-554	Q
WONG, H J	01012310165	50-946	Q	YOUNGBLOD, B J	0101190625	50-443	ZARAKAS, P	0101140000	50-554	Q
WONG, R B	0101080256	BUREAU		YOUNGBLOD, B J	0101160572	50-454	ZARAKAS, P	0101140000	50-554	Q
WONG, A	0101270426	PR		YOUNGBLOD, B J	0101190608	50-330	ZARAKAS, P	0101140000	50-554	Q
WONG, L D	0101100919	EXPORTLIC		YOUNGBLOD, B J	0101200029	50-455	ZARAKAS, P	0101140000	50-554	Q
WONG, J	0101070180	50-466	Q	YOUNGBLOD, B J	0101190114	50-443	ZARAKAS, P	0101140000	50-554	Q
WONG, E J	0101170277	50-412	G	YOUNGBLOD, B J	0101210272	50-548	ZARAKAS, P	0101140000	50-554	Q
WONG, E J	0101030404	50-412	S	YOUNGBLOD, B J	0101190738	50-582	ZARAKAS, P	0101140000	50-554	Q
WONG, E J	0101060199	50-412	S	YOUNGBLOD, B J	0101190741	50-582	ZARAKAS, P	0101140000	50-554	Q
WONG, O S	0101060441	50-395	I	YOUNGBLOD, B J	0101270431	50-548	ZARAKAS, P	0101140000	50-554	Q
WORTHINGTON, P	0101260838	REGOD		YOUNGBLOD, B J	0101270436	50-548	ZARAKAS, P	0101140000	50-554	Q
WU, YIAK, D R	0101140317	EXPORTLIC		YOUNGBLOD, B J	0101290394	50-373	ZARAKAS, P	0101140000	50-554	Q
WRIGHT, Q H	0101270518	50-10	H	YOUNG, F	0101230407	50-259	ZARAKAS, P	0101140000	50-554	Q
WULF, W	0101260752	REG		YOUNG, C P	0101090311	50-344	ZARAKAS, P	0101140000	50-554	Q
WULLER, O E	0101070217	50-461	Q	YOUNG, C P	0101130564	50-344	ZARAKAS, P	0101140000	50-554	Q
WULLER, O E	0101280600	50-461	Q	YOUNG, C P	0101190443	50-344	ZARAKAS, P	0101140000	50-554	Q

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Aspen Industries Services, Inc. Access Corp.	0101060625 0101050189* 0101090399* 0101290341* 0101060429	FOIA CONTRACT CONTRACT CONTRACT 50-228 F
Aerospace Corp. Aerostat Operations	0101220323 0101091000* 0101120407 0101120421 0101050021	50-228 P CONTRACT 50-465 D 50-280 P 50-348 P
Agriculture Dept. of	0101090028 0101090030* 0101090032* 0101090856 0101100319*	50-364 A 50-364 A 50-364 A 50-364 O 50-348 Q
Alabama Power Co.	0101130602 0101130608* 0101140507 0101140554 0101140559*	50-348 B 50-348 B 50-348 P 50-348 Q 50-348 Q
	0101190101 0101210402 0101210402 0101210411 0101210426	50-364 P 50-348 P 50-348 P 50-364 P 50-348 Q
	0101210430* 0101210481 0101210485* 0101210518 0101210521*	50-348 B 50-364 R 50-364 R 50-348 R 50-348 R
	0101220344 0101220359 0101220363* 0101220365* 0101230425	50-364 P 50-348 P 50-348 P 50-348 P 50-348 P
	0101260350 0101260360 0101260360 0101260365 0101270514	50-348 A 50-348 P 50-348 P 50-364 V 50-348 P
	0101270696 0101270696 0101270750 0101270750 0101280164	50-348 P 50-348 P 50-348 P 50-348 P 50-364 P
	0101280288 0101280291* 0101280295* 0101290086 0101290334	50-348 B 50-348 B 50-348 B 50-348 Q 50-348 Q
	0101290334 0101290363 0101290363 0101290728	50-348 Q 50-348 Q 50-348 Q 50-348 O

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Alaska Welding Center	0101300580 0101300580 0101270124 0101270126*	50-348 S 50-348 S 71-404 71-404
Aldrich Chemical Co., Inc. (subs. of Bigma-Aldrich Corp.)	0101140959*	XPORILIC
Allied Chemical Corp.	0101100256 0101190645 0101080189 0101140146	40-3392 71-6273 50-332 O PR
Allied General Nuclear Services American Electric Power Co., Inc.	0101070582 0101070600 0101070628* 0101070638*	PR PR PR PR
American Mining Congress	0101090496	50-320 J
American Nuclear Insurers	0101290419 0101270280 0101210558 0101060258* 0101050070*	50-369 J 50-482 Q FOIA CONTRACT 50-265 P
American Nuclear Society Americana for Nuclear Energy Amco Testing Laboratory, Inc. Argonne National Laboratory	0101120053 0101200010 0101270213 0101290819 0101060425	REVIEW ORP ACRB REB NUMEO 50-528 B
Arizona Public Service Co.	0101060425 0101060478 0101060478 0101060478 0101060900	50-528 B 50-528 A 50-528 A 50-528 A 50-528 A
	0101060504 0101060507* 0101070364 0101070364 0101070364	50-529 B 50-528 A 50-528 K 50-528 K 50-528 K
	0101070463 0101070463 0101070463 0101090718 0101120098	50-528 A 50-528 A 50-528 A REPOD 50-528 A
	0101120098 0101120098 0101130329 0101210330 0101210330	50-528 A 50-528 A 50-528 A 50-528 A 50-528 A
	0101210335 0101210335 0101210335 0101210338 0101220096	50-528 A 50-528 A 50-528 A 50-528 A 50-528 A
	0101220096 0101220096 0101220104 0101220644	50-528 A 50-528 A 50-528 A PR

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER
	8101230492	50-528 S		8101210197
	8101230492	50-528 S		8101280205
	8101230492	50-528 S		8101290259
	8101270441	50-528 A	Atomic Industrial Forum	8101160695
	8101290384	PRM		8101160697
Arlansas Power & Light Co	8101050269	50-313 R		8101220198
	8101050275*	50-313 R	Austria	8101120064
	8101050320	50-313 S		8101120073
	8101050331	50-313 S		8101120080
	8101050336*	50-313 S	Automated Correspondence Systems, Inc	8101060347
	8101050344	50-313 P	ODM Corp	8101070040
	8101050361	50-368 S	BWR Gunars Group	8101060806
	8101050367*	50-368 S		8101090487
	8101050373	50-368 S		8101090493
	8101050377*	50-368 S		8101280187
	8101050381	50-368 S	Babcock & Wilcox Co	8101070286*
	8101050387*	50-368 S		8101190353
	8101050418	50-313 P		8101210359
	8101050432	50-368 S		8101220460
	8101050438*	50-313 S		8101230730
	8101050440	50-368 S	Babcock & Wilcox Co., Nuclear Material	8101200003
	8101050452	50-368 S	Div.	
	8101050463	50-313 S		8101260776*
	8101050501*	50-368 S	Baker & Botts	8101090055
	8101050509*	50-368 S		8101230192
	8101050519*	50-368 S		8101230192
	8101050537*	50-313 S		8101230198
	8101060355	50-313 P		8101230190
	8101060355	50-313 P		8101280577
	8101060355	50-313 P		8101280577
	8101070164*	50-313 O		8101280585*
	8101070399	50-368 S	Belch, Bingham, Baker, Hawthorne,	8101090877
	8101080434	50-313 F	Williams & Ward	
	8101080434	50-313 F	Dalwin, H. A.	8101270057
	8101090225*	50-313 O	Baltimore Gas & Electric Co.	8101090185
	8101090595	50-313 F		8101090192
	8101120044	50-313 O		8101050399
	8101120150	50-313 P		8101050403
	8101120155	50-313 O		8101050408
	8101120165	50-313 O		8101050413
	8101120174	50-313 O		8101050437
	8101120344	50-368 S		8101060283
	8101120389*	50-368 S		8101060283
	8101130439	50-368 S		8101060333
	8101130452*	50-368 S		8101060333
	8101130474	50-368 S		8101060571
	8101130484*	50-368 S		8101060571
	8101130543	50-313 S		8101070379
	8101130546*	50-313 S		8101130597
	8101150177	50-313 P		8101130607
	8101160406	50-313 P		8101130610
	8101190448	50-368 S		8101130615
	8101190451*	50-368 S		
	8101200247	50-313 P		8101130617
	8101200256	50-368 P		8101130623
	8101200298	50-368 P		8101140791
	8101200399	50-368 S		8101140744
	8101200406*	50-368 S		8101150934
	8101200411	50-368 S		
	8101200416*	50-368 S		8101150543
	8101210490	50-313 R		8101150551
	8101210494*	50-313 R		8101150565
	8101210509	50-368 R		8101190164
	8101210514*	50-368 R		8101190320
	8101220156	50-313 P		8101190320
	8101220414	50-368 P		8101190325
	8101230936	50-313 P		8101190325
	8101260384	50-313 P		8101190325
	8101260678*	50-313 F		8101190325
	8101260678*	50-313 F		8101190325
	8101260683*	50-313 F		8101190325
	8101270356	50-313 P		8101190325
	8101270577	50-368 S		8101190325
	8101270585*	50-368 S		8101190325
	8101270742	50-313 J		8101190325
	8101290137	PR		8101190325
	8101290536	50-313 R		8101190325
	8101290540*	50-313 R		8101190325
Arkansas, State of	8101140092	State Prop		8101190325
Army, Dept. of	8101100399*	CONTRACT		8101190325
Army, Dept. of, Corps of Engineers	8101220122*	50-329 A		8101190325
Assessment Designs, Inc.	8101150328*	CONTRACT		8101190325
Association of Community Organizations	8101130037	50-448 O		8101190325
for Reform Now-Texas				8101190325
Atlas Minerals	8101060493	40-3453		8101190325

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Basic Energy Technology Associates Battelle Memorial Institute Battelle Memorial Institute, Columbus Laboratories	8101270611	50-317 P		8101150641	RES
	8101270611	50-317 P		8101210537	50-537 A
	8101270660	50-318 S		8101210544	50-537 A
	8101270677	50-318 S		8101210576	RES
	8101270684	50-318 S		8101210585	RES
	8101290610	50-317 F		8101210610	RES
	8101290621	50-317 F		8101210615	RES
	8101300322	50-317 P		8101210622	RES
	8101300523	50-317 S		8101220023	RES
	8101300530	50-317 S		8101220029	RES
	8101300533	50-318 S		8101220049	RES
	8101300530	50-318 S		8101220053	RES
	8101290729	50-289 T		8101220057	RES
	8101300361	50-255 O		8101220061	RES
	8101060636	RES		8101220076	RES
	8101060923	RES		8101220218	RES
	8101070043	RES		8101220622	RES
	8101070296	TOPREP		8101220623	RES
	8101150609	RES		8101220625	RES
	8101150617	RES		8101220626	RES
Battelle Memorial Institute, Pacific Northwest Laboratory	8101220183	RES		8101220628	RES
	8101220266	RES		8101220631	50-295 P
	8101280087	50-219 R		8101220637	50-298 P
	8101280540	RES		8101220642	RES
	8101290182	RES		8101230047	RES
	8101290560	50-213 S		8101230189	RES
	8101290691	RES		8101230200	RES
	8101290761	RES		8101230202	RES
	8010090609	50-10 P		8101230206	RES
				8101230209	RES
	8101120295	RES		8101230213	RES
	8101120559	RES		8101230636	RES
	8101130683	RES		8101230643	RES
	8101220220	RES		8101230648	RES
	8101220249	RES		8101230654	50-537 A
	8101220620	RES		8101230662	RES
	8101230566	50-250 P		8101230743	RES
	8101270589	NUREG		8101230751	RES
	8101270943	NUREG		8101230757	RES
	8101200551	RES		8101260144	NUREG
Bent Creek Uranium Co. Bachtel Associates Professional Corp. Bachtel Power Corp. (subs. of Bachtel Corp.)	8101290763	RES		8101260163	NUREG
	8101100144	40-8452		8101260752	RES
	8101270305	50-329 K		8101260758	50-537 A
	8101060339	50-317 P		8101260828	RES
				8101260833	RES
	8101070139	50-133 Q		8101260846	RES
				8101260849	RES
	8101120242	RE000		8101260850	RES
	8101150410	0A999		8101260856	RES
	8101150446	0A999		8101270055	50-537 A
	8101210302	TOPREP		8101270071	RES
	8101220581	50-329 S		8101270112	50-537 A
				8101270227	50-537 A
	8101270532	50-528 K		8101270391	RES
	8101290451	50-416 A		8101270545	50-537 A
	8101270217	40-1341		8101270827	50-537 A
	8101140375	CONTRACT		8101290090	RES
	8101190159	FOIA		8101300209	NUREG
				8101300543	RES
	8101070178	PR		8101300674	RES
Bell R F MO Bellway Limousine Service, Inc. Bergson, Borkland, Margolis & Adler Bigbee, Stephenson, Carpenter, Crout & Distead Blect Hill Alliance Blent, Rons, Comisky & McCauley Blum, B. Boston Edison Co.	8101070186	PR		8101300682	RES
	8101190142	FOIA		8101280620	50-275 O
	8101270199	FOIA		8101050187	TOPREP
	8101060730	FOIA		8101150129	CONTRACT
				8101160606	71-402
	8101090485	50-369 O		8101060378	50-335 P
	8101060565	50-293 J		8101070196	50-470 K
	8101070387	50-293 S		8101130284	REVIEW ORP
	8101080356	50-293 S		8101270709	TOPREP
	8101080360	50-293 S		8101270714	TOPREP
	8101090045	50-293 P		8101090318	FOIA
	8101140927	50-293 S		8101190382	EXPORTLIC
	8101160516	50-293 S		8101190557	EXPORTLIC
	8101160573	50-293 S		8101270328	40-8743
	8101190291	50-293 P		8101270979	40-8743
	8101190462	50-293 S		8101190498	50-395 M
	8101190465	50-293 S		8101080024	PR
	8101210470	50-293 R		8101260517	50-133 Q
	8101210473	50-293 R		8101300735	50-275 F
	8101260544	50-293 S		8101070178	PR
Brand & Hall Brokaw, R. O. Brookhaven National Laboratory	8101260547	50-293 S		8101070186	PR
	8101270690	50-293 S		8101290626	70-2529
	8101270349	50-395 K			
	8101290771	50-289 P		8101140988	50-369 Q
	8101060107	RES		8101260311	50-369 Q
	8101150633	RES			
			Bruce Norton Burns & Roe Co. C & R Laboratories C-E Power Systems CBB News, CBB, Inc CERN, Theory Div., Switzerland CONDICO, Inc (Continental Oil Co.) Cahill, Gordon & Reindel California, State of Campbell & Black Cardinal Cushing General Hosp MA Carolina Environmental Study Group		

0101050033	50-324	S			010126064
0101050184	50-261	O			010126064
0101050194	50-261	O			010126064
0101050323	50-400	A			010127059
0101050325	50-400	A			010127059
0101050325	50-400	A			010127060
0101050325	50-400	A			010127060
0101050401	50-324	S			010127060
0101050401	50-324	S			010127060
0101050438	50-261	P			010127060
0101060453	50-261	P			010127060
0101060463	50-261	P			010127060
0101060494	50-324	P			010127070
0101060494	50-324	P			010127070
0101060987	50-324	P			010127070
0101060987	50-324	P			010127070
0101060670	50-261	S			010127080
0101060689	50-261	S			010127080
0101060800	MURDO				010127080
0101070365	50-324	O			010128032
0101070368	50-324	S			010128032
0101070370	50-324	S			010128032
0101070373	50-324	O			010128032
0101070437	50-400	S			010128032
0101070437	50-400	S			010128032
0101070437	50-400	S			010128032
0101070437	50-400	S			010128032
0101070491	50-324	S			010128032
0101070493	50-324	O			010128032
0101070490	50-324	S			010128032
0101070502	50-324	S			010128032
0101070620	50-324	O			010128032
0101090511	50-324	S			010130035
0101090647	50-325	S			010130035
0101090676	50-325	S			010130035
0101120299	50-261	O			010130035
0101130225	50-400	S			010130035
0101130237	50-261	R			010130035
0101130241	50-261	R			010130035
0101130535	50-324	S			010130035
0101130540	50-324	S			010130035
0101130548	50-324	S			010130035
0101130554	50-324	S			010130035
0101130561	50-324	S			010130035
0101130568	50-324	S			010130035
0101140200	50-400	O			010130035
0101140508	50-324	S			010130035
0101140514	50-324	S			010130035
0101150532	50-324	S			010130035
0101150538	50-324	S			010130035
0101150618	50-261	P			010130035
0101150005	50-324	O			010130035
0101160005	50-324	O			010130035
0101160442	50-324	P			010130035
0101160442	50-324	P			010130035
0101160526	50-324	S			010130035
0101160981	50-324	S			010130035
0101190414	50-324	P			010130035
0101190414	50-324	P			010130035
0101190426	50-261	V			010130035
0101190429	50-261	V			010130035
0101190609	50-324	P			010130035

Agency	File Number	Page	Page Count	Page
Denver	8101270044	40-1162		8101270044
	8101270049	40-1162		8101270049
	8101090208	CONTRACT		8101090208
	8101190089	WASTE MGT		8101190089
	8101270195	WASTE MGT		8101270195
	8101270394	WASTE MGT		8101270394
	8101270467	WASTE MGT		8101270467
	8101300365	CONTRACT		8101300365
	8101280074	MISC		8101280074
	8101140221	30-208 J		8101140221
ng, Inc	8101140258	KPOTYLIC		8101140258
	8101220417	30-368 P		8101220417
	8101230541	30-317 O		8101230541
	8101300164	70-1100		8101300164
	8101070489	RECORD		8101070489
	8101090017	30-395 D		8101090017
	8101150223	CONTRACT		8101150223
	8101150237	CONTRACT		8101150237
	8101300586	30-238 R		8101300586
	8101300587	30-238 R		8101300587
National Oceanographic Administration	8101060629	30-184 R		8101060629
	8101060633	30-184 R		8101060633
	8101080317	ACRB		8101080317
	7903190202	30-10 P		7903190202
	7911270339	30-10 P		7911270339
	7911270340	30-10 P		7911270340
	0003240464	30-237 P		0003240464
	8009190849	30-10 P		8009190849
	8011250354	30-254 S		8011250354
	8011250358	30-254 S		8011250358
National Bureau of	8012220456	30-10 P		8012220456
	8101050066	30-365 P		8101050066
	8101050340	30-304 S		8101050340
	8101050345	30-304 S		8101050345
	8101050390	30-254 S		8101050390
	8101050396	30-254 S		8101050396
	8101050415	30-373 S		8101050415
	8101050500	30-10 P		8101050500
	8101050500	30-10 P		8101050500
	8101060073	30-10 O		8101060073
Co	8101060376	30-237 P		8101060376
	8101060467	30-249 S		8101060467
	8101060469	30-249 S		8101060469
	8101060471	30-249 S		8101060471
	8101060472	30-249 S		8101060472
	8101060479	30-249 S		8101060479
	8101060481	30-237 S		8101060481
	8101060482	30-265 S		8101060482
	8101060484	30-237 S		8101060484
	8101060486	30-265 S		8101060486
National Bureau of	8101060492	30-265 S		8101060492
	8101060598	30-237 S		8101060598
	8101060604	30-237 S		8101060604
	8101060608	30-237 S		8101060608
	8101060617	30-237 S		8101060617
	8101070214	30-295 O		8101070214
	8101070251	RECORD		8101070251
	8101080093	30-237 Q		8101080093
	8101080093	30-237 Q		8101080093
	8101080093	30-237 Q		8101080093
National Bureau of	8101080117	30-247 Q		8101080117
	8101080144	30-10 P		8101080144
	8101090001	30-10 P		8101090001
	8101090001	30-10 P		8101090001
	8101090001	30-10 P		8101090001
	8101090001	30-10 P		8101090001
	8101090001	30-10 P		8101090001
	8101090001	30-10 P		8101090001
	8101090001	30-10 P		8101090001
	8101090001	30-10 P		8101090001
National Bureau of	8101090001			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101260386	50-237 S		8101130364	50-247 V
	8101260897	50-10 P		8101140316	50-247 P
	8101260597	50-10 P		8101140316	50-247 P
	8101260658	50-249 B		8101150578	50-247 C
	8101260671	50-237 B		8101210434	50-247 P
	8101260659	50-295 Q		8101210440	50-247 S
	8101260707	50-434 Q		8101210459	50-247 S
	8101270481	50-237 P		8101210591	50-247 P
	8101270313	50-10 R		8101220130	50-247 C
	8101270315	50-10 R		8101220147	50-247 C
	8101270313	50-10 R		8101220315	50-247 C
	8101270320	50-10 R		8101220362	50-247 P
	8101270320	50-10 R		8101220362	50-247 P
	8101270320	50-10 R		8101230582	50-3
	8101270384	50-293 P		8101230582	50-3
	8101270584	50-295 P		8101230589	50-3
	8101270608	50-249 B		8101230589	50-3
	8101270613	50-249 B		8101270194	50-247
	8101270614	50-10 J		8101270664	50-247
	8101270614	50-10 J		8101270679	50-247
	8101270614	50-10 J		8101270685	50-247
	8101270614	50-10 J		8101270724	50-247
	8101270617	50-295 P		8101270729	50-247
	8101270617	50-295 P		8101290671	50-247
	8101270661	50-10 P	Consumers Power Co.	8012310223	50-329
	8101270730	50-295 B		8101050132	50-329
	8101270733	50-295 B		8101050132	50-329
	8101270737	50-10 J		8101050143	50-329
	8101270737	50-10 J		8101050365	50-329
	8101270737	50-10 J		8101050365	50-329
	8101270740	50-263 B		8101050407	50-329
	8101270798	50-263 B		8101050407	50-329
	8101270763	50-254 S		8101050576	50-155
	8101270770	50-254 B		8101050580	50-155
	8101280613	50-454 O		8101050600	50-329
	8101280636	50-454 Q		8101060272	50-329
	8101290510	50-249 B		8101060630	50-155
	8101290514	50-10 B		8101060639	50-155
	8101290791	50-10 P		8101060668	50-155
	8101290791	50-10 P		8101060674	50-155
	8101290791	50-10 P		8101060921	50-155
	8101300470	50-10 P		8101070653	50-255
	8101300470	50-10 P		8101080078	RE000
	8101300577	50-234 Q		8101080124	50-155
	8101060641	50-289 Q		8101080134	50-155
	8101060652	50-289 O		8101090078	50-329
	8101080047	PR		8101090084	50-329
	8101080447	50-213 P		8101090171	50-255
	8101060410	50-213 P		8101090313	50-329
	8101070256	50-213 F		8101090513	50-329
	8101090002	50-213 P		8101090594	50-329
	8101090004	50-213 F		8101120224	50-155
	8101090004	50-213 F		8101120250	50-329
	8101090012	50-213 P		8101120318	50-255
	8101090626	50-213 B		8101120339	50-155
	8101090632	50-213 B		8101120379	50-155
	8101100789	50-213 O		8101120444	50-329
	8101120237	50-213 V		8101120444	50-329
	8101120323	50-213 P		8101120374	50-155
	8101120327	50-213 P		8101130086	50-155
	8101150028	50-213 O		8101130229	50-155
	8101160248	50-213 P		8101130233	50-155
	8101160248	50-213 P		8101130243	50-255
	8101160248	50-213 P		8101130249	50-255
	8101160580	50-213 O		8101130442	50-255
	8101160887	50-213 O		8101130443	50-255
	8101210376	50-213 B		8101130518	50-155
	8101220404	RE000		8101130525	50-155
	8101220408	50-213 R		8101140336	50-255
	8101220410	50-213 R		8101140344	50-255
	8101270712	50-213 F		8101140628	50-255
	8101270882	COMM18810N		8101140653	50-329
	8101280062	50-358 Q		8101140683	50-329
	8101280304	50-510 Q		8101140968	50-329
	8101290740	50-358 O		8101140968	50-329
	8012290320	50-247 P		8101140973	50-329
	8012290320	50-247 P		8101150079	50-255
	8101050348	50-247 B		8101150306	50-255
	8101050353	50-247 B		8101190391	50-290
	8101060299	50-247 Q		8101190604	50-330
	8101060480	50-247 P		8101200154	50-329

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101210609	50-155 O		8101260499	50-488 G
	8101220140*	50-247 O		8101280331	50-395 M
	8101220186*	50-255 O	Decision Research, Inc.	8101280114	NUREC
	8101220200*	50-255 Q	Defense, Dept. of, Defense Nuclear Agency	8101270782*	CONTRACT
	8101220234	50-155 P	Defenders, State of	8101300406*	CONTRACT
	8101220250	50-155 J			
	8101220332	50-255 J	Detroit Edison Co.	8101050080*	50-341 K
	8101220395	50-255 O		8101050095*	50-341 K
	8101230479	50-255 B		8101093172*	FOIA
	8101230483*	50-255 B		8101090911	PR
				8101210588	50-341 A
	8101230530	50-255 B			
	8101230531*	50-255 B		8101270400	50-16 J
	8101230533	50-155 B		8101290006	50-341 S
	8101230535*	50-155 B		8101290770*	50-341 Q
	8101230581	50-329 B	Dignen, T. O.	8101280091	50-443 Q
			Dor-Searsh Associates	8101130629	FOIA
	8101260273	50-329 O			
	8101260273	50-329 O		8101230175	FOIA
	8101260462	50-255 J	Ocherty, J. F.	8101050014	50-466 Q
	8101260480	50-329 O		8101050065	50-466 Q
	8101260738*	50-255 F	Dougless & Berham	8101050616	50-488 Q
			Duke Power Co.	8101050094	50-269 P
	8101260743*	50-255 F			
	8101270373	50-155 P		8101050094	50-269 P
	8101270390*	50-329 K		8101050094	50-269 P
	8101270390*	50-329 K		8101050101*	50-269 P
	8101270691	50-155 P		8101050101*	50-269 P
	8101270664*	50-155 O		8101050107	50-287 P
	8101280093	50-155 P		8101050112*	50-287 P
	8101280299	50-329 O		8101050351	50-287 S
	8101280299	50-329 O		8101050355*	50-287 S
	8101280591	50-329 O		8101050616	50-488 Q
	8101290012	50-329 Q		8101060483	50-269 P
	8101290012	50-329 O		8101060483	50-269 P
	8101290020*	50-329 Q		8101060483	50-269 P
	8101290020*	50-329 O		8101060488*	50-269 P
	8101290083*	50-155 O		8101060488*	50-269 P
	8101290231	50-155 Q		8101060488*	50-269 P
	8101290358	50-155 P		8101060491*	50-269 P
	8101290523	50-155 S		8101060491*	50-269 P
	8101290528*	50-155 S		8101060491*	50-269 P
	8101290580	50-329 R		8101060503	50-269 I
	8101290580	50-329 R		8101070145	50-369 O
	8101290410	FOIA		8101070235	RECGO
	8101270561	WASTE MOT		8101070269	50-269 P
	8101270178	FOIA		8101070313	50-413 O
	8101070172	PR		8101070316*	50-413 O
	8101140116	State Prog		8101070320	50-369 Q
	8101280599	50-389 M		8101080148*	50-269 O
	8101060097	REG		8101090062	50-369 Q
	8101070534	REG		8101090062	50-369 Q
	8101270161	REG		8101090657	50-287 S
	8101090706*	CONTRACT		8101090666*	50-287 B
	8101120227*	50-155 P		8101120248	RECGO
	8101050326	50-409 F		8101130404	50-269 P
	8101050374	50-409 B		8101130404	50-269 P
	8101050380*	50-409 B		8101130404	50-269 P
	8101050383	50-409 B		8101140600	50-413 S
	8101050391*	50-409 B		8101150136	50-269 Q
	8101060561	50-409 B		8101150168	50-369 F
	8101060583*	50-409 S		8101150462	50-369 F
	8101080099	50-409 P		8101150765	50-369 O
	8101080109	50-409 O		8101150907	50-369 O
	8101090042	50-409 P		8101160220	50-413 M
	8101140491	50-409 R		8101160258	50-269 O
	8101140494*	50-409 R		8101160258	50-269 O
	8101160433	50-409 S		8101160258	50-269 Q
	8101200178	50-409 O		8101160366	50-269 P
	8101220025	50-409 F		8101160443	50-369 F
	8101270345	50-409 P		8101160443	50-369 F
	8101280320	50-409 T		8101160668*	50-413 O
	8101280515	50-409 O		8101160724	50-369 O
	8101300181	50-409 P		8101160724	50-369 O
	8101300636	50-409 Q		8101190385	50-269 O
	8101210294	CONTRACT		8101200223	50-269 P
	8101230539*	50-313 P		8101200575	50-269 O
	8101090898*	CONTRACT		8101210213	50-269 C
	8101060956*	50-320 P		8101210213	50-269 C
	8101070270*	50-320 F		8101210213	50-269 C
	8101190148	FOIA		8101210462	50-269 I
	8101070319*	50-267 A		8101210462	50-269 I
	8101050478	50-445 Q		8101210462	50-269 I
	8101070028	FOIA		8101210464*	50-269 I
	8101160220	50-413 M		8101210464*	50-269 I
	8101160233	50-445 Q		8101210493	50-269 I
	8101230404	70-2623		8101210493	50-269 I
	8101230442	70-2623			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101210493	50-269 P		8101220571	50-334
	8101210502	50-269 S		8101230469	50-334
	8101210507	50-269 S		8101230471*	50-334
	8101210511	50-287 B		8101230473*	50-334
	8101210516*	50-287 S		8101230475	50-334
	8101220133	50-369 A		8101230478*	50-334
	8101220133	50-369 A		8101260548	50-334
	8101220138*	50-369 A		8101260634*	50-334
	8101220138*	50-369 A		8101270590	50-334
	8101220378	50-269 B		8101270593*	50-334
	8101220378	50-269 B	Dynapac, Inc.	8101300738*	50-334
	8101220380*	50-269 B		8101300176*	50-498
	8101220380*	50-269 B		8101300182*	50-498
	8101220380*	50-269 S	EO&O Ideho, Inc.	8101050062	NURE0
	8101220380*	50-269 S		8101050069*	NURE0
	8101220428	50-269 P		8101130408	NURE0
	8101220428	50-269 P		8101130414	NURE0
	8101220428	50-269 P		8101150600	REB
	8101230404	70-2623		8101300145	REB
	8101230440	50-269 F		8101300154	50-254
	8101230448	50-269 F		8101300184	50-254
	8101230442	70-2623		8101300179	50-266
	8101230489	50-269 S		8101300186	50-237
	8101230491*	50-269 S		8101300197	REB
	8101230493	50-369 A		8101300760	NURE0
	8101230493	50-369 A		8101300022	REB
	8101230496*	50-369 A		8101300829	50-334
	8101230496*	50-369 A		8101300837	50-309
	8101230502	50-471 S		8101300842	50-10
	8101260209	50-369 Q		8101300845	REB
	8101260499	50-488 Q		8101300847	50-255
	8101260513	50-369 S		8101300849	50-331
	8101260513	50-369 S	EO&O, Inc.	8101120332*	50-244
	8101270640	50-270 B		8101120343*	50-244
	8101270643	50-287 B		8101120353*	50-244
	8101270650*	50-287 B		8101200480*	50-244
	8101270680*	50-270 B		8101300262*	50-244
	8101290404	50-369 Q	Ebasco Services, Inc (subs of Enserch Corp.)	8101150840*	QA999
	8101290404	50-369 Q		8101290116*	FOIA
	8101290408	50-413 Q		8101290124*	FOIA
	8101290492	50-369 Q		8101290131*	FOIA
	8101290591	50-369 J		8101290143*	FOIA
	8101290599*	50-269 F		8101290151*	FOIA
	8101290599*	50-269 F		8101290159*	FOIA
	8101290599*	50-269 F		8101290255*	FOIA
	8101290608*	50-269 F		8101290261*	FOIA
	8101300160	50-369 A		8101290271*	FOIA
	8101300436	50-369 F		8101290281*	FOIA
	8101300576	50-270 B		8101290287*	FOIA
	8101300578*	50-270 B		8101290290*	FOIA
Boquesne Light Co	8101050321	50-334 P		8101290298*	FOIA
	8101050330*	50-334 P		8101290304*	FOIA
	8101050484	50-412 S		8101290310*	FOIA
	8101060450	50-412 B		8101290313*	FOIA
	8101070436	50-334 R		8101290317*	FOIA
	8101070439*	50-334 R		8101290324*	FOIA
	8101070524	50-336 S		8101290330*	FOIA
	8101070531*	50-334 B		8101290335*	FOIA
	8101080126	50-334 Q		8101290346*	50-284
	8101090548	50-334 Q	Eberline Instrument Corp.	8101140931	70-2909
	8101100781	50-334 Q	Eckert, Seamans, Cherin & Mellott		
	8101100786	50-334 Q			
	8101130421	50-334 S	Edison Electric Institute	8101070008	FOIA
	8101130425*	50-334 B	Edison International Co.	8101100208	70-2325
	8101130428*	50-334 B		8101120023	XPCRTL
	8101130432*	50-334 S		8101140890	XPCRTL
	8101130438*	50-334 B		8101160218	XPCRTL
	8101130443*	50-334 B	Eichhorn, Eichhorn & Link	8101280641	50-367
	8101130508	50-334 B	Electric Power Research Institute	8012030440	NURE0
	8101130513*	50-334 B		8101140796*	CONTRAC
	8101130531	50-334 B		8101220346*	50-309
	8101150933	50-334 B	Electric Utility Companies Nuclear Transportation Group	8101290049	70-2622
	8101160464	50-334 R			
	8101160467*	50-334 R	Energy Fuels Nuclear, Inc	8101100023	40-0601
	8101160468*	50-334 R	Energy Incorporated	8101230275	71-405
	8101160470*	50-334 R		8101230286*	71-405
	8101190279*	50-412 B	Energy Research & Development Admin. (Presently DDE)	8101260334*	FOIA
	8101190467	50-334 S	Energy Resources Co., Inc.	8101150118	FOIA
	8101190470*	50-334 S			
	8101190474	50-334 B	Energy Systems Research Group, Inc.	8101270683*	50-322
	8101190477*	50-334 B	Energy, Dept of	8101190360	71-9035
	8101220382	50-334 B		8101190398	71-6144
	8101220384*	50-334 B	Energy, Dept. of, Economic Regulatory Administration	8101290410*	10CFR
	8101220387*	50-334 B		8101160142*	COMHIB
	8101220392*	50-334 B	Energy, Dept. of, Clinch River Breeder Reactor Plant	8101070495	REQ00

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Entsels, E. B. Environmental Coalition on Nuclear Power	8101090492	50-537 B		8101130325	50-250
	8101270282	50-170 Q		8101130337	50-335
	8101090321	50-289 Q		8101130334*	50-250
	8101090320*	50-289 Q		8101130339*	50-335
	8101230635	50-289 Q		8101130341	50-335
Environmental Protection Agency	8101270298	50-387 Q		8101130345	50-335
	8101050019	50-250 P		8101130348	50-250
	8101050056	50-464 D		8101130353	50-250
	8101050618	40-2061		8101130365*	50-335
	8101080042	PR		8101130372*	50-335
	8101120173*	50-320 P		8101130377*	50-250
	8101130017*	FBI A		8101130382*	50-250
	8101130837	40-2061		8101140608	50-250
	8101210590	50-395 D		8101140608	50-250
	8101220297	50-259 P		8101140686	50-250
Equipe; Health Systems Div Exxon Corp. European Communities, Commission of	8101260593	50-395 D		8101150125	50-250
	8101270591	50-361 B		8101150595*	50-389
	8101150801	MUREO		8101160261	50-389
	8101220265*	50-395 A		8101190390	50-250
	8101090912	XPORTLIC		8101190350	50-250
European Organization for Nuclear Research Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)	8101090919	XPORTLIC		8101210092*	50-335
	8101140903	XPORTLIC		8101210098*	50-335
	8101190755	XPORTLIC		8101210162	50-335
	8101130122*	XPORTLIC		8101210208	50-250
				8101210414	50-250
	8101090047	TOPREP		8101210414	50-250
	8101090050*	TOPREP		8101210418*	50-250
	8101140139	XPORTLIC		8101210418*	50-250
	8101200007	71-9070		8101210418*	50-250
	8101220520	TOPREP		8101210425	50-250
FBI Service FUGRO, INC. Federal American Partners	8101220534*	TOPREP		8101210425	50-250
	8101210582	FBI A		8101210429*	50-250
	8101150142*	FBI A		8101210429*	50-250
	8101150149*	FBI A		8101210429*	50-250
	8101070311	40-4492		8101210429*	50-250
Federal Emergency Management Agency	8101080440	50-344 F		8101220150	50-250
	8101090037	ORG		8101220150	50-250
	8101140249*	50-289 Q		8101220172	50-389
	8101140252*	50-289 F		8101230428	50-250
	8101290452	50-250 P		8101230428	50-250
Federal Energy Regulatory Commission	8101300408	50-361 D		8101230430*	50-250
	8101160278	50-275 C		8101230430*	50-250
	8101050324	50-250 B		8101270008	50-389
	8101050328	50-335 B		8101270843	50-389
	8101050338	50-250 P		8101270694	50-335
Fischel, D. B. Florida Power & Light Co.	8101050342*	50-250 B		8101270703*	50-335
	8101050349*	50-335 B		8101280078	50-335
	8101050360	50-250 S		8101280599	50-389
	8101050363*	50-250 S		8101050260	50-302
	8101050392	50-250 F		8101050264*	50-302
Florida Power Corp.	8101050392	50-250 F		8101050285	50-302
	8101030402	50-335 F		8101070422	50-302
	8101050444	50-335 S		8101080221	50-302
	8101050449*	50-335 S		8101090590	50-302
	8101050453	50-250 F		8101090597*	50-302
	8101090453	50-250 F		8101090603	50-302
	8101050480	50-251 S		8101090609*	50-302
	8101050484	50-250 S		8101090614	50-302
	8101050490	50-251 B		8101090622*	50-302
	8101050534*	50-251 S		8101100815	50-302
	8101050542*	50-250 B		8101150024	50-302
	8101050547*	50-251 S		8101150158	50-302
	8101060286	50-250 P		8101160438	50-302
	8101060288	50-335 P		8101160556	50-302
	8101060292*	50-335 P		8101160634*	50-302
	8101060297	50-250 P		8101190454	50-302
	8101060297	50-250 P		8101190456*	50-302
	8101060303*	50-250 P		8101200292	50-302
	8101060303*	50-250 P		8101200294*	50-302
	8101060309	50-250 P		8101210512	50-302
	8101060309	50-250 P		8101230447	50-302
	8101060311*	50-250 P		8101230455*	50-302
	8101060311*	50-250 P		8101290389	50-302
	8101060374	50-335 P		8101140141	50-302
	8101070245	REGD		8101210345	50-250
	8101080137*	50-335 F		8101200422*	CONTRAL
	8101080142*	50-335 F		8101210599	FBI A
	8101100702*	50-335 B		8101060445*	50-395
	8101120207	50-335 P		8101090327	ACRB
	8101120479*	50-250 F			
	8101120479*	50-250 F		8101150045*	CONTRAL
	8101120483*	50-250 F		8101220243	50-286
	8101120483*	50-250 F		8101050059	50-302
Florida, Univ. of. Gainesville Folke United to Thwart Unsafe Radiation Emission (FUTURE) Foster Associates, Inc. Franklin Institute/Franklin Research Center	8101080137*	50-335 F			
	8101080142*	50-335 F			
	8101100702*	50-335 B			
	8101120207	50-335 P			
	8101120479*	50-250 F			
Friends of the Earth	8101120479*	50-250 F			
	8101120483*	50-250 F			
	8101120483*	50-250 F			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER
GM Bettis Corp Oage-Bettis Associates, Inc General Atomic Co. (subs. of Gulf Oil Co. 1	8101270057	50-70 O		810106057
	8012100406	PT21		810106057
	8011100307*	CONTRACT		810106058
	0101050024	50-163 R		810106059
	8101050028*	50-163 R		810106064
	0101070225	XPORTLIC		810106064
	8101200005	XPORTLIC		810106066
	8101200006	XPORTLIC		810107033
General Atomic Co. (subs. of Gulf Oil Corp.)	8101120001	REGOD		810107055
General Electric Co	7912310182	REGOD		010107052
	8012100316*	70-1113		810107052
	8012290515	71-5900		810107052
	8012290532	71-5971		810108020
	8012290549	71-5926		810112029
	8012290565	71-4986		
	8012290569	71-5939		810112030
	8012290571*	71-4986		810112030
	8012290590	71-9044		810112035
	3101050178	TOPREP		810112036
	8101050494	50-70 O		
	8101050506*	50-70 O		810114055
	8101050515*	50-70 O		810116010
	8101060892	XPORTLIC		810119033
	8101000121	REGOD		810119033
	8101090198	TOPREP		810119034
	8101090209*	TOPREP		810119034
	8101100061	REG		810122054
	8101120049	REVIEW ORP		810123045
	8101120309*	50-277 P		810123046
	8101130317	AUREO		810123046
	8101140008	71-9001		810123046
	8101140135	REGOD		810126039
	0101140365	PR		810126046
	8101160197	50-70 O		810126046
	8101160342	TOPREP		810126052
	8101160361*	TOPREP		810126054
	8101190541	FOIA		810126055
	8101210371	TOPREP		810126060
	8101210515	TOPREP		810126061
	8101210523	TOPREP		810126062
	8101210529*	TOPREP		810126066
	8101210531*	TOPREP		810126071
	8101210542	REG		810126072
	8101220224	REG		810128018
	8101220232	REG		
	8101220497	REVIEW ORP		810128019
	8101220649	REG		810129018
	8101220650	REG		810129037
	8101220655	REG		810129037
	8101230038*	70-1300		810129038
	8101230043*	70-1308		810129057
	0101230054*	70-1308		810130037
	8101230059*	70-1308		810130039
	8101230380	TOPREP		810130042
	8101230494*	50-263 O		
	0101270598	TOPREP	Georgie, State of	810114013
	8101280170	50-70 F	Geotechnical Engineers, Inc.	810109023
	8101280567	XPORTLIC	Oibbs & Hill, Inc. (subs. of Dravo Corp.)	810109072
	8101300028	REG		810123050
	0101220569*	50-321 P	Gilbert/Commonwealth Coe	810106065
General Physics Corp				810113010
General Public Utilities	8012160144	50-219 I		810121035
	8012160154*	50-219 I	Olen Rose, TX	810107030
	8101130045*	50-289 O	Orenburg, TX	810107030
	8101130056*	50-289 P	Gulf States Utilities Co	810110017
	8101280406*	50-320 P		810121067
	8101060637*	50-289 O		810121067
	0101270573	50-289 R		810122043
	8101270753	50-219 J		810127068
General Public Utilities - GPU Service Corp	8101280316*	50-289 O		810128030
	0012240278	50-321 O		
	0101050235	50-321 S	H. J. Oruy & Associates, Inc.	810127035
	8101050427	50-321 S	Hemel, Perk, McCabe & Saunders	810107063
	8101050485	50-366 S	Hanford Engineering Development Laboratory	810110085
	8101050460*	50-366 S		810114083
	8101060514	50-321 S		810122050
	8101060514	50-321 S		810122060
	8101060559	50-366 S	Harnon & Weiss	810123046
	8101060564	50-321 P	Harrisburg Hosp. Harrisburg, PA	810108002
	8101060564	50-321 P	Henry County Health Center, Mt. Pleasant, IA	810107023
	8101060566*	50-366 S	Hobbs Brook Agency, Inc.	810114022
Georgia Power Co	8101060572	50-366 S		810107030
	8101060573*	50-321 P	Hood County, TX	010106053
			House of Rep.	810108039

	B101140846*	70-143	U	Illinois, State of	B101130010	FOIA
	B101200054	50-320	U		B101140232	50-367
	B101200077	50-170	U		B101200046	50-367
	B101200301	50-289	H		B101290318	50-10
	B101270508*	50-247	H	Illinois, Univ. of, at Chicago Circle	B101080035	PR
	B101290789*	50-483	H	Indiana & Michigan Electric Co	B101050356	50-316
Dept. of Rep., Government Operations	B101030635*	50-320	F		B101030472	50-316
	B101130606	50-367	U		B101050546*	50-316
Dept. of Rep., Interior & Insular Affairs	B012110032*	COMM18818N			B101080384	50-316
	B101060953*	COMM18818N			B101080397*	50-316
	B101060954*	COMM18810N			B101080406*	50-316
	B101140846*	70-143			B101090441	50-315
Dept. of Rep., Merchant Marine & Fisheries	B101140677*	COMM18818N			B101090685	50-316
Planning & Urban Development, Dept. of	B101230444	50-466	B		B101090692*	50-316
Ston Chronicle	B101200404	50-356	Q		B101120268	50-315
Ston Lighting & Power Co	B101080140*	50-498	A		B101120268	50-315
	B101090023	50-498	I		B101120315	50-315
	B101090023	50-498	I		B101120315	50-315
	B101090035	50-466	O		B101130217	50-315
	B101120391*	50-498	A		B101140146	PR
	B101120391*	50-498	A		B101190512	50-315
	B101120393*	50-498	A		B101190512	50-315
	B101120393*	50-498	A		B101190515*	50-315
	B101140484*	50-498	Q		B101190515*	50-315
	B101150011	50-466	Q		B101230329	50-315
	B101160454	50-498	B		B101260579	50-315
	B101160454	50-498	B		B101270350	50-316
	B101160460	50-498	S		B101280310	50-315
	B101160460	50-498	S		B101290516	50-315
	B101220331	50-498	B		B101290521*	50-315
	B101220331	50-498	B		B101300073*	50-315
	B101220315	50-498	B	Indiana & Michigan Power Co.	B101300494	50-315
	B101220515	50-498	B		B101060789	50-316
	B101230192	50-498	Q		B101060795*	50-316
	B101230192	50-498	Q		B101200367	50-315
	B101230198	50-498	Q		B101200371*	50-315
	B101230198	50-498	Q		B101210443	50-316
	B101270718	50-498	B		B101210451*	50-316
	B101270857*	50-498	A	Indiana, State of	B101220072	PR
	B101270870*	50-498	Q	Institute for Resource Management, Inc.	B101220205	REQ00
	B101270909*	50-498	Q	Institute of Nuclear Power Operations	B101190500*	50-296
	B101270924*	50-498	A	Interior, Dept. of	B1012240399*	State Pr
	B101280577	50-498	Q		B101050079	50-367
	B101280577	50-498	Q		B101090497	50-395
	B101280589*	50-498	Q	Interior, Dept. of, Bureau of Mines	B101200484	CONTRACT
	B101290494*	50-498	Q	Interior, Dept. of, Fish & Wildlife Service	B101210380	50-250
	B101300148*	50-498	G		B101270121	40-1341
Ston, Univ. of	B101100325*	CONTRACT		Interior, Dept. of, Geological Survey	B101060577	50-395
Ston Design Group	B101270723*	50-320	P		B101140560	PR
Ston Factors Society, Inc.	B101060750*	CONTRACT			B101230472	GRQ
Ston County, CA	B101210342	50-133	P	Interior, Dept. of, National Park Service	B101050369	50-367
Ston & Williams	B101070091	FOIA		International Atomic Energy Agency	B101280573	GRQ
	B101130384	50-280	Q	(Austria)		
	B101230103	50-338	Q	International Business Development	B101090429	XPORTELIC
	B101270305	PR		International Structural Engineers, Inc	B101300104*	50-390
	B101280212	50-322	O	lcme Electric Light & Power Co.	B1012050399	50-331
	B101070297*	70-2249			B101050273	50-331
	B101070299*	70-2249			B101060621	50-331
Physiological Associates, Inc.	B101140577*	50-320	R		B101060627*	50-331
	B101270578*	50-289	R		B10120326	50-331
ho National Engineering Laboratory	B101060104	REB			B101120329*	50-331
	B101070555	50-295	P		B101120334	50-331
	B101100581	50-295	P		B101120336*	50-331
	B101100590	50-344	P		B101130631	50-331
	B101100601	REB			B101200280	50-331
	B101100804	50-409	P		B101200284*	50-331
	B101120291	REB			B101200300	50-331
	B101130711	50-247	P		B101200466*	50-331
	B101140673	50-304	P		B101200479*	50-331
	B101290668	REB			B101220335	50-331
	B101290692	NUREQ			B101220343*	50-331
	B101290703	NUREQ			B101220381	50-331
	B101140084	State Prog			B101220389*	50-331
hols, State of	B101060731*	50-461	B		B101220386	50-331
hols Power Co.					B101220397	50-331
	B101070213	50-461	Q		B101220401*	50-331
	B101070444	50-461	S		B101280050	50-331
	B101090631*	50-461	A		B101280356*	50-331
	B101140532	PR		Ishe, Lincoln & Beale	B101210423	50-10
	B101150606*	50-461	Q		B101070394	50-329
	B101280600	50-461	Q		B101070394	50-329
	B101290057	50-461	Q		B101090078	50-329
	B101290057	50-461	Q		B101090078	50-329
	B101290069*	50-461	Q		B101090084	50-329

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B101070267	50-237 0	Kansas State Univ	B101270527	50-123
	B101070284	PR	Kansas, Univ of	B101160391*	50-149
	B101140969	50-329 0		B101160398*	50-149
	B101140973	50-329 0		B101160404*	50-149
	B101160209	50-155 0		B101160408*	50-146
	B101200154	50-329 0		B101160411*	50-149
	B101260480	50-329 0	Waye, Scholer, Fiernan, Waye & Handler	B101070022	FOIA
	B101280299	50-329 0	Kerr-McDoe Chemical Corp (subs of	B101030555	50-10
	B101280599	50-329 0	Kerr-McDoe Corp)		
	B101290012	50-329 0	Kerr-McDoe Corp	B101100252	40-256
	B101290012	50-329 0		B101290535	40-261
	B101290020*	50-329 0	Kerr-McDoe Nuclear Corp	B101070178*	PR
	B101290020*	50-329 0		B101070186*	PR
Isle of Wight County, VA	B101070613*	50-280 F		B101100162	40-876
Isotope Products Laboratories	B101100509	XPORTLIC	Lake and Hosp Elkhorn, WI	B101140537	PR
	B101070102	50-367 0	Laudig, S	B101070049	FOIA
Irish Walton League of America, Porter County Chapter	B101160242	50-367 0	Lave, L	B101060790*	CONTRACT
	B101180127*	FOIA	Lawrence Livermore Laboratory	B101120575	50-244
J F I Acipito & Associates, Inc	B101150134*	FOIA		B101140130	71-5795
Jacksonville, FL	B101270555	50-437 A		B101140923	MAREQ
	B101100089	XPORTLIC		B101150496*	50-247
Japer	B101100092	XPORTLIC		B101160690*	50-280
	B101100099	XPORTLIC		B101220188	REB
	B101100102	XPORTLIC		B101220255	REB
Jersey Central Power & Light Co	B101050197	50-219 B		B101230477	50-206
	B101050204*	50-219 S		B101230480*	50-255
	B101050211	50-219 S		B101280622*	50-29
	B101050219*	50-219 S		B101290193	RES
	B101050223	50-219 S		B101290674	REB
	B101050229*	50-219 S		B101290785	50-255
	B101050252	50-219 S		B101300009	MAREQ
	B101050259*	50-219 S	LeBoeuf, Lamb, Leiby & MacRae	B101300225	MAREQ
	B101050263	50-219 0		B1012240365	Stats Proj
	B101050379	50-219 S		B101050077	50-341
	B101050469	50-219 S		B101150099	FOIA
	B101050541*	50-219 S		B101150631	50-255
	B101080172*	50-219 F	Lehigh Univ	B101290049	70-2623
	B101080179*	50-219 F	Long Island Lighting Co	B101130047	50-219
	B101090034	50-219 P		B101050109	50-322
	B101120216	50-219 F		B101060002*	50-322
	B101130327	50-219 V		B101060485	50-322
	B101140659	50-219 Q		B101130368	50-322
	B101140938	50-219 Q		B101190329*	50-322
	B101150492	50-219 S		B101260470	50-322
	B101150497*	50-219 S		B101280222*	50-322
	B101150690	50-219 S		B101290112	PR
	B101150693*	50-219 S	Los Alamos Scientific Laboratory	B101100808	MAREQ
	B101160466	50-219 P		B101150637	MAREQ
	B101160469*	50-219 P		B101210271	MAREQ
	B101160471*	50-219 P		B101210278	MAREQ
	B101160484*	50-219 F		B101260127	50-537
	B101160489*	50-219 F		B101290135	REB
	B101230546	50-219 A		B101290527*	70-754
	B101230548*	50-219 R		B101290825	MAREQ
	B101230551	50-219 S	Louisiana Power & Light Co.	B101070384	50-382
	B101230556*	50-219 S		B101070389	50-382
	B101230560	50-219 S		B101090500	50-382
	B101230564*	50-219 S		B101100752*	50-382
	B101230567	50-219 S		B101220502	50-382
	B101230574*	50-219 S	Louisiana, State of	B101140122	Stats Proj
	B101260581	50-219 S	Lovell Biomed & Environmental Research Institute	B101300153	MAREQ
	B101260664*	50-219 S			
	B101280083	50-219 R	Lubenstein, Newman, Reis, Axelrad & Toll	B101090055	50-466
	B101290546	50-219 S		B101090094	50-376
	B101290771*	50-209 P		B101090871	PR
Jones, Brown & Clifford KMC, Inc	B101230238	50-133 0		B101150011	50-466
	B101050088	50-29 P		B101160261	50-389
	B101140578	PR		B101220621	PR
Kansas for Sensible Energy	B101230638	50-482 0		B101230192	50-498
Kansas Gas & Electric Co	B101070375	50-482 S		B101230198	50-498
	B101070388	50-482 S		B101230432	50-367
	B101070401	50-482 S		B101280577	50-498
	B101070408	50-482 S		B101280599	50-389
	B101070420	50-482 S	Maine Yankee Atomic Power Co.	B101280641	50-367
	B101070426	50-482 S		B101060320	50-306
	B101070431	50-482 S		B101070584*	50-309
	B101070433	50-482 S		B101070591*	50-309
	B101070490	50-482 S		B101120210	50-359
	B101140573	PR		B101120229	50-309
	B101270343	50-482 Q		B101120233*	50-309
	B101270352	50-482 Q		B101160114*	50-309
	B101270360	50-482 Q		B101220340	50-309
	B101280048	50-482 Q		B101270368	50-309
	B101280497*	50-482 Q		B101270667	50-309
				B101270748	50-309

AFFILIATION	NUMBER	CATEGORY	AFFILIATION	NUMBER	CATEGORY
	8101290302	50-309 R		8101090181*	50-320
	8101290308*	50-309 R		8101090239	50-289
	8101300083	50-309 O		8101090246*	50-289
	8101303542	50-309 F		8101050419	50-320
ine, State of	8101300381*	CONTRACT		8101060409	50-289
pletion Interventors	8101050398	50-329 O		8101060632	50-289
ark II Owners Group	8101210373*	TOPREP		8101080103	50-289
quette Univ	8101220083	PR		8101120437	50-289
rs & McLennan, Inc. - M & M Nuclear	8101090457	50-333 J		8101130042	50-289
Consultants, Inc. Div	8101090457	50-333 J		8101130053	50-289
	8101090463	50-333 J		8101140260	50-320
	8101090464	50-333 J		8101140583	50-289
	8101090464	50-333 J		8101140650	50-320
	8101050466	50-302 J		8101140662	50-320
	8101090469	50-438 J		8101140730	50-320
	8101090469	50-438 J		8101140960	50-289
	8101090475	50-302 J		8101190344	50-320
	8101090478	50-250 J		8101190482	50-320
	8101090478	50-250 J		8101190486*	50-320
	8101090481	50-258 J		8101210740	50-320
	8101090484	50-259 J		8101210279	50-289
	8101090486	50-259 J		8101210379	50-289
	8101090486	50-259 J		8101210469	50-289
	8101090490	50-259 J		8101210471*	50-289
	8101090490	50-259 J		8101210941	50-320
	8101090490	50-259 J		8101210587	50-289
	8101090517	50-438 J		8101210594	50-289
	8101090517	50-438 J		8101220512	50-289
	8101090524	50-327 J		8101230219	50-289
	8101090526	50-327 J		8101230229	50-289
	8101090535	50-390 J		8101230534	50-320
	8101090535	50-390 J		8101230594	50-320
	8101090542	50-399 J		8101230613	50-320
	8101090590	50-321 J		8101230623	50-320
	8101090590	50-321 J		8101260507	50-289
	8101090596	50-335 J		8101260909*	50-289
	8101090596	50-335 J		8101270361*	50-289
	8101090561	50-382 J		8101270367*	50-289
	8101090566	50-382 J		8101270592	50-289
	8101090571	50-250 J		8101270605	50-289
	8101090571	50-250 J		8101270637	50-320
	8101090601	50-348 J		8101270648	50-289
	8101090647	50-259 J		8101270671*	50-320
	8101090647	50-259 J		8101270674	50-289
	8101090647	50-259 J		8101270721	50-289
	8101090650	50-321 J		8101270726*	50-289
	8101090650	50-321 J		8101290493	50-320
	8101090659	50-321 J		8101290520	50-289
	8101090659	50-321 J		8101290593	50-289
	8101090688	50-390 J		8101290692*	50-289
	8101090698	50-340 J		8101290697	50-289
	8101090663	50-327 J		8101290662*	50-289
	8101090663	50-327 J		8101290666*	50-289
	8101130357	50-280 J		8101290729*	50-289
	8101140233	50-321 J		8101290734*	50-289
	8101140393	50-327 J		8101290737*	50-289
	8101210586	50-311 J		8101290795	50-289
	8101220351	50-346 J		8101290799*	50-289
	8101220545	50-348 J		8101300488	50-289
	8101270735	50-272 J		8101290726	50-358
	8101270738	50-272 J		8101300325*	CONTRACT
ryland, State of	8101190817	50-320 H		8101210378*	CONTRACT
	8101300349*	CONTRACT		8101100129	40-858A
achusetts Institute of Technology	8101070362	50-206 P		8101100134*	40-858A
Johnson Oas Products	8101100819	EXPORTIC		8101300079*	CONTRACT
ayer, Brown & Platt	8101230032	70-1308		8101050100	50-416
	8101230049	70-1308		8101050329	50-416
	8101260175	70-1308		8101050329	50-416
utchen, Doyle, Brown & Emerson	8101270286	PROJ		8101050335*	50-416
cklanburg County, NC	8101050072	50-369 O		8101050335*	50-416
etropolitan Edison Co.	8101050039	50-289 P		8101050339	50-416
	8101050039	50-289 P		8101050339	50-416
	8101050064	50-320 H		8101050341*	50-416
	8101050071	50-320 H		8101050341*	50-416
	8101050081	50-289 T		8101050346	50-416
	8101050090*	50-289 T		8101050346	50-416
	8101050098*	50-289 T		8101060435	50-416
	8101050105*	50-289 T		8101060442*	50-416
	8101050111*	50-289 T		8101070445	50-416
	8101050123*	50-289 T		8101070445	50-416
	8101050133*	50-289 T		8101120009	50-416
	8101050150*	50-289 T		8101120077*	50-416
	8101050197*	50-289 T		8101120123	50-416
	8101050174	50-320 B		8101120125	50-416

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	0101130226	50-416 A		8101070353	50-298 0
	8101130226	50-416 A		8101070355	50-298 0
	8101150639	50-416 K		8101070357	50-298 0
	8101150639	50-416 K		8101070360	50-298 0
	8101190147	50-416 S		8101070363	50-298 0
	8101220294	50-416 A		8101070477	50-298 0
	8101220294	50-416 A		8101070400	50-298 0
	8101220337	50-416 A		8101070409	50-298 0
	8101220337	50-416 A		8101070492	50-298 0
	8101220341	50-416 B		8101070507	50-298 0
	8101220341	50-416 S		8101070511	50-298 0
	8101220474	50-416 G		8101070514	50-298 0
	8101230482	50-416 S		8101070521	50-298 0
	8101230482	50-416 S		8101070642	50-298 0
	8101230498	50-416 A		8101080074	50-298 0
	8101230498	50-416 A		8101120050	50-298 0
	8101230500	50-416 S		8101120138	50-298 0
	8101230500	50-416 S		8101120162	50-298 0
	8101230559	50-416 S		8101120167	50-298 0
	8101230599	50-416 S		8101130587	50-298 0
	8101230607	50-416 S		8101130593	50-298 0
	8101230607	50-416 S		8101160448	50-298 0
	8101240519	50-416 S		8101270641	50-298 0
	8101240519	50-416 S		8101270645	50-298 0
	8101240765	50-416 S		8101270649	50-298 0
	8101260765	50-416 S		8101270653	50-298 0
	8101270088	50-416 S		8101270715	50-298 0
	8101270088	50-416 S		8101270719	50-298 0
	8101270104	50-416 S		8101270775	50-298 0
	8101270104	50-416 S		8101270784	50-298 0
	8101270843	50-416 A		8101140096	State Prog
	8101290367	50-416 O	Neve, State of	8101200022	State Prog
	8101300388	50-416 B	New England Coalition on Nuclear	8101070513	50-441 C
	8101300388	50-416 B	Pollution	8101090306	50-441 C
	8101300424	50-416 B	New Jersey, State of	8101080185	50-214 F
	8101300455	50-416 B		8101060127	WASTE MGT
	8101300455	50-416 B	New Mexico, State of	8101130115	XPORILIC
	8101300475	50-416 S	New York International Customs Service,	8101130119	XPORILIC
	8101300475	50-416 S	Inc	8101280376	50-247 F
	8101300371	50-241 H	New York Univ	8101270229	REH
Mississippi State Univ	8101150499	50-416 A	New York Univ Medical Center New York, NY	8101200173	50-57 F
Mississippi, State of	8101260182	50-482 Q		8101100213	State Prog
Missouri, State of	8101260192	50-482 Q	New York, State Univ. of, Buffalo	8101100221	State Prog
	8101140945	XPORILIC	New York, State of	8101190197	50-247 F
Mitsubishi International Corp (subs of	0101140950	XPORILIC		8101190202	50-247 F
Mitsubishi Corp)	8101150031	XPORILIC		8101190207	50-247 F
Mitsui & Co. (U.S.A.), Inc. (subs of	8101150034	XPORILIC		8101190214	50-247 F
Mitsui & Co., Ltd.)	8101280362	XPORILIC		8101190550	State Prog
	8101210027	CONTRACT		8101190579	State Prog
Mobile Systems	8101140930	XPORILIC		8101300316	CONTRACT
Monsanto Research Corp.	8101050506	50-70 G	Newberry Township TMI Steering Committee	8101200018	50-204 C
Morgen, Lewis & Bockius	8101050515	50-70 G	Niagara Mohawk Power Corp.	8101050087	50-220 C
	8101220178	PR		8101060400	50-220 C
Murray & Trettel, Inc	8101220374	50-10 P		8101060540	50-220 C
	8101220379	50-10 P		8101060546	50-220 C
	8101220391	50-10 P		8101060639	50-220 C
N.M. Neumann Consulting Engineering	8101200498	CONTRACT		8101060647	50-220 C
Services				8101070381	50-220 C
NUS Corp	8101060457	50-261 P		8101070441	50-220 C
	8101060498	50-324 P		8101070448	50-220 C
	8101190419	50-324 P		8101070450	50-220 C
	8101220357	50-280 P		8101070451	50-220 C
	8101280075	27-39		8101070455	50-220 C
NYSAC, Inc.	8101280451	F01A		8101070500	50-220 C
	8101280455	F01A		8101070504	50-220 C
	8101280459	F01A		8101100419	50-220 C
	8101200464	F01A		8101100428	50-220 C
	8101280469	F01A		8101120241	50-220 C
	8101280474	F01A		8101120335	50-220 C
	8101280478	F01A		8101120369	50-220 C
National Academy of Sciences	8101100316	CONTRACT		8101130239	50-410 C
National Audubon Society, Central Midwest	8101260249	50-320 G		8101140696	50-220 C
Regional Office				8101150501	50-220 C
Natural Resources Defense Council	8101160200	70-2623		8101150502	50-220 C
	8101230462	70-2623		8101150679	50-220 C
Navy, Dept. of	8101120042	71-400		8101150684	50-220 C
	8101120054	71-358		8101210357	50-220 C
	8101120057	71-358		8101210595	50-220 C
Navy, Dept. of, Naval Research Laboratory	8101160071	CONTRACT		8101220438	50-220 C
Nebraska Public Power District	8101050466	50-298 P		8101230580	50-220 C
	8101070155	50-298 Q		8101300055	50-220 C
	8101070351	50-298 S	Nissho-Iwai American Corp	8101300452	50-410
				8101290806	XPORILIC

Agency	Contract Number	Contract Description	Contract Type	Contract Status
Atomic Energy Commission	B101120010	State Prog		
	B101140147	State Prog		
	B101090076	50-336 P		
	B101090004	50-213 F		
	B101090004	50-213 F		
	B101090012	50-213 P		
	B101090012	50-213 P		
	B101100038*	50-423 S		
	B101100769	50-213 O		
	B101120327	50-213 P		
B101120351	50-336 B			
B101120355*	50-336 B			
B101120413*	50-245 F			
B101120413*	50-245 F			
B101120415*	50-245 F			
B101120415*	50-245 F			
B101130138	50-213 P			
B101130138	50-213 P			
B101140718	50-336 Q			
B101150028	50-213 O			
B101150540*	50-245 Q			
B101150624	50-336 P			
B101160248	50-213 P			
B101160248	50-213 P			
B101160248	50-213 P			
B101160363	50-245 P			
B101160541	50-245 S			
B101160549	50-336 S			
B101160613*	50-245 S			
B101160624*	50-336 B			
B101200274	50-245 R			
B101200277*	50-245 R			
B101200293	50-336 P			
B101200307	50-245 P			
B101210592	50-336 B			
B101220404	RE000			
B101230411	50-336 R			
B101230413*	50-336 R			
B101270670	50-245 P			
B101270712	50-213 F			
B101270712	50-213 F			
B101270712	50-213 F			
B101290219	50-245 P			
B101290265	50-245 P			
B101050460	50-336 P			
B101050476*	50-336 P			
B101260296	50-213 J			
B101260303	50-213 J			
B101270736	50-245 J			
B101270736	50-245 J			
B101270736	50-245 J			
B101270744	50-245 J			
B101270744	50-245 J			
B101270744	50-245 J			
B101270744	50-245 J			
B101290583	50-213 B			
B101050395	50-367 R			
B101050428	50-367 A			
B101060470	50-367 A			
B101070576	50-367 O			
B101090036	50-367 R			
B101090720	50-367 A			
B101100056*	50-367 O			
B101130499	50-367 R			
B101210320	50-367 R			
B101230582	50-367 R			
B101280641	50-367 O			
B101050296	50-282 P			
B101050262	50-282 P			
B101050267*	50-282 P			
B101050278	50-263 P			
B101070212	50-282 Q			
B101080298*	50-282 F			
B101080298*	50-282 F			
B101080266*	50-282 F			
B101080266*	50-282 F			
B101120218	50-263 P			
B101120294	50-282 P			
B101120297*	50-282 R			
B101130118	50-263 O			
B101130575	50-263 R			
B101130581*	50-263 O			
B101140156	50-263 Q			
B101160034*	50-263 F			
B101160392*	50-282 O			
B101160445	50-282 P			
B101190274	50-263 Q			
B101200145	50-282 Q			
B101200170	50-263 O			
B101200241	50-282 P			
B101210132	71-9086			
B101220398	50-282 O			
B101230490	50-263 Q			
B101260498	50-263 Q			
B101270635	50-282 S			
B101270658*	50-282 S			
B101270693	50-282 P			
B101270697*	50-282 P			
B101070306*	50-187 Q			
B101100168	71-6698			
B101270321	40-8771			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101150638*	50-285 P	Pennsylvania Univ of Personnel Decisions, Inc Philadelphia Electric Co	8101160337*	50-320 F
	8101160403	50-285 Q		8101300093*	CONTRACT
	8101160485	50-285 R		8101220074	PR
	8101160488*	50-285 R		8101140843*	CONTRACT
P B Andersen Pacific Gas & Electric Co	8101160542	50-235 Q		8101030265	50-277 S
	8101270731	50-285 J		8101030442	50-277 S
	8101300513	50-285 S		8101070348	50-277 S
	8101300519*	50-289 S		8101070367	50-352 S
	8101140813*	CONTRACT		8101070496	50-277 S
	8012290009	50-275 Q		8101090003	50-277 P
	8101050382	50-275 Q		8101090003	50-277 F
	8101050382	50-275 Q		8101100211*	50-277 Q
	8101050406	50-133 S		8101100775	50-277 Q
	8101050410*	50-133 S		8101120299	50-277 P
	8101060014	50-275 Q		8101120299	50-277 P
	8101060018	50-275 Q		8101120304*	50-277 P
	8101060018	50-275 Q		8101120304*	50-277 P
	8101070135	50-133 Q		8101120308*	50-277 F
	8101070206	50-133 Q		8101120308*	50-277 P
	8101120252	50-133 Q		8101120427	50-277 S
	8101120547	50-133 Q		8101120314	50-277 P
	8101130387	50-275 A		8101140519	50-278 S
	8101130566	50-275 Q		8101140744	50-278 Q
	8101130578	50-133 R		8101150873*	50-277 Q
	8101130585*	50-133 R		8101200266	50-278 S
	8101210555	50-275 A		8101210210	50-352 Q
	8101210555	50-275 A		8101210522	50-277 R
	8101220307	50-133 P		8101210522	50-277 R
	8101260301	50-275 Q		8101210528*	50-277 R
	8101260301	50-275 Q		8101220135*	50-277 Q
	8101270286	PROJ		8101220149*	50-277 S
	8101270452	50-133 P		8101220149*	50-277 S
	8101270672	50-275 A		8101230348	50-277 S
	8101280620	50-275 Q		8101220352	50-270 S
	8101300331	50-275 A		8101220468	50-278 S
	8101300728*	50-275 F		8101220477	50-277 S
Palos Community Hosp Palos Park, IL Paramater, Inc Parsons, Brinkerhoff, Ovada & Douglas, Inc Pathfinder Mines Corp	8101140527	PR		8101220483	50-277 S
	8101290746*	50-282 S		8101220488	50-277 S
	8002050467*	50-333 F		8101220496*	50-277 S
	8011250283	40-225*		8101230330*	50-277 F
	8101200019	40-6622		8101230338*	50-277 F
	8101270681	40-225*		8101230434	50-352 U
	8012310383	50-387 Q		8101230474	50-277 P
	8101050332	50-387 S		8101230586	50-277 S
Pennsylvania Power & Light Co	8101050071*	50-387 F		8101260500	50-352 S
	8101090071*	50-387 F		8101260564	50-277 S
	8101090075*	50-387 F		8101270315	50-463 Q
	8101090075*	50-387 F		8101270550	50-277 Q
	8101090080*	50-387 F		8101270557*	50-277 S
	8101090080*	50-387 F		8101270728	50-277 P
	8101090703	50-387 H		8101280506	50-278 S
	8101090703	50-387 H		8101280644	PR
	8101090897*	50-387 Q	Philadelphia, PA Philbrick, B B	8101160211	50-352 Q
	8101180076*	50-387 S		8101050637	ACRB
	8101120189	50-387 K		8101140934	XPGRI LIC
	8101120189	50-387 K		8101210310	40-344
	8101130320	50-387 A	Physicians for Social Responsibility Plateau Resources, Ltd. Pollack, M.S. Portland General Electric Co.	8101220301	40-7069
	8101130466	50-387 A		8101070446	50-142 Q
	8101130466	50-387 A		8101050311	50-344 S
	8101140861	50-387 Q		8101060020	50-344 Q
	8101150846*	50-387 S		8101070346	50-344 P
	8101190387	50-387 A		8101120567	50-344 Q
	8101190387	50-387 A		8101130271	50-344 P
	8101190390*	50-387 A		8101130564	50-344 R
	8101190390*	50-387 A		8101130572*	50-344 R
	8101190783*	50-387 S		8101140218	50-344 J
	8101210362	50-387 S		8101190443	50-344 S
	8101260370	50-387 A		8101190445*	50-344 S
	8101260370	50-387 A		8101210293	50-344 P
	8101278425	50-387 S		8101220270	50-344 P
	8101278425	50-387 S		8101220274*	50-344 Q
	8101278482	50-387 A		8101270453	50-344 P
	8101288151	50-387 A		8101270503	50-344 Q
	8101288151	50-387 A		8101270657	50-344 Q
	8101288158*	50-387 A		8101280939	50-344 S
	8101288159*	50-387 A		8101280946*	50-344 S
Pennsylvania State Univ	8101300500	50-387 A	Power Authority of the State of New York	8002050463	50-333 F
	8101140431	PR		8101060476	50-286 P
	8101300419	50-5 P		8101070382	50-286 F
	8101070202	50-387 Q		8101080129	50-333 Q
Pennsylvania, State of	8101070325*	50-328 F		8101080407	50-286 P
	8101120506	50-289 Q		8101080416*	50-286 P
	8101120511*	50-289 Q		8101080426*	50-286 P
				8101090604	50-333 P

	8101090812	50-286	P		8101140643	50-546
	8101090818*	50-333	P		8101220560	REG00
	8101090821*	50-286	S		8101230487	50-546
	8101090844*	50-333	P			
	8101120200	50-333	P		8101290504	50-546
	8101120205*	50-333	P		8101300421*	50-546
	8101120207*	50-333	P	Public Service Co. of New Hampshire	8101230497	50-443
	8101120215	50-333	P		8101280091	50-443
	8101120220*	50-333	P	Public Service Electric & Gas Co. of New Jersey	8101290521	50-354
	8101120226*	50-333	P			
	8101120302	50-333	S		8101290528*	50-354
	8101120306	50-333	S		8101050083	50-272
	8101120310*	50-333	S		8101050497*	50-354
	8101120354*	50-333	S		8101060480	50-354
					8101070190	50-311
	8101130308	50-333	R		8101070329	50-272
	8101130552	50-333	R		8101070329	50-272
	8101130550*	50-333	R		8101070340*	50-272
	8101140966	50-333	Q		8101070540*	50-272
	8101140975	50-333	Q		8101070543*	50-272
	8101160645	50-286	V		8101070343*	50-272
	8101160441	50-333	P		8101070557*	50-272
	8101160459	50-333	P		8101070557*	50-272
	8101160508	50-333	S		8101070562*	50-272
	8101160564*	50-333	S		8101080299*	50-272
	8101200287	50-286	R		8101080299*	50-272
	8101200290*	50-286	R		8101080305*	50-272
	8101210492	50-333	G		8101090643	50-272
	8101210496*	50-333	S		8101090651*	50-272
	8101210499	50-333	S		8101090698	50-272
	8101210506*	50-333	S		8101090707*	50-272
	8101260504	50-333	P		8101090852*	50-272
	8101270654	50-286	S		8101100760	50-272
	8101270717	50-286	S		8101120320	50-272
	8101270722*	50-286	S		8101120324*	50-272
	8101270854	50-286	S		8101120337	50-272
	8101280117	50-333	P		8101120376*	50-272
	8101280136	50-333	S		8101130322	50-272
	8101300074*	50-333	Q		8101130382	50-272
	8101300466	50-286	F		8101150629	50-311
	8101300592	50-286	P		8101150629	50-311
	8101300596*	50-286	P		8101160481	50-272
	8101230172	50-461	Q		8101200357	50-272
	8101230172	50-461	Q		8101200359*	50-272
	8101230178*	50-461	Q		8101200396	50-272
	8101230178*	50-461	Q		8101200391*	50-272
	8101290105*	CONTRACT			8101200644*	50-272
	8101140988	50-369	Q		8101200644*	50-272
	8101270047	50-247	Q		8101200645*	50-272
	8101060448	50-267	V		8101200645*	50-272
	8101060556	50-267	V		8101210455	50-311
	8101070205*	50-267	Q		8101210458*	50-311
	8101070211*	50-267	Q		8101210476	50-272
	8101080085	50-267	Q		8101210482*	50-272
	8101090602	50-267	F		8101220103	PR
	8101120134	50-267	Q		8101230441	50-311
	8101120143	50-267	Q		8101260552	50-272
	8101120284	50-267	P		8101260557	50-272
	8101120425	50-267	P		8101260642*	50-272
	8101120427*	50-267	P		8101260650*	50-272
	8101130369	50-267	P		8101270491	50-272
	8101130374*	50-267	P		8101270561	50-272
	8101130393	50-267	P		8101270569*	50-272
	8101130394*	50-267	P		8101270616	50-272
	8101130396*	50-267	P		8101280499	50-272
	8101130398*	50-267	P		8101280504	50-272
	8101140191	50-267	Q		8101290781*	50-354
	8101140486	50-267	R		8101090094	50-376
	8101140489*	50-267	R	Puerto Rico Electric Power Authority	8101231038	50-522
	8101140625	50-267	S	Puget Sound Power & Light Co	8101080111	REG00
				Quadrax Corp		
	8101140630*	50-267	S			
	8101140639	50-267	S	R & B Associates	8101130263	PR
	8101140646*	50-267	S		8101130274*	PR
	8101210406	50-267	S		8101130333	PR
	8101210410*	50-267	S	Reactor Experiments, Inc	8101190756	XPORTEL
				Rehab Group, Inc.	8101060321*	CONTRACT
	8101210480	50-267	S			
	8101210488*	50-267	S	Reliance Testing Laboratories, Inc.	8101080370	71-401
	8101220413	50-267	S		8101080376*	71-401
	8101220421*	50-267	S		8101140152	71-903
	8101220548	50-267	V	Renewable Polytechnic Inst	8101270992	REG
				Reuter-Stokes, Inc.	8101100499	XPORTEL
	8101220553*	50-267	V			
	8101230187	50-267	R		8101140885	XPORTEL
	8101270629	50-267	A	Rhode Island, State of	8101060436*	COMM18
	8101050015	50-546	A		8101060440*	COMM18
	8101060449	NUREG			8101060446*	COMM18
Public Service Co. of Indiana, Inc.						

CORPORATE SOURCE INDEX

40

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101130295*	50-395 A	Standardized Nuclear Unit Power Plant System	8101050052	50-482
	8101130103	50-395 A		8101230565	50-482
	8101160290	50-395 A		8101270264	50-482
	8101160395	50-395 A		8101290690	50-482
	8101200258	50-395 A	State Dept of	8101050487	XPORTLIC
	8101210354	50-395 K	State Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs	8101090256	XPORTLIC
	8101210358*	50-395 K		8101090022	XPORTLIC
	8101220262	50-395 A		8101090792	XPORTLIC
	8101220589	50-395 B		8101100435	XPORTLIC
	8101230406	50-395 A		8101100442	XPORTLIC
	8101230410*	50-395 A		8101100453	XPORTLIC
	8101260491	50-395 B		8101100461	XPORTLIC
	8101260607	50-395 B		8101100474	XPORTLIC
	8101260643	50-395 B		8101100480	XPORTLIC
	8101270011	50-395 G		8101100485	XPORTLIC
	8101270496	50-395 V		8101120027	XPORTLIC
	8101280119	50-395 A		8101120186	XPORTLIC
	8101280287	50-395 B		8101120188	XPORTLIC
	8101280331	50-395 H		8101120198	XPORTLIC
	8101290129	50-395 F		8101200446	XPORTLIC
North Carolina Public Service Authority	8101290194	50-395 G		8101210105	XPORTLIC
North Carolina, State of	8101260161	50-395 H		8101220587	XPORTLIC
North Dakota, State of	8101270062*	State Prog		8101280094	XPORTLIC
Southern California Edison Co	8101200008	PROJ		8101290457	XPORTLIC
	0101050074	50-206 O		8101290470	XPORTLIC
	8101050376	50-206 V		8101290477	XPORTLIC
	8101050376	50-206 V		8101290653	XPORTLIC
	8101050376	50-206 V		8101140886	50-250
	8101050386	50-395 O	Steel, Hector & Davis	8101160261	50-389
	8101060024	50-206 G		8101280503	50-250
	8101060408	50-206 F		8101050473*	50-298
	8101060438*	50-395 I		8101060489*	50-322
	8101060475	50-206 P	Stone & Webster Engineering Corp	8101070536*	50-358
	8101060513	50-206 V		8101090892	REG00
	0101060513	50-206 V		8101200640*	0A999
	8101060513	50-206 V		8101280077*	50-358
	8101060523*	50-206 V		8101210391*	CONTRACT
	8101060523*	50-206 V	Structural Mechanics Associates	8101060002*	50-322
	0101070216	71-9111	Suffolk County, NY	8101200222*	50-322
	8101090460	50-206 P		8101060742*	FOIA
	8101090503	50-395 A	Bun Shipbuilding & Dry Dock Co (subs Bun Co., Inc.)	8101060752*	FOIA
	8101090625	50-361 K		8101060766*	FOIA
	8101090625	50-361 K		8101140467	50-260
	8101130093	50-361 A	Buray County, VA	8101090924	XPORTLIC
	8101130235	50-361 C	Sweden	8101280358	FOIA
	8101130247	50-206 P	Byracuse Univ.		
	8101130289	50-206 P			
	8101130544	50-206 P			
	8101130638	50-206 G	TERA Corp.	8101130555*	CONTRACT
	8101140516	50-361 E	Technimet Corp.	8101290746*	50-282
	8101140516	50-361 E		8101290749*	50-282
	8101160110	50-361 A	Technetron Research, Inc.	8101270727	CONTRACT
	8101160465	50-206 P	Technetron, Inc.	8101060237*	CONTRACT
	8101160504	50-206 B			
	8101160513*	50-206 B	Teledyne Energy Systems	8012290613	71-6744
	8101200286	50-206 P	Teledyne Isotopes	8101190103*	70-124
	8101210232	50-206 G	Tennessee Valley Authority	8011250336	50-327
	8101210384	50-361 B		8011250336	50-327
	8101210384	50-361 B		8011250336	50-327
	8101210484	50-206 R		8101050215	50-327
	8101210489*	50-206 R		8101050227*	50-327
	8101210527	50-206 P		8101050241	50-327
	8101220180	50-361 A		8101050241	50-327
	8101220187	50-361 A		8101050250*	50-327
	8101230128	50-361 G		8101050250*	50-327
	8101230128	50-361 G			
	8101230137*	50-361 G			
	8101230137*	50-361 G			
	8101270511	50-206 G			
	8101270517	50-361 O			
	8101270751	50-206 P			
	8101290807	50-361 B			
	8101300468	50-206 P			
	8101300759*	50-361 G			
	8012120057	PR			
University of Illinois, School of Medicine	8101200112*	0A999			
West Fabricating & Welding Co. subs. of IU International Corp.)	8101300217	NUREG		8101070417	50-438
West Research Institute	8101300824	REB		8101070417	50-438
Wegel & McDiarmid	8101090348	50-389 H		8101070424	50-438
	8101090360*	50-389 H		8101070429	50-438

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101080292*	50-518 G		8101190496	50-296 G
	8101080337*	50-510 G		8101190593	50-299 G
	8101090121*	50-438 G		8101190603*	50-299 G
	8101090677	50-259 S		8101190606	50-296 G
	8101090681*	50-259 S		8101190612*	50-296 G
	8101090834*	50-327 O		8101200233*	50-327 F
	8101090877	RE000		8101200233*	50-327 F
	8101100287*	50-438 O		8101200237*	50-327 F
	8101100287*	50-439 G		8101200237*	50-327 F
	8101100301*	50-553 O		8101210157	50-259 G
	8101120240	50-327 G		8101210157	50-259 G
	8101120240	50-327 O		8101210157	50-259 G
	0101120240	50-327 G		8101210239	50-320 G
	0101120287	50-328 A		8101210239	50-320 G
	8101120331	50-327 P		8101210239	50-320 G
	8101120411	50-327 P		8101210239	50-320 G
	8101120411	50-327 P		8101210327	50-438 O
	8101130409	50-259 S		8101210348	50-553 G
	8101130412*	50-259 S		8101210390	50-318 G
	8101130429	50-260 S		8101210421	50-390 G
	0101130436*	50-260 S		8101210421	50-390 G
	8101130457	50-327 S		8101210449	50-327 G
	8101130463*	50-327 S		8101210454*	50-327 G
	8101130467	50-296 S		8101210466	50-327 G
	8101130503*	50-296 S		8101220043	50-430 K
	8101130582	50-259 R		8101220044*	50-430 K
	8101130582	50-259 R		8101220058*	50-566 G
	8101130582	50-259 R		8101220155	50-327 R
	8101130580*	50-259 R		8101220155	50-327 R
	8101130588*	50-259 R		8101220164*	50-327 R
	0101130588*	50-259 R		8101220202	50-327 G
	8101130595	50-259 R		8101220207	50-553 A
	8101130595	50-259 R		8101220207	50-553 A
	8101130595	50-259 R		8101220211*	50-553 A
	8101130600	50-327 S		8101220291	50-327 P
	8101130601*	50-259 R		8101220291	50-327 P
	8101130601*	50-259 R		8101220311	50-259 G
	0101130601*	50-259 R		8101220311	50-259 G
	8101130612*	50-327 G		8101220311	50-259 G
	8101140474	50-328 S		8101220311	50-259 G
	8101140485	50-328 S		8101220311	50-259 G
	8101140485	50-328 S		8101220311	50-259 G
	8101140485	50-328 S		8101220311	50-259 G
	8101140499	50-518 S		8101220311	50-259 G
	8101140593	50-390 S		8101220311	50-259 G
	8101140593	50-390 S		8101220311	50-259 G
	0101140611	50-438 S		8101220311	50-259 G
	8101140616	50-328 S		8101220318	50-327 G
	8101140616	50-328 S		8101220318	50-327 G
	8101140616	50-328 S		8101220372	50-430 A
	8101140616	50-328 S		8101220372	50-430 A
	8101140618	50-390 S		8101220373*	50-430 A
	0101140618	50-390 S		8101220375*	50-430 A
	8101140619	50-327 O		8101220376	50-259 G
	8101140627	50-438 S		8101220376	50-259 G
	0101140636	50-328 S		8101220376	50-259 G
	8101140866	50-259 G		8101220376	50-259 G
	8101150013	50-327 G		8101220377*	50-430 A
	8101160252	50-259 G		8101220383	50-327 O
	8101160418	50-390 A		8101220411	50-259 P
	8101160418	50-390 A		8101220411	50-259 P
	0101160429	50-327 P		8101220411	50-259 P
	8101160462	50-390 S		8101220444	50-260 G
	8101160462	50-390 S		8101220449*	50-260 G
	8101160472	50-327 R		8101220499	50-327 G
	8101160474*	50-327 R		8101220505*	50-327 G
	8101160477	50-327 G		8101220511	50-327 G
	8101160483*	50-327 G		8101220518*	50-327 G
	8101160490	50-260 S		8101220523	50-327 G
	8101160494	50-327 P		8101220532*	50-327 G
	8101160498*	50-260 S		8101230296	50-391 G
	8101160520	50-259 G		8101230311	50-439 G
	8101160525*	50-259 S		8101230384	50-430 A
	8101160739*	50-260 G		8101230426	50-518 G
	8101190031	50-518 G		8101230436	50-327 G
	8101190362	50-438 S		8101230436	50-327 G
	8101190380	50-328 S		8101230468	50-393 G
	8101190400	50-328 S		8101230468	50-390 G
	8101190405	50-390 S		8101230488	50-438 G
	8101190405	50-390 S		8101230488	50-438 G
	8101190473	50-566 S		8101230542	50-390 S
	8101190480	50-328 S		8101230553	50-390 S
	8101190485	50-328 G		8101230553	50-390 S
	8101190490	50-260 S		8101230562	50-320 G
	8101190494	50-328 S		8101230608	50-390 G
	8101190495*	50-260 S		8101230608	50-390 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101230713	50-518 S		8101300611	50-296
	8101260409	50-390 S		8101300615*	50-296
	8101260409	50-390 S		8101300620	50-299
	8101260416	50-327 P		8101300629*	50-299
	8101260418	50-328 0		8101300632	50-296
	8101260418	50-390 S		8181300641*	50-296
	8101260420*	50-327 P	Teton Exploration Drilling Co. - Inc	8101210369	40-8778
	8101260427	50-328 S		8101210370*	40-8778
	8101260427	50-328 S	Texas A & M Univ	8101140154	71-398
	8101260427	50-328 S		8101140163*	71-398
	8101260436	50-328 S		8012290323*	50-247
	8101260436	50-328 S	Texas Instruments, Inc	8101140326*	50-247
	8101260438	50-390 S		8101230604	50-466
	8101260438	50-390 S	Texas Public Interest Research Group	8101070586*	50-213
	8101260446	50-438 S	Texas Tech Univ.	8101070508*	50-10
	8101260446	50-438 S		8101070608*	50-10
	8101260619*	50-259 F		8101070608*	50-10
	8101260619*	50-259 F		8101120149*	50-206
	8101260619*	50-259 F		8101200206*	50-29
	8101260624*	50-259 F		8101210181*	50-245
	8101260624*	50-259 F		8101210223*	50-219
	8101260624*	50-259 F		8181210233*	50-155
	8101260706*	50-259 F		8101270141*	50-409
	8101260706*	50-259 F		8101270156*	50-244
	8101260706*	50-259 F	Texas Utilities Co	8101070298*	50-445
	8101270030	50-328 G		8101160500	50-445
	8101270231*	40-1341		8101160507*	50-445
	8101270234*	40-1341	Texas Utilities Generating Co	8101050318	50-445
	8101270242*	40-1341		8101050318	50-445
	8101270245	50-390 S		8181050478	50-445
	8101270251*	40-1341		8101050478	50-445
	8101270255*	40-1341		8101060462	50-445
	8101270419	50-438 S		8101100726*	50-445
	8101270427	TOPREF		8101100726*	50-445
	8101270572	50-296 S		8101100738*	50-445
	8101270579*	50-296 S		8101160233	50-445
	8101270609	50-328 0		8101160233	50-445
	8101270622	50-438 S		8101200242	50-445
	8101270639	50-583 S		8101200242	50-445
	8101270647	50-327 P		8181200246	58-445
	8101270659	50-438 R		8101200246	50-445
	8101270662	50-328 A		8101200253	50-445
	8101270668	50-296 R		8101200253	50-445
	8101270673*	50-296 S		8101218666	50-445
	8101270702	50-327 P		8101210666	50-445
	8101270705	50-296 S		8101270117	50-445
	8101270711*	50-296 S		8101270147	50-445
	8101270713	50-296 S		8101270152	50-445
	8101270716*	50-296 S		8101270152	50-445
	8101270732	50-328 S		8101270814	50-445
	8101280505	50-259 0		8101270814	50-445
	8101280505	50-259 0	Texas Utilities Services, Inc	8181270347	50-445
	8101280505	50-259 0	Texas, State of	8101270968	WASTE MGT
	8101280527	50-259 0	The Nuclear Regulatory Commission	8181290024	NUREG
	8101280527	50-259 0	Thorne Ecological Institute	8101130400*	50-267
	8101280527	50-259 0		8101230187	50-267
	8101290236	50-518 0		8101130031	50-289
	8101290262	50-438 R	Three Mile Island Alert	8101160251	50-289
	8101290262	50-438 R		8101200018	50-289
	8101290269*	50-438 R	Tobin, J. B	8101270272	50-528
	8101290269*	50-438 R		8101270272	50-528
	8101290330	50-259 0		8101270306*	50-528
	8101290350	50-259 0		8101270306*	50-528
	8101290489	50-518 S		8101270306*	50-528
	8101290550	50-438 S		8101050626	50-346
	8101290550	50-438 S	Toledo Edison Co.	8101060456	50-346
	8101290645	50-328 S		8101060459*	50-346
	8101290651	50-438 S		8101060473	50-346
	8101290672	50-391 0		8101060581	50-346
	8101290672	50-391 0		8101060589*	50-346
	8101300356	50-259 F		8101060597*	50-346
	8101300356	50-259 F		8101060603*	50-346
	8101300356	50-259 F		8101060610*	50-346
	8101300483	50-370 S		8101060614*	50-346
	8101300493	50-259 P		8101060624*	50-346
	8101300493	50-259 P		8101060667	50-346
	8101300501	50-260 S		8101060680*	50-346
	8101300504	50-296 S		8101060685	50-346
	8101300509	50-327 S		8101060692*	50-346
	8101300511	50-296 S		8101060698	50-346
	8101300512*	50-260 S		8101060705*	50-346
	8101300514*	50-296 S		8101060733	50-346
	8101300520*	50-296 S		8101060745*	50-346
	8101300525*	50-327 S		8101060749	50-346

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101060787*	50-346 S	United Kingdom	8101290809	XP0RTLIC
	8101070200	50-346 P	United Nuclear - Homestake Partners	8101070178*	PR
	8101070378	50-346 P		8101070186*	PR
	8101070380*	50-346 P	United Nuclear Corp.	8012100268*	70-734
	8101080110*	50-346 F		8101100026	40-0720
	8101080170	50-346 Q		8101160412*	70-020
	8101090027	50-346 P		8101160413*	70-020
	8101090029*	50-346 P		8101160414*	70-020
	8101130415	50-346 S	United Nuclear Corp., Naval Products Div.	8101220577*	70-371
	8101130417*	50-346 S		8101220584*	70-371
	8101130521	50-346 R		8101220629*	70-371
	8101130526*	50-346 R		8101290556	71-8006
	8101160461	50-346 P	Utah, State of	0101290249	40-3453
	8101190503	50-346 P	Vermont Yankee Nuclear Power Corp	8101050169	50-271 P
	8101190509*	50-346 P		0101050425	50-271 B
	8101200185	50-346 B		8101050433*	50-271 N
	8101220242	50-346 P		8101060366	50-271 P
	8101220424	50-346 B		8101060389	50-271 P
	8101220429*	50-346 S		8101060416	50-271 V
	8101220435	50-346 S		8101080347	50-271 B
	8101220440*	50-346 B		8101080352*	50-271 U
	8101220575	50-346 P		8101080391	50-271 P
	8101220582*	50-346 P		8101000430	50-271 P
	8101230405	50-346 P		8101090006	50-271 P
	8101260487	50-346 P		8101090533	50-271 P
	8101260493*	50-346 P		8101090539*	50-271 P
	8101270634	50-346 S		8101140707	50-271 J
	8101270636*	50-346 S		8101140913	50-271 U
	8101270676	50-346 P		8101150661	50-271 U
	8101270689	50-346 S		8101150605*	50-271 H
	8101270701*	50-346 B		8101160065*	50-271 B
	8101280348	50-346 Q		8101160379	50-271 P
	8101280348	50-346 Q		8101160447	50-271 P
	8101300484	50-346 P		8101160627*	50-271 Q
	8101300554*	50-346 Q		8101160640*	50-271 Q
	8101300571*	50-346 Q		8101200249	50-271 P
	8101300605	50-346 P		8101200380	50-271 P
	8101100296*	70-2479		8101210364	50-271 P
	8101100322*	FOIA		8101210500	50-271 R
	8101100354*	70-2479		8101210805*	50-271 P
	8101100362*	FOIA		8101220489	50-271 Q
	8101100368*	FOIA		8101220462*	50-271 P
	8101100375*	FOIA		8101270682	50-271 P
	8101140879	XP0RTLIC		8101270746	50-271 P
	8101150020	XP0RTLIC		8101300092	50-271 Q
	8101150026*	XP0RTLIC		8101300315	50-271 P
	8101190366	XP0RTLIC		8101300487	50-271 P
	8101200409	40-800		8101090589*	50-131
	8101290102	XP0RTLIC		8012300480	50-339
	8101090507	50-186 P		8101050352	50-338
	8101100393*	70-1739		8101050414	50-200
	8101070412	50-322 O		8101050423*	50-200
	8101070465	50-322 O		8101050468	50-200
	8101270675	50-322 O		8101050408	50-200
	8101270678*	50-322 O		8101050400	50-200
	8101160120	27-39		8101050400	50-280
	8101060770*	50-320 P		8101060308	50-200 P
	8101090929	ACR8		8101060308	50-200 P
	8101270610	40-8584		8101060300	50-280 P
	8101290448	40-8584		8101060300	50-280 P
	8012290618	71-5957		8101060349	50-338
	8101060111	NUREG		8101060367	50-338
	8101100157	70-687		8101060399*	50-338
	8101130123	50-34 P		8101070294	50-338
	8101220601	PR		8101070303*	50-338
	8101270470*	WASTE MGT		8101070309*	50-338
	8101270475*	WASTE MGT		8101070440*	50-338
	8101290649	WASTE MGT		8101070442*	50-338
	8101290654*	WASTE MGT		8101070454*	50-338
	8101120454	50-483 Q		8101070454*	50-338
	8101120454	50-483 O		8101070457*	50-338
	8101140905	50-483 B		8101070487*	50-338
	8101140509	50-483 B		8101070602*	50-200
	8101190479	50-483 O		8101070607*	50-200
	8101230615	50-483 O		8101090474	50-281
	8101260486	50-483 O		8101090580	50-339
	8101270853*	50-483 O		8101090630	50-339
	8101280307	50-483 O		8101090638*	50-339
	8101090462	40-8584		8101090641	50-280
	8101210329	40-8584		8101090641	50-280
	8101120537	50-289 O		8101090652*	50-280
	8101260261	50-289 O		8101090661*	50-280
				8101120120	50-280
				8101120280	50-330
				8101120341	50-330

	8101080115	REQ00			8101130488*	50-339
	8101090020	50-397	Q		8101130493	50-339
	8101090021*	50-397	Q		8101130528*	50-339
	8101140416	REQ00			8101130534	50-339
	8101140497	50-397	B		8101130539*	50-339
	8101140518	50-397	B			
	8101190347	50-397	A		8101130542*	50-338
	8101190396	50-397	A		8101150114	50-338
	8101210561	58-397	A		8101160436	50-339
	8101220525*	58-508	Q		8101160503*	50-280
	8101270464	50-397	Q			
	8101270471	50-397	Q		8101160511*	50-280
	8101270499	50-397	Q		8101160696*	50-280
	8101270505	50-397	Q		8101190357	50-281
	8101270669	50-397	A		8101190483	50-280
	8101270743	50-395	D		8101200218	50-338
	8101300588*	50-460	Q		8101200227*	50-280
Washington Service Bureau, Inc	8101290061	FD1A			8101200229	50-280
Washington, State of	8101220068	PR			8101200235*	50-200
	8101270941	WASTE NOT			8101200235*	50-280
Washington, Univ. of	8101270201	REB			8101200235*	50-280
	8101130037	50-445	Q		0101200235*	50-280
West Texas Legal Services	8101120004*	50-3	P		8101200278	50-338
Westchester County, NY	8101270319	50-247	Q		8101200278	50-338
	8101270957	40-1162			8101200285*	50-338
Western Nuclear, Inc (subs of Phelps					8101200289*	50-338
Edgemoor Corp I	8101100015	40-1162				
Western Nuclear, Inc.					8101200289*	50-338
	8101100021	40-1162			8101200295	50-280
Westinghouse Electric Corp	81012290495	71-6400			8101200297*	50-280
	81012290498*	71-6400			8101200333	50-281
	81012290502*	71-6400			8101200335*	50-281
	8101050327*	50-334	P			
	8101050347*	50-395	A		8101200337*	50-281
	8101060832	RES			8101200339	50-280
	8101070036	REB			8101200339	50-280
	8101100298	XPORTLIC			8101200343*	50-280
	8101100525	XPORTLIC			8101200348*	50-280
	8101130138*	50-29	P		8101200351	50-339
	8101130450*	50-255	P		8101200355*	50-339
	8101130584	TOPREP			8101200362	50-338
	8101140569	50-205	P		8101200364*	50-338
	8101140796*	CONTRACT			8101200375	50-339
	8101140931	70-2909			8101200383*	50-339
	8101190330	TOPREP			8101200431	50-338
	8101200134	70-1151			8101200437*	50-338
	8101200420	TOPREP			8101200444	50-339
	8101200423*	TOPREP			8101200452*	50-339
	8101210372	TOPREP			8101210439	50-338
	8101210375*	TOPREP			8101210446*	50-338
	8101210401*	TOPREP			8101220328	50-338
	8101210483	REVIEW ORP			8101220354	50-280
	8101220279*	50-344	P		8101220369	50-339
	8101220283	PR			8101220370*	50-339
	8101220333*	50-338	P		8101220452	50-338
	8101220333*	50-338	P		8101220456*	50-338
	8101220349*	50-364	P		8101220485	50-281
	8101220426	TOPREP			8101220492*	50-281
	8101220552	REQ00			8101220614	PR
	8101230109*	50-338	Q		8101230460	50-339
	8101230222*	TOPREP			8101230593	50-339
	8101260136	NUREG			8101230601*	50-339
	8101260317*	GA999			8101230605	50-280
	8101260389*	50-313	P		8101230611*	50-280
	8101260516	TOPREP			8101270582	50-338
	8101260649*	TOPREP			8101270588*	50-338
	8101260652*	TOPREP			8101270707	50-404
	8101260657*	TOPREP			8101290396	50-280
	8101270519*	50-348	P		8101290396	50-280
	8101270526*	50-348	P		8101290396	50-280
	8101270953*	GA999			8101290757	50-338
	8101290676*	50-247	P		8101300188	50-338
	8101290812	XPORTLIC				
	8101300490	XPORTLIC			8101300193	50-280
Westinghouse Electric Corp, Nuclear	8101160473*	50-206	P		8101300582	50-339
Energy Systems	8101160476*	50-206	P		8101300597*	50-339
					8101300706	50-339
					8101300714*	50-339

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Westinghouse Electric Corp., PWR Systems Div WidoFF, Reager, Selikowitz & Adler Wisconsin Electric Power Co	8101210377*	TOPREP		8101090009*	50-271 P
	8101270346*	40-1162		8101090521	50-29 P
	8101230211	TOPREP		8101120293	50-29 P
	8101130031	50-289 G		8101120296*	50-29 P
	81012170375	50-301 S		8101130130	50-29 P
	81012170615*	50-301 S		8101140361	50-29 F
	8101050429	50-266 S		8101140664	50-29 G
	8101050440*	50-266 S		8101140678*	50-29 P
	8101070570	50-266 O		8101140682*	50-29 P
	8101090113*	50-266 F		8101140692*	50-29 P
	8101090113*	50-266 F		8101140953	50-29 O
	8101090113*	50-266 F		0101150021	50-29 G
	8101090113*	50-266 F		8101150512	50-29 R
	8101050110*	50-266 F		8101150814*	50-29 R
	8101120201	50-266 O		8101210367*	50-271 P
	8101120333	50-266 S		8101270362	50-29 P
	8101120367*	50-266 S		8101270652	50-29 P
	8101140127	PR		0101300481	50-29 P
	8101150317	50-266 R		8101300703	50-29 S
	8101150519*	50-266 R		0101300726*	50-29 S
	8101160451	50-266 P	York, PA	8101070622*	50-280 F
	8101160451	50-266 P			
	8101200150	50-266 O			
	8101210589	50-266 P			
	8101210589	50-266 P			
	8101220415*	50-266 G		8101260379	50-305 P
	0101260340	50-266 F		8101270625	50-305 P
	8101260410	50-266 P		8101280518	50-305 S
	0101270360	50-266 S		8101280522*	50-305 S
	8101270364*	50-266 S		0101200520*	50-305 S
	8101270567	50-266 S		8101280535*	50-305 S
	8101270574*	50-266 S	Wisconsin, State of	0101300563*	50-305 S
	8101270666	50-266 P		8101220403	50-266 O
	8101270699	50-266 S	Wisconsin, Univ. of, Madison	8101300187*	CONTRACT
	8101270710*	50-266 S		8101260467	50-156 P
	8101280379	50-266 O	Helfstein, B L	0101300337*	CONTRACT
	8101280379	50-266 O	Worcester Polytechnic Inst	8101160529	50-134 R
	8101280521	50-266 O		8101290631*	50-134 K
	0101280521	50-266 G	Wyle Laboratories	8101290637*	50-134 K
Wisconsin Public Service Corp	8101050047	50-305 P		8101200291*	50-205 P
	8101060555	50-305 S			
	8101060574*	50-305 S		81012180067	40-8502
	8101070650	50-305 O		81012180073*	40-8502
	8101090529	50-305 P		8101270944	40-8502
	8101090708	50-305 S		8101270949*	40-8502
				8101290115	40-8502
	8101130435	50-305 S	Wyoming, State of	0101290552	40-8304
	8101130440*	50-305 S		8101290109	40-8502
	8101130586	50-305 R		8101290543	40-8728
	8101130591*	50-305 R		0101290601	40-8502
	8101210316	50-305 O		8101290606	40-0532
	8101210341	50-305 J	XVIZX Information Corp.	8101210553	CONTRACT
	8101220034	50-305 P	Yankee Atomic Electric Co.	8101070383	50-29 P
	8101220114*	50-305 O		8101000403*	50-271 P
	8101220355	50-305 I		8101060443*	50-271 P
	8101220389	50-305 O			

REPORT NUMBER INDEX

The subject category column in this index gives the document number and the symbol for the category of information within that document, for example, (d) 320 (1). The document subject categories are defined in Appendix A.

Subject categories for medical related items are also entered in this column by symbol, for example, AGRS. These categories are defined in Appendix B and listed by the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

[illegible]

[illegible]

0101230430*	50-230	P
0101230235*	50-280	P
0101230370*	50-339	P
0101210401*	TOPREP	
0101210375*	TOPREP	
0101270519*	50-348	P

VAEC-1235

VAEC-1235 ERR

0101230430*

0101230235*

0101230370*

0101210401*

0101210375*

0101270519*

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ed es enclosures are those indicated by an asterisk
the accession number in the indexes. The second
gives the accession number of the principal docu-
der which the enclosure is listed. Knowing the
number of the principal document, the date
and the category enables locating the title listing of
sure.

The subject category column in this index gives the docket
number and the symbol for the category of information
within that docket; for example, 50-320 P. The docket subject
categories are defined in Appendix A.

Subject categories for nondocketed items are also entered
in this column by symbol; for example, ACRS. These cate-
gories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7809210151	8012220437	80/11/28	50-10 P	8012100091	8012100002	80/11/21	50-550 A
7904040695	8012220437	80/11/28	50-10 P	8012100109	8012100002	80/11/21	50-580 A
7904060018	8011190175	81/01/06	COMM189104	8012100111	8012100002	80/11/21	50-560 A
7905230626	8012220437	80/11/28	50-10 P	8012100120	8012100002	80/11/21	50-580 A
7911270340	7911270339	79/11/14	50-10 P	8012100139	8012100002	80/11/21	50-452 A
8002050467	8002050463	80/01/31	90-333 F	8012100143	8012100002	80/11/21	50-452 A
8003270417	8012240475	80/12/10	50-155 G	8012100151	8012100002	80/11/21	50-492 A
8004250144	8004250139	80/03/10	F01A	8012100155	8012100002	80/11/21	50-452 A
8005060473	8012220437	80/11/28	50-10 P	8012100175	8012100002	80/11/21	70-371
8005080556	8012100002	80/11/21	50-592 A	8012100180	8012100002	80/11/21	70-371
8005220807	8012100002	80/11/21	50-580 A	8012100187	8012100002	80/11/21	70-754
8007250362	8007250359	80/07/09	F01A	8012100192	8012100002	80/11/21	70-754
8007250364	8007250359	80/07/09	F01A	8012100199	8012100002	80/11/21	70-29
8008050201	8012100002	80/11/21	50-452 A	8012100212	8012100002	80/11/21	71-9124
8009190849	8012220437	80/11/28	50-10 P	8012100220	8012100002	80/11/21	40-8712
8010011003	8012220437	80/11/28	50-10 P	8012100238	8012100002	80/11/21	70-1113
8010090608	8012220437	80/11/28	50-10 P	8012100245	8012100002	80/11/21	70-1113
8010090609	8012220437	80/11/28	50-10 P	8012100252	8012100002	80/11/21	F01A
8010100210	8010100204	80/10/01	F01A	8012100269	8012100002	80/11/21	70-734
8010150044	8012100002	80/11/21	70-33	8012100279	8012100002	80/11/21	70-794
8010160686	80101090779	80/12/09	50-201 G	8012100284	8012100002	80/11/21	70-29
8010170702	8012220437	80/11/28	50-10 P	8012100290	8012100002	80/11/21	71-9124
8010230624	8012290489	80/12/11	10CFR	8012100302	8012100002	80/11/21	70-1113
8010280823	8012220437	80/11/28	50-10 P	8012100316	8012100002	80/11/21	70-1113
8011070118	8011070114	80/07/23	F01A	8012100322	8012100002	80/11/21	70-364
8011100496	8012240475	80/12/10	50-155 O	8012100327	8012100002	80/11/21	70-364
8011190620	8011190612	80/11/10	SECY	8012100336	8012100002	80/11/21	70-734
8011190627	8011190612	80/11/10	SECY	8012100340	8012100002	80/11/21	70-734
8011190641	8011190612	80/11/10	SECY	8012100344	8012100002	80/11/21	70-734
8011190657	8011190612	80/11/10	SECY	8012100351	8012100002	80/11/21	40-8707
8011190663	8011190612	80/11/10	SECY	8012100357	8012100002	80/11/21	71-9129
8011190673	8011190612	80/11/10	SECY	8012100360	8012100002	80/11/21	71-9129
8011190681	8011190612	80/11/10	SECY	8012100366	8012100002	80/11/21	71-9129
8011240002	8012100002	80/11/21	50-452 A	8012100380	8012100002	80/11/21	70-925
8011240009	8012100002	80/11/21	50-580 A	8012100386	8012100002	80/11/21	70-925
8011240224	8012100002	80/11/21	50-452 A	8012100397	8012100002	80/11/21	70-925
8011290112	8012100002	80/11/21	50-580 A	8012100396	8012100002	80/11/21	71-4986
8011250339	8011250336	80/11/21	50-327 S	8012100400	8012100002	80/11/21	F01A
8011290350	8011250354	80/11/12	50-254 S	8012100402	8012100002	80/11/21	F01A
8011260093	8012100002	80/11/21	50-592 A	8012100549	8012180252	80/12/11	50-498 O
8012020797	8012020784	80/02/20	ACRS	8012110052	8012110047	80/11/17	COMM18910N
8012020804	8012020784	80/02/20	ACRS	8012110612	8012290499	80/12/11	10CFR
8012080094	80101060699	80/12/11	10CFR	8012150262	80101150262	81/01/07	ORG
8012100023	8012100002	80/11/21	F01A	8012180154	8012160144	80/11/26	50-219 I
8012100031	8012100002	80/11/21	50-592 A	8012170615	8012170575	80/12/11	50-301 B
8012100050	8012100002	80/11/21	50-592 A	8012180073	8012180067	80/11/11	40-8502
8012100059	8012100002	80/11/21	50-592 A	8012180263	8012180252	80/12/11	50-498 O
8012100071	8012100002	80/11/21	50-592 A	8012180267	8012180252	80/12/11	F01A
				8012180288	8012180281	80/12/11	50-384 B

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
801220449	801220437	80/11/20	50-10 P	8101050433	8101050425	80/12/24	50-271 S
801220456	801220437	80/11/20	50-10 P	8101050438	8101050320	80/12/26	50-313 S
801220491	801220485	80/12/16	50-324 S	8101050448	8101050429	80/12/23	50-266 S
801220499	801220436	80/11/17	State Prog	8101050449	8101050444	80/12/05	50-335 S
801220523	801220520	80/12/19	50-247 F	8101050460	8101050455	80/12/23	50-366 S
801220463	801220476	80/12/11	10CFR	8101050473	8101050466	80/12/30	50-290 P
801220498	801220495	80/11/20	71-6400	8101050476	8101050460	80/12/19	50-336 P
801220502	801220495	80/11/20	71-6400	8101050497	8101050491	80/11/07	50-394 S
801220507	801220565	80/12/10	71-4986	8101050501	8101050432	80/12/26	50-360 S
801220581	801220577	80/11/26	71-5805	8101050506	8101050494	80/12/29	50-70 O
8101050508	8101050505	80/12/22	50-483 O	8101050509	8101050440	80/12/26	50-368 S
8101050522	8101050516	80/12/19	50-159 O	8101050515	8101050494	80/12/29	50-70 O
8101050528	8101050524	80/12/16	50-163 R	8101050519	8101050452	80/12/26	50-368 S
8101050542	8101050534	80/12/22	50-289 T	8101050534	8101050480	80/12/10	50-251 S
8101050549	8101050534	80/12/22	50-289 T	8101050536	8101050167	80/12/11	50-302 P
8101050555	8101050534	80/12/22	50-289 T	8101050537	8101050463	80/12/26	50-313 S
8101050563	8101050534	80/12/22	50-289 T	8101050541	8101050469	80/12/23	50-219 S
8101050569	8101050562	80/10/21	WREO	8101050542	8101050464	80/12/03	50-250 S
8101050570	8101050566	80/12/29	50-265 P	8101050546	8101050472	80/12/22	50-316 S
8101050580	8101050577	80/12/31	50-341 K	8101050547	8101050490	80/12/11	50-251 S
8101050585	8101050577	80/12/31	50-341 K	8101050576	8101050570	80/12/29	50-155 F
8101050593	8101050581	80/12/22	50-289 T	8101050579	8101050573	80/12/16	70-1151
8101050598	8101050581	80/12/22	50-289 T	8101050580	8101050570	80/12/29	50-195 F
8101050601	8101050594	80/12/24	50-269 P	8101050589	8101050585	80/12/12	50-131 F
8101050605	8101050581	80/12/22	50-289 T	8101050598	8101050594	80/12/11	70-27
8101050610	8101050612	80/12/10	50-369 A	8101050600	8101050595	80/12/22	50-329 O
8101050611	8101050601	80/12/22	50-289 T	8101050631	8101050628	80/12/02	COMMISSION
8101050612	8101050610	80/12/22	50-289 T	8101050634	8101050628	80/12/02	COMMISSION
8101050613	8101050610	80/12/02	50-261 P	8101050635	8101050633	80/12/19	50-320 F
8101050623	8101050681	80/12/22	50-289 T	8101050635	8101050633	80/12/31	50-322 O
8101050632	8101050616	80/12/30	50-329 F	8101060044	8101060041	80/11/24	10CFR
8101050633	8101050681	80/12/22	50-289 T	8101060089	8101060081	80/12/16	50-312 O
8101050645	8101050616	80/12/30	50-329 F	8101060119	8101060114	80/12/08	WASTE MGT
8101050650	8101050681	80/12/22	50-289 T	8101060122	8101060114	80/12/08	WASTE MGT
8101050657	8101050681	80/12/22	50-289 T	8101060130	8101060114	80/12/08	WASTE MGT
8101050665	810105062	80/12/23	71-9607	8101060204	8101060194	80/12/15	50-282 F
8101050673	8101050671	80/12/23	71-6375	8101060237	8101060231	80/12/19	CONTRACT
8101050681	8101050674	80/12/24	50-320 B	8101060258	8101060249	80/12/18	CONTRACT
8101050687	8101050676	80/12/11	TOPHEP	8101060272	8101060269	80/12/30	50-329 O
8101050689	8101050683	80/12/22	CONTRACT	8101060277	8101060274	80/12/11	50-170 H
8101050692	8101050685	80/12/29	50-317 S	8101060280	8101060275	80/11/13	CONTRACT
8101050694	8101050684	80/11/21	50-261 O	8101060281	8101060278	80/12/30	50-350 O
8101050696	8101050697	80/12/22	50-219 S	8101060287	8101060279	80/12/15	70-143
8101050698	8101050690	80/12/02	CONTRACT	8101060290	8101060285	80/12/23	50-295 O
8101050699	8101050691	80/12/23	50-219 S	8101060291	8101060279	80/12/15	70-143
8101050727	8101050715	80/12/33	50-327 P	8101060292	8101060288	80/12/30	50-335 P
8101050729	8101050723	80/12/23	50-219 S	8101060295	8101060279	80/12/15	70-143
8101050734	8101050720	80/11/15	40-1341	8101060303	8101060297	80/12/30	50-250 P
8101050746	8101050738	80/12/24	50-289 R	8101060306	8101060300	80/11/26	50-546 O
8101050750	8101050741	80/12/31	50-327 R	8101060311	8101060309	80/12/31	50-250 P
8101050759	8101050752	80/12/23	50-219 S	8101060321	8101060313	80/10/15	CONTRACT
8101050764	8101050760	80/12/31	50-302 P	8101060339	8101060333	80/12/30	50-317 P
8101050767	8101050762	80/12/22	50-282 P	8101060341	8101060328	80/12/31	CONTRACT
8101050775	8101050769	80/12/23	50-313 R	8101060347	8101060328	80/12/31	CONTRACT
8101050782	8101050780	80/12/12	50-466 D	8101060353	8101102071	80/12/29	50-369 A
8101050788	8101050781	80/11/18	50-498 A	8101060378	8101060374	81/01/02	50-335 P
8101050797	8101050781	80/12/31	50-334 P	8101060434	8101060431	80/12/31	50-395 I
8101050800	8101050781	80/12/31	50-334 P	8101060476	8101060432	80/12/03	COMMISSION
8101050805	8101050789	80/12/31	50-416 K	8101060438	8101060431	80/12/31	50-395 I
8101050806	8101050781	80/12/26	50-313 S	8101060440	8101060432	80/12/03	COMMISSION
8101050841	8101050789	80/12/31	50-416 K	8101060441	8101060431	80/12/31	50-395 I
8101050842	8101050784	80/11/28	50-250 S	8101060442	8101060435	80/12/29	50-416 A
8101050845	8101050830	80/12/24	50-304 K	8101060445	8101060431	80/12/31	50-395 I
8101050847	8101050837	80/12/30	80-395 A	8101060446	8101060432	80/12/03	COMMISSION
8101050849	8101050828	80/11/28	50-335 S	8101060457	8101060433	80/12/31	50-261 P
8101050853	8101050838	80/12/29	50-287 S	8101060459	8101060436	80/12/15	50-346 O
8101050855	8101050830	80/12/08	50-250 S	8101060468	8101060464	80/12/30	50-244 P
8101050867	8101050861	80/12/26	50-368 S	8101060471	8101060467	80/12/30	50-249 S
8101050877	8101050873	80/12/26	50-368 S	8101060477	8101060466	80/12/30	80-327 S
8101050880	8101050874	80/12/22	50-409 S	8101060479	8101060469	80/12/27	50-249 S
8101050887	8101050881	80/12/26	50-368 S	8101060482	8101060472	80/12/29	50-265 S
8101050888	8101050882	80/12/18	50-275 O	8101060484	8101060481	80/12/27	50-237 S
8101050891	8101050883	80/12/26	50-409 S	8101060488	8101060483	80/12/29	50-269 P
8101050896	8101050890	80/12/22	50-254 S	8101060489	8101060485	80/12/22	50-322 S
8101050903	8101050899	80/12/20	50-317 S	8101060491	8101060483	80/12/29	50-269 P
8101050910	8101050906	80/12/30	50-133 S	8101060492	8101060486	80/12/29	50-265 S
8101050913	8101050908	80/12/30	50-317 S	8101060498	8101060494	80/12/30	50-324 P
8101050920	8101050917	80/12/11	50-302 P	8101060507	8101060500	80/12/23	50-528 A
8101050923	8101050914	80/12/23	50-280 S	8101060509	8101060503	80/12/30	50-269 I

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

419

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8101060923	8101060513	80/12/30	50-206 V	8101070152	8101070145	80/12/11	50-367 Q
8101060930	8101060524	80/12/24	50-289 H	8101070155	8101070146	80/12/15	50-298 Q
8101060933	8101060524	80/12/24	50-289 H	8101070159	8101070145	80/12/11	50-369 Q
8101060938	8101060524	80/12/24	50-289 H	8101070164	8101070158	80/12/05	50-313 Q
8101060943	8101060524	80/12/24	50-289 H	8101070174	8101070170	80/11/21	50-255 Q
8101060545	8101060524	80/12/24	50-289 H	8101070178	8101070172	80/10/28	PR
8101060546	8101060540	80/12/26	50-289 H	8101070181	8101070170	80/11/21	50-255 Q
8101060551	8101060524	80/12/24	50-289 H	8101070183	8101070179	80/12/18	50-213 P
8101060554	8101060524	80/12/24	50-289 H	8101070186	8101070172	80/10/28	PR
8101060560	8101060524	80/12/24	50-289 H	8101070205	8101070198	80/12/04	50-267 Q
8101060563	8101060524	80/12/24	50-289 H	8101070211	8101070198	80/12/04	50-267 Q
8101060566	8101060559	80/12/30	50-366 B	8101070219	8101070215	80/11/14	50-267 Q
8101060568	8101060524	80/12/24	50-289 H	8101070223	8101070215	80/11/14	50-329 Q
8101060573	8101060564	80/12/31	50-321 P	8101070233	8101070229	80/11/19	50-329 Q
8101060574	8101060555	80/12/30	50-305 S	8101070236	8101070229	80/11/19	50-329 Q
8101060579	8101060572	80/12/30	50-366 B	8101070244	8101070240	80/11/18	50-285 Q
8101060583	8101060561	80/12/30	50-409 P	8101070252	8101070247	80/11/19	50-382 Q
8101060588	8101060581	80/12/26	50-346 P	8101070256	8101070248	80/12/02	50-213 F
8101060593	8101060582	80/12/30	50-321 P	8101070261	8101070257	80/11/14	50-382 Q
8101060596	8101060590	80/12/10	10CFR	8101070270	8101070265	80/12/01	50-320 F
8101060597	8101060581	80/12/26	50-346 P	8101070266	8101070269	81/01/02	50-269 P
8101060599	8101060567	81/01/02	50-338 S	8101070277	8101070292	80/12/22	70-2249 F
8101060603	8101060581	80/12/26	50-346 P	8101070298	8101070291	80/12/02	70-2249 F
8101060604	8101060598	80/12/30	50-237 S	8101070299	8101070292	80/12/22	50-445 F
8101060610	8101060581	80/12/26	50-346 P	8101070302	8101070291	80/12/02	50-445 F
8101060614	8101060581	80/12/26	50-346 P	8101070303	8101070294	80/10/14	50-338 Q
8101060617	8101060608	80/12/29	50-237 S	8101070305	8101070301	80/12/04	50-187 Q
8101060624	8101060581	80/12/26	50-346 P	8101070307	8101070291	80/12/02	50-445 F
8101060627	8101060621	80/12/31	50-331 S	8101070309	8101070294	80/10/14	50-338 Q
8101060633	8101060629	80/04/08	50-184 R	8101070310	8101070303	80/12/15	XPDRTLIC
8101060635	8101060630	80/12/30	50-155 S	8101070316	8101070313	80/12/03	50-413 Q
8101060637	8101060632	80/11/17	50-289 Q	8101070319	8101070317	80/12/01	50-367 A
8101060641	8101060632	80/11/17	50-289 Q	8101070325	8101070322	80/12/01	50-320 F
8101060647	8101060639	80/12/29	50-220 J	8101070327	8101070324	81/01/05	50-352 T
8101060652	8101060632	80/11/17	50-289 Q	8101070332	8101070324	81/01/05	50-352 T
8101060657	8101060632	80/11/17	50-289 Q	8101070334	8101070331	80/12/11	50-321 Q
8101060660	8101060640	80/12/30	50-366 B	8101070336	8101070331	80/12/11	50-321 Q
8101060669	8101060648	80/12/30	50-155 S	8101070338	8101070331	80/12/11	50-321 Q
8101060674	8101060668	80/12/30	50-346 S	8101070342	8101070331	80/11/20	50-298 S
8101060680	8101060667	81/01/02	50-261 B	8101070357	8101070355	80/11/25	50-298 S
8101060689	8101060678	80/12/30	50-346 S	8101070363	8101070360	80/11/19	50-298 S
8101060692	8101060685	81/01/02	50-346 S	8101070366	8101070365	80/12/31	50-324 S
8101060705	8101060698	81/01/02	50-257 S	8101070373	8101070370	80/12/30	50-324 S
8101060727	8101060715	80/12/30	50-461 Q	8101070377	8101070374	80/12/30	50-327 S
8101060731	8101060721	80/12/11	FOIA	8101070380	8101070378	81/01/02	50-344 P
8101060736	8101060724	80/12/22	FOIA	8101070385	8101070383	80/12/26	50-29 P
8101060742	8101060724	80/12/22	50-346 S	8101070437	8101070436	80/12/30	50-334 R
8101060745	8101060733	81/01/02	70-1100	8101070440	8101070434	80/12/02	50-338 F
8101060747	8101060739	80/10/31	CONTRACT	8101070443	8101070434	80/12/02	50-338 F
8101060750	8101060743	80/12/14	FOIA	8101070448	8101070448	81/01/03	50-220 Q
8101060752	8101060724	80/12/22	FOIA	8101070451	8101070448	81/01/03	50-220 Q
8101060757	8101060749	81/01/02	50-346 S	8101070452	8101070452	80/12/02	50-338 F
8101060759	8101060724	80/12/22	FOIA	8101070455	8101070448	81/01/03	50-220 Q
8101060766	8101060724	80/12/22	50-285 S	8101070457	8101070452	80/12/02	50-338 F
8101060769	8101060761	80/12/17	50-320 P	8101070468	8101070465	80/12/31	50-322 Q
8101060770	8101060764	80/11/28	FOIA	8101070478	8101070471	80/12/06	REG00
8101060775	8101060724	80/12/22	50-312 S	8101070480	8101070477	80/12/15	50-298 S
8101060781	8101060773	80/12/30	CONTRACT	8101070482	8101070471	80/12/06	REG00
8101060790	8101060783	80/12/18	50-316 B	8101070485	8101070471	80/12/06	REG00
8101060795	8101060789	80/12/31	NUREG	8101070492	8101070489	80/11/26	50-298 S
8101060806	8101060800	80/09/17	70-143	8101070493	8101070491	80/12/31	50-324 S
8101060819	8101060812	80/12/24	50-409 P	8101070502	8101070498	80/12/30	50-220 S
8101060861	8101060856	80/12/08	50-213 P	8101070504	8101070500	80/12/29	50-298 S
8101060873	8101060869	80/11/26	50-313 Q	8101070511	8101070507	80/11/18	50-298 S
8101060887	8101060884	80/11/26	CONTRACT	8101070521	8101070514	80/11/14	50-298 S
8101060942	8101060939	80/12/01	COMM18810N	8101070522	8101070518	80/12/01	50-321 F
8101060953	8101060952	80/12/12	30-320 P	8101070526	8101070518	80/12/01	50-321 F
8101060954	8101060952	80/12/12	FOIA	8101070529	8101070518	80/12/01	50-358 F
8101060956	8101060955	80/12/30	50-395 Q	8101070531	8101070524	80/12/26	50-334 S
8101070012	8101070004	80/12/30	50-395 Q	8101070536	8101070515	80/12/01	50-358 F
8101070017	8101070010	80/12/31	FOIA	8101070537	8101070532	80/12/11	50-272 F
8101070053	8101070046	80/12/30	FOIA	8101070540	8101070533	80/12/17	50-272 F
8101070070	8101070059	80/12/29	FOIA	8101070543	8101070531	80/12/17	COMM18810N
8101070080	8101070076	80/11/25	50-10 Q	8101070546	8101070538	80/12/18	50-289 Q
8101070118	8101070113	80/11/25	50-10 Q	8101070550	8101070541	80/12/17	COMM18810N
8101070125	8101070113	80/12/10	50-338 P	8101070557	8101070551	80/11/14	50-272 F
8101070134	8101070129	80/12/10	50-338 P	8101070562	8101070551	80/11/14	50-272 F
				8101070564	8101070559	80/12/16	50-312 F

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
0101070565	0101070550	00/12/18	50-267 P	0101070070	0101090064	00/12/19	50-254 B
0101070569	0101070559	00/12/16	50-312 F	0101090071	0101090067	00/11/13	50-387 F
0101070584	0101070560	00/12/03	50-309 F	0101090079	0101090067	00/11/13	50-387 F
0101070586	0101070577	00/12/08	50-213 P	0101090079	0101090074	00/11/18	50-295 B
0101070590	0101070582	00/12/04	PR	0101090080	0101090067	00/11/13	50-387 F
0101070591	0101070583	00/12/03	50-387 F	0101090088	0101090064	00/12/19	50-254 S
0101070602	0101070595	00/12/01	50-283 F	0101090091	0101090064	00/12/19	50-254 S
0101070607	0101070595	00/12/01	50-280 F	0101090093	0101090064	00/12/19	50-254 S
0101070608	0101070594	00/12/15	50-10 F	0101090096	0101090064	00/12/19	50-254 S
0101070613	0101070595	00/12/01	50-283 F	0101090113	0101090110	00/12/01	50-266 F
0101070622	0101070595	00/12/01	50-280 F	0101090114	0101090074	00/11/18	50-295 B
0101070628	0101070600	00/11/07	PR	0101090115	0101090110	00/12/01	50-266 F
0101070638	0101070600	00/11/07	PR	0101090118	0101090110	00/12/01	50-266 F
0101070645	0101070641	00/12/08	PR	0101090121	0101090112	00/12/05	50-430 B
0101070655	0101070652	00/12/13	XPORTRIC	0101090125	0101090123	00/12/01	50-393 F
0101080357	0101080047	00/12/12	PR	0101090127	0101090123	00/12/01	50-393 F
0101080358	0101080052	00/12/10	50-333 B	0101090137	0101090132	00/12/09	FOIA
0101080063	0101080079	00/11/28	50-254 B	0101090142	0101090132	00/12/09	50-237 B
0101080092	0101080079	00/11/28	50-254 B	0101090150	0101090132	00/12/09	50-237 B
0101080137	0101080101	00/12/03	50-346 F	0101090157	0101090132	00/12/09	50-237 B
0101080110	0101080101	00/12/03	50-346 F	0101090161	0101090132	00/12/09	50-237 B
0101080114	0101080104	00/12/11	50-272 P	0101090163	0101090132	00/12/09	FOIA
0101080137	0101080133	00/12/01	50-333 F	0101090166	0101090132	00/12/09	FOIA
0101080140	0101080131	00/12/23	50-498 A	0101090169	0101090132	00/12/09	FOIA
0101080142	0101080133	00/12/01	50-333 F	0101090171	0101090168	00/12/08	50-255 B
0101080149	0101080141	00/12/12	50-269 B	0101090172	0101090132	00/12/09	FOIA
0101080155	0101080141	00/12/12	50-269 B	0101090179	0101090132	00/12/09	FOIA
0101080161	0101080141	00/12/12	50-269 B	0101090183	0101090132	00/12/09	FOIA
0101080172	0101080162	00/12/05	50-219 F	0101090188	0101090175	00/12/10	50-269 P
0101080177	0101080141	00/12/12	50-269 B	0101090188	0101090132	00/12/09	FOIA
0101080179	0101080162	00/12/03	50-219 F	0101090195	0101090175	00/12/10	50-269 P
0101080186	0101080162	00/12/03	50-219 F	0101090196	0101090132	00/12/09	FOIA
0101080210	0101080205	00/11/17	50-258 B	0101090202	0101090132	00/12/09	FOIA
0101080227	0101080217	00/12/16	50-395 B	0101090205	0101090175	00/12/10	50-269 P
0101080233	0101080217	00/12/15	50-395 B	0101090209	0101090198	01/01/06	TOPREP
0101080237	0101080217	00/12/16	50-395 B	0101090213	0101090132	00/12/09	FOIA
0101080248	0101080217	00/12/16	50-395 B	0101090225	0101090214	00/11/28	50-313 B
0101080258	0101080249	00/12/01	50-282 F	0101090244	0101090234	00/11/17	50-294 Q
0101080266	0101080249	00/12/01	50-282 F	0101090246	0101090238	00/12/05	COMMISSION
0101080271	0101080264	00/11/19	50-440 B	0101090307	0101090298	00/12/03	FOIA
0101080284	0101080264	00/11/19	50-440 B	0101090318	0101090298	00/12/03	FOIA
0101080292	0101080267	00/12/05	50-518 B	0101090330	0101090321	00/12/25	50-287 B
0101080296	0101080289	00/11/14	50-482 B	0101090335	0101090328	00/11/17	State Prog
0101080297	0101080294	00/11/14	50-272 P	0101090351	0101090343	00/11/10	70-1007
0101080304	0101080279	00/12/12	50-320 U	0101090360	0101090348	01/01/08	50-389 M
0101080305	0101080294	00/11/14	50-272 P	0101090399	0101090392	00/12/10	CONTRACT
0101080307	0101080267	00/12/05	50-518 B	0101090493	0101090407	00/12/29	TOPREP
0101080309	0101080301	00/11/18	50-453 B	0101090518	0101090531	00/12/11	XPORTRIC
0101080318	0101080267	00/12/05	50-518 B	0101090539	0101090533	01/01/05	50-271 P
0101080326	0101080267	00/12/05	50-518 B	0101090597	0101090590	01/01/06	50-302 B
0101080331	0101080314	00/12/22	COMMISSION	0101090609	0101090603	01/01/05	50-302 S
0101080335	0101080330	00/12/11	50-320 H	0101090611	0101090604	01/01/06	50-333 P
0101080336	0101080314	00/12/22	COMMISSION	0101090618	0101090604	01/01/06	50-333 P
0101080340	0101080332	00/12/12	XPORTRIC	0101090621	0101090612	01/01/05	50-286 B
0101080343	0101080267	00/12/05	50-518 B	0101090622	0101090614	01/01/05	50-302 S
0101080352	0101080347	01/01/02	50-271 B	0101090632	0101090626	01/01/05	50-213 B
0101080360	0101080314	00/12/22	COMMISSION	0101090638	0101090630	01/01/02	50-339 B
0101080361	0101080355	00/11/13	50-335 B	0101090651	0101090643	01/01/02	50-272 B
0101080362	0101080314	00/12/22	50-466 U	0101090652	0101090641	01/01/05	50-280 B
0101080368	0101080356	00/12/29	50-293 S	0101090661	0101090641	01/01/05	50-280 B
0101080375	0101080355	00/11/13	50-305 B	0101090666	0101090657	01/01/02	50-287 B
0101080375	0101080355	00/11/13	50-305 B	0101090676	0101090667	01/01/05	50-325 B
0101080376	0101080370	00/12/09	71-401	0101090677	0101090677	00/12/31	50-259 B
0101080392	0101080314	00/12/22	COMMISSION	0101090692	0101090685	01/01/06	50-316 B
0101080397	0101080384	01/01/02	50-316 B	0101090694	0101090685	01/01/06	50-333 P
0101080403	0101080391	00/12/31	50-271 P	0101090705	0101090695	00/12/16	CONTRACT
0101080406	0101080384	01/01/02	50-316 B	0101090707	0101090698	01/01/02	50-272 B
0101080416	0101080407	00/12/30	50-286 P	0101090721	0101090712	00/12/05	50-438 B
0101080420	0101080399	00/12/13	Q&A	0101090727	0101090712	00/12/05	50-438 B
0101080426	0101080407	00/12/30	50-205 P	0101090729	0101090722	00/12/08	WASTE MOT
0101080443	0101080450	00/12/31	50-271 P	0101090735	0101090712	00/12/05	50-438 B
0101090005	0101090001	01/01/02	50-10 P	0101090746	0101090739	00/07/29	50-302 P
0101090009	0101090026	00/12/31	50-271 P	0101090753	0101090745	00/12/11	50-344 P
0101090021	0101090020	00/12/31	50-297 B	0101090756	0101090739	00/07/29	50-302 P
0101090022	0101090019	01/01/06	50-289 U	0101090760	0101090745	00/12/11	50-344 P
0101090029	0101090027	01/01/05	50-346 P	0101090766	0101090739	00/07/29	50-302 P
0101090030	0101090028	01/01/06	50-364 A	0101090789	0101090778	00/12/05	50-10 B
0101090032	0101090028	01/01/05	50-364 A	0101090796	0101090779	00/12/03	70-821
0101090039	0101090047	01/01/05	TOPREP	0101090802	0101090790	00/11/18	50-332 B
0101090046	0101090044	00/12/19	50-254 S	0101090810	0101090800	00/12/01	50-254 B

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8101090821	8101090814	80/11/25	70-142
8101090834	8101090825	80/12/11	50-327 G
8101090838	8101090827	80/12/23	71-9044
8101090841	8101090825	80/12/11	50-327 G
8101090845	8101090825	80/12/11	50-327 G
8101090849	8101090825	80/12/11	50-327 G
8101090852	8101090847	80/11/07	50-272 G
8101090857	8101090853	80/11/10	50-387 G
8101090858	8101090847	80/11/07	50-272 G
8101090862	8101090853	80/11/10	50-387 G
8101090863	8101090847	80/11/07	50-272 G
8101090865	8101090853	80/11/10	50-387 G
8101090869	8101090853	80/11/10	50-387 G
8101090883	8101090878	80/10/30	50-333 G
8101090888	8101090847	80/11/07	50-272 G
8101090890	8101090893	80/12/18	CONTRACT
8101090917	8101090907	80/12/19	71-4786
8101090937	8101090932	80/12/16	50-155 G
8101090938	8101090935	80/12/11	50-344 P
8101090939	8101090935	80/12/11	50-344 P
8101090940	8101090932	80/12/18	50-155 G
8101090942	8101090932	80/12/18	50-155 G
8101090943	8101090941	80/12/12	50-317 P
8101090945	8101090941	80/12/12	50-317 P
8101090947	8101090941	80/12/12	50-317 P
8101090953	8101090950	80/12/19	50-313 P
8101090956	8101090950	80/12/19	50-313 P
8101090959	8101090950	80/12/19	50-313 P
8101091000	8101090958	80/12/17	CONTRACT
8101100008	8101100005	80/12/19	50-313 G
8101100010	8101100007	80/12/10	COMMUNICATION
8101100013	8101100011	80/11/21	50-329 G
8101100031	8101100029	80/11/14	50-298 G
8101100038	8101100033	80/11/20	50-423 S
8101100051	8101100049	80/12/12	50-367 G
8101100056	8101100049	80/12/12	50-367 G
8101100063	8101100059	80/11/19	50-445 G
8101100074	8101100067	80/12/18	50-267 G
8101100076	8101100071	80/11/13	50-387 G
8101100082	8101100079	80/12/03	50-320 G
8101100083	8101100078	80/12/04	50-312 G
8101100084	8101100078	80/12/04	50-312 G
8101100090	8101100078	80/12/04	50-312 G
8101100094	8101100078	80/12/04	50-312 G
8101100097	8101100078	80/12/04	50-312 G
8101100103	8101100078	80/12/04	50-312 G
8101100134	8101100129	80/11/20	40-8584
8101100139	8101100133	80/09/23	50-170 U
8101100153	8101100115	80/11/24	50-254 G
8101100163	8101100155	80/12/09	50-284 H
8101100176	8101100166	80/12/03	50-458 G
8101100178	8101100171	80/11/19	50-445 G
8101100181	8101100174	80/12/10	50-266 G
8101100189	8101100182	80/11/12	50-461 G
8101100193	8101100188	80/12/11	50-305 G
8101100194	8101100182	80/10/16	50-271 G
8101100198	8101100161	80/12/12	FOIA
8101100203	8101100161	80/12/12	FOIA
8101100207	8101100200	80/12/10	COMMUNICATION
8101100209	8101100202	80/10/29	50-305 G
8101100210	8101100161	80/12/12	FOIA
8101100211	8101100204	80/11/13	50-277 G
8101100212	8101100200	80/12/10	COMMUNICATION
8101100218	8101100204	80/11/13	50-277 G
8101100219	8101100200	80/12/10	COMMUNICATION
8101100222	8101100161	80/12/12	FOIA
8101100221	8101100204	80/11/13	50-277 G
8101100225	8101100217	80/11/19	50-313 G
8101100226	8101100200	80/12/10	COMMUNICATION
8101100230	8101100161	80/12/12	FOIA
8101100232	8101100204	80/11/13	50-277 G
8101100233	8101100200	80/12/10	COMMUNICATION
8101100236	8101100217	80/11/19	50-313 G
8101100238	8101100200	80/12/10	COMMUNICATION
8101100239	8101100161	80/12/12	FOIA
8101100244	8101100204	80/11/13	50-277 G
8101100245	8101100200	80/12/10	COMMUNICATION
8101100251	8101100247	80/10/16	50-445 G
8101100259	8101100253	80/12/18	50-184 P

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8101100261	8101100161	80/12/12	FOIA
8101100269	8101100260	80/11/19	50-490 G
8101100271	8101100254	80/11/20	50-3 P
8101100272	8101100161	80/12/12	FOIA
8101100281	8101100161	80/12/12	FOIA
8101100287	8101100279	80/12/22	50-438 G
8101100288	8101100161	80/12/12	FOIA
8101100296	8101100161	80/12/12	70-2179
8101100301	8101100294	80/12/27	50-456 G
8101100306	8101100161	80/12/12	FOIA
8101100307	8101100302	80/11/28	CONTRACT
8101100310	8101100161	80/12/12	FOIA
8101100314	8101100161	80/12/12	FOIA
8101100316	8101100314	80/12/18	CONTRACT
8101100319	8101100300	80/12/22	50-348 G
8101100322	8101100161	80/12/12	FOIA
8101100325	8101100321	80/12/15	CONTRACT
8101100327	8101100161	80/12/12	FOIA
8101100331	8101100308	80/12/22	50-348 G
8101100335	8101100161	80/12/12	FOIA
8101100337	8101100309	80/12/22	50-348 G
8101100347	8101100308	80/12/22	50-348 G
8101100349	8101100161	80/12/12	FOIA
8101100353	8101100348	80/10/09	50-263 G
8101100354	8101100161	80/12/12	70-2479
8101100356	8101100351	80/11/28	50-327 G
8101100361	8101100340	80/10/09	50-363 G
8101100362	8101100161	80/12/12	FOIA
8101100364	8101100351	80/11/28	50-327 G
8101100368	8101100161	80/12/12	FOIA
8101100375	8101100161	80/12/12	FOIA
8101100370	8101100369	80/11/26	50-346 G
8101100371	8101100370	80/12/24	50-353 G
8101100385	8101100161	80/12/12	FOIA
8101100393	8101100161	80/12/12	70-1739
8101100394	8101100370	80/12/24	50-353 G
8101100399	8101100372	80/12/15	CONTRACT
8101100400	8101100370	80/12/24	50-353 G
8101100401	8101100161	80/12/12	50-244 P
8101100410	8101100370	80/12/24	50-353 G
8101100415	8101100161	80/12/12	FOIA
8101100428	8101100419	80/12/19	50-220 G
8101100440	8101100440	80/12/24	50-269 P
8101100449	8101100441	80/12/24	50-312 G
8101100462	8101100440	80/12/24	50-269 P
8101100471	8101100440	80/12/24	50-269 P
8101100479	8101100440	80/12/24	50-269 P
8101100503	8101100493	80/12/03	50-271 G
8101100508	8101100477	80/12/24	50-287 F
8101100519	8101100504	80/09/19	50-250 P
8101100524	8101100512	80/11/25	50-278 G
8101100527	8101100518	80/12/17	50-265 P
8101100534	8101100518	80/12/17	50-266 P
8101100542	8101100518	80/11/20	50-322 G
8101100543	8101100518	80/12/17	50-266 P
8101100549	8101100532	80/09/19	50-315 P
8101100557	8101100551	80/12/09	50-272 P
8101100567	8101100551	80/12/09	50-272 P
8101100572	8101100551	80/12/09	50-272 P
8101100574	8101100563	80/09/19	50-283 P
8101100595	8101100587	80/09/19	50-348 P
8101100614	8101100606	80/12/22	50-327 P
8101100620	8101100606	80/12/22	50-327 P
8101100622	8101100617	80/09/19	50-334 P
8101100626	8101100606	80/12/22	50-327 P
8101100636	8101100629	80/09/19	50-247 P
8101100654	8101100646	80/09/19	50-261 P
8101100656	8101100640	80/09/19	50-286 P
8101100672	8101100664	80/11/26	50-518 G
8101100680	8101100674	80/09/19	50-293 P
8101100689	8101100682	80/11/23	50-321 G
8101100693	8101100690	80/09/19	50-272 P
8101100702	8101100693	80/12/24	50-333 G
8101100706	8101100700	80/09/19	50-305 P
8101100707	8101100693	80/12/24	50-335 G
8101100709	8101100704	80/12/22	70-364 G
8101100711	8101100695	80/12/24	50-335 G
8101100717	8101100712	80/12/18	50-271 P
8101100726	8101100716	80/12/23	50-445 G
8101100727	8101100712	80/12/18	50-271 P

FILE NUMBER	FILE NAME	FILE DATE	FILE TIME	FILE TYPE	FILE STATUS	FILE CATEGORY
8101130528	8101130493	81/01/04	50-739	S		
8101130536	8101130458	81/01/14	50-295	S		
8101130539	8101130534	81/01/06	50-339	S		
8101130540	8101130535	81/01/09	50-724	S		
8101130542	8101130494	81/01/06	50-339	S		
8101130546	8101130543	81/01/10	50-313	S		
8101130551	8101130541	81/01/07	50-295	S		
8101130554	8101130548	81/01/07	50-324	S		
8101130555	8101130547	80/12/31	CONTRACT			
8101130558	8101130552	81/01/07	50-333	R		
8101130559	8101130550	81/01/07	50-304	S		
8101130560	8101130561	81/01/07	50-324	S		
8101130571	8101130562	81/01/08	50-304	S		
8101130572	8101130564	81/01/02	50-344	R		
8101130581	8101130575	81/01/09	50-263	R		
8101130583	8101130574	80/11/12	50-373	O		
8101130585	8101130578	81/01/07	50-133	R		
8101130586	8101130582	81/01/09	50-259	R		
8101130591	8101130584	81/01/09	50-305	R		
8101130592	8101130574	80/11/12	50-373	O		
8101130593	8101130587	81/01/09	50-295	R		
8101130601	8101130595	81/01/09	50-299	R		
8101130605	8101130598	80/12/29	50-265	B		
8101130607	8101130597	81/01/07	50-317	S		
8101130608	8101130602	81/01/06	50-340	B		
8101130612	8101130600	81/01/09	50-327	S		
8101130613	8101130604	81/01/03	50-367	U		
8101130615	8101130610	81/01/09	50-318	S		
8101130622	8101130620	80/12/31	COMMISSION			
8101130623	8101130617	81/01/09	50-317	B		
8101130632	8101130620	80/12/31	COMMISSION			
8101130634	8101130620	80/12/31	COMMISSION			
8101130637	8101130620	80/12/31	COMMISSION			
8101130640	8101130620	80/12/31	COMMISSION			
8101130643	8101130620	80/12/31	COMMISSION			
8101130646	8101130620	80/12/31	COMMISSION			
8101130689	8101130605	79/09/19	NURE			
8101130727	8101130725	80/12/04	COMMISSION			
8101140017	8101140011	81/01/09	50-387	O		
8101140028	8101140011	81/01/09	50-387	O		
8101140037	8101140031	80/12/29	50-483	H		
8101140046	8101140038	80/12/29	50-361	Q		
8101140053	8101140038	80/12/29	50-361	Q		
8101140077	8101140071	80/11/28	50-295	Q		
8101140113	8101140108	80/12/02	50-250	Q		
8101140120	8101140111	80/12/15	10CFR			
8101140128	8101140118	80/11/20	50-272	Q		
8101140129	8101140111	80/12/15	10CFR			
8101140151	8101140135	80/12/02	50-461	Q		
8101140163	8101140154	80/12/09	71-398			
8101140173	8101140166	80/12/17	50-220	P		
8101140214	8101140208	80/12/24	50-443	H		
8101140237	8101140230	81/01/12	50-367	Q		
8101140246	8101140239	80/12/22	50-320	H		
8101140249	8101140245	81/01/12	50-289	Q		
8101140252	8101140245	81/01/12	50-289	F		

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B101150338	B101150522	81/01/09	50-324 S	B101160259	B101160255	80/12/30	50-329 Q
B101150540	B101150536	80/12/16	50-245 S	B101160268	B101160264	80/12/05	50-324 S
B101150542	B101150535	80/12/16	50-245 S	B101160337	B101160331	80/12/01	50-320 F
B101150543	B101150534	81/01/13	50-318 S	B101160361	B101160342	81/01/12	TOPREP
B101150544	B101150534	80/12/16	50-245 S	B101160374	B101160368	80/12/10	50-151 Q
B101150546	B101150536	80/12/16	50-245 S	B101160382	B101160360	80/12/10	50-151 Q
B101150551	B101150549	80/12/10	50-317 Q	B101160391	B101160378	80/12/02	50-148 P
B101150553	B101150549	80/12/10	50-317 Q	B101160392	B101160386	80/12/22	50-282 Q
B101150555	B101150549	80/12/10	50-317 Q	B101160398	B101160378	80/12/02	50-148 P
B101150558	B101150549	80/12/10	50-317 Q	B101160404	B101160378	80/12/02	50-140 P
B101150555	B101150562	80/12/15	50-317 Q	B101160400	B101160378	80/12/02	50-140 P
B101150560	B101150562	80/12/15	50-317 Q	B101160411	B101160378	80/12/02	50-148 P
B101150570	B101150562	80/12/15	50-317 Q	B101160412	B101160410	80/12/16	70-820
B101150572	B101150562	80/12/15	50-317 Q	B101160413	B101160410	80/12/16	70-820
B101150578	B101150575	80/12/17	50-247 Q	B101160414	B101160410	80/12/16	70-820
B101150580	B101150575	80/12/17	50-247 Q	B101160416	B101160415	80/11/28	50-206 P
B101150591	B101150575	80/12/17	50-247 Q	B101160421	B101160417	80/12/29	50-339 P
B101150593	B101150579	80/12/23	50-247 Q	B101160423	B101160417	80/12/29	50-339 P
B101150595	B101150575	80/12/17	50-247 Q	B101160424	B101160417	80/12/29	50-339 P
B101150595	B101150590	81/01/06	50-389 Q	B101160467	B101160464	01/01/06	50-334 R
B101150597	B101150597	80/11/25	50-155 Q	B101160468	B101160464	81/01/06	50-334 R
B101150606	B101150602	81/01/07	50-461 Q	B101160469	B101160466	81/01/08	50-219 P
B101150634	B101150628	80/12/07	50-295 P	B101160470	B101160464	81/01/06	50-334 R
B101150635	B101150631	81/01/14	50-265 P	B101160471	B101160466	81/01/08	50-219 P
B101150638	B101150631	81/01/14	50-265 P	B101160473	B101160465	81/01/14	50-206 P
B101150640	B101150628	80/12/07	50-295 Q	B101160474	B101160472	81/01/07	50-327 R
B101150651	B101150646	80/12/07	50-266 Q	B101160476	B101160465	81/01/14	50-206 P
B101150658	B101150654	80/12/12	50-373 Q	B101160483	B101160477	81/01/07	50-327 B
B101150663	B101150654	80/12/12	50-373 Q	B101160484	B101160479	81/01/13	50-219 P
B101150684	B101150679	81/01/05	50-220 S	B101160489	B101160489	81/01/08	50-289 R
B101150685	B101150681	81/01/12	50-271 S	B101160498	B101160479	81/01/13	50-219 P
B101150695	B101150690	81/01/07	50-219 S	B101160498	B101160490	81/01/06	50-260 B
B101150769	B101150765	80/12/23	50-369 Q	B101160503	B101160493	81/01/08	50-280 F
B101150773	B101150765	80/12/23	50-369 Q	B101160507	B101160500	81/01/08	50-445 C
B101150787	B101150779	80/12/09	50-373 Q	B101160511	B101160493	81/01/08	50-280 F
B101150819	B101150810	80/12/11	50-341 Q	B101160513	B101160504	80/12/23	50-206 S
B101150840	B101150826	81/01/08	50-373 Q	B101160525	B101160520	81/01/15	50-259 S
B101150845	B101150826	81/01/08	50-373 Q	B101160564	B101160508	81/01/12	50-333 S
B101150846	B101150841	80/12/10	50-387 Q	B101160567	B101160562	80/12/18	50-280 P
B101150850	B101150841	80/12/10	50-387 Q	B101160573	B101160516	81/01/14	50-293 S
B101150851	B101150826	81/01/08	50-373 Q	B101160580	B101160575	80/12/12	50-213 S
B101150854	B101150841	80/12/10	50-387 Q	B101160581	B101160575	80/12/12	50-213 S
B101150851	B101150841	80/12/10	50-387 Q	B101160582	B101160575	80/12/12	50-213 S
B101150877	B101150867	80/12/23	50-277 Q	B101160591	B101160575	80/12/12	50-213 S
B101150875	B101150893	80/12/18	50-317 P	B101160595	B101160575	80/12/12	50-213 S
B101150890	B101150867	80/12/23	50-277 Q	B101160604	B101160575	80/12/12	50-213 S
B101150897	B101150867	80/12/23	50-277 Q	B101160612	B101160605	80/12/08	71-402
B101150891	B101150867	80/12/23	50-277 Q	B101160613	B101160541	81/01/09	50-245 S
B101150993	B101150992	80/12/24	50-999 Q	B101160624	B101160549	81/01/08	50-336 S
B101150998	B101150982	80/12/24	50-999 Q	B101160627	B101160621	80/12/16	50-271 Q
B101150999	B101150982	80/12/24	50-999 Q	B101160633	B101160621	80/12/16	50-271 Q
B101150910	B101150952	80/12/24	50-999 Q	B101160634	B101160556	81/01/12	50-302 B
B101150935	B101150931	81/01/13	40-8084	B101160640	B101160621	80/12/16	50-271 Q
B101160039	B101160024	80/12/31	50-361 A	B101160646	B101160621	80/12/16	50-271 Q
B101160034	B101160028	81/01/08	50-263 F	B101160653	B101160621	80/12/16	50-271 Q
B101160057	B101160350	81/01/05	50-346 P	B101160668	B101160662	81/01/02	50-413 Q
B101160361	B101160050	81/01/05	50-346 P	B101160671	B101160662	81/01/02	50-413 Q
B101160364	B101160350	81/01/05	50-346 P	B101160679	B101160662	81/01/02	50-413 Q
B101160065	B101160054	80/12/19	50-271 Q	B101160684	B101160662	81/01/02	50-413 Q
B101160072	B101160354	80/12/19	50-271 Q	B101160690	B101160562	80/12/10	50-280 P
B101160077	B101160054	80/12/19	50-271 Q	B101160696	B101160694	81/01/05	50-280 Q
B101160087	B101160054	80/12/19	50-271 Q	B101160697	B101160695	80/12/31	PR
B101160111	B101160105	81/01/08	CONTRACT	B101160699	B101160694	81/01/05	50-280 Q
B101160114	B101160101	80/12/17	38-309 Q	B101160700	B101160694	81/01/05	50-280 Q
B101160123	B101160101	80/12/17	50-309 Q	B101160706	B101160694	81/01/05	50-280 Q
B101160125	B101160116	80/11/26	70-33	B101160728	B101160724	80/12/31	50-369 S
B101160132	B101160101	80/12/17	50-309 Q	B101160734	B101160724	80/12/31	50-369 Q
B101160135	B101160124	80/12/33	COMMUNICATION	B101160759	B101160754	80/12/31	50-260 Q
B101160138	B101160131	80/12/30	70-143	B101190103	B101190100	80/12/29	70-124
B101160142	B101160124	80/12/30	COMMUNICATION	B101190141	B101190113	80/12/09	50-10 P
B101160145	B101160101	80/12/17	50-309 Q	B101190161	B101190128	81/01/02	50-273 H
B101160147	B101160124	80/12/30	COMMUNICATION	B101190167	B101190154	81/01/09	FOIA
B101160148	B101160131	80/12/20	70-143	B101190176	B101190154	81/01/09	FOIA
B101160157	B101160124	80/12/30	COMMUNICATION	B101190182	B101190175	81/01/06	COMMUNICATION
B101160156	B101160152	80/11/13	50-304 Q	B101190197	B101190190	80/12/30	50-247 H
B101160159	B101160124	80/12/30	COMMUNICATION	B101190202	B101190190	80/12/30	50-247 H
B101160164	B101160124	80/12/30	COMMUNICATION	B101190214	B101190190	80/12/30	50-247 H
B101160172	B101160124	80/12/30	COMMUNICATION	B101190277	B101190272	80/12/18	50-412 S
B101160175	B101160167	81/01/14	50-289 Q	B101190325	B101190320	81/01/08	50-317 P
B101160240	B101160231	80/12/08	50-493 Q				

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B101190329	B101190319	80/12/30	50-322	B101200473	B101200465	80/12/02	CONTRACT
B101190372	B01220437	80/11/28	50-19	B101200475	B101200459	81/01/14	50-331 F
B101190390	B101190387	81/01/07	50-387	B101200480	B101200471	81/01/02	CONTRACT
B101190397	B101140679	80/12/18	50-290	B101200498	B101200489	80/12/22	CONTRACT
B101190408	B101140679	80/12/18	50-290	B101200508	B101220502	80/12/09	50-382 Q
B101190419	B101190414	81/01/13	50-324	B101200508	B101200502	80/12/09	50-382 Q
B101190429	B101190426	80/12/02	50-261	B101200563	B101200557	80/12/29	50-316 A
B101190445	B101190443	81/01/07	50-344	B101200567	B101200557	80/12/29	50-316 A
B101190451	B101190448	81/01/13	50-368	B101200570	B101200566	81/01/07	50-327 Q
B101190456	B101190454	81/01/12	50-302	B101200595	B101200586	81/01/07	50-329 Q
B101190465	B101190462	81/01/12	50-293	B101200628	B101200624	81/01/08	50-324 S
B101190470	B101190467	81/01/07	50-334	B101200629	B101200626	81/01/08	50-325 S
B101190477	B101190474	81/01/12	50-334	B101200636	B101200636	80/12/22	50-272 P
B101190486	B101190482	81/01/13	50-320	B101200640	B101200639	80/12/16	0A999
B101190488	B101190483	81/01/07	50-280	B101200644	B101200642	81/01/05	50-272 F
B101190495	B101190490	81/01/13	50-260	B101200645	B101200642	81/01/05	50-272 F
B101190500	B101190496	81/01/12	50-296	B101210027	B101210022	81/01/12	CONTRACT
B101190507	B101190502	81/01/14	50-317	B101210058	B101210045	80/12/08	50-488 Q
B101190509	B101190503	81/01/15	50-346	B101210075	B101210045	80/12/08	50-458 Q
B101190514	B101190505	80/12/22	50-322	B101210077	B101210072	80/12/23	50-445 Q
B101190515	B101190512	81/01/12	50-315	B101210089	B101210082	80/12/12	50-461 Q
B101190518	B101190512	81/01/12	50-315	B101210092	B101210085	81/01/08	50-335 F
B101190584	B101190579	81/01/08	50-328	B101210098	B101210085	81/01/08	50-235 F
B101190603	B101190593	81/01/08	50-259	B101210104	B101210097	80/12/15	50-446 Q
B101190612	B101190586	81/01/08	50-296	B101210119	B101210110	80/12/24	50-397 Q
B101190617	B101190608	80/12/30	50-338	B101210137	B101210131	81/01/13	50-261 F
B101190621	B101190608	80/12/30	50-338	B101210138	B101210133	80/12/23	50-69 Q
B101190626	B101190623	80/12/30	50-335	B101210144	B101210131	81/01/13	50-261 F
B101190652	B101190649	80/10/27	71-6273	B101210153	B101210145	80/12/24	50-275 Q
B101190657	B101190649	80/10/27	71-6273	B101210181	B101210173	80/12/15	50-245 P
B101190741	B101190738	81/01/09	50-582	B101210223	B101210218	80/12/17	50-219 P
B101190782	B101190780	80/11/06	0A999	B101210225	B101210221	81/01/16	50-269 F
B101190783	B101190779	80/12/24	50-387	B101210233	B101210229	80/12/17	50-135 P
B101190788	B101190786	80/12/10	50-287	B101210267	B101210259	80/11/05	0A999
B101190791	B101190786	80/12/10	50-289	B101210358	B101210354	81/01/19	50-395 H
B101190797	B101190286	81/01/02	50-275	B101210376	B101210364	81/01/14	50-271 P
B101200062	B101200059	81/01/14	50-322	B101210370	B101210369	81/01/09	40-8778
B101200112	B101200106	80/11/14	0A999	B101210373	B101210371	81/01/09	TOPREP
B101200117	B101200106	80/11/14	0A999	B101210375	B101210372	81/01/16	TOPREP
B101200118	B101200106	80/11/14	0A999	B101210377	B101210372	81/01/16	TOPREP
B101200121	B101200106	80/11/14	0A999	B101210376	B101210374	80/12/28	CONTRACT
B101200122	B101200140	81/01/06	40-8724	B101210391	B101210381	80/12/31	CONTRACT
B101200126	B101200209	81/01/02	50-275	B101210461	B101210372	81/01/16	TOPREP
B101200171	B101200129	80/11/26	0A999	B101210465	B101210405	81/01/09	50-324 R
B101200137	B101200134	80/12/04	70-1151	B101210410	B101210406	81/01/14	50-267 S
B101200144	B101200134	80/12/04	70-1151	B101210416	B101210414	81/01/10	50-250 R
B101200191	B101200187	80/12/22	50-454	B101210422	B101210415	81/01/14	50-155 R
B101200195	B101200187	80/12/22	50-454	B101210425	B101210425	81/01/10	50-250 R
B101200206	B101200200	80/12/17	50-29	B101210430	B101210426	81/01/15	50-348 S
B101200233	B101200227	81/01/13	50-327	B101210440	B101210434	81/01/15	50-247 S
B101200235	B101200229	81/01/16	50-280	B101210446	B101210439	81/01/15	50-338 S
B101200237	B101200227	81/01/13	50-327	B101210451	B101210443	81/01/13	50-316 S
B101200277	B101200274	81/01/13	50-245	B101210454	B101210449	81/01/14	50-327 S
B101200284	B101200280	81/01/14	50-331	B101210458	B101210455	81/01/12	50-311 R
B101200285	B101200278	81/01/15	50-338	B101210464	B101210462	81/01/15	50-269 H
B101200289	B101200281	81/01/13	50-312	B101210465	B101210463	81/01/02	50-294 R
B101200289	B101200278	81/01/15	50-338	B101210471	B101210469	81/01/15	50-289 R
B101200290	B101200287	81/01/12	50-286	B101210473	B101210470	81/01/06	50-293 R
B101200291	B101200286	80/09/19	50-204	B101210476	B101210474	81/01/14	50-244 R
B101200294	B101200292	81/01/15	50-302	B101210482	B101210475	81/01/12	50-272 R
B101200297	B101200295	81/01/14	50-282	B101210485	B101210481	81/01/14	50-354 R
B101200303	B101200301	81/01/08	50-289	B101210488	B101210480	81/01/14	50-267 S
B101200335	B101200333	81/01/15	50-281	B101210489	B101210484	81/01/07	50-296 R
B101200337	B101200333	81/01/15	50-281	B101210494	B101210490	81/01/15	50-313 R
B101200343	B101200339	81/01/15	50-280	B101210496	B101210492	81/01/15	50-333 Q
B101200348	B101200339	81/01/15	50-280	B101210505	B101210500	81/01/14	50-271 R
B101200355	B101200351	81/01/14	50-339	B101210505	B101210499	81/01/15	50-333 S
B101200359	B101200357	81/01/14	50-272	B101210507	B101210502	81/01/15	50-269 S
B101200364	B101200362	81/01/14	50-338	B101210514	B101210509	81/01/15	50-268 R
B101200371	B101200367	81/01/15	50-315	B101210516	B101210511	81/01/14	50-287 S
B101200383	B101200375	81/01/14	50-339	B101210521	B101210518	81/01/13	50-348 R
B101200371	B101200386	81/01/14	50-272	B101210528	B101210523	81/01/09	50-277 R
B101200406	B101200399	81/01/15	50-268	B101210529	B101210523	81/01/12	TOPREP
B101200416	B101200411	81/01/14	50-368	B101210531	B101210523	81/01/12	TOPREP
B101200423	B101200420	80/12/10	TOPREP	B101210533	B101210526	80/12/12	50-329 Q
B101200432	B101200426	81/01/08	CONTRACT	B101210539	B101210532	80/12/23	50-324 P
B101200435	B101200396	81/01/02	EXPORT LIC	B101210545	B101210532	80/12/23	50-324 P
B101200437	B101200431	81/01/14	50-338	B101210550	B101210543	80/12/29	50-324 P
B101200452	B101200444	81/01/14	50-339	B101210557	B101210554	81/01/15	50-324 P
B101200466	B101200450	81/01/14	50-331	B101210563	B101210554	81/01/15	50-324 P

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
0101210565	0101210543	00/12/29	50-324 F	0101220396	0101220393	01/01/15	50-325 S
0101210569	0101210554	01/01/15	FBI A	0101220401	0101220397	01/01/14	50-331 S
0101210571	0101210543	00/12/29	50-324 P	0101220402	0101220399	01/01/14	50-325 S
0101210574	0101210554	01/01/15	FBI A	0101220409	0101220405	01/01/15	50-324 S
0101210578	0101210572	00/12/24	CLTRACT	0101220410	0101220408	01/01/12	50-213 R
0101210601	0101210596	00/12/17	50-312 S	0101220415	0101220403	01/01/16	50-266 O
0101210608	0101210604	00/11/28	50-206 S	0101220417	0101220414	01/01/09	50-368 P
0101210617	0101210612	00/12/09	50-275 O	0101220421	0101220413	01/01/16	50-267 S
0101210624	0101210620	00/11/28	50-344 S	0101220427	0101220419	00/12/04	50-340 O
0101210629	0101210626	00/12/12	50-261 O	0101220429	0101220424	01/01/16	50-346 S
0101210630	0101210621	01/01/14	50-361 A	0101220430	0101220433	00/12/11	50-220 O
0101210637	0101210634	01/01/07	CRG	0101220440	0101220435	01/01/16	50-346 S
0101210639	0101210635	01/01/07	50-358 O	0101220442	0101220433	00/12/11	50-220 O
0101210641	0101210640	00/12/16	50-409 S	0101220445	0101220433	00/12/11	50-220 O
0101210643	0101210640	01/12/16	50-409 O	0101220449	0101220444	01/01/15	50-260 S
0101210646	0101210645	00/12/23	50-346 O	0101220450	0101220433	00/12/11	50-220 S
0101210648	0101210645	00/12/23	50-346 O	0101220456	0101220432	01/01/15	50-330 S
0101210651	0101210650	00/12/19	50-346 O	0101220462	0101220439	01/01/16	50-271 S
0101210654	0101210650	00/12/17	50-346 O	0101220492	0101220485	00/12/31	50-281 S
0101210655	0101210652	01/01/08	50-271 O	0101220496	0101220488	01/01/12	50-277 S
0101210659	0101210652	01/01/08	50-271 O	0101220505	0101220499	01/01/14	50-327 S
0101210659	0101210656	00/12/09	50-341 O	0101220510	0101220506	00/12/12	50-483 O
0101210660	0101210652	01/01/08	50-271 O	0101220516	0101220506	00/12/12	50-483 O
0101210661	0101210652	01/01/08	50-271 O	0101220518	0101220511	01/01/14	50-327 S
0101210662	0101210656	00/12/09	50-341 O	0101220525	0101220520	01/01/12	50-508 O
0101210663	0101210652	01/01/08	50-271 O	0101220531	0101220520	01/01/12	50-508 O
0101210665	0101210652	01/01/08	50-271 O	0101220532	0101220523	01/01/15	50-327 S
0101210668	0101210652	01/01/08	50-271 O	0101220534	0101220528	01/01/20	TOPREP
0101210669	0101210652	01/01/08	50-271 O	0101220535	0101220520	01/01/12	50-508 O
0101210671	0101210652	01/01/08	50-271 O	0101220543	0101220520	01/01/12	50-508 O
0101220021	0101220018	01/01/08	50-312 F	0101220546	0101220540	00/11/21	50-277 S
0101220044	0101220043	01/01/16	50-438 A	0101220553	0101220548	01/01/02	50-267 V
0101220058	0101220055	01/01/07	50-566 O	0101220569	0101220563	01/01/16	50-321 S
0101220060	0101220055	01/01/07	50-566 O	0101220577	0101220574	00/12/12	70-371
0101220062	0101220055	01/01/07	50-566 O	0101220581	0101220574	00/12/12	70-371
0101220066	0101220055	01/01/07	50-566 O	0101220582	0101220575	01/01/15	50-346 P
0101220069	0101220051	01/01/02	50-395 O	0101220584	0101220574	00/12/12	70-371
0101220102	0101220100	00/12/16	50-315 O	0101220588	0101220574	00/12/12	70-371
0101220114	0101220110	01/01/09	50-305 O	0101220593	0101220587	00/12/12	XPORTRIC
0101220121	0101220116	01/01/09	50-440 O	0101220616	0101220466	00/11/26	50-3
0101220122	0101220109	01/01/08	50-329 A	0101220629	0101220574	00/12/12	70-371
0101220135	0101220126	00/12/17	50-277 O	0101220632	0101220574	00/12/12	70-371
0101220138	0101220133	01/01/05	50-369 A	0101220634	0101220574	00/12/12	70-371
0101220140	0101220130	01/01/13	50-247 O	0101220638	0101220574	00/12/12	70-371
0101220141	0101220126	00/12/17	50-277 S	0101220638	0101220632	01/01/13	70-1308
0101220147	0101220130	01/01/13	50-247 O	0101220643	0101220632	01/01/13	70-1308
0101220149	0101220126	00/12/17	50-277 O	0101220654	0101220638	01/01/07	70-1308
0101220153	0101220126	00/12/17	50-277 O	0101220659	0101220638	01/01/07	70-1308
0101220161	0101220126	00/12/17	50-277 O	0101220664	0101220658	01/01/08	50-261 F
0101220164	0101220153	01/01/15	50-327 R	0101220670	0101220658	01/01/14	50-338 O
0101220169	0101220126	00/12/17	50-277 O	0101220677	0101220658	01/01/15	50-361 O
0101220186	0101220182	01/01/09	50-255 O	0101220678	0101220658	01/01/14	50-461 O
0101220197	0101220192	01/01/06	70-1257	0101220682	0101220658	01/01/20	TOPREP
0101220200	0101220190	01/01/09	50-255 S	0101220683	0101220658	01/01/20	TOPREP
0101220211	0101220207	01/01/14	50-553 A	0101220686	0101220658	00/12/18	71-409
0101220265	0101220262	01/01/15	50-393 A	0101220305	0101220298	00/12/30	50-311 P
0101220274	0101220270	01/01/13	50-344 P	0101220312	0101220298	00/12/30	50-311 P
0101220279	0101220270	01/01/13	50-344 P	0101220320	0101220298	00/12/30	50-311 P
0101220333	0101220328	01/01/19	50-338 P	0101220323	0101220319	01/01/14	70-682
0101220343	0101220335	01/01/14	50-331 S	0101220328	0101220319	01/01/14	70-682
0101220346	0101220340	01/01/16	50-339 P	0101220330	0101220326	01/01/15	50-277 F
0101220349	0101220344	01/01/16	50-364 P	0101220338	0101220326	01/01/15	50-277 F
0101220357	0101220354	01/01/19	50-280 P	0101220410	0101220406	01/01/15	50-395 A
0101220363	0101220359	01/01/09	50-340 P	0101220413	0101220411	01/01/15	50-336 R
0101220365	0101220359	01/01/09	50-348 P	0101220430	0101220428	01/01/14	50-250 P
0101220370	0101220369	01/01/16	50-339 P	0101220451	0101220446	00/12/29	50-237 P
0101220373	0101220372	01/01/15	50-438 A	0101220453	0101220446	00/12/29	50-237 P
0101220374	0101220368	01/01/19	50-10 P	0101220455	0101220447	01/01/19	50-302 S
0101220375	0101220372	01/01/15	50-438 A	0101220458	0101220446	00/12/29	50-237 P
0101220375	0101220372	01/01/15	50-438 A	0101220461	0101220457	01/01/20	50-318 S
0101220375	0101220372	01/01/15	50-438 A	0101220463	0101220454	01/01/13	50-321 S
0101220377	0101220372	01/01/15	50-438 A	0101220469	0101220466	01/01/13	50-366 S
0101220379	0101220368	01/01/19	50-10 P	0101220471	0101220465	01/01/15	50-334 S
0101220380	0101220378	01/01/16	50-269 S	0101220473	0101220465	01/01/15	50-334 S
0101220384	0101220382	01/01/14	50-334 S	0101220478	0101220475	01/01/19	50-334 S
0101220385	0101220381	01/01/14	50-331 S	0101220480	0101220477	01/01/13	50-206 P
0101220387	0101220382	01/01/14	50-334 S	0101220483	0101220479	01/01/20	50-255 S
0101220390	0101220388	01/01/08	50-318 S	0101220491	0101220489	01/01/19	50-269 S
0101220391	0101220388	01/01/19	50-10 P	0101220494	0101220490	01/01/20	50-263 O
0101220392	0101220382	01/01/14	50-334 S	0101220496	0101220493	01/01/12	50-369 A

ISSUED	CATEGORY	ENCLUSURE	OFFICER	ISSUED	CATEGORY		
8101230503	8101230501	80/12/31	50-237 P	8101260624	8101260611	81/01/15	50-259 F
8101230504	8101230501	80/12/31	50-237 P	8101260626	8101260643	81/01/15	50-321 S
8101230505	8101230501	80/12/31	50-237 P	8101260631	8101260548	81/01/20	50-334 S
8101230507	8101230504	81/01/08	0A999	8101260637	8101260631	81/01/16	50-324 F
8101230508	8101230506	81/01/08	0A999	8101260642	8101260552	81/01/15	50-272 S
8101230509	8101230506	81/01/08	0A999	8101260644	8101260631	81/01/16	50-324 F
8101230510	8101230506	01/01/08	0A999	8101260649	8101260616	81/01/20	TOPREP
8101230524	8101230522	80/12/18	50-250 P	8101260650	8101260657	81/01/15	50-272 S
8101230526	8101230523	81/01/20	50-317 S	8101260652	8101260616	81/01/20	TOPREP
8101230531	8101230530	81/01/16	50-255 S	8101260657	8101260516	81/01/20	TOPREP
8101230535	8101230533	81/01/20	50-155 S	8101260658	8101260570	81/01/11	50-249 S
8101230539	8101230536	81/01/13	50-313 P	8101260664	8101260581	81/01/16	50-219 S
8101230540	8101230538	80/01/19	50-317 S	8101260671	8101260586	81/01/14	50-237 S
8101230541	8101230537	81/01/21	50-317 S	8101260673	8101260673	81/01/16	50-313 F
8101230548	8101230546	81/01/14	50-219 R	8101260679	8101260673	81/01/16	50-313 F
8101230556	8101230551	81/01/15	50-219 S	8101260688	8101260592	81/01/15	50-321 S
8101230564	8101230560	01/01/16	50-219 S	8101260689	8101260675	01/01/12	50-295 S
8101230566	8101230558	80/12/21	50-250 P	8101260693	8101260611	01/01/15	50-259 F
8101230574	8101230569	81/01/16	50-219 S	8101260705	8101260611	81/01/15	50-259 F
8101230601	8101230593	01/01/15	50-339 S	8101260707	8101260693	81/01/12	50-454 Q
8101230602	8101230598	81/01/16	50-312 S	8101260718	8101260714	81/01/16	50-321 F
8101230611	8101230609	81/01/16	50-280 S	8101260724	8101260714	81/01/16	50-321 F
8101230672	8101230667	80/12/11	50-409 Q	8101260729	8101260720	80/12/10	50-346 O
8101230687	8101230678	80/12/12	50-374 Q	8101260738	8101260732	81/01/16	50-235 F
8101260034	8101260025	80/12/31	F01A	8101260743	8101260722	81/01/16	50-255 F
8101260043	8101260025	80/12/31	50-209 H	8101260776	8101260772	80/12/10	70-135
8101260052	8101260025	80/12/31	F01A	8101260782	8101260772	80/12/10	70-135
8101260060	8101260025	80/12/31	50-289 H	8101260787	8101260772	80/12/10	70-135
8101260064	8101260056	80/11/05	0A999	8101260841	8101260838	80/12/31	REG00
8101260065	8101260029	80/12/31	50-289 H	8101270049	8101270044	80/12/10	40-1162
8101260072	8101260025	80/12/31	50-289 H	8101270062	8101270056	81/01/07	State Prog
8101260081	8101260025	80/12/31	50-289 H	8101270070	8101270061	81/01/22	50-400 Q
8101260087	8101260025	00/12/31	F01A	8101270122	8101270118	80/12/02	27-47
8101260091	8101260025	80/12/31	50-320 H	8101270126	8101270124	80/12/18	71-404
8101260099	8101260025	80/12/31	50-320 H	8101270137	8101270133	80/12/18	71-9145
8101260105	8101260025	80/12/31	50-320 P	8101270141	8101270130	80/12/15	50-409 P
8101260113	8101260025	00/12/31	50-320 P	8101270146	8101270143	80/12/17	71-9111
8101260120	8101260025	00/12/31	F01A	8101270156	8101270150	00/12/15	50-244 P
8101260124	8101260095	01/01/06	XPBRTLIC	8101270194	8101270190	01/01/13	50-247 Q
8101260120	8101260025	80/12/31	F01A	8101270205	8101270187	80/12/31	XPBRTLIC
8101260141	8101260025	80/12/31	50-320 P	8101270217	8101270193	81/01/15	40-1341
8101260151	8101260025	80/12/31	50-320 P	8101270231	8101270193	81/01/15	40-1341
8101260161	8101260025	80/12/31	F01A	8101270233	8101270218	80/12/31	XPBRTLIC
8101260173	8101260025	80/12/31	F01A	8101270234	8101270193	81/01/15	40-1341
8101260188	8101260025	80/12/31	F01A	8101270242	8101270193	81/01/15	40-1341
8101260192	8101260182	81/01/16	50-482 Q	8101270251	8101270193	81/01/15	40-1341
8101260201	8101260025	80/12/31	F01A	8101270255	8101270193	81/01/15	40-1341
8101260208	8101260025	80/12/31	F01A	8101270306	8101270275	01/01/16	50-528 O
8101260218	8101260025	80/12/31	F01A	8101270342	8101270337	80/12/19	71-403
8101260222	8101260025	80/12/31	F01A	8101270353	8101270347	81/01/16	50-445 A
8101260224	8101260216	81/01/12	50-367 Q	8101270361	8101270350	01/01/19	50-269 T
8101260227	8101260025	80/12/31	F01A	8101270367	8101270358	81/01/19	50-289 T
8101260237	8101260025	80/12/31	F01A	8101270390	8101270385	81/01/21	50-329 K
8101260245	8101260234	81/01/08	50-320 Q	8101270436	8101270431	81/01/12	50-548 A
8101260247	8101260025	80/12/31	F01A	8101270470	8101270467	80/12/08	WASTE MOT
8101260255	8101260025	80/12/31	F01A	8101270475	8101270467	80/12/08	WASTE MOT
8101260260	8101260025	80/12/31	F01A	8101270508	8101270506	81/01/07	50-247 H
8101260267	8101260025	80/12/31	F01A	8101270519	8101270514	81/01/23	50-340 P
8101260276	8101260025	80/12/31	F01A	8101270520	8101270515	81/01/19	50-10 R
8101260282	8101260025	80/12/31	F01A	8101270526	8101270514	81/01/23	50-348 P
8101260288	8101260025	80/12/31	F01A	8101270557	8101270550	81/01/19	50-277 S
8101260298	8101260025	80/12/31	F01A	8101270564	8101270560	81/01/16	50-266 S
8101260308	8101260025	00/12/31	F01A	8101270569	8101270561	81/01/21	50-272 S
8101260314	8101260025	80/12/31	F01A	8101270574	8101270567	81/01/15	50-246 S
8101260317	8101260310	00/12/24	0A999	8101270578	8101270573	01/01/22	50-287 R
8101260319	8101260025	00/12/31	F01A	8101270579	8101270572	81/01/19	50-296 S
8101260329	8101260025	80/12/31	F01A	8101270585	8101270577	81/01/19	50-360 S
8101260334	8101260025	80/12/31	F01A	8101270588	8101270582	81/01/21	50-330 S
8101260339	8101260025	80/12/31	F01A	8101270597	8101270583	00/12/30	NUREG
8101260389	8101260384	81/01/19	50-313 P	8101270593	8101270590	81/01/21	50-334 S
8101260420	8101260416	81/01/20	50-327 P	8101270595	8101270587	81/01/21	50-325 S
8101260468	8101260463	81/01/10	50-321 H	8101270606	8101270600	81/01/23	50-324 S
8101260473	8101260470	01/01/16	50-322 A	8101270613	8101270608	81/01/19	50-249 S
8101260493	8101260487	81/01/15	50-346 P	8101270631	8101270627	01/01/20	50-325 S
8101260509	8101260507	81/01/19	50-289 P	8101270636	8101270634	01/01/21	50-346 S
8101260527	8101260525	81/01/10	50-346 R	8101270645	8101270641	80/12/19	50-298 S
8101260542	8101260539	81/01/14	50-347 R	8101270646	8101270642	81/01/20	50-353 A
8101260547	8101260344	81/01/19	50-293 S	8101270650	8101270643	01/01/22	50-287 S
8101260614	8101260601	81/01/15	50-321 S	8101270651	8101270642	81/01/20	50-358 A
8101260619	8101260611	81/01/15	50-349 F	8101270653	8101270649	80/12/16	50-278 S

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B101290115	B101290392	81/01/07	10CFR	B101300164	B101300157	80/11/17	70-1100
B101290420	B101290392	01/01/07	10CFR	B101300168	B101300161	81/01/13	50-498 Q
B101290432	B101290428	80/12/18	50-295 Q	B101300169	B101200157	80/11/17	70-1100
B101290438	B101290434	80/12/18	50-294 Q	B101300173	B101300157	80/11/17	70-1100
B101290449	B101290444	80/12/19	50-331 Q	B101300176	B101300161	81/01/13	50-498 Q
B101290482	B101290478	81/01/12	50-339 P	B101300177	B101300157	80/11/17	70-1100
B101290491	B101290486	80/12/22	50-440 Q	B101300182	B101300161	81/01/13	50-498 Q
B101290494	B101290407	80/12/16	50-498 Q	B101300187	B101300183	81/01/26	CONTRACT
B101290506	B101290499	80/12/09	50-315 S	B101300196	B101300191	80/11/14	70-135
B101290521	B101290316	81/01/23	50-315 S	B101300206	B101300198	01/01/14	50-309 H
B101290527	B101290522	81/01/19	70-754	B101300212	B101300203	01/01/06	50-289 P
B101290528	B101290323	81/01/26	50-155 S	B101300239	B101300223	80/12/19	50-250 P
B101290529	B101290522	01/01/19	70-754	B101300250	B101300223	80/12/19	50-250 P
B101290540	B101290536	81/01/29	50-313 R	B101300254	B101300233	81/01/13	50-237 P
B101290541	B101290538	81/10/29	50-70 P	B101300261	B101300223	80/12/19	50-250 P
B101290542	B101290537	80/12/04	70-734	B101300262	B101300248	80/12/12	50-244 P
B101290549	B101290544	80/12/19	50-518 Q	B101300291	B101300285	80/12/26	CONTRACT
B101290563	B101290558	80/12/16	50-358 Q	B101300294	B101300276	80/12/19	50-282 Q
B101290565	B101290561	00/12/19	50-224 Q	B101300308	B101300276	80/12/19	50-207 Q
B101290568	B101290553	81/01/19	50-213 Q	B101300316	B101300312	81/01/26	CONTRACT
B101290573	B101290567	80/12/18	50-282 Q	B101300325	B101300320	81/01/26	CONTRACT
B101290574	B101290569	80/12/16	50-142 Q	B101300328	B101300318	03/12/31	50-295 P
B101290589	B101290583	81/01/27	50-244 F	B101300337	B101300332	81/01/12	CONTRACT
B101290599	B101290594	81/01/26	50-269 F	B101300338	B101300318	80/12/31	50-295 P
B101290608	B101290594	81/01/26	50-269 F	B101300349	B101300344	01/01/26	CONTRACT
B101290618	B101290613	81/01/27	50-317 F	B101300355	B101300351	80/11/28	50-255 Q
B101290621	B101290613	01/01/27	50-317 F	B101300361	B101300351	80/11/28	50-255 Q
B101290622	B101290617	80/12/10	50-261 P	B101300365	B101300359	81/01/26	CONTRACT
B101290625	B101290617	80/12/10	50-261 P	B101300373	B101300358	01/01/13	50-220 P
B101290626	B101290623	80/11/29	70-232V	B101300377	B101300367	80/10/20	50-255 P
B101290631	B101290624	81/01/27	50-134 K	B101300381	B101300372	01/01/26	CONTRACT
B101290637	B101290624	01/01/27	50-134 K	B101300383	B101300367	80/10/20	50-255 P
B101290646	B101290643	80/12/16	50-397 Q	B101300389	B101300379	81/01/13	50-293 P
B101290652	B101290648	81/01/27	50-209 F	B101300390	B101300357	80/10/20	50-255 P
B101290654	B101290649	80/12/16	WASTE HOT	B101300395	B101300386	81/01/13	50-263 P
B101290662	B101290657	81/01/26	50-289 P	B101300406	B101300378	81/01/26	CONTRACT
B101290666	B101290657	01/01/26	50-289 P	B101300409	B101300396	81/01/13	50-298 P
B101290667	B101290659	81/01/02	50-263 H	B101300410	B101300403	81/01/23	50-206 P
B101290675	B101290669	81/01/14	50-311 T	B101300411	B101300402	01/01/13	50-271 P
B101290676	B101290671	01/01/14	50-247 P	B101300416	B101300405	81/01/15	10CFR
B101290729	B101290722	01/01/26	50-289 T	B101300421	B101300413	01/01/14	50-546 Q
B101290734	B101290722	81/01/26	50-269 T	B101300429	B101300398	81/01/28	50-424 A
B101290737	B101290722	81/01/26	50-289 T	B101300430	B101300417	81/01/13	50-331 P
B101290746	B101290742	81/01/23	50-282 S	B101300433	B101300427	80/12/22	50-272 P
B101290749	B101290742	81/01/23	50-282 S	B101300437	B101300427	80/12/22	50-272 P
B101290750	B101290754	80/11/12	70-820	B101300442	B101300437	80/12/22	50-272 P
B101290759	B101290755	81/01/26	50-289 P	B101300460	B101300444	81/01/13	50-259 P
B101290762	B101290755	81/01/26	50-289 P	B101300463	B101300454	80/12/18	50-280 P
B101290766	B101290755	81/01/26	50-289 P	B101300467	B101300444	81/01/13	50-259 P
B101290770	B101290768	01/01/14	50-341 G	B101300473	B101300454	80/12/18	50-280 P
B101290771	B101290755	01/01/26	50-289 P	B101300491	B101300486	01/01/15	50-251 P
B101290781	B101290779	80/11/25	50-354 Q	B101300495	B101300486	81/01/15	50-251 P
B101290789	B101290703	01/01/06	50-483 H	B101300499	B101300486	81/01/15	50-251 P
B101290791	B101290786	81/01/19	50-10 P	B101300507	B101300502	00/12/01	50-325 S
B101290798	B101290794	81/01/26	CONTRACT	B101300512	B101300501	81/01/26	50-260 S
B101290802	B101290799	81/01/14	50-336 P	B101300514	B101300511	01/01/26	50-296 Q
B101290804	B101290799	81/01/14	50-336 P	B101300519	B101300513	81/01/23	50-285 S
B101290807	B101290799	81/01/14	50-336 P	B101300520	B101300504	81/01/27	50-296 S
B101300019	B101300014	80/11/13	50-220 Q	B101300523	B101300509	81/01/22	50-327 S
B101300030	B101300026	80/11/07	50-309 Q	B101300530	B101300523	81/01/23	50-317 S
B101300033	B101300021	81/01/06	50-352 H	B101300538	B101300533	81/01/26	50-318 S
B101300040	B101300034	80/11/12	50-219 Q	B101300534	B101300534	81/01/21	50-346 Q
B101300050	B101300042	81/01/16	50-261 P	B101300563	B101300560	81/01/21	50-305 Q
B101300057	B101300042	81/01/16	50-261 P	B101300571	B101300566	81/01/21	50-346 Q
B101300065	B101300042	81/01/16	50-261 P	B101300572	B101300568	80/12/01	50-325 S
B101300067	B101300059	80/11/03	50-334 Q	B101300577	B101300574	81/01/21	50-254 Q
B101300073	B101300070	81/01/09	50-315 Q	B101300578	B101300576	81/01/09	50-270 S
B101300074	B101300068	80/11/17	50-333 Q	B101300587	B101300586	81/01/26	50-238 R
B101300075	B101300069	81/01/26	CONTRACT	B101300593	B101300583	81/01/26	50-460 Q
B101300080	B101300068	00/11/17	50-333 Q	B101300593	B101300583	81/01/26	50-460 Q
B101300085	B101300077	81/01/12	50-29 P	B101300596	B101300592	81/01/22	50-286 P
B101300085	B101300077	81/01/12	50-29 P	B101300597	B101300592	81/01/09	50-339 S
B101300087	B101300068	80/11/17	50-333 Q	B101300598	B101300583	81/01/26	50-460 Q
B101300089	B101300077	81/01/12	50-29 P	B101300604	B101300583	81/01/26	50-460 Q
B101300093	B101300086	81/01/26	CONTRACT	B101300614	B101300609	81/01/19	50-285 P
B101300104	B101300097	81/01/26	50-390 A	B101300615	B101300611	81/01/27	50-296 S
B101300107	B101300068	80/11/17	50-333 Q	B101300624	B101300609	81/01/19	50-285 P
B101300126	B101300120	80/11/14	YPRFLC	B101300629	B101300628	81/01/26	50-259 S
B101300138	B101300134	80/11/09	50-317 Q	B101300641	B101300632	81/01/26	50-296 S
B101300151	B101300143	80/11/10	50-3 Q	B101300696	B101300691	81/01/06	50-263 E

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8101300714	8101300706	81/01/26	50-339 S
8101300715	8101300711	81/01/19	50-224 P
8101300726	8101300703	81/01/26	50-29 S
8101300727	8101300720	80/11/05	50-245 G
8101300728	8101300722	81/01/26	50-275 F
8101300733	8101300732	81/01/26	50-275 F
8101300728	8101300731	81/01/06	50-324 P
8101300740	8101300734	80/11/10	50-286 U
8101300752	8101300750	81/01/14	50-295 F
8101300754	8101300753	81/01/14	50-295 P

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8101300742	8101300753	81/01/13	50-333 P
8101300759	8101300756	81/01/14	50-361 Q
8101300763	8101300756	81/01/14	50-361 Q
8101300766	8101300756	81/01/14	50-361 Q
8101300771	8101300756	81/01/14	50-361 Q
8101300791	8101300788	80/12/17	50-155 Q
8101300796	8101300788	80/12/17	50-155 Q
8101300820	8101300816	81/01/15	50-295 P
8101300827	8101300816	81/01/15	50-295 P
8101300841	8101300836	81/01/14	50-413 A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Application for construction permit.
2. General Information submitted with construction permit application.
3. Amendments and changes to items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses.
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit.
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license.
13. General Information submitted with operating license application.
14. Amendments and changes to items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR).
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an II-B Bulletin.
17. Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal and acknowledgement letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal register notices citing the availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
2. Supplements to the DES and FES.
3. Correspondence relating to the DES and FES.
4. Comments from other federal, state and local government agencies.
5. Transmittal and acknowledgement letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Federal register notice citing availability of items 1 and 2.
9. Site visits to obtain information for DES or FES.
10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

3. Correspondence relating to SER.
4. Federal register notices citing availability of items 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1. Fire Hazard Protection Plan and surveys.
2. Plant evacuation correspondence.
3. Safeguards Contingency Plans.
4. Review of Health Physics Program.
5. Correspondence relating to aforementioned plans.
6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
2. Federal register notices regarding hearings.
3. Requests to make appearances at hearings.
4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
6. Correspondence to and from intervenors.
7. Board orders and decisions.
8. Petitions for Commission action.
9. Legal filings and Commission orders and decisions resulting from item 8.

2. Changes in structure of organization.
3. Changes in service lists.
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

1. Limited Work Authorizations (LWA) and amendments.
2. Correspondence pertaining to work performed under LWA's.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
2. Correspondence where the primary topic of discussion is antitrust matters.
3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
2. Correspondence from ACRS.
3. Announcement of ACRS meetings.
4. Transmittal and acknowledgement letters.
5. ACRS reports.
6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
7. Minutes at ACRS Subcommittee Meetings.

P. OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes and related correspondence.
2. Technical specifications and changes.

of the operating license.

7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
8. Information on the Standard Review Plan (STP).
9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
11. Owner's group meeting announcements and reports.
12. Quality assurance information.
13. Environmental matters (technical).
14. Emergency core cooling system documents.
15. Radioactive waste information.
16. Correspondence regarding expansion of spent fuel storage pool.
17. Start-up test reports.
18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1. Inspection reports.
2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Pre-service and in-service inspections and procedures.
7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Periodic personnel exposure reports.
4. Operational Logbooks:
 - Logbooks on Environmental Data
 - Logbooks on Radiological Data
 - Operations Log on Plant Systems Core
 - Plant Status Summary Sheets.
5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
2. Potential or possible reportable deficiency reports and related correspondence.
3. Personnel exposure reports.
4. Construction deficiency reports submitted under 10 CFR 50.55c.
5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
6. Environmental Technical Specifications violation reports and Environmental Event reports.
7. Part 21 Reports of defects and noncompliance.
8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
2. Testimony and statements submitted to ASLB and ASLAB.
3. Commission meeting transcripts.
4. NRC staff briefings to the Commission.
5. Statements and written testimony submitted at Commission meeting or hearings.
6. Transcripts of utility briefs to NRC staff.
7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

inquiries are filed in category H.

1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
2. Preparatory and backup documents for item 1.
3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators.
2. NRC examination results.
3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

1. Application for authority to voluntarily surrender license.
2. Application to dismantle the facility and dispose of component parts.
3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
4. Documents relating to disposal of radioactive material and decontamination of the site.
5. Other correspondence relating to above items.
6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR – Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

1. *Sunshine Act Federal Register notices.*
2. *Full, written explanation of closed meetings.*
3. *Certification of General Counsel on closed meetings.*
4. *Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.*
5. *Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.*
6. *Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.*
7. *Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.*

ACRS – Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. *Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.*
2. *ACRS meeting announcements; description of meeting agendas.*
3. *ACRS-generated reports, memoranda and correspondence that are publicly available.*
4. *ACRS consultant reports, comments and related correspondence.*
5. *ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.*

COMMISSION – NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. *Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.*

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
2. Solicitations (RFP or IFB) issued by the NRC.
3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
4. Contractual documents and contract modifications, if any.

DISCLOSURE – Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS – Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

I&E – Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC – Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG – NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR – Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM – Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.

- petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ – Projects–Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

used for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held at the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the *Organization* category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
3. Pre-test production reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RIIs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY – Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

of the Agency's major activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning for radiological incidents, water quality and transportation surveillance,
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting.
 3. State Legislative Reports.
 4. Agreement State Licensing Statistics Reports.
- NOTE: For specific information relating and listing projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC's review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

Title List of Documents Made Publicly Available January 1 1, 1981

AUTHOR(S)

PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20545

SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20545

TYPE OF REPORT

Monthly

PERIOD COVERED (Inclusive dates)

SUPPLEMENTARY NOTES

ABSTRACT (and words or text)

This document is a monthly publication containing descriptions of information received and generated by the US NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The docketed information includes information formerly found through the U.S. Department of Energy's Technical Information Center under the title *Power Reactor Docket Information (PRDI)*. This document replaces PRDI, which will no longer be prepared. This document contains the following indexes: Personal Author Index, Corporate Source Index, and Report Number Index.

2 (Leave blank)

3 DOCUMENT'S ACCESSION NO

5. DATE REPORT COMPLETED

MONTH February YEAR 1981

DATE REPORT ISSUED

MONTH April YEAR 1981

6 (Leave blank)

8 (Leave blank)

10 PROJECT/TASK/WORK UNIT NO

11. CONTRACT NO

14 (Leave blank)

KEY WORDS AND DESCRIPTOR ANALYSIS

17a DESCRIPTORS

IDENTIFIERS OPEN ENDED TERMS

21 NO OF PAGES